| WO ID 76012 Part Cost: Part ID | WO Description SET UP 105377 (525) | WO Type ID | WO Status ID         | Scheduled Date | _       | Completed Date |
|--------------------------------|------------------------------------|------------|----------------------|----------------|---------|----------------|
| Part Cost:                     | SET UP 105377 (525)                |            |                      |                |         | Completed Date |
|                                |                                    | S          | Completed            | 3/17/201       | 6       | 3/21/201       |
| Part ID                        |                                    |            |                      |                |         |                |
|                                |                                    | Code ID    | Code Description     |                | Cost    |                |
| CA012616001                    | CABLE, DC POWER                    |            |                      | :              | \$95.04 |                |
| CA009562030                    | CABLE ASSEMBLY                     |            |                      | :              | \$91.08 |                |
| MAMROS0034NN006                | CABLE ASSEMBLY SPEAKER             |            |                      | !              | \$59.40 |                |
|                                |                                    |            | To                   | otal Cost: \$  | 245.52  |                |
| Labor Cost:                    |                                    |            |                      |                |         |                |
| Craft                          | Resource                           |            |                      |                |         |                |
| MECH                           | 12                                 | 40         | NEW VEHICLE / SET UP | \$             | 112.50  |                |
| MECH                           | 12                                 | 40         | NEW VEHICLE / SET UP | \$             | 112.50  |                |
| MECH                           | 12                                 | 40         | NEW VEHICLE / SET UP | \$             | 112.50  |                |
| MECH                           | 12                                 | 40         | NEW VEHICLE / SET UP | \$             | 112.50  |                |
| MECH                           | 12                                 | 40         | NEW VEHICLE / SET UP | \$             | 225.00  |                |
|                                |                                    |            | Tot                  | al Cost: \$    | 675.00  |                |
| 76012                          | SET UP 105377 (525)                | S          | Completed            | 3/17/201       | 6       | 3/21/201       |
| Part Cost:                     |                                    |            |                      |                |         |                |
| Part ID                        |                                    | Code ID    | Code Description     |                | Cost    |                |
| 01                             | SHOP SUPPLY ASSORTMENT             | 30         | ELECTRONICS          |                | \$5.50  |                |
|                                |                                    |            | To                   | otal Cost:     | \$5.50  |                |
| Labor Cost:                    |                                    |            |                      |                |         |                |
| Craft                          | Resource                           |            |                      |                |         |                |
| MECH                           | 30                                 | 30         | ELECTRONICS          | \$             | 187.50  |                |
|                                |                                    |            | Tot                  | al Cost: \$    | 187.50  |                |
| 77332                          | PM'S 105377 (525)                  | PM         | Cancelled            | 4/26/201       | 6       |                |



| 77835                 | PM'S 105377 (525)             | PM      | Completed        | (           | 6/28/2016 | 6/28/201  |
|-----------------------|-------------------------------|---------|------------------|-------------|-----------|-----------|
| Part Cost:            |                               |         |                  |             |           |           |
| Part ID               |                               | Code ID | Code Description |             | Cost      |           |
| 5W30                  | OIL MOTOR                     | PMA     |                  |             | \$8.10    |           |
| 100010                | OIL FILTER                    | PMA     |                  |             | \$2.97    |           |
|                       |                               |         |                  | Total Cost: | \$11.07   |           |
| Labor Cost:           |                               |         |                  |             |           |           |
| Craft                 | Resource                      |         |                  |             |           |           |
| MECH                  | 28                            | PMA     |                  |             | \$112.50  |           |
|                       |                               |         |                  | Total Cost: | \$112.50  |           |
| 79345                 | PM'S 105377 (525)             | PM      | Completed        | 1:          | 1/28/2016 | 11/28/201 |
| Part Cost:<br>Part ID |                               | Code ID | Code Description |             | Cost      |           |
| 100010                | OIL FILTER                    | PMA     |                  |             | \$2.97    |           |
| 5W20                  | SYNTHETIC OIL                 | PMA     |                  |             | \$13.44   |           |
|                       |                               |         |                  | Total Cost: | \$16.41   |           |
| Labor Cost:           |                               |         |                  |             |           |           |
| Craft                 | Resource                      |         |                  |             |           |           |
| MECH                  | 21                            | PMA     |                  |             | \$112.50  |           |
|                       |                               |         |                  | Total Cost: | \$112.50  |           |
| 80206                 | TOW TICKETS FOR FEBRUARY 2017 | IS      | Completed        |             | 3/3/2017  | 3/1/201   |
| Misc Cost Sublet ID   |                               |         |                  |             |           |           |
| WRECKER CLASS<br>A    | CLASS A WRECKER               | 1       | TOWING           |             | \$46.25   |           |
| WRECKER CLASS<br>A    | CLASS A WRECKER               | 1       | TOWING           |             | \$50.75   |           |
| ^                     |                               |         |                  | Total Cost: | \$97.00   |           |



|                           |                         | Unit Wo | rk Order History |             |           |          |
|---------------------------|-------------------------|---------|------------------|-------------|-----------|----------|
| 81128                     | PM'S 105377 (525)       | PM      | Completed        |             | 6/21/2017 | 7/5/2017 |
| <b>Part Cost:</b> Part ID |                         | Code ID | Code Description |             | Cost      |          |
| 5W20                      | SYNTHETIC OIL           | PMA     |                  |             | \$13.44   |          |
| 100010                    | OIL FILTER              | PMA     |                  |             | \$3.06    |          |
|                           |                         |         |                  | Total Cost: | \$16.50   |          |
| Labor Cost:               |                         |         |                  |             |           |          |
| Craft                     | Resource                |         |                  |             |           |          |
| MECH                      | 28                      | PMA     |                  |             | \$75.00   |          |
|                           |                         |         |                  | Total Cost: | \$75.00   |          |
| 81128                     | PM'S 105377 (525)       | PM      | Completed        |             | 6/21/2017 | 7/5/2017 |
| Part Cost:<br>Part ID     |                         | Code ID | Code Description |             | Cost      |          |
| 003875MB                  | 225/60WR18 FIRE MOUNTED | 12      | TIRES            |             | \$546.80  |          |
|                           |                         |         |                  | Total Cost: | \$546.80  |          |
| Labor Cost:               |                         |         |                  |             |           |          |
| Craft                     | Resource                |         |                  |             |           |          |
| MECH                      | 28                      | 12      | TIRES            |             | \$37.50   |          |
|                           |                         |         |                  | Total Cost: | \$37.50   |          |



| 81128                  | PM'S 105377 (525)                 | PM      | Completed            | 6/21/2017         | 7/5/2017   |
|------------------------|-----------------------------------|---------|----------------------|-------------------|------------|
| Part Cost:<br>Part ID  |                                   | Code ID | Code Description     | Cost              |            |
| 15152                  | BOLT                              | VI      | VEHICLE ENHANCEMENTS | \$0.56            |            |
| 6655121                | PUSH PIN                          | VI      | VEHICLE ENHANCEMENTS | \$3.45            |            |
| 6652874                | PUSH PIN                          | VI      | VEHICLE ENHANCEMENTS | \$3.43            |            |
| 12621                  | FLAT WASHER M8 HARDENED           | VI      | VEHICLE ENHANCEMENTS | \$0.12            |            |
| 725255                 | BUTT CONNECTOR                    | VI      | VEHICLE ENHANCEMENTS | \$1.92            |            |
| 725254                 | BUTT CONNECTOR                    | VI      | VEHICLE ENHANCEMENTS | \$3.78            |            |
| 724111                 | TERMINAL                          | VI      | VEHICLE ENHANCEMENTS | \$0.80            |            |
| 724102                 | TERMINAL                          | VI      | VEHICLE ENHANCEMENTS | \$0.44            |            |
|                        |                                   |         | Tot                  | al Cost: \$14.50  |            |
| Labor Cost:            |                                   |         |                      |                   |            |
| Craft                  | Resource                          |         |                      |                   |            |
| MECH                   | 12                                | VI      | VEHICLE ENHANCEMENTS | \$337.50          |            |
|                        |                                   |         | Tota                 | Cost: \$337.50    |            |
| 1551                   | TOW TICKETS JULY 2017             | PM      | Completed            | 8/4/2017          | 7/31/2017  |
| Misc Cost<br>Sublet ID |                                   |         |                      |                   |            |
| WRECKER<br>JUMP+       | JUMP START LT PLUS MILEAGE        | 1       | TOWING               | \$83.25           |            |
|                        |                                   |         | Tota                 | l Cost: \$83.25   |            |
| 2362                   | DRIVER REAR TIRE SLOW LEAK 105377 | N       | Completed            | 10/30/2017        | 10/30/2017 |
| Part Cost:             |                                   |         |                      |                   |            |
| Part ID                |                                   | Code ID | Code Description     | Cost              |            |
| 003875MB               | 225/60WR18 FIRE MOUNTED           | 12      | TIRES                | \$136.70          |            |
|                        |                                   |         | Tot                  | al Cost: \$136.70 |            |
| Labor Cost:            |                                   |         |                      |                   |            |
| Craft                  | Resource                          |         |                      |                   |            |
| MECH                   | 28                                | 12      | TIRES                | \$37.50           |            |
|                        |                                   |         | Tota                 | Cost: \$37.50     |            |



|                     |                                   | Unit Wo | rk Order History    |                |           |
|---------------------|-----------------------------------|---------|---------------------|----------------|-----------|
|                     |                                   |         |                     |                |           |
| 32362               | DRIVER REAR TIRE SLOW LEAK 105377 | N       | Completed           | 10/30/2017     | 10/30/201 |
| Labor Cost:         |                                   |         |                     |                |           |
| Craft               | Resource                          |         |                     |                |           |
| MECH                | 17                                | ADM     | ADMINISTRATIVE TIME | \$15.00        |           |
|                     |                                   |         | Total C             | Cost: \$15.00  |           |
| 32457               | IS                                | N       | Completed           | 11/9/2017      | 10/31/201 |
| Misc Cost Sublet ID |                                   |         |                     |                |           |
| CAR WASH            | CAR WASH                          |         |                     | \$7.99         |           |
|                     |                                   |         | Total (             | Cost: \$7.99   |           |
| 32772               | PM'S 105377 (525)                 | PM      | Completed           | 12/21/2017     | 12/21/201 |
| Part Cost: Part ID  |                                   | Code ID | Code Description    | Cost           |           |
| -                   | MATDED DI ADE                     |         | Code Description    |                |           |
| NP24                | WIPER BLADE                       | PMA     |                     | \$4.24         |           |
| NP21                | WIPER BLADE                       | PMA     |                     | \$3.14         |           |
| 100010              | OIL FILTER                        | PMA     |                     | \$3.05         |           |
| 0W20                | SYNTHETIC OIL                     | PMA     |                     | \$11.52        |           |
|                     |                                   |         | Total               | Cost: \$21.95  |           |
| Labor Cost:         |                                   |         |                     |                |           |
| Craft               | Resource                          |         |                     |                |           |
| MECH                | 21                                | PMA     |                     | \$112.50       |           |
|                     |                                   |         | Total C             | Cost: \$112.50 |           |
| 32772               | PM'S 105377 (525)                 | PM      | Completed           | 12/21/2017     | 12/21/201 |
| Labor Cost:         |                                   |         |                     |                |           |
| Craft               | Resource                          |         |                     |                |           |
| MECH                | 17                                | ADM     | ADMINISTRATIVE TIME | \$15.00        |           |
|                     |                                   |         | Total C             | Cost: \$15.00  |           |



| 84012       | PMA. UNIT 525.          | PM      | Completed            | 5/29/2018        | 5/30/201 |
|-------------|-------------------------|---------|----------------------|------------------|----------|
| Part Cost:  |                         |         |                      |                  |          |
| Part ID     |                         | Code ID | Code Description     | Cost             |          |
| 21C520XB    | 5W20 FULL SYN QT        | PMA     |                      | \$12.48          |          |
| 100010      | OIL FILTER              | PMA     |                      | \$3.15           |          |
| M506        | WASHER FLUID            | PMA     |                      | \$0.89           |          |
|             |                         |         | Tota                 | l Cost: \$16.52  |          |
| Labor Cost: |                         |         |                      |                  |          |
| Craft       | Resource                |         |                      |                  |          |
| MECH        | 12                      | PMA     |                      | \$112.50         |          |
|             |                         |         | Total                | Cost: \$112.50   |          |
| 84012       | PMA. UNIT 525.          | PM      | Completed            | 5/29/2018        | 5/30/201 |
| Part Cost:  |                         |         |                      |                  |          |
| Part ID     |                         | Code ID | Code Description     | Cost             |          |
| 003875MB    | 225/60WR18 FIRE MOUNTED | 12      | TIRES                | \$576.12         |          |
|             |                         |         | Tota                 | l Cost: \$576.12 |          |
| Labor Cost: |                         |         |                      |                  |          |
| Craft       | Resource                |         |                      |                  |          |
| MECH        | 12                      | 12      | TIRES                | \$75.00          |          |
|             |                         |         | Total                | Cost: \$75.00    |          |
| 84012       | PMA. UNIT 525.          | PM      | Completed            | 5/29/2018        | 5/30/201 |
| Part Cost:  |                         |         |                      |                  |          |
| Part ID     |                         | Code ID | Code Description     | Cost             |          |
| CBC         | BACKUP CAMERA           | VI      | VEHICLE ENHANCEMENTS | \$20.89          |          |
| BCICH41     | BACKUP CAMERA INTERFACE | VI      | VEHICLE ENHANCEMENTS | \$170.71         |          |
|             |                         |         | Tota                 | l Cost: \$191.60 |          |
| Labor Cost: |                         |         |                      |                  |          |
| Craft       | Resource                |         |                      |                  |          |
| MECH        | 12                      | 06      | ELECTRICAL           | \$187.50         |          |
|             |                         |         | Total                | Cost: \$187.50   |          |



|   |   | Unit Wo   | rk Order History                   |                          |  |            |
|---|---|-----------|------------------------------------|--------------------------|--|------------|
| 35312   | IS OCTOBER TOWING                                     | N         | Completed                          |                          | 11/5/2018                                    | 10/31/2018 |
| Misc Cost<br>Sublet ID  |   |           |                                    |                          |  |            |
| WRECKER<br>WINCH  | WINCH OUT   | СТО       | SUBLET / TOWING                    |                          | \$40.00                                      |            |
|   |   |           |                                    | Total Cost:              | \$40.00                                      |            |
| 35715   | PM'S 105377 (525)                                     | PM        | Completed                          |                          | 1/7/2019                                     | 1/7/201    |
| Part Cost:  |   |           |                                    |                          |  |            |
| Part ID   |   | Code ID   | Code Description                   |                          | Cost   |            |
| 21E520SB  | 5W20 FULL SYN QT                                      | PMA       |                                    |                          | \$17.29                                      |            |
| NP21  | WIPER BLADE   | PMA       |                                    |                          | \$3.14                                       |            |
| NP24  | WIPER BLADE   | PMA       |                                    |                          | \$4.24                                       |            |
| 100010  | OIL FILTER  | PMA       |                                    |                          | \$3.23                                       |            |
|   |   |           |                                    |                          |  |            |
|   |   |           |                                    | Total Cost:              | \$27.90                                      |            |
| Lahor Cost:   |   |           |                                    | Total Cost:              | \$27.90                                      |            |
| <b>Labor Cost:</b> Craft                                      | Resource  |           |                                    | Total Cost:              | \$27.90                                      |            |
| <b>Labor Cost:</b> Craft MECH                                 | Resource<br>30  | PMA       |                                    | Total Cost:              |  |            |
| Craft   |   | РМА       |                                    | Total Cost:  Total Cost: | \$27.90<br>\$154.00<br>\$154.00              |            |
| Craft   |   | PMA<br>PM | Completed                          |                          | \$154.00                                     | 1/7/201    |
| Craft MECH 85715  | 30  |           |                                    |                          | \$154.00<br>\$154.00                         | 1/7/201    |
| <u>Craft</u><br>MECH  | 30  |           |                                    |                          | \$154.00<br>\$154.00                         | 1/7/201    |
| Craft MECH 85715 Labor Cost:                                  | 30<br>PM'S 105377 (525)                               |           |                                    |                          | \$154.00<br>\$154.00                         | 1/7/201    |
| Craft MECH 35715  Labor Cost: Craft                           | 30<br>PM'S 105377 (525)<br>Resource                   | РМ        | Completed  ARBITRATOR VIDEO SYSTEM |                          | \$154.00<br>\$154.00<br>1/7/2019             | 1/7/201    |
| Craft MECH 35715  Labor Cost: Craft                           | 30<br>PM'S 105377 (525)<br>Resource                   | РМ        | Completed  ARBITRATOR VIDEO SYSTEM | Total Cost:              | \$154.00<br>\$154.00<br>1/7/2019<br>\$192.50 | 1/7/201    |
| Craft MECH  85715  Labor Cost: Craft MECH                     | 30  PM'S 105377 (525)  Resource 30                    | PM<br>AR  | Completed  ARBITRATOR VIDEO SYSTEM | Total Cost:              | \$154.00<br>\$154.00<br>1/7/2019<br>\$192.50 |            |
| Craft MECH  85715  Labor Cost: Craft MECH  85715              | 30  PM'S 105377 (525)  Resource 30                    | PM<br>AR  | Completed  ARBITRATOR VIDEO SYSTEM | Total Cost:              | \$154.00<br>\$154.00<br>1/7/2019<br>\$192.50 |            |
| Craft MECH  85715  Labor Cost: Craft MECH  85715  Labor Cost: | 30  PM'S 105377 (525)  Resource 30  PM'S 105377 (525) | PM<br>AR  | Completed  ARBITRATOR VIDEO SYSTEM | Total Cost:              | \$154.00<br>\$154.00<br>1/7/2019<br>\$192.50 |            |



|                             |   | Unit Wo | rk Order History |                    |           |
|-----------------------------|---|---------|------------------|--------------------|-----------|
| 86784                       | PM'S 105377 (525) SPOT LIGHT INOP,<br>BATTERY | РМ      | Completed        | 6/7/2019           | 6/10/2019 |
| Part Cost:<br>Part ID       |   | Code ID | Code Description | Cost               |           |
| 100010                      | OIL FILTER                                    | PMA     |                  | \$3.29             |           |
| M506                        | WASHER FLUID                                  | PMA     |                  | \$1.08             |           |
| 21E520SB                    | 5W20 FULL SYN QT                              | PMA     |                  | \$17.29            |           |
|                             |   |         | To               | otal Cost: \$21.66 |           |
| <b>Labor Cost:</b><br>Craft | Resource                                      |         |                  |                    |           |
| MECH                        | 12  | PMA     |                  | \$115.50           |           |
|                             |   |         | Tot              | al Cost: \$115.50  |           |
| 86784                       | PM'S 105377 (525) SPOT LIGHT INOP,<br>BATTERY | PM      | Completed        | 6/7/2019           | 6/10/2019 |
| Part Cost:                  |   |         |                  |                    |           |
| Part ID                     |   | Code ID | Code Description | Cost               |           |
| 4048                        | CABIN AIR FILTER DODGE                        | A15     | CABIN AIR FILTER | \$8.33             |           |
|                             |   |         | To               | otal Cost: \$8.33  |           |
| Labor Cost:                 |   |         |                  |                    |           |
| Craft                       | Resource                                      |         |                  |                    |           |
| MECH                        | 12  | A15     | CABIN AIR FILTER | \$19.25            |           |



\$19.25

Total Cost:

| <b>Unit Work Order History</b> | 7 |
|--------------------------------|---|
|--------------------------------|---|

| 5784                      | PM'S 105377 (525) SPOT LIGHT INOP,<br>BATTERY | PM      | Completed        |             | 6/7/2019 | 6/10/2019 |
|---------------------------|---|---------|------------------|-------------|----------|-----------|
| <b>Part Cost:</b> Part ID |   | Code ID | Code Description |             | Cost     |           |
| CBC                       | BACKUP CAMERA                                 | 06      | ELECTRICAL       |             | \$20.88  |           |
| CBC                       | BACKUP CAMERA                                 | 06      | ELECTRICAL       |             | \$20.88  |           |
| BCICH41                   | BACKUP CAMERA INTERFACE                       | 06      | ELECTRICAL       |             | \$172.48 |           |
|                           |   |         |                  | Total Cost: | \$214.24 |           |
| Labor Cost:<br>Craft      | Resource                                      |         |                  |             |          |           |
| MECH                      | 12  | 06      | ELECTRICAL       |             | \$77.00  |           |
| MECH                      | 12  | 06      | ELECTRICAL       |             | \$77.00  |           |
| MECH                      | 12  | 06      | ELECTRICAL       |             | \$231.00 |           |
|                           |   |         |                  | Total Cost: | \$385.00 |           |
| 784                       | PM'S 105377 (525) SPOT LIGHT INOP,<br>BATTERY | PM      | Completed        |             | 6/7/2019 | 6/10/201  |
| Part Cost:<br>Part ID     |   | Code ID | Code Description |             | Cost     |           |
| 7549                      | BATTERY                                       | 07      | BATTERY          |             | \$100.51 |           |
|                           |   |         |                  | Total Cost: | \$100.51 |           |
| Labor Cost:               |   |         |                  |             |          |           |
| Craft                     | Resource                                      |         |                  |             |          |           |
| MECH                      | 12  | 07      | BATTERY          |             | \$77.00  |           |
|                           |   |         |                  | Total Cost: | \$77.00  |           |

|                           |   | Unit Wo | rk Order History |             |                      |           |
|---------------------------|---|---------|------------------|-------------|----------------------|-----------|
| 36784                     | PM'S 105377 (525) SPOT LIGHT INOP,<br>BATTERY | PM      | Completed        |             | 6/7/2019             | 6/10/2019 |
| Part Cost:<br>Part ID     |   | Code ID | Code Description |             | Cost                 |           |
| 003875MB                  | 225/60WR18 FIRE MOUNTED                       | 12      | TIRES            |             | \$620.12             |           |
|                           |   |         |                  | Total Cost: | \$620.12             |           |
| Labor Cost:               |   |         |                  |             |                      |           |
| Craft<br>MECH             | Resource<br>12                                | 12      | TIRES            |             | <u> </u>             |           |
|                           |   |         |                  | Total Cost: | \$57.75              |           |
| 6784                      | PM'S 105377 (525) SPOT LIGHT INOP,<br>BATTERY | PM      | Completed        |             | 6/7/2019             | 6/10/2019 |
| <b>Part Cost:</b> Part ID |   | Code ID | Code Description |             | Cost                 |           |
| FT8997                    | BRAKE PADS                                    | 15      | BRAKES           |             | \$48.16              |           |
| FT8998                    | DISC PAD                                      | 15      | BRAKES           |             | \$48.92              |           |
|                           |   |         |                  | Total Cost: | \$97.08              |           |
| Labor Cost:               |   |         |                  |             |                      |           |
| Craft                     | Resource                                      | 15      | DDAVEC           |             | #221 00              |           |
| MECH                      | 12  | 15      | BRAKES           | Total Cost: | \$231.00<br>\$231.00 |           |
| 6846                      | IS  | IS      | Completed        |             | 6/17/2019            | 6/21/2019 |
| Part Cost:<br>Part ID     |   | Code ID | Code Description |             | Cost                 |           |
| U8597A                    | TOGGLE ASSEMBLY                               | 06      | ELECTRICAL       |             | \$16.14              |           |
| FREIGHT                   | FREIGHT                                       | 06      | ELECTRICAL       |             | \$6.08               |           |
| -                         | -   |         | <del>-</del>     | Total Cost: | \$22.22              |           |



|                        |                                | Unit Wo  | ork Order History   |                     |          |
|------------------------|--------------------------------|----------|---------------------|---------------------|----------|
| 37037                  | JUNE TOW TICKETS 2019          | N        | Completed           | 7/11/2019           | 7/31/201 |
| Misc Cost Sublet ID    |                                |          |                     |                     |          |
| WRECKER JUMP           | JUMP START                     |          |                     | \$32.50             |          |
| WRECKER JUMP           | JUMP START                     |          |                     | \$32.50             |          |
|                        |                                |          | To                  | otal Cost: \$65.00  |          |
| 36952                  | IS JULY 2019                   | IS       | Completed           | 7/2/2019            | 7/31/20: |
| Misc Cost<br>Sublet ID |                                |          |                     |                     |          |
| BODY REPAIR            | BODY REPAIR                    | СРВ      | SUBLET / PAINT-BODY | \$548.20            |          |
|                        |                                |          | To                  | otal Cost: \$548.20 |          |
| 37148                  | DEAD BATTERY 105377            | N        | Completed           | 7/26/2019           | 7/29/20  |
| Labor Cost:            |                                |          |                     |                     |          |
| Craft                  | Resource                       |          |                     |                     |          |
| MECH                   | 12                             | 07       | BATTERY             | \$250.25            |          |
|                        |                                |          | To                  | tal Cost: \$250.25  |          |
| 37354                  | CHECK OVER FOR REASSIGNMENT, : | 105377 N | Completed           | 8/21/2019           | 9/23/20  |
| Labor Cost:            |                                |          |                     |                     |          |
| Craft                  | Resource                       |          |                     |                     |          |
| MECH                   | 12                             | 20       | CHANGE OUTS         | \$115.50            |          |
|                        |                                |          | To                  | tal Cost: \$115.50  |          |
| 37354                  | CHECK OVER FOR REASSIGNMENT,   | 105377 N | Completed           | 8/21/2019           | 9/23/20  |
| Labor Cost:            |                                |          |                     |                     |          |
| Craft                  | Resource                       |          |                     |                     |          |
| MECH                   | 12                             | 07       | BATTERY             | \$38.50             |          |
|                        |                                |          | To                  | tal Cost: \$38.50   |          |



|                     | •  |         |                         |                      |            |
|---------------------|--|---------|-------------------------|----------------------|------------|
|                     |  | Unit Wo | ork Order History       |                      |            |
| 87489               | TOW TICKETS AUGUST 2019                  | N       | Completed               | 9/10/2019            | 8/31/2019  |
| Misc Cost Sublet ID |  |         |                         |                      |            |
| WRECKER LT+         | TOW PLUS MILEAGE LIGHT VEHICLE           |         |                         | \$44.00              |            |
|                     |  |         | <del>-</del>            | Total Cost: \$44.00  |            |
| 87354               | CHECK OVER FOR REASSIGNMENT, 105377      | 7 N     | Completed               | 8/21/2019            | 9/23/201   |
| Part Cost:          |  |         |                         |                      |            |
| Part ID             |  | Code ID | Code Description        | Cost                 |            |
| 725105              | BUTT CONNECTOR                           | 06      | ELECTRICAL              | \$0.36               |            |
| 725103              | BUTT CONNECTOR                           | 06      | ELECTRICAL              | \$0.32               |            |
| 725292              | SLIDE TERMINAL                           | 06      | ELECTRICAL              | \$0.50               |            |
|                     |  |         | -                       | Total Cost: \$1.18   |            |
| 87354               | CHECK OVER FOR REASSIGNMENT, 105377      | 7 N     | Completed               | 8/21/2019            | 9/23/201   |
| Labor Cost:         |  |         |                         |                      |            |
| Craft               | Resource                                 |         |                         |                      |            |
| MECH                | 12                                       | AR      | ARBITRATOR VIDEO SYSTEM | \$154.00             |            |
|                     |  |         | T                       | Total Cost: \$154.00 |            |
| 88106               | CHECK OVER FOR CHANGE OUT, #4525, 105377 | N       | Completed               | 12/10/2019           | 12/10/2019 |
| Labor Cost:         |  |         |                         |                      |            |
| Craft               | Resource                                 |         |                         |                      |            |
| MECH                | 30                                       | 20      | CHANGE OUTS             | \$77.00              |            |
|                     |  |         | T                       | Total Cost: \$77.00  |            |



|                       |  | Unit Wo | ork Order History                  |            |            |            |
|-----------------------|--|---------|------------------------------------|------------|------------|------------|
| 88106                 | CHECK OVER FOR CHANGE OUT, #4525, 105377 | N       | Completed                          | :          | 12/10/2019 | 12/10/2019 |
| Part Cost:<br>Part ID |  | Code ID | Code Description                   |            | Cost       |            |
| 21E520SB              | 5W20 FULL SYN QT                         | PMA     |                                    |            | \$15.68    |            |
| M506                  | WASHER FLUID                             | PMA     |                                    |            | \$1.08     |            |
| 100010                | OIL FILTER                               | PMA     |                                    |            | \$3.29     |            |
|                       |  |         | To                                 | otal Cost: | \$20.05    |            |
| Labor Cost:           |  |         |                                    |            |            |            |
| Craft<br>MECH         | Resource<br>30                           | PMA     |                                    |            | \$115.50   |            |
| MECH                  | 30                                       | PMA     | Tot                                | al Cost:   | \$115.50   |            |
| 88041                 | DECEMBER ISSUE SLIP                      | N       | Completed                          |            | 12/2/2019  | 12/31/2019 |
| Misc Cost Sublet ID   |  |         |                                    |            |            |            |
| DETAIL                | DETAIL                                   |         |                                    |            | \$140.00   |            |
|                       |  |         | To                                 | tal Cost:  | \$140.00   |            |
| 88216                 | PM'S, FAN HIT RADIATOR, 105377 (525)     | PM      | Completed                          |            | 12/30/2019 | 12/31/2019 |
| Part Cost:<br>Part ID |  | Code ID | Code Description                   |            | Cost       |            |
| 5137713AA             | FAN COOLING                              | A03     | CHARGER COOLING FAN<br>REPLACEMENT |            | \$69.30    |            |
|                       |  |         |                                    | otal Cost: | \$69.30    |            |
| Labor Cost:           |  |         |                                    |            |            |            |
| Craft                 | Resource                                 | 402     | CHARGES COOLTEGES                  |            |            |            |
| MECH                  | 12                                       | A03     | CHARGER COOLING FAN REPLACEMENT    |            | \$57.75    |            |
|                       |  |         | Tot                                | al Cost:   | \$57.75    |            |



| 3216        | PM'S, FAN HIT RADIATOR, 105377 (525) | PM      | Completed        | 1           | 2/30/2019 | 12/31/2019 |
|-------------|--------------------------------------|---------|------------------|-------------|-----------|------------|
| Part Cost:  |                                      |         |                  |             |           |            |
| Part ID     |                                      | Code ID | Code Description |             | Cost      |            |
| AFC10000    | COOLANT                              | 03      | COOLING SYSTEM   |             | \$11.36   |            |
| CU13157     | RADIATOR                             | 03      | COOLING SYSTEM   |             | \$121.69  |            |
|             |                                      |         |                  | Total Cost: | \$133.05  |            |
| Labor Cost: |                                      |         |                  |             |           |            |
| Craft       | Resource                             |         |                  |             |           |            |
| MECH        | 12                                   | 03      | COOLING SYSTEM   |             | \$154.00  |            |
|             |                                      |         |                  | Total Cost: | \$154.00  |            |
| 3216        | PM'S, FAN HIT RADIATOR, 105377 (525) | PM      | Completed        | 1           | 2/30/2019 | 12/31/201  |
| Part Cost:  |                                      |         |                  |             |           |            |
| Part ID     |                                      | Code ID | Code Description |             | Cost      |            |
| 724111      | TERMINAL                             | 06      | ELECTRICAL       |             | \$1.20    |            |
| 725254      | BUTT CONNECTOR                       | 06      | ELECTRICAL       |             | \$7.92    |            |
|             |                                      |         |                  | Total Cost: | \$9.12    |            |
| Labor Cost: |                                      |         |                  |             |           |            |
| Craft       | Resource                             |         |                  |             |           |            |
| MECH        | 12                                   | 06      | ELECTRICAL       |             | \$154.00  |            |
|             |                                      |         |                  | Total Cost: | \$154.00  |            |
| 216         | PM'S, FAN HIT RADIATOR, 105377 (525) | PM      | Completed        | 1           | 2/30/2019 | 12/31/201  |
| Part Cost:  |                                      |         |                  |             |           |            |
| Part ID     |                                      | Code ID | Code Description |             | Cost      |            |
| 921129      | TPMS                                 | 12      | TIRES            |             | \$43.45   |            |
|             |                                      |         |                  | Total Cost: | \$43.45   |            |
| Labor Cost: |                                      |         |                  |             |           |            |
| Craft       | Resource                             |         |                  |             |           |            |
| MECH        | 12                                   | 12      | TIRES            |             | \$57.75   |            |
|             |                                      |         |                  | Total Cost: | \$57.75   |            |



|                          |                                    | Unit Wo | rk Order History |             |            |           |
|--------------------------|------------------------------------|---------|------------------|-------------|------------|-----------|
| 38216                    | PM'S, FAN HIT RADIATOR, 105377 (5. | 25) PM  | Completed        |             | 12/30/2019 | 12/31/201 |
| Labor Cost:              |                                    |         |                  |             |            |           |
| Craft                    | Resource                           |         |                  |             |            |           |
| MECH                     | 12                                 | 37      | DIAGNOSTIC       |             | \$57.75    |           |
|                          |                                    |         |                  | Total Cost: | \$57.75    |           |
| 38400                    | DECEMBER 2019 TOW TICKETS          | N       | Completed        |             | 1/27/2020  | 12/31/201 |
| Misc Cost<br>Sublet ID   |                                    |         |                  |             |            |           |
| WRECKER JUMP             | JUMP START                         |         |                  |             | \$32.50    |           |
| WRECKER LT               | LT TOW IN CITY                     |         |                  |             | \$46.25    |           |
|                          |                                    |         |                  | Total Cost: | \$78.75    |           |
| 38566                    | PM'S , CHECK TIRES, 105377 (525)   | PM      | Completed        |             | 2/19/2020  | 2/19/202  |
| Part Cost:<br>Part ID    |                                    | Code ID | Code Description |             | Cost       |           |
| 100010                   | OIL FILTER                         | PMA     |                  |             | \$3.29     |           |
| M506                     | WASHER FLUID                       | PMA     |                  |             | \$1.08     |           |
| 21E520SB                 | 5W20 FULL SYN QT                   | PMA     |                  |             | \$13.44    |           |
|                          |                                    |         |                  | Total Cost: | \$17.81    |           |
| <b>Labor Cost:</b> Craft | Resource                           |         |                  |             |            |           |
| MECH                     | 12                                 | PMA     |                  |             | \$115.50   |           |
|                          |                                    |         |                  | Total Cost: | \$115.50   |           |
| 38566                    | PM'S , CHECK TIRES, 105377 (525)   | PM      | Completed        |             | 2/19/2020  | 2/19/20   |
| Labor Cost:              |                                    |         |                  |             |            |           |
| Craft                    | Resource                           |         |                  |             |            |           |
| MECH                     | 12                                 | 12      | TIRES            |             | \$19.25    |           |
|                          |                                    |         |                  | Total Cost: | \$19.25    |           |



| 3962        | PM'S 105377 (525)             | PM      | Completed        |            | 4/22/2020 | 4/22/202 |
|-------------|-------------------------------|---------|------------------|------------|-----------|----------|
| Part Cost:  |                               |         |                  |            |           |          |
| Part ID     |                               | Code ID | Code Description |            | Cost      |          |
| 21E520SB    | 5W20 FULL SYN QT              | PMA     |                  |            | \$13.38   |          |
| M506        | WASHER FLUID                  | PMA     |                  |            | \$1.66    |          |
| 100010      | OIL FILTER                    | PMA     |                  |            | \$3.29    |          |
| NP21        | WIPER BLADE                   | PMA     |                  |            | \$3.30    |          |
| NP24        | WIPER BLADE                   | PMA     |                  |            | \$4.46    |          |
|             |                               |         | T                | otal Cost: | \$26.09   |          |
| Labor Cost: |                               |         |                  |            |           |          |
| Craft       | Resource                      |         |                  |            |           |          |
| MECH        | 21                            | PMA     |                  |            | \$77.00   |          |
|             |                               |         | То               | tal Cost:  | \$77.00   |          |
| 9473        | PM'S 105377 (525), CHECK TPMS | PM      | Completed        |            | 7/1/2020  | 7/1/202  |
| Part Cost:  |                               |         |                  |            |           |          |
| Part ID     |                               | Code ID | Code Description |            | Cost      |          |
| NP24        | WIPER BLADE                   | PMA     |                  |            | \$4.46    |          |
| NP21        | WIPER BLADE                   | PMA     |                  |            | \$3.30    |          |
| 100010      | OIL FILTER                    | PMA     |                  |            | \$3.29    |          |
| M506        | WASHER FLUID                  | PMA     |                  |            | \$1.66    |          |
| 21E520SB    | 5W20 FULL SYN QT              | PMA     |                  |            | \$13.38   |          |
|             |                               |         | T                | otal Cost: | \$26.09   |          |
| Labor Cost: |                               |         |                  |            |           |          |
| Craft       | Resource                      |         |                  |            |           |          |
| MECH        | 12                            | PMA     |                  |            | \$115.50  |          |
|             |                               |         | To               | tal Cost:  | \$115.50  |          |



|             |                               | Unit Wo | rk Order History |             |          |          |
|-------------|-------------------------------|---------|------------------|-------------|----------|----------|
| 39473       | PM'S 105377 (525), CHECK TPMS | PM      | Completed        | 7/1         | /2020    | 7/1/2020 |
| Part Cost:  |                               |         |                  |             |          |          |
| Part ID     |                               | Code ID | Code Description |             | Cost     |          |
| 003875MB    | 225/60WR18 FIRE MOUNTED       | 12      | TIRES            |             | \$602.80 |          |
|             |                               |         | •                | Total Cost: | \$602.80 |          |
| Labor Cost: |                               |         |                  |             |          |          |
| Craft       | Resource                      |         |                  |             |          |          |
| MECH        | 12                            | 12      | TIRES            |             | \$77.00  |          |
|             |                               |         |                  | Total Cost: | \$77.00  |          |
| 39473       | PM'S 105377 (525), CHECK TPMS | PM      | Completed        | 7/1         | /2020    | 7/1/2020 |
| Part Cost:  |                               |         |                  |             |          |          |
| Part ID     |                               | Code ID | Code Description |             | Cost     |          |
| 4048        | CABIN AIR FILTER DODGE        | A15     | CABIN AIR FILTER |             | \$8.33   |          |
|             |                               |         |                  | Total Cost: | \$8.33   |          |
| Labor Cost: |                               |         |                  |             |          |          |
| Craft       | Resource                      |         |                  |             |          |          |
| MECH        | 12                            | A15     | CABIN AIR FILTER |             | \$19.25  |          |
|             |                               |         |                  | Total Cost: | \$19.25  |          |
| 39473       | PM'S 105377 (525), CHECK TPMS | PM      | Completed        | 7/1         | /2020    | 7/1/2020 |
| Part Cost:  |                               |         |                  |             |          |          |
| Part ID     |                               | Code ID | Code Description |             | Cost     |          |
| 68277082AA  | ENGINE MOUNT                  | 26      | ENGINE           |             | \$149.56 |          |
|             |                               |         | •                | Total Cost: | \$149.56 |          |
| Labor Cost: |                               |         |                  |             |          |          |
| Craft       | Resource                      |         |                  |             |          |          |
| MECH        | 12                            | 26      | ENGINE           |             | \$154.00 |          |
|             |                               |         |                  | Total Cost: | \$154.00 |          |
| 39473       | PM'S 105377 (525), CHECK TPMS | PM      | Completed        | 7/1         | /2020    | 7/1/2020 |
| Part Cost:  |                               |         |                  |             |          |          |
| Part ID     |                               | Code ID | Code Description |             | Cost     |          |
| R134        | FREON                         | 05      | AIR CONDITIONING |             | \$5.96   |          |
|             |                               |         |                  | Total Cost: | \$5.96   |          |



| 90068       | PM'S 105377 (525), CHECK BRAKES | PM      | Completed        | !           | 9/28/2020 | 9/28/2020  |
|-------------|---------------------------------|---------|------------------|-------------|-----------|------------|
| Part Cost:  |                                 |         |                  |             |           |            |
| Part ID     |                                 | Code ID | Code Description |             | Cost      |            |
| M506        | WASHER FLUID                    | PMA     |                  |             | \$1.66    |            |
| 100010      | OIL FILTER                      | PMA     |                  |             | \$3.29    |            |
| 21E520SB    | 5W20 FULL SYN QT                | PMA     |                  |             | \$13.38   |            |
|             |                                 |         |                  | Total Cost: | \$18.33   |            |
| Labor Cost: |                                 |         |                  |             |           |            |
| Craft       | Resource                        |         |                  |             |           |            |
| MECH        | 12                              | PMA     |                  |             | \$115.50  |            |
|             |                                 |         |                  | Total Cost: | \$115.50  |            |
| 90248       | DEAD BATTERY, 105377            | N       | Completed        | 1           | 0/21/2020 | 10/21/2020 |
| Part Cost:  |                                 |         |                  |             |           |            |
| Part ID     |                                 | Code ID | Code Description |             | Cost      |            |
| 7549        | BATTERY                         | 07      | BATTERY          |             | \$96.33   |            |
|             |                                 |         |                  | Total Cost: | \$96.33   |            |
| Labor Cost: |                                 |         |                  |             |           |            |
| Craft       | Resource                        |         |                  |             |           |            |
| MECH        | 21                              | 07      | BATTERY          |             | \$77.00   |            |
|             |                                 |         |                  | Total Cost: | \$77.00   |            |
| 90589       | PM'S 105377 (525)               | PM      | Completed        | 1           | 2/16/2020 | 12/17/2020 |
| Part Cost:  |                                 |         |                  |             |           |            |
| Part ID     |                                 | Code ID | Code Description |             | Cost      |            |
| 21E520SB    | 5W20 FULL SYN QT                | PMA     |                  |             | \$15.61   |            |
| 100010      | OIL FILTER                      | PMA     |                  |             | \$3.29    |            |
|             |                                 |         |                  | Total Cost: | \$18.90   |            |
| Labor Cost: |                                 |         |                  |             |           |            |
| Craft       | Resource                        |         |                  |             |           |            |
| MECH        | 30                              | PMA     |                  |             | \$154.00  |            |
|             |                                 |         |                  | Total Cost: | \$154.00  |            |



|                       |                                   | Unit Wo | rk Order History |             |            |           |
|-----------------------|-----------------------------------|---------|------------------|-------------|------------|-----------|
| 90589                 | PM'S 105377 (525)                 | PM      | Completed        |             | 12/16/2020 | 12/17/202 |
| Part Cost:            |                                   |         |                  |             |            |           |
| Part ID               |                                   | Code ID | Code Description |             | Cost       |           |
| 003875MB              | 225/60WR18 FIRE MOUNTED           | 12      | TIRES            |             | \$144.20   |           |
|                       |                                   |         |                  | Total Cost: | \$144.20   |           |
| Labor Cost:           |                                   |         |                  |             |            |           |
| Craft                 | Resource                          |         |                  |             |            |           |
| MECH                  | 30                                | 12      | TIRES            |             | \$77.00    |           |
|                       |                                   |         |                  | Total Cost: | \$77.00    |           |
| 90897                 | PM'S 105377 (525), ENGINE TICKING | PM      | Completed        |             | 2/5/2021   | 2/12/202  |
| Part Cost:<br>Part ID |                                   | Code ID | Code Description |             | Cost       |           |
| 100010                | OIL FILTER                        | PMA     | ·                |             | \$3.29     |           |
| 21E520SB              | 5W20 FULL SYN QT                  | PMA     |                  |             | \$23.64    |           |
|                       | ·                                 |         |                  | Total Cost: | \$26.93    |           |
| Labor Cost:           |                                   |         |                  |             |            |           |
| Craft                 | Resource                          |         |                  |             |            |           |
| MECH                  | 32                                | PMA     |                  |             | \$115.50   |           |
|                       |                                   |         |                  | Total Cost: | \$115.50   |           |
| 90897                 | PM'S 105377 (525), ENGINE TICKING | PM      | Completed        |             | 2/5/2021   | 2/12/202  |
| Labor Cost:           |                                   |         |                  |             |            |           |
| Craft                 | Resource                          |         |                  |             |            |           |
| MECH                  | 32                                | 26      | ENGINE           |             | \$77.00    |           |
|                       |                                   |         |                  | Total Cost: | \$77.00    |           |
| 91059                 | REATTACH CAT 5 CABLE , 105377     | N       | Completed        |             | 3/2/2021   | 3/2/202   |
| Labor Cost:           |                                   |         |                  |             |            |           |

06



ELECTRICAL

Craft

MECH

Resource 30

Total Cost:

\$154.00

\$154.00

| <b>Unit Work Orde</b> | er History |  |
|-----------------------|------------|--|
|-----------------------|------------|--|

| 91149                 | PM'S 105377, SPOT LIGHT HANDLE BROKE<br>INSTALL BODY CAM MODULE                                   | , PM    | Completed          |             | 3/16/2021  | 3/16/202 |
|-----------------------|---|---------|--------------------|-------------|------------|----------|
| Part Cost:<br>Part ID |   | Code ID | Code Description   |             | Cost       |          |
| 21E520SB              | 5W20 FULL SYN QT  | PMA     |                    |             | \$27.58    |          |
| 011688MB              | 225/60WR18 FIRESTONE MOUNTED  | PMA     |                    |             | \$594.16   |          |
| 100010                | OIL FILTER  | PMA     | _                  |             | \$3.29     |          |
|                       |   |         |                    | Total Cost: | \$625.03   |          |
| Labor Cost:           |   |         |                    |             |            |          |
| Craft                 | Resource  |         |                    |             |            |          |
| MECH                  | 30  | PMA     |                    |             | \$154.00   |          |
|                       |   |         | ī                  | Total Cost: | \$154.00   |          |
| 91149                 | PM'S 105377, SPOT LIGHT HANDLE BROKE<br>INSTALL BODY CAM MODULE                                   | , PM    | Completed          |             | 3/16/2021  | 3/16/202 |
| Labor Cost:           |   |         |                    |             |            |          |
| Craft                 | Resource  | 0.5     | EL EGEDTONI        |             | +454.00    |          |
| MECH                  |   | 06      | ELECTRICAL         |             | \$154.00   |          |
| MECH                  | 30  | 06      | ELECTRICAL         |             | \$308.00   |          |
|                       |   |         |                    | Total Cost: | \$462.00   |          |
| 91429                 | INSTALL RADAR, INSTALL C54 DOCKING<br>STATION, CHECK BRAKES SQUEAK, CHECK<br>ENGINE LIGHT, 105377 | N       | Completed          |             | 4/23/2021  | 4/28/202 |
| Labor Cost:           |   |         |                    |             |            |          |
| Craft                 | Resource  |         |                    |             |            |          |
| MECH                  | 32  | VI      | VEHICLE ENHANCEMEN | NTS         | \$346.50   |          |
| MECH                  | 32  | VI      | VEHICLE ENHANCEMEN | NTS         | \$577.50   |          |
| MECH                  | 32  | VI      | VEHICLE ENHANCEMEN | NTS         | \$154.00   |          |
| MECH                  | 32  | VI      | VEHICLE ENHANCEMEN | NTS         | \$77.00    |          |
|                       |   |         | _                  | Fotal Cost: | \$1.155.00 |          |



|             |   | Unit Wo      | rk Order History |             |           |          |
|-------------|---|--------------|------------------|-------------|-----------|----------|
| 91429       | INSTALL RADAR, INSTALL C54 DOCKIN<br>STATION, CHECK BRAKES SQUEAK, CH<br>ENGINE LIGHT, 105377 | ig n<br>Ieck | Completed        |             | 4/23/2021 | 4/28/202 |
| Labor Cost: |   |              |                  |             |           |          |
| Craft       | Resource  |              | DD AVEC          |             | +100.50   |          |
| MECH        | 32  | 15           | BRAKES           |             | \$192.50  |          |
|             |   |              |                  | Total Cost: | \$192.50  |          |
| 91429       | INSTALL RADAR, INSTALL C54 DOCKIN<br>STATION, CHECK BRAKES SQUEAK, CH<br>ENGINE LIGHT, 105377 |              | Completed        |             | 4/23/2021 | 4/28/202 |
| Labor Cost: |   |              |                  |             |           |          |
| Craft       | Resource  |              |                  |             |           |          |
| MECH        | 32  | 16           | EMISSION SYSTEM  |             | \$77.00   |          |
|             |   |              |                  | Total Cost: | \$77.00   |          |
| 92188       | PM'S 105377 (525), CHECK ENGINE   | PM           | Completed        |             | 8/6/2021  | 8/12/20  |
| Part Cost:  |   |              |                  |             |           |          |
| Part ID     |   | Code ID      | Code Description |             | Cost      |          |
| 100010      | OIL FILTER  | 26           | ENGINE           |             | \$3.37    |          |
| 21E520SB    | 5W20 FULL SYN QT  | 26           | ENGINE           |             | \$23.64   |          |
|             |   |              |                  | Total Cost: | \$27.01   |          |
| Labor Cost: |   |              |                  |             |           |          |
| Craft       | Resource  |              |                  |             |           |          |
| MECH        | 32  | PMA          |                  |             | \$115.50  |          |
|             |   |              |                  | Total Cost: | \$115.50  |          |
| 92188       | PM'S 105377 (525), CHECK ENGINE   | PM           | Completed        |             | 8/6/2021  | 8/12/20  |
| Labor Cost: |   |              |                  |             |           |          |
| Craft       | Resource  |              |                  |             |           |          |
| MECH        | 32  | 16           | EMISSION SYSTEM  |             | \$308.00  |          |
|             |   |              |                  | Total Cost: | \$308.00  |          |



|                       |                                 | Unit Wo | rk Order History                |                |           |
|-----------------------|---------------------------------|---------|---------------------------------|----------------|-----------|
| 92188                 | PM'S 105377 (525), CHECK ENGINE | PM      | Completed                       | 8/6/2021       | 8/12/2021 |
| Labor Cost:           |                                 |         |                                 |                |           |
| Craft                 | Resource                        |         |                                 |                |           |
| MECH                  | 32                              | A03     | CHARGER COOLING FAN REPLACEMENT | \$231.00       |           |
|                       |                                 |         | Total C                         | Cost: \$231.00 |           |
| 92188                 | PM'S 105377 (525), CHECK ENGINE | PM      | Completed                       | 8/6/2021       | 8/12/202  |
| Part Cost:            |                                 |         |                                 |                |           |
| Part ID               |                                 | Code ID | Code Description                | Cost           |           |
| 194071                | PLUGS                           | 26      | ENGINE                          | \$29.28        |           |
| 9407                  | SPARK PLUG                      | 26      | ENGINE                          | \$11.36        |           |
| MS97205               | PLENUM GASKET                   | 26      | ENGINE                          | \$18.96        |           |
|                       |                                 |         | Total                           | Cost: \$59.60  |           |
| 92188                 | PM'S 105377 (525), CHECK ENGINE | PM      | Completed                       | 8/6/2021       | 8/12/202  |
| Part Cost:<br>Part ID |                                 | Code ID | Code Description                | Cost           |           |
| 99655771              | DUAL HD FAN ASSEMBLY            | 03      | COOLING SYSTEM                  | \$319.90       |           |
|                       |                                 |         | Total                           | <u> </u>       |           |
| 92188                 | PM'S 105377 (525), CHECK ENGINE | PM      | Completed                       | 8/6/2021       | 8/12/202  |
| Part Cost:            |                                 |         |                                 |                |           |
| Part ID               |                                 | Code ID | Code Description                | Cost           |           |
| M506                  | WASHER FLUID                    | 32      | GLASS / INTERIOR                | \$1.85         |           |
| NP21                  | WIPER BLADE                     | 32      | GLASS / INTERIOR                | \$3.30         |           |
| NP24                  | WIPER BLADE                     | 32      | GLASS / INTERIOR                | \$4.46         |           |
|                       |                                 |         | Total                           | Cost: \$9.61   |           |
| 92357                 | ARBITATOR INOP, 105377          | N       | Completed                       | 8/31/2021      | 8/31/202  |
| Labor Cost:           |                                 |         |                                 |                |           |
| Craft                 | Resource                        |         |                                 |                |           |
| MECH                  | 30                              | AR      | ARBITRATOR VIDEO SYSTEM         | \$77.00        |           |
|                       |                                 |         | Total C                         | Cost: \$77.00  |           |



|                       |                                 | Unit Wo | rk Order History                 |             |           |          |
|-----------------------|---------------------------------|---------|----------------------------------|-------------|-----------|----------|
| 92338                 | IS                              | PM      | Completed                        |             | 8/30/2021 | 9/3/202  |
| Part Cost:<br>Part ID |                                 | Code ID | Code Description                 |             | Cost      |          |
| 1RF14DX9AB            | VISOR CLIP                      | 29      | BODY / PAINT                     |             | \$19.58   |          |
|                       |                                 |         |                                  | Total Cost: | \$19.58   |          |
| 92535                 | PM'S 105377 (525) , ENGINE TICK | PM      | Completed                        |             | 9/27/2021 | 9/29/202 |
| Part Cost:            |                                 |         |                                  |             |           |          |
| Part ID               |                                 | Code ID | Code Description                 |             | Cost      |          |
| 99655771              | DUAL HD FAN ASSEMBLY            | A03     | CHARGER COOLING F<br>REPLACEMENT | AN          | \$319.90  |          |
|                       |                                 |         | •                                | Total Cost: | \$319.90  |          |
| Labor Cost:           |                                 |         |                                  |             |           |          |
| Craft                 | Resource                        |         |                                  |             |           |          |
| MECH                  | 21                              | A03     | CHARGER COOLING F<br>REPLACEMENT | AN          | \$154.00  |          |
|                       |                                 |         | •                                | Total Cost: | \$154.00  |          |
| 92535                 | PM'S 105377 (525) , ENGINE TICK | PM      | Completed                        |             | 9/27/2021 | 9/29/202 |
| Part Cost:            |                                 |         |                                  |             |           |          |
| Part ID               |                                 | Code ID | Code Description                 |             | Cost      |          |
| 21E520SB              | 5W20 FULL SYN QT                | PMA     |                                  |             | \$23.64   |          |
| 100010                | OIL FILTER                      | PMA     |                                  |             | \$3.49    |          |
|                       |                                 |         | •                                | Total Cost: | \$27.13   |          |
| Labor Cost:           |                                 |         |                                  |             |           |          |
| Craft                 | Resource                        |         |                                  |             |           |          |
| MECH                  | 21                              | PMA     |                                  |             | \$115.50  |          |
|                       |                                 |         | •                                | Total Cost: | \$115.50  |          |
| 92535                 | PM'S 105377 (525) , ENGINE TICK | PM      | Completed                        |             | 9/27/2021 | 9/29/202 |
| Labor Cost:           |                                 |         |                                  |             |           |          |
| Craft                 | Resource                        |         |                                  |             |           |          |
| MECH                  | 21                              | 26      | ENGINE                           |             | \$38.50   |          |
| TILCIT                |                                 |         |                                  |             |           |          |
| MECH                  | 21                              | 26      | ENGINE                           |             | \$115.50  |          |



| <b>Unit Work Order History</b> |
|--------------------------------|
|--------------------------------|

| 92535  | PM'S 105377 (525), ENGINE TICK           | PM                  | Completed  |             | 9/27/2021                          | 9/29/202 |
|--|--|---------------------|--|-------------|------------------------------------|----------|
| Part Cost:   |  |                     |  |             |                                    |          |
| Part ID  |  | Code ID             | Code Description                                     |             | Cost                               |          |
| M506   | WASHER FLUID                             | 32                  | GLASS / INTERIOR                                     |             | \$1.85                             |          |
| NP21   | WIPER BLADE                              | 32                  | GLASS / INTERIOR                                     |             | \$3.30                             |          |
| NP24   | WIPER BLADE                              | 32                  | GLASS / INTERIOR                                     |             | \$4.46                             |          |
|  |  |                     |  | Total Cost: | \$9.61                             |          |
| 92568  | ENGNE TICK , 105377                      | N                   | Completed  |             | 10/1/2021                          | 10/4/202 |
| Part Cost:   |  |                     |  |             |                                    |          |
| Part ID  |  | Code ID             | Code Description                                     |             | Cost                               |          |
| 29642  | PCV VALVE                                | 26                  | ENGINE   |             | \$32.82                            |          |
| 5184377AG  | EXHAUST CAMSHAFT                         | 26                  | ENGINE   |             | \$279.16                           |          |
| HT2313   | LIFTER                                   | 26                  | ENGINE   |             | \$28.86                            |          |
| 5184296AH  | ROCKER ARM                               | 26                  | ENGINE   |             | \$51.48                            |          |
|  |  |                     | -  | Total Cost: | \$392.32                           |          |
| Labor Cost:  |  |                     |  |             |                                    |          |
| Craft  | Resource                                 |                     |  |             | <u> </u>                           |          |
| MECH   | 21                                       | 26                  | ENGINE   |             | \$154.00                           |          |
| MECH   | 21                                       | 26                  | ENGINE -   |             | \$308.00                           |          |
|  |  |                     | -  | Total Cost: | \$462.00                           |          |
|  |  |                     |  |             |                                    |          |
| 92568  | ENGNE TICK , 105377                      | N                   | Completed  |             | 10/1/2021                          | 10/4/202 |
| Part Cost:   | ENGNE TICK , 105377                      |                     |  |             |                                    | 10/4/202 |
| Part Cost:<br>Part ID                                  |  | Code ID             | Code Description                                     |             | Cost                               | 10/4/202 |
| Part Cost: Part ID 357BPZ3                             | BATTERY                                  | Code ID<br>06       | Code Description ELECTRICAL                          |             | Cost<br>\$4.69                     | 10/4/202 |
| Part Cost: Part ID 357BPZ3 727650                      | BATTERY<br>HEAT SHRINK                   | Code ID<br>06<br>06 | Code Description  ELECTRICAL  ELECTRICAL             |             | \$4.69<br>\$1.24                   | 10/4/20  |
| Part ID<br>357BPZ3                                     | BATTERY                                  | Code ID<br>06       | Code Description  ELECTRICAL  ELECTRICAL  ELECTRICAL | Total Cost: | Cost<br>\$4.69                     | 10/4/20  |
| Part Cost: Part ID 357BPZ3 727650                      | BATTERY<br>HEAT SHRINK                   | Code ID<br>06<br>06 | Code Description  ELECTRICAL  ELECTRICAL  ELECTRICAL | Total Cost: | Cost<br>\$4.69<br>\$1.24<br>\$0.80 | 10/4/20  |
| Part Cost: Part ID  357BPZ3 727650 725111              | BATTERY<br>HEAT SHRINK                   | Code ID<br>06<br>06 | Code Description  ELECTRICAL  ELECTRICAL  ELECTRICAL | Total Cost: | Cost<br>\$4.69<br>\$1.24<br>\$0.80 | 10/4/202 |
| Part Cost: Part ID  357BPZ3 727650 725111  Labor Cost: | BATTERY<br>HEAT SHRINK<br>BUTT CONNECTOR | Code ID<br>06<br>06 | Code Description  ELECTRICAL  ELECTRICAL  ELECTRICAL | Total Cost: | Cost<br>\$4.69<br>\$1.24<br>\$0.80 | 10/4/202 |



|             | Unit Work Order History                |         |                  |                               |            |  |  |  |
|-------------|--|---------|------------------|-------------------------------|------------|--|--|--|
| 2770        | LF TIRE FLAT, 105377                   | N       | Completed        | 10/26/2021                    | 10/26/2021 |  |  |  |
| Labor Cost: |  |         |                  |                               |            |  |  |  |
| Craft       | Resource                               |         |                  |                               |            |  |  |  |
| MECH        | 21                                     | 12      | TIRES            | \$38.50<br>otal Cost: \$38.50 |            |  |  |  |
| 2829        | CHECK OVER FOR REASSIGNMENT , ID# 4892 | N       | Completed        | 11/4/2021                     | 11/5/2021  |  |  |  |
| Labor Cost: |  |         |                  |                               |            |  |  |  |
| Craft       | Resource                               |         |                  |                               |            |  |  |  |
| MECH        | 37                                     | 20      | CHANGE OUTS      | \$0.00                        |            |  |  |  |
| MECH        | 37                                     | A15     | CABIN AIR FILTER | \$0.00                        |            |  |  |  |
|             |  |         | To               | otal Cost: \$0.00             |            |  |  |  |
| 2829        | CHECK OVER FOR REASSIGNMENT , ID# 4892 | N       | Completed        | 11/4/2021                     | 11/5/202   |  |  |  |
| Part Cost:  |  |         |                  |                               |            |  |  |  |
| Part ID     |  | Code ID | Code Description | Cost                          |            |  |  |  |
| NP24        | WIPER BLADE                            | 32      | GLASS / INTERIOR | \$4.46                        |            |  |  |  |
| NP21        | WIPER BLADE                            | 32      | GLASS / INTERIOR | \$3.30                        |            |  |  |  |
| M506        | WASHER FLUID                           | 32      | GLASS / INTERIOR | \$1.85                        |            |  |  |  |
|             |  |         |                  | Fotal Cost: \$9.61            |            |  |  |  |
| 2829        | CHECK OVER FOR REASSIGNMENT , ID# 4892 | N       | Completed        | 11/4/2021                     | 11/5/2021  |  |  |  |
| Part Cost:  |  |         |                  |                               |            |  |  |  |
| Part ID     |  | Code ID | Code Description | Cost                          |            |  |  |  |
| 2608146     | LOWER CONTROL ARM                      | 44      | SUSPENSION       | \$148.72                      |            |  |  |  |
| 2607225     | C/A ASSY                               | 44      | SUSPENSION       | \$83.72                       |            |  |  |  |
| 2607226     | C/A ASSY                               | 44      | SUSPENSION       | \$83.72                       |            |  |  |  |
|             | ·                                      |         | 7                | Fotal Cost: \$316.16          |            |  |  |  |
| Labor Cost: | _                                      |         |                  |                               |            |  |  |  |
| Craft       | Resource                               | 44      | CLICDENCION      | ±0.00                         |            |  |  |  |
| MECH        | 37                                     | 44      | SUSPENSION       | \$0.00                        |            |  |  |  |
|             |  |         | To               | otal Cost: \$0.00             |            |  |  |  |



|               |   | Unit Wo | rk Order History |             |                  |           |
|---------------|---|---------|------------------|-------------|------------------|-----------|
| 92829         | CHECK OVER FOR REASSIGNMENT , ID# 4892            | N       | Completed        |             | 11/4/2021        | 11/5/202  |
| Part Cost:    |   |         |                  |             |                  |           |
| Part ID       |   | Code ID | Code Description |             | Cost             |           |
| 011688MB      | 225/60WR18 FIRESTONE MOUNTED                      | 12      | TIRES            |             | \$297.08         |           |
|               |   |         |                  | Total Cost: | \$297.08         |           |
| Labor Cost:   |   |         |                  |             |                  |           |
| Craft         | Resource  |         |                  |             |                  |           |
| MECH          | 37  | 12      | TIRES            | Total Cost: | \$0.00<br>\$0.00 |           |
|               |   |         |                  | Total Cost: | \$0.00           |           |
| 2829          | CHECK OVER FOR REASSIGNMENT , ID# 4892            | N       | Completed        |             | 11/4/2021        | 11/5/202  |
| Part Cost:    |   |         |                  |             |                  |           |
| Part ID       |   | Code ID | Code Description |             | Cost             |           |
| PMORAYKITAWWB | MINI LED  | 06      | ELECTRICAL       |             | \$108.90         |           |
| 727648        | HEAT SHRINK                                       | 06      | ELECTRICAL       |             | \$2.22           |           |
| 725103        | BUTT CONNECTOR                                    | 06      | ELECTRICAL       |             | \$0.45           |           |
|               |   |         |                  | Total Cost: | \$111.57         |           |
| Labor Cost:   |   |         |                  |             |                  |           |
| Craft         | Resource  |         |                  |             |                  |           |
| MECH          | 37  | 06      | ELECTRICAL       |             | \$0.00           |           |
|               |   |         |                  | Total Cost: | \$0.00           |           |
| 2829          | CHECK OVER FOR REASSIGNMENT , ID# 4892            | N       | Completed        |             | 11/4/2021        | 11/5/202  |
| Part Cost:    |   |         |                  |             |                  |           |
| Part ID       |   | Code ID | Code Description |             | Cost             |           |
| 6652874       | PUSH PIN  | 29      | BODY / PAINT     |             | \$3.88           |           |
|               |   |         |                  | Total Cost: | \$3.88           |           |
| 93101         | PM'S 105377 (525),CHECK ENGINE , WASI<br>SPRAYERS | HER PM  | Completed        |             | 12/20/2021       | 12/20/202 |



|                       |  | Unit Wo   | rk Order History |             |          |            |
|-----------------------|--|-----------|------------------|-------------|----------|------------|
| 93101                 | PM'S 105377 (525),CHECK ENGINE ,<br>SPRAYERS | WASHER PM | Completed        | 12/         | /20/2021 | 12/20/2021 |
| Part Cost:<br>Part ID |  | Code ID   | Code Description |             | Cost     |            |
| 100010                | OIL FILTER                                   | PMA       |                  |             | \$3.49   |            |
| 21E520SB              | 5W20 FULL SYN QT                             | PMA       |                  |             | \$23.64  |            |
|                       |  |           |                  | Total Cost: | \$27.13  |            |
| Labor Cost:           |  |           |                  |             |          |            |
| Craft                 | Resource                                     |           |                  |             |          |            |
| MECH                  | 21   | PMA       |                  |             | \$115.50 |            |
|                       |  |           |                  | Total Cost: | \$115.50 |            |
| 93101                 | PM'S 105377 (525),CHECK ENGINE ,<br>SPRAYERS | WASHER PM | Completed        | 12/         | /20/2021 | 12/20/2021 |
| Labor Cost:           |  |           |                  |             |          |            |
| Craft                 | Resource                                     |           |                  |             |          |            |
| MECH                  | 21   | 16        | EMISSION SYSTEM  |             | ¢115 50  |            |

| Part ID     |   | Code ID        | Code Description |             | Cost      |           |
|-------------|---|----------------|------------------|-------------|-----------|-----------|
| 100010      | OIL FILTER                                | PMA            |                  |             | \$3.49    |           |
| 21E520SB    | 5W20 FULL SYN QT                          | PMA            |                  |             | \$23.64   |           |
|             |   |                |                  | Total Cost: | \$27.13   |           |
| Labor Cost: |   |                |                  |             |           |           |
| Craft       | Resource                                  |                |                  |             |           |           |
| MECH        | 21  | PMA            |                  |             | \$115.50  |           |
|             |   |                |                  | Total Cost: | \$115.50  |           |
| 3101        | PM'S 105377 (525),CHECK ENGIN<br>SPRAYERS | IE , WASHER PM | Completed        | 1           | 2/20/2021 | 12/20/202 |
| Labor Cost: |   |                |                  |             |           |           |
| Craft       | Resource                                  |                |                  |             |           |           |
| MECH        | 21  | 16             | EMISSION SYSTEM  |             | \$115.50  |           |
|             |   |                |                  | Total Cost: | \$115.50  |           |
| 93101       | PM'S 105377 (525),CHECK ENGIN<br>SPRAYERS | IE , WASHER PM | Completed        | 1           | 2/20/2021 | 12/20/202 |
| Part Cost:  |   |                |                  |             |           |           |
| Part ID     |   | Code ID        | Code Description |             | Cost      |           |
| 68057740AD  | HOSE                                      | 32             | GLASS / INTERIOR |             | \$5.30    |           |
| 68239789AC  | NOZZLE                                    | 32             | GLASS / INTERIOR |             | \$75.84   |           |
| 68239794AE  | HOSE                                      | 32             | GLASS / INTERIOR |             | \$50.49   |           |
| NP21        | WIPER BLADE                               | 32             | GLASS / INTERIOR |             | \$3.30    |           |
| NP24        | WIPER BLADE                               | 32             | GLASS / INTERIOR |             | \$4.46    |           |
|             |   |                |                  | Total Cost: | \$139.39  |           |
| Labor Cost: |   |                |                  |             |           |           |
| Craft       | Resource                                  |                |                  |             |           |           |
| MECH        | 21  | 32             | GLASS / INTERIOR |             | \$77.00   |           |
|             |   |                |                  | Total Cost: | \$77.00   |           |

| 68239794AE  | HOSE        | 32 | GLASS / INTERIOR | \$50.49        |
|-------------|-------------|----|------------------|----------------|
| NP21        | WIPER BLADE | 32 | GLASS / INTERIOR | \$3.30         |
| NP24        | WIPER BLADE | 32 | GLASS / INTERIOR | \$4.46         |
|             |             |    | Total            | Cost: \$139.39 |
| Labor Cost: |             |    |                  |                |
| Craft       | Resource    |    |                  |                |
| MECH        | 21          | 32 | GLASS / INTERIOR | \$77.00        |
|             |             |    | Total            | Cost: \$77.00  |
|             |             |    |                  |                |



| Unit | Work | Order | History |
|------|------|-------|---------|
|------|------|-------|---------|

| 93101       | PM'S 105377 (525),CHECK ENGINE , WAS SPRAYERS | ASHER PM | Completed        | 12          | 2/20/2021 | 12/20/2021 |
|-------------|---|----------|------------------|-------------|-----------|------------|
| Part Cost:  |   | C   TD   | C   D   ' ''     |             | 6 1       |            |
| Part ID     |   | Code ID  | Code Description |             | Cost      |            |
| FT8997      | BRAKE PADS                                    | 15       | BRAKES           |             | \$52.44   |            |
|             |   |          |                  | Total Cost: | \$52.44   |            |
| Labor Cost: |   |          |                  |             |           |            |
| Craft       | Resource                                      |          |                  |             |           |            |
| MECH        | 21  | 15       | BRAKES           |             | \$115.50  |            |
| MECH        | 21  | 15       | BRAKES           |             | \$38.50   |            |
|             |   |          |                  | Total Cost: | \$154.00  |            |
| 93101       | PM'S 105377 (525),CHECK ENGINE , WASPRAYERS   | ASHER PM | Completed        | 12          | 2/20/2021 | 12/20/2021 |
| Labor Cost: |   |          |                  |             |           |            |
| Craft       | Resource                                      |          |                  |             |           |            |
| MECH        | 21  | 12       | TIRES            |             | \$77.00   |            |
|             |   |          |                  | Total Cost: | \$77.00   |            |
| 93115       | BRAKES , CHECK ENGINE LIGHT , TPMS<br>105377  | 5, N     | Completed        | 12          | 2/21/2021 | 12/30/2021 |
| Labor Cost: |   |          |                  |             |           |            |
| Craft       | Resource                                      |          |                  |             |           |            |
| MECH        | 21  | 16       | EMISSION SYSTEM  |             | \$115.50  |            |
| MECH        | 21  | 16       | EMISSION SYSTEM  |             | \$231.00  |            |
|             |   |          |                  | Total Cost: | \$346.50  |            |



|                             |   | Unit Wo | ork Order History |             |          |           |
|-----------------------------|---|---------|-------------------|-------------|----------|-----------|
| 3115                        | BRAKES , CHECK ENGINE LIGHT , TPMS , 105377 | N       | Completed         | 12          | /21/2021 | 12/30/202 |
| Part Cost:<br>Part ID       |   | Code ID | Code Description  |             | Cost     |           |
| FT8998                      | DISC PAD                                    | 15      | BRAKES            |             | \$53.25  |           |
| FT881774                    | ROTOR                                       | 15      | BRAKES            |             | \$170.70 |           |
|                             |   |         |                   | Total Cost: | \$223.95 |           |
| <b>Labor Cost:</b><br>Craft | Resource                                    |         |                   |             |          |           |
| MECH                        | 21  | 15      | BRAKES            |             | \$192.50 |           |
|                             |   |         |                   | Total Cost: | \$192.50 |           |
| 3115                        | BRAKES , CHECK ENGINE LIGHT , TPMS , 105377 | N       | Completed         | 12          | /21/2021 | 12/30/202 |
| Part Cost:                  |   |         |                   |             |          |           |
| Part ID                     |   | Code ID | Code Description  |             | Cost     |           |
| 011688MB                    | 225/60WR18 FIRESTONE MOUNTED                | 12      | TIRES             |             | \$163.69 |           |
|                             |   |         |                   | Total Cost: | \$163.69 |           |
| Labor Cost:                 |   |         |                   |             |          |           |
| Craft                       | Resource                                    |         |                   |             |          |           |
| MECH                        | 12  | 12      | TIRES             |             | \$115.50 |           |



\$115.50

Total Cost:

|                    |   | Unit Wo | ork Order History |             |            |            |
|--------------------|---|---------|-------------------|-------------|------------|------------|
| 93115              | BRAKES , CHECK ENGINE LIGHT , TPMS , 105377 | N       | Completed         |             | 12/21/2021 | 12/30/2021 |
| Part Cost: Part ID |   | Code ID | Code Description  |             | Cost       |            |
| 926235             | SOLEINOLD                                   | 26      | ENGINE            |             | \$48.50    |            |
| 5149062AB          | SWITCH                                      | 26      | ENGINE            |             | \$38.06    |            |
| 7651589            | GASKET                                      | 26      | ENGINE            |             | \$5.82     |            |
| 725254             | BUTT CONNECTOR                              | 26      | ENGINE            |             | \$4.14     |            |
| 4800BC             | BRAKE CLEANER                               | 26      | ENGINE            |             | \$19.28    |            |
|                    |   |         |                   | Total Cost: | \$115.80   |            |
| Labor Cost:        |   |         |                   |             |            |            |
| Craft              | Resource                                    | 26      | ENGINE            |             | #24C F0    |            |
| MECH               | 21  | 20      | ENGINE            | T-t-I Ct-   | \$346.50   |            |
|                    |   |         |                   | Total Cost: | \$346.50   |            |
| 93161              | REPLACE RADIO,105377                        | N       | Completed         |             | 1/3/2022   | 1/6/2022   |
| Labor Cost:        |   |         |                   |             |            |            |
| Craft              | Resource                                    |         |                   |             |            |            |
| MECH               | 33  | 30      | ELECTRONICS       |             | \$269.50   |            |
|                    |   |         |                   | Total Cost: | \$269.50   |            |
| 93161              | REPLACE RADIO,105377                        | N       | Completed         |             | 1/3/2022   | 1/6/2022   |
| Part Cost:         |   |         |                   |             |            |            |
| Part ID            |   | Code ID | Code Description  |             | Cost       |            |
| 725105             | BUTT CONNECTOR                              | 06      | ELECTRICAL        |             | \$1.20     |            |
| 725111             | BUTT CONNECTOR                              | 06      | ELECTRICAL        |             | \$2.52     |            |

06



ELECTRICAL

728098

CONNECTOR

Total Cost:

\$1.36 \$5.08

|                             |  | Unit Wo | rk Order History        |             |           |          |
|-----------------------------|--|---------|-------------------------|-------------|-----------|----------|
| 93293                       | BOTH PASSENGER TIRES HAVE LEAKS,<br>105377             | N       | Completed               |             | 1/21/2022 | 1/21/202 |
| Labor Cost:                 |  |         |                         |             |           |          |
| Craft                       | Resource   |         |                         |             |           |          |
| MECH                        | 33   | 12      | TIRES                   |             | \$77.00   |          |
|                             |  |         |                         | Total Cost: | \$77.00   |          |
| 93785                       | PM'S 105377 (525), DOME LIGHT OUT ,<br>ARBITRATOR INOP | PM      | Completed               |             | 4/1/2022  | 4/1/202  |
| Part Cost:<br>Part ID       |  | Code ID | Code Description        |             | Cost      |          |
| 21E520SB                    | 5W20 FULL SYN QT                                       | PMA     |                         |             | \$23.64   |          |
| 100010                      | OIL FILTER   | PMA     |                         |             | \$3.73    |          |
|                             |  |         |                         | Total Cost: | \$27.37   |          |
| <b>Labor Cost:</b><br>Craft | Resource   |         |                         |             |           |          |
| MECH                        | 37   | PMA     |                         |             | \$0.00    |          |
|                             |  |         |                         | Total Cost: | \$0.00    |          |
| 93785                       | PM'S 105377 (525), DOME LIGHT OUT ,<br>ARBITRATOR INOP | PM      | Completed               |             | 4/1/2022  | 4/1/202  |
| Part Cost:                  |  |         |                         |             |           |          |
| Part ID                     |  | Code ID | Code Description        |             | Cost      |          |
| 17314N                      | BULB   | 06      | ELECTRICAL              |             | \$0.59    |          |
|                             |  |         |                         | Total Cost: | \$0.59    |          |
| 93785                       | PM'S 105377 (525), DOME LIGHT OUT ,<br>ARBITRATOR INOP | PM      | Completed               |             | 4/1/2022  | 4/1/202  |
| Labor Cost:                 |  |         |                         |             |           |          |
| Craft                       | Resource   |         |                         |             |           |          |
| MECH                        | 37   | AR      | ARBITRATOR VIDEO SYSTEM |             | \$0.00    |          |
|                             |  |         |                         | Total Cost: | \$0.00    |          |



|                       |  | Unit Wo | rk Order History |             |           |          |
|-----------------------|--|---------|------------------|-------------|-----------|----------|
| 93785                 | PM'S 105377 (525), DOME LIGHT OUT ,<br>ARBITRATOR INOP | PM      | Completed        |             | 4/1/2022  | 4/1/2022 |
| Part Cost:<br>Part ID |  | Code ID | Code Description |             | Cost      |          |
| 011688MB              | 225/60WR18 FIRESTONE MOUNTED                           | 12      | TIRES            |             | \$598.56  |          |
|                       | ·  |         |                  | Total Cost: | \$598.56  |          |
| Labor Cost:           |  |         |                  |             |           |          |
| Craft                 | Resource   |         |                  |             |           |          |
| MECH                  | 37   | 12      | TIRES            |             | \$0.00    |          |
|                       |  |         |                  | Total Cost: | \$0.00    |          |
| 93785                 | PM'S 105377 (525), DOME LIGHT OUT ,<br>ARBITRATOR INOP | РМ      | Completed        |             | 4/1/2022  | 4/1/202  |
| Part Cost:            |  |         |                  |             |           |          |
| Part ID               |  | Code ID | Code Description |             | Cost      |          |
| M506                  | WASHER FLUID   | 32      | GLASS / INTERIOR |             | \$2.40    |          |
| NP21                  | WIPER BLADE  | 32      | GLASS / INTERIOR |             | \$3.30    |          |
| NP24                  | WIPER BLADE  | 32      | GLASS / INTERIOR |             | \$4.46    |          |
|                       |  |         |                  | Total Cost: | \$10.16   |          |
| 94081                 | PM'S 105377 , BATTERY WILL NOT HOLD CHARGE             | PM      | Completed        |             | 5/16/2022 | 5/16/202 |
| Part Cost:            |  |         |                  |             |           |          |
| Part ID               |  | Code ID | Code Description |             | Cost      |          |
| 21E520SB              | 5W20 FULL SYN QT                                       | PMA     |                  |             | \$3.94    |          |
| 100010                | OIL FILTER   | PMA     |                  |             | \$3.95    |          |
|                       |  |         |                  | Total Cost: | \$7.89    |          |
| Labor Cost:           |  |         |                  |             |           |          |
| Craft                 | Resource   |         |                  |             |           |          |
| MECH                  | 12   | PMA     |                  |             | \$115.50  |          |
|                       |  |         |                  | Total Cost: | \$115.50  |          |



|             |  | Unit Wo | rk Order History |             |           |           |
|-------------|--|---------|------------------|-------------|-----------|-----------|
| 94081       | PM'S 105377 , BATTERY WILL NOT HOLD CHARGE | РМ      | Completed        |             | 5/16/2022 | 5/16/2022 |
| Part Cost:  |  |         |                  |             |           |           |
| Part ID     |  | Code ID | Code Description |             | Cost      |           |
| 7549        | BATTERY                                    | 07      | BATTERY          |             | \$107.16  |           |
|             |  |         |                  | Total Cost: | \$107.16  |           |
| Labor Cost: |  |         |                  |             |           |           |
| Craft       | Resource                                   |         |                  |             |           |           |
| MECH        | 12   | 07      | BATTERY          |             | \$57.75   |           |
|             |  |         |                  | Total Cost: | \$57.75   |           |
| 94081       | PM'S 105377 , BATTERY WILL NOT HOLD CHARGE | РМ      | Completed        |             | 5/16/2022 | 5/16/2022 |
| Part Cost:  |  |         |                  |             |           |           |
| Part ID     |  | Code ID | Code Description |             | Cost      |           |
| M506        | WASHER FLUID                               | 32      | GLASS / INTERIOR |             | \$2.40    |           |
|             |  |         |                  | Total Cost: | \$2.40    |           |
| 94081       | PM'S 105377 , BATTERY WILL NOT HOLD CHARGE | PM      | Completed        |             | 5/16/2022 | 5/16/2022 |
| Labor Cost: |  |         |                  |             |           |           |
| Craft       | Resource                                   |         |                  |             |           |           |
| MECH        | 12   | L       | LABOR            |             | \$38.50   |           |
|             |  |         |                  | Total Cost: | \$38.50   |           |
| 94081       | PM'S 105377 , BATTERY WILL NOT HOLD CHARGE | РМ      | Completed        |             | 5/16/2022 | 5/16/2022 |
| Part Cost:  |  |         |                  |             |           |           |
| Part ID     |  | Code ID | Code Description |             | Cost      |           |
| 4048        | CABIN AIR FILTER DODGE                     | A15     | CABIN AIR FILTER |             | \$8.30    |           |
|             |  |         |                  | Total Cost: | \$8.30    |           |
| Labor Cost: |  |         |                  |             |           |           |
| Craft       | Resource                                   |         |                  |             |           |           |
| MECH        | 12   | A15     | CABIN AIR FILTER |             | \$19.25   |           |
|             |  |         |                  |             |           |           |



4/8/2025 12:17:39 PM

| Unit Work Order Histo | orv |
|-----------------------|-----|
|-----------------------|-----|

| 4426        | PMS, ENGINE TICK, CHECK TIRES, 105377 | PM      | Completed        |             | 7/6/2022 | 7/8/202 |
|-------------|---------------------------------------|---------|------------------|-------------|----------|---------|
| Part Cost:  |                                       |         |                  |             |          |         |
| Part ID     |                                       | Code ID | Code Description |             | Cost     |         |
| 100010      | OIL FILTER                            | PMA     |                  |             | \$3.95   |         |
| 21E520SB    | 5W20 FULL SYN QT                      | PMA     |                  |             | \$23.64  |         |
|             |                                       |         |                  | Total Cost: | \$27.59  |         |
| Labor Cost: |                                       |         |                  |             |          |         |
| Craft       | Resource                              |         |                  |             |          |         |
| MECH        | 37                                    | PMA     |                  |             | \$0.00   |         |
|             |                                       |         |                  | Total Cost: | \$0.00   |         |
| 4426        | PMS, ENGINE TICK, CHECK TIRES, 105377 | PM      | Completed        |             | 7/6/2022 | 7/8/20  |
| Part Cost:  |                                       |         |                  |             |          |         |
| Part ID     |                                       | Code ID | Code Description |             | Cost     |         |
| 29642       | PCV VALVE                             | 26      | ENGINE           |             | \$35.23  |         |
| VS50805R    | VALVE COVER GASKET                    | 26      | ENGINE           |             | \$65.77  |         |
| 5184296AH   | ROCKER ARM                            | 26      | ENGINE           |             | \$21.18  |         |
|             |                                       |         |                  | Total Cost: | \$122.18 |         |
| Labor Cost: |                                       |         |                  |             |          |         |
| Craft       | Resource                              |         |                  |             |          |         |
| MECH        | 37                                    | 26      | ENGINE           |             | \$0.00   |         |
| MECH        | 37                                    | 26      | ENGINE           |             | \$0.00   |         |
|             |                                       |         |                  | Total Cost: | \$0.00   |         |
| 4426        | PMS, ENGINE TICK, CHECK TIRES, 105377 | PM      | Completed        |             | 7/6/2022 | 7/8/20  |
| Part Cost:  |                                       |         |                  |             |          |         |
| Part ID     |                                       | Code ID | Code Description |             | Cost     |         |
| 011688MB    | 225/60WR18 FIRESTONE MOUNTED          | 12      | TIRES            |             | \$302.44 |         |
|             |                                       |         |                  | Total Cost: | \$302.44 |         |
| Labor Cost: |                                       |         |                  |             |          |         |
| Craft       | Resource                              |         |                  |             |          |         |
| MECH        | 37                                    | 12      | TIRES            |             | \$0.00   |         |
|             |                                       |         |                  | Total Cost: | \$0.00   |         |



| 426         | PMS, ENGINE TICK, CHECK TIRES, 105377 | PM      | Completed        | •           | 7/6/2022 | 7/8/202 |
|-------------|---------------------------------------|---------|------------------|-------------|----------|---------|
| Part Cost:  |                                       |         |                  |             |          |         |
| Part ID     |                                       | Code ID | Code Description |             | Cost     |         |
| 5278767AB   | CAP                                   | 03      | COOLING SYSTEM   |             | \$12.87  |         |
| AFC10100    | 50/50 ANTIFREEZE                      | 03      | COOLING SYSTEM   |             | \$7.56   |         |
| 55038163AI  | HOSE                                  | 03      | COOLING SYSTEM   |             | \$128.73 |         |
| AFC10100    | 50/50 ANTIFREEZE                      | 03      | COOLING SYSTEM   |             | \$15.12  |         |
| HT203248    | THERMOSTAT                            | 03      | COOLING SYSTEM   |             | \$16.83  |         |
|             |                                       |         | -                | Total Cost: | \$181.11 |         |
| Labor Cost: |                                       |         |                  |             |          |         |
| Craft       | Resource                              |         |                  |             | <u> </u> |         |
| MECH        |                                       | 03      | COOLING SYSTEM   |             | \$0.00   |         |
| MECH        |                                       | 03      | COOLING SYSTEM   |             | \$0.00   |         |
| MECH        | 37                                    | 03      | COOLING SYSTEM   |             | \$0.00   |         |
|             |                                       |         | ٦                | Total Cost: | \$0.00   |         |
| 426         | PMS, ENGINE TICK, CHECK TIRES, 105377 | PM      | Completed        | •           | 7/6/2022 | 7/8/20  |
| Part Cost:  |                                       |         |                  |             |          |         |
| Part ID     |                                       | Code ID | Code Description |             | Cost     |         |
| 2605522     | CONTROL ARM                           | 44      | SUSPENSION       |             | \$112.74 |         |
| 2605521     | CONTROL ARM                           | 44      | SUSPENSION       |             | \$112.74 |         |
| 772665      | STRUT                                 | 44      | SUSPENSION       |             | \$412.42 |         |
|             |                                       |         | -                | Total Cost: | \$637.90 |         |
| Labor Cost: |                                       |         |                  |             |          |         |
| Craft       | Resource                              |         |                  |             |          |         |
| MECH        |                                       | 44      | SUSPENSION       |             | \$0.00   |         |
| MECH        | 37                                    | 44      | SUSPENSION       |             | \$0.00   |         |
|             |                                       |         | 7                | Total Cost: | \$0.00   |         |



| 4571        | PM'S, OVERHEATING, CHECK TPMS, 525 | N       | Completed        |             | 7/25/2022 | 7/26/202 |
|-------------|------------------------------------|---------|------------------|-------------|-----------|----------|
| Part Cost:  |                                    |         |                  |             |           |          |
| Part ID     |                                    | Code ID | Code Description |             | Cost      |          |
| 5184977AH   | THERMOSTAT                         | 03      | COOLING SYSTEM   |             | \$37.10   |          |
|             |                                    |         |                  | Total Cost: | \$37.10   |          |
| Labor Cost: |                                    |         |                  |             |           |          |
| Craft       | Resource                           |         |                  |             |           |          |
| MECH        | 21                                 | 03      | COOLING SYSTEM   |             | \$192.50  |          |
|             |                                    |         |                  | Total Cost: | \$192.50  |          |
| 4571        | PM'S, OVERHEATING, CHECK TPMS, 525 | N       | Completed        |             | 7/25/2022 | 7/26/202 |
| Part Cost:  |                                    |         |                  |             |           |          |
| Part ID     |                                    | Code ID | Code Description |             | Cost      |          |
| 921175C     | TMPS SENSOR                        |         |                  |             | \$49.87   |          |
|             |                                    |         |                  | Total Cost: | \$49.87   |          |
| Labor Cost: |                                    |         |                  |             |           |          |
| Craft       | Resource                           |         |                  |             |           |          |
| MECH        | 21                                 | 12      | TIRES            |             | \$77.00   |          |
|             |                                    |         |                  | Total Cost: | \$77.00   |          |
| 4571        | PM'S, OVERHEATING, CHECK TPMS, 525 | N       | Completed        |             | 7/25/2022 | 7/26/202 |
| Part Cost:  |                                    |         |                  |             |           |          |
| Part ID     |                                    | Code ID | Code Description |             | Cost      |          |
| 21E520SB    | 5W20 FULL SYN QT                   | PMA     |                  |             | \$23.64   |          |
| 100010      | OIL FILTER                         | PMA     |                  |             | \$4.19    |          |
|             |                                    |         |                  | Total Cost: | \$27.83   |          |
| Labor Cost: |                                    |         |                  |             |           |          |
| Craft       | Resource                           |         |                  |             |           |          |
| MECH        | 21                                 | PMA     |                  |             | \$115.50  |          |
| MECH        | <del></del>                        |         |                  |             | 4         |          |



|                       |  | Unit Wo    | rk Order History |            |                      |           |
|-----------------------|--|------------|------------------|------------|----------------------|-----------|
| 94571                 | PM'S, OVERHEATING, CHECK TPMS, 525                                       | N          | Completed        |            | 7/25/2022            | 7/26/2022 |
| Part Cost:            |  |            |                  |            |                      |           |
| Part ID               |  | Code ID    | Code Description |            | Cost                 |           |
| 801651                | PAG 46 OIL   | 05         | AIR CONDITIONING |            | \$6.07               |           |
|                       |  |            | To               | otal Cost: | \$6.07               |           |
| 94714                 | OVERHEATING , 105377   | N          | Completed        |            | 8/11/2022            | 8/11/2022 |
| Part Cost:            |  |            |                  |            |                      |           |
| Part ID               |  | Code ID    | Code Description |            | Cost                 |           |
| AFC10100              | 50/50 ANTIFREEZE   | 03         | COOLING SYSTEM   |            | \$7.56               |           |
|                       |  |            | To               | otal Cost: | \$7.56               |           |
| Labor Cost:           |  |            |                  |            |                      |           |
| Craft                 | Resource   |            |                  |            |                      |           |
| MECH                  | 33   | 03         | COOLING SYSTEM   |            | \$77.00              |           |
|                       |  |            | Tot              | tal Cost:  | \$77.00              |           |
| 5082                  | PM'S 105377 (525), POWER STEERING<br>STICKS , DOOR LOCK INOP, ENGINE TIC | PM<br>KING | Completed        |            | 10/3/2022            | 10/7/2022 |
| Part Cost:<br>Part ID |  | Code ID    | Code Description |            | Cost                 |           |
| 21E530SB              | 5W30 FULL SYN QT   | PMA        |                  |            | \$13.44              |           |
| 100010                | OIL FILTER   | PMA        |                  |            | \$4.19               |           |
|                       |  |            | To               | otal Cost: | \$17.63              |           |
| Labor Cost:           |  |            |                  |            |                      |           |
| Craft                 | Resource<br>33   | PMA        |                  |            | #11F F0              |           |
| MECH                  | 33   | PMA        | Tot              | tal Cost:  | \$115.50<br>\$115.50 |           |
|                       |  |            | 100              |            |                      |           |
| 95082                 | PM'S 105377 (525), POWER STEERING<br>STICKS , DOOR LOCK INOP, ENGINE TIC | PM<br>KING | Completed        |            | 10/3/2022            | 10/7/2022 |
| Labor Cost:           |  |            |                  |            |                      |           |
| Craft                 | Resource   |            |                  |            | 150.50               |           |
| MECH                  | 33   | 35         | STEERING         |            | \$38.50              |           |
|                       |  |            | Tot              | tal Cost:  | \$38.50              |           |



|                       |  | Unit Wo     | rk Order History |                                |          |
|-----------------------|--|-------------|------------------|--------------------------------|----------|
| 5082                  | PM'S 105377 (525), POWER STEERING<br>STICKS , DOOR LOCK INOP, ENGINE TIC | PM<br>CKING | Completed        | 10/3/2022                      | 10/7/202 |
| Labor Cost:           |  |             |                  |                                |          |
| Craft                 | Resource   |             |                  |                                |          |
| MECH                  | 33   | 06          | ELECTRICAL       | \$57.75                        |          |
| MECH                  | 33   | 06          | ELECTRICAL       | \$38.50<br>Total Cost: \$96.25 |          |
| 5082                  | PM'S 105377 (525), POWER STEERING<br>STICKS , DOOR LOCK INOP, ENGINE TIC | PM<br>CKING | Completed        | 10/3/2022                      | 10/7/202 |
| Part Cost:<br>Part ID |  | Code ID     | Code Description | Cost                           |          |
| VS50805R              | VALVE COVER GASKET   | 26          | ENGINE           | \$67.35                        |          |
| 38082                 | IDLER PULLEY   | 26          | ENGINE           | \$26.91                        |          |
| 29642                 | PCV VALVE  | 26          | ENGINE           | \$44.37                        |          |
| 29746                 | AIR FILTER   | 26          | ENGINE           | \$13.35                        |          |
| 7041929               | OIL DRAIN PLUG   | 26          | ENGINE           | \$3.96                         |          |
| 6511905AA             | NUT  | 26          | ENGINE           | \$63.60                        |          |
| 4593955AA             | CUSHION  | 26          | ENGINE           | \$48.19                        |          |
|                       |  |             |                  | Total Cost: \$267.73           |          |
| Labor Cost:           | Description  |             |                  |                                |          |
| Craft<br>MECH         | Resource<br>33   | 26          | ENGINE           | \$154.00                       |          |
| MECH                  | 33   | 26          | ENGINE           | \$154.00                       |          |
| MECH                  | 33   | 26          | ENGINE           | \$77.00                        |          |
| 112011                | 55   | 20          |                  | Total Cost: \$385.00           |          |
| 5082                  | PM'S 105377 (525), POWER STEERING<br>STICKS , DOOR LOCK INOP, ENGINE TIC | PM<br>CKING | Completed        | 10/3/2022                      | 10/7/202 |
| Part Cost:            |  |             |                  |                                |          |
| Part ID               |  | Code ID     | Code Description | Cost                           |          |
| M506                  | WASHER FLUID   | 32          | GLASS / INTERIOR | \$2.40                         |          |
|                       |  |             |                  | Total Cost: \$2.40             |          |



|   |   | 11:4 34/-    | l. Od.a 11:a4                        |             |   |           |
|---|---|--------------|--------------------------------------|-------------|---|-----------|
|   |   | Unit wo      | rk Order History                     |             |   |           |
| 5082  | PM'S 105377 (525), POWER STEERING<br>STICKS , DOOR LOCK INOP, ENGINE TICK | PM<br>(ING   | Completed                            | 10/         | /3/2022   | 10/7/2022 |
| Labor Cost:   |   |              |                                      |             |   |           |
| Craft   | Resource  |              |                                      |             |   |           |
| MECH  | 33  | 12           | TIRES                                |             | \$38.50   |           |
|   |   |              |                                      | Total Cost: | \$38.50   |           |
| 5764  | VIBRATES AND SHAKES , TPMS, 105377<br>DETAIL                              | N            | Completed                            | 1/1         | 7/2023  | 1/18/202  |
| Part Cost:  |   |              |                                      |             |   |           |
| Part ID   |   | Code ID      | Code Description                     |             | Cost  |           |
| 011688MB  | 225/60WR18 FIRESTONE MOUNTED  | 12           | TIRES                                |             | \$298.54  |           |
|   |   |              |                                      | Total Cost: | \$298.54  |           |
| Labor Cost:   |   |              |                                      |             |   |           |
|   | Pocourco  |              |                                      |             |   |           |
| Craft   | Resource  | 12           | TIDES                                |             | \$0.00  |           |
|   | Resource<br>37  | 12           | TIRES                                | Total Costs | \$0.00  |           |
| Craft<br>MECH   |   | 12           | TIRES                                | Total Cost: | \$0.00<br>\$0.00                                      |           |
| Craft   |   | 12<br>N      | TIRES Completed                      |             |   | 1/18/202  |
| Craft<br>MECH   | 37 VIBRATES AND SHAKES , TPMS, 105377                                     |              |                                      |             | \$0.00  | 1/18/202  |
| Craft MECH 5764   | 37 VIBRATES AND SHAKES , TPMS, 105377                                     |              |                                      |             | \$0.00  | 1/18/202  |
| Craft MECH  5764  Part Cost:                                      | 37 VIBRATES AND SHAKES , TPMS, 105377                                     | N            | Completed                            |             | \$0.00  | 1/18/202  |
| Craft MECH  5764  Part Cost: Part ID                              | 37 VIBRATES AND SHAKES , TPMS, 105377 DETAIL                              | N<br>Code ID | Completed  Code Description          |             | \$0.00<br>7/2023<br>Cost                              | 1/18/202  |
| Craft MECH  5764  Part Cost: Part ID  7549                        | 37 VIBRATES AND SHAKES , TPMS, 105377 DETAIL BATTERY                      | N Code ID 07 | Completed  Code Description  BATTERY |             | \$0.00<br>7/2023<br>Cost<br>\$109.76                  | 1/18/202  |
| Craft MECH  5764  Part Cost: Part ID  7549                        | 37 VIBRATES AND SHAKES , TPMS, 105377 DETAIL BATTERY                      | N Code ID 07 | Completed  Code Description  BATTERY | 1/1         | \$0.00<br>7/2023<br><u>Cost</u><br>\$109.76<br>\$4.73 | 1/18/202  |
| Craft MECH  5764  Part Cost: Part ID  7549 ECR2032BP              | 37 VIBRATES AND SHAKES , TPMS, 105377 DETAIL BATTERY                      | N Code ID 07 | Completed  Code Description  BATTERY | 1/1         | \$0.00<br>7/2023<br><u>Cost</u><br>\$109.76<br>\$4.73 | 1/18/202  |
| Craft MECH  5764  Part Cost: Part ID  7549 ECR2032BP  Labor Cost: | VIBRATES AND SHAKES , TPMS, 105377 DETAIL  BATTERY BATTERY                | N Code ID 07 | Completed  Code Description  BATTERY | 1/1         | \$0.00<br>7/2023<br><u>Cost</u><br>\$109.76<br>\$4.73 | 1/18/202  |



| CHECK OVER FOR REASSIGNAPER #,S  Resource  33  CHECK OVER FOR REASSIGNAPER #,S  5W20 SYN OIL  BRAKE CLEANER  INTAKE MANIFOLD  OIL COOLER | NMENT, NEW N                     | CHANGE OUTS  Completed  Change Outs  Completed  Code Description  ENGINE  ENGINE  ENGINE  ENGINE | Total Cost:   | \$77.00<br>\$77.00<br>\$77.00<br>/28/2023<br>Cost<br>\$7.14<br>\$2.41         | 5/1/20                            |
|--|----------------------------------|--|---|---|-----------------------------------|
| Resource 33 CHECK OVER FOR REASSIGN MPER #,S  5W20 SYN OIL BRAKE CLEANER INTAKE MANIFOLD   | 20  NMENT, NEW N  Code ID  26 26 | CHANGE OUTS  Completed  Code Description ENGINE ENGINE   | Total Cost:   | \$77.00<br>\$77.00<br>/28/2023<br>Cost<br>\$7.14<br>\$2.41                    |                                   |
| 33 CHECK OVER FOR REASSIGNAPER #,S  5W20 SYN OIL BRAKE CLEANER INTAKE MANIFOLD   | NMENT, NEW N  Code ID  26  26    | Completed  Code Description  ENGINE  ENGINE  |   | \$77.00<br>/28/2023<br>Cost<br>\$7.14<br>\$2.41                               | 5/1/20                            |
| 33 CHECK OVER FOR REASSIGNAPER #,S  5W20 SYN OIL BRAKE CLEANER INTAKE MANIFOLD   | NMENT, NEW N  Code ID  26  26    | Completed  Code Description  ENGINE  ENGINE  |   | \$77.00<br>/28/2023<br>Cost<br>\$7.14<br>\$2.41                               | 5/1/20                            |
| CHECK OVER FOR REASSIGN<br>MPER #,S<br>5W20 SYN OIL<br>BRAKE CLEANER<br>INTAKE MANIFOLD  | NMENT, NEW N  Code ID  26  26    | Completed  Code Description  ENGINE  ENGINE  |   | \$77.00<br>/28/2023<br>Cost<br>\$7.14<br>\$2.41                               | 5/1/20                            |
| 5W20 SYN OIL BRAKE CLEANER INTAKE MANIFOLD   | Code ID<br>26<br>26              | Code Description ENGINE ENGINE   | 4.  | \$7.14<br>\$2.41  | 5/1/20                            |
| BRAKE CLEANER INTAKE MANIFOLD  | 26<br>26                         | ENGINE<br>ENGINE   |   | \$7.14<br>\$2.41  |                                   |
| BRAKE CLEANER INTAKE MANIFOLD  | 26                               | ENGINE   |   | \$2.41  |                                   |
| INTAKE MANIFOLD  |                                  |  |   | \$2.41  |                                   |
| INTAKE MANIFOLD  |                                  |  |   | ·   |                                   |
|  |                                  |  |   | \$33.94   |                                   |
| OIL COOLEK   | 26                               | ENGINE   |   | \$206.94  |                                   |
|  |                                  |  | Total Cost:   | \$250.43  |                                   |
|  |                                  |  |   |   |                                   |
| Resource   |                                  |  |   |   |                                   |
| 33   | 26                               | ENGINE   |   | \$192.50  |                                   |
|  |                                  |  | Total Cost:   | \$192.50  |                                   |
| CHECK OVER FOR REASSIGN  | NMENT, NEW N                     | Completed  | 4.  | /28/2023  | 5/1/20                            |
|  |                                  |  |   |   |                                   |
|  | Code ID                          | Code Description   |   | Cost  |                                   |
| BUTT CONNECTOR   | 06                               | ELECTRICAL   |   | \$8.60  |                                   |
|  |                                  |  | Total Cost:   | \$8.60  |                                   |
|  |                                  |  |   |   |                                   |
|  | 06                               | FLECTRICAL   |   | #1F4 00   |                                   |
| 33   | Ub                               | ELECTRICAL   | <del></del>   | <u> </u>  |                                   |
|  | MPER #,S                         | Code ID  BUTT CONNECTOR 06  Resource   | Code ID Code Description BUTT CONNECTOR 06 ELECTRICAL  Resource | Code ID Code Description  BUTT CONNECTOR 06 ELECTRICAL  Total Cost:  Resource | Code ID   Code Description   Cost |



|                      |                                 | Unit Wo  | ork Order History |             |           |           |
|----------------------|---------------------------------|----------|-------------------|-------------|-----------|-----------|
| 96425                | MAY 2023 SERVICE TICKET         | N        | Completed         |             | 5/1/2023  | 5/31/2023 |
| Misc Cost _Sublet ID |                                 |          |                   |             |           |           |
| DETAIL               | DETAIL                          |          |                   |             | \$150.00  |           |
|                      |                                 |          |                   | Total Cost: | \$150.00  |           |
| 99083                | PM'S 105377 (525)               | PM       | Completed         |             | 6/25/2024 | 6/25/2024 |
| Part Cost:           |                                 |          |                   |             |           |           |
| Part ID              |                                 | Code ID  | Code Description  |             | Cost      |           |
| 75749                | 5W20 SYN OIL                    | 26       | ENGINE            |             | \$16.44   |           |
| 100010               | OIL FILTER                      | 26       | ENGINE            |             | \$4.11    |           |
|                      |                                 |          |                   | Total Cost: | \$20.55   |           |
| Labor Cost:          |                                 |          |                   |             |           |           |
| Craft                | Resource                        |          |                   |             |           |           |
| MECH                 | 33                              | PMA      |                   |             | \$124.50  |           |
|                      |                                 |          |                   | Total Cost: | \$124.50  |           |
| 99364                | CLUNK NOISE, STEERING STICKS,   | L05377 N | Completed         |             | 8/6/2024  | 8/14/2024 |
| Labor Cost:          |                                 |          |                   |             |           |           |
| Craft                | Resource                        |          |                   |             |           |           |
| MECH                 | 33                              | 35       | STEERING          |             | \$124.50  |           |
|                      |                                 |          |                   | Total Cost: | \$124.50  |           |
| 99364                | CLUNK NOISE, STEERING STICKS, : | L05377 N | Completed         |             | 8/6/2024  | 8/14/2024 |

#### **Unit Totals:**

 Total Number of Work Orders:
 135

 Total Labor Costs:
 \$13,872.25

 Total Part Costs:
 \$10,753.38

 Total Sublet
 \$1,254.19

 Total Costs:
 \$25,879.82



**Site Totals:** 

 Total Number of Work Orders:
 135

 Total Labor Costs:
 \$13,872.25

 Total Part Costs:
 \$10,753.38

 Total Sublet
 \$1,254.19

 Total Costs:
 \$25,879.82

Report Totals:

 Total Number of Work Orders:
 135

 Total Labor Costs:
 \$13,872.25

 Total Part Costs:
 \$10,753.38

 Total Sublet
 \$1,254.19

 Total Costs:
 \$25,879.82

Filter:

Unit id begins with '105377'

