

# Fire Apparatus Inspection Form

Asset ID: 10193	Inventory ID: V-6362	Fair Market Value:
Short Description:		
Year 2014	Manufacturer INTERNATIONAL	Model 4300(HORTON AMBULANCE)
VIN: 1 H T M N A A L 9 E H 0 1 6 5 2 0		Title Restriction: <input type="checkbox"/> Y <input checked="" type="checkbox"/> N
Mileage/Odometer: 1 9 0 4 5 2	Odometer Accurate <input checked="" type="checkbox"/> Y <input type="checkbox"/> N:	

## Long Description:

This Apparatus is a: ☐ Pumper ☐ Ladder ☐ Tanker ☐ Rescue ☐ HazMat ☐ Crash ☒ Other Ambulance

☒ Starts ☐ Starts with a Boost & ☒ Runs ☐ Does Not Run:

Engine: Manufacture: International Size: 7.6 L, V6 ☐ Gas ☒ Diesel Hours: 12,298

This Apparatus was maintained every 180 ☒ Days ☐ Hours

Engine Condition: ☐ Is operable ☒ Needs repair ☐ Is Unknown Condition

Engine Repairs Needed: Check engine light on, needs turbochargers

Transmission: Manufacture: Allison ☒ Automatic ☐ Manual Speed Hours 12,298

Transmission Condition: ☒ Is operable ☐ Needs repair ☐ Is in Unknown Condition

Transmission Repairs Needed: N/A

Date Removed From Service: 6/30/2025 Maintenance Records: ☐ Available ☒ Not Available For Inspection

## NOTE: PUMP AND LADDER CERTIFICATIONS ARE REQUIRED FOR SOME ADVERTISING

Ladder: Manufacture: Model Serial #

Length Last Tested / /

Ladder Certification ☐ Yes-Certification Expires / / ☐ No Certification-Expired / /

Pump: Manufacture: Model Serial #

Operable: ☒ Yes ☐ No Hours GPM Last Tested / /

Pump Certification ☐ Yes-Certification Expires / / ☐ No Certification-Expired / /

Additional Equip: ☐ Tank Size: Gallons ☐ Fiberglass ☐ Poly ☐ Metal ☐ Hose (Gauge Feet )

# Of Intakes Location/Size

# Of Discharges Location/Size

Tire Condition: ☐ Good ☒ Fair ☐ Poor ☐ Low # ☐ Flat #

Additional Features (Lights, Generators, Loose Equipment): Lights, sirens, onboard charger/ inverter

Exterior: Color red/ white Chassis red/ white Body red/ white Windows: ☒ Not Cracked ☐ Cracked

Minor ☒ Dents ☒ Scratches ☒ Dings Damage To:

Decals: ☐ None ☐ Have been sprayed ☒ Have been removed & ☒ Impressions remain ☐ No impressions

Interior: Color Gray ☒ Cloth ☒ Vinyl ☐ Leather

Damage to Seats/Dash/Floor: Rips to seats, and driver arm rest needs to be replaced

Interior Equipment: