

Heavy Equipment Condition Report:

Asset Information:

Equipment Type: _____

Other: Crusher

Unit No: 6-9070

Year: 2014

Make: Kleemann

Model: Mobicone MCO

VIN/SN: K073002

Miles/Hrs.: 11946

Engine Information:

Year: 2012

Make: Scania

Model: _____ HP: 384

SN: _____

Fuel Type: Diesel

Asset Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

Hydraulics are Functional: Yes

Hydraulic Leaks Present: Yes

Unit Moves FWD/REV: Both

All Attachments Articulate Yes

Notes: _____

Control Station Type: Enclosed Cab

AC/Heat: Yes AC/Heat working: Yes

Additional Equipment: _____

Chassis:

Powertrain Type: 4WD

Propulsion Type: Track, Metal

Track Condition: Fair - Track condition shows heavy use and may require maintenance

Wheel Condition: _____

Tire Size: _____

Front: _____

Rear(s): _____

Attachments

Are there additional attachments that are not currently connected to this asset?

Describe: None

Type: _____

Details: _____

Type: _____

Details: _____

Additional Notes: