Vehicle Inspection Form

Inventory ID: 1513 Asset Number: 6159 Fair Market Value:
Short Description: Year 1985 Make KUBOTA Model L3750
VIN: <u>10428</u> Title: Clean Title Salvage Title No Title Court Documents Only SF97 Form Other
Odometer: 2280 Miles Kilometers Kilometers Odometer Accurate? Yes No Unknown
Long Description: This Vehicle: Starts Starts with a Boost & Runs/Drivable Engine Runs Does Not Run For Parts Only Engine- Type: 2.3 L, V Gas Description Propane/Natural Gas Gas/Electric Hybrid
Engine Condition: Runs Needs repair is in unknown condition Repairs needed:
This vehicle was maintained every $\frac{\mathcal{HO}}{\mathcal{HO}}$ Days Hours Miles/Kilometers Date Removed from Service: $\frac{\mathcal{HO}}{\mathcal{HO}}$ Maintenance Records: Available Mot Available For Inspection
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition Repairs Needed:
Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition:
Exterior: Color: Orange Windows: No Cracked Glass Cracked Minor: Dents Scratches Dings Tire Condition: Tread: #Flat Hubcaps #
Major Damage to:
Additional Damage:
Interior: ColorCloth Vinyl Leather
Damage to Seats: Damage to Dash/Floor:
Radio: Stock or Brand & Model:
Cruise Control Tilt Steering Remote Mirrors Climate Control Power: Steering Windows Door Locks Seats
Additional Equipment:
Manufacturer Model Serial #
Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type
Location of Asset: