

Boom Truck Condition Report:

Equipment Information:

| | | | |
|-------------|-------------------|---------------------|-------------------|
| Unit No: | CO12151 | Engine Information: | |
| Year: | 2015 | Year: | 2015 |
| Make: | Freightliner | Make: | Cummins HP: _____ |
| Model: | M2 106 | Model: | ISL |
| VIN/SN: | 3ALHCYCY7FDGD9151 | SN: | _____ |
| Miles/Hrs.: | 223092 | Fuel Type: | Diesel |

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Good - Minor dings and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen Engine Displacement: 8.9 Number of Cylinders 6

Sleeper (if Applicable): Length: _____ # of Bunks: _____ Aux Power Unit? _____

Additional Equipment: _____

Transmission:

Transmission Make: Allison

Auto / Manual: Automatic Number of Speeds: _____

Truck Moves FWD/REV: Both

Comments: _____

Chassis:

Frame Rails: _____ Notes: _____

Suspension: Spring Notes: _____

Wheel Base: _____ in.

Axle Weight Ratings (LBS): GVWR: 56,000 Front Axel: 16,000 Rear(s): 40,000

Tire Size: Front: 11R22.5 Rear(s): 11R22.5

Comments: _____

Flatbed

Bed Dimensions: Length: 26 ft. Width: 8 ft.

Conveyor/Boom Make: Cleasby Conveyor/Boom Model: FBR-6-40

Conveyor/Boom Is Functional: Yes

Additional Notes: