

Boom Truck Condition Report:

Equipment Information:

Unit No: CO6257
Year: 2014
Make: Freightliner
Model: M2 106
VIN/SN: 3ALHCYCY0EDGA1257

Miles/Hrs.: 221686

Engine Information:

Year: _____
Make: Cummins HP: 330
Model: ISL
SN: _____

Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Good - Damage is limited to normal wear and minor scratches.

Exterior Condition: Good - Minor dings and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen Engine Displacement: 8.9 Number of Cylinders 6

Sleeper (if Applicable): Length: _____ # of Bunks: _____ Aux Power Unit? _____

Additional Equipment: _____

Transmission:

Transmission Make: Allison

Auto / Manual: Automatic Number of Speeds: _____

Truck Moves FWD/REV: Both

Comments: _____

Chassis:

Frame Rails: Double Notes: _____

Suspension: Air Notes: _____

Wheel Base: 262 in. _____

Axle Weight Ratings (LBS): GVWR: 56,000 Front Axle: 16,000 Rear(s): 40,000

Tire Size: Front: 385/65R22.5 Rear(s): 11R22.5

Comments: _____

Flatbed

Bed Dimensions: Length: 26 ft. Width: 8 ft.

Conveyor/Boom Make: Cleasby Conveyor/Boom Model: FBR-6-40

Conveyor/Boom Is Functional: Could not confirm

Additional Notes:

Cleasby HDRTH-3000 Turn Table. There was some hydraulic oil pooled up on the ground directly under the turn table. This was after the truck was moved from where it was