

Boom Truck Condition Report:

Equipment Information:

Unit No: CO6258
Year: 2014
Make: Freightliner
Model: M2 106
VIN/SN: 3ALHCYCY2EDGA1258

Miles/Hrs.: 224220

Engine Information:

Year: _____
Make: Cummins HP: 330
Model: ISL
SN: _____

Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Good - Starts and operates; Some parts may require repair or replacement soon.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Good - Minor dings and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen **Engine Displacement:** 8.9 **Number of Cylinders:** 6

Sleeper (if Applicable): Length: _____ # of Bunks: _____ **Aux Power Unit?** _____

Additional Equipment: _____

Transmission:

Transmission Make: Allison 3500 RDA

Auto / Manual: Automatic **Number of Speeds:** _____

Truck Moves FWD/REV: Both

Comments: _____

Chassis:

Frame Rails: Double **Notes:** _____

Suspension: Air **Notes:** _____

Wheel Base: 262 in. _____

Axle Weight Ratings (LBS): GVWR: 56,000 Front Axle: 16,000 Rear(s): 40,000

Tire Size: Front: 385/65R22.5 Rear(s): 11R22.5

Comments: _____

Flatbed

Bed Dimensions: Length: 26 ft. **Width:** 8 ft.

Conveyor/Boom Make: Cleasby **Conveyor/Boom Model:** FBR-6-4

Conveyor/Boom Is Functional: N/A

Additional Notes:

Cleasby Truntable: HDRTH-3000