

Boom Truck Condition Report:

Equipment Information:

Unit No: CO9345
Year: 2014
Make: Freightliner
Model: M2 106
VIN/SN: 1FVHCYCY0EHFP3345

Miles/Hrs.: 130947

Engine Information:

Year: 2014
Make: Cummins
Model: ISL
SN: _____
Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Fair - Starts and operates but some parts require repair or replacement.

Interior Condition: Fair - Interior is heavily worn.

Exterior Condition: Fair - Visible dents and scratches

AC/Heat Functional: Yes

Leaks Present: Not Seen **Engine Displacement:** 8.9 **Number of Cylinders:** 6

Sleeper (if Applicable): Length: _____ # of Bunks: _____ **Aux Power Unit?** _____

Additional Equipment: _____

Transmission:

Transmission Make: _____

Auto / Manual: Automatic **Number of Speeds:** _____

Truck Moves FWD/REV: Both

Comments: _____

Chassis:

Frame Rails: _____ **Notes:** _____

Suspension: Spring **Notes:** _____

Wheel Base: _____ in. _____

Axle Weight Ratings (LBS): **GVWR:** 56,000 **Front Axel:** 16,000 **Rear(s):** 40,000

Tire Size: **Front:** 11R22.5 **Rear(s):** 11R22.5

Comments: _____

Flatbed

Bed Dimensions: Length: 25 ft. **Width:** 8 ft.

Conveyor/Boom Make: Cleasaby **Conveyor/Boom Model:** FBR-6-40

Conveyor/Boom Is Functional: No

Additional Notes:	The boom needs some repairs. Part can be seen in the cab of the truck. ☐
--------------------------	--------------------------------------------------------------------------