

Boom Truck Condition Report:

Equipment Information:

Unit No: KB9383 Engine Information: **Starts and Runs:** **No**
Year: 2012 Year: _____
Make: Freightliner Make: Cummins HP: _____
Model: Coronado 112 Axle: Tri/Axle Model: ISX
VIN/SN: 1FVHGNBG4CDBW9383 SN: _____
Miles/Hrs.: 88582 Fuel Type: Diesel

Equipment Condition:

Mechanical Condition: Poor - Will not start or operate and is in need of repair.
Interior Condition: Fair - Interior is heavily worn.
Exterior Condition: Fair - Visible dents and scratches
AC/Heat Functional: _____
Leaks Present: _____ Engine Displacement: 14.9 Number of Cylinders 6
Air Lift 3rd Axle in front of drive wheels No Air Lift Tag Axle behind drive wheels Yes
Additional Equipment: Flatbed Truck

Transmission:

Transmission Make: Eaton Fuller
Auto / Manual: Manual Number of Speeds: 10
Truck Moves FWD/REV: Neither
Comments: _____

Chassis:

Frame Rails: _____ Notes: _____
Suspension: Spring Notes: _____
Wheel Base: _____ in. _____
Axle Weight Ratings (LBS): GVWR: 66,000 Front Axel: 20,000 Rear(s): 46,000
Tire Size: Front: 425/65R22.5 Rear(s): 11R22.5
Comments: reported to have engine/transmission issues

Flatbed

Bed Dimensions: Length: 22 ft. Width: 8 ft.
Lifting Equipment Type: Knuckle Boom Other: _____
Conveyor/Boom Is Functional: Could not confirm
Turntable Make: _____ Turntable Model: _____
Conveyor/Boom Make: HIAB Conveyor/Boom Model: 322E-5 HIPRO