

Looking for more information on this vehicle?

NHTSA offers more safety information based on a vehicle's year, make and model. Check safety ratings, recommended technologies and other safety issues.

[Learn More →](#)

2022
**FORD
MAVERICK**



Image Not Available

VIN: 3FTTW8F99NRA35286

Recall data refreshed on Dec 26, 2025

6 Unrepaired Recalls associated with this VIN

Aug 08, 2022

Manufacturer Recall Number 22C20

NHTSA Recall Number 22V594

Recall Status Recall Incomplete

Summary

THE SIDE CURTAIN AIRBAGS ON YOUR VEHICLE MAY NOT MEET THE PERFORMANCE REQUIREMENTS OF FMVSS 226 EJECTION MITIGATION FOR FRONT-ROW PASSENGERS.

Safety Risk

A VEHICLE THAT DOES NOT COMPLY WITH FMVSS 226 INCREASES THE RISK OF INJURY IN A CRASH.

Remedy

PARTS ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO REPLACE BOTH SIDE AIRBAG CURTAINS FREE OF CHARGE PARTS AND LABOR.

Manufacturer's Notes

IF YOU HAVE ANY QUESTIONS REGARDING THIS RECALL, OR BELIEVE ANY OF THIS INFORMATION IS INACCURATE, PLEASE CONTACT FORD DIRECTLY AT 800-392-3673 OR LINCOLN AT 800-521-4140.

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: **1-888-327-4236** or TTY: **1-888-275-9171** or file an online complaint with

Dec 15,2023**Manufacturer Recall Number** 23C41**NHTSA Recall Number** 23V848**Recall Status** Recall Incomplete**Summary**

FORD MOTOR COMPANY FORD RECALL NO. 23C41 CERTAIN 2022 2024 MODEL YEAR FORD MAVERICK VEHICLES TURN SIGNAL OUTAGE DETECTION NOTIFICATION FAILURE

Safety Risk

VEHICLE OPERATORS WILL NOT RECEIVE THE INTENDED INCREASE IN FLASHING RATE NOTIFICATION TO ALERT THEM THAT A SINGLE REAR TURN SIGNAL BULB IS OUT. IF THE VEHICLE DOES NOT MEET FMVSS 108 INTENSITY REQUIREMENTS, THE VEHICLE MAY NOT ALERT OTHER ROAD USERS OF AN UPCOMING TURN OR LANE CHANGE, WHICH CAN INCREASE THE RISK OF A CRASH.

Remedy

FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO UPDATE THE BODY CONTROL MODULE BCM SOFTWARE FREE OF CHARGE.

Manufacturer's Notes

IF YOU HAVE ANY QUESTIONS REGARDING THIS RECALL, OR BELIEVE ANY OF THIS INFORMATION IS INACCURATE, PLEASE CONTACT FORD DIRECTLY AT 800-392-3673 OR LINCOLN AT 800-521-4140.

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: **1-888-327-4236** or TTY: **1-888-275-9171** or file an online complaint with NHTSA.

Apr 12,2024**Manufacturer Recall Number** 24S24**NHTSA Recall Number** 24V267**Recall Status** Recall Incomplete**Summary**

ON YOUR VEHICLE, THE BODY CONTROL MODULE BCM AND POWERTRAIN CONTROL MODULE PCM CALIBRATIONS MAY BE UNABLE TO DETECT A SUDDEN CHANGE IN THE 12-VOLT BATTERY STATE OF CHARGE DURING A DRIVE CYCLE.

Safety Risk

IF THE BCM AND PCM CALIBRATIONS ARE UNABLE TO DETECT A SUDDEN BATTERY DEGRADATION DURING A DRIVE, THE VEHICLE MAY BE UNABLE TO RESTART AFTER AN AUTO STOPSTART EVENT OR MAY EXPERIENCE A STALL WHILE COMING TO A STOP AT LOW SPEED. THE VEHICLE MAY ALSO LOSE 12-VOLT ACCESSORIES, INCLUDING HAZARD LIGHTS. A LOSS OF MOTIVE POWER CAN INCREASE THE RISK OF A CRASH.

Remedy

FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO REPROGRAM THE POWERTRAIN CONTROL AND BODY CONTROL MODULES FREE OF CHARGE SOFTWARE AND LABOR.

Manufacturer's Notes

IF YOU HAVE ANY QUESTIONS REGARDING THIS RECALL, OR BELIEVE ANY OF THIS INFORMATION IS INACCURATE, PLEASE CONTACT FORD DIRECTLY AT 800-392-3673 OR LINCOLN AT 800-521-4140.

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: **1-888-327-4236** or TTY: **1-888-275-9171** or file an online complaint with NHTSA.

Apr 26,2024**Manufacturer Recall Number** 24S27**NHTSA Recall Number** 24V293

Recall Status Recall Incomplete**Summary**

THE BODY CONTROL MODULE BCM WAS IMPROPERLY CALIBRATED AND MAY FALSELY DETECT A CURRENT OVERLOAD ON ONE OR BOTH TAILAMP CIRCUITS. IF THIS OCCURS, ONE OR BOTH OF THE REAR TAILAMPS MAY STOP FUNCTIONING DURING A DRIVE CYCLE.

Safety Risk

TAILAMPS THAT FAIL TO ILLUMINATE CAN CAUSE REDUCED VISIBILITY IN DARK CONDITIONS, WHICH MAY INCREASE THE RISK OF A CRASH

Remedy

FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO UPDATE THE BCM SOFTWARE FREE OF CHARGE PARTS AND LABOR.

Manufacturer's Notes

IF YOU HAVE ANY QUESTIONS REGARDING THIS RECALL, OR BELIEVE ANY OF THIS INFORMATION IS INACCURATE, PLEASE CONTACT FORD DIRECTLY AT 800-392-3673 OR LINCOLN AT 800-521-4140.

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: **1-888-327-4236** or TTY: **1-888-275-9171** or file an online complaint with NHTSA.

Sep 13,2024**Manufacturer Recall Number** 24S59**NHTSA Recall Number** 24V684**Recall Status** Recall Incomplete**Summary**

ON YOUR VEHICLE, IT MAY BE POSSIBLE FOR YOU TO EXPERIENCE A FROZEN REAR VIEW CAMERA DISPLAY IMAGE WHILE IN REVERSE.

Safety Risk

THIS MAY RESULT IN A FALSE REPRESENTATION OF WHERE THE VEHICLE IS RELATIVE TO ITS SURROUNDINGS, INCREASING THE RISK OF A CRASH.

Remedy

FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO UPDATE THE AUDIO CONTROL MODULE SOFTWARE FREE OF CHARGE.

Manufacturer's Notes

IF YOU HAVE ANY QUESTIONS REGARDING THIS RECALL, OR BELIEVE ANY OF THIS INFORMATION IS INACCURATE, PLEASE CONTACT FORD DIRECTLY AT 800-392-3673 OR LINCOLN AT 800-521-4140.

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: **1-888-327-4236** or TTY: **1-888-275-9171** or file an online complaint with NHTSA.

Jan 17,2025

Manufacturer Recall Number 25S02

NHTSA Recall Number 25V019

Recall Status Recall Incomplete

Summary

ON YOUR VEHICLE, THE 12-VOLT BATTERY MAY EXPERIENCE INTERNAL WELD AND OR CAST-ON-STRAP FAILURES, WHICH COULD LEAD TO A SUDDEN BATTERY DEGRADATION WHILE DRIVING.

Safety Risk

IF THE BATTERY SUDDENLY DEGRADES DURING A DRIVE, YOUR VEHICLE MAY BE UNABLE TO RESTART AFTER AN AUTO STOPSTART EVENT OR EXPERIENCE A STALL WHILE COMING TO A STOP AT LOW SPEED. EITHER OF THESE CONDITIONS MAY BE ACCCOMPANIED BY A LOSS OF ELECTRICAL ACCESSORIES, INCLUDING HAZARD LIGHTS. A LOSS OF MOTIVE POWER CAN INCREASE THE RISK OF A CRASH.

Remedy

PARTS ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT AND REPLACE THE BATTERY IF NECESSARY FREE OF CHARGE.

Manufacturer's Notes

IF YOU HAVE ANY QUESTIONS REGARDING THIS RECALL, OR BELIEVE ANY OF THIS INFORMATION IS INACCURATE, PLEASE CONTACT FORD DIRECTLY AT 800-392-3673 OR LINCOLN AT 800-521-4140.

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: **1-888-327-4236** or TTY: **1-888-275-9171** or file an online complaint with NHTSA.

Where's my VIN?

Every vehicle has a unique **vehicle identification number**, often referred to as a VIN. Look on the lower left of your car's windshield for your 17-character VIN. Your VIN is also located on your car's registration card, and it may be shown on your insurance card.