## Vehicle/ Item Information

Description:	Car Sedan		999	Vin #: _	2G1WD5E31E1150251	
Year:2014	Make: CHEVY	_	Model:	IMPALA	Mileag	ge: 44,060
Last day in serv	ice: 6/23/2025	Running	g condition:	Operational		
Engine & Transn	nission Information					
Engine size:	3.6 LIT. #	of Cylinders:	V-6	Type: GAS	Brand:	:GM
Transmission Type:	Automatic		Model:		Speed	s:4SPD
Oil change Interval:	200	Meter Type:	Gallons of Gas			
<b>Exterior Color:</b>	Black	Interior Color:	Black			
Police Package	Yes					
Major Vehicle E	quipment				Pass-	
ABS brakes: X	Air Conditioning: X	AC W	Torking: X No	Air bags:	Driver enger	ower Seat: X
Am/Fm Radio : X	CD Player: X	Power W	indows: X	Power Locks:	T:	ilt Wheel: X
Cruise Control: X	Rear Defroster X	Trunk Re				
Front Wheel Drv X	Four Wheel Dr.	All Whee		Rear Wheel Dr.		
<b>Vehicle Condition</b>						
$\begin{array}{ccc} \Gamma \text{ires} & & L \\ \Gamma \text{read} & & \text{Front:} & 8/32 \end{array}$	R L Rear: 8/3 Rear Rear:	_	R R Rear: 8/3 ar Rear: 0	32 S	ize: Front Rear	P235/55R17
BrakeTypes	Front DISC	Rear:	DISC	Rear Rear:		
Brake Life Left	Front 25%	Rear:	25%	Rear Rear:		
GVRW 4,709	Front Axle:	2550		Rear Axle(s):	2159	_

## **Added Description and Accessories:**

2014 Chevy Impala with a 9C-1 Police package Additional dome light mounted Temporary spare included

## **Known Defects:**

Various small dents dings and scratches on the body

AC has to run for a short time before it starts to blow cold air.

Holes on the roof from removed equipment

Interior is dirty

Strobe lights mounted in backup light housings

Holes on interior from removed equipment

Rear speaker covers have holes from removed equipment

Rear door handles, locks and window controls are inoperable

Hole cut in trunk liner

Steering wheel cover worn

B pillar trim is cut

Spot light has been removed