## **Heavy Equipment Condition Report:**

	Asset Informat	1011.
Equipment Type: _	Loader	
Other:		
Unit No: 10201 / 735365		Engine Information:
<b>Year:</b> 1993	Year:	
Make: Link Belt	Make:	
Model: TRC8030	Model:	HP:
VIN/SN: D313-143	SN:	
Miles/Hrs.: 6276	Fuel Type:	
Asset Condition:		
Mechanical Condition:	Poor - Will not start or operate and	d is in need of repair.
Interior Condition:	Fair - Interior is heavily worn.	
Exterior Condition:	Fair - Visible dents and scratches	
Hydraulics are Functional:	Could not confirm Hydra	aulic Leaks Present: Could not confirm
Unit Moves FWD/REV:	Neither	
All Attachments Articulate	Could not confirm Notes:	
Control Station Type:	Enclosed Cab AC/Heat:	Yes AC/Heat working: Could not confirm
Additional Equipment:		
Chassis:		
Powertrain Type:	4WD	
Propulsion Type:	Wheel, Pneumatic - All Terrain	
Track Condition:		
Wheel Condition:	Fair - Wheel condition shows heav	y use and may require maintenance
Tire Size:	Front:	Rear(s):
Attachments		
Are there additional attachments that are not currently connected to this asset?		
Describe:		
Туре:	Details:	
Туре:	Details:	
	Additional No	tes:
		, and the second se