

# DO NOT SAVE THIS TAB AS A PDF

Confirm with the site contact if you are required to provide PPE: Hard Hat, Steel Toes, Safety Vest. . Etc..

When Scheduling the inspection, confirm that the seller has moved the unit to a location where you can take good photos without clutter or branding in the background.

This inspection requires a Tape Measure.

All Photos MUST Be taken Landscape (Camera turned on its side)

## Asset Information:

Equipment Type: Loader

Other: \_\_\_\_\_

Unit No: 12449/1037139 A005

Engine Information:

Year: 2011

Year: \_\_\_\_\_

Make: Caterpillar

Make: \_\_\_\_\_

Model: 980H

Model: \_\_\_\_\_

HP: \_\_\_\_\_

VIN/SN: JMS06021

SN: \_\_\_\_\_

Miles/Hrs.: 17911

Fuel Type: Diesel

## Asset Condition:

**Mechanical Condition:** Good - Starts and operates; Some parts may require repair or replacement soon.

**Interior Condition:** Good - Damage is limited to normal wear and minor scratches.

**Exterior Condition:** Good - Minor dings and scratches

**Hydraulics are Functional:** Could not confirm

**Hydraulic Leaks Present:** No

**Unit Moves FWD/REV:** Neither

**All Attachments Articulate:** Could not confirm

**Notes:** \_\_\_\_\_

**Control Station Type:** Enclosed Cab

**AC/Heat:** Yes

**AC/Heat working:** Could not confirm

**Additional Equipment:** \_\_\_\_\_

## Chassis:

**Powertrain Type:** 4WD

**Propulsion Type:** Wheel, Pneumatic - All Terrain

**Track Condition:**

**Wheel Condition:** Good - Wheel condition shows normal wear from use

**Tire Size:** **Front:** 29.5R25

**Rear(s):** 29.5R25

## Attachments

Are there additional attachments that are not currently connected to this asset?

**Describe:** Seller said this unit runs, but is down for some hydraulic work.

**Type:** \_\_\_\_\_

**Details:** \_\_\_\_\_

**Type:** \_\_\_\_\_

**Details:** \_\_\_\_\_

## Additional Notes: