

WORK ORDER: 99016					
ASSET NUMBER: S30586					
Work Order Status: C - C - Closed			Date In:	09/14/2012	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	10/19/2012	
ASSET NUMBER INFORMATION					
YEAR: 2008	ORG: Active Fleet		TIRE SIZE:		
MAKE: Chevrolet	DEPT: 11731 – Nat Res Faculty Allocations		ENGINE SIZE:		
MODEL: Silverado	BILL CODE: YYYYYYNNNY1NYY		TRANS:		
LICENSE: S30-586	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1GCEC19C38Z188441		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: Truck, Pickup, ½ Ton		METERS: Mileage - 101910			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
LABORIE	09/17/2012	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform	0.58	\$35.000	
HARTNESS.2	10/15/2012	Repaired From PM Service / Tires/Wheels / Tire / Replace All	1.17	\$81.570	
HARTNESS.2	10/15/2012	Repaired From PM Service / Brakes / Shoe Brake / Replace	2.55	\$178.420	
LABORIE	10/18/2012	Repaired From PM Service / Engine / Seal Oil Rear / Replace	8.06	\$564.145	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
045-89060436	NS	1.000	\$22.013	10/17/2012	\$22.013
PART NAME: Seal,Rear Main		REPAIR: Repaired From PM Service / Engine / Seal Oil Rear / PartIssue			
013-UP10855	NS	1.000	\$87.613	10/12/2012	\$87.613
PART NAME: Shoes,Brake,Rear		REPAIR: Repaired From PM Service / Brakes / Shoe Brake / PartIssue			
017-0098	NS	4.000	\$181.175	10/12/2012	\$724.700
PART NAME: Tire,Goodyear Wrangler SR-A		REPAIR: Repaired From PM Service / Tires/Wheels / Tire / PartIssue			
0449-0402	NS	2.000	\$0.015	09/17/2012	\$0.030
PART NAME: Decal,Red,Small		REPAIR: Vehicle Prep / Cab / Decals / PartIssue			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		10/19/2012		\$25.000
MANUAL ADJUSTMENTS					
REASON			CREATED DATE	AMOUNT	
TIRE QUOTED WAS CHEAPER THAN TIRES USED-1017TM0000BN-WP			10/19/2012	(\$50.000)	
TECH EXCEEDED 10% OF LABOR ESTIMATE-1045S28100BN-WL			10/19/2012	(\$63.650)	
TECH EXCEEDED 10% OF LABOR ESTIMATE-1013SC3100BN-WL			10/19/2012	(\$70.620)	

W300d - WorkOrderDetailsByDate

5/23/2025 8:46:25 AM

WORK ORDER TOTALS					
TOTAL PARTS:	\$834.356	PARTS TAX:	\$0.022	MANUAL ADJUSTMENTS:	(\$184.270)
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$859.135	TOTAL MISC:	\$25.000	TOTAL COST:	\$1,534.221
NOTES					

99016 -
09/14/2012 @ 14:59:55 JOHN MARLOW
SAFETY INSPECTION
RED OSU DECALS
09/17/2012 @ 07:17:50 JOHN LABORIE
BEGIN SAFTEY INSPECTION
09/17/2012 @ 07:52:39 JOHN LABORIE
SAFTEY INSPECTION COMPLETE, STICKER NOT ISSUED
REAR BRAKES REQUIRE REPLACEMENT
REAR MAIN SEAL LEAKS, REQUIRES REPLACEMENT
RECOMMEND REPLACING TIRES.
10/12/2012 @ 09:56:41 KAREN CASTRICONE
RECEIVED APPROVAL VIA SIGNED APPROVAL REQUEST FROM ELIZABETH DAYTON, IN THE AMOUNT OF \$1425.54.
10/15/2012 @ 08:37:42 KEVIN HARTNESS
BEGIN TIRE REPLACEMENT.
10/15/2012 @ 09:47:33 KEVIN HARTNESS
COMPLETE TIRE REPLACEMENT. BEGIN REAR BRAKES.
10/15/2012 @ 12:20:52 KEVIN HARTNESS
COMPLETE BRAKE REPAIRS.
10/15/2012 @ 15:22:07 JOHN LABORIE
BEGIN REAR MAIN SEAL REPLACEMENT.
10/16/2012 @ 16:40:56 KAREN CASTRICONE
DAVE TOMASHEFSKI STOPPED IN TO INQUIRE ABOUT THE VEHICLE FOR ELIZABETH DAYTON.
AFTER INFORMING HIM OF THE WORK COMPLETED, I ASKED THE TECHS ABOUT THE MAIN SEAL AND INFORMED DAVE THAT IT HAD SOMETHING TO DO WITH THE ENGINE, HOWEVER THE MECHANIC WAS NOT IN AT THE MOMENT.
10/18/2012 @ 11:22:52 JOHN LABORIE
REAR MAIN SEAL REPLACEMENT COMPLETE.
10/19/2012 @ 08:22:28PHILLIPA DAVIS
LEFT MESSAGE FOR LIBBY THAT VEHICLE IS READY FOR PICK UP.
10/19/2012 @ 10:19:30 KAREN CASTRICONE
INFORMED LIBBY THAT SHE MAY WANT TO ORDER AN OFF-SITE FUEL CARD
10/19/2012 @ 15:56:15 KAREN CASTRICONE
LIBBY DAYTON PICKED UP THE VEHICLE.

WORK ORDER: 105461					
ASSET NUMBER: S30586					
Work Order Status: C - C - Closed			Date In:	09/23/2013	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	12/07/2015	
ASSET NUMBER INFORMATION					
YEAR: 2008	ORG: Active Fleet		TIRE SIZE:		
MAKE: Chevrolet	DEPT: 11731 – Nat Res Faculty Allocations		ENGINE SIZE:		
MODEL: Silverado	BILL CODE: YYYYYYNNNY1NYY		TRANS:		
LICENSE: S30-586	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1GCEC19C38Z188441		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: Truck, Pickup, ½ Ton		METERS: Mileage - 107492			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
BIRMINGHAM.24	09/23/2013	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform	0.41	\$35.000	
HARTNESS.2	09/24/2013	Repaired From PM Service / Suspension / Shock / Replace	0.52	\$36.650	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
016-911533	NS	2.000	\$62.463	09/23/2013	\$124.926
PART NAME: Absorber,Shock,Rear		REPAIR: Repaired From PM Service / Suspension / Shock / PartIssue			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		09/24/2013		\$7.170
WORK ORDER TOTALS					
TOTAL PARTS:	\$124.926	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$71.650	TOTAL MISC:	\$7.170	TOTAL COST:	\$203.746
NOTES					

105461 -
09/23/2013 @ 10:23:38 PHILLIPA DAVIS
DAVE TOMASHEFSKI
216-410-2676
KEYS- YES
SAFETY INSPECTION
GETTING ESTIMATE ON VEHICLE.
09/23/2013 @ 11:24:57 TALLEN BIRMINGHAM
SAFETY INSPECTION STARTED.
09/23/2013 @ 11:49:27 TALLEN BIRMINGHAM
SAFETY INSPECTION FAILED
REAR SHOCKS NEED REPLACED
09/23/2013 @ 13:10:35 CHAD ANDERSON
SENT APPROVAL REQUEST FOR \$240.43
DOCUMENT# S30586_P1_09232013
09/23/2013 @ 13:26:07 CHAD ANDERSON
RECEIVED APPROVAL FOR \$240.43
ORDERED REAR SHOCKS
09/24/2013 @ 09:36:12 KEVIN HARTNESS
COMPLETE SHOCK REPLACEMENT
09/24/2013 @ 09:48:09 KAREN CASTRICONE
LEFT VM FOR DAVE TOMASHEFSKI TO INFORM HIM THE VEHICLE IS READY FOR PIC K UP.
09/25/2013 @ 14:24:49 PHILLIPA DAVIS
DAVE TOMASHEFSKI CALLED CHECKING ON STATUS.
10/02/2013 @ 15:50:02 KAREN CASTRICONE
DAVE TOMASHEFSKI PICKED UP THE VEHICLE UNTIL IT IS TIME TO GO TO THE NEW VENDOR

W300d - WorkOrderDetailsByDate

5/23/2025 8:46:25 AM

105827 -
10/14/2013 @ 13:44:10 CHAD ANDERSON
DELIVERED TO CUSTOM AUTO BODY AND FLEET FOR REPAIR
11/06/2013 @ 14:22:32 BRIANA WILLIAMS
DAVE TOMASHEFSKI (216-410-2676) CALLED TO FIND OUT THE STATUS OF THIS VEHICLE. I LET HIM KNOW THAT IT IS STILL AT THE VENDOR AND THAT I WILL CONTACT THE VENDOR AND LET HIM KNOW THE STATUS.
11/06/2013 @ 14:27:03 BRIANA WILLIAMS
I CALLED CUSTOM AUTO BODY AND FLEET AND THEY SAID THEY ARE NOT SURE WHEN THE VEHICLE WILL BE READY. I GAVE HER MY NAME AND NUMBER AND SHE SAID EMILY WILL CALL ME BACK. CALLED CUSTOMER TO LET HIM KNOW THIS INFORMATION.
11/07/2013 @ 08:33:10 BRIANA WILLIAMS
EMILY CALLED ME BACK YESTERDAY EVENING AND LET ME KNOW THE VEHICLE SHOULD BE READY THIS FRIDAY. I WILL CALL DAVE TO LET HIM KNOW THIS INFORMATION.
11/08/2013 @ 14:53:13 BRIANA WILLIAMS
DAVE CALLED INQUIRING ABOUT THE VEHICLE. I TOLD HIM THAT IT WAS STILL AT THE VENDOR AND I WOULD CALL HIM WHEN IT IS FINISHED.
11/08/2013 @ 15:38:31 BRIANA WILLIAMS
EMILY CALLED ME AND LET ME KNOW THAT THE VEHICLE IS READY AND IT WILL BE DELIVERED HERE BY 5PM. I CALLED DAVE AND HE SAID HE WILL PICK IT UP ON TUESDAY. ALSO LET CHAD KNOW.
11/08/2013 @ 16:59:48 BRIANA WILLIAMS
EMILY DROPPED KEYS OFF.
Custom Fleet & Auto Body dropped off unit on Friday ~ JEB.
Notes from Invoice # 5087:
A. Cab Skin
01. Replace corner cab skin.
B. Front Door
01. Replace Left door shell.
02. Replace Left nameplate " Silverado ".
03. R&I Left door glass GM.
04. Replace Left mirror assembly.
C. Rear Door
01. Replace Left door shell.
02. R&I Left door glass GM w/o deep tint.
D. Pick Up Box
01. Replace Chevrolet box assembly.
11/13/2013 @ 13:12:20 PHILLIPA DAVIS
DAVID TOMASHEFSKI PICKED UP VEHICLE.

WORK ORDER: 112084					
ASSET NUMBER: S30586					
Work Order Status: C - C - Closed			Date In:	10/15/2014	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	10/23/2014	
ASSET NUMBER INFORMATION					
YEAR: 2008	ORG: Active Fleet		TIRE SIZE:		
MAKE: Chevrolet	DEPT: 11731 – Nat Res Faculty Allocations		ENGINE SIZE:		
MODEL: Silverado	BILL CODE: YYYYYYNNNY1NYY		TRANS:		
LICENSE: S30-586	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1GCEC19C38Z188441		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: Truck, Pickup, ½ Ton		METERS: Mileage - 110355			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
BIRMINGHAM.24	10/15/2014	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform	0.09	\$50.000	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
034-0011	S	1.000	\$15.682	10/15/2014	\$15.682
PART NAME: Bulb,Headlight,Low Beam		REPAIR: Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		10/15/2014		\$5.000
WORK ORDER TOTALS					
TOTAL PARTS:	\$15.682	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$50.000	TOTAL MISC:	\$5.000	TOTAL COST:	\$70.682
NOTES					
SAFETY INSPECTION - DAVE 216-410-2676 Wed 10/15/2014 12:00 Wed 10/15/2014 01:00 Keys=yes SAFETY INSPECTION ; REPAIRS COMPLETE - SAFETY INSPECTION COMPLETE RIGHT HEADLIGHT INOP REPLACED HEADLIGHT BULB ; VEHICLE READY CALL - SPOKE TO DAVE VEHICLE READY FOR PICK UP. ; VEHICLE PICKED UP - DAVID TOMASHEFSKI PICKED UP VEHILCE.					

WORK ORDER: 113309					
ASSET NUMBER: S30586					
Work Order Status: C - C - Closed			Date In:	12/19/2014	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	04/15/2015	
ASSET NUMBER INFORMATION					
YEAR: 2008	ORG: Active Fleet		TIRE SIZE:		
MAKE: Chevrolet	DEPT: CC12040 - FAES School of Environment and Natural Resources		ENGINE SIZE:		
MODEL: Silverado	BILL CODE: YYYYYYNNNY1NYY		TRANS:		
LICENSE: S30-586	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1GCEC19C38Z188441		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: Truck, Pickup, ½ Ton			METERS: Mileage - 118504		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
LAUER	12/19/2014	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform	0.67	\$17.000	
LAUER	12/19/2014	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform	0.34	\$50.000	
BIRMINGHAM.24	12/22/2014	Repaired From PM Service / Brakes / BrakeJobFront / Replace	0.93	\$78.625	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
0893-0520	S	6.000	\$2.240	12/19/2014	\$13.440
PART NAME: Oil, 5W20, Synthetic Blend, Bulk;1-Qt.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
0577-7060	S	1.000	\$3.424	12/19/2014	\$3.424
PART NAME: Filter,Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
013-AD7997	NS	1.000	\$62.049	12/22/2014	\$62.049
PART NAME: Pads, Brake, Front		REPAIR: Repaired From PM Service / Brakes / BrakeJobFront / Replace			
2014-9	NS	2.000	\$42.562	12/22/2014	\$85.124
PART NAME: Rotor, Brake, Front		REPAIR: Repaired From PM Service / Brakes / BrakeJobFront / Replace			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		12/22/2014		\$14.560
WORK ORDER TOTALS					
TOTAL PARTS:	\$164.037	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$145.625	TOTAL MISC:	\$14.560	TOTAL COST:	\$324.222
NOTES					

W300d - WorkOrderDetailsByDate

5/23/2025 8:46:25 AM

PMA - - DRAINED OLD OIL -REMOVED OLD OIL FILTER -INSTALLED NEW OIL FILTER -NOTICED FRONT BRAKE PADS ARE EXTREMELY WORN
DOWN AND NEED REPLACED -ADDED 6 QTZ OF OIL -PMA COMPLETE ; CORRECT MILEAGE/FASTER WILL NOT LET ME ENTER - 118,504 ;
APPROVAL SENT - SENT APPROVAL REQUEST FOR \$332.72 DOCUMENT# S30586_P1_12192014 ; APPROVAL RECEIVED - RECEIVED APPROVAL
FOR \$332.72 ; BRAKE REPLACEMENT - BRAKE REPLACEMENT COMPLETE ; VEHICLE READY CALL - DAYTON, LIBBY 614-688-5917 SPOKE WITH
LIBBY VEHICLE READY FOR PICK UP ; VEHICLE PICK UP - DAVE T. PICKED UP VEHICLE

WORK ORDER: 117356					
ASSET NUMBER: S30586					
Work Order Status: C - C - Closed			Date In:	07/06/2015	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	07/13/2015	
ASSET NUMBER INFORMATION					
YEAR: 2008	ORG: Active Fleet		TIRE SIZE:		
MAKE: Chevrolet	DEPT: CC12040 - FAES School of Environment and Natural Resources		ENGINE SIZE:		
MODEL: Silverado	BILL CODE: YYYYYYNNNY1NYY		TRANS:		
LICENSE: S30-586	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1GCEC19C38Z188441		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: Truck, Pickup, ½ Ton		METERS: Mileage - 118504			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
LAUER	07/07/2015	General Repair / Light System / Bulb Light / Replace	0.03	\$2.715	
LAUER	07/07/2015	General Repair / Gauge Instrument / LightCheckEngin / Diagnosis	3.29	\$290.701	
LAUER	07/09/2015	General Repair / Emission System / Sensor Emission / Replace	1.93	\$179.020	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
0741-9006	S	1.000	\$9.119	07/06/2015	\$9.119
PART NAME: Bulb,Headlight,Halogen		REPAIR: General Repair / Light System / Bulb Light / Replace			
047-2282571	NS	1.000	\$16.848	07/07/2015	\$16.848
PART NAME: Solenoid, Purge, Canister, Vapor		REPAIR: General Repair / Emission System / Sensor Emission / Replace			
0308-0006	S	3.000	\$2.196	07/08/2015	\$6.588
PART NAME: Clamp,Hose;Size 6		REPAIR: General Repair / Emission System / Sensor Emission / Replace			
047-2282614	NS	1.000	\$121.459	07/08/2015	\$121.459
PART NAME: Valve, Purge, Canister, Vapor		REPAIR: General Repair / Emission System / Sensor Emission / Replace			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		07/09/2015		\$25.000
MANUAL ADJUSTMENTS					
REASON			CREATED DATE		AMOUNT
Labor credit			07/09/2015		(\$307.450)
WORK ORDER TOTALS					
TOTAL PARTS:	\$154.014	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS: (\$307.450)
TOTAL SUBLET:	\$0.000	SUBLET TAX:		\$0.000	
TOTAL LABOR:	\$472.436	TOTAL MISC:		\$25.000	TOTAL COST: \$344.000

W300d - WorkOrderDetailsByDate

5/23/2025 8:46:25 AM

NOTES
CHECK ENGINE, Replace DRIVERS SIDE FRONT LIGHT - JOHN O'BRYCKI.2 859-420-3481 07/06/2015 08:00am Check Engine light is displayed on dash, Driver's side front light needs replace KEYS - YES ; Vehicle Update - Vehicle will be worked on today. ; FRONT D/S HEAD LIGHT - - BROUGHT VEHICLE INTO SHOP -VERIFIED ISSUE -REMOVED OLD BULB -REQUESTED NEW BULB -INSTALLED NEW BULB -TESTED, WORKS - TASK COMPLETE ; CHECK ENGINE LIGHT - -VERIFIED CHECK ENGINE LIGHT IS ON -SCANNED VEHICLE, RECIEVED CODE P04449 EVAP EMISSION VENT SOLENOID CONTROL CIRCUIT -LOOKED CODE UP ON MITCHELL ON DEMAND -THE SOLENOID VALVE APPEARS TO BE THE PRIMARY SUSPECT -GOING TO REQUEST PART -AWAITING PARTS.. -RECIEVED PART -INSTALLED PART -DIDNT CORRECT THE ISSUE -TOUCHED BASE WITH CHAD AND FOUND OUR NEXT SUSPECT SOLENOID, REQUESTED PART, CHADS GOING TO ORDER -AWAITING PART.. ; Vehicle Update - parts Erequest will be submitted today, parts will be in same or next day once request is approved. ; EMISSION SENSOR - -REMOVED OLD SENSOR -INSTALLED NEW SENSOR -REMOVED OLD VACUUM FILTER -INSTALLED NEW VACUUM FILTER -USED 3 NEW CLAMPS TO SECURE VACUUM LINES DUE TO HAVING TO CUT OLD ONES OFF -STARTED VEHICLE AND CHECK ENGINE LIGHT WENT OFF, LET VEHICLE RUN FOR ROUGHLY 15 MINUTES, NO ISSUES LIGHT IS STILL OFF -TASK COMPLETE ; Vehicle Update - Spoke with customer, explained repairs, vehicle ready for pick up. ; Vehicle pick up - Peter picked up vehicle, explained service.

5/23/2025 8:46:25 AM

WORK ORDER: 119554									
ASSET NUMBER: S30586									
Work Order Status: C - C - Closed							Date In:	10/05/2015	
Work Order Shop: 1 - TTM-VehicleRepair							Date Out:	01/06/2016	
ASSET NUMBER INFORMATION									
YEAR: 2008			ORG: Active Fleet				TIRE SIZE:		
MAKE: Chevrolet			DEPT: CC12040 - FAES School of Environment and Natural Resources				ENGINE SIZE:		
MODEL: Silverado			BILL CODE: YYYYYYNNNY1NYY				TRANS:		
LICENSE: S30-586			SITE: Columbus, Ohio				FUEL TYPE: U, NFT		
OPERATOR:			SERIAL NUMBER: 1GCEC19C38Z188441				ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: Truck, Pickup, ½ Ton							METERS: Mileage - 118504		
TECHNICIAN REPAIRS PERFORMED									
TECH		END DATE		REPAIR DESCRIPTION			HOURS		LABOR COST
RANKIN.165		10/05/2015		General Repair / Unit Services / Vehicle / Diagnosis			1.31		\$110.995
LAUER		10/07/2015		General Repair / Steering / Steering Gear / Replace			1.10		\$93.217
RANKIN.165		11/02/2015		General Repair / Glass Component / Switch Window / Replace			0.38		\$32.111
RANKIN.165		11/02/2015		General Repair / Steering / Steering Gear / Replace			0.00		\$0.048
RANKIN.165		11/02/2015		General Repair / Steering / Rack & Pinion / Replace			3.53		\$299.673
SUBLET REPAIRS									
VENDOR		PARTS	LABOR	OTHER	OPID	DATE BACK	REPAIR DESCRIPTION		SUBLET COST
Goodyear Auto Service Center		\$0.00	\$59.95	\$0.00	226	11/03/2015	General Repair / Unit Services / Vehicle / Alignment Total		\$68.942
PARTS ISSUED									
PART NUMBER			S/NS	ISS QTY	PART PRICE	ISSUE DATE		TOTAL PART COST	
015-19330567			NS	1.000	\$735.000	10/08/2015		\$735.000	
PART NAME: Rack and Pinion Assy					REPAIR: General Repair / Steering / Rack & Pinion / Replace				
015-2693429			NS	2.000	\$28.782	11/02/2015		\$57.564	
PART NAME: End, Rod, Tie, Outer					REPAIR: General Repair / Steering / Rack & Pinion / Replace				
0893-0220			S	1.000	\$7.803	11/02/2015		\$7.803	
PART NAME: Fluid,Power Steering;1-Qt.					REPAIR: General Repair / Steering / Rack & Pinion / Replace				
007-20945129			NS	1.000	\$70.785	10/08/2015		\$70.785	
PART NAME: Switch Assy, Window, Driver's					REPAIR: General Repair / Glass Component / Switch Window / Replace				
MISCELLANEOUS COSTS									
CODE		DESCRIPTION				POSTED DATE		MISC COST	
Environmental Charge		Environmental Charge				11/04/2015		\$25.000	

MANUAL ADJUSTMENTS							
REASON			CREATED DATE		AMOUNT		
LABOR CREDIT			11/04/2015		(\$231.110)		
WORK ORDER TOTALS							
TOTAL PARTS:		\$871.152	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS:	(\$231.110)
TOTAL SUBLET:		\$68.942	SUBLET TAX:		\$0.000		
TOTAL LABOR:		\$536.044	TOTAL MISC:		\$25.000	TOTAL COST:	\$1,270.028
NOTES							
DIAGNOSTIC Noises from Engine and power steering pass window - Dave tomashefski.3 216-410-2676 Appointment Time Mon 10/5/2015 11:00 AM Customer wants diagnostic for power steering and engine noise, Customer doesn't want any repairs don't until they are contacted first. Customer needs vehicle back by tomorrow morning. Noise coming from the engine and power steering. The customer making the appointment states that he was the driver but the complaint was that it was really loud. The powering steering noise is high pitched and has been happening for about a month Passenger side window doesn't roll up or down, This has been a problem for about 6 months (PLEASE DON'T HOLD UP GETTING VEHICLE BACK TO THE CUSTOMER FOR THIS REPAIR) Keys Yes ; Diag. noise - Monday, October 05, 2015 After test drive of this vehicle I was unable to duplicate the complaint. after talking to the driver I found the power steering complaint is the only problem and the engine noise was not heard. They would like for us to look into the power steering problem. After inspecting the window operation I found the drivers side master window switch is defective and needs replaced for the pass side window operation. ; power steering diagnosis - Monday, October 05, 2015 After inspection of the power steering system I found the steering gear is leaking and will need replaced along with both outer tie rods. during inspection I found the transmission oil cooler lines are seeping ?and I recommend replacement. ; Customer Call - Customer called and wants us to keep the vehicle here for repairs. Would like the vehicle back by 9am Thursday Morning. Vehicle needs estimate done. ; Estimate Sent - Estimate Sent to Libby Dayton and Dave. ; Estimate Approved - Hi: I approve these repairs. What account are you going to charge to? When do you anticipate the truck will be ready? Thanks for prompt attention, Libby Dayton? ? ; Ordered parts - Parts are on order ; Customer checking on status - Dave called checking on status of vehicle. ; Customer Call - Spoke with Customer(dave) told him that we are still waiting for part and that he could come and get the vehicle. We will call him to reschedule when parts come in. ; Vehicle reschedule - Dave tomashefski.3 216-410-2676 Rescheduled repair WO#119554 Tue 10/13/2015 3:00 PM ; Rescheduled appointment/cancelled - appointment/cancelled Customer cancelled appointment. Will have to reschedule. ; Customer Call - Spoke with Dave, he states that they still need the vehicle, he will call me when they can schedule. ; Vehicle update - Emailed customer to get update on setting appointment time. ; Vehicle rescheduled - ? Dave tomashefski.3 216-410-2676 Fri 10/30/2015 12:00 PM Rescheduled WO#119554 ; Vehicle Update - John Rankin is scheduled to work on vehicle today. ; Vehicle update - John Rankin is scheduled to work on vehicle. ; window switch - Monday, November 02, 2015 Replace driver side master window switch. Program auto down function .Complete. ; rack and pinion - Monday, November 02, 2015 Replace rack and pinion steering gear. Replace outer tie rod ends. Bleed power steering system. Test drive vehicle Vehicle needs to be sent to vendor for wheel alignment. Complete ; VEHICLE update - Vehicle needs to go to Goodyear ; Vehicle update - Vehicle returned from vendor. ; Vehicle ready call - Left message with Dave, vehicle ready for pick up. ; Vehicle pick up - Dave T picked up vehicle. ; Billing Adjustment - I. Returning Rack & Pinion core after billing. A. Issued CR directly to asset for \$ 150.00. ?							

WORK ORDER: 129928					
ASSET NUMBER: S30586					
Work Order Status: C - C - Closed			Date In:	09/26/2016	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	09/28/2016	
ASSET NUMBER INFORMATION					
YEAR: 2008	ORG: Active Fleet		TIRE SIZE:		
MAKE: Chevrolet	DEPT: CC12040 - FAES School of Environment and Natural Resources		ENGINE SIZE:		
MODEL: Silverado	BILL CODE: YYYYYYNNNY1NYY		TRANS:		
LICENSE: S30-586	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1GCEC19C38Z188441		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: Truck, Pickup, ½ Ton		METERS: Mileage - 134904			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
RANKIN.165	09/26/2016	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform	0.25	\$17.000	
RANKIN.165	09/26/2016	Repaired From PM Service / Engine Air Intake / Filter Air / Replace	0.02	\$1.936	
RANKIN.165	09/26/2016	Repaired From PM Service / Glass Component / Blade Wiper / Replace	0.11	\$8.996	
RANKIN.165	09/26/2016	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform	0.76	\$0.000	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
0893-0520	S	6.000	\$1.779	09/26/2016	\$10.674
PART NAME: Oil, 5W20, Synthetic Blend, Bulk;1-Qt.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
0577-7060	S	1.000	\$3.568	09/26/2016	\$3.568
PART NAME: Filter,Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
007-0100	S	0.500	\$1.661	09/26/2016	\$0.831
PART NAME: Fluid, Washer, Windshield, Bulk; 1-Gal.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
0553-2487	NS	1.000	\$9.932	09/26/2016	\$9.932
PART NAME: Filter, Air		REPAIR: Repaired From PM Service / Engine Air Intake / Filter Air / Replace			
007-22PP	S	2.000	\$13.000	09/26/2016	\$26.000
PART NAME: Blade, Wiper, AccuFit, 22"		REPAIR: Repaired From PM Service / Glass Component / Blade Wiper / Replace			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		09/26/2016		\$2.790

W300d - WorkOrderDetailsByDate

5/23/2025 8:46:25 AM

MANUAL ADJUSTMENTS							
REASON			CREATED DATE		AMOUNT		
Labor credit			09/26/2016		(\$10.930)		
WORK ORDER TOTALS							
TOTAL PARTS:		\$51.005	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS:	(\$10.930)
TOTAL SUBLET:		\$0.000	SUBLET TAX:		\$0.000		
TOTAL LABOR:		\$27.932	TOTAL MISC:		\$2.790	TOTAL COST:	\$70.797
NOTES							
PMA, Safety Inspection, Need back Today - Peter Mcdonough.81 614-515-0012 Walk-in 9/26/2016 9:52:23 AM PMA, Safety Inspection, Need back Today Keys Yes ? ; Safety inspection - 9/26/2016 Perform vehicle safety inspection. Tire's @ 10/32", Air pressure @ 50 brake's @ 8mm F 5mm R Rear drum brakes. (Good) Needs wiper blades and air filter replaced. parts on order. Mirror switch is defective ,will not go up or down . Requested. Complete. ; PMA - 9/26/2016 Perform vehicle PMA service. See safety note's for tire information. Complete, ; Air filter - 9/26/2016 Replace dirty engine air filter. Complete. ; Wiper blades. - 9/26/2016 Replace both front wiper blades. Complete. ; Vehicle ready call - Spoke with Peter, vehicle is ready for pick up. ; VEHICLE pick up - Peter picked up vehicle							

WORK ORDER: 144622				
ASSET NUMBER: S30586				
Work Order Status: C - C - Closed			Date In:	06/25/2018
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	07/12/2018
ASSET NUMBER INFORMATION				
YEAR: 2008		ORG: Active Fleet	TIRE SIZE:	
MAKE: Chevrolet		DEPT: CC12040 - FAES School of Environment and Natural Resources	ENGINE SIZE:	
MODEL: Silverado		BILL CODE: YYYYYYNNNY1NYY	TRANS:	
LICENSE: S30-586		SITE: Columbus, Ohio	FUEL TYPE: U, NFT	
OPERATOR:		SERIAL NUMBER: 1GCEC19C38Z188441	ASSET AVAIL CODE: 0000 to 2359 On Call 24/5	
CLASS: Truck, Pickup, ½ Ton			METERS: Mileage - 140266	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
MADDEN	06/26/2018	General Repair / Cranking System / Battery / Diagnosis	0.30	\$25.240
MADDEN	06/27/2018	General Repair / Cranking System / Battery / Replace	0.64	\$54.093
MADDEN	06/27/2018	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform	1.22	\$17.000
MADDEN	06/27/2018	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform	1.65	\$0.000
MADDEN	07/06/2018	Repaired From PM Service / Heating Vent / MotorBlowerHeat / Replace	1.17	\$99.733
MADDEN	07/06/2018	Repaired From PM Service / Glass Component / Blade Wiper / Replace	0.04	\$3.377
MADDEN	07/06/2018	Repaired From PM Service / Suspension / Strut / Replace	2.88	\$244.635

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
0577-7060	S	1.000	\$4.270	06/26/2018	\$4.270
PART NAME: Filter,Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
045-0520	NS	6.000	\$3.288	06/26/2018	\$19.728
PART NAME: Oil, 5W20, Synthetic, Bulk; 1-Qt.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
007-22PP	S	2.000	\$14.016	06/27/2018	\$28.032
PART NAME: Blade, Wiper, AccuFit, 22"		REPAIR: Repaired From PM Service / Glass Component / Blade Wiper / Replace			
032-8448	NS	1.000	\$155.650	06/26/2018	\$155.650
PART NAME: Battery		REPAIR: General Repair / Cranking System / Battery / Replace			
016-139105	NS	2.000	\$149.450	07/03/2018	\$298.900
PART NAME: Strut, Quick, Front, Modular Assembly		REPAIR: Repaired From PM Service / Suspension / Strut / Replace			
004-20911076	NS	1.000	\$125.313	07/05/2018	\$125.313
PART NAME: Motor, Blower		REPAIR: Repaired From PM Service / Heating Vent / MotorBlowerHeat / Replace			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		07/06/2018		\$25.000
MANUAL ADJUSTMENTS					
REASON			CREATED DATE		AMOUNT
Exceeded estimate			07/06/2018		(\$74.590)
WORK ORDER TOTALS					
TOTAL PARTS:	\$631.893	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS: (\$74.590)
TOTAL SUBLET:	\$0.000	SUBLET TAX:		\$0.000	
TOTAL LABOR:	\$444.078	TOTAL MISC:		\$25.000	TOTAL COST: \$1,026.381
NOTES					
Safety Inspection, Battery Check, PMA - Libby Dayton (614) 688-5917 Dave Tomashefski.3 216-410-2676 Walk-in 6/25/2018 Customer states that the vehicle will only start when jumped. Keys Yes ; Battery - 6/26/2018 Battery completely bad. Unable to run battery tester, only has 4.7V Charging system operating normally. Needs battery. Replaced battery, retest. Starting/charging system acting normally. Complete. ; PM Note - 6/26/2018 Changed oil and filter. 6 qt 5w-20. Set tires to 35 PSI. Front tire tread depth 5/32" Rear tire tread depth 7/32" Wipers chattering and streaking. Complete. ; Safety inspection - 6/26/2018 Performed safety inspection. Cleaned inside of windshield, was very dirty. Front brake pads 6mm rotors rusty. Rear brake shoes 4mm drums ok. Front tires have wear problems, tires cupped and slightly feathered. Front struts are original and very worn out, recommend replacing with quick strut assemblies. Recommend tire rotation and alignment after replacing struts. Lubed door locks and latches. Right front window doesn't go down, motor seems to be running in the "up" direction when switch is pressed though. Blower motor needs replaced, wasn't working when truck came in, started moving after manually moving the fan. Complete. ; Checking Status - Dave Tomashefski called checking on status and will check with boss regarding payment for repairs. ; Estimate - Estimate sent to customer. ; Estimate Approval - Hi Nick, The erequest for the truck repair was just approved. Please proceed with the repairs. The PR # for the approved erequest is PR4471578. The request # is 4471578. Thanks! Dave Tomashefski ; ER - ER PR4471578 ; Blower motor - 7/6/2018 Removed enclosure panel under passenger side of dash. Replaced bower motor. Verified all speeds working. Complete. ; Wipers - 7/6/2018 Replaced both front wiper blades. Complete. ; Vehicle ready call - I left message with Dave, vehicle is ready for pick up. ; Vehicle pick up - Dave picked up vehicle.					

WORK ORDER: 150727					
ASSET NUMBER: S30586					
Work Order Status: C - C - Closed			Date In:	11/05/2019	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	11/15/2019	
ASSET NUMBER INFORMATION					
YEAR: 2008	ORG: Active Fleet		TIRE SIZE:		
MAKE: Chevrolet	DEPT: CC12040 - FAES School of Environment and Natural Resources		ENGINE SIZE:		
MODEL: Silverado	BILL CODE: YYYYYYNNNY1NYY		TRANS:		
LICENSE: S30-586	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1GCEC19C38Z188441		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: Truck, Pickup, ½ Ton		METERS: Mileage - 143575			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
MADDEN	11/05/2019	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform	0.69	\$17.000	
MADDEN	11/05/2019	General Repair / Gauge Instrument / LightCheckEngin / Diagnosis	0.52	\$44.152	
MADDEN	11/05/2019	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform	0.48	\$0.000	
SNOW-WARD	11/14/2019	General Repair / Emission System / SensorOxygen / Replace	0.89	\$75.602	
MADDEN	11/14/2019	General Repair / Emission System / Misc Parts / Replace	1.14	\$97.207	
MADDEN	11/14/2019	General Repair / Emission System / SensorOxygen / Replace	0.34	\$28.734	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
0577-7060	S	1.000	\$4.960	11/05/2019	\$4.960
PART NAME: Filter,Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
045-020	S	6.000	\$3.675	11/05/2019	\$22.050
PART NAME: Oil, 0W20, Synthetic, Bulk; 1-Qt.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
047-21066	NS	1.000	\$72.527	11/14/2019	\$72.527
PART NAME: Sensor, Oxygen		REPAIR: General Repair / Emission System / SensorOxygen / Replace			
047-2282571	NS	1.000	\$58.487	11/14/2019	\$58.487
PART NAME: Solenoid, Purge, Canister, Vapor		REPAIR: General Repair / Emission System / Misc Parts / Replace			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		11/14/2019		\$25.000

W300d - WorkOrderDetailsByDate

5/23/2025 8:46:25 AM

MANUAL ADJUSTMENTS				
REASON		CREATED DATE		AMOUNT
Labor Overage		11/14/2019		(\$42.000)
WORK ORDER TOTALS				
TOTAL PARTS:	\$158.024	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: (\$42.000)
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$262.695	TOTAL MISC:	\$25.000	TOTAL COST: \$403.719
NOTES				
Check Engine light, PMA, Safety Inspection, Brake Check - Dave Tomashefski.3 216-410-2676 Libby Dayton (614) 688-5917 Walk-in 11/5/2019 Check Engine light, PMA, Safety Inspection, Brake Check Customer states that they haven't driven the vehicle in a awhile. When they started the vehicle the check engine light was on. The customer said that one of the drivers of the vehicle felt that the brakes didn't feel right. Customer couldn't give me further information on brake concerns. Keys yes ; PM note - 11/5/2019 Changed oil and filter. 6 qt 0w-20. Set tires to 35 PSI. Front tire tread depth 6mm Rear tire tread depth 6.5mm Complete. ; Check engine diag - 11/5/2019 Retrieved codes from modules, PCM has 3 codes stored: P0138 - HO2S circuit high voltage bank 1 sensor 2 P0496 - EVAP system flow detected during non-purge P2271 HO2S signal stuck rich bank 1 sensor 2 P0138 and P2271 caused by bad oxygen sensor bank 1 downstream. P0496 caused by bad canister purge valve sticking open. Needs to have both replaced to fix check engine light. Complete. ; Safety inspection - 11/5/2019 Performed safety inspection. Wipers ok. Right front window not working. Power mirrors not working. Steering and suspension ok. Lubed door locks and latches. Front brake pads 5mm rotors rusty. Rear brake shoes 4mm drums have a large rust ridge. Suggest putting time into diagnosis for mirrors and window. Complete. ; Estimate - Estimate sent to customer. ; Customer email - Hi Nick, Would it be possible for you to provide me with an estimate that does not include item number 6 (i.e., replace master window and mirror switches)? Best regards, Dave Tomashefski ; Revised Estimate - I sent customer revised estimate. ; Customer call - I left message to get update on estimate. ; Estimate approval - Hi Nick, Thanks very much. Yes, please proceed with the repairs listed on the \$403.47 quote. The approved erequest number is PR5460472. - Dave ; ER - ER PR5460472 ; Oxygen sensor and purge valve - 11/14/2019 Replaced bank 1 downstream O2 sensor and canister purge valve. Cleared codes. Test drive vehicle for 10 miles with 2 startups to verify no codes or warning lights. Complete. ; Vehicle ready call - I left message with Dave vehicle is ready for pick up. ; Vehicle pick up - 11/15 Vehicle pick up by Dave.				

WORK ORDER: 170439					
ASSET NUMBER: S30586					
Work Order Status: C - C - Closed			Date In:	10/07/2021	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	10/11/2021	
ASSET NUMBER INFORMATION					
YEAR: 2008	ORG: Active Fleet		TIRE SIZE:		
MAKE: Chevrolet	DEPT: CC12040 - FAES School of Environment and Natural Resources		ENGINE SIZE:		
MODEL: Silverado	BILL CODE: YYYYYYNNNY1NYY		TRANS:		
LICENSE: S30-586	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1GCEC19C38Z188441		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: Truck, Pickup, ½ Ton		METERS: Mileage - 145696			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
KITTS.12	10/08/2021	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform	0.29	\$0.000	
KITTS.12	10/08/2021	General Repair / Glass Component / Washer W/S / Replace	0.19	\$15.749	
KITTS.12	10/08/2021	General Repair / Tires/Wheels / TPMS / Replace	1.86	\$158.478	
KITTS.12	10/11/2021	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform	0.77	\$17.000	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
0577-7060	S	1.000	\$5.557	10/08/2021	\$5.557
PART NAME: Filter,Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
045-020	S	6.000	\$4.670	10/08/2021	\$28.020
PART NAME: Oil, 0W20, Synthetic, Bulk; 1-Qt.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
007-0100	S	1.000	\$2.142	10/08/2021	\$2.142
PART NAME: Fluid, Washer, Windshield, Bulk; 1-Gal.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
007-22PP	S	2.000	\$9.996	10/08/2021	\$19.992
PART NAME: Blade, Wiper, AccuFit, 22"		REPAIR: General Repair / Glass Component / Washer W/S / Replace			
017-921309	NS	1.000	\$39.780	10/08/2021	\$39.780
PART NAME: Sensor, TPMS		REPAIR: General Repair / Tires/Wheels / TPMS / Replace			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		10/11/2021		\$12.000
MANUAL ADJUSTMENTS					
REASON	CREATED DATE			AMOUNT	
Labor Overage	10/11/2021			(\$70.000)	

W300d - WorkOrderDetailsByDate

5/23/2025 8:46:25 AM

WORK ORDER TOTALS					
TOTAL PARTS:	\$95.491	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	(\$70.000)
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$191.227	TOTAL MISC:	\$12.000	TOTAL COST:	\$228.718
NOTES					
PMA, Safety Inspection - Dave Tomashefski.3 216-410-2676 Appointment Time Thu 10/7/2021 PMA, Safety Inspection Keys Yes ; PM SERVICE - DID PM SERVICE 10:11:17 AM 10/8/2021 ; safety - tires brakes found on safety 10:24:45 AM 10/8/2021 rf - 9/32 lr - 4mm rr -9/32 rr -4mm lf - 9/32 rf - 8mm lr -9/32 lf - 8mm ; wiper BLADES - mounted new wiper blades 10:47:35 AM 10/8/2021 ; tpms sensor - installed new tpms sensor in the left front tire reprogam all the sensors 3:13:08 PM 10/8/2021 ; Vehicle ready email - Emailed customer vehicle is ready for pick up. ; Vehicle pick Up - Vehicle pick Up					

WORK ORDER: 178750		
ASSET NUMBER: S30586		
Work Order Status: C - C - Closed	Date In:	08/29/2023
Work Order Shop: 1 - TTM-VehicleRepair	Date Out:	10/12/2023
ASSET NUMBER INFORMATION		
YEAR: 2008	ORG: Active Fleet	TIRE SIZE:
MAKE: Chevrolet	DEPT: CC12040 - FAES School of Environment and Natural Resources	ENGINE SIZE:
MODEL: Silverado	BILL CODE: YYYYYYNNNY1NYY	TRANS:
LICENSE: S30-586	SITE: Columbus, Ohio	FUEL TYPE: U, NFT
OPERATOR:	SERIAL NUMBER: 1GCEC19C38Z188441	ASSET AVAIL CODE: 0000 to 2359 On Call 24/5
CLASS: Truck, Pickup, ½ Ton		METERS: Mileage - 158618

TECHNICIAN REPAIRS PERFORMED						
TECH	END DATE	REPAIR DESCRIPTION			HOURS	LABOR COST
KAHANA	08/29/2023	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			1.51	\$17.000
KAHANA	08/29/2023	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform			0.08	\$0.000
GODDARD	08/30/2023	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			1.14	\$0.000
GODDARD	09/25/2023	Repaired From PM Service / Engine Air Intake / Filter Air / Replace			0.63	\$62.972
GODDARD	09/25/2023	Repaired From PM Service / Charging System / Belt Alternator / Replace			0.70	\$69.639
KAHANA	09/26/2023	General Repair / Cab / HandleDoorOutsi / Replace			1.73	\$172.500
KAHANA	09/26/2023	Repaired From PM Service / Engine Exhaust / Hanger Exhaust / Replace			0.36	\$36.167
KAHANA	09/27/2023	Repaired From PM Service / Tires/Wheels / TPMS / Diagnosis			0.12	\$11.833
KAHANA	09/27/2023	Repaired From PM Service / Gauge Instrument / LightCheckEngin / Diagnosis			1.26	\$126.222
KAHANA	09/27/2023	Repaired From PM Service / Safety Interior / System / Diagnosis			0.35	\$35.167
KAHANA	09/29/2023	General Repair / Emission System / Valve PCV / Replace			0.33	\$33.111
HOEPKER	09/29/2023	Repaired From PM Service / Brakes / BrakeJobFront / Replace			1.55	\$155.083
KAHANA	09/29/2023	Repaired From PM Service / Brakes / BrakeJobFront / Replace			8.17	\$817.361
KINER	09/29/2023	Repaired From PM Service / Brakes / BrakeJobFront / Replace			1.57	\$157.334
GODDARD	10/03/2023	Repaired From PM Service / Tires/Wheels / Tire / Replace			1.90	\$190.167
KAHANA	10/03/2023	General Repair / Brakes / System / Bleed			3.44	\$343.917
KAHANA	10/04/2023	General Repair / Brakes / Cylinder Master / Replace			2.19	\$218.806
HOEPKER	10/05/2023	General Repair / Brakes / System / Bleed			1.12	\$111.556
GODDARD	10/09/2023	General Repair / Brakes / System / Bleed			8.76	\$875.612
GODDARD	10/11/2023	General Repair / Safety Interior / Sensor AirBag / Replace			0.80	\$79.806
KAHANA	10/11/2023	General Repair / Safety Interior / Sensor AirBag / Replace			1.10	\$110.000
GODDARD	10/12/2023	Repaired From PM Service / Tires/Wheels / TPMS / Diagnosis			1.00	\$100.028
PARTS ISSUED						
PART NUMBER		S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
0577-7060		S	1.000	\$5.486	08/29/2023	\$5.486
PART NAME: Filter,Oil			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
045-020		S	6.000	\$5.598	08/29/2023	\$33.588
PART NAME: Oil, 0W20, Synthetic, Bulk; 1-Qt.			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			

The Ohio State University - Fleet Management
W300d - WorkOrderDetailsByDate
5/23/2025 8:46:25 AM

WORK ORDER DETAILS REPORT

p.25

007-0100	S	1.000	\$3.212	08/29/2023	\$3.212
PART NAME: Fluid, Washer, Windshield, Bulk; 1-Gal.			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform		
2022-113	S	4.000	\$146.159	09/19/2023	\$584.636
PART NAME: Tire, Firestone Destination LE3			REPAIR: Repaired From PM Service / Tires/Wheels / Tire / Replace		
2023-12	NS	1.000	\$50.427	09/20/2023	\$50.427
PART NAME: Pads, Brake, Front			REPAIR: Repaired From PM Service / Brakes / BrakeJobFront / Replace		
2014-9	NS	2.000	\$76.934	09/20/2023	\$153.868
PART NAME: Rotor, Brake, Front			REPAIR: Repaired From PM Service / Brakes / BrakeJobFront / Replace		
2023-1437	NS	1.000	\$153.894	09/20/2023	\$153.894
PART NAME: Caliper, Brake, Front, LH			REPAIR: Repaired From PM Service / Brakes / BrakeJobFront / Replace		
2023-1438	NS	1.000	\$153.894	09/20/2023	\$153.894
PART NAME: Caliper, Brake, Front, RH			REPAIR: Repaired From PM Service / Brakes / BrakeJobFront / Replace		
2023-1535	NS	4.000	\$36.387	09/29/2023	\$145.548
PART NAME: Tpms Valve			REPAIR: Repaired From PM Service / Tires/Wheels / Tire / Replace		
2022-355	NS	1.000	\$32.240	09/20/2023	\$32.240
PART NAME: Hose, Brake, Front			REPAIR: Repaired From PM Service / Brakes / BrakeJobFront / Replace		
2022-354	NS	1.000	\$27.456	09/20/2023	\$27.456
PART NAME: Hose, Brake, Front			REPAIR: Repaired From PM Service / Brakes / BrakeJobFront / Replace		
0553-2487	NS	1.000	\$17.329	09/20/2023	\$17.329
PART NAME: Filter, Air			REPAIR: Repaired From PM Service / Engine Air Intake / Filter Air / Replace		
2023-1439	NS	1.000	\$41.119	09/20/2023	\$41.119
PART NAME: Belt, Serpentine			REPAIR: Repaired From PM Service / Charging System / Belt Alternator / Replace		
001-4K378	NS	1.000	\$17.966	09/20/2023	\$17.966
PART NAME: Belt, V, Micro			REPAIR: Repaired From PM Service / Charging System / Belt Alternator / Replace		
0497-7356554	NS	1.000	\$40.794	09/20/2023	\$40.794
PART NAME: Handle, Door, Exterior, Front, LH			REPAIR: General Repair / Cab / HandleDoorOutsi / Replace		
043-15092802	NS	1.000	\$31.746	09/20/2023	\$31.746
PART NAME: Insulator, Hanger, Exhaust			REPAIR: Repaired From PM Service / Engine Exhaust / Hanger Exhaust / Replace		
2023-1534	NS	1.000	\$46.787	09/29/2023	\$46.787
PART NAME: Valve Canister Purge			REPAIR: General Repair / Emission System / Valve PCV / Replace		
013-DOT3	S	5.000	\$5.937	10/03/2023	\$29.685
PART NAME: Fluid, Brake, 12 Oz.			REPAIR: General Repair / Brakes / System / Bleed		
013-DOT3	S	4.000	\$5.937	10/03/2023	\$23.748
PART NAME: Fluid, Brake, 12 Oz.			REPAIR: General Repair / Brakes / System / Bleed		
013-DOT4	S	5.000	\$5.864	10/04/2023	\$29.320
PART NAME: Fluid, Brake, 12 Oz.			REPAIR: General Repair / Brakes / System / Bleed		
2023-1597	NS	1.000	\$307.801	10/11/2023	\$307.801

W300d - WorkOrderDetailsByDate

5/23/2025 8:46:25 AM

PART NAME: Sensor, Air Bag			REPAIR: Repaired From PM Service / Safety Interior / System / Diagnosis		
2023-1559	NS	1.000	\$132.587	10/04/2023	\$132.587
PART NAME: Cylinder, Brake, Master			REPAIR: General Repair / Brakes / Cylinder Master / Replace		
2023-1559	NS	1.000	\$132.587	10/09/2023	\$132.587
PART NAME: Cylinder, Brake, Master			REPAIR: General Repair / Brakes / Cylinder Master / Replace		
2023-1596	NS	1.000	\$32.045	10/11/2023	\$32.045
PART NAME: Tube, Valve, Purge, Vapor Canister			REPAIR: General Repair / Emission System / CanistrCharcoal / Repair		
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Supply Fee	Supply Fee		08/29/2023		\$30.000
MANUAL ADJUSTMENTS					
REASON			CREATED DATE		AMOUNT
overage in labor and parts credit for damaged master cylinder.			10/17/2023		(\$1,825.560)
WORK ORDER TOTALS					
TOTAL PARTS:	\$2,227.763	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	(\$1,825.560)
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$3,724.281	TOTAL MISC:	\$30.000	TOTAL COST:	\$4,156.484
NOTES					

W300d - WorkOrderDetailsByDate

5/23/2025 8:46:25 AM

Pma/Safety - Customer requests to have a PMA service and a safety inspection performed. ; Contact - Chelsea Whitacre 614-633-7741 ; PMA Completed - PM service and inspection completed Engine oil and filter changed All 4 tires will need replaced, at wear bars and are from 2012 Will require rear brakes shoes, fronts are at 4.5mm, rotors display heating, replacement of front brakes is strongly recommended. Will need engine airfilter Will need Both the stretch serpentine belt and main accessory serpentine belt Will need transmission cooler lines Will need TPMS diagnostic; light is blinking, check engine light diagnostic and SRS diagnostic No other issues at this time Complete. 8/29/2023 5:57:06 PM ; Safety Completed - Safety Completed No suspension concerns SRS concern present, will need diag CEL will need diag, did not read codes TPMS is blinking and will need diag All 4 tires will need replaced, at wear bars and are from 2012 Will require rear brakes shoes, fronts are at 4.5mm, rotors display heating, replacement of front brakes is strongly recommended. Will need engine airfilter Will need Both the stretch serpentine belt and main accessory serpentine belt Will need transmission cooler lines No other issues at this time Complete. 8/29/2023 6:00:07 PM ; Repairs - 8/30/2023 8:50:25 AM Front Brakes Serp Belt AC belt CEL/TPMS/Airbag light diag Recommend 4 tires (7/32 on tread but date code is 12) Engine Air filter Also found driver side door handle sticks Broken exhaust rubber hanger ; Estimate sent - Sent estimate to Chelsea Whitacre for approval. ; Waiting on approval - Contacted Chelsea and sent over the estimate for repairs, her director is out of town and will be back next week, will have to wait til then for approval. ; Estimate approved - Received a call from Chelsea Whitacre to inform that they have approved repairs, moved to "H" status. ; air Filter - 9/25/2023 9:56:46 AM Removed and replaced engine air filter. Had to remove some ducting due to being old and stuck together. ; Belts - 9/25/2023 11:14:16 AM Removed and Replaced AC and drive belt for vehicle. Old belts were cracking severely. ; Door Handle; Exterior - Replaced driver side exterior door handle. Operation verified. Complete. 9/26/2023 5:48:35 PM ; Exhaust Hanger - Rear most exhaust hanger was replaced. Presented as torn in half. Complete. 9/26/2023 6:10:33 PM ; TPMS Diag - Attempted to activate all 4 TPM sensors. Was able to successfully trigger 2/4 sensors. The RR and LF did not trigger. 4 new sensors recommended. Complete. 9/27/2023 1:57:37 PM ; Codes Read Below; not final diag - 9/27/2023 2:01:51 PM Engine P0442; Evap system small leak P0455; Evap System large leak SRS B0084; Front end sensor 2 ; Diagnostic Complete - Found purge valve to not hold vacuum, will begin by replacing purge valve in order to rule out the valve being the only source of leakage. When canister vent and purge valve was commanded closed, system vacuum dropped, point to a purge valve. 9/27/2023 3:12:02 PM ; SRS light - Front right impact sensor bad, will replace sensor and proceed accordingly. 9/27/2023 3:36:04 PM ; Brake replacement started - Started brake job, hardline in FL twisted and snapped. Will need repaired, further action at discretion of managment. 9/27/2023 5:29:04 PM ; Waiting on approval - Called Chelsea Whitacre to update on diagnostic results, left message and will try to contact again. ; Additional repairs approved - Contacted Chelsea Whitacre to inform of additional findings, she has approved all additional repairs, will have parts ordered. ; Parts ~ Cannister Purge Valve & TPMS Sensors Delivered - ; Purge Valve Replaced - Replaced purge valve per previously completed diagnostic. Installed new part, commanded purge seal and no vent. Vacuum built at substantial rate unlike before. Repair Complete. 9/29/2023 1:08:33 PM ; Brake Job completed, need bled - Installed front calipers, rotors, hoses, and a front left brake line due to breakage. Was unable to completely bleed system, will need to be bled the following business day. Utilized DNI fluid 9/29/2023 8:05:03 PM ; TPMS and four tires - 10/3/2023 11:01:44 AM Removed old tires. Replaced and reprogrammed 4 new tpms sensors to vehicle. Installed 4 new tires and balanced all four. Will need to test new tpms once vehicle is back off lift to ensure that programming took properly and is reading with system in vehicle. ; No pedal Diag - 10/4/2023 8:33:16 AM After performing bleeding procedure through scan tool, found that brakes still had no pedal pressure. Found that master cylinder is not holding pressure. Ordered new master cylinder. ; Parts ~ Brake Master Cylinder Delivered - ; Master cylinder replacement began - Removed master cylinder, attempted to bench bleed new unit, was unable with shop provided tool. Attempted to make custom tool, flare leaked on new tool (1/2), will try again following day. 10/4/2023 6:06:40 PM ; Master Cylinder - 10/5/2023 4:08:06 PM Had to order new master cylinder due to new one threads being pulled out on front opening. Could not get line to twist in straight. ; Brakes Complete - 10/6/2023 2:30:27 PM Bled Brakes and had to adjust rear drums. Will need to test drive vehicle once impact sensor is installed to ensure vehicle stops as normal. ; Brakes Complete - 10/9/2023 12:59:23 PM Test drove vehicle and vehicle stops as normal after adjustment and new master cylinder and bleeding procedure. ; Evap Tube & Sensor are in - ; Air bag sensor - Replaced FR crash sensor, did not fix the issue. Will not proceed any further. PCV hose replaced aswell. 10/11/2023 4:37:49 PM ; TPMS - 10/12/2023 9:22:08 AM Relearned system to new TMPS. Light is off and reading pressure correctly. ; Contacted - Contacted Cheslea Whitacre to inform that repairs have been completed. ; 2 Master cylinders on work order -

WORK ORDER: 179907				
ASSET NUMBER: S30586				
Work Order Status: C - C - Closed			Date In:	12/18/2023
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	12/20/2023
ASSET NUMBER INFORMATION				
YEAR: 2008	ORG: Active Fleet		TIRE SIZE:	
MAKE: Chevrolet	DEPT: CC12040 - FAES School of Environment and Natural Resources		ENGINE SIZE:	
MODEL: Silverado	BILL CODE: YYYYYYNNNY1NYY		TRANS:	
LICENSE: S30-586	SITE: Columbus, Ohio		FUEL TYPE: U, NFT	
OPERATOR: Libby Dayton	SERIAL NUMBER: 1GCEC19C38Z188441		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5	
CLASS: Truck, Pickup, ½ Ton			METERS: Mileage - 158618	
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$0.000	TOTAL MISC:	\$0.000	TOTAL COST: \$0.000
NOTES				
Airbag recall - Customer requests to have the vehicle sent off for the airbag recall. ; Vendor pick up - Drivers from Wahlberg Chevrolet came to pick up the asset and take it for the recall repair. ; Recall completed and returned - Airbag recall has been completed and the vehicle was returned. ; Contacted - Contacted Chelsea Whitacre to inform that repairs have been completed.				

WORK ORDER: 186138				
ASSET NUMBER: S30586				
Work Order Status: C - C - Closed			Date In:	01/24/2025
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	03/26/2025
ASSET NUMBER INFORMATION				
YEAR: 2008		ORG: Active Fleet	TIRE SIZE:	
MAKE: Chevrolet		DEPT: CC12040 - FAES School of Environment and Natural Resources	ENGINE SIZE:	
MODEL: Silverado		BILL CODE: YYYYYYNNNY1NYY	TRANS:	
LICENSE: S30-586		SITE: Columbus, Ohio	FUEL TYPE: U, NFT	
OPERATOR:		SERIAL NUMBER: 1GCEC19C38Z188441	ASSET AVAIL CODE: 0000 to 2359 On Call 24/5	
CLASS: Truck, Pickup, ½ Ton			METERS: Mileage - 164198	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
BOROKHOVICH	01/28/2025	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform	2.21	\$0.000
BOROKHOVICH	01/28/2025	Repaired From PM Service / Safety Interior / BagAir Safety / Diagnosis	0.83	\$86.858
BOROKHOVICH	01/29/2025	Repaired From PM Service / Gauge Instrument / LightCheckEngin / Diagnosis	2.61	\$274.021
MADDEN	01/29/2025	Repaired From PM Service / Glass Component / Switch Window / Diagnosis	0.65	\$68.221
BOROKHOVICH	01/29/2025	Repaired From PM Service / Glass Component / Switch Window / Diagnosis	2.51	\$263.317
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$692.417	TOTAL MISC:	\$0.000	TOTAL COST: \$692.417
NOTES				

W300d - WorkOrderDetailsByDate

5/23/2025 8:46:25 AM

Safety inspection - 1/24/2025 9:55:01 AM Vehicle is due for annual safety inspection. ; Needs Estimate - 1/24/2025 Needs fire extinguisher and first aid kit. Check engine light is on, need time to diag. Leak at y-pipe to manifold, both sides. Hole in driver seat. Airbag light is on, need time to diag. Needs wiper blades. Needs both front wheel bearings. Driver window switch does not work for all windows. Each passenger window switch will not activate the window, time to diag. Needs new door decals. Missing 3 of 4 hubcaps. Damage to driver side of vehicle. Battery failed load test. Missing plastic trim piece on tailgate. Front sway bar end links are broken. Oil leak at oil pan and rear main seal. Power steering rack is leaking, lines to cooler and high pressure from pump to rack are also leaking. Transmission lines to cooler are leaking. Rocker panels are rusted. Needs upper and lower ball joints on both sides. ; Safety Inspection - 1/24/2025 Check engine light is on. Airbag light is on. Missing fire extinguisher and first aid kit. Needs wiper blades. Both front wheel bearings extremely loud during test drive. Driver master window switch does not function correctly in all positions. All other window switches are not functioning. Needs new door decals. Missing 3 of 4 hubcaps. Damage to driver side doors and bed. Missing plastic trim piece on liftgate. Battery failed load test. Sway bar end links are broken. Oil leak at pan and rear main seal. Power steering rack is leaking, cooler lines and and high pressure lines also leaking. Rocker panels are rusted . Some rust on tailgate. Needs upper and lower ball joints on both sides, has play. Transmission lines leaking. 35psi front and rear tires. 9/32's remain on front and rear tires. 8mm remain on front brakes. ; Airbag Light Diagnosis - 1/28/2025 Vehicle had fault code B0083 Front end sensor 1- Current fault code. Swapped both front sensors and found that the faulty sensor followed to the new position. Suggest at least on front end sensor but may want to replace both sensors. ; Check Engine Light Diagnosis - 1/29/2025 Check engine light was on during test drive. Fault codes: P0420 Catalyst system efficiency below threshold bank 12 P0442 Evaporative emission (EVAP) system small leak detected- Current DTC P0573 Brake switch circuit 1 high voltage Used smoke machine and found that EVAP line to purge valve at connections on back side of motor to hard line was not fully locked in to position causing leak where it goes in to the hard line. Was able to fully lock in the connection. Used scanner and tested EVAP system after repair, test passed and no other leaks found with smoke tester. P0420 could be showing that vehicle is in need of new catalytic converters. Since vehicle has a lot of miles, it could very well need new converters. Also has exhaust leaks at the manifold to Y-pipe connections, this could be contributing to the efficiency of the catalysts. Vehicle may need converters but hard to tell without fixing other issues first. P0573 Brake switch circuit 1 high voltage is also a history code that could be caused by the failed battery. Need to start with replacing the battery then rechecking the system. Complete ; Assist - 1/29/2025 Helped Brad with power window system diagnosis ; Window Diagnosis - 1/29/2025 Left front window was functioning as it should. Left rear window would work with the driver master switch but not with the left rear window switch. Right rear would work occasionally from the driver switch and not at all with right rear switch. Right front window would not go up or down with any window switch. Was able to find that both rear window switches were faulty and need replaced. Found that the right front window switch was faulty but may have an additional issue once that issue is taken care of. Window motor on right front is able to go up and down when powered manually. Needs left rear, right rear, and right front window switches to start. ; Estimate - 2/5/2025 3:30:54 PM Estimate needs reviewed with department. The cost to repair is higher than the vehicles value. ; Update - Sent email to Chelsea and Joe Messenger recommending disposal.

WORK ORDER: 186698				
ASSET NUMBER: S30586				
Work Order Status: C - C - Closed			Date In:	03/12/2025
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	03/14/2025
ASSET NUMBER INFORMATION				
YEAR: 2008	ORG: Active Fleet		TIRE SIZE:	
MAKE: Chevrolet	DEPT: CC12040 - FAES School of Environment and Natural Resources		ENGINE SIZE:	
MODEL: Silverado	BILL CODE: YYYYYYNNNY1NYY		TRANS:	
LICENSE: S30-586	SITE: Columbus, Ohio		FUEL TYPE: U, NFT	
OPERATOR:	SERIAL NUMBER: 1GCEC19C38Z188441		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5	
CLASS: Truck, Pickup, ½ Ton		METERS: Mileage - 164198		
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
KITTS.12	03/14/2025	Administrative / Unit Services / Vehicle / Decommission	1.04	\$108.792
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$108.792	TOTAL MISC:	\$0.000	TOTAL COST: \$108.792
NOTES				
Decommission - Please complete checklist. ; decommission - got all of the stickers off the plates are off what I couldn't find I put N/A beside it 4:29:24 PM 3/14/2025				

WORK ORDER: 186868				
ASSET NUMBER: S30586				
Work Order Status: C - C - Closed			Date In:	03/26/2025
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	03/26/2025
ASSET NUMBER INFORMATION				
YEAR: 2008	ORG: Active Fleet		TIRE SIZE:	
MAKE: Chevrolet	DEPT: CC12040 - FAES School of Environment and Natural Resources		ENGINE SIZE:	
MODEL: Silverado	BILL CODE: YYYYYYNNNY1NYY		TRANS:	
LICENSE: S30-586	SITE: Columbus, Ohio		FUEL TYPE: U, NFT	
OPERATOR:	SERIAL NUMBER: 1GCEC19C38Z188441		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5	
CLASS: Truck, Pickup, ½ Ton			METERS: Mileage - 164198	
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$0.000	TOTAL MISC:	\$0.000	TOTAL COST: \$0.000

W300d - WorkOrderDetailsByDate

5/23/2025 8:46:25 AM

REPORT PARAMETERS:

Time Zone:	Eastern Standard Time
Start Date:	09/13/2012
End Date:	05/23/2025
Organization:	All Values
Department:	All Values
Asset Number:	S30586
Maint Shop:	All Values
Labor Hours:	Actual Hours
Page Breaks:	Yes
Display Unit Cost or True Cost or Issue Price:	Issue Price

REPORT VERSIONS:

Report Version:	20200729.1200
Script Version:	20210804.1400