Vehicle Inspection Form

Inventory ID:	Asset Number: 0KB1343	Fair Market Value:
Short Description: YearMake	Y Model_MALIBU	
VIN: 1 G 1 Z S 5 7 F 4 7 F 2 8 2 9 1 3 Odometer: 1 6 1 2 6 4 Image: All		
Long Description: This Vehicle: Starts Starts Starts with a Boost & Runs/Driveable Engine- Type: 2.2 L, V Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid Engine Condition: Runs Needs repair is in unknown condition Repairs needed:		
This vehicle was maintained every 5000 Days Hours II Miles Date Removed From Service: 6/12/2025 Maintenance Records: Available II Not Available For Inspection Transmission: II Automatic Manual Speed Condition: Operable Needs repair Brivetrain: II 2 Wheel Drive A Wheel Drive Condition:		
Exterior: Color: Grey. Windows: No Cracked Glass Cracked Minor: Dents Scratches Dings Tire Condition: Poor Tread:#FlatHubcaps # Major Damage to: Paint discoloration.		
Emergency equip: None Has been removed & There are holes in the exterior There are no holes Interior: Color Grey Image Cloth Vinyl Leather Damage to Seats: Dirty. Dirty. Image Cloth Vinyl Leather		
Radio: Stock or Brand & Model: AM _ AM/FM _ AM/FM Cassette _ AM/FM CD AC (Condition: Cold _ Unknown) No AC Air Bags: Driver's Side _ Dual Cruise Control Tilt Steering Remote Mirrors Climate Control Power: Steering Windows Door Locks Seats		
Additional Equipment:		
Location of Asset:		