Vehicle Inspection Form

Inventory ID:	Asset Number: 0KB3575	Fair Market Value:
hort Description: Tear ²⁰⁰⁷ Make CHEVY Model MALIBU		
VIN: 1 G 1 Z S 5 7 F X 7 F 3 0 2 1 2 8 Title Restriction: TY Image: N Odometer: 1 0 1 5 8 3 Image: N Odometers Odometers Odometers Odometers Odometers Odometers N: Image: N Image: N		
Long Description: This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only Engine- Type: 2.2 L, V 4 \blacksquare Gas Diesel Engine Propane/Natural Gas \Box Gas/Electric Hybrid Engine Condition: \blacksquare Runs Needs repair \blacksquare is in unknown condition Repairs needed: $_$		
This vehicle was maintained every 5000 Days Miles Date Removed From Service: 6/5/2025 Maintenance Records: Available Not Available For Inspection Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition Repairs Needed:		
Exterior: Color: White Windows: No Cracked Glass Cracked Minor: Dents Scratches Dings Tire Condition: Fair Tread:#FlatHubcaps # Major Damage to: Rust rings on the roof from lights.		
Decals: □ None □ Have Been Sprayed or ■ Have been Removed & ■ Impressions Remain □ No Impressions Emergency equip: ■ None □ Has been removed & □ There are holes in the exterior □ There are no holes		
Interior: Color Grey Cloth Vinyl Leather Damage to Seats:		
Additional Equipment: Manufacturer Model Serial # Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type Location of Asset: For more information contact: Division of Fleet Management - Annie Smith 502-782-0094		
Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		