Vehicle Inspection Form

Inventory ID:	Asset Number: 0KB1590	Fair Market Value:
Short Description: YearMake	Model Malibu	
I G I Z S 5 7 Odometer: I 6 7 2 5 1	1	8 4 1 Title Restriction: \Box Y IN ometer Accurate Y V N:
Long Description: This Vehicle: Starts with a Boost & Runs/Driveable Engine- Type: 2.2 L, V Image: Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid Engine Condition: Runs Needs repair is in unknown condition Repairs needed:		
Date Removed From Service: 6/10/2025 Maintenance Records: Available Not Available For Inspection Transmission: Automatic ManualSpeed Condition: Operable Needs repair Is Unknown Condition Repairs Needed:		
Exterior: Color: White Windows: No Cracked Glass Cracked Headlight Minor: Dents Scratches Dings Tire Condition: Tread: #Flat Hubcaps # Major Damage to: Drivers side wrecked and light is broken. Additional Damage: Rust spots.		
Decals: \Box None \Box Have Been Sprayed <u>or</u> \blacksquare Have been Removed & \blacksquare Impressions Remain \Box No Impressions Emergency equip: \blacksquare None \Box Has been removed & \Box There are holes in the exterior \Box There are no holes		
Interior: Color Grey Cloth Vinyl Leather Damage to Seats: Dirty and stained.		
Additional Equipment:		
Location of Asset:		