

UAF Facilities Services PM Asset Notes Log

For Asset:
E4183

WO/Ph/Seq	Notes	
UAF16-0013040 001 1	TIMECARD:520691 ITEM:4 Inspect and order tires.	CPLOWMAN Nov 24, 2015
UAF16-0013040 001 2	TIMECARD:522355 ITEM:3 inspect pmi recently performed. Replace fuel filter. Order and replace right washer nozzle. Mount and balance 4 tires. Begin diagnosis of inop lift gate. 26373MI 4184 HR	CPLOWMAN Dec 4, 2015
UAF16-0013040 001 3	TIMECARD:522765 ITEM:4 Diagnose inoperative lift gate. Inspect found hydraulic pump, motor, and electrical severely corroded due to excessive salt intrusion. Advised. Holding at this time.	CPLOWMAN Dec 7, 2015
UAF16-0013040 001 4	Advised to disregard lift gate repair at this time, users would use as a standard tailgate.	CPLOWMAN Dec 9, 2015
UAF16-0017925 001 1	TIMECARD:529145 ITEM:2 Verify heater inoperative. Diagnose order parts.	CPLOWMAN Jan 20, 2016
UAF16-0017925 001 2	TIMECARD:529326 ITEM:5 Replace blower motor. Verify repair.	CPLOWMAN Jan 21, 2016
UAF17-0016575 001 1	TIMECARD:580961 ITEM:6 INSPECT VERIFY TIRE FLAT. SIDE WAS CUT. TAKE SPARE TO VEHICLE AND SWAP AT SUSTAINABLE VILLAGE.	CPLOWMAN Jan 25, 2017
UAF17-0016575 001 2	TIMECARD:583775 ITEM:4 BEGIN TIRE REPLACEMENT.	CPLOWMAN Feb 15, 2017
UAF17-0016575 001 3	TIMECARD:584266 ITEM:4 ORDER REPLACEMENT TIRES. MOUNT AND BALANCE 2 TIRES ROTATE REAR TIRES INSTALL 2 NEW IN REAR. INSPECT. NO ABS LIGHT ON AT THIS TIME TPMS LIGHT ON DUE TO SPARE TIRE ON VEHICLE.	CPLOWMAN Feb 20, 2017
UAF17-0018525 001 1	TIMECARD:584266 ITEM:2 31,555 MILES BEGIN PERFORM PMI-AIR, OIL. ORDER FRONT SHOCKS	CPLOWMAN Feb 20, 2017
UAF17-0018525 001 2	TIMECARD:584272 ITEM:3 COMPLETE PMI. REPLACE 2 FRONT SHOCKS. ROAD TEST NOW OK	CPLOWMAN Feb 20, 2017
UAF18-0007541 001 1	TIMECARD:612235 ITEM:3 GOT ESTIMATES FOR NEW LIFTGATE FROM TWO VENDORS, BOB'S AND TRUCKWELL, BOB'S HAS ONE INSTOCK AND PRICE IS ABOUT THE SAME, PROBABLY GO WITH BOB'S	AGALE Sep 20, 2017
UAF18-0007541 001 2	TIMECARD:616678 ITEM:1 REMOVED DAMAGED AND RUSTED LIFTGATE, INSTALL (MOUNT) NEW LIFTGATE, CLEAN UP AREA AND MOVE VECILES BACK AROUND	AGALE Oct 21, 2017

UAF Facilities Services PM Asset Notes Log

For Asset:
E4183

WO/Ph/Seq	Notes	
UAF18-0007541 001 3	TIMECARD:617479 ITEM:3 INSTALL EXTRA SUPPORT BRACKET ON LIFTGATE, BRACKET HAS TO BE FABBED AND WELDED UP PER INSTALLATION INSTRUCTIONS, FINISHED BRACKET NEEDS TO BE PAINTED FOR PROTECTION FROM ELEMENTS.	AGALE Oct 25, 2017
UAF18-0007541 001 4	TIMECARD:617630 ITEM:3 FINISH UP LIFT GATE INSTALL,	AGALE Oct 26, 2017
UAF18-0015085 001 1	TIMECARD:633528 ITEM:6 34287 MI. 5675 HR. PERFOROM PMI-AIR, OIL. INSPECT RATTLE NOISE IN DRIVERS DOOR. FOUND REAR WINDOW TRACK LOWER MOUNT BROKEN FREE FROM DOOR AND CRACK ON INNER DOOR PANEL. REMOVE DOOR REPAIR CRACKS AND TRACK MOUNT. REINSTALL DOOR VERIFY DOOR ALIGNMENT	CPLOWMAN Mar 5, 2018
UAF18-0025026 001 1	WORK DONE BY VENDOR	EROBINSON Apr 20, 2018
UAF18-0029506 001 1	TIMECARD:645788 ITEM:8 ORDERED PARTS	AGALE Jun 6, 2018
UAF18-0029506 001 2	TIMECARD:647249 ITEM:5 REPLACE PIG TAIL FOR TRAILER PLUG, BUTT CONNECTOR AND SOLDER WIRES, TEST WIRING, RETURN TO SERVICE	AGALE Jun 18, 2018
UAF19-0012149 001 1	TIMECARD:664886 ITEM:6 CAME IN FOR WIPERS AND OPERATOR COMPLAINED ABOUT ON OF THE WASHER SPRAYERS NOT WORKING, FOUND SPRAYER BROKEN, TRIED TO TEMPORARILY REPAIR, NEEDS NEW SPRAYER,	AGALE Oct 30, 2018
UAF19-0012149 001 2	TIMECARD:666025 ITEM:3 REPLACED WINDSHIELD WASHER SPRAYER	AGALE Nov 8, 2018
UAF19-0013006 001 1	TIMECARD:666210 ITEM:5 VERIFY CONCERN TEST BLOCK HEATER AND PAN HEATERS. PAN HEATERS OPERATING NORMALLY. BLOCK HEATER CORD END GETTING WARM DUE TO RESISTANCE INTERNALLY. ORDER 4 WAY BOX, BLOCK HEATER AND CORD,	CPLOWMAN Nov 8, 2018
UAF19-0013006 001 2	TIMECARD:666346 ITEM:5 R AND I STARTER FOR ACCESS, REMOVE AND REPLACE BLOCK HEATER. REPLACE BLOCK HEATER CORD. REPLACE 4 WAY BOX AND CORD ASSEMBLY. REFILL AND PURGE COOLING SYSTEM. ROAD TEST OK. WILL RECHECK FLUID LEVEL AFTER COLD SOAK.	CPLOWMAN Nov 9, 2018
UAF19-0013006 001 3	TIMECARD:666519 ITEM:2 FILL PURGE COOLING SYSTEM VERIFY PROPER LEVEL. ROAD TEST FOUND RIGHT HEAD LIGHT AIMED AT GROUND. INSPECT FOUND LIGHT HOUSING DAMAGED AND POPPED OFF OF VERTICAL ADJUSTER. REMOVE AND REPAIR LIGHT HOUSING REINSTALL HOUSING AND LIGHT VERIFY ALIGNMENT.	CPLOWMAN Nov 12, 2018
UAF19-0013010 001 1	TIMECARD:666346 ITEM:4 VERIFY BACK UP ALARM DAMAGED NON AUDIBLE. REPLACE BACK UP ALARM AND REWIRE DUE TO CORRODED TERMINALS.	CPLOWMAN Nov 9, 2018
UAF19-0013011 001 1	TIMECARD:666210 ITEM:4 37984 MI PERFORM PMI-AIR, OIL.	CPLOWMAN Nov 8, 2018

UAF Facilities Services PM Asset Notes Log

For Asset:
E4183

WO/Ph/Seq	Notes	
UAF19-0015250 001 1	TIMECARD:669763 ITEM:3 REPLACE ALTERNATOR CHARGE BATTERY	CPLOWMAN Dec 7, 2018
UAF19-0019003 001 1	WORK DONE ON P002 DARRELL	EROBINSON Feb 12, 2019
UAF19-0019003 002 1	TIMECARD:675696 ITEM:4 STRAIGHTENED TOMMY GATE LATCH, LUBED UP DRIVER'S DOOR LATCH, HELPED NICOLE SWITCH TOOLS TO LOANER TRUCK.	DGPODVIN Jan 31, 2019
UAF19-0019003 002 2	TIMECARD:676521 ITEM:4 R&R DRIVERS DOOR MIRROR AND R&R DRIVERS SIDE FRONT SEAT BELT.	DGPODVIN Feb 8, 2019
UAF19-0019342 001 1	WORK DONE BY VENDOR	EROBINSON Feb 12, 2019
UAF19-0019991 001 1	LABOR DONE ON P002	EROBINSON Mar 11, 2019
UAF19-0019991 002 1	TIMECARD:677305 ITEM:2 R&R DRIVER SEAT CUSHIN & SEAT COVER.	DGPODVIN Feb 14, 2019
UAF20-0011815 001 1	TIMECARD:708685 ITEM:5 INSPECT, GAUGE READING JUST UNDER 3/4 TANK. MONITOR PIDS. PCM AND INSTRUMENT CLUSTER INDICATE 68 PERCENT FUEL LEVEL. ATTEMPT TO ADD FUEL. NOZZLE KICKED OFF IN LESS THAN A HALF GALLON. MONITOR EVAP PIDS. POSSIBLE VENT RESTRICTION. BEGIN FURTHER DIAGNOSIS.	CPLOWMAN Nov 7, 2019
UAF20-0011815 001 2	TIMECARD:709010 ITEM:2 REPLACE CARBON CANISTER. REASSEMBLE. HOLDING FOR ADDITIONAL UPDATE PARTS FOR VENT KIT.	CPLOWMAN Nov 11, 2019
UAF20-0011815 001 3	TIMECARD:709743 ITEM:2 INSTALL EVAP UPGRADE TUBE TEST DRIVE AND ATTEMPT TO PUT GAS IN IT BUT SUPPOSEDLY IT IS FULL OF GAS WHICH MEANS THE FUEL SENDING UNIT IS PROBABLY BAD CAUSE THE FURL GUAGE IS NOT READING FULL	TRBEASLEY Nov 18, 2019
UAF20-0011815 001 4	TIMECARD:724664 ITEM:5 DIAGNOSE ORDER BLOWER MOTOR	CPLOWMAN Mar 19, 2020
UAF20-0011815 001 5	TIMECARD:731966 ITEM:1 REPLACE HYD. PUMP FOR LIFT GATE AS THE OLD ONE WAS LEAKING	TRBEASLEY May 18, 2020
UAF20-0011815 001 6	TIMECARD:746218 ITEM:3 REPLACE LEFT TAIL LIGHT.	CPLOWMAN Oct 15, 2020

UAF Facilities Services PM Asset Notes Log

For Asset:
E4183

WO/Ph/Seq	Notes	
UAF20-0019358 002 1	TIMECARD:722794 ITEM:3 PM MILES 41683. COOLANT -60 COMPLETE PM SERVICE.	DGPODVIN Mar 3, 2020
UAF21-0009703 001 1	TIMECARD:752424 ITEM:2 PM 44528 MILES -60 COOLANT NO OTHER ISSUES	TRBEASLEY Dec 30, 2020
UAF21-0009703 001 2	TIMECARD:752483 ITEM:2 PM 44528 MILES -60 COOLANT	TRBEASLEY Dec 30, 2020
UAF21-0017433 001 1	TIMECARD:765205 ITEM:4 FOUND A/C CLUTCH BAD. WILL NEED TO GO OUTSIDE SOURCE FOR REPAIRS	JSCANNON May 26, 2021
UAF21-0017553 002 1	THIS CAN BE CLOSED	TRBEASLEY Mar 2, 2022
UAF22-0010148 001 1	TIMECARD:790269 ITEM:2 HOOKED UP SCAN TOOL AND FOUND CODE P0128 STUCK THERMOSTAT CLEARED CODE AND SEE IF IT COMES BACK	TRBEASLEY Mar 25, 2022
UAF22-0011018 001 1	TIMECARD:790269 ITEM:3 PM 49597 MILES 8639 HOURS - 60 COOLANT NEEDS BACK BRAKES	TRBEASLEY Mar 25, 2022
UAF22-0013150 001 1	TIMECARD:790887 ITEM:5 REAR BRAKES	DGPODVIN Apr 4, 2022
UAF22-0013150 001 2	DONE	DGPODVIN Apr 4, 2022
UAF22-0017673 001 1	TIMECARD:801393 ITEM:4 ORDER REPLACEMENT DRIVERS DOOR WINDOW	CPLOWMAN Jun 30, 2022
UAF22-0017673 001 2	WINDOW WAS REPLACED BY A VENDOR. UNKNOWN WHERE IT WAS BILLED TO.	CPLOWMAN Oct 28, 2022
UAF23-0001555 001 1	I THINK THIS WAS DONE.	TRBEASLEY Aug 17, 2022
UAF23-0001555 001 2	DONE ON 8-17-22	TRBEASLEY Aug 18, 2022

UAF Facilities Services PM Asset Notes Log

For Asset:
E4183

WO/Ph/Seq	Notes	
UAF23-0001555 001 3	TIMECARD:804726 ITEM:4 REPLACE FRONT HEAD LIGHT	TRBEASLEY Aug 22, 2022
UAF23-0011029 001 1	TIMECARD:819715 ITEM:4 R AND R BLOWER MOTOR MOTOR WORKS CORRECTLY	DEBURTON Feb 16, 2023
UAF23-0011154 001 1	TIMECARD:822413 ITEM:4 ORDERED THE NEW TIRES FOR E4183	JEMITCHELL3 Mar 28, 2023
UAF23-0011170 001 1	PER JAMES' NOTES, NEEDS NEW FRONT BRAKE PADS AND BLOWER MOTOR	ACKASKIE Feb 28, 2023
UAF23-0011170 001 2	TIMECARD:822580 ITEM:6 55,134 MILES, PM SERVICE. CHECKED OVER ALL INTERIOR COMPONENTS AND REPLACED FLARES, FIRST AID KIT, AND FIRE EXTINGUISHER. WAS NOT ABLE TO FINISH THIS DATE.	JEMITCHELL3 Mar 29, 2023
UAF23-0011170 001 3	TIMECARD:822614 ITEM:4 55,134 MILES, PM SERVICE. CHANGED OIL & FILTER, AIR FILTER, FLARES, FIRE EXTINGUISHER, FIRST AID KIT. ALL JOINTS HAVE BEEN GREASED AS NEEDED. THE ONLY ISSUES NOTED WITH VEHICLE: NEEDS FRONT BRAKE PADS, NEEDS NEW BLOWER MOTOR. ALL OTHER COMPONENTS WERE IN ACCEPTABLE CONDITION.	JEMITCHELL3 Mar 30, 2023
UAF23-0011170 002 1	WORK REQUEST ADDED VIA IPAD 182759	AANDRUS Apr 4, 2023
UAF23-0011545 001 1	ORDERED NEW STEERING WHEEL COVER WORK COMPLETED	DEBURTON Mar 3, 2023
UAF23-0011545 001 2	TIMECARD:822614 ITEM:2 ORDERED AND INSTALLED STEERING WHEEL COVER.	JEMITCHELL3 Mar 30, 2023
UAF23-0011548 001 1	TIMECARD:820320 ITEM:3 STARTED CLEANING BED OUT TO SEE WHAT NEEDED REPAIR IN THE BED	DEBURTON Feb 27, 2023
UAF23-0011548 001 2	JAMES USED A PIECE OF PLWOOD TO COVER THE HOLES WORK COMPLETED	DEBURTON Mar 3, 2023
UAF23-0011548 001 3	TIMECARD:822614 ITEM:3 ASSISTED CARPENTERS SHOP WITH INSTALLING PLATE TO THE BACK OF THE BED	JEMITCHELL3 Mar 30, 2023
UAF23-0011548 002 1	HAD SCRAP MATERIAL, IT DIDNT TAKE ANY TIME SO IM CANCELING THIS WORK ORDER .	JEMITCHELL4 Apr 19, 2023

UAF Facilities Services PM Asset Notes Log

For Asset:
E4183

WO/Ph/Seq	Notes	
UAF23-0014022 001 1	TIMECARD:824882 ITEM:4 REMOVED AND REPLACED BRAKE PADS. ENSURED NEW PADS WORK AS INTENDED.	JEMITCHELL3 Apr 27, 2023
UAF23-0015433 001 1	TIMECARD:825809 ITEM:2 REPLACED ALTERNATOR. BATTERY HELD GOOD CHARGE AND NO CHECK ENGINE LIGHTS APPEARED.	JEMITCHELL3 May 8, 2023
UAF23-0016608 001 1	TIMECARD:827879 ITEM:1 IT STARTED AND BROUGHT DOWN THE SHOP RESET THE CODES AND NOW NO OTHER ISSUES DONE	TRBEASLEY Jun 6, 2023
UAF24-0000632 001 1	TIMECARD:832174 ITEM:4 FASTENED DOWN NEW TAIL LIGHT SO VEHICLE CAN BE USED UNTIL IT'S SCHEDULED FOR GETTING BODYWORK.	JEMITCHELL3 Jul 27, 2023
UAF24-0001386 001 1	TIMECARD:832619 ITEM:3 HAD TO GO TO HOT LICKS WHERE IT STOPPED RUNNING OR WAS SOUNDING LIKE CRAP BUT IT STARTED AND GOT IT BACK TO SHOP, HAS ALL KIND OF DTCS THE MAIN ONE THAT IS CAUSING ISSUES IS THE OXYGEN SENSORS	TRBEASLEY Aug 3, 2023
UAF24-0001386 001 2	TIMECARD:837986 ITEM:2 BROUGHT VEHICLE IN AND REPLACED O2 SENSORS. ENSURED VEHICLE DROVE FINE AFTERWARDS.	JEMITCHELL3 Oct 2, 2023
UAF24-0011604 001 1	TIMECARD:850555 ITEM:3 56,927 MILES EXCHANGED: AIR FILTER, FUEL FILTER, OIL & FILTER	JEMITCHELL3 Mar 11, 2024
UAF24-0012966 001 1	TIMECARD:850648 ITEM:2 BROUGHT THE VEHICLE IN TO PERFORM REPAIR. THE REVERSE LIGHT SOCKET HAS NOT SHOWN UP YET, SO I ONLY CHANGED THE BLOWER MOTOR OUT.	JEMITCHELL3 Mar 12, 2024
UAF24-0019034 001 1	TIMECARD:862590 ITEM:3 GOT THE LIFT GATE UN-JAMMED AND WORKING AS IT SHOULD PUT LOTS OF WD-40 ON IT DONE	TRBEASLEY Jul 16, 2024
UAF25-0001039 001 1	TIMECARD:863309 ITEM:4 HAD SEVERAL CODES BUT I TOOK IT OUT ON A FEW TEST DRIVES AND IT SEEMS TO ONLY SHUDDER WHEN IT IS WANTING MORE FUEL SO I THINK IT MAY BE A FUEL FILTER OR EVEN A FUEL PUMP I TOLD THE USER TO TAKE IT AND USE IT ON CAMPUS TILL WE COULD DIG IN TO IT MORE	TRBEASLEY Jul 24, 2024
UAF25-0001039 001 2	TIMECARD:864598 ITEM:2 TEST DROVE AFTER REPLACING FUEL FILTER NO ISSUES FOUND IF PROBLEM PERSISTS WILL BE MOVING FORWARD WITH FUEL PUMP REPLACEMENT	JDSTAMEY Aug 7, 2024
UAF25-0013082 001 1	TIMECARD:883358 ITEM:2 58,061 MILES; 10,186 ENGINE HOURS EXCHANGED: AIR FILTER, OIL & FILTER	JEMITCHELL3 Feb 20, 2025
UAF25-0013082 001 2	TIMECARD:883411 ITEM:3 ASSIST WITH GETTING VEHICLE IN SHOP	CPLOWMAN Feb 21, 2025

UAF Facilities Services PM Asset Notes Log

For Asset:
E4183

WO/Ph/Seq	Notes	
UAF25-0013082 001 3	REFERENCE WORK ORDER UAF25-0015079 FOR FOLLOWUP REPAIRS.	KNUSS Mar 24, 2025
UAF25-0015079 001 1	TIMECARD:887830 ITEM:2 GOT IT IN THE SHOP TO DO SOME WORK ON IT	TRBEASLEY Apr 7, 2025
UAF25-0015079 001 2	TIMECARD:887857 ITEM:4 REPLACE RIGHT FRONT BRAKE CALIPER AND BLEED THE LINES REPLACE REAR SIDE E NUMBERS APPLY SOME NO SLIP TRACTION TAPE ON THE RUNNING BOARDS THE RUNNING BOARD ITSELF IS FINE	TRBEASLEY Apr 7, 2025
UAF26-0005024 001 1	TIMECARD:887857 ITEM:4 REPLACE RIGHT FRONT BRAKE CALIPER AND BLEED THE LINES REPLACE REAR SIDE E NUMBERS APPLY SOME NO SLIP TRACTION TAPE ON THE RUNNING BOARDS THE RUNNING BOARD ITSELF IS FINE SURPLUS	JDSTAMEY Nov 6, 2025
UAF26-0005082 001 1	TIMECARD:906255 ITEM:3 MULTIPLE ISSUES CODES ARE AS FOLLOWS P0128- THERMOSTAT STUCK OPEN P0420- BANK1 THRESHOLD	JDSTAMEY Oct 13, 2025
UAF26-0005082 001 2	WE WOULD RECOMMEND THE BED REPLACED, TRANSMISSION TO BE REPLACED, ALONG WITH OTHER MAJOR WORK, RECOMMEND SURPLUSING VEHICLE.	SLBOONEGRANT Oct 28, 2025
UAF26-0005621 001 1	TIMECARD:906058 ITEM:2 REPLACE RIGHT REAR TAIL LIGHT BULB.	CPLOWMAN Oct 9, 2025
UAF26-0007138 001 1	TIMECARD:908106 ITEM:4 EMPTY AND STRIP VEHICLE FOR SURPLUS	CPLOWMAN Nov 3, 2025