

Work Order

Work Order #: 86515
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 55.00

Date Opened: 23. Nov 2020.
Date Closed: 4. Dec 2020.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC00	ACCESSORIES GENERAL	Install pedal extension. Make floor spacer.	[REDACTED]	Drill and tap pedal, install extension. Have floor spacer made, install rubber mat and fit to machine.			8.00	\$1,104.00	\$1,104.00
Total:					0	\$0.00	8.00	\$1,104.00	\$1,104.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT00	OTHER ACTIVITIES - GENE	Operator lost fuel cap	[REDACTED]	Supply cap					\$0.00
				FILLER CAP AT342385 CAH-643	1	\$223.90			\$223.90
Total:					1	\$223.90	0	\$0.00	\$223.90

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EL00	ELECTRICAL - GENERAL REPAIRS	Relocate block heater cord	[REDACTED]	install new block heater cord with out side recepticle.			4.00	\$552.00	\$552.00
				LRG HOLE SAW ARBOR 49-56-7250 CAH-643 TONY	1	\$21.15			\$21.15
				10' W/PROOF POWER CORD 860-6013 CAH-643 TONY	1	\$90.61			\$90.61
Total:					2	\$111.76	4.00	\$552.00	\$663.76

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	Bolts loose on blade		Tighten bolts			1.00	\$138.00	\$138.00
Total:					0	\$0.00	1.00	\$138.00	\$138.00
Total:					3	\$335.66	13.00	\$1,794.00	\$2,129.66

Work Order

Work Order #: 86786
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: ZZZRHAINDS, ZZZBEN
Odometer:
Hours: 258.00

Date Opened: 21. Dec 2020.
Date Closed: 22. Dec 2020.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	Blade controls not working properly		Sublet to Brandt for warranty. replade solenoid, joystick and valve section.					\$0.00
Total:					0	\$0.00	0	\$0.00	\$0.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EL00	ELECTRICAL - GENERAL REPAIRS	Front and rear work lights not working randomly		Sublet to Brandt. Warranty					\$0.00
Total:					0	\$0.00	0	\$0.00	\$0.00
Total:					0	\$0.00	0	\$0.00	\$0.00

Work Order

Work Order #: 86874
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: CONTANT, MARC
Odometer:
Hours: 401.00

Date Opened: 5. Jan 2021.
Date Closed: 6. Jan 2021.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT15	ENGINE SERVICE AND INSPECTION	went ot snow dump to inspect cat to be serviced		Tony: Help Mark perform service @ snow dump. changed oil and filter 25lt 5w40, replaced both primary air filters also replaced both cab filters hyd tank level ok.			8.70	\$1,200.60	\$1,200.60
				OIL SYN 5W40 5 LITER 1110016 CAH-643 MARC	6	\$222.75			\$222.75
				FILTER AIR RECIRCULATION JD# CAH-643 MARC	1	\$88.98			\$88.98
				FILTER CAB AIR AT191102 P621643 CAH-643 MARC	1	\$9.83			\$9.83
				OIL FILTER CAH-643 MARC	1	\$70.64			\$70.64
				Total:	9	\$392.21	8.70	\$1,200.60	\$1,592.81
				Total:	9	\$392.21	8.70	\$1,200.60	\$1,592.81

Work Order

Work Order #: 87237
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: CONTANT, MARC
Odometer:
Hours: 899.00

Date Opened: 16. Feb 2021.
Date Closed: 7. May 2021.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT15	ENGINE SERVICE AND INSPECTION	engine service		changed oil and filter 25lt 5w40, air filters ok cab filter ok, all fluid levels, ok hyd tank level ok.			3.90	\$538.20	\$538.20
				OIL SYN 5W40 5 LITER	5	\$188.38			\$188.38
				1110016 CAH-643 MARC					
				OIL FILTER DZ101884 CAH-643 MARC	1	\$51.25			\$51.25
				Total:	6	\$239.62	3.90	\$538.20	\$777.82

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
FF00	FUEL SYSTEM REPAIRS	fuel filter service		replaced all three fuel filters			2.20	\$303.60	\$303.60
				FILTER FUEL PRIMARY, RE539465 CAH-643 MARC	1	\$133.14			\$133.14
				FUEL FILTER AT365870 CAH-643 MARC	1	\$55.67			\$55.67
				FILTER FUEL DZ112918 CAH-643 MARC	1	\$141.89			\$141.89
				Total:	3	\$330.70	2.20	\$303.60	\$634.30

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT43	OIL SAMPLE, ALL MAJOR	TO RESET PM SCEDULE		TO RESET PM SCEDULE					\$0.00

COMPONENTS

Total:	0	\$0.00	0	\$0.00	\$0.00
Total:	9	\$570.32	6.10	\$841.80	\$1,412.12

Work Order

Work Order #: 87316
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 1120.00

Date Opened: 24. Feb 2021.
Date Closed: 25. Feb 2021.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	Cust requests to flip cutting edges	[REDACTED]	Drive to unit @ snow dump. Outside cutting edges appear to not be flippable as the bolt pattern does not line up. Center section cutting edges appear to be flippable. Ordered left & right outer cutting edges. Drive back out to unit & install new outer cutting edges and flip center section cutting edges.			4.25	\$586.50	\$586.50
				BOLT PLOW 3/4" X 2 1/2" 750X250 CAH-643 KELSON	50	\$79.10			\$79.10
				NUT FOR PLOW BOLT 3/4" 750 CAH-643 KELSON	50	\$35.03			\$35.03
				END BIT T187244X CAH-643 KELSON	1	\$115.44			\$115.44
				END BIT T187243X CAH-643 KELSON	1	\$115.44			\$115.44
				BOLT PLOW 3/4" X 2 1/2" 750X250 CAH-643 KELSON	2	\$3.17			\$3.17
				NUT FOR PLOW BOLT 3/4" 750 CAH-643 KELSON	5	\$3.47			\$3.47

Total:	109	\$351.65	4.25	\$586.50	\$938.15
Total:	109	\$351.65	4.25	\$586.50	\$938.15

Work Order

Work Order #: 87469
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 1397.00

Date Opened: 12. Mar 2021.
Date Closed: 17. Mar 2021.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EN00	ENGINE REPAIRS	Leaking fuel from bottom sight glass of filter	[REDACTED]	Brian - march 15, travel to snow dump and inspect. has steady drip from lower seal on fuel seperator. drained fuel and inspected. cant find any fault. replaced filter and seal. primmed unit and ran. no leaks.			4.80	\$662.40	\$662.40
				TOWEL PAPER 35401 CAH-643 RANDY	2	\$17.41			\$17.41
				BATTERY 6 VOLT SQUARE LANTERN 1209 CAH-643 RANDY	1	\$3.31			\$3.31
				FILTER FUEL PRIMARY, RE539465 BF9866-O CAH-643 BRI	1	\$133.14			\$133.14
Total:					4	\$153.87	4.80	\$662.40	\$816.27
Total:					4	\$153.87	4.80	\$662.40	\$816.27

Work Order

Work Order #: 88289
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: ZZLUSSIER, ZZKALVIN
Odometer: 0.00
Hours: 1367.00

Date Opened: 31. May 2021.
Date Closed: 9. Jun 2021.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT03	TRANSMISSION/6 WD CALIBRATION	due		not safe in shop yard needs to be done at snow dump			2.50	\$345.00	\$345.00
Total:					0	\$0.00	2.50	\$345.00	\$345.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT15	ENGINE SERVICE AND INSPECTION	due		completed engine service			1.30	\$179.40	\$179.40
				FILTER OIL DZ101884 CAH-643 KALVIN	1	\$45.91			\$45.91
				OIL 15W40 4L 1126651 CAH-643 KALVIN	5	\$107.38			\$107.38
				OIL SAMPLE PROGRAM JD AT346594 CAH-643 KALVIN	1	\$24.03			\$24.03
				GLOVES XL GREASE MONKEY CAH-643 KALVIN	1	\$37.53			\$37.53
Total:					8	\$214.85	1.30	\$179.40	\$394.25

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT43	OIL SAMPLE, ALL MAJOR COMPONENTS	due	ZZLUSSIER, ZZKALVIN	done			0.50	\$69.00	\$69.00
				OIL SAMPLE PROGRAM JD AT346594 CAH-643	1	\$24.03			\$24.03

KALVIN

Total:	1	\$24.03	0.50	\$69.00	\$93.03
--------	---	---------	------	---------	---------

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	transport from	ZZZRHAINDS, ZZZBEN	done					\$0.00
				HAULING 850 DOZER CAH -643 BEN	1	\$500.00			\$500.00
Total:					1	\$500.00	0	\$0.00	\$500.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EL00	ELECTRICAL - GENERAL REPAIRS	Batteries dead	ZZZRHAINDS, ZZZBEN	starts fine			2.00	\$276.00	\$276.00
Total:					0	\$0.00	2.00	\$276.00	\$276.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT14	CVIP INSPECTION	due	ZZZRHAINDS, ZZZBEN	completed inspection			4.00	\$552.00	\$552.00
Total:					0	\$0.00	4.00	\$552.00	\$552.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EN00	ENGINE REPAIRS	took two jugs coolant to top up tank, inspect for leaks	REISWIG, BRIAN	cant find leak			1.00	\$138.00	\$138.00
				ANTIFREEZE LONGLIFE RED 3.78L GD3000 CFH-643 BRIAN	1	\$16.53			\$16.53
Total:					1	\$16.53	1.00	\$138.00	\$154.53

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO00	BODY - GENERAL REPAIRS NON-ACCIDENT RELATED	Bolts missing on engine compartments. the ones still there loosen up every day. See Ben if unsure of location		replaced bolt			0.30	\$41.40	\$41.40
Total:					0	\$0.00	0.30	\$41.40	\$41.40

Total:	11	\$755.42	11.60	\$1,600.80	\$2,356.22
--------	----	----------	-------	------------	------------

Work Order

Work Order #: 88501
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 1367.00

Date Opened: 21. Jun 2021.
Date Closed: 21. Jun 2021.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EN00	ENGINE REPAIRS	inspect for coolant leak	[REDACTED]	pressure tested sytem to cap pressure 18 lbs. system looses pressure. cant see leaks. hose from bottom of resivour has coolant traces on it. tried to tihgten clamp and hose blew off. found clamp had been stripped out. tightened lower clamp and installed new clamp on upper side. filled with coolant and pressure tested. bottom clamp leaking now. removed hose and found pin hole from clamp. cut end off installed new clamp and tightened. pressure tested 1hr. held pressure at 17 lbs. found a clamp had broken off rad causing it to wear int rad. brandt coming to do warrenty on unit			4.50	\$621.00	\$621.00
				ANTIFREEZE LONGLIFE RED 3.78L GD3000 CAH-643 BRIAN	2	\$33.48			\$33.48
				CLAMP HOSE SIZE 20 EXTENDED TONGUE CAH	2	\$2.79			\$2.79

-643 BRIAN

Total:	4	\$36.27	4.50	\$621.00	\$657.27
Total:	4	\$36.27	4.50	\$621.00	\$657.27

Work Order

Work Order #: 88813
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 1370.00

Date Opened: 22. Jul 2021.
Date Closed: 22. Jul 2021.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	hyd oil low	[REDACTED]	top up hyd oil with 4lt TDH			0.70	\$96.60	\$96.60
				OIL TXM HYD BULK 5190 CAH-643 MARC	4	\$15.69			\$15.69
				Total:	4	\$15.69	0.70	\$96.60	\$112.29
				Total:	4	\$15.69	0.70	\$96.60	\$112.29

Work Order

Work Order #: 88942
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 1370.00

Date Opened: 9. Aug 2021.
Date Closed: 31. Aug 2021.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	Transport from service centre to South bear creek	[REDACTED]	Sublet to Mark's hauling					\$0.00
				HAUL CAH-643 TO SBC BEN	1	\$420.00			\$420.00
				Total:	1	\$420.00	0	\$0.00	\$420.00
				Total:	1	\$420.00	0	\$0.00	\$420.00

Work Order

Work Order #: 89218
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 1375.00

Date Opened: 13. Sep 2021.
Date Closed: 30. Sep 2021.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT03	TRANSMISSION/6 WD CALIBRATION	transmission calibration not performed properly. set codes in system. had to be completed by brandt	[REDACTED]	Sublet to Brandt Inv 1780146					\$0.00
				CALIBRATE TRANSMISSION CAH-643	1	\$226.53			\$226.53
				Total:	1	\$226.53	0	\$0.00	\$226.53
TR11	TOW/TRANSPORT/ DELIVERY	Mover unit from south bear creek to snow dump	[REDACTED]	Sublet to Mark's hauling					\$0.00
				HAUL JD CRAWLER UNIT CAH-643 BEN	1	\$560.00			\$560.00
				Total:	1	\$560.00	0	\$0.00	\$560.00
				Total:	2	\$786.53	0	\$0.00	\$786.53

Work Order

Work Order #: 89477
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 1405.80

Date Opened: 19. Oct 2021.
Date Closed: 22. Nov 2021.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO00	BODY - GENERAL REPAIRS NON-ACCIDENT RELATED	Needs lower engine door hinge on lefthand side.	[REDACTED]	Nov 8/21 replace lower hinge TW			0.75	\$103.50	\$103.50
				HINGE AT210600 CAH-643 RANDY	1	\$97.56			\$97.56
				Total:	1	\$97.56	0.75	\$103.50	\$201.06
Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO11	HEATING, AIR CONDITIONING REPAIRS	Concern from Operator about air circulation at cab floor level.	[REDACTED]	Ran unit until it got to operation temperature and found there was good air circulation throughout the interior cab. Also depended on what air vents were closed and which ones were open effected the air circulation			2.80	\$386.40	\$386.40
				Total:	0	\$0.00	2.80	\$386.40	\$386.40
				Total:	1	\$97.56	3.55	\$489.90	\$587.46

Work Order

Work Order #: 89656
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 1406.00

Date Opened: 9. Nov 2021.
Date Closed: 9. Nov 2021.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EN00	ENGINE REPAIRS	engine will not start	[REDACTED]	batteries are dead. went to boost the machine but the welder/generator would not start. returned to the shop and repaired the weld/gen. back on site i charged the unit until the generator ran out of gas, but was enough to start the machine			2.00	\$276.00	\$276.00
Total:					0	\$0.00	2.00	\$276.00	\$276.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
CH00	CHASSIS/SUSPENSION REPAIRS	remove seized bolts for the track adjustment cover.	[REDACTED]	attempted to remove the bolt but it broke off, tried to take it out with heat and a chisel, no luck. back to the shop for more tools. drilled out the bolt and clean the threads. checked the other side and it was seized as well but i was lucky and worked it out.			2.25	\$310.50	\$310.50
Total:					0	\$0.00	2.25	\$310.50	\$310.50

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
-------------	-------------	-----------------	----------	-----------------	-----------	-------	------------	--------------	-------

TR11	TOW/TRANSPORT/ DELIVERY	travel to and from the snow dump		went back and forth three times.	2.50	\$345.00	\$345.00
Total:					0	\$0.00	\$345.00
Total:					0	\$0.00	\$931.50

Work Order

Work Order #: 89862
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 1406.00

Date Opened: 30. Nov 2021.
Date Closed: 3. Dec 2021.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC00	ACCESSORIES GENERAL	Replace all blade cutting edges	[REDACTED]	Cutting edges & Hardware were purchased previously. Drive to unit @ snow dump. Started changing cutting edges, one wrong cutting edge was provided by Brandt. Drive to Brandt to pick up correct cutting edge. Drive back to unit & install last cutting edges. BOLT PLOW 3/4" X 2 1/2" 750X250 CAH-643 GARY	35	\$56.65	4.00	\$268.00	\$268.00
				NUT FOR PLOW BOLT 3/4" 7502H CAH-643 GARY	35	\$24.93			\$24.93
				CUTTING XY T425102 CAH- 643 GARY	1	\$971.12			\$971.12
				CUTTING T187987X CAH- 643 GARY	1	\$170.51			\$170.51
				CUTTING XY T187987X CAH-643 GARY	1	\$170.51			\$170.51
				DURAMAX T187244X CAH- 643 GARY	1	\$121.99			\$121.99
				DURAMAX T187243X CAH- 643 GARY	1	\$110.45			\$110.45
Total:					75	\$1,626.16	4.00	\$268.00	\$1,894.16

Total:	75	\$1,626.16	4.00	\$268.00	\$1,894.16
--------	----	------------	------	----------	------------

Work Order

Work Order #: 90142

Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 1406.00

Date Opened: 30. Dec 2021.
Date Closed: 6. Jan 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	hydraulic leak	[REDACTED]	inspect unit. leaking from hose going to dozer blade. removed covers to access hose, ran unit and found pin hole in hose. tried to remove line but it was seized. used heat and penetrating oil to free hose up. upon removal it pulled threads. couldnt get correct metal line, was in usa. built rubber line and installed as tempary fix. had to paracute in unit and use heater to work in -35 temps. extra time required			19.55	\$2,697.90	\$2,697.90
				GLOVES WINTER XL BDG 30-9-473TFL-XL Steve	1	\$12.25			\$12.25
				Hydraulic hose & O Rings T77932 CAH-643 Brain	1	\$146.10			\$146.10
				OIL TUBE CY AT485078 CAH-643 BRIAN	1	\$109.20			\$109.20
				1/2" 2 WIRE HYD HOSE GA8M2T CAH-643 STEVE	31	\$11.47			\$11.47
				FM ORS STR GANG58-10-8 CAH-643 STEVE	2	\$38.94			\$38.94

1.04 ID SPRING GUARD	30	\$30.90			\$30.90
GASGR-1055 CAH-643					
STEVE					
Total:	66	\$348.86	19.55	\$2,697.90	\$3,046.76

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	travel to snow dump		travel b ack and forth to dump twice			3.00	\$414.00	\$414.00
				Total:	0	\$0.00	3.00	\$414.00	\$414.00
				Total:	66	\$348.86	22.55	\$3,111.90	\$3,460.76

Work Order

Work Order #: 90283
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 2140.00

Date Opened: 12. Jan 2022.
Date Closed: 12. Jan 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT15	ENGINE SERVICE AND INSPECTION	engine service required	[REDACTED]	changed engine oil and filter. added 25 liters of 0w/40. was going to change the air filters but they were the wrong ones.			4.00	\$552.00	\$552.00
				FILTER OIL B7335MPG BALDWIN CAH-643 TREVOR	1	\$25.14			\$25.14
				OIL SYNTHETIC 0W40 18.9L KLHD2580 CAH-643 MORGAN2	1	\$155.24			\$155.24
				GREASE EXTREME PRESSURE DELO EP2 CAH-643 TREVOR	1	\$7.96			\$7.96
Total:					3	\$188.35	4.00	\$552.00	\$740.35

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO00	BODY - GENERAL REPAIRS NON-ACCIDENT RELATED	1)side guards have bolts missing. 2) LH side guard is cracked.	[REDACTED]	1) installed bolts as required. the machine will have to shut down for a few hours to take the panel off and repaired					\$0.00
Total:					0	\$0.00	0	\$0.00	\$0.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
-------------	-------------	-----------------	----------	-----------------	-----------	-------	------------	--------------	-------

TR11	TOW/TRANSPORT/ DELIVERY	travel to and from the snow dump		travel		0.75	\$103.50	\$103.50	
Total:					0	\$0.00	0.75	\$103.50	\$103.50
Total:					3	\$188.35	4.75	\$655.50	\$843.85

Work Order

Work Order #: 90284
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 2136.00

Date Opened: 12. Jan 2022.
Date Closed: 1. Feb 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT00	OTHER ACTIVITIES - GENE	Unit requires tracks to be corked	[REDACTED]	Sublet to industrial metal works					\$0.00
				REPAIR PANEL CAH-643 BEN	1	\$1,190.00			\$1,190.00
				LUG 3/X8X ECUT3 CAH- 643 BEN	250	\$555.00			\$555.00
				LUG 3/8" CAH-643 BEN	150	\$333.00			\$333.00
				Total:	401	\$2,078.00	0	\$0.00	\$2,078.00
				Total:	401	\$2,078.00	0	\$0.00	\$2,078.00

Work Order

Work Order #: 90352
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 2140.00

Date Opened: 19. Jan 2022.
Date Closed: 26. Jan 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	hydraulic leak	[REDACTED]	Hydraulic leak on hose for blade tilt fitting broken off. remove hose and install replacement hose			1.80	\$120.60	\$120.60
				FM ORS STR GANG58-10-8 CAH-643 STEVE	2	\$38.94			\$38.94
				1/2" 2 WIRE HYD HOSE GA8M2T CAH-643 STEVE	32	\$11.84			\$11.84
				1.04 ID SPRING GUARD GASGR-1055 CAH-643 STEVE	32	\$32.96			\$32.96
				OIL HYD TDH 18.9L KLHF8080 CAH-643 STEVE	2	\$162.55			\$162.55
Total:					68	\$246.29	1.80	\$120.60	\$366.89

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC12	RADIO EQUIPMENT REPAIRS	radio not funtioning properly	[REDACTED]	Checked out two way radio found no powering up. checked wires to battery found both wires were broken off at battery terminals. in stall new ends on wires and install on terminals . tested radio			1.40	\$93.80	\$93.80

make sure functioning properly

Total:	0	\$0.00	1.40	\$93.80	\$93.80
Total:	68	\$246.29	3.20	\$214.40	\$460.69

Work Order

Work Order #: 90382
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 2296.00

Date Opened: 21. Jan 2022.
Date Closed: 24. Jan 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	blown hyd line	[REDACTED]	remove & replace both hyd line for tilt shift ,got hoses made at lemans,put hoses on test no leaks top up hyd oil put in 40 lts in not enough had to come back to shop & get more hyd oil & top up unit all good			5.20	\$348.40	\$348.40
				OIL HYD TDH 18.9L KLHF8080 CAH-643 NORM	2	\$162.55			\$162.55
				OIL HYDRAULIC BULK 226606990 CAH-643 NORM	40	\$157.32			\$157.32
				GLOVES HYFLEX SIZE 9 ANS 11-801-9 CAH-643 NORM	2	\$7.88			\$7.88
				TOWEL PAPER 35401 CAH-643 NORM	2	\$17.96			\$17.96
				HOSE ASSEMBLY CAH-643 NORM	2	\$511.04			\$511.04
Total:					48	\$856.74	5.20	\$348.40	\$1,205.14
Total:					48	\$856.74	5.20	\$348.40	\$1,205.14

Work Order

Work Order #: 90429
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 2393.00

Date Opened: 27. Jan 2022.
Date Closed: 4. Feb 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	Track tension cover missing	[REDACTED]	Get Kelson to fabricate temporary cover and order replacement cover. Install temporary cover.			2.00	\$134.00	\$134.00
				PETTY CASH	1	\$10.50			\$10.50
				PLATE T347825 CAH-643	2	\$213.02			\$213.02
				Total:	3	\$223.52	2.00	\$134.00	\$357.52
				Total:	3	\$223.52	2.00	\$134.00	\$357.52

Work Order

Work Order #: 90677
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 2815.00

Date Opened: 25. Feb 2022.
Date Closed: 25. Feb 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT15	ENGINE SERVICE AND INSPECTION	engine service	[REDACTED]	changed oil and filter 25lt 5w40, top up hyd tank with klondyk hyd oil. antifreeze level ok, Note engine oil filter washing.			5.10	\$341.70	\$341.70
				OIL SAMPLE PROGRAM JD AT346594 CAH-643 MARC	4	\$132.10			\$132.10
				OIL TDH 4.73L KLHF8060 CAH-643 MARC	1	\$25.12			\$25.12
				OIL SYNTHETIC 5W40 3.785L 257002464 CAH-643 MARC	5	\$168.59			\$168.59
				FILTER OIL B7335MPG BALDWIN CAH-643 MARC	1	\$26.71			\$26.71
				Total:	11	\$352.52	5.10	\$341.70	\$694.22

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
FF00	FUEL SYSTEM REPAIRS	fuel filter service	[REDACTED]	replaced all three fuel filters.			1.00	\$67.00	\$67.00
				FILTER FUEL FS1093 FLEETGUARD CAH-643 MARC	1	\$146.58			\$146.58
				FILTER FUEL, PRIMARY FS1091 FLEETGUARD	1	\$55.63			\$55.63

CAH-643 MAR					
FILTER FUEL BF46100O	1	\$58.37			\$58.37
BALDWIN CAH-643 MARC					
Total:	3	\$260.58	1.00	\$67.00	\$327.58

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT43	OIL SAMPLE, ALL MAJOR COMPONENTS	oil samples		engine tranny and hyd tank oil samples to be sent out			0.50	\$33.50	\$33.50
Total:					0	\$0.00	0.50	\$33.50	\$33.50
Total:					14	\$613.10	6.60	\$442.20	\$1,055.30

Work Order

Work Order #: 90715
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 2815.00

Date Opened: 1. Mar 2022.
Date Closed: 10. Mar 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT05	WHEEL STUD REPLACEMENT	Unit needs re corking	[REDACTED]	Sublet to industrial metal works					\$0.00
				CORK SNOW DUMP DOZER CAH-643 BEN	9	\$1,071.00			\$1,071.00
				Total:	9	\$1,071.00	0	\$0.00	\$1,071.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	Cutting edges need replaced	[REDACTED]	ordered parts brian march 9. flipped three middle blades and installed two new corners. used all new hardware			2.50	\$167.50	\$167.50
				BOLT PLOW 3/4" X 2 1/2" 750X250 CAH-643 KELSON	50	\$86.96			\$86.96
				NUT FOR PLOW BOLT 3/4" 7502HCAH-643 KELSON	50	\$35.94			\$35.94
				DURA-MAXX T187243 CAH-643 BEN	1	\$121.99			\$121.99
				DURA-MAX T187244 CAH-643 BEN	1	\$121.99			\$121.99
				CUTTING T425102 CAH-643 BEN	1	\$971.12			\$971.12
				CUTTING T187987 CAH-643 BEN	2	\$414.94			\$414.94

DURA-MAXX T187243 CAH -643 BRIAN	1	\$121.99			\$121.99
DURA-MAXX T187244 CAH -643 BRIAN	1	\$121.99			\$121.99
KIT HDW PB750250ITR CAH-643 BRIAN	12	\$67.08			\$67.08
WASHER 5P8248 CAH-643 BRIAN	12	\$7.32			\$7.32
Total:	131	\$2,071.33	2.50	\$167.50	\$2,238.83
Total:	140	\$3,142.33	2.50	\$167.50	\$3,309.83

Work Order

Work Order #: 90865
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 2815.00

Date Opened: 7. Mar 2022.
Date Closed: 28. Mar 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT05	WHEEL STUD REPLACEMENT	Unit needs new corks	[REDACTED]	sublet to industrial metalworks Inv 5354-4					\$0.00
				CORK SNOW DUMP	9	\$1,071.00			\$1,071.00
				DOZER CAH-643 BEN					
				Total:	9	\$1,071.00	0	\$0.00	\$1,071.00
				Total:	9	\$1,071.00	0	\$0.00	\$1,071.00

Work Order

Work Order #: 90895
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3154.00

Date Opened: 18. Mar 2022.
Date Closed: 29. Mar 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	Track pads have a couple bolts missing on both sides.	[REDACTED]	Installed 3 new track pad bolts. Had to go to the snow dump to do the work.			2.00	\$134.00	\$134.00
				6V1792 BOLT CAH-643 MORGAN	10	\$22.30			\$22.30
				1S1860 NUT CAH-643 MORGAN	10	\$9.50			\$9.50
Total:					20	\$31.80	2.00	\$134.00	\$165.80
Total:					20	\$31.80	2.00	\$134.00	\$165.80

Work Order

Work Order #: 91284
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3155.00

Date Opened: 29. Apr 2022.
Date Closed: 2. May 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EL00	ELECTRICAL - GENERAL REPAIRS	Unit needed a boost at the snow dump.	[REDACTED]	Boosted unit at the snow dump.			1.00	\$67.00	\$67.00
				DIAGNOSE & REPAIR HYD CAH-643	1	\$627.95			\$627.95
				Total:	1	\$627.95	1.00	\$67.00	\$694.95
Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	Mark's hauling picked up unit and Hauled it to the shop.	[REDACTED]	Mark's Hauling picked up unit at the snow dump and brought it back to the shop.					\$0.00
				HAUL CAH-643 FROM SNOW DUMP TO CSC CAH-643 BEN	1	\$735.00			\$735.00
				Total:	1	\$735.00	0	\$0.00	\$735.00
				Total:	2	\$1,362.95	1.00	\$67.00	\$1,429.95

Work Order

Work Order #: 91532

Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3155.00

Date Opened: 26. May 2022.
Date Closed: 31. May 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT00	OTHER ACTIVITIES - GENE	boost unit in the yard	[REDACTED]	the mule batteries were low, and the booster pack was dead. used the service truck and genny to use the charger.			1.50	\$100.50	\$100.50
Total:					0	\$0.00	1.50	\$100.50	\$100.50
Total:					0	\$0.00	1.50	\$100.50	\$100.50

Work Order

Work Order #: 91650
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3155.00

Date Opened: 6. Jun 2022.
Date Closed: 9. Jun 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO11	HEATING, AIR CONDITIONING REPAIRS	heat not shutting off in cab	[REDACTED]	Checked all fuses to heater and checked connections on water vlave . determined water valve was not functioning properly. Remove cover on rear top corner of cab. pinch off collant lines to water valve remove water vlave and install new assembly. check for proper operation of heater and a/c . all good hot to cold while engine temp was up to operating temperature VAVLE AT502233 CAH-643 BRIAN PETTY CASH	1 1 Total:	 \$365.06 \$12.60 \$377.66	4.25 4.25	\$284.75 \$284.75	\$284.75 \$365.06 \$12.60 \$662.41
Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	Tarnsport unit from service centre to Kensington area	[REDACTED]	Sublet to Marks's hauling HAUL CAH-643	 1	 \$490.00			\$0.00 \$490.00

Total:	1	\$490.00	0	\$0.00	\$490.00
Total:	3	\$867.66	4.25	\$284.75	\$1,152.41

Work Order

Work Order #: 92244

Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3235.00

Date Opened: 8. Aug 2022.
Date Closed: 24. Aug 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EL00	ELECTRICAL - GENERAL REPAIRS	Go check over unit and boost unit at 117 and 84 ave before the truck comes to haul it back to CSC.	[REDACTED]	Go check over unit and boost unit at 117 and 84 ave before the truck comes to haul it back to CSC.			1.50	\$100.50	\$100.50
Total:					0	\$0.00	1.50	\$100.50	\$100.50

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	Haul unit from kensington to city centre	[REDACTED]	sublet to Mark's hauling BOL 207-0070					\$0.00
				HAUL FROM KENSINGTON TO CITY SHOP CAH-643	1	\$490.00			\$490.00
Total:					1	\$490.00	0	\$0.00	\$490.00
Total:					1	\$490.00	1.50	\$100.50	\$590.50

Work Order

Work Order #: 92368
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer: 0.00
Hours: 3155.00

Date Opened: 24. Aug 2022.
Date Closed: 31. Oct 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT16	TRANS OIL & FILTER CHANGE	required	[REDACTED]	changed oil and filter			4.00	\$268.00	\$268.00
				BREATHER AT4155455 CAH-643 TREVOR	1	\$226.95			\$226.95
				FILTER OIL HF6587 FLEETGUARD CAH-643 TREVOR	1	\$51.27			\$51.27
				OIL SYNTHETIC 0W40 18.9L KLHD2580 CAH-643 TREVOR	6	\$1,010.03			\$1,010.03
				Total:	8	\$1,288.25	4.00	\$268.00	\$1,556.25
OT17	DIFF OIL CHANGE	required	[REDACTED]	changed inner and outer final drives.			3.00	\$201.00	\$201.00
				Total:	0	\$0.00	3.00	\$201.00	\$201.00
OT22	HYD/PS OIL REPLACMENT & FILTER	required	[REDACTED]	changed hyd oil and filter			4.00	\$268.00	\$268.00
				OIL SYNTHETIC 0W40 18.9L KLHD2580 CAH-643 TREVOR	6	\$1,010.03			\$1,010.03

Total: 6 \$1,010.03 4.00 \$268.00 \$1,278.03

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT33	ENGINE VALVE LASH SET	required		removed side guards, exhaust pipe, intake pipe, turbo pressure lines and drain line. found the valves loose, adjusted to spec. intake 0.007" exhaust .025"			12.50	\$837.50	\$837.50
				O-RING R534793 CAH-643 TREVOR	1	\$4.19			\$4.19
				GASKETS/ORINGS/SEALS CAH-643 TREVOR	1	\$348.21			\$348.21
				TOWEL PAPER 35401 CAH-643 TREVOR	1	\$8.98			\$8.98
				FREIGHT	1	\$12.60			\$12.60
				SENSOR RE546613 CAH-643 TREVOR	1	\$287.45			\$287.45
				GASKET R521158 CAH-643 TREVOR	1	\$5.34			\$5.34
				LINE RE544029 CAH-643 TREVOR	1	\$353.49			\$353.49
				Total:	7	\$1,020.26	12.50	\$837.50	\$1,857.76

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT14	CVIP INSPECTION	required		inspected as per the John Deere form			6.00	\$402.00	\$402.00
				OIL SAMPLE PROGRAM JD AT346594 CAH-643 TREVOR	7	\$231.24			\$231.24
				FILTER AIR CAB LAF-5314 CAH-643 TREVOR	1	\$10.61			\$10.61
				FILTER AIR CAB PA30292 BALDWIN CAH-643 TREVOR	1	\$88.98			\$88.98
				Total:	9	\$330.82	6.00	\$402.00	\$732.82

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
FF00	FUEL SYSTEM REPAIRS	required		replaced three fuel filters.			3.25	\$217.75	\$217.75
				FILTER FUEL FS1093 FLEETGUARD CAH-643 TREVOR	1	\$55.63			\$55.63
				FILTER FUEL, PRIMARY FS1091 FLEETGUARD CAH-643 TRE	1	\$55.63			\$55.63
				FILTER FUEL BF461000 BALDWIN CAH-643 TREVOR	1	\$40.62			\$40.62
				Total:	3	\$151.88	3.25	\$217.75	\$369.63

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
-------------	-------------	-----------------	----------	-----------------	-----------	-------	------------	--------------	-------

OT43	OIL SAMPLE, ALL MAJOR COMPONENTS	required		sample all fluids		0.50	\$33.50	\$33.50		
					Total:	0	\$0.00	0.50	\$33.50	\$33.50

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT15	ENGINE SERVICE AND INSPECTION	required		changed engine oil and filter. Baldwin filter B7335MPG was leaking sent pictures to Gary.			8.75	\$586.25	\$586.25
				OIL FILTER AT318160 CAH-643 TREVOR	1	\$173.08			\$173.08
				OIL SYNTHETIC 0W40 18.9L KLHD2580 CAH-643 TREVOR	1	\$168.34			\$168.34
				GREASE EXTREME PRESSURE DELO EP2 CAH-643 TREVOR	2	\$18.22			\$18.22
				EAR PLUGS STETHESCOPE QB2HYD CAH-643 TREVOR	1	\$6.12			\$6.12
				LUBRICANT WD40 01011 CAH-641 TREVOR	1	\$7.61			\$7.61
				FILTER AIR AF25292 FELETGUARD CAH-643 TREVOR	2	\$50.74			\$50.74
Total:					8	\$424.12	8.75	\$586.25	\$1,010.37

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO00	BODY - GENERAL REPAIRS NON-ACCIDENT RELATED	1) replace damaged door latches. 2) modify the bottom engine guard so the engine oil drain valve and hose are more accessible		1) ordered aug 26/3:45/Daryl, brian installed two door latches. completed task. 2) hugo modified the guard for better access.			4.50	\$301.50	\$301.50
				LATCH AT225885 CAH-643 TREVOR	2	\$304.46			\$304.46
				RIVET H85233 CAH-643 TREVOR	8	\$19.12			\$19.12
				LABEL CY T390452 CAH-643 TREVOR	1	\$39.58			\$39.58
				LABEL CY T390485 CAH-643 TREVOR	1	\$61.06			\$61.06
Total:					12	\$424.22	4.50	\$301.50	\$725.72

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	replace hyd tubing for the angle function		replaced the hose from a previous repair to the hyd tubing. ordered aug 26/3:45/Daryl			4.00	\$268.00	\$268.00
				BREATHER AT4155455 CAH-643 TREVOR	1	\$226.95			\$226.95
				FILTER DZ18283 CAH-643 TREVOR	1	\$38.23			\$38.23

FLOOR DRY 20 POUND BAG FD85N CAH-643 TREVOR	2	\$30.84			\$30.84
CLAMP GEAR 10 PHS-10 CAH-643 TREVOR	4	\$4.59			\$4.59
OIL TUBE AT485077 CAH- 643 TREVOR	1	\$117.25			\$117.25
Total:	9	\$417.87	4.00	\$268.00	\$685.87

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EL00	ELECTRICAL - GENERAL REPAIRS	batteries are weak and need to be replaced.		replaced both batteries.			2.75	\$184.25	\$184.25
				DELCOR GR31 AUTO POST CAH-643 TREVOR	2	\$280.00			\$280.00
				Total:	2	\$280.00	2.75	\$184.25	\$464.25
				Total:	64	\$5,347.44	53.25	\$3,567.75	\$8,915.19

Work Order

Work Order #: 92421
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3238.00

Date Opened: 29. Aug 2022.
Date Closed: 1. Sep 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO00	BODY - GENERAL REPAIRS NON-ACCIDENT RELATED	there are a bunch of cracks around the rear left mounting holes of the hood. Some of the cracks have been scabbed over bu are cracked again as well as new ones apearing.	[REDACTED]	Replaced the entire corner of the rear left of the engine hood and repainted to match.			8.90	\$596.30	\$596.30
				ADHESIVE REMOVER 08987 CAH-643 HUGO	1	\$23.27			\$23.27
				GREEN SPRAY TY25661 CAH-643 HUGO	2	\$47.36			\$47.36
				ANNULAR CUTTER CAH-643 HUGO	1	\$91.71			\$91.71
				Total:	4	\$162.34	8.90	\$596.30	\$758.64
				Total:	4	\$162.34	8.90	\$596.30	\$758.64

Work Order

Work Order #: 92502
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3238.00

Date Opened: 7. Sep 2022.
Date Closed: 13. Sep 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
MO00	MODIFICATIONS	Oil pan cover needs to be modified so that the oil drain can be accessed through the pan cover.	[REDACTED]	Cut off the internal support / hinge assembly and rewelded it 180 degrees from the original position.			7.30	\$489.10	\$489.10
				PAINT CAT YELLOW	1	\$20.78			\$20.78
				TY25627 CAH-643 HUGO					
				Total:	1	\$20.78	7.30	\$489.10	\$509.88
				Total:	1	\$20.78	7.30	\$489.10	\$509.88

Work Order

Work Order #: 92578
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3238.00

Date Opened: 16. Sep 2022.
Date Closed: 23. Sep 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	Transport unit from service centre to snow dump	[REDACTED]	Sublet to Mark's hauling					\$0.00
				HAUL CAH-643 TO SNOW DUMP	1	\$490.00			\$490.00
				Total:	1	\$490.00	0	\$0.00	\$490.00
				Total:	1	\$490.00	0	\$0.00	\$490.00

Work Order

Work Order #: 92875
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3238.00

Date Opened: 26. Oct 2022.
Date Closed: 5. Jan 2023.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	remove blade	[REDACTED]	[REDACTED]	travel to snow dump Remove blade from machine. remove all pins from cylinders and dog bone. put blade on trailer and dro off st steel industries			22.25	\$1,490.75	\$1,490.75
Total:						0	\$0.00	22.25	\$1,490.75	\$1,490.75

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
CA00	CARELESSNESS	OPERATOR DID NOT CHECK BLADE AND WORE OFF CUTTING EDGE AND WORE IN ATTACHMENT POINT OF CUTTING EDGE	[REDACTED]	[REDACTED]	SENT TO STEEL INDUSTRIES FOR REPAIR					\$0.00
BLADE REPAIRS						1	\$4,411.03			\$4,411.03
Total:						1	\$4,411.03	0	\$0.00	\$4,411.03

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE	[REDACTED]	[REDACTED]	PARTS ISSUE					\$0.00
GLOVES WINTER XL BDG						2	\$22.28			\$22.28
30-9-473TFL-XL										
GP EXPRESS LTD						1	\$12.60			\$12.60

GLOVES HYFLEX SIZE 10	2	\$6.96			\$6.96
ANS 11-801-10					
Total:	5	\$41.84	0	\$0.00	\$41.84

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
MO00	MODIFICATIONS	A skid plate has a crack in it		Repaired skid plate crack			1.00	\$67.00	\$67.00
				BLADE RETAINER, T393645	1	\$889.01			\$889.01
				BLADE RETAINER T393645	1	\$889.01			\$889.01
				Total:	2	\$1,778.02	1.00	\$67.00	\$1,845.02

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EN00	ENGINE REPAIRS	Fuel tank on the unit is creating a vacuume. Going to change the tank vent in the cap		chanked tank cap					\$0.00
				Total:	0	\$0.00	0	\$0.00	\$0.00
				Total:	8	\$6,230.89	23.25	\$1,557.75	\$7,788.64

Work Order

Work Order #: 93201
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3238.00

Date Opened: 30. Nov 2022.
Date Closed: 5. Dec 2022.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT00	OTHER ACTIVITIES - GENE	Please update hour meter reading	[REDACTED]	3180					\$0.00
Total:					0	\$0.00	0	\$0.00	\$0.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
DR00	DRIVE TRAIN - GENERAL	Tracks loose. Some bolts broken and some can't be removed	[REDACTED]	Removed seized boltsa on Rh side and lh side			2.00	\$134.00	\$134.00
Total:					0	\$0.00	2.00	\$134.00	\$134.00
Total:					0	\$0.00	2.00	\$134.00	\$134.00

Work Order

Work Order #: 93245
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3238.00

Date Opened: 2. Dec 2022.
Date Closed: 29. Mar 2023.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	either Trans or hyd leak under machine	[REDACTED]	[REDACTED]	Travelled to snow dump with morgan ran machine found hydraulic oil leaking on rear of engine and transmission area. warrnaty brandt is heading over to inspect			3.60	\$241.20	\$241.20
					OT DIFFERENTIAL CHRGS	1	\$2,159.92			\$2,159.92
					Total:	1	\$2,159.92	3.60	\$241.20	\$2,401.12
Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	Transport from brandt to Snow dump	[REDACTED]	[REDACTED]	sublet to Mark's hauling					\$0.00
					Total:	0	\$0.00	0	\$0.00	\$0.00
					Total:	1	\$2,159.92	3.60	\$241.20	\$2,401.12

Work Order

Work Order #: 93429

Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3238.00

Date Opened: 22. Dec 2022.
Date Closed: 29. Mar 2023.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	Operator started unit at -40 and dumped the oil out the filter. Unit will need a new hyd oil filter and to be filled up the tank.	[REDACTED]	REPLACED HYD FILTER. FOUND SEAL BLOWN AND HYD FILTER CRACKED AS WELL AS FILTER NIPPLE CAME OUT OF HOUSING. UPON INSPECTION APPEARS FILTER NIPPLE INSTALLED UPSIDE DOWN. INSTALL CORRECT WAY INTO HOUSING. INSTALLED NEW FILTER AND SEAL. FILL HYD SYSTEM. TRY TO START UNIT BUT APPEARS BLOCK HEATER IS INOP AND BAT FILLER RE546811	1	\$154.22	8.70	\$582.90	\$154.22
				OIL FILTER AT318160	1	\$193.35			\$193.35
				Total:	2	\$347.57	8.70	\$582.90	\$930.47

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	Went to Brant to pick up a filter and was given the wrong part, had to go back and pick up the	[REDACTED]	Brought the filter to the snow dump.			2.00	\$134.00	\$134.00

correct part.

Total: 0 \$0.00 2.00 \$134.00 \$134.00

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE			PARTS ISSUE					\$0.00
					OIL TDH 4.73L KLHF8060	3	\$85.16			\$85.16
					OIL HYD TDH 18.9L KLHF8080	5	\$582.80			\$582.80
					OIL HYD TDH 18.9L KLHF8080	3	\$349.68			\$349.68
					Total:	11	\$1,017.64	0	\$0.00	\$1,017.64

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EL00	ELECTRICAL - GENERAL REPAIRS	Check block heater			checked block heater foun pin broke ooff in plug tested inside on engine block pins on block heater found dead heater element order new block heater and cord BLOCK HEATER CORD AT73296 BLOCK HEATER RE50588			3.20	\$214.40	\$214.40
					BLOCK HEATER CORD AT73296	1	\$52.50			\$52.50
					BLOCK HEATER RE50588	1	\$174.08			\$174.08
					Total:	2	\$226.58	3.20	\$214.40	\$440.98
					Total:	15	\$1,591.79	13.90	\$931.30	\$2,523.09

Work Order

Work Order #: 93592
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3519.00

Date Opened: 12. Jan 2023.
Date Closed: 29. Mar 2023.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
CH19	WHEEL RE-TORQUE	re cork unit	[REDACTED]	re corke unit					\$0.00
				RECORK DOZER	1	\$1,250.00			\$1,250.00
				Total:	1	\$1,250.00	0	\$0.00	\$1,250.00
Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	Cutting edge needs flipping/replacing	[REDACTED]	Replaced corner bits on blade. flip cuttin edges on blade			4.10	\$274.70	\$274.70
				ICE LUGS ECUT3	200	\$1,570.00			\$1,570.00
				Total:	200	\$1,570.00	4.10	\$274.70	\$1,844.70
				Total:	201	\$2,820.00	4.10	\$274.70	\$3,094.70

Work Order

Work Order #: 93716
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3637.00

Date Opened: 24. Jan 2023.
Date Closed: 26. Jan 2023.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
DR00	DRIVE TRAIN - GENERAL	Bolts sheared on track adjustment access cover	[REDACTED]	Remove broken bolt in track adjuster cover and intsaall new bolt with never seize			2.00	\$134.00	\$134.00
Total:					0	\$0.00	2.00	\$134.00	\$134.00
Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT43	OIL SAMPLE, ALL MAJOR COMPONENTS	complete oil sample	[REDACTED]	drain oil sample into sample bottle and bring to parts to get sent off					\$0.00
Total:					0	\$0.00	0	\$0.00	\$0.00
Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT27	FUEL FILTERS	fuel filters need changing	[REDACTED]	removed fuel filters and install new ones			0.80	\$53.60	\$53.60
Total:					0	\$0.00	0.80	\$53.60	\$53.60
Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT15	ENGINE SERVICE AND INSPECTION	service engine	[REDACTED]	drained enginer oil and changed out filters refill with new oil new filters.			2.90	\$194.30	\$194.30
Total:					0	\$0.00	2.90	\$194.30	\$194.30
Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total

AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE		PARTS ISSUE					\$0.00
				OIL SAMPLE PROGRAM	1	\$48.08			\$48.08
				JD AT346594					
				FILTER OIL B7335MPG	1	\$26.60			\$26.60
				BALDWIN					
				FILTER FUEL, PRIMARY	1	\$50.57			\$50.57
				FS1091 FLEETGUARD					
				FILTER FUEL BF46100O	1	\$36.93			\$36.93
				BALDWIN					
				OIL SYNTHETIC 0W40	2	\$428.32			\$428.32
				18.9L KLHD2580					
				Total:	6	\$590.50	0	\$0.00	\$590.50
				Total:	6	\$590.50	5.70	\$381.90	\$972.40

Work Order

Work Order #: 93738
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3637.00

Date Opened: 26. Jan 2023.
Date Closed: 29. Mar 2023.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EN00	ENGINE REPAIRS	Bracket broke off . hole in air to air	[REDACTED]	Kelson confirms intercooler is punctured. Spoke to Brandt tractor. Nwe one ordered, covered under warranty. ETA FEB 1st			1.50	\$100.50	\$100.50
				REPAIR INTERCOOLER LEAK CAH-643	1	\$883.70			\$883.70
				Total:	1	\$883.70	1.50	\$100.50	\$984.20
				Total:	1	\$883.70	1.50	\$100.50	\$984.20

Work Order

Work Order #: 93955
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3637.00

Date Opened: 22. Feb 2023.
Date Closed: 14. Apr 2023.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	Has a decent size hydraulic leak coming from the front ram (up and down arm)	[REDACTED]	found hydraulic oil leakinf at crimp on hose to upper blade cylinder. remove hose brought to gregs to get new one built for replacement. install new replacement hose on machine and run up to temp and check for leaks all good . topped up hydraulic oil level with pail of oil			3.00	\$201.00	\$201.00
				HYDRAULIC HOSE	1	\$283.71			\$283.71
				Total:	1	\$283.71	3.00	\$201.00	\$484.71

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE	[REDACTED]	PARTS ISSUE					\$0.00
				OIL HYD TDH 18.9L KLHF8080	1	\$116.56			\$116.56
				Total:	1	\$116.56	0	\$0.00	\$116.56
				Total:	2	\$400.27	3.00	\$201.00	\$601.27

Work Order

Work Order #: 93960
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 3637.00

Date Opened: 22. Feb 2023.
Date Closed: 29. Mar 2023.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC00	ACCESSORIES GENERAL	RE-CORK DOZER, HAVE JEFF AT ALLOY INDUCTRIES 780-876-0554 GOING TO SET UP FOR LATER THIS WEEK OR EARL	[REDACTED]	[REDACTED]	HAD ALLOY INDUSTRIED RECORK TRACKS					\$0.00
RECORK DOZER						1	\$2,263.73			\$2,263.73
Total:						1	\$2,263.73	0	\$0.00	\$2,263.73

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT00	OTHER ACTIVITIES - GENE	Please advise on proper ice lug pattern & quantity needed	[REDACTED]	[REDACTED]	Advised on ice lug pattern & quantity needed. Drive to snow dump location & back. About 36~ per side in a 2-0- 1 Pattern			1.50	\$100.50	\$100.50
Total:						0	\$0.00	1.50	\$100.50	\$100.50
Total:						1	\$2,263.73	1.50	\$100.50	\$2,364.23

Work Order

Work Order #: 94105
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer: 0.00
Hours: 4198.00

Date Opened: 10. Mar 2023.
Date Closed: 23. Jan 2024.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT43	OIL SAMPLE, ALL MAJOR COMPONENTS	oil samples	[REDACTED]	[REDACTED]	engine trany and hyd oil samples to be sent out			0.50	\$33.50	\$33.50
Total:						0	\$0.00	0.50	\$33.50	\$33.50
Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT15	ENGINE SERVICE AND INSPECTION	engine service	[REDACTED]	[REDACTED]	changed oil and filter 25lt 5w40, replaced both primary air filters, hyd tank level ok,			3.40	\$227.80	\$227.80
Total:						0	\$0.00	3.40	\$227.80	\$227.80
Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT27	FUEL FILTERS	fuel filter service	[REDACTED]	[REDACTED]	replaced all three fuel filters.			1.20	\$80.40	\$80.40
Total:						0	\$0.00	1.20	\$80.40	\$80.40
Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE	[REDACTED]	[REDACTED]	PARTS ISSUE					\$0.00
					FILTER FUEL BF461000 BALDWIN	1	\$40.70			\$40.70
					OIL SYNTHETIC 5W40 3.785L 257002464	6	\$292.82			\$292.82
					FILTER FUEL, PRIMARY	1	\$65.92			\$65.92

FS1091 FLEETGUARD					
FILTER FUEL FS1093	1	\$74.45			\$74.45
FLEETGUARD					
FILTER AIR AF25292	2	\$50.84			\$50.84
FELETGUARD					
FILTER OIL B7335MPG	1	\$26.11			\$26.11
BALDWIN					
OIL SAMPLE PROGRAM	3	\$155.07			\$155.07
JD AT346594					
Total:	15	\$705.91	0	\$0.00	\$705.91
Total:	15	\$705.91	5.10	\$341.70	\$1,047.61

Work Order

Work Order #: 94209
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4298.00

Date Opened: 23. Mar 2023.
Date Closed: 3. Apr 2023.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA01	UPDATE MILAGE/HOUR METER	UPDATE HRS	[REDACTED]	4298 HRS					\$0.00
Total:					0	\$0.00	0	\$0.00	\$0.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EN00	ENGINE REPAIRS	ADDED 1 JUG OFF COOLANT, INSOECT FOR LEAK	[REDACTED]	PULL PANELS FOR ACCESS. FOUND RADIATOR CAP LOOSE CAUSING CODE, LOOSE RADIATOR MOUNTS, TOP RAD HOSE AND HOSE OFF TOP OF RADIATOR TO SURGE TANK LEAKING. RUN TO GO PICKUP HOSE AS DID NOT HAVE THAT SIZE IN SERVICE TRUCK. REPLACE HOSES AND CLAMPS AS REQUIRED. TIGHTEN ALL RADIATOR MOUNTS/BRACKETS/ETC. FILL COOLING SYSTEM AND WASH OFF RADIATOR. RUN UNIT AND MAKE SURE NO			13.80	\$924.60	\$924.60

MORE LEAKS AND CEL IS
OUT NOW.

Total: 0 \$0.00 13.80 \$924.60 \$924.60

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
DI00	DIAGNOSTIC TIME	CODES SET			SCAN CODES AND FOUND LOW COOLANT AND LOW COOLANT PRESSURE ACTIVE DUE TO COOLANT LEAKS. AFTER ALL REPAIRS MADE SURE CODES WENT OUT AND ARE INACTIVE NOW.			0.40	\$26.80	\$26.80

Total: 0 \$0.00 0.40 \$26.80 \$26.80

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE			PARTS ISSUE					\$0.00

CLAMP HOSE SIZE 4 PMH 4 \$3.72 \$3.72

-4
CLAMP HOSE SIZE 8 2 \$2.70 \$2.70
EXTENDED TONGUE PET-
8

Total: 6 \$6.42 0 \$0.00 \$6.42

Total: 6 \$6.42 14.20 \$951.40 \$957.82

Work Order

Work Order #: 94625
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4298.00

Date Opened: 8. May 2023.
Date Closed: 9. May 2023.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
CA00	CARELESSNESS	unit dead batteries night switch left on.	[REDACTED]	[REDACTED]	brian tony, replaced two batteries, night switch was left on. had to recable. Didnt have the correct batteries. recables to our most common style on hand			10.00	\$670.00	\$670.00
Total:						0	\$0.00	10.00	\$670.00	\$670.00
Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	replace dozer cutting edges	[REDACTED]	[REDACTED]	brian and tony replaced dozer blades, couldnt do until batteries were replaced.			6.00	\$402.00	\$402.00
Total:						0	\$0.00	6.00	\$402.00	\$402.00
Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE	[REDACTED]	[REDACTED]	PARTS ISSUE					\$0.00
						BATTERY 31S-1000	2	\$280.00		\$280.00
Total:						2	\$280.00	0	\$0.00	\$280.00
Total:						2	\$280.00	16.00	\$1,072.00	\$1,352.00

Work Order

Work Order #: 94657
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4298.00

Date Opened: 10. May 2023.
Date Closed: 13. Jul 2023.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	Dozer Blade Pivot Ball Is cracked, JOSE MOLINA IF NEED MORE DETAILS	[REDACTED]	[REDACTED]	Drive to snow dump to inspect damage, misalignment spacer on cylinder is cracked. Ordered both sides w/ expedite as this unit may be used to fight Dunes west wildfire. Received part, drive back out to snow dump, attempt to install into cylinder. Needed to bring cylinder back to shop to complete installation. Reinstalled hyd cylinder and guards.			9.50	\$636.50	\$636.50
					SNAP RINGS, 40M1873	4	\$104.24			\$104.24
					BUSHINGS, AT157174	2	\$572.64			\$572.64
					Total:	6	\$676.88	9.50	\$636.50	\$1,313.38
Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE	[REDACTED]	[REDACTED]	PARTS ISSUE					\$0.00
					DELIVERY CHARGES	1	\$12.00			\$12.00
					Total:	1	\$12.00	0	\$0.00	\$12.00

Total:	7	\$688.88	9.50	\$636.50	\$1,325.38
--------	---	----------	------	----------	------------

Work Order

Work Order #: 94808

Status: Closed

Unit #: CAH-643

Status: Replaced (pool)

Type: HEAVY EQUIPMENT

Sub-Type: DOZER

Year: 2020

Make: JOHN DEERE MFG

Model: 850L

VIN: 1T0850LXALF388897

Color: YELLOW

Licence:

Location: CITY SERVICE CENTRE

Fuel Type: DIESEL

Supervisor: [REDACTED] [REDACTED]

Odometer:

Hours: 4322.00

Date Opened: 29. May 2023.

Date Closed: 27. Jun 2023.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA01	UPDATE MILAGE/HOUR METER	?			?					\$0.00
Total:						0	\$0.00	0	\$0.00	\$0.00
Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	HYDROLIC LINE BLOWN, LAURIE PRICHUK CALL IN FOR TECH TO LOOK AT			replaced hose for RH angle cylinder.			2.50	\$167.50	\$167.50
Total:						0	\$0.00	2.50	\$167.50	\$167.50
Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE			PARTS ISSUE					\$0.00
						HOSE ASSEMBLY	1	\$100.67		\$100.67
Total:						1	\$100.67	0	\$0.00	\$100.67
Total:						1	\$100.67	2.50	\$167.50	\$268.17

Work Order

Work Order #: 94828
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4322.00

Date Opened: 30. May 2023.
Date Closed: 1. Jun 2023.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	CALLED IN HYDROLIC OIL IS EXTERMELY LOW, PLEASE TOP UP	[REDACTED]	added 120 lts of hyd oil			2.50	\$167.50	\$167.50
Total:					0	\$0.00	2.50	\$167.50	\$167.50
Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA01	UPDATE MILAGE/HOUR METER	?	[REDACTED]	?					\$0.00
Total:					0	\$0.00	0	\$0.00	\$0.00
Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE	[REDACTED]	PARTS ISSUE					\$0.00
				OIL HYD TDH 18.9L KLHF8080	4	\$466.24			\$466.24
				OIL HYD TDH 18.9L KLHF8080	3	\$349.68			\$349.68
Total:					7	\$815.92	0	\$0.00	\$815.92
Total:					7	\$815.92	2.50	\$167.50	\$983.42

Work Order

Work Order #: 94912
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4354.00

Date Opened: 7. Jun 2023.
Date Closed: 18. Jul 2023.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC00	ACCESSORIES GENERAL	ORAANGE LENZE MISSING FROM BEACON	[REDACTED]	parts ordered, installed new beacon, decision made not to replace the damaged bracket. BEACON STROKE, AT435890	1	\$452.73	2.50	\$167.50	\$167.50
Total:					1	\$452.73	2.50	\$167.50	\$620.23
Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	This unit has a hydraulic leak on the left side, blade cylinder.	[REDACTED]	loose fitting, tightened			2.00	\$134.00	\$134.00
Total:					0	\$0.00	2.00	\$134.00	\$134.00
Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA01	UPDATE MILAGE/HOUR METER	?	[REDACTED]	?					\$0.00
Total:					0	\$0.00	0	\$0.00	\$0.00
Total:					1	\$452.73	4.50	\$301.50	\$754.23

Work Order

Work Order #: 95093
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4360.00

Date Opened: 27. Jun 2023.
Date Closed: 31. Jul 2023.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	Have unit moved from snow dump to South Bear Creek ball diamonds.	[REDACTED]	Mark's Hauling was called to come move the unit from the snow dump to South Bear Creek ball diamonds. HAUL 850 JOHN DEERE CRAWLER					\$0.00
Total:					1	\$735.00	0	\$0.00	\$735.00
Total:					1	\$735.00	0	\$0.00	\$735.00

Work Order

Work Order #: 95855

Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4396.00

Date Opened: 22. Sep 2023.
Date Closed: 15. Nov 2023.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA01	UPDATE MILAGE/HOUR METER	?	[REDACTED]	?					\$0.00
Total:					0	\$0.00	0	\$0.00	\$0.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT48	ANNUAL EQUIPMENT INSPECTION	INSPECT UNIT, UPDATE GARY WITH HRS ON UNIT TO SEE IF REQUIRES MAINATANCE WHILE HERE	[REDACTED]	performed inspection as per OEM service inerval form. only issue was the batteries are marginal (8.9v and 8.7v). replaced batteries.			4.00	\$268.00	\$268.00
Total:					0	\$0.00	4.00	\$268.00	\$268.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	HAVING PICKED UP AT SOUTH BEAR CREEK AND BROUGHT TO CITY SERVICE CENTER	[REDACTED]	HAS BROUGHT TO SERVICE CENTER, THEN DELIVERED TO SNOW DUMP AFTER REPAIRS TOW					\$0.00
					1	\$954.00			\$954.00
Total:					1	\$954.00	0	\$0.00	\$954.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC00	ACCESSORIES GENERAL	INSPECT TRACKS, SOME OF THE PADS ARE	[REDACTED]	five pads cracked, parts on order Sept 28 moved			13.50	\$904.50	\$904.50

CRACKING , SEE GARY

machine out side waiting for
a track pad. travelled to the
snow dump and installed
master pad and torqued to
spec.

TOW	1	\$650.00			\$650.00
Total:	1	\$650.00	13.50	\$904.50	\$1,554.50
Total:	2	\$1,604.00	17.50	\$1,172.50	\$2,776.50

Work Order

Work Order #: 96309
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4396.00

Date Opened: 22. Nov 2023.
Date Closed: 22. Nov 2023.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	6 pads are longer than the rest please cut them to same length as the rest as the ride quality is poor.	[REDACTED]	[REDACTED]	drive to snow dump, cut a few pads. Ran out of gas, went to messer to replace bottles in service truck. Went back to snow dump cut off rest of pads.			6.50	\$435.50	\$435.50
Total:						0	\$0.00	6.50	\$435.50	\$435.50
Total:						0	\$0.00	6.50	\$435.50	\$435.50

Work Order

Work Order #: 96635
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4432.00

Date Opened: 12. Jan 2024.
Date Closed: 25. Jan 2024.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	HYDROLIC LEAK R/F RAM, SEE GARY FOR PICTURE	[REDACTED]	removed leaking hose and gave to Daryl at 8:45, installed at 1:30.			3.00	\$201.00	\$201.00
				KIT ASSEMBLY	1	\$262.89			\$262.89
				OIL HYD TDH 18.9L KLHF8080	1	\$110.37			\$110.37
Total:					2	\$373.26	3.00	\$201.00	\$574.26

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA01	UPDATE MILAGE/HOUR METER	request	[REDACTED]	done					\$0.00
Total:					0	\$0.00	0	\$0.00	\$0.00
Total:					2	\$373.26	3.00	\$201.00	\$574.26

Work Order

Work Order #: 96674
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4432.00

Date Opened: 16. Jan 2024.
Date Closed: 29. Jan 2024.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC00	ACCESSORIES GENERAL	INSTALL NEW CUTTING EDGE	[REDACTED]	Grab new corner cutting edges from yard & change out/flip cutting edge at snow dump. -KM - SC DURA-MAX C/EDGE T187243X CUTTING EDGE, T425102 DURA-MAX C/EDGE T187244X CUTTING EDGE T187987X KIT, HARDWARE PB750250ITR Total:	 1 1 1 2 34 39	 \$132.60 \$971.90 \$132.60 \$451.00 \$101.32 \$1,789.42	6.00 6.00	\$402.00 \$402.00	\$402.00 \$132.60 \$971.90 \$132.60 \$451.00 \$101.32 \$2,191.42
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE	[REDACTED]	PARTS ISSUE BOLT PLOW 3/4" X 2 1/2" 750X250 NUT FOR PLOW BOLT 3/4" 7502H Total:	 34 34 68	 \$57.46 \$22.41 \$79.87	 0	 \$0.00	\$0.00 \$57.46 \$22.41 \$79.87

Total:	107	\$1,869.29	6.00	\$402.00	\$2,271.29
--------	-----	------------	------	----------	------------

Work Order

Work Order #: 96738
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4474.00

Date Opened: 23. Jan 2024.
Date Closed: 23. Jan 2024.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC12	RADIO EQUIPMENT REPAIRS	REPAIR RADIO cant send or recieve	[REDACTED]	[REDACTED]	travel to and from snow dump, radio has no power, checked fuses ok, found power wires broken off at isolation posts. crimped on new ends and installed wires. radio has power now. completed			1.50	\$100.50	\$100.50
Total:						0	\$0.00	1.50	\$100.50	\$100.50
Total:						0	\$0.00	1.50	\$100.50	\$100.50

Work Order

Work Order #: 96785
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4552.00

Date Opened: 29. Jan 2024.
Date Closed: 30. Jan 2024.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC00	ACCESSORIES GENERAL	ORDER FROST PLUG THAT WAS SHOWN MISSING BY TRANSPORATATION (CAMILLE)	[REDACTED]	ordered Jan 29, PARTS ARRIVED JAN 30, LAURIE PRICHUK PICKING AND WILL INSTALL THEM PLUG					\$0.00
					2	\$20.39			\$20.39
Total:					2	\$20.39	0	\$0.00	\$20.39
					2	\$20.39	0	\$0.00	\$20.39

Work Order

Work Order #: 96829
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4727.00

Date Opened: 13. Feb 2024.
Date Closed: 16. Feb 2024.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA01	UPDATE MILAGE/HOUR METER	requested	[REDACTED]	done					\$0.00
Total:					0	\$0.00	0	\$0.00	\$0.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO00	BODY - GENERAL REPAIRS NON- ACCIDENT RELATED	LOCKING MECHANISM FIOR THE LEFT SIDE ENGINE COMPARTMENT BROKEN	[REDACTED]	parts on order. Daryl Feb 13/1:30			0.25	\$16.75	\$16.75
Total:					0	\$0.00	0.25	\$16.75	\$16.75

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EN00	ENGINE REPAIRS	coolant leak	[REDACTED]	traveled to snow dump, found coolant all over the ground and the upper radiator hose is split wide open. called brandt to check on warrenty. BRANDT REPAIRED UNDER WARRANTY			1.00	\$67.00	\$67.00
Total:					0	\$0.00	1.00	\$67.00	\$67.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
-------------	-------------	-----------------	----------	-----------------	-----------	-------	------------	--------------	-------

AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE		PARTS ISSUE						\$0.00
				FILTER AIR AF25292	2		\$56.80			\$56.80
				FELETGUARD						
				FILTER OIL B7335MPG	1		\$28.29			\$28.29
				BALDWIN						
				FILTER FUEL, PRIMARY	1		\$65.15			\$65.15
				FS1091 FLEETGUARD						
				FILTER FUEL BF461000	1		\$40.70			\$40.70
				BALDWIN						
				FILTER FUEL FS1093	1		\$76.13			\$76.13
				FLEETGUARD						
				LATCH,RIVET, WASHER,	17		\$274.12			\$274.12
				CAP SCREW						
				OIL SAMPLE PROGRAM	1		\$51.84			\$51.84
				JD AT346594						
				OIL SYNTHETIC 5W40	8		\$295.69			\$295.69
				3.785L 257002464						
				TOWEL PAPER 35401	1		\$10.07			\$10.07
				TOWEL PAPER 35401	1		\$10.07			\$10.07
				DOOR GRABBER 4 1/2"	1		\$42.31			\$42.31
				DEMERS E602185						
				Total:	35		\$951.17	0	\$0.00	\$951.17

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT15	ENGINE SERVICE AND INSPECTION	due		changed engine oil and filter. refilled with 25 Lts of 5/40. changed outer air filters			2.00	\$134.00	\$134.00
				Total:	0	\$0.00	2.00	\$134.00	\$134.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
D100	DIAGNOSTIC TIME	CRACKS FORMING ON LEFT SIDE ENGINE CABNET, AND A FEW BOLTS MISSING, BRING TO SHOP HAVE WELDERS REPAIR							\$0.00
				Total:	0	\$0.00	0	\$0.00	\$0.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT27	FUEL FILTERS	due		replaced three fuel filters			1.00	\$67.00	\$67.00
				Total:	0	\$0.00	1.00	\$67.00	\$67.00

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT43	OIL SAMPLE, ALL MAJOR COMPONENTS	due		done			0.25	\$16.75	\$16.75
				Total:	0	\$0.00	0.25	\$16.75	\$16.75

Total:	35	\$951.17	4.50	\$301.50	\$1,252.67
--------	----	----------	------	----------	------------

Work Order

Work Order #: 96898
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4803.00

Date Opened: 14. Feb 2024.
Date Closed: 10. May 2024.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO00	BODY - GENERAL REPAIRS NON-ACCIDENT RELATED	CRACKS FORMING ON LEFT SIDE ENGINE CABNET, AND A FEW BOLTS MISSING, BRING TO SHOP HAVE WELDERS REPAIR	[REDACTED]	[REDACTED]	Door latch for wo 96829 BO00 has arrived Feb 15 and is on shelf #2. SEE WORK ORDER 96898			0.25	\$16.75	\$16.75
Total:						0	\$0.00	0.25	\$16.75	\$16.75

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
DI00	DIAGNOSTIC TIME	leak on unit inspect plz	[REDACTED]	[REDACTED]	Inspect unit 2/26/24 - 3pm - hyd hose for blade lift is leaking and one end appears to be a bulkhead - not sure we have caps to plug it off over night. Did not take off hose. 2/27/24 10am remove hose and cap as best as possible, bring hose to greggs to be built new.			2.75	\$184.25	\$184.25
Total:						0	\$0.00	2.75	\$184.25	\$184.25

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	Replace hose	[REDACTED]	[REDACTED]	Replaced hose on unit, check for hyd leaks & check hyd resvoir.			1.70	\$113.90	\$113.90
Total:						0	\$0.00	1.70	\$113.90	\$113.90

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	Deliver hoses to and from greggs back to snow dump			Deliver hoses to and from greggs back to snow dump			0.75	\$50.25	\$50.25
Total:						0	\$0.00	0.75	\$50.25	\$50.25
Total:						0	\$0.00	5.45	\$365.15	\$365.15

Work Order

Work Order #: 96915
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: GREIG, GARY
Odometer:
Hours: 4730.00

Date Opened: 15. Feb 2024.
Date Closed:

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC00	ACCESSORIES GENERAL	NEED FUEL TANK CAP			SHAY ORDERED AND JOSE HAD OPERATOR PICKUP AND INSTALL					\$0.00
Total:						0	\$0.00	0	\$0.00	\$0.00
Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE			PARTS ISSUE					\$0.00
FUEL CAP						1	\$144.32			\$144.32
Total:						1	\$144.32	0	\$0.00	\$144.32
Total:						1	\$144.32	0	\$0.00	\$144.32

Work Order

Work Order #: 96974
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: MCMURDO, KELSON
Odometer:
Hours: 4782.00

Date Opened: 27. Feb 2024.
Date Closed: 19. Mar 2024.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO00	BODY - GENERAL REPAIRS NON-ACCIDENT RELATED	LHS Panels are cracked and need repaired / replaced			Door latch for wo 96829 BO00 has arrived Feb 15 and is on shelf #2. 2/27/24 - panels are intact at this point, ambient temp is -30. Advise crew cheif - opted to take panels off at a later time as season is almost to close.					\$0.00
Total:						0	\$0.00	0	\$0.00	\$0.00

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
C000	COOLING SYSTEM REPAIRS	added one jug of HD 50/50 mix red coolant to the unit when the sensor went off. LEAKING COOLANT			Service call to unit 3/1/24 - low on coolant. Coolant is everywhere due to fan. Cleaned & pressured cooling rad - upper rad hose & resvoir hose are leaking. Tightened and repressured - no leaks found. Ran unit - lots of coolant leaking from belly pan at back by cab but hoses are still fine. Came back after responding to another call - Run unit for a while, tipped & tried to drain			6.50	\$435.50	\$435.50

residue coolant from pan -
found heater hoses are split
after cab was lifted. Brandt
to get heater hose pn# and
replace as needed.

Total: 0 \$0.00 6.50 \$435.50 \$435.50

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE			PARTS ISSUE					\$0.00
					BRAKE CLEAN RNCBC1	3	\$14.81			\$14.81
					GLOVES MEN NINJA ICE L MCR N9690QL	1	\$10.96			\$10.96
					GLOVES HYFLEX SIZE 10 ANS 11-801-10	1	\$2.81			\$2.81
					TOWEL PAPER 35401	1	\$10.08			\$10.08
					ANTIFREEZE LONGLIFE RED 3.78L END-3.78	2	\$34.00			\$34.00
					KIT ASSEMBLY	1	\$260.79			\$260.79
					KIT ASSEMBLY	1	\$287.97			\$287.97
					Total:	10	\$621.42	0	\$0.00	\$621.42
					Total:	10	\$621.42	6.50	\$435.50	\$1,056.92

Work Order

Work Order #: 97030
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4956.00

Date Opened: 6. Mar 2024.
Date Closed: 11. Apr 2024.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA01	UPDATE MILAGE/HOUR METER	update	[REDACTED]	[REDACTED]	update					\$0.00
Total:						0	\$0.00	0	\$0.00	\$0.00

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC00	ACCESSORIES GENERAL	arrange to have the cutting edges replaced	[REDACTED]	[REDACTED]	Get blades from blade area - took 1 long, 2 short and 2 corner edges. Drive to location and install cutting edges. One long blade is too short must have been for last dozer? Return to yard to find correct long section - last one left. Return to location and installed corect cutting edge. Dispose of all bolts & old cutting edges in steel bin. - KM / SC			5.65	\$378.55	\$378.55
Total:						0	\$0.00	5.65	\$378.55	\$378.55

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE	[REDACTED]	[REDACTED]	PARTS ISSUE					\$0.00

BOLT PLOW 3/4" X 2 1/2" 750X250	40	\$67.60			\$67.60
BOLT PLOW 3/4" X 2 1/2" 750X250	6	\$10.14			\$10.14
NUT FOR PLOW BOLT 3/4" 7502H	34	\$22.44			\$22.44
Total:	80	\$100.18	0	\$0.00	\$100.18
Total:	80	\$100.18	5.65	\$378.55	\$478.73

Work Order

Work Order #: 97122
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 4996.00

Date Opened: 20. Mar 2024.
Date Closed: 6. May 2024.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
CH17	TIRES	noticed a couple of cracks on a couple of pads on the dozer	[REDACTED]	[REDACTED]	Drive to location - found 34 pads (without moving the machine) were cracked or starting to crack from the bolt holes. One pad is split in half almost, a few pads do not have reliefs cut into them. Advised that it might be time to replace pads. Cracks likely due to on concrete use, perhaps a smaller pad width wise might help alleviate side loading pads. SEE WO 97340 FOR WORK			1.40	\$93.80	\$93.80
Total:						0	\$0.00	1.40	\$93.80	\$93.80

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE	[REDACTED]	[REDACTED]	PARTS ISSUE					\$0.00
						BOLT TRACK, NUT	704		\$1,383.72	\$1,383.72
						36" SINGLE GROUSER, MASTER SHOE	90		\$14,770.66	\$14,770.66
Total:						794	\$16,154.38	0	\$0.00	\$16,154.38

Total:	794	\$16,154.38	1.40	\$93.80	\$16,248.18
--------	-----	-------------	------	---------	-------------

Work Order

Work Order #: 97430
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: MCMURDO, KELSON
Odometer: 0.00
Hours: 5107.00

Date Opened: 26. Apr 2024.
Date Closed: 7. Jan 2025.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT16	TRANS OIL & FILTER CHANGE	HYD Oil was replaced @ 3155hr - not required yet as it is under every 4000hour service. Likely next time we see this unit HYD oil & hydrostatic oil will need be changed.			HYD Oil was replaced @ 3155hr - not required yet as it is under every 4000hour service. Likely next time we see this unit HYD oil & hydrostatic oil will need be changed. Just changed filter & took samples.			0.75	\$50.25	\$50.25
Total:						0	\$0.00	0.75	\$50.25	\$50.25

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT17	DIFF OIL CHANGE	Change Inner and outer final drive oil both sides			Change Inner and outer final drive oil both sides			4.00	\$268.00	\$268.00
Total:						0	\$0.00	4.00	\$268.00	\$268.00

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT22	HYD/PS OIL REPLACEMENT & FILTER	HYD Oil was replaced @ 3155hr - not required yet as it is under every 4000hour service. Likely next time we see this unit HYD oil & hydrostatic oil will need be changed.			HYD Oil was replaced @ 3155hr - not required yet as it is under every 4000hour service. Likely next time we see this unit HYD oil & hydrostatic oil will need to be changed. Just changed filter & took sample. Changed hydrostatic			1.75	\$117.25	\$117.25

breather.

Total: 0 \$0.00 1.75 \$117.25 \$117.25

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT27	FUEL FILTERS	Replace fuel filters			Replace 3x fuel filters, bleed fuel system & drain sediment from fuel tank.			4.25	\$284.75	\$284.75

Total: 0 \$0.00 4.25 \$284.75 \$284.75

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT15	ENGINE SERVICE AND INSPECTION	Engine oil service & inspection			Inspected using John Deere forms and literature up to 5000hours. Perform engine oil service, lubed all grease points and inspected unit. **Noticed engine oil leak from injection pump/timing cover, not bad yet. Noticed 3 rollers starting to seep and leak oil - advised supervisor. Replaced both cab filters, test all functions & lights. Reinstalled all stump pans.			10.25	\$686.75	\$686.75

Total: 0 \$0.00 10.25 \$686.75 \$686.75

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT43	OIL SAMPLE, ALL MAJOR COMPONENTS	Take oil samples from 7 different components			Take oil samples from 7 different components			0.75	\$50.25	\$50.25

Total: 0 \$0.00 0.75 \$50.25 \$50.25

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	HAVING DECKIT BRING TO CITY SERVICE CENTER			DONE					\$0.00

Total: 0 \$0.00 0 \$0.00 \$0.00

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA01	UPDATE MILAGE/HOUR METER	Update			updated 5701 hr					\$0.00

Total: 0 \$0.00 0 \$0.00 \$0.00

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO00	BODY - GENERAL REPAIRS NON-ACCIDENT RELATED	Body panel LHS is cracked - replace/repair			Machine is scheduled to come back before winter season and we will modify or fix as needed then.					\$0.00

Total: 0 \$0.00 0 \$0.00 \$0.00

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS -	Install replacement track pads			Wrong track pads have					\$0.00

GENERAL

previously purchased as they
were all or mostly crackedarrived, advised we need
track pads w/ the reliefs cut
into them as snowpack is
the majority of use for this
machine. Without relief
holes tracks can pack with
snow causing accelerated
wear on undercarriage and
even start skipping sprocket
teeth. See WO 97576

Total:	0	\$0.00	0	\$0.00	\$0.00
--------	---	--------	---	--------	--------

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT00	OTHER ACTIVITIES - GENE	Misc work done for or on unit			Misc work done for or on unit			1.50	\$100.50	\$100.50
Total:						0	\$0.00	1.50	\$100.50	\$100.50

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	ARTS ISSUE			PARTS ISSUE					\$0.00
					FREIGHT	1	\$12.00			\$12.00
					FILTER OIL HF6587 FLEETGUARD	1	\$46.61			\$46.61
					FILTER FUEL, PRIMARY FS1091 FLEETGUARD	1	\$69.24			\$69.24
					FILTER FUEL FS1093 FLEETGUARD	1	\$78.73			\$78.73
					FILTER FUEL BF461000 BALDWIN	1	\$42.15			\$42.15
					FILTER AIR, CAB LBF LAF5314 LUBERFINER	1	\$13.34			\$13.34
					FILTER AIR CAB PA30292 BALDWIN	1	\$48.35			\$48.35
					FILTER AIR AF25292 FELETGUARD	1	\$29.16			\$29.16
					OIL SAMPLE PROGRAM JD AT346594	7	\$252.18			\$252.18
					FILTER AIR AF25292 FELETGUARD	1	\$29.62			\$29.62
					OIL SYNTHETIC 0W40 18.9L KLHD2580	3	\$622.44			\$622.44
					GREASE EXTREME PRESSURE DELO EP2 235280652	2	\$25.17			\$25.17
					OIL SYNTHETIC 0W40 18.9L KLHD2580	1	\$207.48			\$207.48
					GLOVES HYFLEX LARGE (9) ANS 118019	1	\$3.66			\$3.66
					GLASSES SAFETY CLEAR DAL A700	1	\$3.24			\$3.24
					FLOOR DRY 20LB BAG EAGLE PICHER III FD85N	1	\$21.95			\$21.95
					OIL SYNTHETIC 0W40	1	\$214.16			\$214.16

18.9L KLHD2580					
DEF FILTER KIT, DZ11464	1	\$246.89			\$246.89
TOW	1	\$400.00			\$400.00
Total:	28	\$2,366.37	0	\$0.00	\$2,366.37
Total:	28	\$2,366.37	23.25	\$1,557.75	\$3,924.12

Work Order

Work Order #: 97576
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 5141.00

Date Opened: 14. May 2024.
Date Closed: 26. Sep 2024.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO00	BODY - GENERAL REPAIRS NON-ACCIDENT RELATED	Please fix or replaced LHS body panel by engine	[REDACTED]	[REDACTED]	Lifted cab to access broken panel, build new section of panel and weld up cracks. Painted & reinstalled panel/lower cab.			6.20	\$415.40	\$415.40
Total:						0	\$0.00	6.20	\$415.40	\$415.40
Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC00	ACCESSORIES GENERAL	Reinstall weather fronts	[REDACTED]	[REDACTED]	Reinstalled weather fronts			0.25	\$16.75	\$16.75
Total:						0	\$0.00	0.25	\$16.75	\$16.75
Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	Incorrect track pads were ordered & delivered, requested track pads with relief cuts pre-cut in them.	[REDACTED]	[REDACTED]	Unable to return as per supervisor, track pad reliefs will have to be cut into pads. Cut all reliefs into pads, stack on pallets and store outside ready for installation. R&R all track pads including extracting broken bolts from masterlink and setting track tension. Torque & procedure as per Deere specs. Check & set			61.65	\$4,130.55	\$4,130.55

track tension for both tracks.

Total: 0 \$0.00 61.65 \$4,130.55 \$4,130.55

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
MO00	MODIFICATIONS	Build, install & test jig to see if we can cut all pads cut on CNC plasma cutter			Build jig on table and test to see if cutting pads on CNC is viable. Worked ok - proceeded to cut all pads. Jig was welded in so I cut jig out and reinstalled all components removed/changed for the CNC plasma			6.65	\$445.55	\$445.55

Total: 0 \$0.00 6.65 \$445.55 \$445.55

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE			PARTS ISSUE					\$0.00

EXTENDED FACESHIELD	1	\$49.54		\$49.54
GLOVES HYFLEX X-LARGE (10) ANS 1180110	1	\$3.66		\$3.66
FACE SHIELD HEADGEAR FIB F500	1	\$52.84		\$52.84
DISC 4.5 IN STRIPPING SILICON	6	\$71.94		\$71.94
OIL ENGINE SYNTHETIC BLEND 5W20 BULK	1	\$4.37		\$4.37
OIL ENGINE SYNTHETIC BLEND 5W20 BULK	1	\$4.37		\$4.37
GLOVES HYFLEX LARGE (9) ANS 118019	1	\$3.66		\$3.66
FREIGHT	1	\$12.00		\$12.00
BOTTOMING TAP, HEX DI	2	\$103.20		\$103.20
KOPR-KOTE COPPER ANTI-SIEZE LUBRICANT 225ML	1	\$14.06		\$14.06
BATTERY ALKALINE 1.5V SIZE AAA EVE EN92	2	\$1.92		\$1.92
PLATE MS 1/4	10	\$240.41		\$240.41
Total:	28	\$561.97	0	\$0.00 \$561.97

Total: 28 \$561.97 74.75 \$5,008.25 \$5,570.22

Work Order

Work Order #: 97583
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 5107.00

Date Opened: 15. May 2024.
Date Closed: 26. Jul 2024.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	MOVE DOZER TO SOUTH BEAR CREEK FOR TOM MARTINEAU	[REDACTED]	CONTACTED DECKIT TO MOVE MAY 16					\$0.00
				TOW	1	\$480.00			\$480.00
				Total:	1	\$480.00	0	\$0.00	\$480.00
				Total:	1	\$480.00	0	\$0.00	\$480.00

Work Order

Work Order #: 98226
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 5126.00

Date Opened: 8. Aug 2024.
Date Closed: 29. Aug 2024.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	MOVE DOZER BCK TO CSC FRONM SOUTH BEAR BALL DIAMOND AS TOM MARTINEAU IS FINISHED WITH IT	[REDACTED]	CONTACTED DECK IT TOWING FOR TRANSPORT OF DOZER, HAULED DOZER FROM SOUTH BEAR DIAMOND TO CSC SEE INVOICE #2024-01437 TOW					\$0.00
					1	\$640.00			\$640.00
Total:					1	\$640.00	0	\$0.00	\$640.00
Total:					1	\$640.00	0	\$0.00	\$640.00

Work Order

Work Order #: 98573
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 5141.00

Date Opened: 24. Sep 2024.
Date Closed: 29. Oct 2024.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	MOVE DOZER FROM CSC TO THE SNOW DUMP	[REDACTED]	DOZER TRANSPORTED BY DECK-IT TOWING INVOICE # 2024-02215 TOW	1	\$650.50			\$650.50
Total:					1	\$650.50	0	\$0.00	\$650.50
Total:					1	\$650.50	0	\$0.00	\$650.50

Work Order

Work Order #: 99124
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 5203.00

Date Opened: 30. Nov 2024.
Date Closed: 17. Dec 2024.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	After hours call out - 2024-11-30 hyd leak	[REDACTED]	[REDACTED]	Drive to snow dump, dozer is empty on hyd oil. leak came from under cab and it has sprayed everywhere. Drive out to location @8am, attempt to lift cab - unable to lift cab, starts to lift but then just stops w/ no resistance. Call brandt technical support to confirm that cab lift and other hydraulic systems are seperate, Brent @ brandt tractor confirms they are seperate systems and the pumps can fail preventing you from physically pumping the unit up and reccomends using a portapower to power unit up and lift cab. We do not have a portapower or the couplers to make that work, advised fleet supervisor to either contract out a dozer in the mean time or brandt is available dec 1st. Dec 1 - go back to dozer, worked with brandt to			16.00	\$1,072.00	\$1,072.00

get cab up and inspect for damaged. Found filter oil ring blew out and hard line under cab backed off. Tighten up, replace filter & fill up 120~ litres of 0w40. Get machine running with use of herman nelson and run machine and check all functions.

Total: 0 \$0.00 16.00 \$1,072.00 \$1,072.00

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE			PARTS ISSUE					\$0.00
					FILTER OIL BALDWIN BT8874-MPG	1	\$69.86			\$69.86
					OIL SYNTHETIC 0W40 18.9L KLO KL-HD-2580	1	\$207.48			\$207.48
					OIL ENGINE SYNTHETIC 0W40 4.73L KLO KL-HD- 2560	19	\$752.59			\$752.59
					DIAGNOSE & REPAIR FOR HYDRAULIC LEAK	1	\$777.00			\$777.00
					Total:	22	\$1,806.93	0	\$0.00	\$1,806.93
					Total:	22	\$1,806.93	16.00	\$1,072.00	\$2,878.93

Work Order

Work Order #: 99142
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 5222.00

Date Opened: 2. Dec 2024.
Date Closed: 4. Dec 2024.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC12	RADIO EQUIPMENT REPAIRS	2-WAY RADIO STOPPED WORKING	[REDACTED]	[REDACTED]	found the power and ground wires pulled off, extended harness and installed new ends, installed back on studs and checked operation			1.50	\$100.50	\$100.50
Total:						0	\$0.00	1.50	\$100.50	\$100.50
Total:						0	\$0.00	1.50	\$100.50	\$100.50

Work Order

Work Order #: 99287
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 5459.00

Date Opened: 16. Dec 2024.
Date Closed: 24. Dec 2024.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC00	ACCESSORIES GENERAL	INSPECT FOR LOCK ON FUEL TANK WILL NOT OPEN	[REDACTED]	[REDACTED]	Removed broken key from lock in DEF access door. lube up and spray air brake anitfreeze in lock. now working as it should			2.20	\$147.40	\$147.40
Total:						0	\$0.00	2.20	\$147.40	\$147.40
Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	hydraulicx hose blown	[REDACTED]	[REDACTED]	hose blown on blade. remove hose and bring to shop. called out parts and bring hose to leymans. had new hose made and re installed. topped up with oil ran machine check for leaks			12.00	\$804.00	\$804.00
Total:						0	\$0.00	12.00	\$804.00	\$804.00
Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE	[REDACTED]	[REDACTED]	PARTS ISSUE					\$0.00
					FLUID DIESEL EXHAUST 9.46L RECOCHEM LLL DEF946	2	\$30.18			\$30.18
Total:						2	\$30.18	0	\$0.00	\$30.18

Total:	2	\$30.18	14.20	\$951.40	\$981.58
--------	---	---------	-------	----------	----------

Work Order

Work Order #: 99328
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 5789.00

Date Opened: 20. Dec 2024.
Date Closed: 27. Jan 2025.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO00	BODY - GENERAL REPAIRS NON-ACCIDENT RELATED	1. BOLTS MISSING FROM LEFT SIDE ENGINE BODY WORK 2. BOLTS MISSING FROM INSIDE AREA AROUND JOYSTICK CONTROLS 3. LEFT HAND DOOR WILL NOT OPEN FROM THE INSIDE	[REDACTED]	[REDACTED]	Tighten up bolts in front cover on engine. ordered new covers for windsheild wiper motor assembly					\$0.00
Total:						0	\$0.00	0	\$0.00	\$0.00

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	1. LEFT SIDE TRACK ADJUSTMENT COVER HAS MISSING BOLT BECAUSE THREADS ARE STRIPPED OUT 2. BLOCK HEATER IS TRIPPING GFI	[REDACTED]	[REDACTED]	Replaved bolt with one a little bigger in size in track tewnsion cover. BLOCK HEATER CORD HAS BEEN REPAIRED BY ELECTRCIAL GUYS .			1.60	\$107.20	\$107.20
Total:						0	\$0.00	1.60	\$107.20	\$107.20

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT43	OIL SAMPLE, ALL MAJOR COMPONENTS	Completed oil sample	[REDACTED]	[REDACTED]	Completed and handed in					\$0.00
Total:						0	\$0.00	0	\$0.00	\$0.00

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT27	FUEL FILTERS	DUE			Removed all 3 fuel filters and install new ones.			1.00	\$67.00	\$67.00
Total:						0	\$0.00	1.00	\$67.00	\$67.00

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT15	ENGINE SERVICE AND INSPECTION	DUE			Drain oil out of engine into buckets. removed oil filter element and install new filter. refill engine with 30 L of 0W40 engine oil. reun machine and re check level on dipstick			6.20	\$415.40	\$415.40
Total:						0	\$0.00	6.20	\$415.40	\$415.40

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE			PARTS ISSUE			2.80	\$187.60	\$187.60
						2	\$9.51			\$9.51
						1	\$68.51			\$68.51
						1	\$42.42			\$42.42
						1	\$78.14			\$78.14
						1	\$54.43			\$54.43
						1	\$38.48			\$38.48
						6	\$308.69			\$308.69
						1	\$33.03			\$33.03
Total:						14	\$633.21	2.80	\$187.60	\$820.81

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	Hydraulic hose leaking on blade			Removed hose brought to greggs got repla' cemnt made and installed. checked oil level and topped up to full			0.80	\$53.60	\$53.60
Total:						0	\$0.00	0.80	\$53.60	\$53.60
Total:						14	\$633.21	12.40	\$830.80	\$1,464.01

Work Order

Work Order #: 99487
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 5789.00

Date Opened: 17. Jan 2025.
Date Closed: 19. Feb 2025.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
DI00	DIAGNOSTIC TIME	First call by Jose at 5:17pm	[REDACTED]	Got called out to snow dump by Jose due to codes coming up. Called in Kelson to help as Jose wanted unit running for monday and I am unfamiliar with unit. Found codes active code ATC, PDU codes, ECU codes, VCU codes, all communication errors. Jose requesting to inquire with Brandt on next available tech. Assist Brianne in troubleshooting dozer as she was unfamiliar with the unit and situation. -KM			12.20	\$817.40	\$817.40
Total:					0	\$0.00	12.20	\$817.40	\$817.40

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
CH00	CHASSIS/SUSPENSION REPAIRS	Track bottom Roller broken	[REDACTED]	Went to inspect unit for broken roller and bolts. hydraulic leak on front blade. found one roller has all bolts broken off and is moving around in undercarriage. found			21.85	\$1,463.95	\$1,463.95

another roller on RH side
loose bolts. ordered new
rollers from shaylene in
parts. Bring all neccessary
equipment and Attempt to
replace track roller in field -
improper stands and lifting.
Unable to successfully lift
machine to get to rollers,
attempted to extract bolts as
is - unsuccessful in field
conditions - bolts are seized.
Reccomend bringing
machine back to shop for
better access.-KM

Total: 0 \$0.00 21.85 \$1,463.95 \$1,463.95

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	HYDRAULIC HOSE LEAKING AT FRONT OF UNIT			Checked hose and found two hoses rubbed bad . dozer is being transported to shop now for roller bolt repairs. will access at shop. KM - found one other hose rubbed through - replaced			2.25	\$150.75	\$150.75
Total:						0	\$0.00	2.25	\$150.75	\$150.75

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	Extract bolts from track frame to be able to reinstall new rollers - check over unit while at shop.			Extract 3 bolts from LHS lost roller, installed new roller to MFG procedure. RHS has one roller that has loose bolts - attempt to tighten bolts - bolts break instantly. Removed 2 other rollers on RHS, extract 7 more bolts and reinstalled new rollers according to MFG procedures.			14.50	\$971.50	\$971.50
Total:						0	\$0.00	14.50	\$971.50	\$971.50

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO00	BODY - GENERAL REPAIRS NON-ACCIDENT RELATED	Missing body bolts on LHS and engine panel is cracked with missing bolts.			Replaced missing bolts. Panel to be replaced at a later time. Inspected rest of machine looking for any obvious signs of things that should be replaced before unit gets shipped back to location.			1.00	\$67.00	\$67.00
Total:						0	\$0.00	1.00	\$67.00	\$67.00

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN	PARTS ISSUE			PARTS ISSUE					\$0.00

USE ONLY

GLOVES WORK WINTER X -LARGE BDG 309473TFLXL	1	\$9.64			\$9.64
BATTERY 31S-1000	2	\$280.00			\$280.00
3/4-10 UCG TAPER TAP	1	\$84.46			\$84.46
FREIGHT	1	\$23.00			\$23.00
HOSE, SPRING SLEEVE	1	\$126.97			\$126.97
FREIGHT	1	\$12.00			\$12.00
GROUP 31 BATTERY AUTOMOTIVE POST 31A	1	\$280.00			\$280.00
SCREW M20X70	8	\$20.16			\$20.16
SINGLE FLANGE TRACK ROLLER CR6088	1	\$481.70			\$481.70
WASHER 8T3282	8	\$2.96			\$2.96
DOUBLE FLANGE TRACK ROLLER CR6089	1	\$538.21			\$538.21
WASHER, 8T3282	4	\$1.48			\$1.48
M20X70, 6V5845	4	\$10.48			\$10.48
SINGLE FLANGE TRACK ROLLER, CR6088	1	\$412.90			\$412.90
TOW FROM SNOW DUMP TO CITY YARD	1	\$640.00			\$640.00
TOW FROM CITY YARD TO SNOW DUMP	1	\$520.00			\$520.00
WINDOW WIPER COVER T159875	1	\$125.49			\$125.49
CAB LH DOOR LATCH AT452174	1	\$405.88			\$405.88
DIAG/REPAIR FOR COMMUNICATION CODES	1	\$531.30			\$531.30
LIFT MACHINE TO REPAIR	1	\$778.39			\$778.39
Total:	41	\$5,285.02	0	\$0.00	\$5,285.02
Total:	41	\$5,285.02	51.80	\$3,470.60	\$8,755.62

Work Order

Work Order #: 99557
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 5806.00

Date Opened: 27. Jan 2025.
Date Closed: 10. Feb 2025.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	Hydraulic lines leaking at front of blade	[REDACTED]	[REDACTED]	Drive to location - no leaks found, all hyd oil is full. A couple other hoses have been replaced at some time and could have leaked onto the rest. Some hoses do look bad. Talked w/ operator - fleet to do blade change wednesday. Can order hoses today to have ready to go for wednesday from shay. Drive to location, replaced all bad hoses, a couple hoses needed to be built by leymans.			7.62	\$510.54	\$510.54
Total:						0	\$0.00	7.62	\$510.54	\$510.54

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC00	ACCESSORIES GENERAL	Latch broken and windshield washer cover is missing	[REDACTED]	[REDACTED]	Ordered through Des 1/27/25			3.00	\$201.00	\$201.00
					CAB LH DOOR LATCH AT4521741	1	\$591.04			\$591.04
					WINDOW WIPER COVER T159875	1	\$125.49			\$125.49
Total:						2	\$716.53	3.00	\$201.00	\$917.53

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
DI00	DIAGNOSTIC TIME	Communication codes on display			No communication codes active at this time. This has been looked at previously by Brandt. See previous work orders for those details. We had swapped in new batteries but don't have the programs to hook up to john deere. Load tested old batteries as they hadn't been tested yet - failed both load test. Possible bad batteries causing communication codes.			0.50	\$33.50	\$33.50
Total:						0	\$0.00	0.50	\$33.50	\$33.50

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	Needs new cutting edges on the ends and center sections flipped			Drive to location, replace/flip cutting edges.			3.13	\$209.71	\$209.71
Total:						0	\$0.00	3.13	\$209.71	\$209.71

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY				Parts Issue					\$0.00
					#8, 1/2" ID 2 WIRE BRAID HOSE MAN ROCKMASTER2SC08	21	\$102.48			\$102.48
					BOLT PLOW 3/4" X 2 1/2" 750X250	34	\$57.46			\$57.46
					NUT FOR PLOW BOLT 3/4" 7502H	34	\$22.44			\$22.44
					TOWEL PAPER WYPALL X60 KIM 35401	2	\$18.68			\$18.68
					29/32" ID SPRING SLEEVE AER 9005643	20	\$107.80			\$107.80
					4.5" SQ LED SPOT LIGHT TEC 725226EA	2	\$85.38			\$85.38
					HOSE KIT	1	\$296.95			\$296.95
					HOSE KIT	1	\$314.95			\$314.95
Total:						115	\$1,006.14	0	\$0.00	\$1,006.14
Total:						117	\$1,722.67	14.25	\$954.75	\$2,677.42

Work Order

Work Order #: 99673
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 5920.00

Date Opened: 5. Feb 2025.
Date Closed: 12. Feb 2025.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
EN00	ENGINE REPAIRS	OIL leak	[REDACTED]	[REDACTED]	Engine oil leak. all the engine oil is in skid plates. drained out the oil . removed oil filter and instal new one. re filled engine oil and ran engine no leaks			7.60	\$509.20	\$509.20
Total:						0	\$0.00	7.60	\$509.20	\$509.20

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	hydraulic hose leaking on ram	[REDACTED]	[REDACTED]	Removed hose on Ram for blade lift got new one made and installed on unit.			3.10	\$207.70	\$207.70
Total:						0	\$0.00	3.10	\$207.70	\$207.70

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE	[REDACTED]	[REDACTED]	PARTS ISSUE					\$0.00
						OIL FILTER	1	\$209.22		\$209.22
						FREIGHT	1	\$12.00		\$12.00
						ORING, FITTING, FLANGE	8	\$105.92		\$105.92
						FILTER OIL BALDWIN BLD B7335MPG	1	\$40.15		\$40.15
						OIL SYNTHETIC 0W40	2	\$408.55		\$408.55

18.9L KLO KL-HD-2580

Total:	13	\$775.84	0	\$0.00	\$775.84
Total:	13	\$775.84	10.70	\$716.90	\$1,492.74

Work Order

Work Order #: 99710
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 6190.90

Date Opened: 7. Feb 2025.
Date Closed: 2. Jun 2025.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO00	BODY - GENERAL REPAIRS NON-ACCIDENT RELATED	Latch broken on LHS cab door	[REDACTED]	[REDACTED]	STEVE ORIGINALLY ORDERED LATCH - WRONG LATCH ORDERED IN RE ORDER NEW LATCH. NEW DOOR LATCH ARRIVED FEB 18 AND IS ON SHELF #2. WRONG LATCH AGAIN - KELSON REORDERED CORRECT LATCH. 4/1/25. Installed and tested latch.			0.50	\$33.50	\$33.50
Total:						0	\$0.00	0.50	\$33.50	\$33.50

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
HY00	HYDRAULIC REPAIRS	Hydraulic leak under cab	[REDACTED]	[REDACTED]	Brian/Steve-travel to dump site. inspected unit and se oil coming from under cab. removed bolts and lifted cab. no oil in sight glass on passanger tank. inspected hoses, do not see issues with hoses. filled tank with oil and started unit. found flange at pump with a broken bolt and split oring. removed 3 other bolts.			9.20	\$616.40	\$616.40

drilled out broken bolt and replaced oring. installed new bolts. filled hydraulics and ran unit. no leaks. lowered cab and returned init to service

BRAKE CLEANER NON-CHLORINATED 396G CRC CRC 1754922	4	\$18.73			\$18.73
OIL SYNTHETIC 0W40 18.9L KLO KL-HD-2580	1	\$204.28			\$204.28
Total:	5	\$223.01	9.20	\$616.40	\$839.41

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	BOLT MISSING FROM TRACK ADJUSTMENT COVER IBN RIGHT SIDE			All bolts are present?			1.50	\$100.50	\$100.50
					7/32" VORTEX DRILL BIT, VIK22673	6	\$80.64			\$80.64
					Total:	6	\$80.64	1.50	\$100.50	\$181.14

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA01	UPDATE MILAGE/HOUR METER	Update			update 6190.9 hr					\$0.00
					Total:	0	\$0.00	0	\$0.00	\$0.00

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE			PARTS ISSUE					\$0.00
					STRIKER, AT307096	1	\$97.69			\$97.69
					LATCH, AT326979	1	\$420.59			\$420.59
					FREIGHT	1	\$12.00			\$12.00
					Total:	3	\$530.28	0	\$0.00	\$530.28
					Total:	14	\$833.93	11.20	\$750.40	\$1,584.33

Work Order

Work Order #: 99812
Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 6050.00

Date Opened: 24. Feb 2025.
Date Closed: 24. Feb 2025.

Repair Code	Repair Name	Opening Comment	Mechanic	Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
BO11	HEATING, AIR CONDITIONING REPAIRS	Green fluid on back of cab	[REDACTED]	Found a/c condensor leaking dye on back of cab from reffridgerant. Heater is still working fine so no repair at trhis time. will repair late rin springtime.					\$0.00
Total:					0	\$0.00	0	\$0.00	\$0.00
Total:					0	\$0.00	0	\$0.00	\$0.00

Work Order

Work Order #: 100063

Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 6190.90

Date Opened: 27. Mar 2025.
Date Closed: 3. Jun 2025.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AT00	ATTACHMENTS - GENERAL	TRACK ROLLER IS BROKEN ON THE LEFT SIDE AND MISSING 4 BOLTS	[REDACTED]	[REDACTED]	Drive to location, unit is in 4" inches of water. One roller seal failed and all the oil came out of it causing the roller to fail. One at the back near the sprocket is missing bolts. All bolts are broken off flush or recessed into holes. Unit does move slowly ok. Attempted to lift machine and remove loose rollers - unsuccessful. Advised supervisor machine likely to come back as it was too difficult in the past to extract undercarriage bolts in field. Near end of season as well. 03/31/25, removed stuck rollers, put machine on stands, ended up bending one stand pin as the weight was too much trying to set it up on stands. Had brandt come down with procedure to put machine on stands, recommended getting proper stands as per john deere			40.80	\$2,733.60	\$2,733.60

procedure. Prop up machine with use of extra stands as work needed to commence and stands to be ordered at a later date. Extracted all bolts (stubborn) cleaned up threads and installed new rollers.

ASSIST WITH PUTTING MACHINE ON STANDS	1	\$1,472.63			\$1,472.63
Total:	1	\$1,472.63	40.80	\$2,733.60	\$4,206.23

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AA00	PARTS-ADMIN USE ONLY	PARTS ISSUE			PARTS ISSUE					\$0.00
					FREIGHT	1	\$55.00			\$55.00
					METRIC TAP	2	\$381.38			\$381.38
					FILTER OIL BALDWIN BLD B7335MPG	1	\$33.47			\$33.47
					OIL SYNTHETIC 0W40 18.9L KLO KL-HD-2580	2	\$408.42			\$408.42
					WASHER, RLR 8T3282	16	\$6.08			\$6.08
					80LT ROLLER, V5845	16	\$40.96			\$40.96
					S/F RLR GRP, CR6088	2	\$996.38			\$996.38
					D/F RLR GRP, CR089	2	\$1,113.26			\$1,113.26
					3/4-10 HCS BOTTOMING TAP VIK 55650	1	\$24.46			\$24.46
					13/64"SST + DRILL BIT, WAL 01A513	1	\$5.19			\$5.19
					Total:	44	\$3,064.60	0	\$0.00	\$3,064.60

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
TR11	TOW/TRANSPORT/ DELIVERY	TOWING FORM SNOW DUMP			TOWING PROVIDED BY DECK IT TOWING TOM BRING DOZER FROM SNOW DUMP BACK TO THE CSC INVOICE #2025-01534					\$0.00
					TOW CAH-643	1	\$720.00			\$720.00
					Total:	1	\$720.00	0	\$0.00	\$720.00

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
OT15	ENGINE SERVICE AND INSPECTION	Engine service			Performed engine service. 30L of 0w30. Did not do oil sample as fleet supervisor declined doing due to replacement unit on order.			1.00	\$67.00	\$67.00
					Total:	0	\$0.00	1.00	\$67.00	\$67.00

Total:	46	\$5,257.23	41.80	\$2,800.60	\$8,057.83
--------	----	------------	-------	------------	------------

Work Order

Work Order #: 101359

Status: Closed

Unit #: CAH-643
Status: Replaced (pool)
Type: HEAVY EQUIPMENT
Sub-Type: DOZER

Year: 2020
Make: JOHN DEERE MFG
Model: 850L
VIN: 1T0850LXALF388897

Color: YELLOW
Licence:
Location: CITY SERVICE CENTRE
Fuel Type: DIESEL

Supervisor: [REDACTED]
Odometer:
Hours: 6191.00

Date Opened: 15. Aug 2025.
Date Closed: 18. Aug 2025.

Repair Code	Repair Name	Opening Comment	Mechanic		Closing Comment	Parts Qty	Parts	Labour hrs	Labour Costs	Total
AC00	ACCESSORIES GENERAL	Remove radio, radio mount bracket, mic bracket, do not remove wiring or attenae. Look for personal items or anything that is city property. Decals alreaday removed.	[REDACTED]	[REDACTED]	Removed radio, radio bracket, mic bracket, left wiring and attenae intact as requested			1.50	\$100.50	\$100.50
Total:						0	\$0.00	1.50	\$100.50	\$100.50
Total:						0	\$0.00	1.50	\$100.50	\$100.50