

ActivityDttm	ActivityToDttm	ActivityType	Subject	FleetNbr	VinNbr
7/28/2022 12:08	7/28/2022 12:08	OTHR1	Enable Dark Mode \$59.95	old-104-2022	1FM5K8AC5NGB29739
9/15/2022 15:07	9/15/2022 15:07	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
9/15/2022 15:08	9/15/2022 15:08	TIRER	Tire Rotation	old-104-2022	1FM5K8AC5NGB29739
9/15/2022 15:08	9/15/2022 15:08	OTHR1	MultiPoint Inspection: Front Brakes @ 12MM Rear Brakes @ 10mm Front Tires @ 8mm Rear Tires @ 9mm - Mileage 7185	old-104-2022	1FM5K8AC5NGB29739
10/21/2022 11:15	10/21/2022 11:15	OTHR1	Repair Drivers Rear Tire has a leak \$33.25	old-104-2022	1FM5K8AC5NGB29739
10/21/2022 11:16	10/21/2022 11:17	OTHR1	MultipointInspection: All tires @ 6mm Mileage 13121	old-104-2022	1FM5K8AC5NGB29739
10/27/2022 10:07	10/27/2022 10:07	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
10/27/2022 10:08	10/27/2022 10:08	TIRER	Tire Rotation	old-104-2022	1FM5K8AC5NGB29739
10/27/2022 10:08	10/27/2022 10:08	OTHR1	MultiPointInspection: Front Brakes @ 10mm Rear Brakes @ 8mm All Tires @ 6 Mllege: 14095	old-104-2022	1FM5K8AC5NGB29739
2/2/2023 9:30	2/2/2023 9:30	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
2/2/2023 9:32	2/2/2023 9:32	OTHR1	Oil Leaking Front Axle-Concern Verified WI-BASE#4A015-Replaced Left Front Axle Shaft Intermediate Housing Seal \$	old-104-2022	1FM5K8AC5NGB29739
2/2/2023 9:34	2/2/2023 9:34	TIREN	Mount & Balance (3) New Tires \$78.93	old-104-2022	1FM5K8AC5NGB29739
2/2/2023 9:35	2/2/2023 9:35	OTHR1	Perform 4 Wheel Alignment \$129.95	old-104-2022	1FM5K8AC5NGB29739
2/2/2023 9:35	2/2/2023 9:35	FILTR	Replace Cabin Air Filter \$42.16	old-104-2022	1FM5K8AC5NGB29739
4/3/2023 12:40	4/3/2023 12:40	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
4/3/2023 12:40	4/3/2023 12:41	TIRER	Tire Rotation	old-104-2022	1FM5K8AC5NGB29739
4/3/2023 12:41	4/3/2023 12:41	OTHR1	Multipoint Inspection: Front Brakes @ 8mm Rear Brakes @ 6mm Front Tires @ 7 Rear Tires @ 8 Mileage: 29381	old-104-2022	1FM5K8AC5NGB29739
6/9/2023 12:21	6/9/2023 12:21	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
6/9/2023 12:23	6/9/2023 12:23	TIREN	Mount & Balance (4) new tires \$105.24	old-104-2022	1FM5K8AC5NGB29739
6/9/2023 12:23	6/9/2023 12:23	OTHR1	Perform 4 Wheel Alignment \$129.95	old-104-2022	1FM5K8AC5NGB29739
6/9/2023 12:24	6/9/2023 12:24	BRAK1	Replace Front Pads & Rotors \$444.47	old-104-2022	1FM5K8AC5NGB29739
6/9/2023 12:25	6/9/2023 12:25	BRAK1	Replace Rear Pads & Rotors \$326.44	old-104-2022	1FM5K8AC5NGB29739
6/13/2023 12:31	6/13/2023 12:31	BRAK1	Concern Brakes Grinding-Verified repositioned backing plate	old-104-2022	1FM5K8AC5NGB29739
8/10/2023 13:27	8/10/2023 13:27	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
8/10/2023 13:28	8/10/2023 13:28	TIRER	Tire Rotation	old-104-2022	1FM5K8AC5NGB29739
8/10/2023 13:29	8/10/2023 13:29	ENGCK	Concern Veriified - Replaced Purge Valve \$230.67	old-104-2022	1FM5K8AC5NGB29739
8/10/2023 13:30	8/10/2023 13:30	OTHR1	Concern of Oil Leak from Engine Area-Verified Replaced oil pan seal and blew out front differential vent tube that was plugged w/debris	old-104-2022	1FM5K8AC5NGB29739
9/19/2023 14:40	9/19/2023 14:40	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
9/19/2023 14:41	9/19/2023 14:41	TIRER	Tire Rotation	old-104-2022	1FM5K8AC5NGB29739

ActivityDttm	ActivityToDttm	ActivityType	Subject	FleetNbr	VinNbr
9/19/2023 15:42	9/19/2023 15:43	BATRY	Battery Fail-Replaced w/New Battery \$191.30	old-104-2022	1FM5K8AC5NGB29739
9/21/2023 0:00		ENGCK	Engine check light on: Concern Verified Solenoids distorted both replaced	old-104-2022	1FM5K8AC5NGB29739
10/19/2023 15:51	10/19/2023 15:51	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
10/19/2023 15:51	10/19/2023 15:51	TIRER	Tire Rotation	old-104-2022	1FM5K8AC5NGB29739
10/19/2023 15:52	10/19/2023 15:52	OTHR1	Patch HOle in Front Passenger Tire \$26.30	old-104-2022	1FM5K8AC5NGB29739
10/19/2023 15:53	10/19/2023 15:53	OTHR1	Preliminary NOtice for FSA 23S55 Rear Axle Bolt Recall	old-104-2022	1FM5K8AC5NGB29739
10/19/2023 15:55	10/19/2023 15:55	OTHR1	MultipointInspection: Front Tires @ 5/32nds Rear Tires @ 6/32nds Front brakes @ 6mm Rear Brakes @ 8mm	old-104-2022	1FM5K8AC5NGB29739
11/21/2023 15:23	11/21/2023 15:23	TIREN	Mount & Balance (4) New Tires \$105.24	old-104-2022	1FM5K8AC5NGB29739
11/21/2023 15:23	11/21/2023 15:23	OTHR1	Perform 4 Wheel Alignment \$142.95	old-104-2022	1FM5K8AC5NGB29739
12/21/2023 9:56	12/21/2023 9:56	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
12/21/2023 9:57	12/21/2023 9:57	TIRER	Tire Rotation	old-104-2022	1FM5K8AC5NGB29739
12/21/2023 9:57	12/21/2023 9:57	FILTR	Replaced Air Filter \$26.76	old-104-2022	1FM5K8AC5NGB29739
12/21/2023 9:58	12/21/2023 9:58	FILTR	Replaced Pollen Filter \$43.42	old-104-2022	1FM5K8AC5NGB29739
12/21/2023 9:58	12/21/2023 9:58	LIGHT	Replaced Burnt out License Plate Bulb \$23.29	old-104-2022	1FM5K8AC5NGB29739
2/19/2024 10:47	2/19/2024 10:47	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
2/19/2024 10:48	2/19/2024 10:48	TIRER	Tire Rotation	old-104-2022	1FM5K8AC5NGB29739
2/19/2024 10:48	2/19/2024 10:48	OTHR1	Perform Recall 23S35-Inspect & Repair EPB Wire Harness	old-104-2022	1FM5K8AC5NGB29739
2/19/2024 10:49	2/19/2024 10:49	OTHR1	Perform Recall 23S55 Rear Axle Bolt Fractures-Replaced Rear Sub Frame Bushing & Bolt	old-104-2022	1FM5K8AC5NGB29739
2/19/2024 10:50	2/19/2024 10:50	BRAK1	Replace Front Pads & Rotors \$549.80	old-104-2022	1FM5K8AC5NGB29739
2/19/2024 10:51	2/19/2024 10:51	OTHR1	BG Brake System Flush \$160.19	old-104-2022	1FM5K8AC5NGB29739
4/8/2024 10:24	4/8/2024 10:24	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
4/8/2024 10:25	4/8/2024 10:25	LIGHT	Replace Right Rear License Plate Light Bulb \$23.29	old-104-2022	1FM5K8AC5NGB29739
4/8/2024 10:26	4/8/2024 10:26	OTHR1	Concern Fluid On Ground: Verified Concern Warr WI Base#3C084 Replaced Left Rear Axle Seal & Hardware/Adjusted Rear Toe	old-104-2022	1FM5K8AC5NGB29739
4/8/2024 10:27	4/8/2024 10:27	TIREN	Mount & Balance (4) New Tires \$117.24	old-104-2022	1FM5K8AC5NGB29739
4/8/2024 10:28	4/8/2024 10:28	OTHR1	Perform 4 Wheel Alignment \$129.95	old-104-2022	1FM5K8AC5NGB29739
4/8/2024 10:28	4/8/2024 10:28	OTHR1	Replace 6 Cylinder Spark Plugs \$327.46	old-104-2022	1FM5K8AC5NGB29739
4/8/2024 10:29	4/8/2024 10:29	OTHR1	Permormed BG 4/4 Drive Line Service \$726.29	old-104-2022	1FM5K8AC5NGB29739
6/28/2024 15:54	6/28/2024 15:54	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
6/28/2024 15:55	6/28/2024 15:55	OTHR1	Noise Rear of Vehicle: Verified Concern REplaced Rear Diff Unit & corrected rear toe \$	old-104-2022	1FM5K8AC5NGB29739

ActivityDttm	ActivityToDttm	ActivityType	Subject	FleetNbr	VinNbr
6/28/2024 15:56	6/28/2024 15:56	BRAK1	Replaced Rear Pads & Rotors \$405.72	old-104-2022	1FM5K8AC5NGB29739
6/28/2024 15:57	6/28/2024 15:57	OTHR1	Replaced Passenger Side Under Body Shield which was hanging down \$551.96	old-104-2022	1FM5K8AC5NGB29739
6/28/2024 15:57	6/28/2024 15:57	OTHR1	Replaced broken driver side flex pipe \$290.85	old-104-2022	1FM5K8AC5NGB29739
8/14/2024 11:00	8/14/2024 11:00	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
8/14/2024 11:02	8/14/2024 11:02	TIREN	Mount & Balance (4) New tires \$124.00	old-104-2022	1FM5K8AC5NGB29739
8/14/2024 11:02	8/14/2024 11:02	OTHR1	Perform 4 Wheel Alignment \$129.95	old-104-2022	1FM5K8AC5NGB29739
8/14/2024 11:03	8/14/2024 11:03	WNSHL	(2) New Front Wiper Blades \$31.38	old-104-2022	1FM5K8AC5NGB29739
8/14/2024 11:04	8/14/2024 11:04	LIGHT	Replace Burnt Out License Plate Bulb \$26.90	old-104-2022	1FM5K8AC5NGB29739
8/14/2024 11:04	8/14/2024 11:04	BRAK1	Replace Front Brake Pads & Rotors \$552.10	old-104-2022	1FM5K8AC5NGB29739
8/14/2024 11:05	8/14/2024 11:05	OTHR1	Replaced broken Drivers Front Fender Liner \$257.27	old-104-2022	1FM5K8AC5NGB29739
8/28/2024 7:48	8/28/2024 7:48	TIREN	Mount & Balance (1) New Tire \$31.00	old-104-2022	1FM5K8AC5NGB29739
9/24/2024 0:00	9/24/2024 12:40	ENGCK	Check Engine Light Concern:Replaced Canister Purge Valve \$578.89	old-104-2022	1FM5K8AC5NGB29739
9/24/2024 12:38	9/24/2024 12:38	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
9/24/2024 12:39	9/24/2024 12:39	TIRER	Tire Rotation	old-104-2022	1FM5K8AC5NGB29739
9/24/2024 12:40	9/24/2024 12:40	EXHAO	Concern Noisy Exhaust-Welded Crack in Left Catalytic Converter \$186.08	old-104-2022	1FM5K8AC5NGB29739
10/23/2024 8:03	10/23/2024 8:03	BRAK1	Concern Noise near front tire when using brakes-Verified Replaced Front Pads & Rotors \$540.60	old-104-2022	1FM5K8AC5NGB29739
10/23/2024 8:05	10/23/2024 8:05	OTHR1	Replace 6 cylinder spark plugs \$370.32	old-104-2022	1FM5K8AC5NGB29739
11/19/2024 11:31	11/19/2024 11:31	TIRER	Tire Rotation	old-104-2022	1FM5K8AC5NGB29739
11/19/2024 11:31	11/19/2024 11:31	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
11/19/2024 11:32	11/19/2024 11:32	FILTR	Air Filter Replaced \$32.34	old-104-2022	1FM5K8AC5NGB29739
12/31/2024 9:22	12/31/2024 9:22	OTHR1	Accident Repairs- AcLabel/BumperCover/LowerCover/RadiatorSupport/SkidPlate /Radiator/TransCooler/FanAssy/Condenser/SealKit/Lt Fender LedgeCover/FuelTankStrap/Paint\$7306.13	old-104-2022	1FM5K8AC5NGB29739
1/28/2025 12:56	1/28/2025 12:56	TIREN	Mount & balance (4) New Tires \$124.00	old-104-2022	1FM5K8AC5NGB29739
1/28/2025 12:56	1/28/2025 12:56	OTHR1	Perform 4 Wheel Alignment \$129.95	old-104-2022	1FM5K8AC5NGB29739
1/28/2025 12:57	1/28/2025 12:57	BATRY	Install New Battery \$223.90	old-104-2022	1FM5K8AC5NGB29739
2/19/2025 11:26	2/19/2025 11:26	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
3/27/2025 10:34	3/27/2025 10:34	OTHR1	Concern Vehicle sounds rough-Verified Replaced broken Right Side Flex Pipe \$383.40	old-104-2022	1FM5K8AC5NGB29739
4/11/2025 15:19	4/11/2025 15:19	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739

ActivityDttm	ActivityToDttm	ActivityType	Subject	FleetNbr	VinNbr
4/11/2025 15:20	4/11/2025 15:20	TIRER	Tire Rotation	old-104-2022	1FM5K8AC5NGB29739
4/11/2025 15:20	4/11/2025 15:20	FILTR	Replace Air Filter \$33.62	old-104-2022	1FM5K8AC5NGB29739
4/11/2025 15:21	4/11/2025 15:21	BRAK1	Replace Rear Pads & Rotors \$411.57	old-104-2022	1FM5K8AC5NGB29739
6/2/2025 14:19	6/2/2025 14:19	07	Oil Change , Miles: 5000	old-104-2022	1FM5K8AC5NGB29739
6/2/2025 14:20	6/2/2025 14:20	TIREN	Mount & balance 4 Tires \$124.00	old-104-2022	1FM5K8AC5NGB29739
6/2/2025 14:21	6/2/2025 14:21	FILTR	Replace Pollen Filter \$46.42	old-104-2022	1FM5K8AC5NGB29739
6/2/2025 14:21	6/2/2025 14:21	OTHR1	Perform 4 Wheel Alignment \$129.95	old-104-2022	1FM5K8AC5NGB29739