UTAH DEPARTMENT OF TRANSPORTATION SURPLUS EQUIPMENT CONDITION REPORT

SUMMARY OF CONDITION

This front-end loader starts and runs fine, and all of the functions seem to be working. There is a small crack in the bucket that should be addressed if the machine is going to be doing heavy amounts of work. The tires are in quite poor shape and should be replaced before regular operation.