## **Unit Work Order History**

t ID 105379		Description: SEI	DAN POLICE PATROL/TRAF	FIC	
WO ID	WO Description	WO Type ID	WO Status ID	Scheduled Date	Completed Date
76018	SET UP 105379 (527)	S	Completed	3/18/2016	3/21/2016
Part Cost: Part ID		Code ID	Code Description	Cost	
MAMROS0034NN06	CABLE ASSEMBLY SPEAKER			\$59.40	_
CA012616001	CABLE, DC POWER			\$95.04	
CA009562030	CABLE ASSEMBLY			\$91.08	1
			Tota	al Cost: \$245.52	<u>-</u>
Labor Cost:					
Craft	Resource				_
MECH	12	40	NEW VEHICLE / SET UP	\$112.50	)
MECH	12	40	NEW VEHICLE / SET UP	\$112.50	)
MECH	12	40	NEW VEHICLE / SET UP	\$112.50	)
MECH	12	40	NEW VEHICLE / SET UP	\$112.50	)
MECH	12	40	NEW VEHICLE / SET UP	\$75.00	)
			Total	Cost: \$525.00	)
76350	R/R PRINTER USB CABLE 527	N	Completed	4/19/2016	4/21/2016
Labor Cost:					
Craft	Resource				_
MECH	28	30	ELECTRONICS	\$131.25	5
			Total	Cost: \$131.25	5
77323	PM'S 105379 (527)	PM	Cancelled	3/23/2016	
77323	PM'S 105379 (527)	PM	Cancelled	3/23/2016	



## **Unit Work Order History**

7371	FIRST PM A. UNIT 527	PM	Completed	!	5/11/2016	5/16/2016
Part Cost:						
Part ID		Code ID	Code Description		Cost	
WL10010	FILTER	PMA			\$3.63	
5W30	OIL MOTOR	PMA			\$10.80	
M506	WASHER FLUID	PMA			\$1.15	
				Total Cost:	\$15.58	
Labor Cost:						
Craft	Resource					
MECH	30	PMA			\$112.50	
				Total Cost:	\$112.50	
8141	PM'S 105379 (527)	PM	Completed	•	7/27/2016	7/27/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
5W20	SYNTHETIC OIL	PMA			\$16.17	
100010	OIL FILTER	PMA			\$2.97	
				Total Cost:	\$19.14	
Labor Cost:						
Craft	Resource					
MECH	28	PMA			\$112.50	
				Total Cost:	\$112.50	
8141	PM'S 105379 (527)	PM	Completed		7/27/2016	7/27/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES		\$546.80	
				Total Cost:	\$546.80	
Labor Cost:	_					
Craft MECH	Resource 28	12	TIRES		\$37.50	
	/ŏ	17	LIKES		<b>%1/5U</b>	



		Unit Wo	rk Order History			
78314	LOW TIRE 527	N	Completed		8/12/2016	8/16/2016
Part Cost:						
Part ID		Code ID	Code Description		Cost	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES		\$137.24	
				Total Cost:	\$137.24	
Labor Cost:						
Craft	Resource					
MECH	28	12	TIRES		\$37.50	
				Total Cost:	\$37.50	
78970	PM'S 105379 (527)	PM	Completed	1	0/14/2016	10/14/2016
Part Cost:						
Part ID		Code ID	Code Description		Cost	
5W20	SYNTHETIC OIL	PMA			\$13.44	
100010	OIL FILTER	PMA			\$2.97	
				Total Cost:	\$16.41	
Labor Cost:						
Craft	Resource					
MECH	12	PMA			\$112.50	
				Total Cost:	\$112.50	
79120	RF LEAKS 527	N	Completed	1	0/31/2016	10/31/2016
Labor Cost:						
Craft	Resource					
MECH	28	12	TIRES		\$37.50	
				Total Cost:	\$37.50	



	•					
		Unit Wo	rk Order History			
79680	PM'S 105379 (527)	PM	Completed		1/6/2017	1/6/2017
	FM 3 103379 (327)	FIM	Combleted		1/0/2017	1/0/201/
Part Cost:						
Part ID		Code ID	Code Description		Cost	
4048	CABIN AIR FILTER DODGE	A15	CABIN AIR FILTER		\$9.81	
				Total Cost:	\$9.81	
Labor Cost:						
Craft	Resource					
MECH	21	A15	CABIN AIR FILTER		\$18.75	
				Total Cost:	\$18.75	
79680	PM'S 105379 (527)	PM	Completed		1/6/2017	1/6/2017
Part Cost:						
Part ID		Code ID	Code Description		Cost	
5W20	SYNTHETIC OIL	PMA			\$11.52	

Part Cost:						
Part ID		Code ID	Code Description		Cost	
5W20	SYNTHETIC OIL	PMA			\$11.52	
100010	OIL FILTER	PMA			\$3.06	
				Total Cost:	\$14.58	
Labor Cost:						
Craft	Resource					
MECH	21	PMA			\$75.00	
				Total Cost:	\$75.00	
19	PM'S 105379 (527)	PM	Completed		4/11/2017	4/11/2017
Part Cost:						
Part ID		Code ID	Code Description		Cost	
100010	OIL FILTER	PMA			\$3.06	
5W20	SYNTHETIC OIL	PMA			\$15.36	
M506	WASHER FLUID	PMA			\$1.15	
				Total Cost:	\$19.57	
Labor Cost:						
Craft	Resource					
MECH	12	PMA			\$112.50	



Total Cost:

\$112.50

		Unit Wo	rk Order History		
80519	PM'S 105379 (527)	PM	Completed	4/11/2017	4/11/2017
Part Cost:					
Part ID		Code ID	Code Description	Cost	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES	\$136.70	
			Total C	Cost: \$136.70	
Labor Cost:					
Craft	Resource				
MECH	12	12	TIRES	\$37.50	
			Total Co	ost: \$37.50	
80519	PM'S 105379 (527)	PM	Completed	4/11/2017	4/11/201
Part Cost: Part ID		Code ID	Code Description	Cost	
15152	BOLT	VI	VEHICLE ENHANCEMENTS	\$0.56	
12621	FLAT WASHER M8 HARDENED	VI	VEHICLE ENHANCEMENTS	\$0.12	
FS24010	6-32 X 2 SS	VI	VEHICLE ENHANCEMENTS	\$17.37	
FS25318	6-32 LOCK NUT SS	VI	VEHICLE ENHANCEMENTS	\$14.29	
			Total (		
Labor Cost:					
Craft	Resource				
MECH	12	VI	VEHICLE ENHANCEMENTS	\$337.50	
			Total Co	ost: \$337.50	
80791	RELOCATE MIC HOLDER 527	S	Completed	5/16/2017	5/16/201
Labor Cost:					
Craft	Resource				
MECH	28	VI	VEHICLE ENHANCEMENTS	\$75.00	
			Total Co	st: \$75.00	
81081	CHECK FOR BATTERY DRAIN 527	N	Completed	6/16/2017	6/27/201
Labor Cost:					
Craft	Resource				
MECH	30	07	BATTERY	\$262.50	
			Total Co	st: \$262.50	



		Heit Wa	ul Oudou History			
		Unit Wo	ork Order History			
81237	PM'S 105379 (527)	PM	Completed		7/5/2017	7/5/2017
Part Cost:	• •					
Part ID		Code ID	Code Description		Cost	
0W20	SYNTHETIC OIL	PMA			\$15.36	
100010	OIL FILTER	PMA			\$3.06	
				Total Cost:	\$18.42	
Labor Cost:						
Craft	Resource					
MECH	30	PMA			\$150.00	
				Total Cost:	\$150.00	
82026	PM'S 105379 (527) CHECK TIRES	PM	Completed		9/27/2017	9/27/2017
Part Cost:						
Part ID		Code ID	Code Description		Cost	
100010	OIL FILTER	PMA			\$3.05	
0W20	SYNTHETIC OIL	PMA			\$13.44	
				Total Cost:	\$16.49	
Labor Cost:						
Craft	Resource					
MECH	28	PMA			\$112.50	
				Total Cost:	\$112.50	
82026	PM'S 105379 (527) CHECK TIRES	PM	Completed		9/27/2017	9/27/2017
Part Cost:						
Part ID		Code ID	Code Description		Cost	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES		\$546.80	

12



TIRES

Labor Cost: Craft

MECH

Resource

28

Total Cost:

Total Cost:

\$546.80

\$37.50

\$37.50

		Unit Wo	rk Order History		
32026	PM'S 105379 (527) CHECK TIRES	PM	Completed	9/27/2017	9/27/201
Labor Cost:					
Craft	Resource				
MECH	17	ADM	ADMINISTRATIVE TIME	\$15.00	
			Total Cos	st: \$15.00	
82754	PM'S 105379 (527)	PM	Completed	12/20/2017	12/20/201
Part Cost:					
Part ID		Code ID	Code Description	Cost	
0W20	SYNTHETIC OIL	PMA		\$13.44	
M506	WASHER FLUID	PMA		\$1.14	
100010	OIL FILTER	PMA		\$3.05	
			Total Co	ost: \$17.63	
Labor Cost:					
Craft MECH	Resource	PMA			
				<b>₹112 F0</b>	
PILOTI	28	PMA	<del></del>	\$112.50	
PILGIT	28	РМА	Total Cos		
	PM'S 105379 (527)	РМ	Total Cos Completed		12/20/201
82754				st: \$112.50	12/20/201
				st: \$112.50	12/20/201
32754 Labor Cost:	PM'S 105379 (527)			st: \$112.50	12/20/201
32754  Labor Cost:  Craft	PM'S 105379 (527) Resource	РМ	Completed	\$112.50 12/20/2017 \$15.00	12/20/201
32754  Labor Cost:  Craft	PM'S 105379 (527) Resource	PM ADM	Completed  ADMINISTRATIVE TIME	\$112.50 12/20/2017 \$15.00	
82754  Labor Cost:  Craft  MECH	PM'S 105379 (527)  Resource  17  CHECK OVER FOR REASSIGNMENT, R	PM ADM	Completed  ADMINISTRATIVE TIME  Total Cos	\$112.50 12/20/2017 \$15.00 st: \$15.00	12/20/201
Labor Cost: Craft MECH	PM'S 105379 (527)  Resource  17  CHECK OVER FOR REASSIGNMENT, R	PM ADM	Completed  ADMINISTRATIVE TIME  Total Cos	\$112.50 12/20/2017 \$15.00 st: \$15.00	
Labor Cost: Craft MECH  82794  Labor Cost:	PM'S 105379 (527)  Resource  17  CHECK OVER FOR REASSIGNMENT, R BUMPER #'S 105379	PM ADM	Completed  ADMINISTRATIVE TIME  Total Cos	\$112.50 12/20/2017 \$15.00 st: \$15.00	



	ı						
			Unit Wo	ork Order History			
82794	CHECK OVER FOR REASSIGNMENT, R BUMPER #'S 105379	EMOVE	N	Completed		12/27/2017	1/3/2018
Labor Cost:							
Craft	Resource						
MECH	17	ADM	1	ADMINISTRATIVE T	IME	\$15.00	
					Total Cost:	\$15.00	
83064	CHANGE #'S TO 4043, CHECK OVER, OF DETAIL 105379	SEND	N	Completed		1/24/2018	1/24/2018
Labor Cost:							
Craft	Resource						
MECH	12	20		CHANGE OUTS		\$37.50	
					Total Cost:	\$37.50	
83064	CHANGE #'S TO 4043, CHECK OVER, OF DETAIL 105379	SEND	N	Completed		1/24/2018	1/24/2018
Labor Cost:							
Craft	Resource						
MECH	12	AR		ARBITRATOR VIDEO SYSTEM	)	\$37.50	
					Total Cost:	\$37.50	
82815	IS JANUARY 2018		IS	Completed		1/2/2018	1/31/2018
Misc Cost Sublet ID							
DETAIL	DETAIL	С	D	SUBLET / DETAIL		\$140.00	
				•			



## **Unit Work Order History**

3823	PM'S 105379 (527), PRINTER NOT W	ORKING PM	Completed	5/2/2018	5/2/201
Part Cost:					
Part ID		Code ID	Code Description	Cost	
100010	OIL FILTER	PMA		\$3.15	
21C520XB	5W20 FULL SYN QT	PMA		\$14.56	
M506	WASHER FLUID	PMA		\$1.63	
			To	tal Cost: \$19.34	
Labor Cost:					
Craft	Resource	214		+440.50	
MECH	28	PMA		\$112.50	
			Tota	al Cost: \$112.50	
823	PM'S 105379 (527), PRINTER NOT W	ORKING PM	Completed	5/2/2018	5/2/20
Part Cost:					
Part ID		Code ID	Code Description	Cost	
4048	CABIN AIR FILTER DODGE	A15	CABIN AIR FILTER	\$9.80	
			To	tal Cost: \$9.80	
Labor Cost:					
Craft	Resource				
MECH	28	A15	CABIN AIR FILTER	\$37.50	
			Tota	al Cost: \$37.50	
823	PM'S 105379 (527), PRINTER NOT W	ORKING PM	Completed	5/2/2018	5/2/20
Labor Cost:					
Craft	Resource				
MECH	28	VI	VEHICLE ENHANCEMENTS	\$150.00	
			Tota	al Cost: \$150.00	



		Unit Wo	rk Order History			
		Offic Wo	ik Order mistory			
4297	LEFT REAR TIRE HAS SLOW LEAK, I.T. STATES LAPTOP DOCK HAS BAD USB POR 105379	N T	Completed		7/6/2018	7/6/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES		\$144.03	
				Total Cost:	\$144.03	
Labor Cost:						
Craft	Resource					
MECH	21	12	TIRES		\$75.00	
				Total Cost:	\$75.00	
						7/6/201
4297	LEFT REAR TIRE HAS SLOW LEAK, I.T. STATES LAPTOP DOCK HAS BAD USB POR 105379	N T	Completed		7/6/2018	//6/201
Labor Cost:	STATES LAPTOP DOCK HAS BAD USB POR 105379		Completed		7/6/2018	7/6/201
Labor Cost: Craft	STATES LAPTOP DOCK HAS BAD USB POR 105379 Resource	Т				//6/201
Labor Cost:	STATES LAPTOP DOCK HAS BAD USB POR 105379		Completed	Total Cost:	\$75.00	//6/201
Labor Cost: Craft MECH	STATES LAPTOP DOCK HAS BAD USB POR 105379  Resource 21	T 06	ELECTRICAL	Total Cost:	\$75.00 \$75.00	
Labor Cost: Craft MECH	STATES LAPTOP DOCK HAS BAD USB POR 105379 Resource	Т		Total Cost:	\$75.00	
Labor Cost: Craft MECH	STATES LAPTOP DOCK HAS BAD USB POR 105379  Resource 21	T 06	ELECTRICAL	Total Cost:	\$75.00 \$75.00	8/31/201
Labor Cost: Craft MECH  4771 Part Cost:	STATES LAPTOP DOCK HAS BAD USB POR 105379  Resource 21  PM'S 105379 (527)	06 PM	ELECTRICAL Completed	Total Cost:	\$75.00 \$75.00 8/31/2018	
Labor Cost: Craft MECH  4771 Part Cost: Part ID	STATES LAPTOP DOCK HAS BAD USB POR 105379  Resource 21	T  06  PM  Code ID	ELECTRICAL Completed	Total Cost:	\$75.00 \$75.00 8/31/2018 Cost \$16.64	
Labor Cost: Craft MECH  4771 Part Cost: Part ID 21C520XB	STATES LAPTOP DOCK HAS BAD USB POR 105379  Resource 21  PM'S 105379 (527)  5W20 FULL SYN QT	06 PM Code ID PMA	ELECTRICAL Completed	Total Cost:	\$75.00 \$75.00 8/31/2018	
Labor Cost: Craft MECH  4771 Part Cost: Part ID 21C520XB 100010  Labor Cost:	STATES LAPTOP DOCK HAS BAD USB POR 105379  Resource 21  PM'S 105379 (527)  5W20 FULL SYN QT OIL FILTER	06 PM Code ID PMA	ELECTRICAL Completed		\$75.00 \$75.00 8/31/2018 Cost \$16.64 \$3.15	
Labor Cost: Craft MECH  4771 Part Cost: Part ID 21C520XB 100010	STATES LAPTOP DOCK HAS BAD USB POR 105379  Resource 21  PM'S 105379 (527)  5W20 FULL SYN QT	06 PM Code ID PMA	ELECTRICAL Completed		\$75.00 \$75.00 8/31/2018 Cost \$16.64 \$3.15	



84771	PM'S 105379 (527)	PM	Completed	8	/31/2018	8/31/2018
Part Cost:						
Part ID		Code ID	Code Description		Cost	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES		\$576.12	
				Total Cost:	\$576.12	
Labor Cost:						
Craft	Resource					
MECH	30	12	TIRES		\$75.00	
				Total Cost:	\$75.00	
84771	PM'S 105379 (527)	PM	Completed	8	/31/2018	8/31/2018
Part Cost: Part ID		Code ID	Code Description		Cost	
FT8997	BRAKE PADS	15	BRAKES		\$43.81	
FT8998	DISC PAD	15	BRAKES		\$44.11	
110330	DISCIND	13	DIV INCO	Total Cost:	\$87.92	
Labor Cost:	_					
Craft	Resource					
MECH	30	15	BRAKES		\$150.00	
MECH	30	15	BRAKES		\$150.00	
				Total Cost:	\$300.00	
85277	FLAT TIRE, 105379	N	Completed	10	/31/2018	10/31/2018
Part Cost:						
Part ID		Code ID	Code Description		Cost	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES		\$144.03	
				Total Cost:	\$144.03	
Labor Cost:						
Craft	Resource					
MECH	12	12	TIRES		\$38.50	
				Total Cost:	\$38.50	



		Unit Wo	rk Order History		
85312	IS OCTOBER TOWING	N	Completed	11/5/2018	10/31/201
Misc Cost _Sublet ID					
WRECKER TIRE	TIRE CHANGE ON LIGHT VEHICLE	СТО	SUBLET / TOWING	\$32.50	
			Tota	l Cost: \$32.50	
35746	PM'S 105379 (527), VARIOUS ISSUES (SEE COMMENTS)	PM	Completed	1/9/2019	1/10/20:
Part Cost:					
Part ID		Code ID	Code Description	Cost	
NP24	WIPER BLADE	PMA		\$4.24	
M506	WASHER FLUID	PMA		\$0.89	
100010	OIL FILTER	PMA		\$3.23	
NP21	WIPER BLADE	PMA		\$3.14	
21E520SB	5W20 FULL SYN QT	PMA		\$17.29	
			Tota	al Cost: \$28.79	
Labor Cost:					
Craft	Resource				
MECH	12 F	PMA		\$115.50	
			Total	Cost: \$115.50	
5746	PM'S 105379 (527), VARIOUS ISSUES (SEE COMMENTS)	PM	Completed	1/9/2019	1/10/20
35746	PM'S 105379 (527), VARIOUS ISSUES (SEE COMMENTS)	PM	Completed	1/9/2019	1/10/20:



		Unit Wo	ork Order History			
85746	PM'S 105379 (527), VARIOUS ISSUES (SEE COMMENTS)	PM	Completed		1/9/2019	1/10/2019
Part Cost: Part ID		Code ID	Code Description		Cost	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES		\$144.03	
				Total Cost:	\$144.03	
Labor Cost:						
<u>Craft</u> MECH	Resource 12	12	TIRES		\$77.00	
				Total Cost:	\$77.00	
85746	PM'S 105379 (527), VARIOUS ISSUES (SEE COMMENTS)	PM	Completed		1/9/2019	1/10/2019
<b>Part Cost:</b> Part ID		Code ID	Code Description		Cost	
CBC	BACKUP CAMERA	06	ELECTRICAL		\$20.46	
BCICH41	BACKUP CAMERA INTERFACE	06	ELECTRICAL		\$170.54	
				Total Cost:	\$191.00	
<b>Labor Cost:</b> Craft	Resource					
MECH		06	ELECTRICAL		\$154.00	
				Total Cost:	\$154.00	
85746	PM'S 105379 (527), VARIOUS ISSUES (SEE COMMENTS)	PM	Completed		1/9/2019	1/10/2019
Labor Cost:						
Craft	Resource					
MECH	12	AR	ARBITRATOR VIDEO SYSTEM		\$115.50	
				Total Cost:	\$115.50	



		Unit Wo	rk Order History			
36272	BAD BATTERY 105379	R	Completed		3/25/2019	4/2/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
7549	BATTERY	07	BATTERY		\$95.70	
				Total Cost:	\$95.70	
Labor Cost:						
Craft	Resource					
MECH	28	07	BATTERY		\$77.00	
				Total Cost:	\$77.00	
36385	TOW TICKETS MARCH 2019	IS	Completed		4/9/2019	3/31/201
Misc Cost Sublet ID						
WRECKER TIRE	TIRE CHANGE ON LIGHT VEHICLE	сто	SUBLET / TOWING		\$32.50	
WRECKER JUMP	JUMP START	СТО	SUBLET / TOWING		\$32.50	
				Total Cost:	\$65.00	
6553	PM'S 105379 (527)	PM	Completed		5/6/2019	5/6/20:
Part Cost: Part ID		Code ID	Code Description		Cost	
M506	WASHER FLUID	PMA	<del>`</del>		\$1.08	
21E520SB	5W20 FULL SYN QT	PMA			\$17.29	
100010	OIL FILTER	PMA			\$3.29	
				Total Cost:	\$21.66	
Labor Cost:						
Craft	Resource					
MECH	28	PMA			\$115.50	
				Total Cost:	\$115.50	



Unit	Work	Order	History
------	------	-------	---------

86553	PM'S 105379 (527)	PM	Completed		5/6/2019	5/6/2019
Part Cost:						
Part ID		Code ID	Code Description		Cost	
4048	CABIN AIR FILTER DODGE	A15	CABIN AIR FILTER		\$8.33	
				Total Cost:	\$8.33	
Labor Cost:						
Craft	Resource					
MECH	28	A15	CABIN AIR FILTER		\$38.50	
				Total Cost:	\$38.50	
86553	PM'S 105379 (527)	PM	Completed		5/6/2019	5/6/2019
Part Cost:						
Part ID		Code ID	Code Description		Cost	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES		\$288.06	
				Total Cost:	\$288.06	
Labor Cost:						
Craft	Resource					
MECH	28	12	TIRES		\$77.00	
				Total Cost:	\$77.00	
86711	LAPTOP DOCK NOT CHARGING AND P NOT WORK 527	RINTER N	Completed		5/29/2019	5/30/2019
Labor Cost:						
Craft	Resource					
MECH	30	06	ELECTRICAL		\$154.00	
				Total Cost:	\$154.00	

<b>Unit Work Order History</b>
--------------------------------

87517	PM'S 105379, GAS CAP LOCK INOP(527)	PM	Completed		9/13/2019	9/20/2019
Part Cost:						
Part ID		Code ID	Code Description		Cost	
100010	OIL FILTER	PMA			\$3.29	
21E520SB	5W20 FULL SYN QT	PMA			\$15.54	
				Total Cost:	\$18.83	
Labor Cost:						
Craft	Resource					
MECH	30	PMA			\$154.00	
				Total Cost:	\$154.00	
87517	PM'S 105379, GAS CAP LOCK INOP(527)	PM	Completed		9/13/2019	9/20/201
Part Cost: Part ID		Code ID	Code Description		Cost	
68037875AE	FILLER HOUSING ACTUATOR	27	FUEL SYSTEM		\$100.82	
68141862AB	FUEL FILLER RELEASE SWITCH	27	FUEL SYSTEM		\$20.02	
				Total Cost:	\$120.84	
Labor Cost:						
Craft	Resource					
MECH	30	27	FUEL SYSTEM		\$308.00	
				Total Cost:	\$308.00	
87517	PM'S 105379, GAS CAP LOCK INOP(527)	PM	Completed		9/13/2019	9/20/201
Labor Cost:						
Craft	Resource					
MECH	30	A03	CHARGER COOLING F REPLACEMENT	-AN	\$154.00	
				Total Cost:	\$154.00	



			Unit W	ork Order History			
87579	REASSIGN TO #4627, HAVIS RADIOVOI CUTS OUT, DETAIL, INSTALL FUE DOOF LATCH, 105379 3	LUME R	PM	Completed		9/24/2019	9/27/2019
Labor Cost:							
Craft	Resource						
MECH	30	20		CHANGE OUTS		\$154.00	
					Total Cost:	\$154.00	
87579	REASSIGN TO #4627, HAVIS RADIOVOI CUTS OUT, DETAIL, INSTALL FUE DOOF LATCH, 105379		PM	Completed		9/24/2019	9/27/2019
Labor Cost:							
Craft	Resource						
MECH	30	06		ELECTRICAL		\$308.00	
					Total Cost:	\$308.00	
87579	REASSIGN TO #4627, HAVIS RADIOVOI CUTS OUT, DETAIL, INSTALL FUE DOOF LATCH, 105379 3		PM	Completed		9/24/2019	9/27/2019
Labor Cost:							
Craft	Resource						
MECH	30	27		FUEL SYSTEM		\$269.50	
					Total Cost:	\$269.50	
87622	OCTOBER 2019 ISSUE SLIP		IS	Completed		10/1/2019	10/31/2019
Misc Cost Sublet ID							
DETAIL	DETAIL					\$140.00	
					Total Cost:	\$140.00	



	<u> </u>				
		Unit Wo	rk Order History		
88036	PM'S, VARIOUS ISSUES, 105379 (527)	PM	Completed	11/27/2019	12/2/2019
Part Cost: Part ID		Code ID	Code Description	Cost	
5137713AA	FAN COOLING	A03	CHARGER COOLING FAN REPLACEMENT	\$69.30	
			То	tal Cost: \$69.30	
<b>Labor Cost:</b> Craft	Resource				
MECH	12	A03	CHARGER COOLING FAN REPLACEMENT	\$77.00	
				al Cost: \$77.00	
88036	PM'S, VARIOUS ISSUES, 105379 (527)	PM	Completed	11/27/2019	12/2/2019
Labor Cost:					
Craft	Resource				
MECH	12	26	ENGINE	\$77.00	
			Tota	al Cost: \$77.00	
88036	PM'S, VARIOUS ISSUES, 105379 (527)	PM	Completed	11/27/2019	12/2/201
Part Cost:					
Part ID		Code ID	Code Description	Cost	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES	\$598.40	
			То	tal Cost: \$598.40	
Labor Cost:					
Craft	Resource				
MECH	12	12	TIRES	\$77.00	
			Tota	al Cost: \$77.00	
88036	PM'S, VARIOUS ISSUES, 105379 (527)	PM	Completed	11/27/2019	12/2/2019
88036	PM'S, VARIOUS ISSUES, 105379 (527)	PM	Completed	11/27/2019	12/2/2019

AR

<b>** ** ** ** ** ** ** **</b>		,
	GI	,

ARBITRATOR VIDEO SYSTEM

Total Cost:

\$77.00

\$77.00

MECH

**Labor Cost:** Craft

Resource

12

		Unit Wo	rk Order History		
88036	PM'S, VARIOUS ISSUES, 105379 (527)	PM	Completed	11/27/2019	12/2/201
Labor Cost:					
Craft	Resource				
MECH	12	L	LABOR	\$38.50	
			•	Total Cost: \$38.50	
88036	PM'S, VARIOUS ISSUES, 105379 (527)	PM	Completed	11/27/2019	12/2/201
Labor Cost:					
Craft MECH	Resource 12	16	EMISSION SYSTEM	\$77.00	
MECH	12	10		Total Cost: \$77.00	
				Total Cost: \$77.00	
88036	PM'S, VARIOUS ISSUES, 105379 (527)	PM	Completed	11/27/2019	12/2/20
Part Cost:					
Part ID		Code ID	Code Description	Cost	
NP21	WIPER BLADE	32	GLASS / INTERIOR	\$3.30	
NP24	WIPER BLADE	32	GLASS / INTERIOR	\$4.46	
M506	WASHER FLUID	32	GLASS / INTERIOR	\$1.08	
				Total Cost: \$8.84	
88222	TOW TICKECTS NOVEMBER 2019	N	Completed	12/31/2019	11/30/201
Misc Cost Sublet ID					
WRECKER TIRE	TIRE CHANGE ON LIGHT VEHICLE			\$32.50	
				Total Cost: \$32.50	
88488	CAMERA FEEL OFF, 105379	N	Completed	2/7/2020	2/7/202
Labor Cost:					
Craft	Resource				
MECH	21	AR	ARBITRATOR VIDEO SYSTEM	\$77.00	
				Total Cost: \$77.00	



	Unit Work Order History							
8488	CAMERA FEEL OFF, 105379	N	Completed		2/7/2020	2/7/2020		
Part Cost:								
Part ID		Code ID	Code Description		Cost			
1RF14DX9AB	VISOR CLIP	32	GLASS / INTERIOR		\$16.84			
				Total Cost:	\$16.84			
8436	FEBRUARY 2020 ISSUE SLIP	N	Completed		2/3/2020	2/28/202		
Misc Cost Sublet ID								
WARRANTY DEDUCTABLE	WARRANTY DEDUCTABLE	CWD	SUBLET / WARRANTY DEDUCTIBLE		\$100.00			
				Total Cost:	\$100.00			
8572	PM'S , ENGINE TICK, FRONT NUMBERS REPLACE, 105379 (527)	PM	Completed		2/20/2020	2/20/202		
Part Cost: Part ID		Code ID	Code Description		Cost			
M506	WASHER FLUID	PMA			\$1.08			
21E520SB	5W20 FULL SYN QT	PMA			\$13.44			
100010	OIL FILTER	PMA			\$3.29			
				Total Cost:	\$17.81			
Labor Cost:								
Craft	Resource							
MECH	12	PMA			\$115.50			
				Total Cost:	\$115.50			
8572	PM'S , ENGINE TICK, FRONT NUMBERS REPLACE, 105379 (527)	PM	Completed		2/20/2020	2/20/202		
Part Cost:								
Part ID		Code ID	Code Description		Cost			
68277082AA	ENGINE MOUNT	26	ENGINE		\$131.20			
				Total Cost:	\$131.20			
Labor Cost:								
Craft	Resource							
MECH	12	26	ENGINE		\$231.00			
				Total Cost:	\$231.00			



		Unit Wo	rk Order History			
88656	CHECK ENGINE NO POWER, 105379	N	Completed		3/4/2020	3/3/202
Labor Cost:						
Craft	Resource					
MECH	12	16	EMISSION SYSTEM		\$77.00	
				Total Cost:	\$77.00	
89352	FLAT TIRE , 105379	R	Completed		6/12/2020	6/15/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES		\$301.68	
				Total Cost:	\$301.68	
Labor Cost:						
Craft	Resource					
MECH	12	12	TIRES		\$57.75	
				Total Cost:	\$57.75	
89360	CHECK FRONT END , BRAKES , LIGHT BA LIGHT STAYS ON, 105379	R PM	Completed		6/15/2020	6/17/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
2608146	LOWER CONTROL ARM	44	SUSPENSION		\$128.30	
2607226	C/A ASSY	44	SUSPENSION		\$75.68	
2607225	C/A ASSY	44	SUSPENSION		\$75.68	
				Total Cost:	\$279.66	
Labor Cost:						
Craft	Resource					
MECH	12	44	SUSPENSION		\$154.00	
MECH	12	44	SUSPENSION		\$77.00	
				Total Cost:	\$231.00	



		Unit Wo	ork Order History			
9360	CHECK FRONT END , BRAKES , LIGHT BAR LIGHT STAYS ON, 105379	РМ	Completed		6/15/2020	6/17/202
Labor Cost:						
Craft	Resource					
MECH	12	06	ELECTRICAL		\$19.25	
				Total Cost:	\$19.25	
9360	CHECK FRONT END , BRAKES , LIGHT BAR LIGHT STAYS ON, 105379	PM	Completed		6/15/2020	6/17/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
21E520SB	5W20 FULL SYN QT	PMA			\$13.38	
100010	OIL FILTER	PMA			\$3.29	
M506	WASHER FLUID	PMA			\$1.66	
				Total Cost:	\$18.33	
<b>Labor Cost:</b> Craft	Resource					
MECH		PMA			\$115.50	
				Total Cost:	\$115.50	
9360	CHECK FRONT END , BRAKES , LIGHT BAR LIGHT STAYS ON, 105379	PM	Completed		6/15/2020	6/17/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
FT8997	BRAKE PADS	15	BRAKES		\$49.25	
FT8998	DISC PAD	15	BRAKES		\$50.02	
68245094AA	CALIPER	15	BRAKES		\$194.04	
68245095AA	CALIPER	15	BRAKES		\$194.04	
				Total Cost:	\$487.35	
Labor Cost:	_					
Craft	Resource	4.5	DDAI/EC		+260.50	
		15	BRAKES	Total Cost:	\$269.50 \$269.50	



		Unit Wo	rk Order History			
89360	CHECK FRONT END , BRAKES , LIGHT BAF LIGHT STAYS ON, 105379	R PM	Completed		6/15/2020	6/17/2020
Part Cost: Part ID		Code ID	Code Description		Cost	
4048	CABIN AIR FILTER DODGE	A15	CABIN AIR FILTER		\$8.33	
				Total Cost:	\$8.33	
<b>Labor Cost:</b> Craft	Resource					
MECH	12	A15	CABIN AIR FILTER		\$19.25	
				Total Cost:	\$19.25	
89360	CHECK FRONT END , BRAKES , LIGHT BAF LIGHT STAYS ON, 105379	R PM	Completed		6/15/2020	6/17/202
Labor Cost: Craft	Resource					
MECH	12	L	LABOR		\$38.50	
				Total Cost:	\$38.50	
89257	ISSUE SLIP JUNE 2020	N	Completed		6/1/2020	6/30/202
Misc Cost Sublet ID						
ALIGNMENT	ALIGNMENT	CAB	SUBLET / ALIGNMEN BALANCING	Γ-	\$49.95	
				Total Cost:	\$49.95	
89491	JULY SER SLIP 2020	N	Completed		7/2/2020	7/31/202
Misc Cost Sublet ID						
ALIGNMENT	ALIGNMENT	CAB	SUBLET / ALIGNMEN BALANCING	Γ-	\$49.95	
				Total Cost:	\$49.95	
89588	POP IN STEERING , SOFT BRAKES, CHECK AC, VARIOUS CONCERNS SEE WRITE UP , 105379	C N	Completed		7/17/2020	7/20/202



	· ·					
		Unit	: Work Order History			
89588	POP IN STEERING , SOFT BRAKES, CHECK AC, VARIOUS CONCERNS SEE WRITE UP , 105379	N	Completed	7,	/17/2020	7/20/2020
Labor Cost:						
Craft	Resource					
MECH	12	06	ELECTRICAL		\$77.00	
MECH	12	06	ELECTRICAL		\$77.00	
				Total Cost:	\$154.00	
39588	POP IN STEERING , SOFT BRAKES, CHECK AC, VARIOUS CONCERNS SEE WRITE UP , 105379	N	Completed	7,	/17/2020	7/20/2020
Labor Cost: Craft	Resource					
MECH	12	05	AIR CONDITIONING		\$115.50	
				Total Cost:	\$115.50	
89588	POP IN STEERING , SOFT BRAKES, CHECK AC, VARIOUS CONCERNS SEE WRITE UP , 105379	N	Completed	7,	/17/2020	7/20/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
FT881774	ROTOR	15	BRAKES		\$145.60	
FT880395	ROTOR	15	BRAKES		\$106.42	
				Total Cost:	\$252.02	
Labor Cost:						
Craft	Resource					
MECH	12	15	BRAKES		\$192.50	



		Unit Wo	rk Order History			
89714	CLUNKING NOISE IN FRONT END, CHECK OVER FOR REASSIGNMENT, SHINE SHACK ,105379	N	Completed		8/3/2020	8/13/2020
Part Cost: Part ID		Code ID	Code Description		Cost	
51914	OIL MAT	35	STEERING		\$1.56	
2607225	C/A ASSY	35	STEERING		\$75.68	
2607226	C/A ASSY	35	STEERING		\$75.68	
				Total Cost:	\$152.92	
Labor Cost:						
Craft	Resource					
MECH	12	35	STEERING		\$77.00	
MECH	12	35	STEERING		\$231.00	
				Total Cost:	\$308.00	
89714	CLUNKING NOISE IN FRONT END, CHECK OVER FOR REASSIGNMENT, SHINE SHACK ,105379	N	Completed		8/3/2020	8/13/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
329024	WHITE NUMBER KIT	20	CHANGE OUTS		\$1.62	
				Total Cost:	\$1.62	
Labor Cost:						
Craft	Resource					
MECH	12	20	CHANGE OUTS		\$57.75	
				Total Cost:	\$57.75	
89714	CLUNKING NOISE IN FRONT END, CHECK OVER FOR REASSIGNMENT, SHINE SHACK ,105379	N	Completed		8/3/2020	8/13/202
Labor Cost:						
Craft	Resource					
MECH	12	L	LABOR		\$57.75	
				Total Cost:	\$57.75	



Unit	Work	Order	History

90561	PM'S 105379 (527)	PM	Completed		12/9/2020	12/9/202
Part Cost: Part ID		Code ID	Code Description		Cost	
NP24	WIPER BLADE	PMA			\$4.46	
NP21	WIPER BLADE	PMA			\$3.30	
100010	OIL FILTER	PMA			\$3.29	
21E520SB	5W20 FULL SYN QT	PMA			\$13.38	
				Total Cost:	\$24.43	
Labor Cost:						
Craft	Resource					
MECH	21	PMA			\$115.50	
				Total Cost:	\$115.50	
90721	L/F HEADLIGHT OUT, 105379	N	Completed		1/12/2021	1/11/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
9005N	BOXED CAPSULES	06	ELECTRICAL		\$6.77	
				Total Cost:	\$6.77	
Labor Cost:						
Craft MECH	Resource 30	06	ELECTRICAL		\$154.00	
MECH	30	UU	ELECTRICAL	<del></del>		
				Total Cost:	\$154.00	

		Unit Wo	ork Order History		
91239	PM'S 105379 , INSTALL NEW RADIO , A/C INOP	РМ	Completed	3/29/2021	3/30/2021
Part Cost:					
Part ID		Code ID	Code Description	Cost	
176130	FENDER WASHER	VI	VEHICLE ENHANCEMENTS	\$0.22	
21E520SB	5W20 FULL SYN QT	PMA		\$23.64	
29746	AIR FILTER	PMA		\$10.75	
100010	OIL FILTER	PMA		\$3.29	
			Total C	ost: \$37.90	
Labor Cost:					
Craft	Resource				
MECH	33	PMA		\$115.50	
			Total Co	st: \$115.50	
91239	$\ensuremath{PM'S}$ 105379 , INSTALL NEW RADIO , A/C INOP	PM	Completed	3/29/2021	3/30/202
Labor Cost:					
Craft	Resource				
MECH	33	VI	VEHICLE ENHANCEMENTS	\$192.50	
MECH	33	VI	VEHICLE ENHANCEMENTS	\$154.00	
			Total Co	st: \$346.50	
91239	$\ensuremath{PM'S}$ 105379 , INSTALL NEW RADIO , A/C INOP	PM	Completed	3/29/2021	3/30/202
Labor Cost:					
Craft	Resource				
MECH	33	05	AIR CONDITIONING	\$77.00	
			Total Co	st: \$77.00	



		Unit Wo	rk Order History			
1239	PM'S 105379 , INSTALL NEW RADIO , A/C INOP	PM	Completed		3/29/2021	3/30/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
R134	FREON	05	AIR CONDITIONING		\$5.96	
721324	TERMINALS	06	ELECTRICAL		\$0.75	
728098	CONNECTOR	06	ELECTRICAL		\$1.86	
				Total Cost:	\$8.57	
Labor Cost: Craft	Resource					
MECH	33	06	ELECTRICAL		\$38.50	
			T	otal Cost:	\$38.50	
2025	PRINTER INOP, 105379	N	Completed		7/14/2021	7/14/202
Part Cost: Part ID		Code ID	Code Description		Cost	
7822165	FUSE	06	ELECTRICAL		\$0.32	
LB3692001	CAR ADAPTER	06	ELECTRICAL		\$27.49	
725103	BUTT CONNECTOR	06	ELECTRICAL		\$0.16	
			<del>-</del>	Total Cost:	\$27.97	
Labor Cost:						
Craft	Resource	0.5	EL EGERTONI		+77.00	
MECH	33	06	ELECTRICAL =		\$77.00	
			T	otal Cost:	\$77.00	
2119	PM'S 105379	PM	Completed		7/27/2021	7/29/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
100010	OIL FILTER	PMA			\$3.37	
21E520SB	5W20 FULL SYN QT	PMA			\$23.64	
			<del>-</del>	Total Cost:	\$27.01	
Labor Cost:	2					
Craft	Resource					
MECH	32	PMA			\$115.50	



92119	PM'S 105379	PM	Completed		7/27/2021	7/29/2021
Part Cost:					,,_,,_	77237232
Part ID		Code ID	Code Description		Cost	
011688MB	225/60WR18 FIRESTONE MOUNTED	12	TIRES		\$297.08	
	.,			Total Cost:	\$297.08	
Labor Cost:						
Craft	Resource					
MECH	32	12	TIRES		\$154.00	
				Total Cost:	\$154.00	
92119	PM'S 105379	PM	Completed		7/27/2021	7/29/202
Part Cost: Part ID		Code ID	Code Description		Cost	
4048	CABIN AIR FILTER DODGE	A15	CABIN AIR FILTER		\$7.08	
				Total Cost:	\$7.08	
<b>Labor Cost:</b> Craft	Resource					
MECH	32	A15	CABIN AIR FILTER		\$38.50	
				Total Cost:	\$38.50	
92119	PM'S 105379	PM	Completed		7/27/2021	7/29/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
AFC10100	50/50 ANTIFREEZE	03	COOLING SYSTEM		\$12.62	
HT203248	THERMOSTAT	03	COOLING SYSTEM		\$15.43	
44020	WATER PUMP	03	COOLING SYSTEM		\$111.89	
5184653AF	CROSSOVER	03	COOLING SYSTEM		\$56.10	
				Total Cost:	\$196.04	
Labor Cost:						
Craft	Resource					
MECH	32	03	COOLING SYSTEM		\$385.00	
				Total Cost:	\$385.00	



	•					
		Unit W	ork Order History			
92887	PM'S 105379 (527), CHECK OVER FOR CHANGE OUT, ID#'S 4894, WIPER BLADES	РМ	Completed		11/15/2021	11/23/202
22887	PM'S 105379 (527), CHECK OVER FOR CHANGE OUT, ID#'S 4894, WIPER BLADES	PM	Completed		11/15/2021	11/23/202
Part Cost: Part ID		Code ID	Code Description		Cost	
21E520SB	5W20 FULL SYN QT	PMA			\$27.58	
100010	OIL FILTER	PMA			\$3.49	
				Total Cost:	\$31.07	
Labor Cost:						
Craft	Resource	DNAA			+151.00	
MECH	30	PMA			\$154.00	
				Total Cost:	\$154.00	
92887	PM'S 105379 (527), CHECK OVER FOR CHANGE OUT, ID#'S 4894, WIPER BLADES	PM	Completed		11/15/2021	11/23/202
Labor Cost:						
Craft	Resource					
MECH	30	20	CHANGE OUTS		\$154.00	
				Total Cost:	\$154.00	
92887	PM'S 105379 (527), CHECK OVER FOR CHANGE OUT, ID#'S 4894, WIPER BLADES	PM	Completed		11/15/2021	11/23/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
011690MB	22560VR18 FIRESTONE FIREHAWK	12	TIRES		\$640.88	
				Total Cost:	\$640.88	
Labor Cost:	_					
Craft	Resource		TIRE		<u> </u>	
MECH	30	12	TIRES	<del></del>	\$77.00	
				Total Cost:	\$77.00	



		Unit Wo	rk Order History			
02887	PM'S 105379 (527), CHECK OVER FOR CHANGE OUT, ID#'S 4894, WIPER BLADES	РМ	Completed		11/15/2021	11/23/2021
Part Cost: Part ID		Code ID	Code Description		Cost	
	MATDED DI ADE					
NP24	WIPER BLADE	32	GLASS / INTERIOR		\$4.46	
NP21	WIPER BLADE	32	GLASS / INTERIOR		\$3.30	
90670	COUPLER	32	GLASS / INTERIOR		\$5.64	
				Total Cost:	\$13.40	
2987	REASSIGN ID# 4968, WINDOW SWITCH INOP, 105379	N	Completed		12/1/2021	12/1/2021
Labor Cost:						
Craft	Resource					
MECH	37	20	CHANGE OUTS		\$0.00	
				Total Cost:	\$0.00	
92987	REASSIGN ID# 4968, WINDOW SWITCH INOP, 105379	N	Completed		12/1/2021	12/1/2021
Part Cost:						
Part ID		Code ID	Code Description		Cost	
PA4766	SWITCH	06	ELECTRICAL		\$131.32	
				Total Cost:	\$131.32	
Labor Cost:						
Craft	Resource					
MECH	37	06	ELECTRICAL		\$0.00	
				Total Cost:	\$0.00	
2993	DEC 2021 SERVICE TICKET	N	Completed		12/1/2021	12/31/2021
Misc Cost Sublet ID						
DETAIL	DETAIL				\$150.00	
				Total Cost:	\$150.00	



		Unit W	ork Order History			
93904	PM'S 105379 (527), CHANGE OUT #S ,S12 DETAIL	, PM	Completed		4/18/2022	4/21/2022
<b>Part Co</b> Part ID	st:	Code ID	Code Description		Cost	
100010	OIL FILTER	PMA			\$3.95	
21E520S	B 5W20 FULL SYN QT	PMA			\$23.64	
				Total Cost:	\$27.59	
Labor C						
<u>Craft</u> MECH	Resource 21	PMA			\$115.50	
				Total Cost:	\$115.50	
93904	PM'S 105379 (527), CHANGE OUT #S ,S12 DETAIL	, PM	Completed		4/18/2022	4/21/2022
Labor C	ost:					
<u>Craft</u>	Resource					
MECH	21	20	CHANGE OUTS		\$77.00	
				Total Cost:	\$77.00	
93904	PM'S 105379 (527), CHANGE OUT #S ,S12 DETAIL	, PM	Completed		4/18/2022	4/21/2022
Labor C	ost:					
Craft	Resource					
MECH	21	12	TIRES		\$77.00	
MECH	21	12	TIRES		\$115.50	
				Total Cost:	\$192.50	



		Unit Wo	rk Order History			
93904	PM'S 105379 (527), CHANGE OUT #S DETAIL	,S12 , PM	Completed		4/18/2022	4/21/2022
Part Cost:					_	
Part ID		Code ID	Code Description		Cost	
725254	BUTT CONNECTOR	06	ELECTRICAL		\$6.88	
724112	TERMINAL	06	ELECTRICAL		\$1.80	
724103	TERMINAL	06	ELECTRICAL		\$0.39	
				Total Cost:	\$9.07	
Labor Cost:						
Craft	Resource					
MECH	21	06	ELECTRICAL		\$269.50	
				Total Cost:	\$269.50	
93904	PM'S 105379 (527), CHANGE OUT #S DETAIL	,S12 , PM	Completed		4/18/2022	4/21/2022
Labor Cost:						
Craft	Resource					
MECH	21	AR	ARBITRATOR VIDEO		\$154.00	
			SYSTEM			
				Total Cost:	\$154.00	
93986	ENGINE TICK , BACK SEAT CAMERA I 105379	NOP, N		Total Cost:		5/2/2022
		NOP, N		Total Cost:	\$154.00	5/2/2022
Labor Cost:	105379	NOP, N		Total Cost:	\$154.00	5/2/2022
		NOP, N		Total Cost:	\$154.00	5/2/2022
Labor Cost: Craft	105379 Resource		Completed	Total Cost:	\$154.00 4/28/2022	5/2/2022
Labor Cost: Craft	105379 Resource	26	Completed		\$154.00 4/28/2022 \$231.00	
Labor Cost: Craft MECH 93986	Resource 33  ENGINE TICK , BACK SEAT CAMERA I	26	Completed		\$154.00 4/28/2022 \$231.00 \$231.00	5/2/2022
Labor Cost: Craft MECH	Resource 33  ENGINE TICK , BACK SEAT CAMERA I	26	Completed		\$154.00 4/28/2022 \$231.00 \$231.00	
Labor Cost: Craft MECH 93986 Labor Cost:	Resource  33  ENGINE TICK , BACK SEAT CAMERA I 105379	26	Completed		\$154.00 4/28/2022 \$231.00 \$231.00	



94449	OVERHEATED , BELT BROKE , 105379	N	Completed		7/11/2022	7/13/2022
Part Cost:						
Part ID		Code ID	Code Description		Cost	
5278767AB	CAP	03	COOLING SYSTEM		\$12.87	
				Total Cost:	\$12.87	
Labor Cost:						
Craft	Resource					
MECH	33	03	COOLING SYSTEM		\$77.00	
				Total Cost:	\$77.00	
94449	OVERHEATED , BELT BROKE , 105379	N	Completed		7/11/2022	7/13/2022
94449	OVERHEATED , BELT BROKE , 105379	N	Completed		7/11/2022	7/13/2022
Part Cost:						
Part ID		Code ID	Code Description		Cost	
2138994	REMAN ALTERNATOR	09	ALTERNATOR		\$338.81	
				Total Cost:	\$338.81	
Labor Cost:						
Craft	Resource					
MECH	33	09	ALTERNATOR		\$115.50	
				Total Cost:	\$115.50	
94449	OVERHEATED , BELT BROKE , 105379	N	Completed		7/11/2022	7/13/2022
Part Cost:						
Part ID		Code ID	Code Description		Cost	
219301	PULLEY	26	ENGINE		\$8.70	
25060658	SERP BELT	26	ENGINE		\$21.41	
38082	IDLER PULLEY	26	ENGINE		\$26.91	
				Total Cost:	\$57.02	



Unit '	Work	Order	History
--------	------	-------	---------

94449	OVERHEATED , BELT BROKE , 105379	N	Completed		7/11/2022	7/13/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
6653246	RETAINERS	29	BODY / PAINT		\$4.22	
6655121	PUSH PIN	29	BODY / PAINT		\$4.28	
				Total Cost:	\$8.50	
Labor Cost:						
Craft	Resource					
MECH	33	29	BODY / PAINT		\$38.50	
				Total Cost:	\$38.50	
94449	OVERHEATED , BELT BROKE , 105379	N	Completed		7/11/2022	7/13/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
011688MB	225/60WR18 FIRESTONE MOUNTED	12	TIRES		\$604.88	
				Total Cost:	\$604.88	
Labor Cost:						
Craft	Resource					
MECH	33	12	TIRES		\$57.75	
				Total Cost:	\$57.75	
94449	OVERHEATED , BELT BROKE , 105379	N	Completed		7/11/2022	7/13/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
68239789AC	NOZZLE	32	GLASS / INTERIOR		\$78.50	
68239794AE	HOSE	32	GLASS / INTERIOR		\$52.97	
				Total Cost:	\$131.47	
Labor Cost:						
Craft	Resource					
MECH	33	32	GLASS / INTERIOR		\$38.50	
				Total Cost:	\$38.50	



	·					
		Unit Wo	ork Order History			
94449	OVERHEATED , BELT BROKE , 105379	N	Completed		7/11/2022	7/13/2022
Labor Cost:						
Craft	Resource					
MECH	33	PMA			\$115.50	
				Total Cost:	\$115.50	
94427	SERVICE TICKET JULY 2022	N	Completed		7/6/2022	7/31/202
<b>Misc Cost</b> Sublet ID						
TOW	TOW				\$45.00	
TOW	TOW				\$45.00	
TOW	TOW				\$152.00	
				Total Cost:	\$242.00	
94936	PM'S 105379 (527), ENGINE RUNS HOT	PM	Completed		9/12/2022	9/16/202
Part Cost: Part ID		Code ID	Code Description		Cost	
21E520SB	5W20 FULL SYN QT	PMA			\$23.64	
100010	OIL FILTER	PMA			\$4.19	
7041929	OIL DRAIN PLUG	PMA			\$3.52	
7011323	OIL DIVERTILES			Total Cost:	\$31.35	
Labor Cost:						
Craft	Resource					
MECH	37	PMA			\$0.00	
				Total Cost:	\$0.00	



# **Unit Work Order History**

94936	PM'S 105379 (527), ENGINE RUNS HOT	PM	Completed		9/12/2022	9/16/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
99655771	DUAL HD FAN ASSEMBLY	A03	CHARGER COOLING FA REPLACEMENT	AN	\$388.08	
			_	Total Cost:	\$388.08	
Labor Cost:						
Craft	Resource					
MECH	37	A03	CHARGER COOLING FA REPLACEMENT	AN	\$0.00	
			T	Total Cost:	\$0.00	
94936	PM'S 105379 (527), ENGINE RUNS HOT	PM	Completed		9/12/2022	9/16/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
AFC10100	50/50 ANTIFREEZE	03	COOLING SYSTEM		\$15.12	
AFC10100	50/50 ANTIFREEZE	03	COOLING SYSTEM		\$15.12	
55038163AI	HOSE	03	COOLING SYSTEM		\$139.43	
HT203248	THERMOSTAT	03	COOLING SYSTEM		\$16.83	
HT203248	THERMOSTAT	03	COOLING SYSTEM		\$16.83	
NR13157A	RADIATOR	03	COOLING SYSTEM		\$180.96	
			_	Total Cost:	\$384.29	
Labor Cost:						
Craft	Resource					
MECH	37	03	COOLING SYSTEM		\$0.00	
MECH	37	03	COOLING SYSTEM		\$0.00	
MECH	37	03	COOLING SYSTEM		\$0.00	
MECH	37	03	COOLING SYSTEM		\$0.00	
			Ţ	Total Cost:	\$0.00	



		Unit Wo	rk Order History			
94936	PM'S 105379 (527), ENGINE RUNS HOT	PM	Completed		9/12/2022	9/16/2022
Part Cost:						
Part ID		Code ID	Code Description		Cost	
270355	canister	16	EMISSION SYSTEM		\$83.09	
				Total Cost:	\$83.09	
Labor Cost:						
<u>Craft</u> MECH	Resource 37	16	EMICCION CYCTEM		+0.00	
МЕСП	3/	16	EMISSION SYSTEM	Total Cost:	\$0.00 \$0.00	
94936	PM'S 105379 (527), ENGINE RUNS HOT	PM	Completed		9/12/2022	9/16/2022
Part Cost:						
Part ID		Code ID	Code Description		Cost	
NP24	WIPER BLADE	32	GLASS / INTERIOR		\$4.76	
M506	WASHER FLUID	32	GLASS / INTERIOR		\$2.40	
NP21	WIPER BLADE	32	GLASS / INTERIOR		\$3.30	
				Total Cost:	\$10.46	
94936	PM'S 105379 (527), ENGINE RUNS HOT	PM	Completed		9/12/2022	9/16/2022
Part Cost:						
Part ID		Code ID	Code Description		Cost	
737301	LOOM	06	ELECTRICAL		\$2.88	
06133	ELECTRICAL TAPE	06	ELECTRICAL		\$6.29	
7701755	TAPE	06	ELECTRICAL		\$5.91	
50020R	PIG TAIL	06	ELECTRICAL		\$1.29	
				Total Cost:	\$16.37	
Labor Cost:						
Craft	Resource					
MECH	37	06	ELECTRICAL		\$0.00	
				Total Cost:	\$0.00	



94936	PM'S 105379 (527), ENGINE RUNS HOT	PM	Completed		9/12/2022	9/16/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
7651589	GASKET	26	ENGINE		\$7.06	
				Total Cost:	\$7.06	
Labor Cost:						
Craft	Resource					
MECH	37	26	ENGINE		\$0.00	
MECH	37	26	ENGINE		\$0.00	
MECH	37	26	ENGINE		\$0.00	
			T	Fotal Cost:	\$0.00	
95378	DEAD BATTERY , 105379	N	Completed		11/9/2022	11/9/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
7549	BATTERY	07	BATTERY		\$116.31	
725105	BUTT CONNECTOR	07	BATTERY		\$0.10	
			-	Total Cost:	\$116.41	
Labor Cost:						
Craft	Resource					
MECH	12	07	BATTERY		\$77.00	
			T	Fotal Cost:	\$77.00	
95672	JANUARY 2023 SERVICE TICKET	N	Completed		1/3/2023	1/31/202
Misc Cost						
Sublet ID						
INSURANCE DEDUCTIBLE	INSURANCE DEDUCTIBLE	CID	SUBLET / INSURANCE DEDUCTIBLE		\$1,000.00	
DEDUCTIBLE			· · · · · · · · · · · · · · · · · · ·	Total Cost:	\$1,000.00	
95891	FUEL SMELL IN CAR, 105379	N	Completed		2/3/2023	2/6/202
Labor Cost:						
Craft	Resource					
MECH	33	27	FUEL SYSTEM		\$346.50	
			-	Total Cost:	\$346.50	



Report ID: 1111

		Unit Wo	rk Order History		
95891  Part Cost:	FUEL SMELL IN CAR, 105379	N	Completed	2/3/2023	2/6/2023
Part Cost: Part ID		Code ID	Code Description	Cost	
725255	BUTT CONNECTOR	06	ELECTRICAL	\$0.41	
725254	BUTT CONNECTOR	06	ELECTRICAL	\$4.30	
			•	Total Cost: \$4.71	
95891	FUEL SMELL IN CAR, 105379	N	Completed	2/3/2023	2/6/2023
Part Cost: Part ID		Code ID	Code Description	Cost	
68596317AA	OIL COOLER	26	ENGINE	\$206.25	
75749	5W20 SYN OIL	26	ENGINE	\$21.42	
MIS19879	GASKET SET	26	ENGINE	\$67.10	
			•	Total Cost: \$294.77	
Labor Cost: Craft	Resource				
MECH	33	26	ENGINE	\$269.50	
			-	Total Cost: \$269.50	
95891	FUEL SMELL IN CAR, 105379	N	Completed	2/3/2023	2/6/2023
Part Cost: Part ID		Code ID	Code Description	Cost	
4800BC	BRAKE CLEANER	03	COOLING SYSTEM	\$4.82	
5184977AH	THERMOSTAT	03	COOLING SYSTEM	\$42.33	
RTU1EXT	COOLANT	03	COOLING SYSTEM	\$16.70	
				Total Cost: \$63.85	



		Unit Wo	rk Order History			
96930	PM'S 105379 (527),HEADLIGHT OUT , REMOVE ARBITRATOR	РМ	Completed		7/19/2023	7/28/2023
Part Cost: Part ID		Code ID	Code Description		Cost	
100010	OIL FILTER	PMA			\$4.19	
9746	AIR FILTER	PMA			\$17.83	
75749	5W20 SYN OIL	PMA			\$21.42	
				Total Cost:	\$43.44	
Labor Cost:						
Craft	Resource					
MECH	33	PMA			\$115.50	
				Total Cost:	\$115.50	
96930	PM'S 105379 (527),HEADLIGHT OUT , REMOVE ARBITRATOR	PM	Completed		7/19/2023	7/28/2023

Code ID

A15

A15

CABIN AIR FILTER DODGE

Resource 33

		_	
1		a	

Code Description

CABIN AIR FILTER

CABIN AIR FILTER

Total Cost:

Total Cost:

Part Cost:

**Labor Cost:** Craft

Part ID

4048

MECH

Cost

\$8.78

\$8.78

\$19.25

\$19.25

Unit	Work	Order	History
------	------	-------	---------

96930	PM'S 105379 (527),HEADLIGHT OUT , REMOVE ARBITRATOR	PM	Completed	7/19/2023	7/28/2023
Part Cost: Part ID		Code ID	Code Description	Cost	
725254	BUTT CONNECTOR	06	ELECTRICAL	\$8.60	
9005N	BOXED CAPSULES	06	ELECTRICAL	\$7.11	
50020R	50020R PIG TAIL	06	ELECTRICAL	\$2.52	
			Total	Cost: \$18.23	
Labor Cost:					
Craft	Resource				
MECH	33	06	ELECTRICAL	\$154.00	
MECH	33	06	ELECTRICAL	\$19.25	
			Total C	Cost: \$173.25	
96930	PM'S 105379 (527),HEADLIGHT OUT , REMOVE ARBITRATOR	РМ	Completed	7/19/2023	7/28/202
Labor Cost:					
Craft	Resource				
MECH	33	AR	ARBITRATOR VIDEO SYSTEM	\$77.00	
			Total 0	Cost: \$77.00	

		Unit Wo	rk Order History			
96930	PM'S 105379 (527),HEADLIGHT OUT , REMOVE ARBITRATOR	РМ	Completed		7/19/2023	7/28/2023
Part Cost:						
Part ID		Code ID	Code Description		Cost	
6511905AA	NUT	44	SUSPENSION		\$12.88	
772665	STRUT	44	SUSPENSION		\$279.26	
2608146	LOWER CONTROL ARM	44	SUSPENSION		\$160.50	
2607225	C/A ASSY	44	SUSPENSION		\$68.79	
2607226	C/A ASSY	44	SUSPENSION		\$68.79	
				Total Cost:	\$590.22	
Labor Cost:						
Craft	Resource					
MECH	33	44	SUSPENSION		\$231.00	
MECH	33	44	SUSPENSION		\$96.25	
				Total Cost:	\$327.25	
96930	PM'S 105379 (527),HEADLIGHT OUT , REMOVE ARBITRATOR	PM	Completed		7/19/2023	7/28/2023
Part Cost:						
Part ID		Code ID	Code Description		Cost	
NP24	WIPER BLADE	32	GLASS / INTERIOR		\$5.06	
NP21	WIPER BLADE	32	GLASS / INTERIOR		\$3.75	
M506	WASHER FLUID	32	GLASS / INTERIOR		\$2.55	
				Total Cost:	\$11.36	
Labor Cost:						
Craft	Resource					
MECH	33	32	GLASS / INTERIOR		\$57.75	



\$57.75

Total Cost:

		Unit Wo	rk Order History		
6930	PM'S 105379 (527),HEADLIGHT OUT , REMOVE ARBITRATOR	PM	Completed	7/19/2023	7/28/2023
Part Cost: Part ID		Code ID	Code Description	Cost	
	ENCINE MOUNT				
68277082AA	ENGINE MOUNT	26	ENGINE	\$223.20	
				Total Cost: \$223.20	
Labor Cost:					
Craft	Resource				
MECH	33	26	ENGINE	\$115.50	
				Total Cost: \$115.50	
7005	AUGUST 2023, ISSUE SLIP, SER	N	Completed	8/1/2023	8/31/2023
Misc Cost Sublet ID					
ALIGNMENT	ALIGNMENT			\$49.95	
				Total Cost: \$49.95	
7415	R/R TURN SIGNAL OUT, 105379	N	Completed	10/2/2023	10/2/2023
Labor Cost:					
Craft	Resource				
MECH	33	06	ELECTRICAL	\$38.50	
				Total Cost: \$38.50	
7872	PM'S 105379, RIGHT TURN SIGNAL OUT	PM	Completed	12/7/2023	12/7/2023
Part Cost:					
Part ID		Code ID	Code Description	Cost	
100010	OIL FILTER	26	ENGINE	\$4.11	
75749	5W20 SYN OIL	26	ENGINE	\$19.80	
				Total Cost: \$23.91	
Labor Cost:	_				
Craft	Resource	D144		140.1-0	
MECH	12	PMA		\$124.50	
				Total Cost: \$124.50	



Report ID: 1111

		Unit Wo	rk Order History			
97872	PM'S 105379, RIGHT TURN SIGNAL OUT	PM	Completed		12/7/2023	12/7/2023
Labor Cost:						
Craft	Resource					
MECH	12	06	ELECTRICAL		\$41.50	
				Total Cost:	\$41.50	
97872	PM'S 105379, RIGHT TURN SIGNAL OUT	PM	Completed		12/7/2023	12/7/2023
Part Cost:						
Part ID		Code ID	Code Description		Cost	
M506	WASHER FLUID	32	GLASS / INTERIOR		\$2.55	
				Total Cost:	\$2.55	
98675	PM'S 105379 , RIGHT BLINKER INOP	PM	Completed		4/18/2024	4/24/2024
Part Cost:						
Part ID		Code ID	Code Description		Cost	
75749	5W20 SYN OIL	26	ENGINE		\$16.44	
100010	OIL FILTER	26	ENGINE		\$4.11	
				Total Cost:	\$20.55	
Labor Cost:						
Craft	Resource					
MECH	21	PMA			\$124.50	
				Total Cost:	\$124.50	
98675	PM'S 105379 , RIGHT BLINKER INOP	PM	Completed		4/18/2024	4/24/2024
Labor Cost:						
Craft	Resource					
MECH	21	06	ELECTRICAL		\$166.00	
				Total Cost:	\$166.00	



	Unit Work Order History							
8675	PM'S 105379 , RIGHT BLINKER INOP	PM	Completed		4/18/2024	4/24/2024		
Part Cost: Part ID		Code ID	Code Description		Cost			
NP24	WIPER BLADE	32	GLASS / INTERIOR		\$5.06			
NP21	WIPER BLADE	32	GLASS / INTERIOR		\$3.75			
				Total Cost:	\$8.81			
8675	PM'S 105379 , RIGHT BLINKER INOP	PM	Completed		4/18/2024	4/24/2024		
Part Cost: Part ID		Code ID	Code Description		Cost			
FT881774	ROTOR	15	BRAKES		\$177.54			
FT8997	BRAKE PADS	15	BRAKES		\$57.15			
FT8998	DISC PAD	15	BRAKES		\$58.06			
				Total Cost:	\$292.75			
Labor Cost: Craft	Resource							
MECH	21	15	BRAKES		\$207.50			
MECH	21	15	BRAKES		\$166.00			
				Total Cost:	\$373.50			
8675	PM'S 105379 , RIGHT BLINKER INOP	PM	Completed		4/18/2024	4/24/2024		
Part Cost: Part ID		Code ID	Code Description		Cost			
011688MB	225/60WR18 FIRESTONE MOUNTED	12	TIRES		\$623.92			
				Total Cost:	\$623.92			
<b>Labor Cost:</b> Craft	Resource							
MECH	21	12	TIRES		\$83.00			
MECH	21	12	TIRES		\$41.50			



		Unit Wo	rk Order History			
98675	PM'S 105379 , RIGHT BLINKER INOP	PM	Completed	4/18	3/2024	4/24/2024
Labor Cost:						
Craft	Resource					
MECH	21	16	EMISSION SYSTEM		\$124.50	
			T	otal Cost:	\$124.50	
98675	PM'S 105379 , RIGHT BLINKER INOP	PM	Completed	4/18	3/2024	4/24/2024
Labor Cost:						
Craft	Resource		NATOCELL ANEQUIC		+62.25	
MECH	21	М	MISCELLANEOUS		\$62.25	
MECH	21	М	MISCELLANEOUS		\$41.50	
			T	otal Cost:	\$103.75	
98675	PM'S 105379 , RIGHT BLINKER INOP	PM	Completed	4/18	3/2024	4/24/2024
Part Cost:						
Part ID		Code ID	Code Description		Cost	
IC751	COIL	26	ENGINE		\$27.69	
9407	SPARK PLUG	26	ENGINE		\$36.36	
			<del>-</del>	Total Cost:	\$64.05	
Labor Cost:						
Craft	Resource					
MECH	21	26	ENGINE		\$249.00	
			Ti	otal Cost:	\$249.00	
98844	A/C INOP, 105379	N	Completed	5/16	5/2024	5/16/2024
Part Cost:						
Part ID		Code ID	Code Description		Cost	
R134	FREON	05	AIR CONDITIONING		\$9.64	
			-	Total Cost:	\$9.64	
Labor Cost:						
Craft	Resource					
MECH	33	05	AIR CONDITIONING		\$124.50	
				otal Cost:	\$124.50	



## **Unit Work Order History**

		Offic Wo	ik Order History			
344	A/C INOP, 105379	N	Completed	į	5/16/2024	5/16/2024
Part Cost: Part ID		Code ID	Code Description		Cost	
58893899	HOOD SUPPORT	29	BODY / PAINT		\$24.18	
				Total Cost:	\$24.18	
Labor Cost:						
Craft	Resource					
MECH	33	29	BODY / PAINT		\$20.75	
				Total Cost:	\$20.75	

Total Number of Work Orders:	157
Total Labor Costs:	\$15,270.50
Total Part Costs:	\$12,061.36
Total Sublet	\$2,051.85
Total Costs: —	\$29,383.71

## Site Totals:

Total Number of Work Orders:	157
<b>Total Labor Costs:</b>	\$15,270.50
Total Part Costs:	\$12,061.36
Total Sublet	\$2,051.85
Total Costs:	\$29,383.71

### Report Totals:

Total Number of Work Orders:	157
Total Labor Costs:	\$15,270.50
Total Part Costs:	\$12,061.36
Total Sublet	\$2,051.85
Total Costs:	\$29,383.71

Filter:

Unit id begins with '105379'



Report ID: 1111

Printed Date: