ID 105307		Description: SEI	OAN POLICE PATROL/TRAF	FIC	
WO ID	WO Description	WO Type ID	WO Status ID	Scheduled Date	Completed Date
73947	SET UP 105307	S	Completed	8/20/2015	9/25/2015
Labor Cost:					
Craft	Resource				
MECH	12	40	NEW VEHICLE / SET UP	\$240.00	
MECH	12	40	NEW VEHICLE / SET UP	\$120.00	
			Total	Cost: \$360.00	•
74228	TIRES 105307	N	Completed	9/17/2015	9/30/2015
Labor Cost:	_				
Craft	Resource	12	TIDEC	±40.00	•
MECH	28	12	TIRES	\$40.00	-
			lotal	Cost: \$40.00	
74566	PM 105307 TAG LIGHT OUT	PM	Completed	10/21/2015	10/25/2015
Part Cost: Part ID		Code ID	Code Description	Cost	
5W30	OIL MOTOR		· · · · · · · · · · · · · · · · · · ·	\$8.82	•
WL10010	FILTER			\$3.27	
***************************************	TELEK		Tota	al Cost: \$12.09	_
Labor Cost:					
Craft	Resource				<u>-</u>
MECH	21	A10	LUBE,OIL,FILTER SERVICE	\$18.75	_
			Total	Cost: \$18.75	
74566	PM 105307 TAG LIGHT OUT	PM	Completed	10/21/2015	10/25/2015
Labor Cost:					
Craft	Resource				
MECH	21	A11	SAFETY / PREVENT. MAINTENANCE SERVICE	\$37.50	
			Total	Cost: \$37.50	

iMaint

		Unit Wo	rk Order History		
74566	PM 105307 TAG LIGHT OUT	PM	Completed	10/21/2015	10/25/201
Labor Cost:					
Craft	Resource				
MECH	21	A30	BRAKE INSPECTION	\$37.50	
			Total Cos	st: \$37.50	
74566	PM 105307 TAG LIGHT OUT	PM	Completed	10/21/2015	10/25/201
Labor Cost:					
Craft	Resource				
MECH	21	06	ELECTRICAL	\$37.50	
			Total Cos	st: \$37.50	
76027	PM'S 105307 (503), MOVE CHARGER	PM	Completed	3/18/2016	3/24/201
Part Cost:					
Part ID		Code ID	Code Description	Cost	
WL10010	FILTER			\$3.63	
5W30	OIL MOTOR			\$8.76	
			Total Co	ost: \$12.39	
Labor Cost:					
Craft	Resource				
MECH 28	28	A10-D	LOF DODGE CHARGER	\$18.75	
			Total Cos	st: \$18.75	
76027	PM'S 105307 (503), MOVE CHARGER	PM	Completed	3/18/2016	3/24/201
Labor Cost:					
Craft	Resource				
MECH	28	A11	SAFETY / PREVENT. MAINTENANCE SERVICE	\$56.25	
			Total Cos	st: \$56.25	



	Unit Work Order History						
76027	PM'S 105307 (503), MOVE CHARGER	PM	Completed	3/18/2016	3/24/201		
Labor Cost:							
Craft	Resource						
MECH	28	A30	BRAKE INSPECTION	\$37.50			
			Total Co.	st: \$37.50			
76027	PM'S 105307 (503), MOVE CHARGER	PM	Completed	3/18/2016	3/24/201		
Labor Cost:							
Craft	Resource						
MECH	28	VI	VEHICLE ENHANCEMENTS	\$112.50			
			Total Co.	st: \$112.50			
75852	IS	IS	Completed	3/1/2016	3/30/201		
Misc Cost Sublet ID							
SUBLET / PAINT BODY		СРВ	SUBLET / PAINT-BODY	\$1,000.00			
			Total Co	st: \$1,000.00			
77312	PM'S 105307 (503)	РМ	Cancelled	2/25/2016			
77313	PM'S 105307 (503)	PM	Cancelled	5/10/2016			
77990	STALLED AND WONT RESTART 105307	N	Cancelled	7/12/2016			
78036	UNIT 105307 DIAG INOP VIDEO SYSTEM, INSTALL ANGLED RADIO BRACKET AND CHECK LAPTOP CHARGER	N	Completed	7/18/2016	7/18/201		

	,						
			Unit Wo	rk Order History			
78036	UNIT 105307 DIAG INOP VIDEO SYSTEM, INSTALL ANGLED RADIO BRACKET AND CHECK LAPTOP CHARGER		N	Completed		7/18/2016	7/18/2016
Labor Cost:							
Craft	Resource						
MECH	12	VI		VEHICLE ENHANCEM		\$56.25	
					Total Cost:	\$56.25	
78036	UNIT 105307 DIAG INOP VIDEO SYSTEM, INSTALL ANGLED RADIO BRACKET AND CHECK LAPTOP CHARGER		N	Completed		7/18/2016	7/18/2016
Labor Cost:							
Craft	Resource						
MECH	30	AR		ARBITRATOR VIDEO SYSTEM		\$75.00	
					Total Cost:	\$75.00	
78239	TOW TICKETS FOR JULY 2016		N	Completed		8/4/2016	7/31/201
Misc Cost Sublet ID							
WRECKER CLASS A	CLASS A WRECKER	1		TOWING		\$50.75	
					Total Cost:	\$50.75	
78307	PUSH BUMPER LIGHT OUT 105307		N	Completed		8/11/2016	8/11/2016
Labor Cost:							
Craft	Resource						
MECH	12	06		ELECTRICAL		\$18.75	
					Total Cost:	\$18.75	

78562	PM'S 105307 (503)	PM	Completed		9/2/2016	9/2/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
5W30	OIL MOTOR	PMA			\$10.22	
M506	WASHER FLUID	PMA			\$1.15	
100010	OIL FILTER	PMA			\$2.97	
				Total Cost:	\$14.34	
Labor Cost:						
Craft	Resource					
MECH	12	PMA			\$93.75	
				Total Cost:	\$93.75	
78932	TOW TICKETS FOR SEPTEMBER 2016	IS	Completed		10/12/2016	9/30/201
Misc Cost Sublet ID						
WRECKER CLASS A	CLASS A WRECKER	1	TOWING		\$68.75	
				Total Cost:	\$68.75	
79015	NAIL IN TIRE 503	N	Cancelled		10/19/2016	
79886	PM'S 105307 (503)	PM	Completed		1/31/2017	1/31/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
100010	OIL FILTER	PMA			\$3.06	
5W20	SYNTHETIC OIL	PMA			\$13.44	
31120				Total Cost:	\$16.50	
3.1.23						



	Unit Work Order History							
79944	EMERGENCY LIGHT OUT 503	N	Completed		2/6/2017	2/6/201		
Labor Cost:								
Craft	Resource							
MECH	12	06	ELECTRICAL		\$56.25			
				Total Cost:	\$56.25			
30611	IS	IS	Completed		4/21/2017	4/21/20		
Misc Cost Sublet ID								
WRECK REPAIR DEDUCTIBLE	WRECK REPAIR DEDUCTIBLE	CA	SUBLET / ACCIDENT		\$681.65			
				Total Cost:	\$681.65			
80995	TOW TICKETS MAY 2017	IS	Completed		6/8/2017	6/12/20		
Misc Cost Sublet ID								
WRECKER TIRE	TIRE CHANGE ON LIGHT VEHICLE	1	TOWING		\$32.50			
				Total Cost:	\$32.50			
31114	PM'S 105307 (503)	PM	Completed		6/20/2017	6/19/20		
Part Cost: Part ID		Code ID	Code Description		Cost			
5W20	SYNTHETIC OIL	PMA			\$15.36			
100010	OIL FILTER	PMA			\$3.06			
				Total Cost:	\$18.42			
Labor Cost:								
Craft	Resource							
MECH	28	PMA			\$112.50			
				Total Cost:	\$112.50			



		Unit Wo	rk Order History			
81114	PM'S 105307 (503)	PM	Completed		6/20/2017	6/19/2017
Part Cost:						
Part ID		Code ID	Code Description		Cost	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES		\$546.80	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES		\$136.70	
				Total Cost:	\$683.50	
Labor Cost:						
Craft	Resource					
MECH	28	12	TIRES		\$37.50	
				Total Cost:	\$37.50	
81192	FLAT TIRE 503	N	Completed		6/28/2017	7/3/2017
Labor Cost:						
Craft	Resource					
MECH	28	12	TIRES		\$37.50	
				Total Cost:	\$37.50	
82299	PM'S 105307 (503)	PM	Completed	:	10/23/2017	10/23/2017
Part Cost:						
Part ID		Code ID	Code Description		Cost	
100010	OIL FILTER	PMA			\$3.05	
0W20	SYNTHETIC OIL	PMA			\$13.44	
				Total Cost:	\$16.49	
Labor Cost:						
Craft	Resource					
MECH	21	PMA			\$75.00	
				Total Cost:	\$75.00	
82299	PM'S 105307 (503)	PM	Completed	:	10/23/2017	10/23/2017
Labor Cost:						
Craft	Resource					
MECH	17	ADM	ADMINISTRATIVE TI		\$15.00	
				Total Cost:	\$15.00	



	Unit Work Order History							
83297	PM'S 105307, WIPER BLADES, REMO BUMPER	VE PUSH PM	Completed		2/21/2018	2/23/2018		
Part Cost: Part ID		Code ID	Code Description		Cost			
0W20	SYNTHETIC OIL	PMA	Code Description					
					\$11.52			
100010	OIL FILTER	PMA			\$3.05			
				Total Cost:	\$14.57			
Labor Cost:								
Craft	Resource 30	PMA			#1F0.00			
MECH	30	PMA		T-t-LCt-	\$150.00			
				Total Cost:	\$150.00			
83297	PM'S 105307, WIPER BLADES, REMO BUMPER	VE PUSH PM	Completed		2/21/2018	2/23/2018		
Labor Cost:								
Craft	Resource							
MECH	30	32	GLASS / INTERIOR	1	\$18.75			
				Total Cost:	\$18.75			
83297	PM'S 105307, WIPER BLADES, REMO BUMPER	VE PUSH PM	Completed		2/21/2018	2/23/2018		
Labor Cost:								
Craft	Resource							
MECH	12	VI	VEHICLE ENHANCEM		\$300.00			
				Total Cost:	\$300.00			
83736	VPU LOOSE IN TRUNK 105307	N	Completed		4/19/2018	4/19/2018		
Labor Cost:								
Craft	Resource							
MECH	30	AR	ARBITRATOR VIDEO SYSTEM		\$112.50			
				Total Cost:	\$112.50			



		Unit Work Order History						
84133	LEFT HEADLIGHT OUT 105307	N	Completed	6/	13/2018	6/13/2018		
Part Cost: Part ID		Code ID	Code Description		Cost			
9012LLN	BULB	06	ELECTRICAL		\$13.20			
			-	Total Cost:	\$13.20			

Labor	Cost:
Craft	

MECH

84133

Resource

12

06

ELECTRICAL

Completed

\$37.50 Total Cost: \$37.50

6/13/2018

Part Cost:

LEFT HEADLIGHT OUT 105307

Code ID Code Description

12 TIRES

Cost \$288.06

Total Cost: \$288.06

6/13/2018

Labor Cost:

Craft Resource MECH 12

12

TIRES

\$56.25 Total Cost: \$56.25

84228

PM'S 105307 (503), CHANGE #'S TO 3236, CHANGE BACKUP CAMERA

5W20 FULL SYN QT

PM

Ν

Completed

6/26/2018

6/25/2018

Part Cost: Part ID

100010 M506

21C520XB

OIL FILTER PMA
WASHER FLUID PMA

Code Description

Cost \$3.15

\$0.89 \$12.48

\$112.50

Total Cost: \$16.52

Labor Cost:

Craft Resource MECH 12

PMA

PMA

\$112.50

Total Cost:

	Unit Work Order History						
84228	PM'S 105307 (503), CHANGE #'S TO 3236, CHANGE BACKUP CAMERA	РМ	Completed		6/26/2018	6/25/2018	
Part Cost:							
Part ID		Code ID	Code Description		Cost		
BCICH41	BACKUP CAMERA INTERFACE	20	CHANGE OUTS		\$171.09		
				Total Cost:	\$171.09		
Labor Cost:							
Craft	Resource				_		
MECH	12	VI	VEHICLE ENHANCEN	MENTS	\$243.75		
				Total Cost:	\$243.75		
84228	PM'S 105307 (503), CHANGE #'S TO 3236, CHANGE BACKUP CAMERA	PM	Completed		6/26/2018	6/25/2018	
Labor Cost: Craft	Resource						
MECH	12	20	CHANGE OUTS		\$37.50		
				Total Cost:	\$37.50		
84270	IS JULY 2018	IS	Completed		7/2/2018	7/31/2018	
Misc Cost Sublet ID							
DETAIL	DETAIL	CD	SUBLET / DETAIL		\$140.00		
				Total Cost:	\$140.00		
84587	HEADLIGHT OUT, ENGINE STALLING, RIGI SIDE A/C FAN CLICKING 105307	HT N	Completed		8/8/2018	8/8/2018	
Part Cost:							
Part ID		Code ID	Code Description		Cost		
9012LLN	BULB	06	ELECTRICAL		\$13.20		
				Total Cost:	\$13.20		
Labor Cost:							
Craft	Resource				_		
MECH	12	06	ELECTRICAL		\$37.50		
				Total Cost:	\$37.50		



		Unit W	Ork Order History			
4587	HEADLIGHT OUT, ENGINE STAL SIDE A/C FAN CLICKING 105307	LING, RIGHT N	Completed		8/8/2018	8/8/201
Labor Cost:						
Craft	Resource					
MECH	12	26	ENGINE		\$18.75	
				Total Cost:	\$18.75	
4587	HEADLIGHT OUT, ENGINE STAL SIDE A/C FAN CLICKING 105307		Completed		8/8/2018	8/8/201
Labor Cost:						
Craft	Resource					
MECH	12	05	AIR CONDITIONING		\$18.75	
				Total Cost:	\$18.75	
5298	LOW TIRE 105307	R	Completed		11/2/2018	11/2/20
Labor Cost:						
Craft	Resource					
MECH	21	12	TIRES		\$77.00	
				Total Cost:	\$77.00	
35401	PM'S 105307 (503), TPMS LIGHT CAMERA UNUSABLE	ON, BACKUP PM	Completed	1	11/16/2018	11/16/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
21C520XB	5W20 FULL SYN QT	PMA			\$17.29	
100010	OIL FILTER	PMA			\$3.23	
				Total Cost:	\$20.52	
Labor Cost:						
Craft	Resource					
MECH	12	PMA			\$115.50	
				Total Cost:	\$115.50	



		Unit Wo	rk Order History		
35401	PM'S 105307 (503), TPMS LIGHT ON, CAMERA UNUSABLE	BACKUP PM	Completed	11/16/2018	11/16/201
Part Cost: Part ID		Code ID	Code Description	Cost	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES	\$144.03	
			Tot	al Cost: \$144.03	
Labor Cost: Craft	Resource				
MECH	12	12	TIRES	\$38.50	
			Total	Cost: \$38.50	
85401	PM'S 105307 (503), TPMS LIGHT ON, CAMERA UNUSABLE	BACKUP PM	Completed	11/16/2018	11/16/201
Part Cost:					
Part ID		Code ID	Code Description	Cost	
CBC	BACKUP CAMERA	VI	VEHICLE ENHANCEMENTS	\$20.46	
			Tot	al Cost: \$20.46	
Labor Cost:					
Craft	Resource				
MECH	12	VI	VEHICLE ENHANCEMENTS	\$38.50	
			Total	Cost: \$38.50	
85401	PM'S 105307 (503), TPMS LIGHT ON, CAMERA UNUSABLE	BACKUP PM	Completed	11/16/2018	11/16/201

Ν

27

 _	
 =	nt
- 1	

Completed

FUEL SYSTEM

12/11/2018

Report ID: 1111

Total Cost:

\$192.50

\$192.50

12/17/2018

85565

Labor Cost: Craft

MECH

UNIT SHUT DOWN AND WOULD NOT

RESTART 105307

Resource

28

		Unit Wo	rk Order History			
85565	UNIT SHUT DOWN AND WOULD NOT RESTART 105307	N	Completed		12/11/2018	12/17/2018
Labor Cost: Craft	Resource					
MECH	28	07	BATTERY		\$154.00	
				Total Cost:	\$154.00	
85728	TOW INVOICES DEC 2018	PM	Completed		1/7/2019	12/31/2018
Misc Cost Sublet ID						
WRECKER LT+	TOW PLUS MILEAGE LIGHT VEHICLE	сто	SUBLET / TOWING		\$62.00	
				Total Cost:	\$62.00	
85852	NEEDS NEW WIPER BLADES, BATTERY DIE AFTER 1 DAY 105307	ES N	Completed		1/23/2019	1/23/2019
Part Cost: Part ID		Code ID	Code Description		Cost	
NP21	WIPER BLADE	32	GLASS / INTERIOR		\$3.14	
NP24	WIPER BLADE	32	GLASS / INTERIOR		\$4.24	
				Total Cost:	\$7.38	
Labor Cost:						
Craft	Resource					
MECH	28	32	GLASS / INTERIOR		\$38.50	
				Total Cost:	\$38.50	
85852	NEEDS NEW WIPER BLADES, BATTERY DIE AFTER 1 DAY 105307	ES N	Completed		1/23/2019	1/23/2019
Part Cost:						
Part ID		Code ID	Code Description		Cost	
7549	BATTERY	07	BATTERY		\$95.70	
				Total Cost:	\$95.70	
Labor Cost:						
Craft	Resource					
MECH	28	07	BATTERY		\$115.50	
				Total Cost:	\$115.50	



Unit \	Work	Order	History
--------	------	-------	---------

36568	ABS ISSUES, PRINTER INOP, BRAKE NOISI 105307	E N	Completed		5/8/2019	5/10/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
FT8997	BRAKE PADS	15	BRAKES		\$48.16	
FT8998	DISC PAD	15	BRAKES		\$48.92	
68199987AD	SPEED SENSOR	15	BRAKES		\$48.10	
				Total Cost:	\$145.18	
Labor Cost:						
Craft	Resource					
MECH	12	15	BRAKES		\$77.00	
MECH	12	15	BRAKES		\$231.00	
				Total Cost:	\$308.00	
6568	ABS ISSUES, PRINTER INOP, BRAKE NOISI 105307	E N	Completed		5/8/2019	5/10/20
Part Cost:						
Part ID		Code ID	Code Description		Cost	
725255	BUTT CONNECTOR	06	ELECTRICAL		\$2.56	
725254	BUTT CONNECTOR	06	ELECTRICAL		\$5.04	
				Total Cost:	\$7.60	
Labor Cost:						
Craft	Resource					
MECH	12	06	ELECTRICAL		\$57.75	
				Total Cost:	\$57.75	
36568	ABS ISSUES, PRINTER INOP, BRAKE NOIS 105307	E N	Completed		5/8/2019	5/10/201
Labor Cost:						
Craft	Resource					
MECH	12	AR	ARBITRATOR VIDEO SYSTEM		\$77.00	
				Total Cost:	\$77.00	



		Unit Wo	ork Order History			
86568	ABS ISSUES, PRINTER INOP, BRAKE NOISI 105307	E N	Completed		5/8/2019	5/10/2019
Part Cost: Part ID		Code ID	Code Description		Cost	
1RF14DX9AB	VISOR CLIP	32	GLASS / INTERIOR		\$16.45	
				Total Cost:	\$16.45	
86568	ABS ISSUES, PRINTER INOP, BRAKE NOISI 105307	E N	Completed		5/8/2019	5/10/2019
Labor Cost:						
Craft	Resource					
MECH	12	VI	VEHICLE ENHANCEM	IENTS	\$269.50	
				Total Cost:	\$269.50	
87149	PM'S 105307 (503), A03	PM	Completed		7/26/2019	7/31/2019
Part Cost: Part ID		Code ID	Code Description		Cost	
21E520SB	5W20 FULL SYN QT	PMA			\$17.29	
100010	OIL FILTER	PMA			\$3.29	
				Total Cost:	\$20.58	
Labor Cost:						
Craft	Resource					
MECH	30	PMA			\$154.00	
				Total Cost:	\$154.00	
87149	PM'S 105307 (503), A03	PM	Completed		7/26/2019	7/31/2019
Labor Cost: Craft	Resource					
MECH	30	03	COOLING SYSTEM		\$154.00	
0			3321113313111	Total Cost:	\$154.00	
					22200	



		Unit Wo	rk Order History		
37149	PM'S 105307 (503), A03	PM	Completed	7/26/2019	7/31/2019
Part Cost: Part ID		Code ID	Code Description	Cost	
5137713AA	FAN COOLING	A03	CHARGER COOLING FAN REPLACEMENT	\$69.30	
			Total C	ost: \$69.30	
Labor Cost:	_				
Craft MECH	Resource 30	A03	CHARGER COOLING FAN	\$154.00	
MECH	30	AUS	REPLACEMENT		
			Total Co	st: \$154.00	
37149	PM'S 105307 (503), A03	PM	Completed	7/26/2019	7/31/201
Part Cost:					
Part ID		Code ID	Code Description	Cost	
003875MB	225/60WR18 FIRE MOUNTED	12	TIRES	\$288.28	
			Total C	ost: \$288.28	
37149	PM'S 105307 (503), A03	PM	Completed	7/26/2019	7/31/201
Part Cost:					
Part ID		Code ID	Code Description	Cost	
68214806AF	TPMS MODULE	06	ELECTRICAL	\$94.71	
			Total C	ost: \$94.71	
Labor Cost:					
Craft	Resource				
MECH	21	12	TIRES	\$269.50	
MECH	21	12	TIRES	\$385.00	
			Total Co.	st: \$654.50	
37189	ISSUE SLIP AUGUST 2019	IS	Completed	8/2/2019	8/31/201
Misc Cost Sublet ID					
TPMS REPAIR	TPMS REPAIR	CEL	SUBLET / ELECTRONICS	\$89.95	
			Total Co	st: \$89.95	



88223	PMA, 105307	PM	Completed		12/31/2019	12/31/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
21E520SB	5W20 FULL SYN QT	PMA			\$15.68	
100010	OIL FILTER	PMA			\$3.29	
M506	WASHER FLUID	PMA			\$1.08	
				Total Cost:	\$20.05	
Labor Cost:						
Craft	Resource					
MECH	30	PMA			\$154.00	
				Total Cost:	\$154.00	
88946	CHECK OVER REASSIGN # 4152, 105307 DETAIL	N	Completed		4/20/2020	4/22/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
329024	WHITE NUMBER KIT	20	CHANGE OUTS		\$1.62	
				Total Cost:	\$1.62	
Labor Cost:						
Craft	Resource					
MECH	12	20	CHANGE OUTS		\$77.00	
				Total Cost:	\$77.00	
88946	CHECK OVER REASSIGN # 4152, 105307 DETAIL	N	Completed		4/20/2020	4/22/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
NP21	WIPER BLADE	32	GLASS / INTERIOR		\$3.30	
NP24	WIPER BLADE	32	GLASS / INTERIOR		\$4.46	
				Total Cost:	\$7.76	



			Unit Wo	ork Order History			
88946	CHECK OVER REASSIGN # 4152, 105307 DETAIL		N	Completed		4/20/2020	4/22/2020
Labor Cost:							
Craft	Resource						
MECH	12	12		TIRES		\$77.00	
				Tota	al Cost:	\$77.00	
88946	CHECK OVER REASSIGN # 4152, 105307 DETAIL		N	Completed		4/20/2020	4/22/2020
Labor Cost:							
Craft	Resource						
MECH	12	AR		ARBITRATOR VIDEO SYSTEM		\$77.00	
					al Cost:	\$77.00	
88946	CHECK OVER REASSIGN # 4152, 105307 DETAIL		N	Completed		4/20/2020	4/22/2020
Labor Cost:							
Craft	Resource						
MECH	12	06		ELECTRICAL		\$38.50	
				Tota	al Cost:	\$38.50	
88946	CHECK OVER REASSIGN # 4152, 105307 DETAIL		N	Completed		4/20/2020	4/22/2020
Labor Cost:							
Craft	Resource						
MECH	12	L		LABOR		\$38.50	
				Tota	al Cost:	\$38.50	
89025	ISSUE SLIP MAY 2020		N	Completed		5/5/2020	5/29/2020
Misc Cost Sublet ID							
DETAIL	DETAIL					\$150.00	



		Unit Wo	rk Order History			
89587	TOW TICKETS JUNE 2020	N	Completed		7/17/2020	7/17/2020
Misc Cost _Sublet ID						
WRECKER FUEL SERVICE +	FUEL SERVICE + FUEL				\$37.50	
				Total Cost:	\$37.50	
89700	PM'S 105307 (503)	PM	Completed		7/31/2020	8/3/2020
Labor Cost:						
Craft	Resource					
MECH	30	PMA			\$115.50	
				Total Cost:	\$115.50	
90335	PM'S 105307	PM	Completed		11/2/2020	11/2/2020
Part Cost: Part ID		Code ID	Code Description		Cost	
100010	OIL FILTER	PMA			\$3.29	
M506	WASHER FLUID	PMA			\$1.66	
21E520SB	5W20 FULL SYN QT	PMA			\$13.38	
				Total Cost:	\$18.33	
Labor Cost: Craft	Resource					
MECH	21	PMA			\$115.50	
				Total Cost:	\$115.50	
90335	PM'S 105307	PM	Completed		11/2/2020	11/2/2020
Part Cost:						
Part ID		Code ID	Code Description		Cost	
6599	LOCK RING TOOL	27	FUEL SYSTEM		\$27.38	
68145815AC	FUEL PUMP	27	FUEL SYSTEM		\$264.88	
				Total Cost:	\$292.26	
Labor Cost:						
Craft	Resource					
MECH	21	27	FUEL SYSTEM		\$231.00	
				Total Cost:	\$231.00	



4/8/2025 12:18:20 PM

		Unit Wo	rk Order History			
0335	PM'S 105307	PM	Completed		11/2/2020	11/2/202
Labor Cost:						
Craft	Resource					
MECH	21	16	EMISSION SYSTEM		\$154.00	
				Total Cost:	\$154.00	
0335	PM'S 105307	PM	Completed		11/2/2020	11/2/20
Part Cost:						
Part ID		Code ID	Code Description		Cost	
120106	BOLT	29	BODY / PAINT		\$0.30	
176121	NUT	29	BODY / PAINT		\$0.04	
140106	NUT	29	BODY / PAINT		\$0.06	
				Total Cost:	\$0.40	
Labor Cost:						
	Resource					
Craft MECH	Resource 21	29	BODY / PAINT		\$38.50	
Craft		29	BODY / PAINT	Total Cost:	\$38.50 \$38.50	
Craft		29 N	BODY / PAINT Completed	Total Cost:	·	12/31/20
Craft MECH 00740 Misc Cost	21			Total Cost:	\$38.50	12/31/20
Craft MECH 00740	21			Total Cost:	\$38.50	12/31/20
Craft MECH 00740 Misc Cost Sublet ID	21 TOW TICKETS DECEMBER 2020			Total Cost:	\$38.50 1/14/2021	12/31/20
Craft MECH 00740 Misc Cost Sublet ID	21 TOW TICKETS DECEMBER 2020				\$38.50 1/14/2021 \$50.00	12/31/20
Craft MECH 00740 Misc Cost Sublet ID WRECKER LT	TOW TICKETS DECEMBER 2020 LT TOW IN CITY	N	Completed		\$38.50 1/14/2021 \$50.00 \$50.00	
Craft MECH 00740 Misc Cost Sublet ID WRECKER LT 00924 Misc Cost	TOW TICKETS DECEMBER 2020 LT TOW IN CITY	N	Completed		\$38.50 1/14/2021 \$50.00 \$50.00	



		Unit Wo	rk Order History			
90926	INSTALL DOCKSTATION C54, 105307	N	Completed		2/10/2021	2/10/202
Labor Cost:						
Craft	Resource					
MECH	30	VI	VEHICLE ENHANCE	MENTS	\$77.00	
				Total Cost:	\$77.00	
91118	TOW TICKETS FEBRUARY	N	Completed		3/11/2021	2/28/202
Misc Cost Sublet ID						
WRECKER LT	LT TOW IN CITY				\$45.00	
				Total Cost:	\$45.00	
91213	REPLACE FRONT TIRES , LF/ FRONT HEADLIGHT, 105307	N	Completed		3/25/2021	3/25/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
9012LLN	BULB	06	ELECTRICAL		\$13.20	
				Total Cost:	\$13.20	
Labor Cost:						
Craft	Resource	0.5	EL ECTRICAL		+20.50	
MECH	33	06	ELECTRICAL		\$38.50	
				Total Cost:	\$38.50	
91213	REPLACE FRONT TIRES , LF/ FRONT HEADLIGHT, 105307	N	Completed		3/25/2021	3/25/202
Labor Cost:						
Craft	Resource					
MECH	33	12	TIRES		\$77.00	
				Total Cost:	\$77.00	



Unit Work Order History 91517 PM'S 105307 (503) PM Completed 5/6/2021 5/6/2021 Part Cost: Part ID Code ID Code Description Cost 21E520SB 5W20 FULL SYN QT PMA \$23.64 NP21 WIPER BLADE 32 GLASS / INTERIOR \$3.30 NP24 32 WIPER BLADE GLASS / INTERIOR \$4.46 100010 OIL FILTER PMA \$3.29 32 M506 WASHER FLUID GLASS / INTERIOR \$1.66 Total Cost: \$36.35 **Labor Cost:** Craft Resource MECH 21 PMA \$154.00 Total Cost: \$154.00 91517 PM Completed 5/6/2021 5/6/2021 PM'S 105307 (503) 92005 FRONT END REPAIR, ENGINE TICK, TRUCK Ν Completed 7/12/2021 7/16/2021 DOESNT OPEN, 105307 Part Cost: Part ID Code ID Code Description Cost 2607225 C/A ASSY 35 **STEERING** \$75.68 2607226 C/A ASSY 35 **STEERING** \$75.68

35

_		_	
-6	4. V		
	11 7	-1	

STEERING

Labor Cost: Craft

MECH

Resource 33 \$151.36

\$154.00 \$154.00

Total Cost:

Total Cost:

Unit Work Order History	

2005	FRONT END REPAIR, ENGINE TICK DOESNT OPEN, 105307	, TRUCK N	Completed	7/12/2021	7/16/202
Part Cost: Part ID		Code ID	Code Description	Cost	
38082	IDLER PULLEY	26	ENGINE	\$25.04	
6022857	MOUNT	26	ENGINE	\$67.77	
			-	Total Cost: \$92.81	
Labor Cost:					
Craft	Resource				
MECH	33	26	ENGINE	\$192.50	
MECH	33	26	ENGINE	\$77.00	
			To	otal Cost: \$269.50	
2005	FRONT END REPAIR, ENGINE TICK DOESNT OPEN, 105307	, TRUCK N	Completed	7/12/2021	7/16/20
	DOLSINI OI LIN, 103307				
Labor Cost:	DOLSNY OF EN, 103307				
Craft	Resource				
		06	ELECTRICAL	\$77.00	
Craft	Resource	06		\$77.00 otal Cost: \$77.00	
Craft	Resource				
Craft MECH	Resource 33		To	otal Cost: \$77.00	
Craft MECH 2548	Resource 33		To	otal Cost: \$77.00	
Craft MECH 2548 Part Cost:	Resource 33	TIRES PM	Closed	otal Cost: \$77.00 9/28/2021	
Craft MECH 2548 Part Cost: Part ID	Resource 33 PM'S 105307 (503), ENGINE TICK ,	. TIRES PM Code ID	Closed	9/28/2021 Cost	
Craft MECH 2548 Part Cost: Part ID 21E520SB	Resource 33 PM'S 105307 (503), ENGINE TICK , 5W20 FULL SYN QT	TIRES PM Code ID PMA	Closed Code Description	9/28/2021 Cost \$23.64	
Craft MECH 2548 Part Cost: Part ID 21E520SB	Resource 33 PM'S 105307 (503), ENGINE TICK , 5W20 FULL SYN QT	TIRES PM Code ID PMA	Closed Code Description	9/28/2021 Cost \$23.64 \$3.49	
Craft MECH 2548 Part Cost: Part ID 21E520SB 100010	Resource 33 PM'S 105307 (503), ENGINE TICK , 5W20 FULL SYN QT OIL FILTER Resource	TIRES PM Code ID PMA	Closed Code Description	9/28/2021 Cost \$23.64 \$3.49	
Craft MECH 2548 Part Cost: Part ID 21E520SB 100010 Labor Cost:	Resource 33 PM'S 105307 (503), ENGINE TICK , 5W20 FULL SYN QT OIL FILTER	TIRES PM Code ID PMA	Closed Code Description	9/28/2021 Cost \$23.64 \$3.49	



2548	PM'S 105307 (503), ENGINE TICK , TIRES	PM	Closed	9	/28/2021	
Part Cost:						
Part ID		Code ID	Code Description		Cost	
29642	PCV VALVE	26	ENGINE		\$32.82	
				Total Cost:	\$32.82	
Labor Cost:						
Craft	Resource					
MECH	37	26	ENGINE		\$0.00	
				Total Cost:	\$0.00	
2548	PM'S 105307 (503), ENGINE TICK , TIRES	PM	Closed	9	/28/2021	
Part Cost:						
Part ID		Code ID	Code Description		Cost	
011690MB	22560VR18 FIRESTONE FIREHAWK	12	TIRES		\$640.88	
				Total Cost:	\$640.88	
Labor Cost:						
Craft	Resource					
MECH	37	12	TIRES		\$0.00	
				Total Cost:	\$0.00	
2548	PM'S 105307 (503), ENGINE TICK , TIRES	PM	Closed	9	/28/2021	
Part Cost:						
Part ID		Code ID	Code Description		Cost	
2608146	LOWER CONTROL ARM	44	SUSPENSION		\$148.72	
				Total Cost:	\$148.72	
Labor Cost:						
Craft	Resource					
MECH	37	44	SUSPENSION		\$0.00	
				Total Cost:	\$0.00	



92548	PM'S 105307 (503), ENGINE TICK , TIRES	PM	Closed		9/28/2021	
Part Cost:						
Part ID		Code ID	Code Description		Cost	
NP21	WIPER BLADE	32	GLASS / INTERIOR		\$3.30	
NP24	WIPER BLADE	32	GLASS / INTERIOR		\$4.46	
M506	WASHER FLUID	32	GLASS / INTERIOR		\$1.85	
				Total Cost:	\$9.61	
92537	IS	PM	Completed		9/27/2021	9/30/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
7041929	OIL DRAIN PLUG	26	ENGINE		\$3.41	
				Total Cost:	\$3.41	
92731	A/C INOP, R/F HEADLIGHT OUT,105307	N	Completed		10/21/2021	10/21/202
Part Cost: Part ID		Code ID	Code Description		Cost	
68160395AF	COMPRESSOR	05	AIR CONDITIONING		\$743.92	
00100393AF	COMPRESSOR	03	AIR CONDITIONING	Total Cost:	\$743.92 \$743.92	
				Total Cost.	ఫ7 +3.32	
Labor Cost:						
Craft	Resource				<u> </u>	
MECH	33	05	AIR CONDITIONING		\$192.50	
				Total Cost:	\$192.50	
92731	A/C INOP, R/F HEADLIGHT OUT,105307	N	Completed		10/21/2021	10/21/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
9012LLN	BULB	06	ELECTRICAL		\$13.20	
				Total Cost:	\$13.20	
Labor Cost:						
Craft	Resource					
MECH	33	06	ELECTRICAL		\$38.50	
				Total Cost:	\$38.50	



		Unit Wo	rk Order History			
93022	PM'S 105307 (503), CHECKOVER FOR REASSIGNMENT, SEE WRITE UP	РМ	Completed		12/6/2021	12/7/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
21E520SB	5W20 FULL SYN QT	PMA			\$23.64	
29746	AIR FILTER	PMA			\$11.12	
100010	OIL FILTER	PMA		Total Cost:	\$3.49 \$38.25	
Labor Cost:				rotal cost.	\$30.23	
Craft	Resource					
MECH	37	PMA			\$0.00	
				Total Cost:	\$0.00	
93022	PM'S 105307 (503), CHECKOVER FOR REASSIGNMENT, SEE WRITE UP	РМ	Completed		12/6/2021	12/7/202
Labor Cost:						
Craft	Resource					
MECH	37	20	CHANGE OUTS		\$0.00	
				Total Cost:	\$0.00	
93022	PM'S 105307 (503), CHECKOVER FOR REASSIGNMENT, SEE WRITE UP	РМ	Completed		12/6/2021	12/7/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
NP24	WIPER BLADE	32	GLASS / INTERIOR		\$4.46	
NP21	WIPER BLADE	32	GLASS / INTERIOR		\$3.30	
M506	WASHER FLUID	32	GLASS / INTERIOR		\$1.85	
				Total Cost:	\$9.61	
93022	PM'S 105307 (503), CHECKOVER FOR REASSIGNMENT, SEE WRITE UP	PM	Completed		12/6/2021	12/7/202
Part Cost:					_	
Part ID		Code ID	Code Description		Cost	
4048	CABIN AIR FILTER DODGE				\$7.32	
				Total Cost:	\$7.32	



		Unit Wo	rk Order History			
93061	PRINTER INOP , 105307	N	Completed		12/13/2021	12/13/202
Labor Cost:						
Craft	Resource					
MECH	33	06	ELECTRICAL		\$38.50	
				Total Cost:	\$38.50	
92993	DEC 2021 SERVICE TICKET	N	Completed		12/1/2021	12/31/202
Misc Cost _Sublet ID						
DETAIL	DETAIL				\$150.00	
				Total Cost:	\$150.00	
93306	ENGINE TICKING, 105307	N	Completed		1/24/2022	1/25/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
29642	PCV VALVE	26	ENGINE		\$35.23	
VS50805R	VALVE COVER GASKET	26	ENGINE		\$64.48	
9407	SPARK PLUG	26	ENGINE		\$36.00	
4800BC	BRAKE CLEANER	26	ENGINE		\$4.82	
				Total Cost:	\$140.53	
Labor Cost:						
Craft	Resource					
MECH	33	26	ENGINE		\$154.00	
MECH	33	26	ENGINE		\$231.00	
				Total Cost:	\$385.00	
93372	JANUARY 2022 TOW TICKETS	N	Completed		2/2/2022	1/31/202
Misc Cost _Sublet ID						
TOWING	TOWING				\$45.00	
				Total Cost:	\$45.00	



		Unit Wo	rk Order History			
3478	BAD BATTERY 105307	R	Completed		2/17/2022	2/21/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
7549	BATTERY	07	BATTERY		\$107.16	
				Total Cost:	\$107.16	
Labor Cost:						
Craft	Resource					
MECH	30	07	BATTERY		\$77.00	
				Total Cost:	\$77.00	
3493	IS	PM	Completed		2/21/2022	2/25/202
Misc Cost Sublet ID						
TOW	TOW				\$45.00	
TOW	TOW				\$45.00	
TOW	TOW				\$45.00	
				Total Cost:	\$135.00	
3703	PMS' 105307, LOCKS INTERMITT THEMSELVES	ENTLY LOCK PM	Completed		3/21/2022	3/21/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
21E520SB	5W20 FULL SYN QT	PMA			\$23.64	
100010	OIL FILTER	PMA			\$3.73	
				Total Cost:	\$27.37	
Labor Cost:						
Craft	Resource					
MECH	37	PMA			\$0.00	
				Total Cost:	\$0.00	



		Unit Wo	rk Order History		
93703	PMS' 105307, LOCKS INTERMITTENTL THEMSELVES	Y LOCK PM	Completed	3/21/2022	3/21/2022
Part Cost: Part ID		Code ID	Code Description	Cost	
NP24	WIPER BLADE	32	GLASS / INTERIOR	\$4.46	
M506	WASHER FLUID	32	GLASS / INTERIOR	\$2.40	
NP21	WIPER BLADE	32	GLASS / INTERIOR	\$3.30	
			T	otal Cost: \$10.16	
93703	PMS' 105307, LOCKS INTERMITTENTL THEMSELVES	Y LOCK PM	Completed	3/21/2022	3/21/2022
Part Cost:					
Part ID		Code ID	Code Description	Cost	
PA4766	SWITCH	06	ELECTRICAL	\$131.32	
			T	otal Cost: \$131.32	
Labor Cost:					
Craft MECH	Resource 37	06	ELECTRICAL	φ0.00	
МЕСП	3/	06		\$0.00 tal Cost: \$0.00	
93848	DRIVERS SIDE DOOR HANDLE INOP,	105307 N	Completed	4/11/2022	4/12/2022
Labor Cost:					
Craft	Resource				
MECH	37	29	BODY / PAINT	\$0.00	
			To	tal Cost: \$0.00	



		Unit Wo	ork Order History			
4292	PM'S, ENGINE TICK, DRIVERS SIDE MIRR HELD ON BY TAPE, PRINTER KEEPS TURI OFF, 503		Completed	ϵ	5/14/2022	6/17/2022
Part Cost:						
Part ID		Code ID	Code Description		Cost	
21E520SB	5W20 FULL SYN QT	PMA			\$23.64	
100010	OIL FILTER	PMA			\$3.95	
				Total Cost:	\$27.59	
Labor Cost:						
Craft	Resource					
MECH	37	37	DIAGNOSTIC		\$0.00	
				Total Cost:	\$0.00	
4292	PM'S, ENGINE TICK, DRIVERS SIDE MIRR HELD ON BY TAPE, PRINTER KEEPS TURI OFF, 503	OR PM NING	Completed	É	5/14/2022	6/17/2022
Part Cost:						
Part ID		Code ID	Code Description		Cost	
VS50805R	VALVE COVER GASKET	26	ENGINE		\$64.48	
5184296AH	ROCKER ARM	26	ENGINE		\$9.75	
				Total Cost:	\$74.23	
Labor Cost:						
Craft	Resource					
MECH	37	26	ENGINE		\$0.00	
				Total Cost:	\$0.00	
4292	PM'S, ENGINE TICK, DRIVERS SIDE MIRR HELD ON BY TAPE, PRINTER KEEPS TURI OFF, 503	OR PM NING	Completed	6	5/14/2022	6/17/202
Labor Cost:						
Craft	Resource					
MECH	37	29	BODY / PAINT		\$0.00	
				Total Cost:	\$0.00	



		Unit Wo	ork Order History		
4292	PM'S, ENGINE TICK, DRIVERS SIDE MIRROF HELD ON BY TAPE, PRINTER KEEPS TURNIN OFF, 503		Completed	6/14/2022	6/17/2022
Part Cost: Part ID		Code ID	Code Description	Cost	
M506	WASHER FLUID	32	GLASS / INTERIOR	\$2.40	
NP21	WIPER BLADE	32	GLASS / INTERIOR	\$3.30	
NP24	WIPER BLADE	32	GLASS / INTERIOR	\$4.46	
			-	Total Cost: \$10.16	
4292	PM'S, ENGINE TICK, DRIVERS SIDE MIRROF HELD ON BY TAPE, PRINTER KEEPS TURNIN OFF, 503	R PM IG	Completed	6/14/2022	6/17/2022
Part Cost:					
Part ID		Code ID	Code Description	Cost	
011688MB	225/60WR18 FIRESTONE MOUNTED	12	TIRES	\$604.88	
			_	Total Cost: \$604.88	
4292	PM'S, ENGINE TICK, DRIVERS SIDE MIRROF HELD ON BY TAPE, PRINTER KEEPS TURNIN OFF, 503	R PM IG	Completed	6/14/2022	6/17/2022
Labor Cost: Craft	Resource				
MECH	37	06	ELECTRICAL	\$0.00	
			7	Fotal Cost: \$0.00	
4670	COOLANT LEAK , OVERHEATING, 105307	N	Completed	8/4/2022	8/11/202
Part Cost:					
Part ID		Code ID	Code Description	Cost	
AFC10100	50/50 ANTIFREEZE	03	COOLING SYSTEM	\$7.56	
NR13157A	RADIATOR	03	COOLING SYSTEM	\$180.96	
				Total Cost: \$188.52	
Labor Cost:					
Craft	Resource				
MECH	21 ()3	COOLING SYSTEM	\$269.50	
				Fotal Cost: \$269.50	



94670	COOLANT LEAK , OVERHEATING, 105307	N	Completed		8/4/2022	8/11/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
99655771	DUAL HD FAN ASSEMBLY	A03	CHARGER COOLING REPLACEMENT	FAN	\$388.08	
				Total Cost:	\$388.08	
Labor Cost:	_					
Craft	Resource					
MECH	21	A03	CHARGER COOLING REPLACEMENT	FAN	\$115.50	
			NET DIGETIENT	Total Cost:	\$115.50	
94670	COOLANT LEAK , OVERHEATING, 105307	N	Completed		8/4/2022	8/11/202
Labor Cost:						
Craft	Resource					
MECH	21	16	EMISSION SYSTEM		\$231.00	
				Total Cost:	\$231.00	
94670	COOLANT LEAK , OVERHEATING, 105307	N	Completed		8/4/2022	8/11/202
Labor Cost:						
Craft	Resource					
MECH	21	06	ELECTRICAL		\$115.50	
				Total Cost:	\$115.50	
95045	PM'S 105307	PM	Completed		9/27/2022	9/27/20
Part Cost:						
Part ID		Code ID	Code Description		Cost	
21E520SB	5W20 FULL SYN QT	PMA			\$23.64	
100010	OIL FILTER	PMA			\$4.19	
				Total Cost:	\$27.83	
Labor Cost:						
Craft	Resource					
MECH	21	PMA			\$115.50	
				Total Cost:	\$115.50	



		Unit Wo	rk Order History		
5045	PM'S 105307	PM	Completed	9/27/2022	9/27/2022
Labor Cost:					
Craft	Resource				
MECH	21	VI	VEHICLE ENHANCEMEN	TS \$77.00	
			To	otal Cost: \$77.00	
5045	PM'S 105307	PM	Completed	9/27/2022	9/27/202
Part Cost:					
Part ID		Code ID	Code Description	Cost	
M506	WASHER FLUID	32	GLASS / INTERIOR	\$2.40	
NP24	WIPER BLADE	32	GLASS / INTERIOR	\$4.76	
NP21	WIPER BLADE	32	GLASS / INTERIOR	\$3.30	
			-	Fotal Cost: \$10.46	
5143	ENGINE TICK , PRINTER INOP , TINT R WINDOW , 105307	EAR N	Completed	10/10/2022	10/17/202
Part Cost:					
Part ID		Code ID	Code Description	Cost	
25060658	SERP BELT	26	ENGINE	\$21.41	
65635	ZEP SPLIT EQUIP CLEANER	26	ENGINE	\$168.94	
6022955	MOUNT	26	ENGINE	\$186.82	
38082	IDLER PULLEY	26	ENGINE	\$26.91	
M10176	SAFE CRACKER	26	ENGINE	\$20.99	
			-	Total Cost: \$425.07	
Labor Cost: Craft	Resource				
MECH	30	26	ENGINE	\$616.00	
MECH	30	26	ENGINE	\$308.00	
MECH	30	26	ENGINE	\$346.50	
			_	otal Cost: \$1.270.50	



		Unit W	ork Order History		
95143	ENGINE TICK , PRINTER INOP , TINT REAR WINDOW , 105307	N	Completed	10/10/2022	10/17/2022
Labor Cost:					
Craft	Resource				_
MECH	30 06		ELECTRICAL	\$577.50)
			Tota	l Cost: \$577.50)
95143	ENGINE TICK , PRINTER INOP , TINT REAR WINDOW , 105307	N	Completed	10/10/2022	10/17/2022
Misc Cost Sublet ID					_
TINT GLASS	TINT GLASS			\$170.00)
			Tota	al Cost: \$170.00	-
95511	ENGINE TICKING , WASHER LEAK, COMPUTER STAND NOT CHARGING, SMELLS LIKE GAS , 105307	N	Completed	12/5/2022	12/12/2022
Labor Cost:					
Craft	Resource				_
MECH	33 26		ENGINE	\$192.50)
			Tota	l Cost: \$192.50)



95511	ENGINE TICKING , WASHER LE COMPUTER STAND NOT CHAR LIKE GAS , 105307		Completed	12/5/2022	12/12/2022
Part Cost: Part ID		Code ID	Code Description	Cost	
FREIGHT	FREIGHT			\$13.00	
55366298AA	ORING	27	FUEL SYSTEM	\$37.06	
68159764AC	MODULE	27	FUEL SYSTEM	\$294.94	
68258723AD	FUEL TANK	27	FUEL SYSTEM	\$1,168.75	
				Total Cost: \$1,513.75	
Labor Cost:					
Craft	Resource				
MECH	33	27	FUEL SYSTEM	\$154.00	
MECH	33	27	FUEL SYSTEM	\$385.00	
MECH	33	27	FUEL SYSTEM	\$327.25	
				Total Cost: \$866.25	

5511	ENGINE TICKING , WASHER LEAK, COMPUTER STAND NOT CHARGING, SMEL LIKE GAS , 105307	N LS	Completed	12/5/2022	12/12/2022
Part Cost: Part ID		Code ID	Code Description	Cost	
68057740AD	HOSE	32	GLASS / INTERIOR	\$5.67	
68125524AA	WASHER RESERVOIR	32	GLASS / INTERIOR	\$107.80	
68239789AC	NOZZLE	32	GLASS / INTERIOR	\$89.70	
68239794AE	HOSE	32	GLASS / INTERIOR	\$60.89	
6655121	PUSH PIN	32	GLASS / INTERIOR	\$4.86	
68231862AA	FRONT SHIELD	32	GLASS / INTERIOR	\$226.05	
9903	CONNECTOR	32	GLASS / INTERIOR	\$2.50	
				Total Cost: \$497.47	
Labor Cost: Craft MECH	Resource 33	32	GLASS / INTERIOR	\$77.00	
MECH	33	32	GLASS / INTERIOR	\$77.00	
MECH	33	32	GLASS / INTERIOR	\$38.50	
112011	55	5 2		Total Cost: \$192.50	
511	ENGINE TICKING , WASHER LEAK, COMPUTER STAND NOT CHARGING, SMEL LIKE GAS , 105307	N LS	Completed	12/5/2022	12/12/202
Labor Cost:					
Craft	Resource				
MECH	33	32	GLASS / INTERIOR	\$77.00	
MECH	33	06	ELECTRICAL	\$57.75	
				Total Cost: \$134.75	



		Unit Wo	rk Order History		
511	ENGINE TICKING , WASHER LEAK, COMPUTER STAND NOT CHARGING, SME LIKE GAS , 105307	N LLS	Completed	12/5/2022	12/12/2022
Part Cost: Part ID		Code ID	Code Description	Cost	
2605521	CONTROL ARM	44	SUSPENSION	\$112.74	
2605522	CONTROL ARM	44	SUSPENSION	\$112.74	
k80996	BALL JOINT	44	SUSPENSION	\$105.36	
2607225	C/A ASSY	44	SUSPENSION	\$84.62	
2607226	C/A ASSY	44	SUSPENSION	\$84.62	
			-	Total Cost: \$500.08	
Labor Cost:					
Craft	Resource				
MECH	33	44	SUSPENSION	\$192.50	
MECH	33	44	SUSPENSION	\$192.50	
			٦	Fotal Cost: \$385.00	
511	ENGINE TICKING , WASHER LEAK, COMPUTER STAND NOT CHARGING, SME LIKE GAS , 105307	N LLS	Completed	12/5/2022	12/12/202
Part Cost:					
Part ID		Code ID	Code Description	Cost	
RA881774	PERFORMANCE ROTOR	15	BRAKES	\$158.48	
FT8998	DISC PAD	15	BRAKES	\$58.06	
			-	Total Cost: \$216.54	
Labor Cost:	_				
Craft MECH	Resource 33	15	BRAKES	\$77.00	
PILOTI	33	15	_	Fotal Cost: \$77.00	
691	CHANGE ID#S TO S 3 , DEAD BATTERY, 105307	N	Completed	1/5/2023	1/6/202
Labor Cost:					
Craft	Resource				
MECH	37	20	CHANGE OUTS	\$0.00	



		Unit Wo	ork Order History			
5691	CHANGE ID#S TO S 3 , DEAD BATTERY, 105307	N	Completed		1/5/2023	1/6/2023
Part Cost:		6 1 75	C D ' ''		6.1	
Part ID		Code ID	Code Description		Cost	
7549	BATTERY	07	BATTERY		\$109.76	
				Total Cost:	\$109.76	
Labor Cost:						
Craft	Resource					
MECH	37	07	BATTERY		\$0.00	
				Total Cost:	\$0.00	
5691	CHANGE ID#S TO S 3 , DEAD BATTERY, 105307	N	Completed		1/5/2023	1/6/2023
Part Cost: Part ID		Code ID	Code Description		Cost	
55113665AI	HINGE	29	BODY / PAINT		\$76.00	
				Total Cost:	\$76.00	
5959	R/F HEADLIGHT OUT , 105307	N	Completed		2/14/2023	2/14/2023
Part Cost: Part ID		Code ID	Code Description		Cost	
9012LLN	BULB	06	 ELECTRICAL		\$13.86	
				Total Cost:	\$13.86	
Labor Cost:						
Craft	Resource					
MECH	12	06	ELECTRICAL		\$19.25	
				Total Cost:	\$19.25	



Unit '	Work	Order	History
--------	------	-------	---------

6552	PM'S 105307 (503), RUNNING ROUGH	PM	Completed	5/18/2023	5/22/202
Part Cost:					
Part ID		Code ID	Code Description	Cost	
100010	OIL FILTER	PMA		\$4.19	
75749	5W20 SYN OIL	PMA		\$21.42	
			Total	Cost: \$25.61	
Labor Cost:					
Craft	Resource				
MECH	37	PMA		\$0.00	
			Total (Cost: \$0.00	
6552	PM'S 105307 (503), RUNNING ROUGH	PM	Completed	5/18/2023	5/22/202
Part Cost:					
Part ID		Code ID	Code Description	Cost	
99655771	DUAL HD FAN ASSEMBLY	A03	CHARGER COOLING FAN REPLACEMENT	\$401.52	
			INEL ENGLITERY		
				Cost: \$401.52	
				Cost: \$401.52	
Labor Cost:				Cost: \$401.52	
Craft	Resource	402	Total		
	Resource 37	A03		\$0.00	
Craft		A03	Total CHARGER COOLING FAN	\$0.00	
Craft	37		Total CHARGER COOLING FAN REPLACEMENT	\$0.00	5/22/202
Craft MECH 6552		A03	CHARGER COOLING FAN REPLACEMENT Total (\$0.00 Cost: \$0.00	5/22/202
<u>Craft</u> MECH	37		CHARGER COOLING FAN REPLACEMENT Total (\$0.00 Cost: \$0.00	5/22/202
Craft MECH 96552 Part Cost:	37	РМ	CHARGER COOLING FAN REPLACEMENT Total C	\$0.00 Cost: \$0.00 5/18/2023	5/22/202
Craft MECH 6552 Part Cost: Part ID	37 PM'S 105307 (503), RUNNING ROUGH	PM Code ID	CHARGER COOLING FAN REPLACEMENT Total C Completed Code Description ENGINE	\$0.00 Cost: \$0.00 5/18/2023	5/22/202
Craft MECH 6552 Part Cost: Part ID	37 PM'S 105307 (503), RUNNING ROUGH	PM Code ID	CHARGER COOLING FAN REPLACEMENT Total C Completed Code Description ENGINE	\$0.00 Cost: \$0.00 5/18/2023 Cost \$64.86	5/22/202
Craft MECH 96552 Part Cost: Part ID 9407	37 PM'S 105307 (503), RUNNING ROUGH	PM Code ID	CHARGER COOLING FAN REPLACEMENT Total C Completed Code Description ENGINE	\$0.00 Cost: \$0.00 5/18/2023 Cost \$64.86	5/22/202
Craft MECH 6552 Part Cost: Part ID 9407 Labor Cost:	37 PM'S 105307 (503), RUNNING ROUGH SPARK PLUG	PM Code ID	CHARGER COOLING FAN REPLACEMENT Total C Completed Code Description ENGINE	\$0.00 Cost: \$0.00 5/18/2023 Cost \$64.86	5/22/202
Craft MECH 6552 Part Cost: Part ID 9407 Labor Cost: Craft	37 PM'S 105307 (503), RUNNING ROUGH SPARK PLUG Resource	PM Code ID 26	CHARGER COOLING FAN REPLACEMENT Total C Completed Code Description ENGINE Total	\$0.00 Cost: \$0.00 5/18/2023 Cost \$64.86 Cost: \$64.86	5/22/202
Craft MECH MECH Part Cost: Part ID 9407 Labor Cost: Craft MECH	37 PM'S 105307 (503), RUNNING ROUGH SPARK PLUG Resource 37	PM Code ID 26	CHARGER COOLING FAN REPLACEMENT Total C Completed Code Description ENGINE Total	\$0.00 Cost: \$0.00 5/18/2023 Cost \$64.86 Cost: \$64.86	5/22/202

iMaint

		Unit Wo	rk Order History			
552 Part Cost:	PM'S 105307 (503), RUNNING ROUGH	РМ	Completed		5/18/2023	5/22/2023
Part ID		Code ID	Code Description		Cost	
FT880395	ROTOR	15	BRAKES		\$128.84	
FT8997	BRAKE PADS	15	BRAKES		\$57.15	
				Total Cost:	\$185.99	
Labor Cost: Craft	Resource					
MECH	37	15	BRAKES		\$0.00	
				Total Cost:	\$0.00	
552	PM'S 105307 (503), RUNNING ROUGH	PM	Completed		5/18/2023	5/22/2023
Part Cost: Part ID		Code ID	Code Description		Cost	
NP21	WIPER BLADE	32	GLASS / INTERIOR		\$3.75	
NP24	WIPER BLADE	32	GLASS / INTERIOR		\$5.06	
				Total Cost:	\$8.81	
552	PM'S 105307 (503), RUNNING ROUGH	PM	Completed		5/18/2023	5/22/2023
Part Cost: Part ID		Code ID	Code Description		Cost	
2283707	PURGE VALVE				\$24.50	
RTU1EXT	COOLANT	03	COOLING SYSTEM		\$16.70	
5184977AH	THERMOSTAT	03	COOLING SYSTEM		\$43.90	
				Total Cost:	\$85.10	
Labor Cost:	Deserves					
Craft MECH	Resource 37	03	COOLING SYSTEM		\$0.00	
PILCH	J/	03	COOLING 3131EM		φυ.υυ	



		Unit Wo	rk Order History			
96552	PM'S 105307 (503), RUNNING ROUGH	PM	Completed		5/18/2023	5/22/202
Part Cost: Part ID		Code ID	Code Description		Cost	
4593937AC	CANISTER	16	EMISSION SYSTEM		\$134.20	
				Total Cost:	\$134.20	
96845	DEAD BATTERY, S2	N	Completed		7/7/2023	7/7/202
Labor Cost:						
Craft	Resource					
MECH	33	07	BATTERY		\$38.50	
				Total Cost:	\$38.50	
96845	DEAD BATTERY, S2	N	Completed		7/7/2023	7/7/202
Labor Cost:						
Craft	Resource					
MECH	33	AR	ARBITRATOR VIDEO SYSTEM		\$77.00	
				Total Cost:	\$77.00	
97763	LAPTOP CHARGER INOP, 105307	N	Completed		11/21/2023	11/21/202
Labor Cost:						
Craft	Resource					
MECH	12	06	ELECTRICAL		\$20.75	
				Total Cost:	\$20.75	
97763	LAPTOP CHARGER INOP, 105307	N	Completed		11/21/2023	11/21/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
011688MB	225/60WR18 FIRESTONE MOUNTED	12	TIRES		\$604.88	
				Total Cost:	\$604.88	
Labor Cost:						
Craft	Resource					
MECH	12	12	TIRES		\$124.50	
				Total Cost:	\$124.50	



	•						
			Unit W	ork Order History			
97958	105307 ENGINE LIGHT ON .MDT STAND DOES NOT WORK		N	Completed		12/27/2023	12/27/2023
Labor Cost:							
Craft	Resource						
MECH	33	26		ENGINE		\$124.50	
					Total Cost:	\$124.50	
97958	105307 ENGINE LIGHT ON .MDT STAND DOES NOT WORK		N	Completed		12/27/2023	12/27/2023
Labor Cost:							
Craft	Resource						
MECH	33	30		ELECTRONICS		\$83.00	
					Total Cost:	\$83.00	
97958	105307 ENGINE LIGHT ON .MDT STAND DOES NOT WORK		N	Completed		12/27/2023	12/27/2023
Labor Cost:							
Craft	Resource						
MECH	33	05		AIR CONDITIONING		\$41.50	
					Total Cost:	\$41.50	
97999	105307 MDT WONT CHARGE		N	Completed		1/4/2024	1/5/2024
Labor Cost:							
Craft	Resource						
				EL ECTRICAL		+02.00	
MECH	12	06		ELECTRICAL		\$83.00	

		Unit Wo	rk Order History			
97999	105307 MDT WONT CHARGE	N	Completed		1/4/2024	1/5/2024
Part Cost: Part ID		Code ID	Code Description		Cost	
100010	OIL FILTER	26	ENGINE		\$4.11	
75749	5W20 SYN OIL	26	ENGINE		\$19.80	
			-	Total Cost:	\$23.91	
Labor Cost:						
Craft	Resource					
MECH	12	PMA	_		\$124.50	
			•	Total Cost:	\$124.50	
97999	105307 MDT WONT CHARGE	N	Completed		1/4/2024	1/5/2024
Part Cost: Part ID		Code ID	Code Description		Cost	
M506	WASHER FLUID	32	GLASS / INTERIOR		\$2.55	
			•	Total Cost:	\$2.55	
98491	ABS LIGHT ON , 105307	N	Completed		3/18/2024	3/21/2024
Part Cost: Part ID		Code ID	Code Description		Cost	
4779646AF	SPEED SENSOR	15	BRAKES		\$29.80	
			-	Total Cost:	\$29.80	
Labor Cost:						
Craft	Resource					
MECH	33	15	BRAKES		\$41.50	
MECH	33	15	BRAKES		\$83.00	



\$124.50

Total Cost:

11:4	Wast.	Oud ou	History
Unit	WOLK	Uraer	History

98491	ABS LIGHT ON , 105307	N	Completed		3/18/2024	3/21/2024
Part Cost:						
Part ID		Code ID	Code Description		Cost	
011688MB	225/60WR18 FIRESTONE MOUNTE	D 12	TIRES		\$162.22	
				Total Cost:	\$162.22	
Labor Cost:						
Craft	Resource					
MECH	33	12	TIRES		\$41.50	
				Total Cost:	\$41.50	
98491	ABS LIGHT ON , 105307	N	Completed		3/18/2024	3/21/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
VS50567	GASKET SET	26	ENGINE		\$52.98	
29642	PCV VALVE	26	ENGINE		\$39.93	
68277082AA	ENGINE MOUNT	26	ENGINE		\$241.36	
4800BC	BRAKE CLEANER	26	ENGINE		\$7.94	
				Total Cost:	\$342.21	
Labor Cost:						
Craft	Resource					
MECH	33	26	ENGINE		\$124.50	
MECH	33	26	ENGINE		\$124.50	
MECH	33	26	ENGINE		\$124.50	
				Total Cost:	\$373.50	
98981	A/C INOP, 105307	N	Completed		6/6/2024	6/6/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
68160395AG	COMPRESSOR				\$1,127.50	
				Total Cost:	\$1,127.50	
Labor Cost:						
Craft	Resource					
MECH	33	05	AIR CONDITIONING		\$290.50	
				Total Cost:	\$290.50	



4/8/2025 12:18:21 PM

OIIIL	i otais.	

 Total Number of Work Orders:
 160

 Total Labor Costs:
 \$13,957.75

 Total Part Costs:
 \$12,829.55

 Total Sublet
 \$2,958.10

 Total Costs:
 \$29,745.40

Site Totals:

Unit Totals

 Total Number of Work Orders:
 160

 Total Labor Costs:
 \$13,957.75

 Total Part Costs:
 \$12,829.55

 Total Sublet
 \$2,958.10

 Total Costs:
 \$29,745.40

Report Totals:

 Total Number of Work Orders:
 160

 Total Labor Costs:
 \$13,957.75

 Total Part Costs:
 \$12,829.55

 Total Sublet
 \$2,958.10

 Total Costs:
 \$29,745.40

Filter:

Unit id begins with '105307'

