# **Unit Work Order History**

ID	105440		Description: VAI	N, CARGO/TRANSIT RV	VD		
wo	ID	WO Description	WO Type ID	WO Status ID	Sched	uled Date	<b>Completed Dat</b>
78003	3	SET UP 105440 (2350)	S	Completed		7/13/2016	7/19/201
ı	Labor Cost:						
(	Craft	Resource					
N	MECH	12	40	NEW VEHICLE / SET U	P	\$225.00	
				7	Total Cost:	\$225.00	•
78003	3	SET UP 105440 (2350)	S	Completed		7/13/2016	7/19/201
	Part Cost:						
F	Part ID		Code ID	Code Description		Cost	
7	7707018	FIRE EXTINGUISHER	40W	BLUE BOATS, FIRE EXT BLUETOOTH	ΓAND	\$18.35	•
				-	Total Cost:	\$18.35	-
78582	2	TOW TICKETS FOR AUGUST 2016	IS	Completed		9/6/2016	9/8/201
r	Misc Cost						
_9	Sublet ID						
	WRECKER WINCH	WINCH OUT	1	TOWING		\$45.00	
					Total Cost:	\$45.00	
7920	1	PM'S 2350, THROTTLE BODY REPLACED UNDER WARRANTY	PM	Completed		11/8/2016	11/8/201
	Part Cost:						
	Part ID		Code ID	Code Description		Cost	
5	5W20	SYNTHETIC OIL	PMA			\$11.52	•
1	1348	OIL FILTER	PMA			\$2.84	
				-	Total Cost:	\$14.36	-
ı	Labor Cost:						
<u>(</u>	Craft	Resource					_
N	MECH	21	PMA			\$112.50	
				7	Total Cost:	\$112.50	•



		Unit Wo	rk Order History			
79201	PM'S 2350, THROTTLE BODY REPLACED UNDER WARRANTY	PM	Completed		11/8/2016	11/8/201
Misc Cost Sublet ID						
FUEL SYS REPAIRS	FUEL SYSTEM REPAIRS	CW	SUBLET / WARRANTY		\$0.00	
				Total Cost:	\$0.00	
9742	INSTALL ADDITIONAL LIGHTING 2350	S	Completed		1/12/2017	1/18/201
<b>Labor Cost:</b> Craft	Resource					
MECH	28	VI	VEHICLE ENHANCEME	NTS	\$112.50	
MECH	30	VI	VEHICLE ENHANCEME	NTS	\$562.50	
			-	Total Cost:	\$675.00	
31423	FLAT TIRE 105440	N	Completed		7/25/2017	7/24/201
Labor Cost:						
Craft	Resource					
MECH	15	12	TIRES -		\$37.50	
				Total Cost:	\$37.50	
31540	PM'S 2350, TPMS LIGHT ON	PM	Completed		8/4/2017	8/4/201
Part Cost: Part ID		Code ID	Code Description		Cost	
M506	WASHER FLUID	PMC	"C" LEVEL PM		\$1.15	
4800BC	BRAKE CLEANER	PMC	"C" LEVEL PM		\$2.28	
1348	OIL FILTER	PMC	"C" LEVEL PM		\$2.87	
0W20	SYNTHETIC OIL	PMC	"C" LEVEL PM		\$11.52	
			-	Total Cost:	\$17.82	
Labor Cost:	_					
Craft	Resource	DMC	IICII I EVEL DM		#1F0 00	
MECH	28	PMC	"C" LEVEL PM		\$150.00	
				Total Cost:	\$150.00	



			Unit Wo	rk Order History			
31540	PM'S 2350, TPMS LIGHT ON		PM	Completed		8/4/2017	8/4/201
Labor Cost:							
Craft	Resource						
MECH	28	12		TIRES		\$75.00	
					Total Cost:	\$75.00	
31540	PM'S 2350, TPMS LIGHT ON		PM	Completed		8/4/2017	8/4/201
Labor Cost:							
Craft	Resource						
MECH	17	ADM		ADMINISTRATIVE TIN		\$18.75	
					Total Cost:	\$18.75	
32056	FRONT DRIVER TIRE FLAT 105440 (2350)	)	N	Completed		9/29/2017	9/29/20
Labor Cost:							
Craft	Resource						
MECH	21	12		TIRES		\$75.00	
					Total Cost:	\$75.00	
32056	FRONT DRIVER TIRE FLAT 105440 (2350)	)	N	Completed		9/29/2017	9/29/20
Labor Cost:							
Craft	Resource						
MECH	17	ADM		ADMINISTRATIVE TIN	<b>Ч</b> Е	\$15.00	
					Total Cost:	\$15.00	
33813	IS MAY 2018		IS	Completed		5/1/2018	5/31/20
<b>Misc Cost</b> Sublet ID							
Misc Cost Sublet ID WARRANTY	WARRANTY	CV	v	SUBLET / WARRANTY	,	\$0.00	



		Unit Wo	rk Order History			
84084	PM'S 2350	PM	Completed		6/7/2018	6/11/2018
Part Cost:						
Part ID		Code ID	Code Description		Cost	
PROH592	NO SMOKING SIGN	PMC	"C" LEVEL PM		\$3.07	
21C520XB	5W20 FULL SYN QT	PMC	"C" LEVEL PM		\$10.40	
1348	OIL FILTER	PMC	"C" LEVEL PM		\$2.90	
			T	otal Cost:	\$16.37	
Labor Cost:						
Craft	Resource					
MECH	19	PMC	"C" LEVEL PM		\$150.00	
			То	otal Cost:	\$150.00	
84052	IS JUNE 2018	IS	Completed		6/4/2018	6/29/2018
Misc Cost						
Sublet ID		040	CURLET / ALTONIATRIT		+40.05	
ALIGNMENT	ALIGNMENT	CAB	SUBLET / ALIGNMENT- BALANCING		\$49.95	
			To	otal Cost:	\$49.95	
84116	IS	IS	Completed	6	5/11/2018	6/15/2018
Part Cost:						
Part ID		Code ID	Code Description		Cost	
119001307	215/55/R16 CONTI PURE	12	TIRES		\$812.08	
			T	otal Cost:	\$812.08	
84503	BAD BATTERY 105440 (2350)	R	Completed		7/31/2018	7/31/2018
Part Cost:						
Part ID		Code ID	Code Description		Cost	
8496R	BATTERY	07	BATTERY		\$80.07	
			T	otal Cost:	\$80.07	
Labor Cost:						
Craft	Resource					
MECH	12	07	BATTERY		\$75.00	
			To	tal Cost:	\$75.00	



Unit	Work	Order	History
------	------	-------	---------

36015	PM'S 2350	PM	Completed		2/14/2019	2/14/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
21E520SB	5W20 FULL SYN QT	PMC	"C" LEVEL PM		\$14.82	
1348	OIL FILTER	PMC	"C" LEVEL PM		\$2.96	
M506	WASHER FLUID	PMC	"C" LEVEL PM		\$0.89	
				Total Cost:	\$18.67	
Labor Cost:						
Craft	Resource					
MECH	12	PMC	"C" LEVEL PM		\$192.50	
				Total Cost:	\$192.50	
36376	FLAT TIRE BY WATER DIST OFFIC (2350)	CES 105440 R	Completed		4/8/2019	4/8/20:
<b>Labor Cost:</b> Craft	Resource					
MECH	31	12	TIRES		\$77.00	
				Total Cost:	\$77.00	
37336	PM'S 2350	PM	Completed		8/20/2019	8/21/20
Part Cost:						
Part ID		Code ID	Code Description		Cost	
1348	OIL FILTER	PMC	"C" LEVEL PM		\$3.12	
21E520SB	5W20 FULL SYN QT	PMC	"C" LEVEL PM		\$11.10	
6029PP	WIPER BLADE	PMC	"C" LEVEL PM		\$26.16	
60141	WIPER BLADE	PMC	"C" LEVEL PM		\$10.64	
				Total Cost:	\$51.02	
Labor Cost:						
Craft	Resource					
MECH	21	PMC	"C" LEVEL PM		\$154.00	



	•					
		Unit Wo	rk Order History			
87949	R/F HEADLIGHT OUT, PASSEN MIRROR DAMAGE, 2350	GER SIDE VIEW N	Completed	11/	13/2019	11/15/2019
Labor Cost:						
Craft	Resource					
MECH	12	29	BODY / PAINT		\$38.50	
				Total Cost:	\$38.50	
87949	R/F HEADLIGHT OUT, PASSEN MIRROR DAMAGE, 2350	GER SIDE VIEW N	Completed	11/	13/2019	11/15/2019
Part Cost:						
Part ID		Code ID	Code Description		Cost	
1255H11	BULB	06	ELECTRICAL		\$6.19	
				Total Cost:	\$6.19	
Labor Cost:						
Craft	Resource					
MECH	12	06	ELECTRICAL		\$19.25	
				Total Cost:	\$19.25	
87949	R/F HEADLIGHT OUT, PASSEN MIRROR DAMAGE, 2350	GER SIDE VIEW N	Completed	11/	13/2019	11/15/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
				·	·	
DT1Z17K707E	MIRROR GLASS	32	GLASS / INTERIOR		\$97.21	



88811	PM'S 2350	PM	Completed	3/25/2020	3/26/202
Part Cost:					
Part ID		Code ID	Code Description	Cost	
6029PP	WIPER BLADE	PMC	"C" LEVEL PM	\$26.16	
21E520SB	5W20 FULL SYN QT	PMC	"C" LEVEL PM	\$11.15	
1348	OIL FILTER	PMC	"C" LEVEL PM	\$3.12	
M506	WASHER FLUID	PMC	"C" LEVEL PM	\$1.08	
				Total Cost: \$41.51	
Labor Cost:					
Craft	Resource				
MECH	21	PMC	"C" LEVEL PM	\$154.00	
				Total Cost: \$154.00	
88811	PM'S 2350	PM	Completed	3/25/2020	3/26/202
Part Cost: Part ID		Code ID	Code Description	Cost	
RS2021	UNIVERSAL SWITCH	06	ELECTRICAL	\$7.26	
NOCOCI	OHITERO, LE OWITCH			Total Cost: \$7.26	
Labor Cost:					
Craft	Resource				
MECH	21	06	ELECTRICAL	\$154.00	
				Total Cost: \$154.00	
88811	PM'S 2350	PM	Completed	3/25/2020	3/26/202
Labor Cost:					
Craft	Resource				
MECH	21	12	TIRES	\$38.50	
				Total Cost: \$38.50	
88831	IS	IS	Completed	3/30/2020	4/3/202
Part Cost:					
Part ID		Code ID	Code Description	Cost	
1549332	215/55R16 CONT PRO CONTACT	12	TIRES	\$684.16	
				Total Cost: \$684.16	



		Unit Wo	rk Order History			
8932	HEADLIGHT, 105440	R	Completed		4/17/2020	4/17/2020
Part Cost:						
Part ID		Code ID	Code Description		Cost	
1255H11	BULB	06	ELECTRICAL		\$6.19	
				Total Cost:	\$6.19	
Labor Cost:						
Craft	Resource					
MECH	21	06	ELECTRICAL		\$38.50	
				Total Cost:	\$38.50	
9398	IS	IS	Completed		6/22/2020	6/26/2020
Part Cost:						
Part ID		Code ID	Code Description		Cost	
1550477	215/55R16XL MB	12	TIRES		\$161.47	
				Total Cost:	\$161.47	
9532	LEFT FRONT LOW BEAM OUT 2350	R	Completed		7/9/2020	8/11/2020
Part Cost:						
Part ID		Code ID	Code Description		Cost	
1255H11	BULB	06	ELECTRICAL		\$6.19	
				Total Cost:	\$6.19	
Labor Cost:						
Craft	Resource					
MECH	30	06	ELECTRICAL		\$77.00	
				Total Cost:	\$77.00	



<b>Unit Work</b>	Order	History
------------------	-------	---------

90218	PM'S 2350	PM	Completed		10/16/2020	10/16/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
1348	OIL FILTER	PMC	"C" LEVEL PM		\$3.12	
21E520SB	5W20 FULL SYN QT	PMC	"C" LEVEL PM		\$13.38	
6029PP	WIPER BLADE	PMC	"C" LEVEL PM		\$26.16	
				Total Cost:	\$42.66	
Labor Cost:						
Craft	Resource					
MECH	15	PMC	"C" LEVEL PM		\$154.00	
				Total Cost:	\$154.00	
90432	IS	IS	Completed		11/16/2020	11/20/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
7822184	ATC FUSE	06	ELECTRICAL		\$0.48	
				Total Cost:	\$0.48	
90496	STROBES LIGHTS OUT, L/F HEDI 2350	LIGHT OUT, N	Completed		11/30/2020	12/1/202
Labor Cost:						
Craft	Resource					
MECH	21				\$192.50	
MECH	21				\$38.50	
				Total Cost:	\$231.00	
90861	FEBRUARY 2021 SER	N	Completed		2/1/2021	2/28/202
Misc Cost Sublet ID						
CARWASH	CARWASH				\$7.99	
				Total Cost:	\$7.99	



Unit \	Work	Order	History
--------	------	-------	---------

92191	PM'S 2350, AC INOP, REAR PARKING LIGHT OUT	- PM	Completed		8/6/2021	8/11/202
Part Cost: Part ID		Code ID	Code Description		Cost	
21E520SB	5W20 FULL SYN QT	PMC	"C" LEVEL PM		\$19.70	
200095	AIR FILTER	PMC	"C" LEVEL PM		\$6.75	
1348	OIL FILTER	PMC	"C" LEVEL PM		\$3.37	
			-	Total Cost:	\$29.82	
Labor Cost:	_					
Craft	Resource	DMC	IICII I EVEL DM		4115 50	
MECH	33	PMC	"C" LEVEL PM		\$115.50	
				Total Cost:	\$115.50	
92191	PM'S 2350, AC INOP, REAR PARKING LIGHT OUT	- PM	Completed		8/6/2021	8/11/20
Part Cost: Part ID		Code ID	Code Description		Cost	
R134	FREON	05	AIR CONDITIONING		\$2.98	
724305	TERMINAL	05	AIR CONDITIONING		\$2.70	
MM1162	BLOWER MOTOR	05	AIR CONDITIONING		\$73.41	
RU827	RESISTOR	05	AIR CONDITIONING		\$33.70	
YJ686	CONDENSER	05	AIR CONDITIONING		\$132.92	
			-	Total Cost:	\$245.71	
Labor Cost:						
Craft	Resource					
MECH		05	AIR CONDITIONING		\$77.00	
MECH		05	AIR CONDITIONING		\$192.50	
MECH	33	05	AIR CONDITIONING		\$385.00	
			=	Total Cost:	\$654.50	



		Unit Wo	rk Order History			
2191	PM'S 2350, AC INOP, REAR PARKING LIGHT OUT	PM	Completed		8/6/2021	8/11/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
194N	BULB	06	ELECTRICAL		\$0.40	
723304	TERMINALS	06	ELECTRICAL		\$0.76	
				Total Cost:	\$1.16	
Labor Cost:						
Craft	Resource					
MECH	33 0	06	ELECTRICAL		\$38.50	
				Total Cost:	\$38.50	
2191	PM'S 2350, AC INOP, REAR PARKING LIGHT OUT	PM	Completed		8/6/2021	8/11/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
M506	WASHER FLUID	32	GLASS / INTERIOR		\$1.85	
				Total Cost:	\$1.85	
2191	PM'S 2350, AC INOP, REAR PARKING LIGHT OUT	РМ	Completed		8/6/2021	8/11/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
EUR1095	BRAKE PADS	15	BRAKES		\$63.45	
FT8873	BRAKE PADS	15	BRAKES		\$43.07	
				Total Cost:	\$106.52	
Labor Cost:						
Craft	Resource					
MECH	33	.5	BRAKES		\$77.00	
MECH	33	.5	BRAKES		\$77.00	
				Total Cost:	\$154.00	
2191	PM'S 2350, AC INOP, REAR PARKING LIGHT OUT	PM	Completed		8/6/2021	8/11/202



		Unit Wo	rk Order History			
191	PM'S 2350, AC INOP, REAR PARKING LIGHT OUT	- PM	Completed	8/6/20	21	8/11/2
Part Cost: Part ID		Code ID	Code Description		Cost	
08813	FUEL TREATMENT	27	FUEL SYSTEM		\$7.82	
00013	TOLL TREATMENT	21	TOLL STSTEM	Total Cost:	\$7.82	
529	PM'S 2350, OVERHEATING	PM	Completed	2/25/20	22	3/4/2
Part Cost:						
Part ID		Code ID	Code Description		Cost	
1348	OIL FILTER	PMC	"C" LEVEL PM		\$3.73	
21E520SB	5W20 FULL SYN QT	PMC	"C" LEVEL PM		\$19.70	
				Total Cost:	\$23.43	
<b>Labor Cost:</b> Craft	Resource					
MECH		PMC	"C" LEVEL PM		\$115.50	
				Total Cost:	\$115.50	
529	PM'S 2350, OVERHEATING	PM	Completed	2/25/20	22	3/4/2
Part Cost: Part ID		Code ID	Code Description		Cost	
AFC10100	50/50 ANTIFREEZE	03	COOLING SYSTEM		\$7.16	
902231	OUTLET	03	COOLING SYSTEM		\$23.05	
7057	CAP	03	COOLING SYSTEM		\$15.77	
DV6Z18472B	HEATER HOSE	03	COOLING SYSTEM		\$27.54	
DV6Z18472C	HEATER HOSE	03	COOLING SYSTEM		\$36.30	
				Total Cost:	\$109.82	
<b>Labor Cost:</b> Craft	Resource					
MECH	33	03	COOLING SYSTEM		\$192.50	
MECH	33	03	COOLING SYSTEM		\$38.50	
MECH	33	03	COOLING SYSTEM		\$77.00	
MECH	33	03	COOLING SYSTEM		\$38.50	
				Total Cost:	\$346.50	



		Unit Wo	rk Order History			
			in order motor,			
3529	PM'S 2350, OVERHEATING	PM	Completed		2/25/2022	3/4/20
Labor Cost:						
Craft	Resource					
MECH	33	15	BRAKES		\$77.00	
				Total Cost:	\$77.00	
3529	PM'S 2350, OVERHEATING	PM	Completed		2/25/2022	3/4/20
Part Cost:						
Part ID		Code ID	Code Description		Cost	
DT1Z13A613A	LAMP	06	ELECTRICAL		\$84.34	
				Total Cost:	\$84.34	
Labor Cost:						
Craft	Resource					
MECH	33	06	ELECTRICAL		\$38.50	
				Total Cost:	\$38.50	
3529	PM'S 2350, OVERHEATING	PM	Completed		2/25/2022	3/4/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
60141	WIPER BLADE	32	GLASS / INTERIOR		\$11.02	
				Total Cost:	\$11.02	
3686	105440 HEADLIGHT OUT	N	Completed		3/18/2022	3/18/20
Part Cost:						
Part ID		Code ID	Code Description		Cost	
1255H11	BULB	06	ELECTRICAL		\$6.96	
				Total Cost:	\$6.96	
Labor Cost:						
Craft	Resource					
MECH	30	06	ELECTRICAL		\$77.00	
				Total Cost:	\$77.00	



		Unit Wo	rk Order History			
3644	IS	PM	Completed		3/14/2022	3/18/202
<b>Part Cost:</b> Part ID		Code ID	Code Description		Cost	
DT1Z1130B	HUB CAB	12	TIRES		\$72.50	
				Total Cost:	\$72.50	
14133	LOW ON RADIATOR, 105440	N	Completed		5/23/2022	5/23/202
Labor Cost:						
Craft	Resource					
MECH	37	03	COOLING SYSTEM		\$0.00	
				Total Cost:	\$0.00	
4860	SERVICE TICKET SEPTEMBER 2022	N	Completed		9/1/2022	9/30/202
Misc Cost Sublet ID						
ALIGNMENT	ALIGNMENT				\$49.95	
				Total Cost:	\$49.95	
14983	PM'S 2350, R/F TIRE FLAT	PM	Completed		9/19/2022	9/19/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
1348	OIL FILTER	PMC	"C" LEVEL PM		\$4.19	
21E520SB	5W20 FULL SYN QT	PMC	"C" LEVEL PM		\$23.64	
				Total Cost:	\$27.83	
Labor Cost:						
Craft	Resource					
MECH	12	PMC	"C" LEVEL PM		\$115.50	
				Total Cost:	\$115.50	



		Unit Wo	rk Order History			
94983	PM'S 2350, R/F TIRE FLAT	PM	Completed		9/19/2022	9/19/2022
Part Cost: Part ID		Code ID	Code Description		Cost	
1550477	215/55R16XL MB	12	TIRES		\$476.66	
				Total Cost:	\$476.66	
Labor Cost:						
Craft	Resource					
MECH	12	12	TIRES		\$77.00	
				Total Cost:	\$77.00	
94983	PM'S 2350, R/F TIRE FLAT	PM	Completed		9/19/2022	9/19/2022
Part Cost: Part ID		Code ID	Code Description		Cost	
M506	Washer Fluid	32	GLASS / INTERIOR		\$2.40	
				Total Cost:	\$2.40	
95169	BRAKE LIGHT OUT, 105440	N	Completed		10/12/2022	10/14/2022
Part Cost:						
Part ID		Code ID	Code Description		Cost	
7443N	BULB	06	ELECTRICAL		\$1.25	
DT1Z13404F	TAIL LAMP	06	ELECTRICAL		\$265.78	
DT1Z13405F	TAIL LAMP	06	ELECTRICAL		\$265.78	
				Total Cost:	\$532.81	
Labor Cost:						
Craft	Resource					
MECH	30	06	ELECTRICAL		\$231.00	
				Total Cost:	\$231.00	



		Unit Wo	rk Order History			
96123	HEADLIGHT OUT 105440	R	Completed		3/13/2023	3/13/2023
Part Cost:						
Part ID		Code ID	Code Description		Cost	
1255H11	BULB	06	ELECTRICAL		\$7.43	
				Total Cost:	\$7.43	
Labor Cost:						
<u>Craft</u> MECH	Resource 33	06	ELECTRICAL		\$38.50	
MECH	33	00	LLLCTRICAL	Total Cost:	\$38.50	
05005	DMG 405 440			Total Cost.		4/40/2025
96285	PM'S 105440	PM	Completed		4/6/2023	4/10/2023
Part Cost: Part ID		Code ID	Code Description		Cost	
1348	OIL FILTER	PMC	"C" LEVEL PM		\$4.19	
200095	AIR FILTER	THE	CLEVELIN		\$8.40	
75749	5W20 SYN OIL	PMC	"C" LEVEL PM		\$21.42	
737 13	31120 3111 312	1110	CLEVEETTI	Total Cost:	\$34.01	
Labor Cost:						
Craft	Resource					
MECH	37	PMC	"C" LEVEL PM		\$0.00	
				Total Cost:	\$0.00	
96285	PM'S 105440	PM	Completed		4/6/2023	4/10/2023
Part Cost:						
Part ID		Code ID	Code Description		Cost	
6029PP	WIPER BLADE	32	GLASS / INTERIOR		\$28.34	
M506	WASHER FLUID	32	GLASS / INTERIOR		\$2.55	
				Total Cost:	\$30.89	
96467	WRECKER CAR WASHES	N	Completed		5/8/2023	6/9/2023
Misc Cost Sublet ID						
CARWASH	CARWASH				\$7.99	
				Total Cost:	\$7.99	



	Unit Work Order History						
96645	SHIFTER BROKE, BLOWER ONLY WORKS ON 4, REPLACE INVERTOR , 105440	N	Completed	6/6/2023	6/21/2023		
Part Cost:							

Part ID		Code ID	Code Description	Cost
EC851	CONNECTOR	05	AIR CONDITIONING	\$29.50
BR727	RESISTOR	05	AIR CONDITIONING	\$31.53
			Total Cost	t· \$61.03

#### Labor Cost:

Craft	Resource			
MECH	12	05	AIR CONDITIONING	\$38.50
			Total Cost:	\$38.50

96645	SHIFTER BROKE, BLOWER ONLY WORKS ON	N	Completed	6/6/2023	6/21/2023
	4, REPLACE INVERTOR, 105440				

## Labor Costs

Labor Cost:						
Craft	Resource					
MECH	12	06	ELECTRICAL		\$154.00	
				Total Cost:	\$154.00	
96645	SHIFTER BROKE, BLOWER 4, REPLACE INVERTOR , 1		Completed		6/6/2023	6/21/2023

### **Labor Cost:**

Craft	Resource			
MECH	12	22	TRANSMISSION / CLUTCH	\$154.00
			Total Cost:	\$154.00



		Unit Wo	rk Order History			
96844	A/C ONLY BLOWING ON 4 , 105440	N	Completed		7/6/2023	7/7/2023
Part Cost:						
Part ID		Code ID	Code Description		Cost	
RU827	RESISTOR	05	AIR CONDITIONING		\$40.71	
MM1162	BLOWER MOTOR	05	AIR CONDITIONING		\$106.68	
			•	Total Cost:	\$147.39	
Labor Cost:						
<u>Craft</u>	Resource					
MECH	12	05	AIR CONDITIONING		\$462.00	
			•	Total Cost:	\$462.00	
96829	JUNE WRECKER AND VEHICLE REGISTRATION	N	Completed		7/11/2023	7/11/2023
Misc Cost Sublet ID						
WRECKER	WRECKER				\$103.00	
				Total Cost:	\$103.00	
96838	JULY 2023 , ISSUE SLIP	N	Completed		7/6/2023	7/31/2023
Misc Cost Sublet ID						
WARRANTY	WARRANTY				\$0.00	
				Total Cost:	\$0.00	
97058	DEAD BATTERY, 105440	N	Completed		8/8/2023	8/11/2023
Part Cost:						
Part ID		Code ID	Code Description		Cost	
40RPRM	BATTERY	07	BATTERY		\$129.00	
			•	Total Cost:	\$129.00	
Labor Cost:						
Craft	Resource					
MECH	30	07	BATTERY		\$77.00	



\$77.00

Total Cost:

		Unit Wo	ork Order History			
97257	PM'S 105440 , BLOWER ONLY WORKS ON HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT	PM	Completed		9/8/2023	9/11/2023
<b>Part Cost:</b> Part ID		Code ID	Code Description		Cost	
75749	5W20 SYN OIL	PMC	"C" LEVEL PM		\$19.80	
PH2835	OIL FILTER	PMC	"C" LEVEL PM		\$2.74	
				Total Cost:	\$22.54	
Labor Cost:	_					
<u>Craft</u> MECH	Resource 12	PMC	"C" LEVEL PM		¢115 50	
МЕСП	12	PIVIC	C LEVEL PIM	Total Cost:	\$115.50 \$115.50	
97257	PM'S 105440 , BLOWER ONLY WORKS ON HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT	PM	Completed		9/8/2023	9/11/2023
Part Cost:						
Part ID		Code ID	Code Description		Cost	
AV1Z18591	RESISTOR	05	AIR CONDITIONING		\$52.79	
				Total Cost:	\$52.79	
Labor Cost:						
Craft	Resource					
MECH	12	05	AIR CONDITIONING		\$154.00	
				Total Cost:	\$154.00	

		Unit Wo	rk Order History		
97257	PM'S 105440 , BLOWER ONLY WORKS ON HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT	PM	Completed	9/8/2023	9/11/2023
Part Cost:					
Part ID		Code ID	Code Description	Cos	<u>st</u>
WG337	Washer Pump	32	GLASS / INTERIOR	\$42.5	3
M506	WASHER FLUID	32	GLASS / INTERIOR	\$2.5	5
				Total Cost: \$45.0	8
Labor Cost:					
Craft	Resource				_
MECH	12	32	GLASS / INTERIOR	\$96.2	<u> 25</u>
				Total Cost: \$96.2	25
97257	PM'S $105440$ , BLOWER ONLY WORKS ON HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT	РМ	Completed	9/8/2023	9/11/2023
Labor Cost:	HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT		Completed	9/8/2023	9/11/2023
Labor Cost: Craft	HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT Resource				9/11/2023
Labor Cost:	HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT Resource		Completed	9/8/2023 \$77.0 Total Cost: \$77.0	00
Labor Cost: Craft	HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT Resource	12 PM		\$77.0	00
<b>Labor Cost:</b> Craft MECH	HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT  Resource  12  PM'S 105440 , BLOWER ONLY WORKS ON HIGH, WASHER INOP, , CHECK R/R TIRE ,	12 PM	TIRES	\$77.0 Total Cost: \$77.0	00 00
Labor Cost: Craft MECH 97257	HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT  Resource  12  PM'S 105440 , BLOWER ONLY WORKS ON HIGH, WASHER INOP, , CHECK R/R TIRE ,	12 PM	TIRES	\$77.0 Total Cost: \$77.0	9/11/2023
Labor Cost: Craft MECH 97257 Part Cost:	HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT  Resource  12  PM'S 105440 , BLOWER ONLY WORKS ON HIGH, WASHER INOP, , CHECK R/R TIRE ,	12 PM	TIRES Completed	\$77.0 Total Cost: \$77.0 9/8/2023	9/11/202:
Labor Cost: Craft MECH  97257  Part Cost: Part ID	HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT  Resource  12  PM'S 105440 , BLOWER ONLY WORKS ON HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT	12 PM Code ID	TIRES  Completed  Code Description	\$77.0 Total Cost: \$77.0 9/8/2023	9/11/2023 st
Labor Cost: Craft MECH  97257  Part Cost: Part ID	HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT  Resource  12  PM'S 105440 , BLOWER ONLY WORKS ON HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT	12 PM Code ID	TIRES  Completed  Code Description	\$77.0 Total Cost: \$77.0 9/8/2023	9/11/2023 st
Part Cost: Part ID  1255H11	HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT  Resource  12  PM'S 105440 , BLOWER ONLY WORKS ON HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT  BULB  Resource	PM Code ID 06	TIRES  Completed  Code Description	\$77.0 Total Cost: \$77.0 9/8/2023	9/11/2023 st
Part Cost: Part ID 1255H11  Labor Cost:	HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT  Resource  12  PM'S 105440 , BLOWER ONLY WORKS ON HIGH, WASHER INOP, , CHECK R/R TIRE , L/F HEADLIGHT  BULB  Resource	12 PM Code ID	TIRES  Completed  Code Description	\$77.0 Total Cost: \$77.0 9/8/2023	9/11/2023 st 13



Unit '	Work	Order	History
--------	------	-------	---------

97494	R/F HEADLIGHT OUT, 105440	N	Completed	10	)/11/2023	10/11/2023
Part Cost:						
Part ID		Code ID	Code Description		Cost	
1255H11	BULB	06	ELECTRICAL		\$7.43	
				Total Cost:	\$7.43	
Labor Cost:						
Craft	Resource					
MECH	30	06	ELECTRICAL		\$192.50	
				Total Cost:	\$192.50	
97807	DRIVER SLIDING DOOR STCKING, REREAR LIGHTS, 105440	EPLACE N	Completed	11	/29/2023	11/29/2023
Labor Cost:						
Craft	Resource					
MECH	33	29	BODY / PAINT		\$83.00	
				Total Cost:	\$83.00	
97807	DRIVER SLIDING DOOR STCKING, REREAR LIGHTS, 105440	EPLACE N	Completed	11	/29/2023	11/29/2023
Labor Cost:						
Craft	Resource					
MECH	33	06	ELECTRICAL		\$373.50	
				Total Cost:	\$373.50	
97828	IS	PM	Completed	1	.2/4/2023	12/8/2023
Part Cost:						
Part ID		Code ID	Code Description		Cost	
725101	CONNECTOR	32	GLASS / INTERIOR		\$0.60	
725103	BUTT CONNECTOR	32	GLASS / INTERIOR		\$0.90	
AM5Z586174AB	COVER	32	GLASS / INTERIOR		\$70.33	
				Total Cost:	\$71.83	



		Unit Wo	rk Order History			
98152	PM'S 105440, WINDSHEILD WASHER INOP, LOW TIRE PRESSURE , DRIVER SEAT TRIM INVERTOR	PM ,	Completed		1/24/2024	1/29/2024
Part Cost: Part ID		Code ID	Code Description		Cost	
PH2835	OIL FILTER	26	ENGINE		\$2.74	
75749	5W20 SYN OIL	26	ENGINE		\$19.80	
				Total Cost:	\$22.54	
Labor Cost:						
Craft	Resource					
MECH	12 F	MC	"C" LEVEL PM		\$124.50	
				Total Cost:	\$124.50	
98152	PM'S 105440, WINDSHEILD WASHER INOP, LOW TIRE PRESSURE , DRIVER SEAT TRIM INVERTOR	PM ,	Completed		1/24/2024	1/29/2024
Labor Cost: Craft	Resource					
MECH	12	2	TIRES		\$41.50	
MECH	12	2	TIRES		\$41.50	
				Total Cost:	\$83.00	
98152	PM'S 105440, WINDSHEILD WASHER INOP, LOW TIRE PRESSURE , DRIVER SEAT TRIM INVERTOR	PM ,	Completed		1/24/2024	1/29/2024
Part Cost:						
Part ID		Code ID	Code Description		Cost	
M506	WASHER FLUID	32	GLASS / INTERIOR		\$2.55	
				Total Cost:	\$2.55	
98152	PM'S 105440, WINDSHEILD WASHER INOP, LOW TIRE PRESSURE , DRIVER SEAT TRIM INVERTOR	PM ,	Completed		1/24/2024	1/29/2024
Labor Cost:						
Craft	Resource					
MECH	12	6	ELECTRICAL		\$83.00	
				Total Cost:	\$83.00	



Report ID: 1111

		Unit Wo	rk Order History			
98170 <b>Part Cost:</b>	IS	PM	Completed		1/29/2024	2/2/2024
Part ID		Code ID	Code Description		Cost	
67420	INVERTER	06	ELECTRICAL		\$141.90	
				Total Cost:	\$141.90	
98170	IS	PM	Completed		1/29/2024	2/2/202
Part Cost:		0 1 75				
Part ID		Code ID	Code Description		Cost	
1550477	215/55R16XL MB	12	TIRES		\$485.88	
				Total Cost:	\$485.88	
98853	PM'S 105440 , WIPER SPRAYER, MOVE IN REVERSE	WOULD NOT PM	Completed		5/20/2024	5/20/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
200095	AIR FILTER	26	ENGINE		\$8.23	
1348	OIL FILTER	26	ENGINE		\$4.11	
75749	5W20 SYN OIL	26	ENGINE		\$13.70	
				Total Cost:	\$26.04	
Labor Cost:						
Craft	Resource					
MECH	33	PMC	"C" LEVEL PM		\$124.50	
				Total Cost:	\$124.50	
98853	PM'S 105440 , WIPER SPRAYER, MOVE IN REVERSE	WOULD NOT PM	Completed		5/20/2024	5/20/202
Labor Cost:						
Craft	Resource					
MECH	33	22	TRANSMISSION / C	LUTCH	\$41.50	
				Total Cost:	\$41.50	



Unit Work O	rder History
-------------	--------------

98853	PM'S 105440 , WIPER SPRAYER MOVE IN REVERSE	, WOULD NOT PM	Completed	5/	/20/2024	5/20/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
171645	PADS	15	BRAKES		\$33.61	
EBR897SCR	ROTOR	15	BRAKES		\$120.38	
			•	Total Cost:	\$153.99	
Labor Cost:						
Craft	Resource					
MECH	33	15	BRAKES		\$124.50	
				Total Cost:	\$124.50	
98853	PM'S 105440 , WIPER SPRAYER MOVE IN REVERSE	, WOULD NOT PM	Completed	5/	/20/2024	5/20/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
CAF6174	CABIN FILTER	A15	CABIN AIR FILTER		\$13.19	
				Total Cost:	\$13.19	
Labor Cost:						
Craft	Resource					
MECH	33	A15	CABIN AIR FILTER		\$41.50	
				Total Cost:	\$41.50	
98853	DIVIS 405 440 NUTDED CDD AVED			5/	/20/2024	5/20/20
70033	PM'S 105440 , WIPER SPRAYER MOVE IN REVERSE	, WOULD NOT PM	Completed	5,	20,2021	
Part Cost:		, WOULD NOT PM	Completed	5,	20,2021	
		, WOULD NOT PM  Code ID	Code Description	3,	Cost	
Part Cost:				<i>J.</i>		
Part Cost: Part ID	MOVE IN REVERSE	Code ID	Code Description		Cost	
Part Cost: Part ID  14	MOVE IN REVERSE  WIPER BLADE	Code ID 32	Code Description GLASS / INTERIOR	<i>.</i>	Cost \$6.59	
Part Cost: Part ID  14  M506	MOVE IN REVERSE  WIPER BLADE  WASHER FLUID	Code ID 32 32	Code Description  GLASS / INTERIOR  GLASS / INTERIOR	Total Cost:	\$6.59 \$2.55	
Part Cost: Part ID  14  M506 60141  Labor Cost:	MOVE IN REVERSE  WIPER BLADE  WASHER FLUID	Code ID 32 32	Code Description  GLASS / INTERIOR  GLASS / INTERIOR		Cost \$6.59 \$2.55 \$6.62	
Part Cost: Part ID  14  M506 60141  Labor Cost: Craft	MOVE IN REVERSE  WIPER BLADE  WASHER FLUID  WIPER BLADE  Resource	Code ID  32  32  32  32	Code Description  GLASS / INTERIOR  GLASS / INTERIOR  GLASS / INTERIOR		\$6.59 \$2.55 \$6.62 \$15.76	
Part Cost: Part ID  14  M506 60141  Labor Cost:	MOVE IN REVERSE  WIPER BLADE  WASHER FLUID  WIPER BLADE	Code ID 32 32	Code Description  GLASS / INTERIOR  GLASS / INTERIOR		Cost \$6.59 \$2.55 \$6.62	

*iMaint* 

Unit	Work	Order	History
------	------	-------	---------

8853	PM'S 105440 , WIPER SPRAYER, WOULD MOVE IN REVERSE	NOT PM	Completed		5/20/2024	5/20/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
9T1Z13K376A	LAMP	06	ELECTRICAL		\$20.48	
				Total Cost:	\$20.48	
Labor Cost:						
Craft	Resource					
MECH	33	06	ELECTRICAL		\$20.75	
				Total Cost:	\$20.75	
8898	BRAKES LOCKING UP AFTER DRIVING, 105440	N	Completed		5/24/2024	6/17/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
14161147	CALIPER	15	BRAKES		\$77.46	
14161148	CALIPER	15	BRAKES		\$88.46	
2206134	BRAKE HOSE	15	BRAKES		\$42.98	
KV6Z2140C	MASTER CYLINDER	15	BRAKES		\$179.20	
9V4Z2K478B	RESERVOIR	15	BRAKES		\$72.45	
EV3Z2K478A	RESERVOIR	15	BRAKES		\$38.43	
GV6Z2C405F	CONTROL UNIT	15	BRAKES		\$802.27	
35032	BRAKE FLUID	15	BRAKES		\$6.06	
35032	BRAKE FLUID	15	BRAKES		\$6.06	
				Total Cost:	\$1,313.37	
Labor Cost:						
Craft	Resource					
MECH	33	15	BRAKES		\$41.50	
MECH	33	15	BRAKES		\$145.25	
MECH	33	15	BRAKES		\$249.00	
MECH	33	15	BRAKES		\$332.00	
MECH	33	15	BRAKES		\$207.50	
MECH	33	15	BRAKES		\$332.00	
				Total Cost:	\$1 <i>.</i> 307.25	



Report ID: 1111

		Unit Wo	rk Order History			
98898	BRAKES LOCKING UP AFTER DRIVING, 105440	N	Completed		5/24/2024	6/17/2024
Part Cost:						
Part ID		Code ID	Code Description		Cost	
RK622907	CONTROL ARM	44	SUSPENSION		\$179.81	
RK622906	CONTROL ARM	44	SUSPENSION		\$179.81	
				Total Cost:	\$359.62	
Labor Cost:						
Craft	Resource					
MECH	33	44	SUSPENSION		\$166.00	
				Total Cost:	\$166.00	
99008	WRECKER/VEHICLE REGISTRATIONS	N	Completed		6/12/2024	5/31/202
Misc Cost Sublet ID						
WRECKER	WRECKER				\$70.00	
				Total Cost:	\$70.00	
99350	R/F HEADLIGHT , 105440	N	Completed		8/5/2024	8/5/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
1255H11	BULB	06	ELECTRICAL		\$7.43	
				Total Cost:	\$7.43	
Labor Cost:						
Craft	Resource					
MECH	33	06	ELECTRICAL		\$20.75	
				Total Cost:	\$20.75	
99463	IS	PM	Completed		8/26/2024	8/30/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
DTZ5862187FA	SHIELD	32	GLASS / INTERIOR		\$112.21	
				Total Cost:	\$112.21	



Report ID: 1111

Unit '	Work	Order	History
--------	------	-------	---------

5W20 SYN OIL OIL FILTER  Resource 12 S 105440 , CHECK ENGINE LIGHT  Resource 12	PMC PM PM	Code Description  ENGINE  ENGINE  "C" LEVEL PM  Completed  ENGINE	Total Cost:  Total Cost:  11.  Total Cost:	\$18.96 \$4.11 \$23.07 \$124.50 \$124.50 \$15/2024 \$41.50	11/18/2024
Resource 12 S 105440 , CHECK ENGINE LIGHT Resource 12	26 26 PMC PM	ENGINE ENGINE "C" LEVEL PM Completed	Total Cost:	\$18.96 \$4.11 \$23.07 \$124.50 \$124.50 /15/2024	11/18/202
Resource 12 S 105440 , CHECK ENGINE LIGHT Resource 12	PMC PM	"C" LEVEL PM  Completed	Total Cost:	\$4.11 \$23.07 \$124.50 \$124.50 /15/2024	11/18/202
Resource 12 S 105440 , CHECK ENGINE LIGHT Resource 12	PMC PM	"C" LEVEL PM Completed	Total Cost:	\$23.07 \$124.50 \$124.50 /15/2024 \$41.50	11/18/2024
S 105440 , CHECK ENGINE LIGHT  Resource 12	PM 26	Completed	Total Cost:	\$124.50 \$124.50 /15/2024 \$41.50	11/18/202·
S 105440 , CHECK ENGINE LIGHT  Resource 12	PM 26	Completed	11.	\$124.50 /15/2024 \$41.50	11/18/202
S 105440 , CHECK ENGINE LIGHT  Resource 12	PM 26	Completed	11.	\$124.50 /15/2024 \$41.50	11/18/202
S 105440 , CHECK ENGINE LIGHT  Resource 12	PM 26	Completed	11.	\$124.50 /15/2024 \$41.50	11/18/2024
Resource 12	26		11.	\$41.50	11/18/2024
Resource 12	26			\$41.50	11/18/2024
12		ENGINE	Total Cost:		
12		ENGINE	Total Cost:		
		ENGINE	Total Cost:		
S 105440 , CHECK ENGINE LIGHT	DM		Total Cost:	\$41.50	
S 105440 , CHECK ENGINE LIGHT	DM				
	PIVI	Completed	11.	/15/2024	11/18/2024
	Code ID	Code Description		Cost	
WASHER FLUID	32	GLASS / INTERIOR		\$2.61	
			Total Cost:	\$2.61	
S 105440 , CHECK ENGINE LIGHT	PM	Completed	11.	/15/2024	11/18/2024
2155516 CONTI	12	TIRES			
			Total Cost:	\$501.74	
_					
	12	TIDEC		402.00	
	12	TIKES		\$83.00	
	2155516 CONTI  Resource 12	Resource	2155516 CONTI 12 TIRES  Resource	2155516 CONTI 12 TIRES  Total Cost:  Resource	2155516 CONTI 12 TIRES \$501.74  Total Cost: \$501.74  Resource



## **Unit Work Order History**

100000

DEAD BATTERY, 105440

Ν

07

Completed

11/25/2024

11/25/2024

**Labor Cost:** 

Craft Resource

MECH 30

BATTERY

IEKY

\$124.50 \$124.50

Total Cost:

**Unit Totals:** 

 Total Number of Work Orders:
 96

 Total Labor Costs:
 \$9,585.50

 Total Part Costs:
 \$7,641.94

 Total Sublet
 \$333.88

 Total Costs:
 \$17,561.32

**Site Totals:** 

 Total Number of Work Orders:
 96

 Total Labor Costs:
 \$9,585.50

 Total Part Costs:
 \$7,641.94

 Total Sublet
 \$333.88

 Total Costs:
 \$17,561.32

Report Totals:

 Total Number of Work Orders:
 96

 Total Labor Costs:
 \$9,585.50

 Total Part Costs:
 \$7,641.94

 Total Sublet
 \$333.88

 Total Costs:
 \$17,561.32

Filter:

Unit id begins with '105440'

