

## Asset Work Order History



Asset: **2976** - 2012 - CRANE LET2-46 2012 Crane Carrier Let2-46  
From 9-30-2020 to 9-30-2025

### FLEET-2021-62 - TURN OFF HEAT

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 04/15/2021 10:22 / 04/15/2021 10:32

Meter 1 Reading: 104,572

Meter 1 Life: 104,572

Meter 2 Reading: 11,937

Meter 2 Life: 11,937

Comments: TURN OFF HEAT

Task:	WAC	Labor	Parts	CML
001-002 - HEATING & VENTILATING	50	\$0.00	\$0.00	\$0.00
TURNED OFF HEAT VALVES				

### FLEET-2021-229 - AIR CONDITIONING

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 04/28/2021 14:42 / 05/17/2021 09:54

Meter 1 Reading: 104,768

Meter 1 Life: 104,768

Meter 2 Reading: 11,937

Meter 2 Life: 11,937

Comments: AIR CONDITIONING

Task:	WAC	Labor	Parts	CML
001-002 - HEATING & VENTILATING	00	\$0.00	\$0.00	\$0.00

### FLEET-2021-629 - WARNING LIGHT

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 06/09/2021 20:40 / 06/14/2021 13:37

Meter 1 Reading: 105,501

Meter 1 Life: 105,501

Meter 2 Reading: 11,937

Meter 2 Life: 11,937

Comments: WARNING LIGHT

Task:	WAC	Labor	Parts	CML
003-001 - GAUGES & WARNING DEVICES	10	\$0.00	\$55.27	\$0.00
L - CHASSIS LUBRICATION 2000 MILE	97	\$0.00	\$168.00	\$0.00
I - ANNUAL STATE INSPECTION	97	\$0.00	\$0.00	\$0.00

### FLEET-2021-766 - VARIOUS REPAIRS

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 06/25/2021 22:35 / 06/30/2021 14:08

Meter 1 Reading: 105,542

Meter 1 Life: 105,542

Meter 2 Reading: 11,946

Meter 2 Life: 11,946

Comments: VARIOUS REPAIRS

Task:	WAC	Labor	Parts	CML
013-999 - BRAKES-INVESTIGATE	10	\$0.00	\$80.88	\$0.00
174-005 - BUS STANDARD SIDE WINDOW COMPONENTS	12	\$0.00	\$0.00	\$0.00
034-001 - HEAD LAMPS	10	\$0.00	\$12.32	\$0.00

## Asset Work Order History

### FLEET-2021-827 - ENGINE LIGHT

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 07/12/2021 10:19 / 07/12/2021 13:37

Meter 1 Reading: 105,750

Meter 1 Life: 105,750

Meter 2 Reading: 11,946

Meter 2 Life: 11,946

Comments: ENGINE LIGHT

Task:	WAC	Labor	Parts	CML
003-999 - INSTRUMENTS-	02	\$0.00	\$0.00	\$0.00

### FLEET-2021-1050 - HUB SEAL

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 11/05/2021 13:48 / 11/17/2021 10:04

Meter 1 Reading: 105,832

Meter 1 Life: 105,832

Meter 2 Reading: 11,946

Meter 2 Life: 11,946

Comments: HUB SEAL

Task:	WAC	Labor	Parts	CML
013-027 - SLACK ADJUSTER - AIR BRAKE	00	\$0.00	\$0.00	\$0.00
017-001 - TIRE - PNEUMATIC	10	\$0.00	\$0.00	\$0.00
018-002 - DRIVE AXLE HUBS - BEARINGS & SEALS	10	\$0.00	\$9,679.61	\$0.00
022-003 - DIFFERENTIAL CARRIER	10	\$0.00	\$0.00	\$0.00
059-032 - LINE ASSEMBLY - HYDRAULIC SYSTEM	10	\$0.00	\$70.08	\$0.00
180-980 - DRIVE BELT	10	\$0.00	\$34.85	\$0.00
L - CHASSIS LUBRICATION 2000 MILE	97	\$0.00	\$0.00	\$0.00

### FLEET-2021-1921 - TURN ON HEAT

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 11/09/2021 07:55 / 11/15/2021 11:01

Meter 1 Reading: 106,164

Meter 1 Life: 106,164

Meter 2 Reading: 11,946

Meter 2 Life: 11,946

Comments: TURN ON HEAT

Task:	WAC	Labor	Parts	CML
001-002 - HEATING & VENTILATING	00	\$0.00	\$0.00	\$0.00

### FLEET-2021-2241 - AIR LEAK

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 01/06/2022 07:47 / 01/18/2022 09:27

Meter 1 Reading: 106,797

Meter 1 Life: 106,797

Meter 2 Reading: 11,946

Meter 2 Life: 11,946

Comments: AIR LEAK

Task:	WAC	Labor	Parts	CML
013-005 - PEDAL ASSEMBLY - SERVICE BRAKE	10	\$0.00	\$0.00	\$0.00
094-008 - LINE - AIR SUPPLY	02	\$0.00	\$10.56	\$0.00
013-999 - BRAKES-INVESTIGATE	02	\$0.00	\$0.00	\$0.00

## Asset Work Order History

### FLEET-2021-2343 - REGEN ISSUE

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 03/17/2022 05:50 / 03/21/2022 08:58

Meter 1 Reading: 107,054

Meter 1 Life: 107,054

Meter 2 Reading: 11,946

Meter 2 Life: 11,946

Comments: REGEN ISSUE

Task:	WAC	Labor	Parts	CML
043-006 - EXHAUST AFTER-TREATMENT DEVICES	10	\$0.00	\$0.00	\$0.00

### FLEET-2022-2603 - ENGINE SHUT DOWN LIGHT ON

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 02/01/2022 16:10 / 02/18/2022 10:55

Meter 1 Reading: 108,101

Meter 1 Life: 108,101

Meter 2 Reading: 11,946

Meter 2 Life: 11,946

Comments: ENGINE SHUT DOWN LIGHT ON

Task:	WAC	Labor	Parts	CML
043-001 - EMISSION CONTROLS	01	\$0.00	\$0.00	\$0.00
045-021 - ELECTRONIC ENGINE CONTROLS	02	\$0.00	\$98.86	\$0.00
043-009 - EXHAUST PIPE	10	\$0.00	\$69.04	\$0.00

### FLEET-2022-2759 - STEP

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 02/17/2022 10:38 / 02/17/2022 10:52

Meter 1 Reading: 108,695

Meter 1 Life: 108,695

Meter 2 Reading: 11,946

Meter 2 Life: 11,946

Comments: STEP

Task:	WAC	Labor	Parts	CML
174-002 - BUS ENTRY STEP COMPONENTS	26	\$0.00	\$0.00	\$0.00

### FLEET-2022-2765 - CHECK ENGINE LIGHT

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 02/25/2022 06:31 / 02/28/2022 10:27

Meter 1 Reading: 108,695

Meter 1 Life: 108,695

Meter 2 Reading: 11,946

Meter 2 Life: 11,946

Comments: CHECK ENGINE LIGHT

Task:	WAC	Labor	Parts	CML
003-999 - INSTRUMENTS-	07	\$0.00	\$0.00	\$0.00

### FLEET-2022-2998 - ENGINE LIGHT ON

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 03/15/2022 08:08 / 03/16/2022 08:36

Meter 1 Reading: 109,786

Meter 1 Life: 109,786

Meter 2 Reading: 11,946

Meter 2 Life: 11,946

Comments: ENGINE LIGHT ON

Task:	WAC	Labor	Parts	CML
045-021 - ELECTRONIC ENGINE CONTROLS	06	\$0.00	\$0.00	\$0.00

# Asset Work Order History

## FLEET-2022-3047 - CAMERA NOT WORKING

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 03/24/2022 12:00 / 03/29/2022 11:00

Meter 1 Reading: 109,786

Meter 1 Life: 109,786

Meter 2 Reading: 12,423

Meter 2 Life: 12,423

Comments: CAMERA NOT WORKING

Task:	WAC	Labor	Parts	CML
003-006 - MONITORING DEVICES	02	\$0.00	\$442.19	\$0.00

## FLEET-2022-3134 - CHECK ENGINE LIGHT

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 03/30/2022 16:13 / 03/31/2022 08:53

Meter 1 Reading: 110,032

Meter 1 Life: 110,032

Meter 2 Reading: 12,423

Meter 2 Life: 12,423

Comments: CHECK ENGINE LIGHT

Task:	WAC	Labor	Parts	CML
002-035 - WINDSHIELD WIPER & WASHER	10	\$0.00	\$17.53	\$0.00
L - CHASSIS LUBRICATION 2000 MILE	97	\$0.00	\$0.00	\$0.00
D - CRANK CASE FILTER 2000HRS	97	\$0.00	\$104.19	\$0.00
A - TASK LISTS	10	\$0.00	\$187.20	\$0.00
999-002 - WASH/CLEAN VEHICLE	01	\$0.00	\$0.00	\$0.00
034-004 - BULBS - FUSES & WIRING - CLEARANCE / MARKER /	10	\$0.00	\$45.63	\$0.00
034-003 - SIGNAL - PARKING - & BACKUP LAMPS	10	\$0.00	\$100.68	\$0.00
027-036 - OIL PAN & SCREEN ASSEMBLY	10	\$0.00	\$60.99	\$0.00
018-002 - DRIVE AXLE HUBS - BEARINGS & SEALS	10	\$0.00	\$34.65	\$0.00
014-004 - CAB & BODY MOUNTINGS	10	\$0.00	\$124.94	\$0.00
013-035 - AIR TANK SUPPLY	10	\$0.00	\$3.13	\$0.00
013-002 - REAR BRAKES & DRUMS	10	\$0.00	\$758.60	\$0.00
003-999 - INSTRUMENTS-	10	\$0.00	\$67.76	\$0.00

## FLEET-2022-3179 - FLIPPER ASSEMBLY

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 06/21/2022 05:32 / 06/28/2022 13:31

Meter 1 Reading: 110,231

Meter 1 Life: 110,231

Meter 2 Reading: 12,423

Meter 2 Life: 12,423

Comments: FLIPPER ASSEMBLY

Task:	WAC	Labor	Parts	CML
002-035 - WINDSHIELD WIPER & WASHER	10	\$0.00	\$6.78	\$0.00
I - ANNUAL STATE INSPECTION	97	\$0.00	\$0.00	\$0.00
034-003 - SIGNAL - PARKING - & BACKUP LAMPS	10	\$0.00	\$52.64	\$0.00
014-015 - LIFTING DEVICES	27	\$0.00	\$0.00	\$0.00
MISSING BOLT ON, FLIPPER. ADDED NEW BOLT				

## FLEET-2022-3188 - SEAT REPAIR

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 04/11/2022 14:07 / 04/18/2022 10:40

Meter 1 Reading: 110,231

Meter 1 Life: 110,231

Meter 2 Reading: 12,423

Meter 2 Life: 12,423

Comments: SEAT REPAIR

Task:	WAC	Labor	Parts	CML
002-037 - SEATS	10	\$0.00	\$0.00	\$0.00

## Asset Work Order History

### FLEET-2022-3218 - ROAD CALL TO 12 16 JENKS CARPENTER RDENGINE SHUT DOWN LIGHT

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 08/02/2022 10:08 / 08/30/2022 14:49

Meter 1 Reading: 110,231

Meter 1 Life: 110,231

Meter 2 Reading: 12,423

Meter 2 Life: 12,423

Comments: ROAD CALL TO 12 16 JENKS CARPENTER RDENGINE SHUT DOWN LIGHT

Task:	WAC	Labor	Parts	CML
043-008 - CATALYTIC CONVERTOR	00	\$0.00	\$3,684.19	\$0.00
045-021 - ELECTRONIC ENGINE CONTROLS	02	\$0.00	\$0.00	\$0.00

### FLEET-2022-3718 - HEAT VENT

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 06/07/2022 15:14 / 06/13/2022 14:27

Meter 1 Reading: 111,797

Meter 1 Life: 111,797

Meter 2 Reading: 12,423

Meter 2 Life: 12,423

Comments: HEAT VENT

Task:	WAC	Labor	Parts	CML
001-002 - HEATING & VENTILATING	00	\$0.00	\$0.00	\$0.00

### FLEET-2022-3927 - EJECTOR CYLINDER

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 08/09/2022 05:20 / 09/07/2022 10:14

Meter 1 Reading: 112,662

Meter 1 Life: 112,662

Meter 2 Reading: 12,423

Meter 2 Life: 12,423

Comments: EJECTOR CYLINDER

Task:	WAC	Labor	Parts	CML
002-012 - FLOOR PAN	20	\$0.00	\$5.75	\$0.00
L - CHASSIS LUBRICATION 2000 MILE	97	\$0.00	\$0.00	\$0.00
999-002 - WASH/CLEAN VEHICLE	01	\$0.00	\$0.00	\$0.00
066-001 - BLADE ASSEMBLY	20	\$0.00	\$0.00	\$0.00
057-325 - EXTENSION HYDRAULIC CYLINDERS	01	\$0.00	\$39.53	\$0.00
057-115 - BLEEDER/DRAIN VALVES	00	\$0.00	\$0.00	\$0.00
043-006 - EXHAUST AFTER-TREATMENT DEVICES	10	\$0.00	\$193.40	\$0.00
034-002 - LAMPS - TAIL - STOP - TURN & LICENSE - REAR	10	\$0.00	\$94.01	\$0.00
016-007 - STABILIZER - REAR	10	\$0.00	\$0.00	\$0.00
003-001 - GAUGES & WARNING DEVICES	02	\$0.00	\$0.00	\$0.00
002-016 - TAILGATE - REAR	05	\$0.00	\$58.96	\$0.00

### FLEET-2022-4291 - NOISE

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 08/19/2022 13:16 / 08/24/2022 10:19

Meter 1 Reading: 112,938

Meter 1 Life: 112,938

Meter 2 Reading: 12,423

Meter 2 Life: 12,423

Comments: NOISE

Task:	WAC	Labor	Parts	CML
065-001 - HYDRAULIC SYSTEMS	04	\$0.00	\$1,107.59	\$0.00

## Asset Work Order History

### FLEET-2022-4299 - TURN SIGNAL NOT WORKING

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 08/25/2022 16:41 / 08/26/2022 08:27

Meter 1 Reading: 113,041

Meter 1 Life: 113,041

Meter 2 Reading: 12,423

Meter 2 Life: 12,423

Comments: TURN SIGNAL NOT WORKING

Task:	WAC	Labor	Parts	CML
034-007 - SIGNALING DEVICES	01	\$0.00	\$0.00	\$0.00

### FLEET-2022-4394 - HYDRAULIC CONTROL BOX HANGING

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 09/13/2022 16:35 / 09/15/2022 09:28

Meter 1 Reading: 113,379

Meter 1 Life: 113,379

Meter 2 Reading: 12,423

Meter 2 Life: 12,423

Comments: HYDRAULIC CONTROL BOX HANGING

Task:	WAC	Labor	Parts	CML
065-001 - HYDRAULIC SYSTEMS	02	\$0.00	\$1,401.31	\$0.00

### FLEET-2022-4693 - THE NEW HYDRAULIC CONTROL BOX HAS BEEN RECALLED

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 10/21/2022 07:48 / 10/27/2022 08:56

Meter 1 Reading: 114,633

Meter 1 Life: 114,633

Meter 2 Reading: 12,423

Meter 2 Life: 12,423

Comments: THE NEW HYDRAULIC CONTROL BOX HAS BEEN RECALLED

Task:	WAC	Labor	Parts	CML
367-003 - HYDRAULIC	10	\$0.00	\$0.00	\$0.00

### FLEET-2022-4753 - REAR CAMERA

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 11/16/2022 07:42 / 11/29/2022 10:09

Meter 1 Reading: 114,759

Meter 1 Life: 114,759

Meter 2 Reading: 13,002

Meter 2 Life: 13,002

Comments: REAR CAMERA

Task:	WAC	Labor	Parts	CML
003-001 - GAUGES & WARNING DEVICES	06	\$0.00	\$0.00	\$0.00
L - CHASSIS LUBRICATION 2000 MILE	97	\$0.00	\$0.51	\$0.00
175-675 - MONITORS	10	\$0.00	\$589.03	\$0.00

### FLEET-2022-4865 - ROAD CALL - BRAKES

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 11/16/2022 07:03 / 11/28/2022 09:42

Meter 1 Reading: 114,759

Meter 1 Life: 114,759

Meter 2 Reading: 13,002

Meter 2 Life: 13,002

Comments: ROAD CALL - BRAKES

Task:	WAC	Labor	Parts	CML
013-999 - BRAKES-INVESTIGATE	10	\$0.00	\$78.11	\$0.00

Asset Work Order History

**FLEET-2022-4993 - FUEL FILTERS**

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 11/15/2022 15:56 / 11/21/2022 11:49

Meter 1 Reading: 115,202  
Meter 2 Reading: 13,002

Meter 1 Life: 115,202  
Meter 2 Life: 13,002

Comments: FUEL FILTERS

Task:	WAC	Labor	Parts	CML
044-002 - FILTERS	10	\$0.00	\$50.77	\$0.00

**FLEET-2022-5010 - INSPECT FRONT END AND STEERING.**

Department: 5460 | Project Code: | Account:

Date Finished/Closed: 02/09/2023 05:30 / 02/09/2023 08:54

Meter 1 Reading: 115,473  
Meter 2 Reading: 13,002

Meter 1 Life: 115,473  
Meter 2 Life: 13,002

Comments: INSPECT FRONT END AND STEERING.

Task:	WAC	Labor	Parts	CML
015-999 - STEERING-INVESTIGATE	02	\$0.00	\$0.00	\$0.00

**FASTER WORK ORDER PRINT**

**WORK ORDER # 36827**  
**EQUIPMENT # 2976**

Date In: 06/12/2012 Date Out: 06/12/2012 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 40 A
			M 1,549 A

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
12	1.00	N	1	06/12/2012	PME BS	PDI	60.00
SUBTOTAL:							60.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
DEF25-1BG	S	1	19.78	06/12/2012	1000001000BS	Unit Services Complete Unit Part Issue	19.78
KEY-CL	S	4	5.60	06/12/2012	1000001000BS	Unit Services Complete Unit Part Issue	22.40
SUBTOTAL:							42.18

WORK ORDER TOTALS	TOTAL:	102.18
-------------------	--------	--------

NOTES

06/12/2012 @ 07:28:48

1. PDI
2. NCSI.

1. PERFORMED PDI, ALSO ADDED DEF FLUID.  
SM.

2. CHECKED NCSI , WAS ALREADY DONE PER DOT INSPECTION.  
SM.

06/12/2012 @ 08:29:34



# FASTER WORK ORDER PRINT

## WORK ORDER # 37452 EQUIPMENT # 2976

Date In: 07/30/2012 Date Out: 07/30/2012 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 5
			M 3,113

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
13	2.00	N	1	07/30/2012	2214000001BN	Compact Hopper System Diagnosis	120.00
SUBTOTAL:							120.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
7651589-BK	S	1	8.47	07/30/2012	1000001000BS	Unit Services Complete Unit Part Issue	8.47
SUBTOTAL:							8.47

WORK ORDER TOTALS	TOTAL:	128.47
-------------------	--------	--------

### NOTES

07/30/2012 @ 07:44:17

1. Tailgate ajar warning light is staying on

1. rewired the proxi switch it had been ripped out out with a tree branch #13

07/30/2012 @ 10:53:03

**FASTER WORK ORDER PRINT**

**WORK ORDER # 37547  
EQUIPMENT # 2976**

Date In: 08/06/2012 Date Out: 08/07/2012 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 244
			M 3,528

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	2.50	N	2	08/06/2012	2036W31001BN	Warning Device Warning Reverse Diagnosis	150.00
11	2.00	N	1	08/07/2012	2065F23T01BN	Hydraulic Syste Fitting Hydraul TIGHTEN	120.00
SUBTOTAL:							270.00

WORK ORDER TOTALS	TOTAL:	270.00
-------------------	--------	--------

NOTES

08/06/2012 @ 15:02:26

1. Hyd leak on fitting hyd control valve area
2. Back up alarm and camera not working

1. Cleaned off area and tested. Leak is coming from elbow adapter fitting between main sweep blade spool valve assembly and add-on flipper diverter block. Attempt to tighten fitting, no change. Looks like flipper diverter block will have to be removed for access and to reseal with thread tape. Warranty repair? #11

08/07/2012 @ 22:31:36

2. Found backup camera wire cut through above hopper. Repaired with another section of camera wire. Back up alarm is working properly at this time. #11

08/06/2012 @ 23:01:07

# FASTER WORK ORDER PRINT

## WORK ORDER # 38405 EQUIPMENT # 2976

Date In: 10/16/2012 Date Out: 10/17/2012 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 244
			M 6,672

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
24	4.00	N	1	10/17/2012	PMA BS	PM A Service	240.00
24	0.50	N	1	10/17/2012	1053T90100BS	Expendable Tape Replace	30.00
SUBTOTAL:							270.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1748XD-FIL	S	1	39.26	10/18/2012	1000001000BS	Unit Services Complete Unit Part Issue	39.26
3604XE-FIL	S	1	32.98	10/18/2012	1000001000BS	Unit Services Complete Unit Part Issue	32.98
3936-FIL	S	1	17.90	10/18/2012	1000001000BS	Unit Services Complete Unit Part Issue	17.90
110-1BG	S	4	8.33	10/18/2012	1000001000BS	Unit Services Complete Unit Part Issue	33.32
9600-MAC	S	2	8.41	10/18/2012	1000001000BS	Unit Services Complete Unit Part Issue	16.83
15W40-9OC	S	26	4.76	10/18/2012	1000001000BS	Unit Services Complete Unit Part Issue	123.76
SUBTOTAL:							264.04

WORK ORDER TOTALS	TOTAL:	534.04
-------------------	--------	--------

### NOTES

10/16/2012 @ 15:37:10

#### 1. PM SERVICE

#### 2. INSTALL SSAFETY REFLECTIVE TAPE ON REAR OF HOPPER AREA

pm and safty stickers are done parked truck across street

**FASTER WORK ORDER PRINT**

**WORK ORDER # 38814  
EQUIPMENT # 2976**

Date In: 11/07/2012 Date Out: 11/07/2012 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 244
			M 7,441

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	11/07/2012	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
WINGFOOT/GOO DYEAR COMM TIRE	17.94	62.00	-79.94	11/07/2012	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

11/07/2012 @ 15:48:44

CAROLINA HEAVY DUTY TRUCK INV OF 8-27-12

LUBRICATION

TT

11/08/2012 @ 15:41:01

WINGFOOT INV OF 08/27/2012

1-REG SCHD 1HR YARD SVC  
2-VSTEMS

TT

**FASTER WORK ORDER PRINT**

**WORK ORDER # 38909**  
**EQUIPMENT # 2976**

Date In: 11/14/2012 Date Out: 11/14/2012 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 244
			M 7,597

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
24	0.50	N	2	11/14/2012	2065F23165BN	Hydraulic Syste Fitting Hydraul Repair	30.00

SUBTOTAL: 30.00

WORK ORDER TOTALS TOTAL: 30.00

NOTES

11/14/2012 @ 11:27:49

1. Repair hydrraualc fitting on flipper control.  
tightend fitting

# FASTER WORK ORDER PRINT

## WORK ORDER # 38951 EQUIPMENT # 2976

Date In: 11/16/2012 Date Out: 11/17/2012 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 652
			M 7,832

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	1.00	N	1	11/17/2012	2003LN4001BS	Gauge Instro Light Brake War Diagnosis	60.00
SUBTOTAL:							60.00

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	574.15	35.97	-610.12	11/17/2012	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
WINGFOOT/GOO DYEAR COMM TIRE	0.00	62.00	-62.00	11/17/2012	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	11/28/2012	8000001Z99BN	Unit Services Complete Unit Transaction Fee	38.00
SUBTOTAL:					38.00

WORK ORDER TOTALS TOTAL: 98.00

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 38951**  
**EQUIPMENT # 2976**

11/16/2012 @ 16:15:30

**1. ABS LIGHT ON**

1. Bendix code 5-3 "right side drive axle speed sensor circuit open or shorted". Checked circuit, found break in karnes at rear tandem on right side.  
Repaired wiring. #11

11/17/2012 @ 15:55:12

11/28/2012 @ 14:33:53

WINGFOOT INV OF 9-7-12

1 REG SCHD 1HR YARD SVC

TT

11/28/2012 @ 14:37:02

WINGFOOT INV OF 9-6-12

1 GY 315/80R22.5 G289 SHA DURA 20  
1 VSTEM

TT

**FASTER WORK ORDER PRINT**

**WORK ORDER # 39607**  
**EQUIPMENT # 2976**

Date In: 01/11/2013   Date Out: 01/14/2013   Work Order Status: C   Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H                      854
			M                      10,170

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

01/11/2013 @ 13:58:58  
1. NCSI

1. Inspection computer will not allow an NCSI at this time, vehicle cannot be inspected more than 90 days before it's due. Checked history, it does not appear that we have inspected it. On the first WO on 06/12/2012, Scott PDI'd and said NCSI "WAS ALREADY DONE PER DOT INSPECTION". #11  
01/11/2013 @ 15:27:48

Inspection sheet faxed over from Southern Truck Crane Carrier. #11  
01/14/2013 @ 14:49:00



# FASTER WORK ORDER PRINT

## WORK ORDER # 39626 EQUIPMENT # 2976

Date In: 01/15/2013 Date Out: 01/15/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 861
			M 10,237

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	0.50	N	1	01/15/2013	2003LN9001BN	Gauge Instro LightCheckEngin Diagnosis	30.00
11	0.50	N	1	01/15/2013	2003LN9001BN	Gauge Instro LightCheckEngin Diagnosis	30.00
11	1.00	N	1	01/15/2013	2044F15100BN	Fuel System Filter Fuel Pri Replace	60.00
SUBTOTAL:							120.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
3936-FIL	S	1	17.90	01/16/2013	1000001000BS	Unit Services Complete Unit Part Issue	17.90
3604XE-FIL	S	1	32.98	01/16/2013	1000001000BS	Unit Services Complete Unit Part Issue	32.98
9600-MAC	S	2	8.41	01/16/2013	1000001000BS	Unit Services Complete Unit Part Issue	16.83
H6054-LMP	S	1	8.91	01/16/2013	1000001000BS	Unit Services Complete Unit Part Issue	8.91
SUBTOTAL:							76.61

WORK ORDER TOTALS	TOTAL:	196.61
-------------------	--------	--------

### NOTES

01/15/2013 @ 14:27:24

1. Check engine light on and no power

1. Multiple stored inactive codes, most recent were 559 fuel metering rail pressure low and 2372 furl filter differential pressure high. Cleared codes. #11

01/15/2013 @ 20:27:43

2. Replaced fuel filters. OEM Fleetguard filter was still installed at rear of transmission. #11

01/15/2013 @ 21:41:30

**FASTER WORK ORDER PRINT**

**WORK ORDER # 39937  
EQUIPMENT # 2976**

Date In: 02/05/2013 Date Out: 02/05/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 861
			M 11,000

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	02/05/2013	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
WINGFOOT/GOO DYEAR COMM TIRE	35.88	124.00	-159.88	02/05/2013	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
WINGFOOT/GOO DYEAR COMM TIRE	12.00	93.00	-105.00	02/05/2013	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	02/05/2013	8000001Z99BN	Unit Services Complete Unit Transaction Fee	38.00
SUBTOTAL:					38.00

WORK ORDER TOTALS	TOTAL:	38.00
-------------------	--------	-------

NOTES

02/05/2013 @ 13:50:06

CAROLINA HEAVY DUTY TRUCK INV OF 10-30-12

LUBRICATION

TT

02/05/2013 @ 15:08:55

WINGFOOT INV OF 10-29-12

1.5 REG SCHD YARD SVC  
3 VSTEMS

TT

02/06/2013 @ 15:22:34

WINGFOOT INV OF 9-24-12

2 1 HR YARD SVC  
4 VSTEMS

TT

# FASTER WORK ORDER PRINT

## WORK ORDER # 40160 EQUIPMENT # 2976

Date In: 02/21/2013 Date Out: 02/21/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 993
			M 11,910

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	0.50	N	1	02/21/2013	1003LN9001BS	Gauge Instr LightCheckEngin Diagnosis	30.00
24	4.00	N	1	02/21/2013	PMA BS	PM A Service	240.00
24	0.70	N	1	02/21/2013	PMI BS	Annual State In	42.00
SUBTOTAL:							312.00

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	02/21/2013	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1748-FIL	S	1	35.50	02/22/2013	1000001000BS	Unit Services Complete Unit Part Issue	35.50
3604XE-FIL	S	1	32.98	02/22/2013	1000001000BS	Unit Services Complete Unit Part Issue	32.98
3936-FIL	S	1	17.90	02/22/2013	1000001000BS	Unit Services Complete Unit Part Issue	17.90
110-1BG	S	4	9.06	02/22/2013	1000001000BS	Unit Services Complete Unit Part Issue	36.22
9600-MAC	S	2	8.41	02/22/2013	1000001000BS	Unit Services Complete Unit Part Issue	16.83
15W40-9OC	S	26	4.76	02/22/2013	1000001000BS	Unit Services Complete Unit Part Issue	123.76
SUBTOTAL:							263.18

WORK ORDER TOTALS TOTAL: 575.18

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 40160**  
**EQUIPMENT # 2976**

02/21/2013 @ 14:07:54

1. NCSI
2. PM SERVICE
3. CHECK ENGINE LIGHT ON

3. Stored active DTCs 559 fuel metering rail pressure low, and 2372 fuel filter differential pressure high. Fuel filters clogged, replaced on PM.  
Cleared codes. #11

02/21/2013 @ 17:14:26

02/26/2013 @ 13:23:19

CAROLINA HEAVY DUTY INV OF 9-25-12

LUBRICATION

TT

**FASTER WORK ORDER PRINT**

**WORK ORDER # 40584  
EQUIPMENT # 2976**

Date In: 04/01/2013 Date Out: 04/01/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 1,176 A
			M 13,677 A

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
12	1.00	N	1	04/01/2013	2003LN9001BN	Gauge Instro LightCheckEngin Diagnosis	60.00
SUBTOTAL:							60.00

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	04/01/2013	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	04/01/2013	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
3604XE-FIL	S	1	32.98	04/01/2013	1000001000BS	Unit Services Complete Unit Part Issue	32.98
9600-MAC	S	2	8.41	04/01/2013	1000001000BS	Unit Services Complete Unit Part Issue	16.83
7100-MAC	S	2	2.73	04/01/2013	1000001000BS	Unit Services Complete Unit Part Issue	5.45
248-1BG	S	1	11.32	04/01/2013	1000001000BS	Unit Services Complete Unit Part Issue	11.32
SUBTOTAL:							66.57

WORK ORDER TOTALS	TOTAL:	126.57
-------------------	--------	--------

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 40584**  
**EQUIPMENT # 2976**

04/01/2013 @ 07:34:19

1. Check engine light on and low on power.

1. Checked out, replaced both fuel filters and added conditioner to fuel system, tested.  
sm.

04/01/2013 @ 08:23:50

04/16/2013 @ 10:03:59

CAROLINA HEAVY DUTY INV OF 11-27-12

LUBRICATION

TT

04/22/2013 @ 13:44:10

CAROLINA HEAVY DUTY INV OF 12-17-12

LUBRICATION

TT

# FASTER WORK ORDER PRINT

## WORK ORDER # 40795 EQUIPMENT # 2976

Date In: 04/17/2013 Date Out: 04/17/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 993
			M 14,373

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
13	0.50	N	1	04/17/2013	2001MH0165BN	Air Conditionin Misc Parts Repair	30.00
SUBTOTAL:							30.00

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	570.18	25.00	-595.18	04/17/2013	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
WINGFOOT/GOO DYEAR COMM TIRE	24.00	186.00	-210.00	04/17/2013	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/23/2013	8000001Z99BN	Unit Services Complete Unit Transaction Fee	19.00
SUBTOTAL:					19.00

WORK ORDER TOTALS TOTAL: 49.00

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 40795**  
**EQUIPMENT # 2976**

04/17/2013 @ 14:57:09

A/C NOT OPERATING, PLEASE REPAIR

TT

closed head valves #13  
04/17/2013 @ 15:24:26

04/23/2013 @ 15:07:54

WINGFOOT INV OF 12-27-12

1 TIRE  
1 VSTEM

TT

04/25/2013 @ 16:03:17

WINGFOOT INV OF 1-8-13

3 TIRES  
6 STEMS

TT



**FASTER WORK ORDER PRINT**

**WORK ORDER # 41319**  
**EQUIPMENT # 2976**

Date In: 05/30/2013 Date Out: 05/30/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 993
			M 16,374

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	05/30/2013	Z000001055NS	Unit Services Complete Unit Lubrication	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

05/30/2013 @ 14:43:46

CAROLINA HEAVY DUTY TRUCK INV OF 3-25-13

LUBRICATION

TT

**FASTER WORK ORDER PRINT**

**WORK ORDER # 41398**  
**EQUIPMENT # 2976**

Date In: 06/05/2013 Date Out: 06/11/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 993
			M 16,374

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
28	1.00	N	1	06/05/2013	8032MH0001BN	Cranking System Misc Parts Diagnosis	60.00
SUBTOTAL:							60.00

WORK ORDER TOTALS	TOTAL:	60.00
-------------------	--------	-------

NOTES

06/05/2013 @ 13:01:32

TRUCK SHUT DOWN ON ROUTE, PLEASE SEE IF YOU CAN GET STARTED

TT

06/05/2013 @ 14:08:09

PER DUANE; UNIT WILL NOT GO INTO GEAR

MUSTER'S TAKING TO CARDINAL INTERNATIONAL for transmission repair.

TT

# FASTER WORK ORDER PRINT

## WORK ORDER # 41482 EQUIPMENT # 2976

Date In: 06/13/2013 Date Out: 06/13/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 1,445
			M 16,790

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	1.50	N	2	06/13/2013	2051DQ0165BN	Air Supply Drain Air Tank Repair	90.00
11	2.50	N	2	06/13/2013	2003LN4001BN	Gauge Instro Light Brake War Diagnosis	150.00
11	0.50	N	2	06/13/2013	2214000001BN	Compact Hopper System Diagnosis	30.00
SUBTOTAL:							270.00

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	06/21/2013	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	06/21/2013	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
MUSTERS WRECKER & RP SERV INC.	0.00	200.00	-200.00	06/13/2013	Z000001500NN	Unit Services Complete Unit Towing	0.00
MUSTERS WRECKER & RP SERV INC.	0.00	300.00	-300.00	06/13/2013	Z000001500NN	Unit Services Complete Unit Towing	0.00
SUBTOTAL:							0.00

WORK ORDER TOTALS	TOTAL:	270.00
-------------------	--------	--------

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 41482  
EQUIPMENT # 2976**

06/13/2013 @ 16:57:52

1. Operator states tailgate ajar warning light and alarm stay on.
2. Operator states ABS light is on.
3. Operator states air tank drain valves will not open.

MC

1. Proximity sensor at top of tailgate failed. Shorted to turn off alarms, ordered part. #11

06/13/2013 @ 22:56:38

2. Bendix ACom diagnostics code 5-3 right drive axle wheel speed sensor circuit open. Inspected right drive axle WSS, found harness broken. Repaired wiring, cleared DTC. #11

06/13/2013 @ 22:21:22

3. Replaced air tank drain valves. #11

06/13/2013 @ 19:00:40

CAROLINA HEAVY DUTY TRUCK INV OF 2/26/13

LUBRICATION

PD

CAROLINA HEAVY DUTY TRUCK INV OF 1/29/13

LUBRICATION

PD

CAROLINA HEAVY DUTY TRUCK INV OF 4/23/13

LUBRICATION

PD

CAROLINA HEAVY DUTY TRUCK INV OF 5/28/13

LUBRICATION

PD

CAROLINA HEAVY DUTY TRUCK INV OF 6/25/13

LUBRICATION

PD

MUSTER'S WRECKER INVOICE OF 6/5/13

PD

MUSTER'S WRECKER INVOICE OF 6/12/13

PD

# FASTER WORK ORDER PRINT

## WORK ORDER # 42067 EQUIPMENT # 2976

Date In: 08/02/2013 Date Out: 08/03/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7025	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 1,688
			M 18,965

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	1.50	N	1	08/03/2013	PMA BS	PM A Service	90.00
10	0.50	N	1	08/03/2013	1111SY7165BS	PTO Switch PTO Repair	30.00
10	0.50	N	1	08/03/2013	1214FL1165BS	Compact Hopper FLIPPER ASSY. Repair	30.00
24	1.50	N	1	08/03/2013	PMA BS	PM A Service	90.00
35	1.50	N	1	08/03/2013	PMA BS	PM A Service	90.00
SUBTOTAL:							330.00

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	08/02/2013	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
WINGFOOT/GOOD YEAR COMM TIRE	12.00	62.00	-74.00	08/03/2013	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
WINGFOOT/GOOD YEAR COMM TIRE	24.00	124.00	-148.00	08/02/2013	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
WINGFOOT/GOOD YEAR COMM TIRE	0.00	124.00	-124.00	08/02/2013	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
WINGFOOT/GOOD YEAR COMM TIRE	0.00	31.00	-31.00	08/02/2013	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1748XD-FIL	S	1	39.26	08/02/2013	1000001000BS	Unit Services Complete Unit Part Issue	39.26
3604XE-FIL	S	1	32.98	08/02/2013	1000001000BS	Unit Services Complete Unit Part Issue	32.98
3936-FIL	S	1	17.90	08/02/2013	1000001000BS	Unit Services Complete Unit Part Issue	17.90
110-NON	S	4	9.06	08/02/2013	1000001000BS	Unit Services Complete Unit Part Issue	36.22
9600-MAC	S	2	9.29	08/02/2013	1000001000BS	Unit Services Complete Unit Part Issue	18.59
15W40-9OC	S	26	4.76	08/02/2013	1000001000BS	Unit Services Complete Unit Part Issue	123.76
7651274-BK	S	1	7.34	08/05/2013	1000001000BS	Unit Services Complete Unit Part Issue	7.34
SUBTOTAL:							276.05

**FASTER WORK ORDER PRINT**

**WORK ORDER # 42067**  
**EQUIPMENT # 2976**

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	08/14/2013	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	19.00
SUBTOTAL:					19.00
WORK ORDER TOTALS					TOTAL: 625.05
NOTES					

**FASTER WORK ORDER PRINT**

**WORK ORDER # 42067  
EQUIPMENT # 2976**

08/02/2013 @ 14:13:21

1. PM SERVICE
- 2.. FLIPPER HANDLE IS BENT ON DRIVER SIDE REAR
3. PTO DASH BUTTON KEEPS FALLING OFF

1. Performed PM service. #10 #35 #24

08/03/2013 @ 12:27:10

2. Removed and streightend handel. #10

08/03/2013 @ 12:28:58

3. PTO dash switch not in stock. Used 5min epox to hold on. Switch repaired. #10, #24

08/03/2013 @ 12:29:14

Wingfoot Invoice of 2/18/13

2 tires

pd

Wingfoot Inv of 4/8/13

4 tires

pd

08/30/2013 @ 11:26:09

Wingfoot Inv of 7/30/13

4 tires

pd

08/30/2013 @ 13:32:48

Carolina Heavy Duty Inv of 8/26/13

lubrication

pd

08/30/2013 @ 14:05:28

Wingfoot Inv of 8/27/13

6 tires

pd

08/30/2013 @ 14:08:17

Wingfoot Inv of 8/20/13

1 tire

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 42489  
EQUIPMENT # 2976**

Date In: 09/04/2013 Date Out: 09/04/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 1,688
			M 18,965

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	09/19/2013	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
WINGFOOT/GOO DYEAR COMM TIRE	0.00	31.00	-31.00	09/04/2013	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
WINGFOOT/GOO DYEAR COMM TIRE	0.00	155.00	-155.00	09/04/2013	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
WINGFOOT/GOO DYEAR COMM TIRE	26.00	93.00	-119.00	09/04/2013	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
WINGFOOT/GOO DYEAR COMM TIRE	418.00	0.00	-418.00	09/04/2013	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
WINGFOOT/GOO DYEAR COMM TIRE	0.00	62.00	-62.00	09/04/2013	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	09/04/2013	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	19.00
SUBTOTAL:					19.00

WORK ORDER TOTALS	TOTAL:	19.00
-------------------	--------	-------

NOTES



**FASTER WORK ORDER PRINT**

**WORK ORDER # 42489**  
**EQUIPMENT # 2976**

09/04/2013 @ 12:25:52  
Wingfoot Inv of 7/9/13

3 tires

pd

09/06/2013 @ 15:25:02  
Wingfoot Inv of 5/30/13

5 tires

pd

09/09/2013 @ 15:31:22  
Wingfoot Inv of 4/24/13

1 tire

pd

09/12/2013 @ 13:08:43  
Wingfoot Inv. of 8/29/13

2 tires

pd

09/12/2013 @ 13:10:02  
Wingfoot Inv. of 8/30/13

2 tires

pd

09/19/2013 @ 15:35:14  
Carolina Heavy Duty Inv of 7/30/13

lubrication

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 42771 EQUIPMENT # 2976

Date In: 09/20/2013 Date Out: 09/20/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 1,888
			M 21,242 A

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	1.50	N	2	09/20/2013	PMD BS	PM D Service	90.00
SUBTOTAL:							90.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
CV50628-NON	S	1	113.65	09/20/2013	1000001000BS	Unit Services Complete Unit Part Issue	113.65
SUBTOTAL:							113.65

WORK ORDER TOTALS	TOTAL:	203.65
-------------------	--------	--------

### NOTES

09/20/2013 @ 15:33:57

1. PM D SERVICE

1. Performed PM-D service. #11

09/20/2013 @ 22:37:16

# FASTER WORK ORDER PRINT

## WORK ORDER # 42831 EQUIPMENT # 2976

Date In: 09/26/2013 Date Out: 09/26/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 1,909
			M 21,492

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	0.50	N	2	09/26/2013	2011001100BN	Axle Front HUB SEAL Replace	30.00
10	0.50	N	2	09/26/2013	2034B60100BN	Light System Bulb Headlight Replace	30.00
SUBTOTAL:							60.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
H6054-LMP	S	1	8.91	09/26/2013	1000001000BS	Unit Services Complete Unit Part Issue	8.91
75210-NOL	S	1	5.47	09/26/2013	1000001000BS	Unit Services Complete Unit Part Issue	5.47
1643-NOS	S	1	19.96	09/26/2013	1000001000BS	Unit Services Complete Unit Part Issue	19.96
SUBTOTAL:							34.34

WORK ORDER TOTALS	TOTAL:	94.34
-------------------	--------	-------

### NOTES

09/26/2013 @ 15:17:47  
1. right hub seal leaking  
2. headlight bulb is out

1. Replaced right front hub cap. #10
2. Replaced left headlight. #10

# FASTER WORK ORDER PRINT

## WORK ORDER # 43138 EQUIPMENT # 2976

Date In: 10/22/2013 Date Out: 10/22/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,000
			M 22,508

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	0.50	N	2	10/22/2013	2044F15100BN	Fuel System Filter Fuel Pri Replace	30.00
10	1.00	N	2	10/22/2013	2003000001BN	Gauge Instro System Diagnosis	60.00
SUBTOTAL:							90.00

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	10/22/2013	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
3604XE-FIL	S	1	32.98	10/23/2013	1000001000BS	Unit Services Complete Unit Part Issue	32.98
3936-FIL	S	1	17.90	10/23/2013	1000001000BS	Unit Services Complete Unit Part Issue	17.90
9600-MAC	S	2	9.29	10/23/2013	1000001000BS	Unit Services Complete Unit Part Issue	18.59
SUBTOTAL:							69.46

WORK ORDER TOTALS	TOTAL:	159.46
-------------------	--------	--------

### NOTES

10/22/2013 @ 15:59:30

1. CHECK ENGINE LIGHT ON AND LOW POWER

1. DTC for fuel filter differential pressure was inactive. Replaced fuel filters and cleared code. #10

10/22/2013 @ 20:29:51

10/31/2013 @ 12:27:20

Carolina Heavy Duty Inv of 9/25/13

Lubrication

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 43389**  
**EQUIPMENT # 2976**

Date In: 11/08/2013 Date Out: 11/08/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,000
			M 22,508

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	11/08/2013	Z000001055NS	Unit Services Complete Unit Lubrication	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

11/08/2013 @ 14:59:42  
Carolina Heavy Duty Inv of 10/30/13

Lubrication

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 43652**  
**EQUIPMENT # 2976**

Date In: 11/30/2013 Date Out: 11/30/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,000
			M 23,746

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	0.50	N	1	11/30/2013	2065000001BN	Hydraulic Syste System Diagnosis	30.00

SUBTOTAL: 30.00

WORK ORDER TOTALS TOTAL: 30.00

NOTES

11/30/2013 @ 10:48:57

1. PACKER MOVING REAL SLOW

1. Master switch for ACCL power inside cab was turned off. #10

# FASTER WORK ORDER PRINT

## WORK ORDER # 43659 EQUIPMENT # 2976

Date In: 12/02/2013 Date Out: 12/02/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,000
			M 23,746

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
13	0.50	N	1	12/02/2013	PMA BS	PM A Service	30.00
13	3.50	N	1	12/02/2013	PMA BS	PM A Service	210.00
SUBTOTAL:							240.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1748XD-FIL	S	1	39.26	12/02/2013	1000001000BS	Unit Services Complete Unit Part Issue	39.26
3604XE-FIL	S	1	32.98	12/02/2013	1000001000BS	Unit Services Complete Unit Part Issue	32.98
3936-FIL	S	1	17.90	12/02/2013	1000001000BS	Unit Services Complete Unit Part Issue	17.90
110-NON	S	4	9.06	12/02/2013	1000001000BS	Unit Services Complete Unit Part Issue	36.22
9600-MAC	S	2	9.29	12/02/2013	1000001000BS	Unit Services Complete Unit Part Issue	18.59
15W40-NON	S	26	4.76	12/02/2013	1000001000BS	Unit Services Complete Unit Part Issue	123.76
SUBTOTAL:							268.70

WORK ORDER TOTALS	TOTAL:	508.70
-------------------	--------	--------

### NOTES

12/02/2013 @ 10:55:00  
1. PM SERVICE  
  
1. pm is done #13  
12/02/2013 @ 15:24:13

**FASTER WORK ORDER PRINT**

**WORK ORDER # 43827**  
**EQUIPMENT # 2976**

Date In: 12/13/2013 Date Out: 12/16/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,000
			M 23,882

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	0.50	N	1	12/13/2013	2065F16100BN	Hydraulic Syste Filter Hydraul Replace	30.00
SUBTOTAL:							30.00

WORK ORDER TOTALS	TOTAL:	30.00
-------------------	--------	-------

NOTES

12/13/2013 @ 13:51:34  
1. RREPLACE HYD. FILTER

1. Replaced filter. #11  
12/13/2013 @ 15:38:37



# FASTER WORK ORDER PRINT

## WORK ORDER # 43938 EQUIPMENT # 2976

Date In: 12/20/2013 Date Out: 12/23/2013 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,000
			M 24,957

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	0.50	N	1	12/20/2013	2013000001BN	Brakes System Diagnosis	30.00
04	1.00	N	1	12/20/2013	2011000001BN	Axle Front System Diagnosis	60.00
04	2.50	N	1	12/23/2013	2013000001BN	Brakes System Diagnosis	150.00
04	0.50	N	1	12/23/2013	2013000001BN	Brakes System Diagnosis	30.00
11	1.00	N	1	12/23/2013	2013SC2100BN	Brakes Shoe/LiningA-Br Replace	60.00
SUBTOTAL:							330.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
GG4726ES2RKIT-STP	S	2	113.06	12/23/2013	1000001000BS	Unit Services Complete Unit Part Issue	226.13
GG4726ES2G-MBI	S	2	109.09	12/23/2013	1000001000BS	Unit Services Complete Unit Part Issue	218.17
66854B-TWD	S	4	317.22	12/23/2013	1000001000BS	Unit Services Complete Unit Part Issue	1,268.87
1643-NOS	S	1	19.96	12/23/2013	1000001000BS	Unit Services Complete Unit Part Issue	19.96
75140-NOL	S	1	4.13	12/27/2013	1000001000BS	Unit Services Complete Unit Part Issue	4.13
101724-NCB	S	1	29.85	12/27/2013	1000001000BS	Unit Services Complete Unit Part Issue	29.85
DEF002-NAF	S	1	14.44	12/27/2013	1000001000BS	Unit Services Complete Unit Part Issue	14.44
SUBTOTAL:							1,781.54

WORK ORDER TOTALS	TOTAL:	2,111.54
-------------------	--------	----------

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 43938**  
**EQUIPMENT # 2976**

12/20/2013 @ 18:08:28

1. Operator states truck is hard to stop.

2. Check front hubs for leak.

needs brakes on both rear axles. #04

12/20/2013 @ 18:11:06

need outer wheel hub on front left wheel.#04

12/20/2013 @ 18:39:59

Removed right rear tandem for brake part numbers, shoes:4726, drums:66854. #11

12/23/2013 @ 09:27:35

replaced brakes. #04

12/23/2013 @ 20:39:28

replaced front hub cap. #04

12/23/2013 @ 20:40:14

# FASTER WORK ORDER PRINT

## WORK ORDER # 44086 EQUIPMENT # 2976

Date In: 01/08/2014 Date Out: 01/08/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,268
			M 25,792

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	1.00	N	1	01/08/2014	2003LN9001BN	Gauge Instro LightCheckEngin Diagnosis	60.00
SUBTOTAL:							60.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
3936-FIL	S	1	17.90	01/08/2014	1000001000BS	Unit Services Complete Unit Part Issue	17.90
3604XE-FIL	S	1	32.98	01/08/2014	1000001000BS	Unit Services Complete Unit Part Issue	32.98
9600-MAC	S	2	9.29	01/08/2014	1000001000BS	Unit Services Complete Unit Part Issue	18.59
SUBTOTAL:							69.46

WORK ORDER TOTALS	TOTAL:	129.46
-------------------	--------	--------

### NOTES

01/08/2014 @ 09:09:55

1. Check engine light on and low power

1. Stored DTC for fuel rail pressure low. Replaced fuel filters and cleared. #11

01/08/2014 @ 13:09:30

# FASTER WORK ORDER PRINT

## WORK ORDER # 45083 EQUIPMENT # 2976

Date In: 03/07/2014 Date Out: 03/07/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,268
			M 27,286

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	1.00	N	2	03/07/2014	2003LN9001BN	Gauge Instro LightCheckEngin Diagnosis	60.00
SUBTOTAL:							60.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
3936-FIL	S	1	17.90	03/10/2014	1000001000BS	Unit Services Complete Unit Part Issue	17.90
3604XE-FIL	S	1	32.98	03/10/2014	1000001000BS	Unit Services Complete Unit Part Issue	32.98
9600-MAC	S	2	9.29	03/10/2014	1000001000BS	Unit Services Complete Unit Part Issue	18.59
SUBTOTAL:							69.46

WORK ORDER TOTALS	TOTAL:	129.46
-------------------	--------	--------

### NOTES

03/07/2014 @ 14:14:20

1. Check engine light on and low power

Code showed possible fuel filter pressure replaced filters and found loose connector on top of water seperator plugged in no fault codes runs normally. #04

# FASTER WORK ORDER PRINT

## WORK ORDER # 45106 EQUIPMENT # 2976

Date In: 03/10/2014 Date Out: 03/11/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,507
			M 28,100

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	1.00	N	1	03/11/2014	1022S1E100BS	Axle Rear Drive Seal Grease Rea Replace	60.00
11	3.00	N	1	03/11/2014	1022S1E100BS	Axle Rear Drive Seal Grease Rea Replace	180.00
35	4.00	N	2	03/10/2014	PMA BS	PM A Service	240.00
SUBTOTAL:							480.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1748XD-FIL	S	1	39.26	03/11/2014	1000001000BS	Unit Services Complete Unit Part Issue	39.26
3604XE-FIL	S	1	32.98	03/11/2014	1000001000BS	Unit Services Complete Unit Part Issue	32.98
110-1BG	S	4	9.06	03/11/2014	1000001000BS	Unit Services Complete Unit Part Issue	36.22
9600-MAC	S	2	9.29	03/11/2014	1000001000BS	Unit Services Complete Unit Part Issue	18.59
15W40-9OC	S	26	4.76	03/11/2014	1000001000BS	Unit Services Complete Unit Part Issue	123.76
66854B-9HD	S	2	257.97	03/11/2014	1000001000BS	Unit Services Complete Unit Part Issue	515.93
GG4726ES2KIT-9HD	S	2	113.06	03/11/2014	1000001000BS	Unit Services Complete Unit Part Issue	226.13
3303036-TWD	S	1	2.36	03/11/2014	1000001000BS	Unit Services Complete Unit Part Issue	2.36
370003A-NTL	S	1	46.52	03/11/2014	1000001000BS	Unit Services Complete Unit Part Issue	46.52
SUBTOTAL:							1,041.74

WORK ORDER TOTALS	TOTAL:	1,521.74
-------------------	--------	----------

### NOTES

03/10/2014 @ 15:35:21  
1. PM SERVICE

TRUCK IS ACROSS STREET AND KEY IS IN IT

03/10/2014 @ 23:01:49 PM Done hub seal leaking intermediate axle LOTO

2. Replaced left intermediate tandem hub seal, and both sets of brakes and drums on intermediate tande axle. #1  
03/11/2014 @ 15:41:56

**FASTER WORK ORDER PRINT**

**WORK ORDER # 45166**  
**EQUIPMENT # 2976**

Date In: 03/11/2014 Date Out: 03/11/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,507
			M 28,100

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	03/11/2014	Z000001055NS	Unit Services Complete Unit Lubrication	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

03/11/2014 @ 14:22:11

CAROLINA HEAVY DUTY INV OF 12/3/13

LUBRICATION

CS

**FASTER WORK ORDER PRINT**

**WORK ORDER # 45224**  
**EQUIPMENT # 2976**

Date In: 03/12/2014 Date Out: 03/12/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,515
			M 28,187

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	0.50	N	2	03/12/2014	2013AB1165BN	Brakes Adjuster Brake Repair	30.00
SUBTOTAL:							30.00

WORK ORDER TOTALS	TOTAL:	30.00
-------------------	--------	-------

NOTES

03/12/2014 @ 15:48:41

1. Adjust rear brakes.

1. Adjusted brakes. #10

**FASTER WORK ORDER PRINT**

**WORK ORDER # 45264**  
**EQUIPMENT # 2976**

Date In: 03/13/2014   Date Out: 03/13/2014   Work Order Status: C   Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H                      2,515
			M                      28,187

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

03/13/2014 @ 13:04:06

Carolina Heavy Duty Inv for 12/30/2013

LUBRICATION

CS



**FASTER WORK ORDER PRINT**

**WORK ORDER # 45330**  
**EQUIPMENT # 2976**

Date In: 03/13/2014 Date Out: 03/13/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,515
			M 28,187

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	03/13/2014	Z000001055NS	Unit Services Complete Unit Lubrication	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

03/13/2014 @ 13:04:06

Carolina Heavy Duty Inv for 1/27/2014

LUBRICATION

CS

**FASTER WORK ORDER PRINT**

**WORK ORDER # 45486**  
**EQUIPMENT # 2976**

Date In: 03/19/2014 Date Out: 03/19/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,515
			M 28,187

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	12.00	62.00	-74.00	03/19/2014	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

03/19/2014 @ 13:32:48

GOODYEAR INV OF 1/13/14

REPLACED TWO TIRES

CS

**FASTER WORK ORDER PRINT**

**WORK ORDER # 45531**  
**EQUIPMENT # 2976**

Date In: 03/20/2014 Date Out: 03/20/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,515
			M 28,582

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	0.50	N	2	03/20/2014	2018NB0100BN	Wheel / Rim Nut Wheel Replace	30.00
SUBTOTAL:							30.00

WORK ORDER TOTALS	TOTAL:	30.00
-------------------	--------	-------

NOTES

03/20/2014 @ 14:35:20

1. LUG NUTS MISSING ON RIGHT REAR TIRE

1. Replaced lug nuts. #10

# FASTER WORK ORDER PRINT

## WORK ORDER # 45595 EQUIPMENT # 2976

Date In: 03/25/2014 Date Out: 03/25/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,515
			M 28,582

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	18.00	93.00	-111.00	03/25/2014	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00

SUBTOTAL: 0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/15/2014	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	19.00

SUBTOTAL: 19.00

WORK ORDER TOTALS	TOTAL:	19.00
-------------------	--------	-------

### NOTES

03/25/2014 @ 14:02:43

GOODYEAR INV OF 12/31/2013

REPLACED THREE TIRES

CS

**FASTER WORK ORDER PRINT**

**WORK ORDER # 45713**  
**EQUIPMENT # 2976**

Date In: 03/27/2014 Date Out: 03/27/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,515
			M 28,659

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	12.00	62.00	-74.00	03/27/2014	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

03/27/2014 @ 13:07:08

GOODYEAR INV OF 3/17/2014

REPLACED TWO TIRES

CS

# FASTER WORK ORDER PRINT

## WORK ORDER # 45801 EQUIPMENT # 2976

Date In: 03/27/2014 Date Out: 03/27/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,515
			M 28,659

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	03/27/2014	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/15/2014	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	19.00
SUBTOTAL:					19.00

WORK ORDER TOTALS	TOTAL:	19.00
-------------------	--------	-------

### NOTES

03/27/2014 @ 13:07:08

CAROLINA HEAVY DUTY INC INV OF 2/24/2014

LUBRICATION

CS

**FASTER WORK ORDER PRINT**

**WORK ORDER # 46199**  
**EQUIPMENT # 2976**

Date In: 04/30/2014 Date Out: 04/30/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,515
			M 29,954

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	12.00	62.00	-74.00	04/30/2014	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/30/2014	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	19.00
SUBTOTAL:					19.00
WORK ORDER TOTALS					TOTAL: 19.00

NOTES

04/30/2014 @ 13:09:18

WINGFOOT/GOODYEAR INV OF 1/30/2014

TIRE REPLACEMENT

CS

# FASTER WORK ORDER PRINT

## WORK ORDER # 46448 EQUIPMENT # 2976

Date In: 05/13/2014 Date Out: 05/13/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,515
			M 29,954

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	60.00	186.00	-246.00	05/13/2014	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00

SUBTOTAL: 0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/13/2014	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	19.00

SUBTOTAL: 19.00

WORK ORDER TOTALS TOTAL: 19.00

### NOTES

05/13/2014 @ 12:10:27

WINGFOOT/GOODYEAR INV OF 4/28/2014

TIRE REPLACE/TIRE BANK

CS



**FASTER WORK ORDER PRINT**

**WORK ORDER # 46595**  
**EQUIPMENT # 2976**

Date In: 05/15/2014 Date Out: 05/15/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,515
			M 29,954

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	05/15/2014	Z000001055NS	Unit Services Complete Unit Lubrication	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

05/15/2014 @ 13:02:47

CAROLINA HEAVY DUTY INC INV OF 3/24/2014

LUBRICATION

CS

**FASTER WORK ORDER PRINT**

**WORK ORDER # 46618**  
**EQUIPMENT # 2976**

Date In: 05/15/2014 Date Out: 05/15/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,515
			M 29,954

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	05/15/2014	Z000001055NS	Unit Services Complete Unit Lubrication	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

05/15/2014 @ 13:02:47

CAROLINA HEAVY DUTY INC INV OF 4/28/2014

LUBRICATION

CS

**FASTER WORK ORDER PRINT**

**WORK ORDER # 46947**  
**EQUIPMENT # 2976**

Date In: 06/04/2014 Date Out: 06/04/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,902
			M 32,195

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	1.00	N	2	06/04/2014	2065H58165BN	Hydraulic Syste Hose Hydraulic Repair	60.00
SUBTOTAL:							60.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
04U605-WH	S	3	6.44	06/05/2014	1000001000BS	Unit Services Complete Unit Part Issue	19.31
H42504-WH	S	4	5.01	06/05/2014	1000001000BS	Unit Services Complete Unit Part Issue	20.04
SUBTOTAL:							39.35

WORK ORDER TOTALS	TOTAL:	99.35
-------------------	--------	-------

NOTES

06/04/2014 @ 16:10:36

PASSENGER SIDE HOSE FROM FLIPPER TO OPERATE VALVE HAS LEAK AT BOTTOM. THE OPERATOR SAYS HE HAS DISCUSSED WITH YOU.

TT

1. Replaced HYD hose on flipper. #10

# FASTER WORK ORDER PRINT

## WORK ORDER # 47306 EQUIPMENT # 2976

Date In: 06/13/2014 Date Out: 06/16/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,902
			M 32,283

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	0.50	N	2	06/13/2014	1053000001BS	Expendable System Diagnosis	30.00
04	1.50	N	2	06/13/2014	PMA BS	PM A Service	90.00
04	2.50	N	2	06/13/2014	PMA BS	PM A Service	150.00
04	1.00	N	2	06/13/2014	1034LN5165BS	Light System Light Exterior Repair	60.00
04	0.50	N	2	06/16/2014	1034LN5165BS	Light System Light Exterior Repair	30.00
04	0.70	N	2	06/16/2014	PMI BS	Annual State In	42.00
04	0.50	N	2	06/16/2014	1053000001BS	Expendable System Diagnosis	30.00
04	2.00	N	2	06/16/2014	1036W31165BS	Warning Device Warning Reverse Repair	120.00
04	0.50	N	2	06/16/2014	1034LN5165BS	Light System Light Exterior Repair	30.00
SUBTOTAL:							582.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1748XD-FIL	S	1	39.26	06/16/2014	1000001000BS	Unit Services Complete Unit Part Issue	39.26
3604XE-FIL	S	1	32.98	06/16/2014	1000001000BS	Unit Services Complete Unit Part Issue	32.98
3936-FIL	S	1	18.56	06/16/2014	1000001000BS	Unit Services Complete Unit Part Issue	18.56
110-1BG	S	4	9.06	06/16/2014	1000001000BS	Unit Services Complete Unit Part Issue	36.22
9600-MAC	S	2	9.29	06/16/2014	1000001000BS	Unit Services Complete Unit Part Issue	18.59
15W40-90C	S	26	5.01	06/16/2014	1000001000BS	Unit Services Complete Unit Part Issue	130.26
SUBTOTAL:							275.87

WORK ORDER TOTALS TOTAL: 857.87

### NOTES

06/13/2014 @ 15:11:56

1. PM SERVICE
2. NCSI
3. Straighten bent rear step
4. Backup alarm and camera not not working
5. Running lights at top of packer body and check all

1. Performed PM. #04
2. NCSI Passed #04
3. Ordered new step. #04
4. Backup alarm works installed new camera cable. #04
5. ordered new running lights non in stock that i could find, others working properly. #04 wich step need to be order was not told or written down

# FASTER WORK ORDER PRINT

## WORK ORDER # 47554 EQUIPMENT # 2976

Date In: 06/20/2014 Date Out: 06/20/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,977
			M 33,011

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	0.50	N	2	06/20/2014	2036W31165BN	Warning Device Warning Reverse Repair	30.00
10	1.00	N	2	06/20/2014	2214000001BN	Compact Hopper System Diagnosis	60.00
10	1.00	N	2	06/20/2014	2034LN5165BN	Light System Light Exterior Repair	60.00
10	0.50	N	2	06/20/2014	2044F15100BN	Fuel System Filter Fuel Pri Replace	30.00
SUBTOTAL:							180.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
9600-MAC	S	2	9.29	06/23/2014	1000001000BS	Unit Services Complete Unit Part Issue	18.59
3604XE-FIL	S	1	32.98	06/23/2014	1000001000BS	Unit Services Complete Unit Part Issue	32.98
3936-FIL	S	1	18.56	06/23/2014	1000001000BS	Unit Services Complete Unit Part Issue	18.56
47123-GRO	S	1	11.35	06/23/2014	1000001000BS	Unit Services Complete Unit Part Issue	11.35
10700-LIT	S	1	1.35	06/23/2014	1000001000BS	Unit Services Complete Unit Part Issue	1.35
7301082-BK	S	1	120.24	06/27/2014	1000001000BS	Unit Services Complete Unit Part Issue	120.24
SUBTOTAL:							203.06

WORK ORDER TOTALS TOTAL: 383.06

### NOTES

06/20/2014 @ 15:08:59

1. Repair auot packing system
2. Repair body lights on packer
3. Repair backup alarm
4. Replace fuel filters

1. Replaced fuse for auto accel. #10
2. Replaced amber marker. #10
3. Backup alarm working at this time. #10
4. Replaced fuel filters. #10

# FASTER WORK ORDER PRINT

## WORK ORDER # 47795 EQUIPMENT # 2976

Date In: 06/26/2014 Date Out: 06/26/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 2,999
			M 33,272

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	0.50	N	2	06/26/2014	2212000001BN	Control Compact System Diagnosis	30.00
10	0.50	N	2	06/26/2014	2212000001BN	Control Compact System Diagnosis	30.00
10	1.00	N	2	06/26/2014	2036W31100BN	Warning Device Warning Reverse Replace	60.00
SUBTOTAL:							120.00
WORK ORDER TOTALS							TOTAL: 120.00

### NOTES

06/26/2014 @ 16:00:15

1. Auto packer not working
2. Replace backup alarm.

1. Replaced fuse. Incorrect fuse amperage used previously. Installed correct fuse. #10
2. Replaced alarm. #10

# FASTER WORK ORDER PRINT

## WORK ORDER # 47990 EQUIPMENT # 2976

Date In: 07/01/2014 Date Out: 07/02/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,010
			M 33,361

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	3.00	N	2	07/02/2014	2013AB2100BN	Brakes Adjuster Slack Replace	267.00
11	2.00	N	1	07/01/2014	2013000001BN	Brakes System Diagnosis	178.00
SUBTOTAL:							445.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
GG4726ES2G-MBI	S	1	110.73	07/03/2014	1000001000BS	Unit Services Complete Unit Part Issue	110.73
66854B-TWD	S	1	334.68	07/03/2014	1000001000BS	Unit Services Complete Unit Part Issue	334.68
R801042-TWD	S	2	122.39	07/03/2014	1000001000BS	Unit Services Complete Unit Part Issue	244.78
SUBTOTAL:							690.19

WORK ORDER TOTALS TOTAL: 1,135.19

### NOTES

07/01/2014 @ 13:58:17

1. UNIT WAS TOWED IN FOR NO BRAKES ON TRUCK BUT AIR PRESSURE IS UP

1. Found brake pedal sticking. Disassembled, found corrosion in pedal shaft. Cleaned and lubricated. Brakes are all out of adjustment. Right rear tandem slack adjuster reachet mechanism is broken, and left rear tandem brake shoes are worn out. Needs brake shoes and slack adjusters replaced on rear-most tandem axle. #11

07/01/2014 @ 16:22:52

1. Replaced slack adjusters on rear axle. Replaced left rear brake shoes and drum on rear axle. Right side shoes and drum still new. #10

# FASTER WORK ORDER PRINT

## WORK ORDER # 48047 EQUIPMENT # 2976

Date In: 07/08/2014 Date Out: 07/09/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,034
			M 33,590

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	1.50	N	2	07/08/2014	2214CLP001BN	Compact Hopper Control Hopper Diagnosis	133.50
04	0.50	N	2	07/08/2014	2214000001BN	Compact Hopper System Diagnosis	44.50
04	1.00	N	2	07/09/2014	2214000001BN	Compact Hopper System Diagnosis	89.00
11	1.00	N	2	07/09/2014	2051000001BN	Air Supply System Diagnosis	89.00
SUBTOTAL:							356.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
G311000402-GAT	S	1	3.43	07/09/2014	1000001000BS	Unit Services Complete Unit Part Issue	3.43
117284-AEC	S	1	89.04	07/09/2014	1000001000BS	Unit Services Complete Unit Part Issue	89.04
7821108-BK	S	5	0.57	07/15/2014	1000001000BS	Unit Services Complete Unit Part Issue	2.86
SUBTOTAL:							95.32

WORK ORDER TOTALS	TOTAL:	451.32
-------------------	--------	--------

### NOTES

07/08/2014 @ 16:11:30

1. AUTO PACKER NOT WORKING
2. TAILGATE AJAR NOT WORKING

1 replaced fuse. #04

2. Needs new proximity sensor for tailgate. #04

3. Needs new purge valve for air dryer. #04

Replaced purcge valve and governor fitting on yellow 1/4-inch hose. #11

07/09/2014 @ 09:33:49



**FASTER WORK ORDER PRINT**

**WORK ORDER # 48088**  
**EQUIPMENT # 2976**

Date In: 07/11/2014 Date Out: 07/11/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 33,741

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	1.50	N	2	07/11/2014	2214000001BN	Compact Hopper System Diagnosis	133.50
11	0.50	N	2	07/11/2014	2001000001BN	Air Conditionin System Diagnosis	44.50
11	1.50	N	2	07/11/2014	2214CP1001BN	Compact Hopper PACKER ROLLERS Diagnosis	133.50

SUBTOTAL: 311.50

WORK ORDER TOTALS TOTAL: 311.50

NOTES

07/11/2014 @ 14:43:24

1. THE AUTO PACK NOT WORKING
2. Tailgate adjar light on
3. Air vent on bottom right of dash ffell off

1. Actual write up states "Packer accel doesn't work again." Found Ignition 2 fuse in New Way control box failed. Traced power circuit (green/white) and found intermittent short to ground, repaired and replaced fuse. #11

07/11/2014 @ 19:23:23

2. Installed previously ordered tailgate warning proximity switch. #11  
07/11/2014 @ 17:02:31

3. Ordered replacement vent assembly. #11  
07/11/2014 @ 17:02:53

**FASTER WORK ORDER PRINT**

**WORK ORDER # 48226**  
**EQUIPMENT # 2976**

Date In: 07/17/2014 Date Out: 07/17/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 33,840

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	07/17/2014	Z000001055NS	Unit Services Complete Unit Lubrication	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

07/17/2014 @ 12:13:50

CAROLINA HEAVY DUTY INC INV OF 6/23/2014

LUBRICATION

CS

**FASTER WORK ORDER PRINT**

**WORK ORDER # 48278**  
**EQUIPMENT # 2976**

Date In: 07/18/2014 Date Out: 07/18/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 33,905

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
BARBOUR'S TOWING & RECOVERY	0.00	200.00	-200.00	07/18/2014	Z000001500NN	Unit Services Complete Unit Towing	0.00

SUBTOTAL: 0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	07/18/2014	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	19.00

SUBTOTAL: 19.00

WORK ORDER TOTALS TOTAL: 19.00

NOTES

07/18/2014 @ 12:29:17

BARBOUR'S TOWING INV OF 7/1/2014

TOWING

CS

**FASTER WORK ORDER PRINT**

**WORK ORDER # 48706**  
**EQUIPMENT # 2976**

Date In: 08/01/2014 Date Out: 08/01/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 34,504

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	08/01/2014	Z000001055NS	Unit Services Complete Unit Lubrication	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

08/01/2014 @ 13:37:25

CAROLINA HEAVY DUTY INC INV OF 7/28/2014

LUBRICATION

CS

**FASTER WORK ORDER PRINT**

**WORK ORDER # 48752**  
**EQUIPMENT # 2976**

Date In: 08/01/2014 Date Out: 08/05/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 34,587

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	0.50	N	2	08/01/2014	2214MH0100BN	Compact Hopper Misc Parts Replace	44.50

SUBTOTAL: 44.50

WORK ORDER TOTALS TOTAL: 44.50

NOTES

08/01/2014 @ 20:19:47

1. Install plug in hopper floor.

1. installed drain plug for hopper. #04

**FASTER WORK ORDER PRINT**

**WORK ORDER # 48876**  
**EQUIPMENT # 2976**

Date In: 08/07/2014 Date Out: 08/07/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 34,679

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	12.00	62.00	-74.00	08/07/2014	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

08/07/2014 @ 12:10:30

WINGFOOT/GOODYEAR INV OF 7/23/2014

HEAVY TIRE REPLACE/TIRE BANK

CS

**FASTER WORK ORDER PRINT**

**WORK ORDER # 49486**  
**EQUIPMENT # 2976**

Date In: 09/15/2014 Date Out: 09/15/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 36,457

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	09/15/2014	Z000001055NS	Unit Services Complete Unit Lubrication	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

09/15/2014 @ 12:48:23

CAROLINA HEAVY DUTY INC INV OF 8/25/2014

LUBRICATION

CS

**FASTER WORK ORDER PRINT**

**WORK ORDER # 49542**  
**EQUIPMENT # 2976**

Date In: 09/16/2014 Date Out: 09/16/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 36,541

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	12.00	62.00	-74.00	09/16/2014	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

09/16/2014 @ 12:23:16

WINGFOOT/GOODYEAR INV OF 8/21/2014

HEAVY TIRE REPLACE/TIRE BANK

CS



# FASTER WORK ORDER PRINT

## WORK ORDER # 49830 EQUIPMENT # 2976

Date In: 09/25/2014 Date Out: 09/25/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 36,936

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	24.00	124.00	-148.00	09/25/2014	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00

SUBTOTAL: 0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	09/25/2014	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	19.00

SUBTOTAL: 19.00

WORK ORDER TOTALS	TOTAL:	19.00
-------------------	--------	-------

### NOTES

09/25/2014 @ 12:43:30

WINGFOOT/GOODYEAR INV OF 9/16/2014

HEAVY TIRE REPLACE/TIRE BANK

CS

# FASTER WORK ORDER PRINT

## WORK ORDER # 50024 EQUIPMENT # 2976

Date In: 10/10/2014 Date Out: 10/10/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 37,655

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	0.50	N	2	10/10/2014	2011000001BN	Axle Front System Diagnosis	44.50
04	1.50	N	2	10/10/2014	2214FL1165BN	Compact Hopper FLIPPER ASSY. Repair	133.50
SUBTOTAL:							178.00
WORK ORDER TOTALS							TOTAL: 178.00

### NOTES

10/10/2014 @ 15:44:27

- Operator states right rear flipper leaking hyd fluid by handle area
- driver side hub seal low on fluid

- removed large fitting on side replaced Oring and retightened no leaks. #04
- refilled with gear oil was not very low but raised to proper level no evidence of leaks at this time. #04

# FASTER WORK ORDER PRINT

## WORK ORDER # 50088 EQUIPMENT # 2976

Date In: 10/14/2014 Date Out: 10/14/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 37,794

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	645.00	93.00	-738.00	10/14/2014	2017TM0100NN	Tire / Tube Tire Bus Replace	0.00
SUBTOTAL:							0.00

### MISCELANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	10/14/2014	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	19.00
SUBTOTAL:					19.00
WORK ORDER TOTALS					TOTAL: 19.00

### NOTES

WINGFOOT 9-12-14

3 TIRES, VSTEMS AND GATOR CAPS

# FASTER WORK ORDER PRINT

## WORK ORDER # 50092 EQUIPMENT # 2976

Date In: 10/14/2014 Date Out: 10/14/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 37,794

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	12.00	62.00	-74.00	10/14/2014	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00

SUBTOTAL: 0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	10/14/2014	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	19.00

SUBTOTAL: 19.00

WORK ORDER TOTALS TOTAL: 19.00

### NOTES

WINGFOOT 9-29-14

YARD SERV  
2 VSTEMS  
2 GATOR CAPS

# FASTER WORK ORDER PRINT

## WORK ORDER # 50981 EQUIPMENT # 2976

Date In: 12/10/2014 Date Out: 12/16/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 39,052

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	4.00	N	2	12/11/2014	PMA BS	PM A Service	356.00
04	2.50	N	2	12/16/2014	1022F92100BS	Axle Rear Drive Flange Axle Rea Replace	222.50
10	2.50	N	2	12/16/2014	2013SC2100BN	Brakes Shoe/LiningA-Br Replace	222.50
SUBTOTAL:							801.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1748-FIL	S	1	36.68	12/10/2014	1000001000BS	Unit Services Complete Unit Part Issue	36.68
3604XE-FIL	S	1	32.98	12/10/2014	1000001000BS	Unit Services Complete Unit Part Issue	32.98
3936-FIL	S	1	18.56	12/10/2014	1000001000BS	Unit Services Complete Unit Part Issue	18.56
9600-MAC	S	2	9.29	12/10/2014	1000001000BS	Unit Services Complete Unit Part Issue	18.59
110-1BG	S	4	9.06	12/10/2014	1000001000BS	Unit Services Complete Unit Part Issue	36.22
15W40-9OC	S	26	5.36	12/10/2014	1000001000BS	Unit Services Complete Unit Part Issue	139.23
GG4726ES2G-MBI	S	2	110.73	12/17/2014	1000001000BS	Unit Services Complete Unit Part Issue	221.46
66854B-TWD	S	2	336.81	12/17/2014	1000001000BS	Unit Services Complete Unit Part Issue	673.61
370003A-NTL	S	2	48.90	12/17/2014	1000001000BS	Unit Services Complete Unit Part Issue	97.79
3303107-TWD	S	1	2.43	12/17/2014	1000001000BS	Unit Services Complete Unit Part Issue	2.43
SUBTOTAL:							1,277.55

WORK ORDER TOTALS	TOTAL:	2,078.55
-------------------	--------	----------

### NOTES

12/10/2014 @ 14:51:25

1. PM SERVICE

2. FLANGE GASKET ON REAR WHEEL IS LEAKING

1. Performed PM. #04

2. inside hub seal leaking. #04 Replaced both rear brakes and assisted #10 in replacing hub seal. #04

# FASTER WORK ORDER PRINT

## WORK ORDER # 51098 EQUIPMENT # 2976

Date In: 12/17/2014 Date Out: 12/17/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 39,052

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	1.00	N	2	12/17/2014	2013000040BN	Brakes System Adjust	89.00
SUBTOTAL:							89.00

WORK ORDER TOTALS	TOTAL:	89.00
-------------------	--------	-------

### NOTES

12/17/2014 @ 19:03:25

1. Adjust brakes.

1. Operator thought the hub seal was leaking again. Checked seal it is not leaking. Adjusted brakes. Operator could have been smelling residual oil left from previous repair. #10

**FASTER WORK ORDER PRINT**

**WORK ORDER # 51243**  
**EQUIPMENT # 2976**

Date In: 12/30/2014 Date Out: 12/30/2014 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,637 A
			M 39,874

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
35	0.70	N	2	12/30/2014	PML BS	LUBRICATION	62.30
SUBTOTAL:							62.30

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
TRANSYNQT-1BG	S	5	8.09	12/31/2014	1000001000BS	Unit Services Complete Unit Part Issue	40.46
SUBTOTAL:							40.46

WORK ORDER TOTALS	TOTAL:	102.76
-------------------	--------	--------

NOTES

12/30/2014 @ 15:57:23  
1. SCHEDULED LUBE  
12/30/2014 @ 19:09:40 Lubed truck Wingfoot changed a tire

## FASTER WORK ORDER PRINT

DATE: 04/24/2021 14:37

**WORK ORDER # 51658**  
**EQUIPMENT # 2976**

Date In: 01/28/2015    Date Out: 01/28/2015    Work Order Status: C    Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 40,822

## TECHNICIAN REPAIRS PERFORMED

TECH	OVER			LABOR		LABOR	
ID	HOURS	TIME	SHIFT	END DATE	REPAIR TYPE	RTY DESCRIPTION	COST
72	0.70	N	2	01/28/2015	PML BS	LUBRICATION	62.30

SUBTOTAL:	62.30
-----------	-------

WORK ORDER TOTALS	TOTAL:	62.30
-------------------	--------	-------

## NOTES

01/28/2015 @ 15:52:00

### 1. Lubrication.

**1. Lube complete.**



**FASTER WORK ORDER PRINT**

**WORK ORDER # 52057**  
**EQUIPMENT # 2976**

Date In: 02/16/2015   Date Out: 02/16/2015   Work Order Status: C   Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H                      3,049
			M                      40,822

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	0.50	N	2	02/16/2015	2247SP6165BN	SNOW PLOW PLOW FRAME Repair	44.50
SUBTOTAL:							44.50

WORK ORDER TOTALS	TOTAL:	44.50
-------------------	--------	-------

NOTES

02/16/2015 @ 12:32:43

PROPERLY INSTALL PLOW GUIDES

TT

Installed plow guide sticks. #11  
02/16/2015 @ 12:57:37

**FASTER WORK ORDER PRINT**

**WORK ORDER # 52218**  
**EQUIPMENT # 2976**

Date In: 02/21/2015   Date Out: 02/21/2015   Work Order Status: C   Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H                      3,049
			M                      41,295

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
72	0.70	N	2	02/21/2015	PML BS	LUBRICATION	62.30
SUBTOTAL:							62.30

WORK ORDER TOTALS	TOTAL:	62.30
-------------------	--------	-------

NOTES

02/21/2015 @ 14:23:09

LUBRICATION

TT

1. Lube Completed # 72

**FASTER WORK ORDER PRINT**

**WORK ORDER # 52777**  
**EQUIPMENT # 2976**

Date In: 03/25/2015   Date Out: 03/25/2015   Work Order Status: C   Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H                      3,049
			M                      41,530

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	0.70	N	2	03/25/2015	PML BS	LUBRICATION	62.30

SUBTOTAL: 62.30

WORK ORDER TOTALS TOTAL: 62.30

NOTES

03/25/2015 @ 18:11:01

1. Scheduled lube.

Lube Complete. #04

**FASTER WORK ORDER PRINT**

**WORK ORDER # 53039**  
**EQUIPMENT # 2976**

Date In: 04/13/2015 Date Out: 05/06/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,007 A
			M 42,930

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	1.00	N	1	04/13/2015	2003LN9001BN	Gauge Instro LightCheckEngin Diagnosis	89.00
SUBTOTAL:							89.00

PARTS ISSUED

PART NUMBER/ DESCRIPTIION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
4056-FIL	S	1	5.76	04/14/2015	1000001000BS	Unit Services Complete Unit Part Issue	5.76
SUBTOTAL:							5.76

WORK ORDER TOTALS	TOTAL:	94.76
-------------------	--------	-------

NOTES

04/13/2015 @ 08:18:07

1. CHECK ENGINE LIGHT ON

1. Coolant level sensor failed, replaced. #11

04/13/2015 @ 09:32:27

Sent to Amick Eq. for body damage repairs to L/S rear roller track.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 53239**  
**EQUIPMENT # 2976**

Date In: 04/23/2015 Date Out: 04/23/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 42,930

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	41.09	0.00	-41.09	04/23/2015	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/23/2015	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	19.00
SUBTOTAL:					19.00
WORK ORDER TOTALS					TOTAL: 19.00

NOTES

04/23/2015 @ 12:40:00

GOOD YEAR  
12/31/14  
DD

**FASTER WORK ORDER PRINT**

**WORK ORDER # 53258  
EQUIPMENT # 2976**

Date In: 04/23/2015 Date Out: 04/23/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 42,930

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	872.15	0.00	-872.15	04/23/2015	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/23/2015	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	19.00
SUBTOTAL:					19.00

WORK ORDER TOTALS	TOTAL:	19.00
-------------------	--------	-------

NOTES

04/23/2015 @ 13:33:05

GOOD YEAR  
02/25/15  
DD

**FASTER WORK ORDER PRINT**

**WORK ORDER # 53486**  
**EQUIPMENT # 2976**

Date In: 05/04/2015 Date Out: 05/04/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 42,930

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	1.50	N	2	05/04/2015	1003LN9001BS	Gauge Instro LightCheckEngin Diagnosis	133.50
04	0.70	N	2	05/04/2015	PML BS	LUBRICATION	62.30
SUBTOTAL:							195.80

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
3604XE-FIL	S	1	32.98	05/05/2015	1000001000BS	Unit Services Complete Unit Part Issue	32.98
3936-FIL	S	1	18.56	05/05/2015	1000001000BS	Unit Services Complete Unit Part Issue	18.56
9600-MAC	S	3	9.29	05/05/2015	1000001000BS	Unit Services Complete Unit Part Issue	27.88
SUBTOTAL:							79.42

WORK ORDER TOTALS	TOTAL:	275.22
-------------------	--------	--------

NOTES

05/04/2015 @ 18:22:56

1. Check engine light is on.
2. Scheduled lube.

Code for coolant and fuel filters replaced fuel filters and topped off coolant cleared codes . #04

Lube Complete. #04

# FASTER WORK ORDER PRINT

## WORK ORDER # 53624 EQUIPMENT # 2976

Date In: 05/07/2015 Date Out: 05/07/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 42,930

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	41.09	0.00	-41.09	05/07/2015	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00

SUBTOTAL: 0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/07/2015	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	19.00

SUBTOTAL: 19.00

WORK ORDER TOTALS	TOTAL:	19.00
-------------------	--------	-------

### NOTES

05/07/2015 @ 12:54:03

GOODYEAR  
12/31/15

DD



**FASTER WORK ORDER PRINT**

**WORK ORDER # 53770**  
**EQUIPMENT # 2976**

Date In: 05/14/2015 Date Out: 05/14/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 43,389

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	47.49	0.00	-47.49	05/14/2015	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/14/2015	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	19.00
SUBTOTAL:					19.00
WORK ORDER TOTALS					TOTAL: 19.00

NOTES

05/14/2015 @ 11:34:09

GOODYEAR  
2/2/15

DD

# FASTER WORK ORDER PRINT

## WORK ORDER # 53855 EQUIPMENT # 2976

Date In: 05/18/2015 Date Out: 05/19/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 43,472

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	1.50	N	2	05/18/2015	1012001100BS	Axle Rear HUB SEAL Replace	133.50
04	1.00	N	2	05/18/2015	1012001100BS	Axle Rear HUB SEAL Replace	89.00
04	2.00	N	2	05/18/2015	1013DT0100BS	Brakes Drum Air Brake Replace	178.00
19	4.00	N	1	05/18/2015	PMB BS	PM B Service	356.00
19	2.00	N	1	05/18/2015	PMB BS	PM B Service	178.00
19	0.50	N	1	05/18/2015	1034B60100BS	Light System Bulb Headlight Replace	44.50
19	0.50	N	1	05/18/2015	1054HP1165BS	Horn Horn Air Repair	44.50
19	1.50	N	1	05/18/2015	1001A09325BS	Air Conditionin RECHARGE Evacuate/Charge	133.50
SUBTOTAL:							1,157.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTIION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
110-1BG	S	4	9.76	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	39.03
15W40-9OC	S	26	5.77	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	150.07
1748XD-FIL	S	1	39.26	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	39.26
3604XE-FIL	S	1	32.98	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	32.98
3936-FIL	S	1	18.56	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	18.56
9600-MAC	S	2	9.29	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	18.59
7740XE-FIL	S	1	70.45	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	70.45
TRANSYNQT-1BG	S	32	8.09	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	258.94
H6054-LMP	S	1	10.62	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	10.62
7702402-BK	S	1	9.64	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	9.64
3303107-TWD	S	1	2.45	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	2.45
370003A-NTL	S	1	48.90	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	48.90
66854B-TWD	S	2	336.81	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	673.61
GG4726ES2G-MBI	S	2	113.43	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	226.86
MINUS20-WWS	S	1	2.56	05/18/2015	1000001000BS	Unit Services Complete Unit Part Issue	2.56
R134AOZ-90C	S	5	2.14	05/19/2015	1000001000BS	Unit Services Complete Unit Part Issue	10.71

**FASTER WORK ORDER PRINT**

**WORK ORDER # 53855**  
**EQUIPMENT # 2976**

	SUBTOTAL:	1,613.23
<hr/>		
WORK ORDER TOTALS	TOTAL:	2,770.23
<hr/>		

NOTES

05/18/2015 @ 07:45:24

1. PM B SERVICE
2. PASSANGER SIDE HEADLIGHT NOT WORKING
3. AIR HORN NOT WORKING
4. A/C NEEDS RECHARGED

Performed PMB service #19, Mike welded broken lower radiator pipe bracket.

Replaced passenger side headlamp #19.

Removed dash panel and checked operation of switch, Austin saw ground wire to horn solenoid was unplugged, re-connected and tightened connection, air horn now works properly #19.

Gauges showed refrigerant level being slightly low, (added .5 lbs of refrigerant). A/C blows cold as it should found that air wasn't blowing hard out of vents, replaced cabin filter #19.

Replaced tandem passenger inner hub seal and replaced passenger side brakes they were only 2 months old and looked brand new #04

**FASTER WORK ORDER PRINT**

**WORK ORDER # 54141**  
**EQUIPMENT # 2976**

Date In: 05/28/2015 Date Out: 05/28/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 43,909

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	0.70	N	2	05/28/2015	PML BS	LUBRICATION	62.30
SUBTOTAL:							62.30

WORK ORDER TOTALS	TOTAL:	62.30
-------------------	--------	-------

NOTES

05/28/2015 @ 19:36:07

1. Scheduled lube.

1. Lube complete. #10

**FASTER WORK ORDER PRINT**

**WORK ORDER # 54416**  
**EQUIPMENT # 2976**

Date In: 06/11/2015 Date Out: 06/11/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 44,574

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	06/11/2015	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
CAROLINA HEAVY DUTY TRK & TRL	0.00	38.00	-38.00	06/11/2015	Z000001055NS	Unit Services Complete Unit Lubrication	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

06/11/2015 @ 11:44:50

CAROLINA HEAVY DUTY TRUCK 10-28-14

LUBRICATION

TT

06/15/2015 @ 14:17:03

CAROLINA HEAVY DUTY TRUCK 10-1-14

TT

# FASTER WORK ORDER PRINT

## WORK ORDER # 54449 EQUIPMENT # 2976

Date In: 06/12/2015 Date Out: 06/12/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 44,574

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	0.50	N	2	06/12/2015	2214000001BN	Compact Hopper System Diagnosis	44.50
10	0.50	N	2	06/12/2015	2034LN5165BN	Light System Light Exterior Repair	44.50
10	1.00	N	2	06/12/2015	2065F23001BN	Hydraulic Syste Fitting Hydraul Diagnosis	89.00
10	1.00	N	2	06/12/2015	2102LN8165BN	Light Emergency Light Strobe Repair	89.00
10	1.00	N	2	06/12/2015	2214000001BN	Compact Hopper System Diagnosis	89.00
SUBTOTAL:							356.00

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	42.00	225.22	-267.22	06/12/2015	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTIION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
10700-LIT	S	2	1.35	06/15/2015	1000001000BS	Unit Services Complete Unit Part Issue	2.69
47123-GRO	S	2	11.56	06/15/2015	1000001000BS	Unit Services Complete Unit Part Issue	23.11
85601-GAT	S	6	4.84	06/15/2015	1000001000BS	Unit Services Complete Unit Part Issue	29.06
G251700606-GAT	S	2	6.37	06/15/2015	1000001000BS	Unit Services Complete Unit Part Issue	12.73
200SD-9EM	S	1	130.63	06/15/2015	1000001000BS	Unit Services Complete Unit Part Issue	130.63
7821108-BK	S	5	0.61	06/15/2015	1000001000BS	Unit Services Complete Unit Part Issue	3.04
AW46BO-9OC	S	39	6.00	06/15/2015	1000001000BS	Unit Services Complete Unit Part Issue	233.92
SUBTOTAL:							435.18

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	06/16/2015	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	19.00
SUBTOTAL:					19.00

**FASTER WORK ORDER PRINT**

**WORK ORDER # 54449**  
**EQUIPMENT # 2976**

---

WORK ORDER TOTALS	TOTAL:	810.18
-------------------	--------	--------

---

NOTES

06/12/2015 @ 15:36:23

1. Hyd leak passanger side rear when packing
2. Tailgate adjar light stays on
3. Rear strobe light not working
4. Running light on front of packer body is out

1. Replaced blown hose on flipper. #10

2. Proxy switch was loose in housing. Tightened switch, light still not going off. found wiring damaged on top of truck. Pins pulled from connector and no poewer top any pins. Found 10amp fuse blown in body PDC. Replaced fuse and rewired proxy switch. Light is off. #10

3. Replaced strobe light

4. Replaced two amber markers on body. #10

06/16/2015 @ 13:47:19

WINGFOOT 6-1-15

CAP/V STEM

TT

**FASTER WORK ORDER PRINT**

**WORK ORDER # 54628**  
**EQUIPMENT # 2976**

Date In: 06/19/2015 Date Out: 06/19/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 44,947

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	0.70	N	2	06/19/2015	PML BS	LUBRICATION	62.30
SUBTOTAL:							62.30

WORK ORDER TOTALS	TOTAL:	62.30
-------------------	--------	-------

NOTES

06/19/2015 @ 19:50:29

1. Scheduled lube.

1. Lube complete. #10



**FASTER WORK ORDER PRINT**

**WORK ORDER # 54704**  
**EQUIPMENT # 2976**

Date In: 06/24/2015 Date Out: 06/24/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 45,102

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
AMICK EQUIPMENT	2,538.19	4,642.20	-7,180.39	06/24/2015	Z214CP1165NN	Compact Hopper PACKER ROLLERS Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	06/24/2015	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	19.00
SUBTOTAL:					19.00

WORK ORDER TOTALS	TOTAL:	19.00
-------------------	--------	-------

NOTES

06/24/2015 @ 13:24:23

AMICK 5-6-15

SLIDE ASSY

TT

**FASTER WORK ORDER PRINT**

**WORK ORDER # 55095**  
**EQUIPMENT # 2976**

Date In: 07/17/2015   Date Out: 07/17/2015   Work Order Status: C   Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H                      3,049
			M                      46,010

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	0.50	N	2	07/17/2015	2007ME0T01BN	Glass-Component Mirror TIGHTEN	44.50
SUBTOTAL:							44.50

WORK ORDER TOTALS	TOTAL:	44.50
-------------------	--------	-------

NOTES

07/17/2015 @ 07:37:49  
1. Operator states left mirror is loose.  
MC

1. Tighted mirror. #11  
07/17/2015 @ 13:09:38

**FASTER WORK ORDER PRINT**

**WORK ORDER # 55199**  
**EQUIPMENT # 2976**

Date In: 07/23/2015 Date Out: 07/23/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 46,317

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	0.70	N	2	07/23/2015	PML BS	LUBRICATION	62.30
SUBTOTAL:							62.30

WORK ORDER TOTALS	TOTAL:	62.30
-------------------	--------	-------

NOTES

07/23/2015 @ 21:00:09

1. Scheduled lube.

No Key available. #04

**FASTER WORK ORDER PRINT**

**WORK ORDER # 55482**  
**EQUIPMENT # 2976**

Date In: 08/17/2015 Date Out: 08/17/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 46,731

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
35	0.70	N	2	08/17/2015	PML BS	LUBRICATION	62.30
SUBTOTAL:							62.30

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	12.14	62.00	-74.14	08/17/2015	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	08/31/2015	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	87.30
-------------------	--------	-------

NOTES

08/17/2015 @ 15:46:39  
1. SCHEDULED LUBE  
08/17/2015 @ 23:02:39 lube done

08/31/2015 @ 11:00:48

WINGFOOT 7-16-15

YARD SVC

TT

# FASTER WORK ORDER PRINT

## WORK ORDER # 55676 EQUIPMENT # 2976

Date In: 08/28/2015 Date Out: 08/31/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 47,368

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
19	2.00	N	1	08/31/2015	1013SC2100BS	Brakes Shoe/LiningA-Br Replace	178.00
19	2.00	N	1	08/31/2015	1013SC2100BS	Brakes Shoe/LiningA-Br Replace	178.00
23	2.00	N	1	08/28/2015	PMA BS	PM A Service	178.00
35	0.50	N	2	08/28/2015	PMA BS	PM A Service	44.50
35	1.50	N	2	08/28/2015	PMA BS	PM A Service	133.50
SUBTOTAL:							712.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1748-FIL	S	1	37.60	08/31/2015	1000001000BS	Unit Services Complete Unit Part Issue	37.60
3604XE-FIL	S	1	33.81	08/31/2015	1000001000BS	Unit Services Complete Unit Part Issue	33.81
3936-FIL	S	1	19.03	08/31/2015	1000001000BS	Unit Services Complete Unit Part Issue	19.03
110-1BG	S	4	10.00	08/31/2015	1000001000BS	Unit Services Complete Unit Part Issue	40.02
9600-MAC	S	2	9.53	08/31/2015	1000001000BS	Unit Services Complete Unit Part Issue	19.06
15W40-9OC	S	26	5.92	08/31/2015	1000001000BS	Unit Services Complete Unit Part Issue	153.84
66854B-TWD	S	2	327.19	08/31/2015	1000001000BS	Unit Services Complete Unit Part Issue	654.38
GG4726ES2G-MBI	S	2	116.29	08/31/2015	1000001000BS	Unit Services Complete Unit Part Issue	232.58
SUBTOTAL:							1,190.32

WORK ORDER TOTALS	TOTAL:	1,902.32
-------------------	--------	----------

### NOTES

08/28/2015 @ 15:55:10

1. PM SERVICE

08/28/2015 @ 22:13:16 #23 #35 Pm Done Needs FRont Tandem Brakes and tires

Replaced front tandem brakes, had trouble with passenger side dragging and not adjusting properly but drove and re-adjusted. Now brakes are adjusted and working as they should #19.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 55916**  
**EQUIPMENT # 2976**

Date In: 09/16/2015 Date Out: 09/18/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 47,640

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
13	0.50	N	1	09/16/2015	2017TM1165BN	Tire / Tube Tire Heavy Repair	44.50
23	0.70	N	1	09/18/2015	PML BS	LUBRICATION	62.30
SUBTOTAL:							106.80

WORK ORDER TOTALS	TOTAL:	106.80
-------------------	--------	--------

NOTES

09/16/2015 @ 10:15:19

TIGHTEN LUG NUTS

TT

1. wingfoot needs to come replace wheels and tires #13  
09/16/2015 @ 15:24:15

09/17/2015 @ 16:19:15

WINGFOOT HAS COMPLETED ABOVE

09/17/2015 @ 16:17:23

SCHEDULED LUBE

TT

09/18/2015 @ 16:18:58  
pm done#23

# FASTER WORK ORDER PRINT

## WORK ORDER # 56164 EQUIPMENT # 2976

Date In: 09/29/2015 Date Out: 09/29/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 48,371

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	30.00	163.22	-193.22	09/29/2015	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	09/29/2015	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00
WORK ORDER TOTALS					TOTAL: 25.00

### NOTES

09/29/2015 @ 12:33:32

WINGFOOT 9-1-15

YARD SVC

TT

**FASTER WORK ORDER PRINT**

**WORK ORDER # 56393**  
**EQUIPMENT # 2976**

Date In: 10/12/2015 Date Out: 10/16/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 48,786

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
23	0.70	N	1	10/12/2015	PML BS	LUBRICATION	62.30
SUBTOTAL:							62.30

WORK ORDER TOTALS	TOTAL:	62.30
-------------------	--------	-------

NOTES

10/12/2015 @ 15:44:58  
1. SCHEDULED LUBE

10/12/2015 @ 19:54:04  
could not locate keys #23



# FASTER WORK ORDER PRINT

## WORK ORDER # 56685 EQUIPMENT # 2976

Date In: 10/28/2015 Date Out: 10/28/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 49,355

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	2.00	N	2	10/28/2015	2247SP4001BN	SNOW PLOW PLOW CONTROL Diagnosis	178.00
SUBTOTAL:							178.00

WORK ORDER TOTALS	TOTAL:	178.00
-------------------	--------	--------

### NOTES

10/28/2015 @ 10:17:21  
1. PLOW WILL NOT TURN RIGHT

1. Right left switch failed, replaced. #11  
10/28/2015 @ 15:10:56

10/29/2015 @ 13:30:14

WINGFOOT 10-22-15

YARD SVC

TT

# FASTER WORK ORDER PRINT

## WORK ORDER # 56944 EQUIPMENT # 2976

Date In: 11/12/2015 Date Out: 11/13/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 3,049
			M 49,783

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	0.70	N	2	11/12/2015	PML BS	LUBRICATION	62.30
SUBTOTAL:							62.30

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	6.00	39.22	-45.22	11/13/2015	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	11/30/2015	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	87.30
-------------------	--------	-------

### NOTES

11/12/2015 @ 19:11:59  
Scheduled Lube.

Lube Complete. #04

11/30/2015 @ 14:23:00

WINGFOOT 11-3-15

YARD SVC

TT

**FASTER WORK ORDER PRINT**

**WORK ORDER # 57289  
EQUIPMENT # 2976**

Date In: 12/07/2015 Date Out: 12/07/2015 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913 Y
			M 50,701

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	0.50	N	2	12/07/2015	2065F16001BN	Hydraulic Syste Filter Hydraul Diagnosis	44.50
11	1.00	N	2	12/07/2015	2034LN5165BN	Light System Light Exterior Repair	89.00
11	0.50	N	2	12/07/2015	2065F23T01BN	Hydraulic Syste Fitting Hydraul TIGHTEN	44.50
11	0.70	N	2	12/07/2015	PML BS	LUBRICATION	62.30
SUBTOTAL:							240.30

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	6.00	39.22	-45.22	12/07/2015	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	12/30/2015	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	265.30
-------------------	--------	--------

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 57289**  
**EQUIPMENT # 2976**

12/07/2015 @ 12:40:49

1. PLOW LIGHTS NEED REPAIRED
2. HYD FILTER LEAKING AT TOP
3. FITTING LEAKING ON PASSANGER REAR FLIPER
4. SCHEDULED LUBE

1. Repaired right plow light. #11

12/07/2015 @ 14:54:11

2. Ordered hydraulic filter mount. #11

12/07/2015 @ 14:53:27

3. Cleaned vlave and tested, tightened all fittings. #11

12/07/2015 @ 15:43:31

4. Scheduled lube complete. #11

12/07/2015 @ 15:43:52

12/30/2015 @ 19:39:27

WINGFOOT 11-17-15

YARD SVC

TT

# FASTER WORK ORDER PRINT

## WORK ORDER # 57615 EQUIPMENT # 2976

Date In: 01/04/2016 Date Out: 01/07/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 51,347

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	2.00	N	2	01/04/2016	PMA BS	PM A Service	178.00
64	0.70	N	2	01/04/2016	PML BS	LUBRICATION	62.30
SUBTOTAL:							240.30

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
CV50628-9HD	S	1	117.69	01/05/2016	1000001000BS	Unit Services Complete Unit Part Issue	117.69
SUBTOTAL:							117.69

WORK ORDER TOTALS	TOTAL:	357.99
-------------------	--------	--------

### NOTES

01/04/2016 @ 14:23:00  
1. SCHEDULED LUBE  
2. PM D SERVICE

lube and pm d service complete #64

# FASTER WORK ORDER PRINT

## WORK ORDER # 57812 EQUIPMENT # 2976

Date In: 01/19/2016 Date Out: 01/19/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 51,347

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
19	1.50	N	1	01/19/2016	2032000001BN	Cranking System System Diagnosis	133.50
24	1.50	N	1	01/19/2016	2032000001BN	Cranking System System Diagnosis	133.50
SUBTOTAL:							267.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
3604-FIL	S	1	30.22	01/19/2016	1000001000BS	Unit Services Complete Unit Part Issue	30.22
3936-FIL	S	1	19.42	01/19/2016	1000001000BS	Unit Services Complete Unit Part Issue	19.42
9600-MAC	S	2	7.31	01/19/2016	1000001000BS	Unit Services Complete Unit Part Issue	14.62
SUBTOTAL:							64.26

WORK ORDER TOTALS	TOTAL:	331.26
-------------------	--------	--------

### NOTES

**01/19/2016 @ 09:10:16**

**1. UNIT WILL NOT START**

Charles and I jump started and had to use either to move truck over to fleet. Replaced both fuel filters #19, #24.

# FASTER WORK ORDER PRINT

## WORK ORDER # 58135 EQUIPMENT # 2976

Date In: 01/28/2016 Date Out: 01/28/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 52,483

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	12.00	62.00	-74.00	01/28/2016	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	01/28/2016	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00
WORK ORDER TOTALS					TOTAL: 25.00

### NOTES

01/28/2016 @ 19:27:44

WINGFOOT 1-5-16

YARD SVC

TT

**FASTER WORK ORDER PRINT**

**WORK ORDER # 58167**  
**EQUIPMENT # 2976**

Date In: 02/01/2016 Date Out: 02/02/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 52,577

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	0.70	N	2	02/01/2016	PML BS	LUBRICATION	62.30
SUBTOTAL:							62.30

WORK ORDER TOTALS	TOTAL:	62.30
-------------------	--------	-------

NOTES

02/01/2016 @ 15:42:33  
1. SCHEDULED LUBE

lube complete #64



**FASTER WORK ORDER PRINT**

**WORK ORDER # 58507  
EQUIPMENT # 2976**

Date In: 02/19/2016 Date Out: 02/19/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 52,577

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	0.50	N	2	02/19/2016	2065F23T01BN	Hydraulic Syste Fitting Hydraul TIGHTEN	44.50
04	0.50	N	2	02/19/2016	2034LN5100BN	Light System Light Exterior Replace	44.50
SUBTOTAL:							89.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
101724-NCB	S	1	35.45	02/22/2016	1000001000BS	Unit Services Complete Unit Part Issue	35.45
1157-LMP	S	1	0.98	02/22/2016	1000001000BS	Unit Services Complete Unit Part Issue	0.98
SUBTOTAL:							36.43

WORK ORDER TOTALS	TOTAL:	125.43
-------------------	--------	--------

NOTES

02/19/2016 @ 21:58:53

Plow light marker out.

Filter housing is leaking hyd fluid.

Replaced blown bulb. #04

Removed return lines going into filter housing on tanke then removed housing and applied thread tape to pipe fitting and reinstalled housing and replaced lines verified no leaks on system after running hydraulics. #04

**FASTER WORK ORDER PRINT**

**WORK ORDER # 58627**  
**EQUIPMENT # 2976**

Date In: 03/01/2016 Date Out: 03/07/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 53,356

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	0.70	N	2	03/01/2016	PML BS	LUBRICATION	62.30

SUBTOTAL: 62.30

WORK ORDER TOTALS

TOTAL: 62.30

NOTES

03/01/2016 @ 14:37:55  
1. SCHEDULED LUBE

lube complete #64

**FASTER WORK ORDER PRINT**

**WORK ORDER # 59026  
EQUIPMENT # 2976**

Date In: 03/28/2016 Date Out: 03/29/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 54,098

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	0.70	N	2	03/28/2016	PML BS	LUBRICATION	62.30

SUBTOTAL: 62.30

WORK ORDER TOTALS TOTAL: 62.30

NOTES

03/28/2016 @ 14:11:19  
1. SCHEDULED LUBE

lube complete #64

Noticed that the side step ladder was cracked and pin that holds ladder in place was broken off.#64  
Repaired by welding the side step ladder and pin #64

**FASTER WORK ORDER PRINT**

**WORK ORDER # 59128**  
**EQUIPMENT # 2976**

Date In: 03/30/2016 Date Out: 03/30/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 54,098

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	12.00	124.00	-136.00	03/30/2016	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	03/30/2016	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	25.00
-------------------	--------	-------

NOTES

03/30/2016 @ 13:42:12  
.  
WINGFOOT 3-15-16  
YARD SVC  
TT

# FASTER WORK ORDER PRINT

## WORK ORDER # 59352 EQUIPMENT # 2976

Date In: 04/12/2016 Date Out: 04/13/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 5,423 A
			M 54,813

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	2.00	N	2	04/12/2016	2013SC2100BN	Brakes Shoe/LiningA-Br Replace	178.00
11	3.50	N	2	04/12/2016	2013SC2100BN	Brakes Shoe/LiningA-Br Replace	311.50
11	1.50	N	2	04/13/2016	2013SC2100BN	Brakes Shoe/LiningA-Br Replace	133.50
11	1.00	N	2	04/13/2016	2022S1E100BN	Axle Rear Drive Seal Grease Rea Replace	89.00
SUBTOTAL:							712.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
GG4726ES2G-MBI	S	4	116.29	04/12/2016	1000001000BS	Unit Services Complete Unit Part Issue	465.16
66854B-TWD	S	4	327.24	04/12/2016	1000001000BS	Unit Services Complete Unit Part Issue	1,308.96
370003A-NTL	S	2	51.01	04/12/2016	1000001000BS	Unit Services Complete Unit Part Issue	102.02
3303107-TWD	S	2	2.56	04/12/2016	1000001000BS	Unit Services Complete Unit Part Issue	5.12
SUBTOTAL:							1,881.26

WORK ORDER TOTALS	TOTAL:	2,593.26
-------------------	--------	----------

### NOTES

04/12/2016 @ 09:36:36

1. Operator states brakes not working or holding on hill

1. Replaced 3 of the 4 tandem axle brakes. #11

04/12/2016 @ 16:01:46

Replaced 4th brake. Adjusted brakes. #11

04/13/2016 @ 09:10:12

2. Replaced leaking inner axle seals on both right side tandem axle wheel ends. #11

04/13/2016 @ 09:11:18

# FASTER WORK ORDER PRINT

## WORK ORDER # 59422 EQUIPMENT # 2976

Date In: 04/13/2016 Date Out: 04/13/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 5,423 A
			M 54,813

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
35	1.50	N	2	04/13/2016	PMD BS	PM D Service	133.50
SUBTOTAL:							133.50

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
CV50628-9HD	S	1	142.39	04/14/2016	1000001000BS	Unit Services Complete Unit Part Issue	142.39
SUBTOTAL:							142.39

WORK ORDER TOTALS	TOTAL:	275.89
-------------------	--------	--------

### NOTES

04/13/2016 @ 15:47:08  
1. PM D SERVICE

UNIT IS X-STREET  
04/13/2016 @ 19:45:48 pm d complete

**FASTER WORK ORDER PRINT**

**WORK ORDER # 59627**  
**EQUIPMENT # 2976**

Date In: 04/25/2016 Date Out: 04/27/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 5,491 A
			M 55,323

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
35	0.70	N	2	04/27/2016	PML BS	LUBRICATION	62.30

SUBTOTAL: 62.30

WORK ORDER TOTALS TOTAL: 62.30

NOTES

04/25/2016 @ 15:47:47  
1. SCHEDULED LUBE  
04/27/2016 @ 22:02:50 lube done

# FASTER WORK ORDER PRINT

## WORK ORDER # 59875 EQUIPMENT # 2976

Date In: 05/16/2016 Date Out: 05/16/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 55,377

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	48.00	136.00	-184.00	05/16/2016	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/16/2016	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00
WORK ORDER TOTALS					TOTAL: 25.00

### NOTES

05/16/2016 @ 09:29:10

WINGFOOT 5-3-16

YARD SVC

TT



**FASTER WORK ORDER PRINT**

**WORK ORDER # 60077**  
**EQUIPMENT # 2976**

Date In: 05/26/2016 Date Out: 05/26/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 56,027

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	0.70	N	2	05/26/2016	PML BS	LUBRICATION	62.30

SUBTOTAL: 62.30

WORK ORDER TOTALS TOTAL: 62.30

NOTES

05/26/2016 @ 15:25:05

1. Scheduled lube

lube complete #64

**FASTER WORK ORDER PRINT**

**WORK ORDER # 60116  
EQUIPMENT # 2976**

Date In: 05/31/2016 Date Out: 05/31/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 56,027

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	8.00	39.47	-47.47	05/31/2016	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/31/2016	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	25.00
-------------------	--------	-------

NOTES

05/31/2016 @ 10:39:56

WINGFOOT 4-13-16

YARD SVC

TT

**FASTER WORK ORDER PRINT**

**WORK ORDER # 60178  
EQUIPMENT # 2976**

Date In: 05/31/2016 Date Out: 05/31/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 56,027

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	8.00	39.47	-47.47	05/31/2016	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/31/2016	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	25.00
-------------------	--------	-------

NOTES

05/31/2016 @ 14:30:08

WINGFOOT 5-17-16

YARD SVC

TT

**FASTER WORK ORDER PRINT**

**WORK ORDER # 60514**  
**EQUIPMENT # 2976**

Date In: 06/23/2016 Date Out: 06/23/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 56,879

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
35	0.70	N	2	06/23/2016	PML BS	LUBRICATION	62.30

SUBTOTAL: 62.30

WORK ORDER TOTALS TOTAL: 62.30

NOTES

06/23/2016 @ 19:50:21

1. Scheduled lube.

06/23/2016 @ 22:58:11 lube done

# FASTER WORK ORDER PRINT

## WORK ORDER # 60559 EQUIPMENT # 2976

Date In: 06/28/2016 Date Out: 06/30/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 5,781 A
			M 57,213

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	1.00	N	2	06/29/2016	1022S1E100BS	Axle Rear Drive Seal Grease Rea Replace	89.00
11	2.50	N	2	06/29/2016	1022S1E100BS	Axle Rear Drive Seal Grease Rea Replace	222.50
11	0.50	N	2	06/30/2016	1022S1E100BS	Axle Rear Drive Seal Grease Rea Replace	44.50
11	1.00	N	2	06/30/2016	1022S1E100BS	Axle Rear Drive Seal Grease Rea Replace	89.00
11	1.50	N	2	06/30/2016	1022S1E100BS	Axle Rear Drive Seal Grease Rea Replace	133.50
35	2.00	N	2	06/28/2016	PMA BS	PM A Service	178.00
35	2.00	N	2	06/28/2016	PMA BS	PM A Service	178.00
35	0.70	N	2	06/30/2016	PMI BS	Annual State In	62.30
SUBTOTAL:							996.80

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1748XD-FIL	S	1	41.46	06/29/2016	1000001000BS	Unit Services Complete Unit Part Issue	41.46
3604XE-FIL	S	1	35.22	06/29/2016	1000001000BS	Unit Services Complete Unit Part Issue	35.22
3936-FIL	S	1	19.42	06/29/2016	1000001000BS	Unit Services Complete Unit Part Issue	19.42
110-1BG	S	4	10.00	06/29/2016	1000001000BS	Unit Services Complete Unit Part Issue	40.02
15W40-9OC	S	26	3.37	06/29/2016	1000001000BS	Unit Services Complete Unit Part Issue	87.54
9600-MAC	S	2	9.53	06/29/2016	1000001000BS	Unit Services Complete Unit Part Issue	19.06
500166-FIL	S	1	62.99	06/30/2016	1000001000BS	Unit Services Complete Unit Part Issue	62.99
500167-FIL	S	1	79.11	06/30/2016	1000001000BS	Unit Services Complete Unit Part Issue	79.11
75213-NOL	S	1	70.07	06/30/2016	1000001000BS	Unit Services Complete Unit Part Issue	70.07
3303107-TWD	S	2	2.56	06/30/2016	1000001000BS	Unit Services Complete Unit Part Issue	5.12
370003A-NTL	S	2	51.01	06/30/2016	1000001000BS	Unit Services Complete Unit Part Issue	102.02
GG4726ES2G-MBI	S	2	116.29	06/30/2016	1000001000BS	Unit Services Complete Unit Part Issue	232.58
66854B-TWD	S	2	327.24	06/30/2016	1000001000BS	Unit Services Complete Unit Part Issue	654.48
SUBTOTAL:							1,449.07

WORK ORDER TOTALS

TOTAL: 2,445.87

**FASTER WORK ORDER PRINT**

**WORK ORDER # 60559**  
**EQUIPMENT # 2976**

---

NOTES

06/28/2016 @ 19:28:35

1. PM A

2. NCSI

06/28/2016 @ 23:00:23 pm done needs both air filters and rear axle seals

3. Replaced right front tandem axle seal, brake shoes, and drum. #11  
Needs right rear as well.

06/29/2016 @ 15:53:51

4. Replaced right rear tandem wheel seal and brakes. #11

06/30/2016 @ 15:29:11

06/30/2016 @ 22:42:28 ncsi done

**FASTER WORK ORDER PRINT**

**WORK ORDER # 60606  
EQUIPMENT # 2976**

Date In: 06/29/2016 Date Out: 06/29/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 56,879

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	8.00	39.47	-47.47	06/29/2016	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	06/29/2016	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	25.00
-------------------	--------	-------

NOTES

06/29/2016 @ 20:33:21

WINGFOOT 6-10-16

YARD SVC

TT

**FASTER WORK ORDER PRINT**

**WORK ORDER # 60697**  
**EQUIPMENT # 2976**

Date In: 06/30/2016 Date Out: 06/30/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 56,879

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	16.00	68.00	-84.00	06/30/2016	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	06/30/2016	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	25.00
-------------------	--------	-------

NOTES

06/30/2016 @ 14:30:46

WINGFOOT 6-21-16

STOCK TIRES

TT



**FASTER WORK ORDER PRINT**

**WORK ORDER # 60930  
EQUIPMENT # 2976**

Date In: 07/15/2016 Date Out: 07/18/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 57,213

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	2.00	N	2	07/15/2016	2042000001BN	Cooling Engine System Diagnosis	224.00
SUBTOTAL:							224.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1536-NBH	S	3	32.35	07/18/2016	1000001000BS	Unit Services Complete Unit Part Issue	97.06
DELOXLC55-90C	S	60	2.65	07/18/2016	1000001000BS	Unit Services Complete Unit Part Issue	158.82
SUBTOTAL:							255.88

WORK ORDER TOTALS	TOTAL:	479.88
-------------------	--------	--------

NOTES

07/15/2016 @ 19:56:50

1. Vehicle was towed in for loss of coolant.  
MC

1. Found upper hose burst at thermostat neck, replaced. Drained small amount of remaining coolant and installed FluidXchange fitting. Filled with Delo XLC. Also found lower pipe bracket to alternator bolt broken, welded. #11  
07/15/2016 @ 23:12:42

**FASTER WORK ORDER PRINT**

**WORK ORDER # 61009  
EQUIPMENT # 2976**

Date In: 07/22/2016 Date Out: 07/22/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 57,123 A

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	16.00	68.00	-84.00	07/22/2016	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	07/22/2016	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

07/22/2016 @ 09:57:19

WINGFOOT 6-28-16

YARD SVC

TT

# FASTER WORK ORDER PRINT

## WORK ORDER # 61316 EQUIPMENT # 2976

Date In: 08/19/2016 Date Out: 08/19/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 58,215

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	0.50	N	2	08/19/2016	2003000001BN	Gauge Instro System Diagnosis	56.00
04	1.00	N	2	08/19/2016	2102LN8001BN	Light Emergency Light Strobe Diagnosis	112.00
SUBTOTAL:							168.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
7304378-BK	S	1	155.49	08/22/2016	1000001000BS	Unit Services Complete Unit Part Issue	155.49
SUBTOTAL:							155.49

WORK ORDER TOTALS	TOTAL:	323.49
-------------------	--------	--------

### NOTES

08/19/2016 @ 15:12:27

1. Poswible yellow trans light on
2. Rear strobe light is out

code for trand fluid deterriorated cleared and reset oil life. #04

replaced strobe light. #04

**FASTER WORK ORDER PRINT**

**WORK ORDER # 61451  
EQUIPMENT # 2976**

Date In: 08/24/2016 Date Out: 08/24/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 58,713

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	48.00	204.00	-252.00	08/24/2016	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	08/24/2016	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

08/24/2016 @ 09:34:11

WINGFOOT 8-3-16

YARD SVC

**FASTER WORK ORDER PRINT**

**WORK ORDER # 61967  
EQUIPMENT # 2976**

Date In: 09/29/2016 Date Out: 09/29/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 60,081

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	09/29/2016	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	09/29/2016	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	25.00
-------------------	--------	-------

NOTES

TRACKS TO TIRES 8-23-16

SCHEDULED LUBE

# FASTER WORK ORDER PRINT

## WORK ORDER # 62201 EQUIPMENT # 2976

Date In: 10/07/2016 Date Out: 10/19/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 60,081

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	1.00	N	2	10/07/2016	2214FL1165BN	Compact Hopper FLIPPER ASSY. Repair	112.00
04	0.50	N	2	10/07/2016	2214FL1165BN	Compact Hopper FLIPPER ASSY. Repair	56.00
04	0.50	N	2	10/10/2016	2214FL1165BN	Compact Hopper FLIPPER ASSY. Repair	56.00
04	0.50	N	2	10/10/2016	2214FL1165BN	Compact Hopper FLIPPER ASSY. Repair	56.00
04	2.50	N	2	10/11/2016	2214FL1165BN	Compact Hopper FLIPPER ASSY. Repair	280.00
SUBTOTAL:							560.00

WORK ORDER TOTALS	TOTAL:	560.00
-------------------	--------	--------

### NOTES

10/07/2016 @ 15:29:33

1. Repair flipper > Part of the flipper fell off, Part is on floorboard passanger side

attempted to remove stuck bolts could not get nuts or bolts to weld onto them ordered new bar to replace it. #04

**FASTER WORK ORDER PRINT**

**WORK ORDER # 62323  
EQUIPMENT # 2976**

Date In: 10/18/2016 Date Out: 10/18/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 60,081

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	24.44	68.00	-92.44	10/18/2016	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	10/18/2016	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

10/18/2016 @ 11:04:33

WINGFOOT 9-20-16

YARD SVC

# FASTER WORK ORDER PRINT

## WORK ORDER # 62516 EQUIPMENT # 2976

Date In: 10/26/2016 Date Out: 10/26/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 60,081

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	1.00	N	2	10/26/2016	2003LN9001BN	Gauge Instro LightCheckEngin Diagnosis	112.00
11	0.50	N	2	10/26/2016	2034LN5165BN	Light System Light Exterior Repair	56.00
11	0.50	N	2	10/26/2016	2044F15100BN	Fuel System Filter Fuel Pri Replace	56.00
11	0.50	N	2	10/26/2016	2044F18100BN	Fuel System Filter Fuel 2nd Replace	56.00
SUBTOTAL:							280.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
3936-FIL	S	1	19.42	10/26/2016	1000001000BS	Unit Services Complete Unit Part Issue	19.42
3604XE-FIL	S	1	35.22	10/26/2016	1000001000BS	Unit Services Complete Unit Part Issue	35.22
9600-MAC	S	2	8.70	10/26/2016	1000001000BS	Unit Services Complete Unit Part Issue	17.40
SUBTOTAL:							72.04

WORK ORDER TOTALS	TOTAL:	352.04
-------------------	--------	--------

### NOTES

10/26/2016 @ 09:34:54  
1. Check engine light on  
2. plow lights not angled correctly

1. Stored DTCs for fuel rail pressure insufficient and fuel filter differential high, cleared. #11  
10/26/2016 @ 10:43:04

2. Reangled plow lights. #11  
10/26/2016 @ 10:44:15

3. Replaced primary fuel filter. #11  
10/26/2016 @ 10:45:02

4. Replaced secondary fuel filter. #11  
10/26/2016 @ 10:45:50



**FASTER WORK ORDER PRINT**

**WORK ORDER # 62612**  
**EQUIPMENT # 2976**

Date In: 10/26/2016 Date Out: 10/26/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 60,081

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	44.88	136.00	-180.88	10/26/2016	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	10/26/2016	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

10/26/2016 @ 16:31:36

WINGFOOT 10-18-16

YARD SVC

# FASTER WORK ORDER PRINT

## WORK ORDER # 62653 EQUIPMENT # 2976

Date In: 10/28/2016 Date Out: 11/01/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 61,218

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	0.50	N	2	10/31/2016	1013000001BS	Brakes System Diagnosis	56.00
04	0.50	N	2	11/01/2016	1013000001BS	Brakes System Diagnosis	56.00
04	1.50	N	2	11/01/2016	1013SC2100BS	Brakes Shoe/LiningA-Br Replace	168.00
11	0.50	N	2	11/01/2016	1013000001BS	Brakes System Diagnosis	56.00
11	1.00	N	2	11/01/2016	1013SC2100BS	Brakes Shoe/LiningA-Br Replace	112.00
64	0.50	N	2	10/28/2016	1013000001BS	Brakes System Diagnosis	56.00
64	4.00	N	2	10/28/2016	PMA BS	PM A Service	448.00
64	2.00	N	2	10/31/2016	1013000001BS	Brakes System Diagnosis	224.00
64	2.00	N	2	10/31/2016	1013000001BS	Brakes System Diagnosis	224.00
SUBTOTAL:							1,400.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1748-FIL	S	1	37.97	10/31/2016	1000001000BS	Unit Services Complete Unit Part Issue	37.97
110-1BG	S	4	10.00	10/31/2016	1000001000BS	Unit Services Complete Unit Part Issue	40.02
15W40-9OC	S	26	3.37	10/31/2016	1000001000BS	Unit Services Complete Unit Part Issue	87.54
DELOXLC-9OC	S	4	14.52	11/01/2016	1000001000BS	Unit Services Complete Unit Part Issue	58.07
370003A-NTL	S	2	51.01	11/01/2016	1000001000BS	Unit Services Complete Unit Part Issue	102.02
3303107-TWD	S	2	2.56	11/01/2016	1000001000BS	Unit Services Complete Unit Part Issue	5.12
GG4726ES2G-MBI	S	2	116.29	11/01/2016	1000001000BS	Unit Services Complete Unit Part Issue	232.58
66854B-TWD	S	2	360.73	11/01/2016	1000001000BS	Unit Services Complete Unit Part Issue	721.46
SUBTOTAL:							1,284.78

WORK ORDER TOTALS TOTAL: 2,684.78

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 62653**  
**EQUIPMENT # 2976**

10/28/2016 @ 15:49:15

**1. PM SERVICE**

**2. Operator states brakes are smoking and getting hot**

**pm complete #64**

**truck needs brakes on back axle #64**

**assisted with rear hubseal replacement. #04**

**started brake job and hubseal replacement on rear axle #64**

**Installed brake shoes and drums and finished rear hub seals on rear-most tandem axle. #11 #04**

**11/01/2016 @ 14:26:20**

**FASTER WORK ORDER PRINT**

**WORK ORDER # 62687  
EQUIPMENT # 2976**

Date In: 10/31/2016 Date Out: 10/31/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 61,218

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	11.22	39.47	-50.69	10/31/2016	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	10/31/2016	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

10/31/2016 @ 14:23:29

WINGFOOT 10-25-16

YARD SVC

**FASTER WORK ORDER PRINT**

**WORK ORDER # 62887**  
**EQUIPMENT # 2976**

Date In: 11/10/2016 Date Out: 11/10/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 61,957

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	0.50	N	2	11/10/2016	2004V17165BN	Heating Vent Valve Heater Repair	56.00
SUBTOTAL:							56.00

WORK ORDER TOTALS	TOTAL:	56.00
-------------------	--------	-------

NOTES

11/10/2016 @ 08:06:08

1. Operator stes open heater valves for winter heat operation.  
MC

1. Opened valves. #11

11/10/2016 @ 08:34:29

**FASTER WORK ORDER PRINT**

**WORK ORDER # 63243**  
**EQUIPMENT # 2976**

Date In: 11/30/2016 Date Out: 11/30/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 62,044

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	11/30/2016	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	11/30/2016	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

11/30/2016 @ 11:12:28

TRACKS TO TIRES 11-15-16

LUBE

# FASTER WORK ORDER PRINT

## WORK ORDER # 63357 EQUIPMENT # 2976

Date In: 12/06/2016 Date Out: 12/06/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 62,044

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	1.00	N	1	12/06/2016	2051000001BN	Air Supply System Diagnosis	112.00
SUBTOTAL:							112.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
G311000402-GAT	S	1	3.83	12/07/2016	1000001000BS	Unit Services Complete Unit Part Issue	3.83
SUBTOTAL:							3.83

WORK ORDER TOTALS	TOTAL:	115.83
-------------------	--------	--------

### NOTES

12/06/2016 @ 14:48:46

1. Pressure gauge reading max

found signal air hose fitting busted at air govonor replaced with new fitting air now purges at 120psi. #04

# FASTER WORK ORDER PRINT

## WORK ORDER # 63404 EQUIPMENT # 2976

Date In: 12/09/2016 Date Out: 12/20/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 62,044

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
19	0.50	N	1	12/09/2016	2065000001BN	Hydraulic Syste System Diagnosis	56.00
19	0.50	N	1	12/09/2016	2214FL1165BN	Compact Hopper FLIPPER ASSY. Repair	56.00
28	0.50	N	1	12/20/2016	2041F10100BN	Air Intake Engi Filter Air Replace	56.00
28	0.50	N	1	12/20/2016	2214FL1165BN	Compact Hopper FLIPPER ASSY. Repair	56.00
SUBTOTAL:							224.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
500167-FIL	S	1	79.11	12/21/2016	1000001000BS	Unit Services Complete Unit Part Issue	79.11
500166-FIL	S	1	62.99	12/21/2016	1000001000BS	Unit Services Complete Unit Part Issue	62.99
SUBTOTAL:							142.09

WORK ORDER TOTALS	TOTAL:	366.09
-------------------	--------	--------

### NOTES

12/09/2016 @ 13:51:30

1. PASSANGER SIDE FLIPPER IS LEAKING AT THE CONTROL
2. REPAIR DRIVER SIDE FLIPPER
3. Replace air filter

Tightened valve block fitting on Pass. flipper control #19.

Flipper parts ordered from Curtis #19.

12/15/2016 @ 10:26:32 parts came in wednesday

Replace air filters.

Rebuild driver side flipper

Order new left flipper control valve.

DT



**FASTER WORK ORDER PRINT**

**WORK ORDER # 63595  
EQUIPMENT # 2976**

Date In: 12/21/2016 Date Out: 12/21/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 62,044

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	1.50	N	2	12/21/2016	2003000001BN	Gauge Instro System Diagnosis	168.00
64	1.00	N	2	12/21/2016	2003000001BN	Gauge Instro System Diagnosis	112.00
SUBTOTAL:							280.00

WORK ORDER TOTALS	TOTAL:	280.00
-------------------	--------	--------

NOTES

12/21/2016 @ 15:29:25  
1. EMMISION LIGHT ON

found a exhaust clamp that was loose on passenger side of truck tightened clamp #64

found loose hydraulic hose fitting on driver side under air filter tightened fitting #64

**FASTER WORK ORDER PRINT**

**WORK ORDER # 63614**  
**EQUIPMENT # 2976**

Date In: 12/22/2016 Date Out: 12/22/2016 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 62,044

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	1.50	N	2	12/22/2016	2040000001BN	Engine System Diagnosis	168.00

SUBTOTAL: 168.00

WORK ORDER TOTALS TOTAL: 168.00

NOTES

12/22/2016 @ 15:06:27

DIAGNOSE CHECK ENGINE LIGHT ON

TT

check engine light was for regen, performed regen manually on truck #64

# FASTER WORK ORDER PRINT

## WORK ORDER # 63828 EQUIPMENT # 2976

Date In: 01/07/2017 Date Out: 01/07/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 63,034

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
11	1.00	N	2	01/07/2017	2040000001BN	Engine System Diagnosis	112.00
SUBTOTAL:							112.00

WORK ORDER TOTALS	TOTAL:	112.00
-------------------	--------	--------

### NOTES

01/07/2017 @ 16:25:36

CHECK ENGINE LIGHT COMING ON, LOSS OF POWER

TT

7 DTCs total.

Active:

Aftertreatment particulate trap differential pressure above normal

Inactive:

Voltage above normal operating range

Injector metering rail pressure below normal operating range

Coolant level below normal operating range

Turbocharger Variable Geometry Actuator mechanical not responding

EGR differential pressure erratic

VGT actuator out of calibration

Ran regen, cleared DTCs.

01/07/2017 @ 17:24:18

# FASTER WORK ORDER PRINT

## WORK ORDER # 63972 EQUIPMENT # 2976

Date In: 01/17/2017 Date Out: 01/18/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 64,000

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
10	2.75	N	2	01/18/2017	2043A06001BN	Exhaust Engine Turbocharger As Diagnosis	308.00
28	5.00	N	1	01/18/2017	2040000001BN	Engine System Diagnosis	560.00
64	4.00	N	2	01/17/2017	2040000001BN	Engine System Diagnosis	448.00
SUBTOTAL:							1,316.00

### PARTS ISSUED

PART NUMBER/DESCRIPTION	S/NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
3604XE-FIL	S	1	35.23	01/18/2017	1000001000BS	Unit Services Complete Unit Part Issue	35.23
3936-FIL	S	1	19.42	01/18/2017	1000001000BS	Unit Services Complete Unit Part Issue	19.42
9600-MAC	S	2	8.70	01/18/2017	1000001000BS	Unit Services Complete Unit Part Issue	17.40
406-1BG	S	1	6.87	01/18/2017	1000001000BS	Unit Services Complete Unit Part Issue	6.87
DELOXLC-9OC	S	2	14.52	01/18/2017	1000001000BS	Unit Services Complete Unit Part Issue	29.04
4307166-CFR	S	1	151.77	01/19/2017	1000001000BS	Unit Services Complete Unit Part Issue	151.77
SUBTOTAL:							259.73

WORK ORDER TOTALS	TOTAL:	1,575.73
-------------------	--------	----------

### NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 63972**  
**EQUIPMENT # 2976**

01/17/2017 @ 17:27:46

1. Towed in for no start issue.

replaced both fuel filters and was able to get truck running  
truck only has about 13000 psi on fuel rail  
performed fuel pressure test and pressure went up to 29000psi  
and held at 9500psi with the truck off  
check engine light came on for vgt actuator needs further diagnosis #64

01/18/2017 @ 07:31:25

PLEASE CONTINUE WITH REPAIR

TT

Troubleshoot engine light.  
Clear codes.  
Test drive. Truc klow on power.  
EGR data not correct. Remove Pressure sensor. Clean ports and replace sensor.  
Test drive. Normal power now. Now truck has high coolant temp. Add 3 gallons of coolant.  
DT

# FASTER WORK ORDER PRINT

## WORK ORDER # 64150 EQUIPMENT # 2976

Date In: 01/29/2017 Date Out: 01/29/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 64,000

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
BARBOUR'S TOWING & RECOVERY	0.00	200.00	-200.00	01/29/2017	Z000001500NN	Unit Services Complete Unit Towing	0.00
SUBTOTAL:							0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	01/29/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

### NOTES

01/29/2017 @ 13:05:00

BARBOUR'S TOWING 1-18-17

**FASTER WORK ORDER PRINT**

**WORK ORDER # 64162**  
**EQUIPMENT # 2976**

Date In: 01/30/2017 Date Out: 01/30/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 64,000

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	107.47	-129.91	01/30/2017	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	01/30/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

01/30/2017 @ 09:42:34

WINGFOOT 1-24-17

YARD SVC

# FASTER WORK ORDER PRINT

## WORK ORDER # 64270 EQUIPMENT # 2976

Date In: 02/03/2017 Date Out: 02/03/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 64,000

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
25	1.25	N	2	02/03/2017	2214FL1165BN	Compact Hopper FLIPPER ASSY. Repair	140.00
25	3.25	N	2	02/03/2017	2002ST1620BN	Cab StepDoorEntranc WeldSurfaceFace	364.00
SUBTOTAL:							504.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
DA1670-DC	S	1	7.67	02/06/2017	1000001000BS	Unit Services Complete Unit Part Issue	7.67
476180-THM	S	1	25.17	02/08/2017	1000001000BS	Unit Services Complete Unit Part Issue	25.17
DELOXLC-9OC	S	3	14.52	02/08/2017	1000001000BS	Unit Services Complete Unit Part Issue	43.55
DELOXLC-9OC	S	3	-14.52	02/08/2017	1000001000BS	Unit Services Complete Unit Part Issue	-43.55
SUBTOTAL:							32.84

WORK ORDER TOTALS TOTAL: 536.84

### NOTES

02/03/2017 @ 15:19:57

REAR STEP NEED WELDING  
PASSENGER SIDE FLIPPER CONTROL IS LEAKING WHEN IN USE

TT

#25---Found o-ring fitting leaking at right rear flipper valve. Replaced o-ring.

welded and repaired step. #25



**FASTER WORK ORDER PRINT**

**WORK ORDER # 64308**  
**EQUIPMENT # 2976**

Date In: 02/08/2017 Date Out: 02/08/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 64,000

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
28	1.00	N	1	02/08/2017	2042TF0100BN	Cooling Engine Thermostat Replace	112.00
SUBTOTAL:							112.00

WORK ORDER TOTALS	TOTAL:	112.00
-------------------	--------	--------

NOTES

02/08/2017 @ 08:55:38

THERMOSTAT REPLACEMENT

TT

Add Hyd fluid to make sure fan pump is working normal.  
Replace sticking Thermostat.  
Test for overheating.  
DT

# FASTER WORK ORDER PRINT

## WORK ORDER # 64639 EQUIPMENT # 2976

Date In: 03/06/2017 Date Out: 03/06/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 65,463

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	68.00	-90.44	03/06/2017	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	03/06/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

### NOTES

03/06/2017 @ 09:10:37

WINGFOOT 1-31-17

YARD SVC

TT

# FASTER WORK ORDER PRINT

## WORK ORDER # 64910 EQUIPMENT # 2976

Date In: 03/17/2017 Date Out: 03/17/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 65,463

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
23	4.00	N	2	03/17/2017	PMA BS	PM A Service	448.00
23	0.50	N	2	03/17/2017	1000TCD021BS	Unit Services TOWN DECALS INSTALL/REMOVE	56.00
SUBTOTAL:							504.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTIION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
11232-1BG	S	2	28.30	03/20/2017	1000001000BS	Unit Services Complete Unit Part Issue	56.61
9600-MAC	S	2	8.70	03/20/2017	1000001000BS	Unit Services Complete Unit Part Issue	17.40
1748XD-FIL	S	1	41.99	03/20/2017	1000001000BS	Unit Services Complete Unit Part Issue	41.99
3604XE-FIL	S	1	35.23	03/20/2017	1000001000BS	Unit Services Complete Unit Part Issue	35.23
3936-FIL	S	1	19.42	03/20/2017	1000001000BS	Unit Services Complete Unit Part Issue	19.42
15W40-9OC	S	26	3.53	03/20/2017	1000001000BS	Unit Services Complete Unit Part Issue	91.68
SUBTOTAL:							262.33

WORK ORDER TOTALS	TOTAL:	766.33
-------------------	--------	--------

### NOTES

03/17/2017 @ 19:21:41  
PMA  
03/17/2017 @ 21:39:50  
pm done #23  
town decals replaced #23

**FASTER WORK ORDER PRINT**

**WORK ORDER # 65002**  
**EQUIPMENT # 2976**

Date In: 03/24/2017 Date Out: 03/27/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 65,463

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	2.00	N	2	03/24/2017	2051LS1001BN	Air Supply Line Air Diagnosis	224.00
04	0.50	N	2	03/24/2017	2034LN5165BN	Light System Light Exterior Repair	56.00
04	0.50	N	2	03/24/2017	2001MH0165BN	Air Conditionin Misc Parts Repair	56.00
04	2.00	N	2	03/24/2017	2013DT0100BN	Brakes Drum Air Brake Replace	224.00
SUBTOTAL:							560.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
GG4726ES2G-MBI	S	2	116.57	03/27/2017	1000001000BS	Unit Services Complete Unit Part Issue	233.14
66854B-TWD	S	2	396.81	03/27/2017	1000001000BS	Unit Services Complete Unit Part Issue	793.61
SUBTOTAL:							1,026.75

WORK ORDER TOTALS	TOTAL:	1,586.75
-------------------	--------	----------

NOTES

03/24/2017 @ 13:47:19

OPERATOR STATES BRAKES AREA SQUEALING AND GRINDING  
FRONT RUNNING LIGHT ON PACKER BODY FELL OUT OF MOUNT  
SOUNDS LIKE SMALL LEAK UNDER FRONT OF CAB  
SWITCH FROM HEAT TO A/C

TT

Found rear brakes bad replaced. #04  
could not find air leak #04  
turned off heater valves. #04

**FASTER WORK ORDER PRINT**

**WORK ORDER # 65153  
EQUIPMENT # 2976**

Date In: 04/06/2017   Date Out: 04/06/2017   Work Order Status: C   Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H                      4,913
			M                      65,463

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

04/06/2017 @ 13:47:08

RE-BILL OF PARTS FROM WO#64270

**FASTER WORK ORDER PRINT**

**WORK ORDER # 65508  
EQUIPMENT # 2976**

Date In: 05/01/2017 Date Out: 05/01/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 66,937

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	05/01/2017	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/01/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

05/01/2017 @ 12:15:15  
Tracks to Tires  
Scheduled Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 65534  
EQUIPMENT # 2976**

Date In: 05/01/2017 Date Out: 05/01/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 66,937

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	05/01/2017	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/01/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

05/01/2017 @ 13:27:44  
Tracks to Tires  
Scheduled Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 65628**  
**EQUIPMENT # 2976**

Date In: 05/02/2017 Date Out: 05/02/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 66,937

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOOD YEAR COMM TIRE	0.00	68.00	-68.00	05/02/2017	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/02/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

05/02/2017 @ 10:22:46  
Wingfoot invoice 091-1053437  
2 tires

pd



**FASTER WORK ORDER PRINT**

**WORK ORDER # 65641**  
**EQUIPMENT # 2976**

Date In: 05/02/2017 Date Out: 05/02/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 66,937

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	0.00	68.00	-68.00	05/02/2017	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/02/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

05/02/2017 @ 11:38:44  
Wingfoot invoice 091-1053512  
1 tire

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 65821**  
**EQUIPMENT # 2976**

Date In: 05/09/2017 Date Out: 05/09/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 68,118

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	68.00	-90.44	05/09/2017	Z017TM1445NN	Tire / Tube Tire Heavy Flat Repair,Hvy	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/09/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

05/09/2017 @ 13:14:13  
Wingfoot 5/2/17  
Road service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 65854**  
**EQUIPMENT # 2976**

Date In: 05/10/2017 Date Out: 05/10/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 68,118

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	05/10/2017	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/10/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

05/10/2017 @ 07:26:59  
Tracks to Tires 2/17/17

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 65927**  
**EQUIPMENT # 2976**

Date In: 05/10/2017 Date Out: 05/10/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 68,221

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	05/10/2017	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/10/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

05/10/2017 @ 14:28:58  
Tracks to Tires 5/2/17  
lube service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 66053**  
**EQUIPMENT # 2976**

Date In: 05/16/2017 Date Out: 05/16/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 68,653

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	68.00	-90.44	05/16/2017	Z017TM1445NN	Tire / Tube Tire Heavy Flat Repair,Hvy	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/16/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

05/16/2017 @ 08:33:03  
Wingfoot 5/9/17  
Yard service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 66146**  
**EQUIPMENT # 2976**

Date In: 05/22/2017 Date Out: 05/22/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 68,676

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	68.00	-90.44	05/22/2017	Z017TM1445NN	Tire / Tube Tire Heavy Flat Repair,Hvy	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/22/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

05/22/2017 @ 13:17:28  
Wingfoot 5/16/17  
Yard service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 66165  
EQUIPMENT # 2976**

Date In: 05/22/2017 Date Out: 05/23/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 68,676

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
23	3.00	N	2	05/23/2017	2007ME0100BN	Glass-Component Mirror Replace	336.00
SUBTOTAL:							336.00

WORK ORDER TOTALS	TOTAL:	336.00
-------------------	--------	--------

NOTES

05/22/2017 @ 15:13:02

REPLACE PASSENGER SIDE MIRRORS

TT

05/22/2017 @ 15:19:39

DION --- CURTIS IS ORDERING THE MIRRORS

TT

05/23/2017 @ 14:19:13 parts are in

05/23/2017 @ 19:17:57

modified brackets, spliced power window wires together and replaced 4 mirriors on pass. side #23

**FASTER WORK ORDER PRINT**

**WORK ORDER # 66387  
EQUIPMENT # 2976**

Date In: 06/06/2017 Date Out: 06/06/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 68,776

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
04	0.50	N	2	06/06/2017	2065H58T01BN	Hydraulic Syste Hose Hydraulic TIGHTEN	56.00
SUBTOTAL:							56.00

WORK ORDER TOTALS	TOTAL:	56.00
-------------------	--------	-------

NOTES

06/06/2017 @ 13:53:09

CAP THE HYD HOSES TO THE FLIPPERS

TT

caped hoses. #04



# FASTER WORK ORDER PRINT

## WORK ORDER # 66404 EQUIPMENT # 2976

Date In: 06/07/2017 Date Out: 06/07/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 68,776

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	06/07/2017	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	06/07/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

### NOTES

06/07/2017 @ 07:52:34  
Tracks to Tires 6/2/17  
Lube service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 66774**  
**EQUIPMENT # 2976**

Date In: 06/27/2017 Date Out: 06/27/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 68,776

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	06/27/2017	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	06/27/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

06/27/2017 @ 08:20:31  
Tracks to Tires 6/19/17  
Lube service

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 66963 EQUIPMENT # 2976

Date In: 07/05/2017 Date Out: 07/05/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 68,776

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
25	3.00	N	2	07/05/2017	2040000001BN	Engine System Diagnosis	330.00
SUBTOTAL:							330.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
DELOXLC55-90C	S	15	2.65	07/06/2017	1000001000BS	Unit Services Complete Unit Part Issue	39.71
SUBTOTAL:							39.71

WORK ORDER TOTALS	TOTAL:	369.71
-------------------	--------	--------

### NOTES

07/05/2017 @ 14:51:37

TRUCK CRANKS BUT KEEPS KNOCKING OFF

TT

#25 - Truck starts with no problem. Pulled codes and found 2 inactive codes. low coolant level and voltage to high. Inspected and found no coolant leaks added 15 qts to the coolant tank, it may have a cold leak. Will need to be looked at in the AM.  
Checked charging system and found no defects. Cleared codes

**FASTER WORK ORDER PRINT**

**WORK ORDER # 67031  
EQUIPMENT # 2976**

Date In: 07/11/2017 Date Out: 07/11/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 68,776

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	1.00	N	1	07/11/2017	2214FL1165BN	Compact Hopper FLIPPER ASSY. Repair	110.00
SUBTOTAL:							110.00

WORK ORDER TOTALS	TOTAL:	110.00
-------------------	--------	--------

NOTES

07/11/2017 @ 10:46:58

HYD TO FLIPPER WHICH ARE NEWER IS LEAKING

TT

hydraulic line fittings going to flipper were loose  
tightened fittings #64

**FASTER WORK ORDER PRINT**

**WORK ORDER # 67094**  
**EQUIPMENT # 2976**

Date In: 07/14/2017 Date Out: 07/25/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 69,070

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
25	1.50	N	2	07/14/2017	1040000001BN	Engine System Diagnosis	165.00
25	1.00	N	2	07/14/2017	2036MH0001BN	Warning Device Misc Parts Diagnosis	110.00
25	0.50	N	2	07/14/2017	2001BLK001BN	Air Conditionin Blower Diagnosis	55.00
25	0.50	N	2	07/14/2017	1040000001BN	Engine System Diagnosis	55.00
SUBTOTAL:							385.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
725254-NW	S	50	1.10	07/17/2017	1000001000BS	Unit Services Complete Unit Part Issue	54.90
SUBTOTAL:							54.90

WORK ORDER TOTALS	TOTAL:	439.90
-------------------	--------	--------

NOTES

07/14/2017 @ 16:13:42

Truck seemed like it was running hot.  
A/C isnt blowing cold as it should.  
No backup camera

JF

#25 - Found trash in radiator and cleaned out

Checked a/c it is blowing cold

The backup camera cable was cut inside the tailgate. I could not find a cable or camera in curtis on monday.

the parts room will talk to

# FASTER WORK ORDER PRINT

## WORK ORDER # 67275 EQUIPMENT # 2976

Date In: 07/24/2017 Date Out: 07/24/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 69,262

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
19	3.00	N	1	07/24/2017	2013000001BN	Brakes System Diagnosis	330.00
SUBTOTAL:							330.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
CS56033-MBI	S	2	120.57	07/25/2017	1000001000BS	Unit Services Complete Unit Part Issue	241.15
SUBTOTAL:							241.15

WORK ORDER TOTALS	TOTAL:	571.15
-------------------	--------	--------

### NOTES

07/24/2017 @ 06:51:59

Check brakes  
DT

Adjusted rear tandems #19.

Replaced both slack adjusters on front tandems #19.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 67540**  
**EQUIPMENT # 2976**

Date In: 08/08/2017 Date Out: 08/08/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 69,799

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	08/08/2017	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	08/08/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

08/08/2017 @ 14:24:57  
Tracks to Tires 7/26/17  
lube service

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 67702 EQUIPMENT # 2976

Date In: 08/14/2017 Date Out: 08/14/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 70,116

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	68.00	-90.44	08/14/2017	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	08/14/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

### NOTES

08/14/2017 @ 11:21:38

Wingfoot 8/8/17  
Yard Service

pd



**FASTER WORK ORDER PRINT**

**WORK ORDER # 67709**  
**EQUIPMENT # 2976**

Date In: 08/14/2017 Date Out: 08/14/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 70,116

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	08/14/2017	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	08/14/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

08/14/2017 @ 12:10:16

Tracks to Tires 8/9/17  
Lube

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 68044 EQUIPMENT # 2976

Date In: 08/30/2017 Date Out: 08/30/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 70,602

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
44	4.00	N	2	08/30/2017	2065H58165BN	Hydraulic Syste Hose Hydraulic Repair	440.00
SUBTOTAL:							440.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
85604-GAT	S	16	10.42	08/31/2017	1000001000BS	Unit Services Complete Unit Part Issue	166.70
G251700606-GAT	S	2	7.19	08/31/2017	1000001000BS	Unit Services Complete Unit Part Issue	14.37
SUBTOTAL:							181.08

WORK ORDER TOTALS	TOTAL:	621.08
-------------------	--------	--------

### NOTES

08/30/2017 @ 14:54:53

HYD LEAK AT HOSE AT TOP OF TAILGATE WHEN PTO IS ON

TT

08/30/2017 @ 20:43:42

Hose from spool valve to left flipper valve leaking hydraulic fluid. Make up hose with proper fittings and route properly through rear of body. Had to enlarge pass through hole in left side due to fitting on replacement hose being larger diameter. Secure hose and operate all functions to verify proper operation and no leaks. #44

# FASTER WORK ORDER PRINT

## WORK ORDER # 68087 EQUIPMENT # 2976

Date In: 09/01/2017 Date Out: 09/01/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 70,602

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
23	4.00	N	2	09/01/2017	PMA BS	PM A Service	440.00
23	0.70	N	2	09/01/2017	PMI BS	Annual State In	77.00
SUBTOTAL:							517.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1748XD-FIL	S	1	32.29	09/05/2017	1000001000BS	Unit Services Complete Unit Part Issue	32.29
11232-1BG	S	2	28.30	09/05/2017	1000001000BS	Unit Services Complete Unit Part Issue	56.61
3604-FIL	S	1	23.72	09/05/2017	1000001000BS	Unit Services Complete Unit Part Issue	23.72
3936-FIL	S	1	14.95	09/05/2017	1000001000BS	Unit Services Complete Unit Part Issue	14.95
9600-MAC	S	2	8.70	09/05/2017	1000001000BS	Unit Services Complete Unit Part Issue	17.40
15W40-9OC	S	26	3.53	09/05/2017	1000001000BS	Unit Services Complete Unit Part Issue	91.68
SUBTOTAL:							236.64

WORK ORDER TOTALS	TOTAL:	753.64
-------------------	--------	--------

### NOTES

09/01/2017 @ 15:09:06

NCSI.

PMA.

09/01/2017 @ 16:54:31

pm done #23

ncsi done #23

**FASTER WORK ORDER PRINT**

**WORK ORDER # 68254  
EQUIPMENT # 2976**

Date In: 09/14/2017 Date Out: 09/15/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 71,159

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
25	2.00	N	2	09/14/2017	2065H58100BN	Hydraulic Syste Hose Hydraulic Replace	220.00
SUBTOTAL:							220.00

PARTS ISSUED

PART NUMBER/ DESCRIPTIION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
G251700606-GAT	S	3	7.19	09/18/2017	1000001000BS	Unit Services Complete Unit Part Issue	21.56
SUBTOTAL:							21.56

WORK ORDER TOTALS	TOTAL:	241.56
-------------------	--------	--------

NOTES

09/14/2017 @ 16:53:32

Leak in pto hydraulic line passenger side. Sprays when operating.

JF

#25 -Found hyd oil leak at handles on right side rear. We only had 1 fitting for hose. I cut the end of the hose off and just replaced the fitting.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 68289**  
**EQUIPMENT # 2976**

Date In: 09/15/2017 Date Out: 09/15/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 71,159

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	09/15/2017	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	09/15/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

09/15/2017 @ 10:05:47

Tracks to Tires 9/5/17  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 68351  
EQUIPMENT # 2976**

Date In: 09/19/2017 Date Out: 09/19/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 71,159

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	68.00	-90.44	09/19/2017	Z017TM1445NN	Tire / Tube Tire Heavy Flat Repair,Hvy	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	09/19/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

09/19/2017 @ 08:00:25

Wingfoot 9/12/17  
Yard service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 68370**  
**EQUIPMENT # 2976**

Date In: 09/19/2017 Date Out: 09/19/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 71,159

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	68.00	-90.44	09/19/2017	Z017TM1445NN	Tire / Tube Tire Heavy Flat Repair,Hvy	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	09/19/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

09/19/2017 @ 09:06:01

Wingfoot 8/1/17  
Yard service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 68572  
EQUIPMENT # 2976**

Date In: 09/29/2017 Date Out: 09/29/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 71,875

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	68.00	-90.44	09/29/2017	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	09/29/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

09/29/2017 @ 12:53:57

Wingfoot 9/26/17  
Yard Service

pd



**FASTER WORK ORDER PRINT**

**WORK ORDER # 68629**  
**EQUIPMENT # 2976**

Date In: 10/04/2017 Date Out: 10/04/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 72,068

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	10/04/2017	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	10/04/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

10/04/2017 @ 12:33:41

Tracks to Tires 9/20/17  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 68858**  
**EQUIPMENT # 2976**

Date In: 10/17/2017 Date Out: 10/17/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 72,412

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	44.88	136.00	-180.88	10/17/2017	Z017TM1445NN	Tire / Tube Tire Heavy Flat Repair,Hvy	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	10/17/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

10/17/2017 @ 07:57:01

Wingfoot 10/9/17  
Yard service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 68949**  
**EQUIPMENT # 2976**

Date In: 10/19/2017 Date Out: 10/19/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 72,506

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	10.22	41.90	-52.12	10/19/2017	Z017TM1445NN	Tire / Tube Tire Heavy Flat Repair,Hvy	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	10/19/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

10/19/2017 @ 09:46:04

Wingfoot 10/11/17  
Yard service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 69332**  
**EQUIPMENT # 2976**

Date In: 11/07/2017 Date Out: 11/07/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 7,637 A
			M 73,382 A

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
44	0.50	N	2	11/07/2017	2007WP0100BN	Glass-Component Wiper Windshiel Replace	55.00
44	0.50	N	2	11/07/2017	2004V17165BN	Heating Vent Valve Heater Repair	55.00
SUBTOTAL:							110.00

WORK ORDER TOTALS	TOTAL:	110.00
-------------------	--------	--------

NOTES

11/07/2017 @ 22:14:37

Replace wiper blades  
Open heater valves

CL

Wiper blades complete #44

Heater valves open. Heater working normal. #44

**FASTER WORK ORDER PRINT**

**WORK ORDER # 69356**  
**EQUIPMENT # 2976**

Date In: 11/08/2017 Date Out: 11/08/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 73,382

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
44	1.00	N	2	11/08/2017	2034B60001BN	Light System Bulb Headlight Diagnosis	110.00
SUBTOTAL:							110.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
H6054-LMP	S	2	12.09	11/09/2017	1000001000BS	Unit Services Complete Unit Part Issue	24.18
SUBTOTAL:							24.18

WORK ORDER TOTALS	TOTAL:	134.18
-------------------	--------	--------

NOTES

11/08/2017 @ 14:48:21

DRIVER'S SIDE HEADLIGHT INOP

TT

Drivers side headlamp out, passenger side has water in it. Replace both headlamps and verify normal operation. #44

**FASTER WORK ORDER PRINT**

**WORK ORDER # 69730  
EQUIPMENT # 2976**

Date In: 11/29/2017 Date Out: 11/29/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 73,944

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	11/29/2017	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	11/29/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

11/29/2017 @ 14:39:40

Tracks to Tires 11/14/17  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 69761  
EQUIPMENT # 2976**

Date In: 11/30/2017 Date Out: 11/30/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 74,027

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	68.00	-90.44	11/30/2017	Z017TM1445NN	Tire / Tube Tire Heavy Flat Repair,Hvy	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	11/30/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

11/30/2017 @ 14:39:26

Wingfoot 11/20/17  
Yard service

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 69787 EQUIPMENT # 2976

Date In: 12/01/2017 Date Out: 12/01/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 7,736 A
			M 74,084 A

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
44	0.50	N	2	12/01/2017	2047000001BN	Emission System System Diagnosis	55.00
44	1.00	N	1	12/01/2017	2044F18100BN	Fuel System Filter Fuel 2nd Replace	110.00
44	1.00	N	1	12/01/2017	2034LN5001BN	Light System Light Exterior Diagnosis	110.00
SUBTOTAL:							275.00

### PARTS ISSUED

PART NUMBER/DESCRIPTION	S/NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
3936-FIL	S	1	13.15	12/04/2017	1000001000BS	Unit Services Complete Unit Part Issue	13.15
3604-FIL	S	1	20.86	12/04/2017	1000001000BS	Unit Services Complete Unit Part Issue	20.86
H6054-LMP	S	1	10.42	12/04/2017	1000001000BS	Unit Services Complete Unit Part Issue	10.42
9600-MAC	S	2	8.70	12/04/2017	1000001000BS	Unit Services Complete Unit Part Issue	17.40
47122-GRO	S	1	11.32	12/04/2017	1000001000BS	Unit Services Complete Unit Part Issue	11.32
SUBTOTAL:							73.15

WORK ORDER TOTALS	TOTAL:	348.15
-------------------	--------	--------

### NOTES

12/01/2017 @ 15:24:35

1. Check engine light on, no power
2. Check lights, right side headlamp, right side markere light out.

CL

1. DTCs for restriction in fuel system. Fuel filters restricted with debris.
1. Replace primary and secondary fuel filters. Add conditioner and verify no leaks. Clear DTC and verify normal operation. #44
2. Replace right side headlamp #44
2. Replace marker light on right side rear of truck. #44

NOTE: Radio not install in bracket under dash, microphone was under seat. Inspected cab and found radio underneath seat. Did not reinstall in bracket, Inoperative ??



**FASTER WORK ORDER PRINT**

**WORK ORDER # 70113  
EQUIPMENT # 2976**

Date In: 12/15/2017 Date Out: 12/15/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 74,506

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	46.22	0.00	-46.22	12/15/2017	Z017TM1445NN	Tire / Tube Tire Heavy Flat Repair,Hvy	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	12/15/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

12/15/2017 @ 08:20:27

Wingfoot 12/12/17  
yard service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 70271  
EQUIPMENT # 2976**

Date In: 12/29/2017 Date Out: 12/29/2017 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 74,954

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.00	-92.44	12/29/2017	Z017TM1445NN	Tire / Tube Tire Heavy Flat Repair,Hvy	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	12/29/2017	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

12/29/2017 @ 14:52:39

Wingfoot 12/18/17  
Yard service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 70305  
EQUIPMENT # 2976**

Date In: 01/02/2018 Date Out: 01/02/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 75,008

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	453.92	35.00	-488.92	01/02/2018	Z017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	01/02/2018	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

01/02/2018 @ 14:48:54

Wingfoot 12/19/17  
1 tire

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 70385**  
**EQUIPMENT # 2976**

Date In: 01/04/2018 Date Out: 01/04/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 75,086

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	01/04/2018	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	01/04/2018	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

01/04/2018 @ 07:59:25

Tracks to Tires 12/26/17  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 70584  
EQUIPMENT # 2976**

Date In: 01/16/2018 Date Out: 01/16/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 75,407

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	25.28	64.00	-89.28	01/16/2018	Z017TM1445NN	Tire / Tube Tire Heavy Flat Repair,Hvy	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	01/16/2018	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

01/16/2018 @ 08:53:34

Wingfoot 1/9/18  
Yard service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 70622**  
**EQUIPMENT # 2976**

Date In: 01/17/2018 Date Out: 01/18/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 75,407

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	1.00	N	1	01/17/2018	2170CG0001BS	Compressor Compressor Diagnosis	110.00
SUBTOTAL:							110.00

WORK ORDER TOTALS	TOTAL:	110.00
-------------------	--------	--------

NOTES

01/17/2018 @ 06:26:29

Air leak around compressor  
Replace driver's side wiper blade

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 70633  
EQUIPMENT # 2976**

Date In: 01/17/2018 Date Out: 01/18/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 75,518

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	1.00	N	1	01/18/2018	2247SP4001BS	SNOW PLOW PLOW CONTROL Diagnosis	110.00
SUBTOTAL:							110.00

WORK ORDER TOTALS	TOTAL:	110.00
-------------------	--------	--------

NOTES

01/17/2018 @ 14:49:43

Arm that raises the chain on the plow will not go up and down

pd

chackle that holds plow chain broken replaced it and adjusted chains #64

**FASTER WORK ORDER PRINT**

**WORK ORDER # 70968**  
**EQUIPMENT # 2976**

Date In: 02/08/2018 Date Out: 02/08/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 78,000

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	0.00	32.00	-32.00	02/08/2018	Z017TM1445NN	Tire / Tube Tire Heavy Flat Repair,Hvy	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	02/08/2018	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

02/08/2018 @ 12:11:03

Wingfoot 1/10/18  
Yard service

pd



**FASTER WORK ORDER PRINT**

**WORK ORDER # 70974  
EQUIPMENT # 2976**

Date In: 02/08/2018 Date Out: 02/08/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 78,000

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	02/08/2018	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	02/08/2018	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

02/08/2018 @ 13:37:05

Tracks to Tires 1/15/18  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 71022  
EQUIPMENT # 2976**

Date In: 02/09/2018 Date Out: 02/09/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 78,000

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.00	-92.44	02/09/2018	Z017TM1445NN	Tire / Tube Tire Heavy Flat Repair,Hvy	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	02/09/2018	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

02/09/2018 @ 08:29:39

Wingfoot 2/5/18  
Yard service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 71063  
EQUIPMENT # 2976**

Date In: 02/12/2018 Date Out: 02/12/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 78,000

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	02/12/2018	Z000001055NS	Unit Services Complete Unit Lubrication	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	02/12/2018	Z000001Z99BN	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

02/12/2018 @ 13:25:48

Tracks to Tires 1/31/18  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 71428**  
**EQUIPMENT # 2976**

Date In: 03/02/2018 Date Out: 03/02/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 78,000

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	44.88	140.00	-184.88	03/02/2018	Z017TM1165NS	Tire / Tube Tire Heavy Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	03/02/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

03/02/2018 @ 08:47:41

Wingfoot 2/13/18  
Yard service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 71471  
EQUIPMENT # 2976**

Date In: 03/02/2018 Date Out: 03/02/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 78,000

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	03/02/2018	PML NS	LUBRICATION	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	03/02/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

03/02/2018 @ 15:10:27

Tracks to Tires 2/2/18  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 71848**  
**EQUIPMENT # 2976**

Date In: 03/26/2018 Date Out: 03/28/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 78,000

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
28	1.00	N	1	03/26/2018	2210000001BN	Compaction System Diagnosis	110.00
SUBTOTAL:							110.00

WORK ORDER TOTALS	TOTAL:	110.00
-------------------	--------	--------

NOTES

03/26/2018 @ 07:23:34

HOPPER SWITCH IS STAYING ON

TT

Check switch operation. Needs new switch. Not in stock. Order new one.  
DT

**FASTER WORK ORDER PRINT**

**WORK ORDER # 72151  
EQUIPMENT # 2976**

Date In: 04/17/2018 Date Out: 04/17/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 78,826

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.00	-92.44	04/17/2018	Z017TM1165NS	Tire / Tube Tire Heavy Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/17/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

04/17/2018 @ 11:36:01

Wingfoot 4/2/18  
Yard Service - LRI LRO

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 72265  
EQUIPMENT # 2976**

Date In: 04/19/2018   Date Out: 04/19/2018   Work Order Status: C   Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H                      4,913
			M                      78,826

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	04/19/2018	PML NS	LUBRICATION	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/19/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

04/19/2018 @ 08:53:29

Tracks to Tires 3/14/18  
Lube

pd



**FASTER WORK ORDER PRINT**

**WORK ORDER # 72457  
EQUIPMENT # 2976**

Date In: 04/25/2018 Date Out: 04/25/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 4,913
			M 79,004

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	33.66	105.00	-138.66	04/25/2018	Z017TM1165NS	Tire / Tube Tire Heavy Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/25/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

04/25/2018 @ 14:19:07

Wingfoot 4/17/18  
Yard Service - LF RFI/O

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 72484 EQUIPMENT # 2976

Date In: 04/26/2018 Date Out: 04/27/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364 Y
			M 79,166 Y

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
25	1.00	N	2	04/26/2018	2051MH0165BN	Air Supply Misc Parts Repair	110.00
25	6.50	N	2	04/27/2018	2013DT0100BN	Brakes Drum Air Brake Replace	715.00
25	0.50	N	2	04/27/2018	2042MH0165BN	Cooling Engine Misc Parts Repair	55.00
SUBTOTAL:							880.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
800404K-MBI	S	1	79.74	04/27/2018	1000001000BS	Unit Services Complete Unit Part Issue	79.74
G314000404-GAT	S	1	7.45	04/27/2018	1000001000BS	Unit Services Complete Unit Part Issue	7.45
GG4726ES2G-MBI	S	4	116.57	05/01/2018	1000001000BS	Unit Services Complete Unit Part Issue	466.28
66854B-TWD	S	4	342.59	05/01/2018	1000001000BS	Unit Services Complete Unit Part Issue	1,370.35
370003A-NTL	S	1	51.01	05/01/2018	1000001000BS	Unit Services Complete Unit Part Issue	51.01
3303036-TWD	S	1	2.64	05/01/2018	1000001000BS	Unit Services Complete Unit Part Issue	2.64
75210-NOL	S	9	5.76	05/01/2018	1000001000BS	Unit Services Complete Unit Part Issue	51.82
370900-NSE	S	1	13.59	05/01/2018	1000001000BS	Unit Services Complete Unit Part Issue	13.59
G606050606-GAT	S	1	2.20	05/01/2018	1000001000BS	Unit Services Complete Unit Part Issue	2.20
G606400606-GAT	S	1	7.83	05/01/2018	1000001000BS	Unit Services Complete Unit Part Issue	7.83
GC3030-MBI	S	1	83.81	05/01/2018	1000001000BS	Unit Services Complete Unit Part Issue	83.81
SUBTOTAL:							2,136.73

WORK ORDER TOTALS TOTAL: 3,016.73

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 72484**  
**EQUIPMENT # 2976**

04/26/2018 @ 23:02:03

Switch from heat to a/c  
Abs light on  
Air leak behind cab

JF

#25 - Found leaking air line and purge valve leaking. Repaired line and replaced purge valve.

04/27/2018 @ 23:15:58

#25 - Found right rear abs sensor wire rubbed at diff. Repaired wire.

Drove to verify repair, light went out

#25 - shut off water valves for heater.

#25 - While working on abs found rear brakes at dot. Replaced brake shoes and drums on all drive wheels. Replaced wheel seal at left rear drive.  
Replaced brake chamber at right front drive. Added 9 QTS 80w90 gear oil. Adjusted brakes and torqued wheels to 500#

**FASTER WORK ORDER PRINT**

**WORK ORDER # 72609**  
**EQUIPMENT # 2976**

Date In: 05/08/2018 Date Out: 05/14/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364
			M 79,325

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
25	1.00	N	2	05/08/2018	2044T62165BN	Fuel System Tank Fuel Repair	110.00
25	3.00	N	2	05/14/2018	2054000001BN	Horn System Diagnosis	330.00
SUBTOTAL:							440.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
32P165-ST5	S	2	270.19	05/14/2018	1000001000BS	Unit Services Complete Unit Part Issue	540.38
-FRT	S	1	68.88	05/14/2018	1000001000BS	Unit Services Complete Unit Part Issue	68.88
SUBTOTAL:							609.26

WORK ORDER TOTALS	TOTAL:	1,049.26
-------------------	--------	----------

NOTES

05/08/2018 @ 14:38:45

HORN IS NOT WORKING  
ONE OF THE BANDS THAT HOLDS THE FUEL TANK ON BROKE

NAPA IS ORDERING FUEL TANK BAND

TT

#25 - Found 1 bracket broken on fuel tank and the other bracket cracked. Ordered both brackets and both straps.Truck is down.  
05/14/2018 @ 12:51:45 parts are here  
05/14/2018 @ 19:14:35 #25 - Replaced both fuel tank brackets. Reused straps.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 72651  
EQUIPMENT # 2976**

Date In: 05/09/2018   Date Out: 05/09/2018   Work Order Status: C   Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H                      8,364
			M                      79,475

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	05/09/2018	PML NS	LUBRICATION	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/09/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

05/09/2018 @ 13:35:09

Tracks to Tires 4/23/18  
Lube

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 72861 EQUIPMENT # 2976

Date In: 05/18/2018 Date Out: 05/29/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364
			M 79,692

### PARTS ISSUED

PART NUMBER/ DESCRIPTIION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
10700-LIT	S	1	1.49	05/18/2018	1000001000BS	Unit Services Complete Unit Part Issue	1.49
5040202R3-LIT	S	1	4.61	05/18/2018	1000001000BS	Unit Services Complete Unit Part Issue	4.61
47123-GRO	S	2	12.40	05/18/2018	1000001000BS	Unit Services Complete Unit Part Issue	24.79
94925-LIT	S	1	2.00	05/18/2018	1000001000BS	Unit Services Complete Unit Part Issue	2.00
CV50628-9HD	S	1	122.57	05/18/2018	1000001000BS	Unit Services Complete Unit Part Issue	122.57
109493X-MBI	S	1	70.96	05/18/2018	1000001000BS	Unit Services Complete Unit Part Issue	70.96
150111-LIT	S	1	6.31	05/18/2018	1000001000BS	Unit Services Complete Unit Part Issue	6.31
SUBTOTAL:							232.73

WORK ORDER TOTALS	TOTAL:	232.73
-------------------	--------	--------

### NOTES

05/18/2018 @ 14:32:03

PMD

TT

# FASTER WORK ORDER PRINT

## WORK ORDER # 72970 EQUIPMENT # 2976

Date In: 05/25/2018 Date Out: 05/29/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,475 A
			M 79,973 A

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
23	7.50	N	2	05/29/2018	PMC BS	PM C Service	825.00
44	0.50	N	2	05/25/2018	2054000001BN	Horn System Diagnosis	55.00
44	0.50	N	2	05/25/2018	2054SYG100BN	Horn SwitchHornContr Replace	55.00
SUBTOTAL:							935.00

### PARTS ISSUED

PART NUMBER/DESCRIPTION	S/NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
3936-FIL	S	1	13.35	05/30/2018	1000001000BS	Unit Services Complete Unit Part Issue	13.35
3604XE-FIL	S	1	23.97	05/30/2018	1000001000BS	Unit Services Complete Unit Part Issue	23.97
7740XE-FIL	S	1	51.19	05/30/2018	1000001000BS	Unit Services Complete Unit Part Issue	51.19
9600-MAC	S	2	8.70	05/30/2018	1000001000BS	Unit Services Complete Unit Part Issue	17.40
11232-1BG	S	2	28.30	05/30/2018	1000001000BS	Unit Services Complete Unit Part Issue	56.61
15W40-9OC	S	25	3.65	05/30/2018	1000001000BS	Unit Services Complete Unit Part Issue	91.20
TRANSYNQT-1BG	S	10	8.30	05/30/2018	1000001000BS	Unit Services Complete Unit Part Issue	82.96
DELOXLC55-9OC	S	6	2.82	05/30/2018	1000001000BS	Unit Services Complete Unit Part Issue	16.91
SUBTOTAL:							353.59

WORK ORDER TOTALS	TOTAL:	1,288.59
-------------------	--------	----------

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 72970**  
**EQUIPMENT # 2976**

05/25/2018 @ 21:13:11

PMC  
Horn doesn't work

CL

05/25/2018 @ 22:01:33

#44 Worn horn contact ring inside steering column  
#44 R&R steering and replace horn ring kit. Verify normal operation. Truck on ready line  
Tech #23 to complete PM service next week.

05/29/2018 @ 22:59:05pmc done #23

05/29/2018 @ 22:59:15  
6qts delo



**FASTER WORK ORDER PRINT**

**WORK ORDER # 73174  
EQUIPMENT # 2976**

Date In: 06/11/2018 Date Out: 06/11/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364
			M 80,289

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	44.88	140.00	-184.88	06/11/2018	Z017TM1165NS	Tire / Tube Tire Heavy Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	06/11/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

06/11/2018 @ 10:43:41

Wingfoot 5/29/18  
Yard Service - RFI/O RRI/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 73288  
EQUIPMENT # 2976**

Date In: 06/18/2018 Date Out: 07/12/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364
			M 80,667

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
25	2.50	N	2	06/20/2018	2210000001BN	Compaction System Diagnosis	275.00
SUBTOTAL:							275.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
122571-AEC	S	1	1,924.85	06/20/2018	1000001000BS	Unit Services Complete Unit Part Issue	1,924.85
-FRT	S	1	40.50	06/20/2018	1000001000BS	Unit Services Complete Unit Part Issue	40.50
SUBTOTAL:							1,965.35

WORK ORDER TOTALS	TOTAL:	2,240.35
-------------------	--------	----------

NOTES

06/18/2018 @ 11:24:46

PACKER MOVING VERY SLOWLY AND NOT PACKING ALL THE WAY

TT

#25 - Found signal from prox into power module but no signal out. Needs a power module. Ordered part. ok to run  
06/20/2018 @ 21:24:46 We received the wrong style box. The box that is on the truck is on a hinged panel and hangs upside down. The box we received is designed to sit upright, If installed it will collect water in the lid. Will check with curtis tomorrow.  
06/21/2018 @ 11:04:26 call aec. they said it was right box look inside box for part number to see if they are the same  
07/10/2018 @ 13:51:41 box has been replace with the one that we got in new box replace old box cant get no more

**FASTER WORK ORDER PRINT**

**WORK ORDER # 73311**  
**EQUIPMENT # 2976**

Date In: 06/19/2018 Date Out: 06/19/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364
			M 80,667

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.00	-92.44	06/19/2018	Z017TM1165NS	Tire / Tube Tire Heavy Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	06/19/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

06/19/2018 @ 11:27:23

Wingfoot 6/11/18  
Yard Service - LR/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 73407**  
**EQUIPMENT # 2976**

Date In: 06/26/2018 Date Out: 06/26/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364
			M 80,968

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
CAROLINA ENVIRONMENTAL SYSTEM	0.00	635.00	-635.00	06/26/2018	PMD NS	PM D Service	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	06/26/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

06/26/2018 @ 11:35:05

CES 6/13/18  
PMD

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 73453 EQUIPMENT # 2976

Date In: 07/02/2018 Date Out: 07/13/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364
			M 81,091

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
28	2.00	N	1	07/02/2018	2040000001BN	Engine System Diagnosis	220.00
SUBTOTAL:							220.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
2894943RX-CFR	S	1	583.81	07/06/2018	1000001000BS	Unit Services Complete Unit Part Issue	583.81
SUBTOTAL:							583.81

WORK ORDER TOTALS	TOTAL:	803.81
-------------------	--------	--------

### NOTES

07/02/2018 @ 07:46:14  
Engine light on.  
DT

Pull codes  
Fault code 1885 Aftertreatment intake NOx sensor circuit.  
Order new sensor kit.  
DT

**FASTER WORK ORDER PRINT**

**WORK ORDER # 73524  
EQUIPMENT # 2976**

Date In: 07/05/2018 Date Out: 07/05/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364
			M 81,157

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.00	-92.44	07/05/2018	Z017TM1165NS	Tire / Tube Tire Heavy Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	07/05/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

07/05/2018 @ 11:55:56

Wingfoot 6/29/18  
Yard Service LFI/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 73591**  
**EQUIPMENT # 2976**

Date In: 07/05/2018   Date Out: 07/05/2018   Work Order Status: C   Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H                      8,364
			M                      81,203

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	07/05/2018	PML NS	LUBRICATION	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	07/05/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

07/05/2018 @ 13:36:12

Tracks to Tires 7/2/18  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 73645  
EQUIPMENT # 2976**

Date In: 07/05/2018 Date Out: 07/05/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364
			M 81,203

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	07/05/2018	PML NS	LUBRICATION	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	07/05/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

07/05/2018 @ 14:44:04

Tracks to Tires 6/18/18  
Lube

pd



**FASTER WORK ORDER PRINT**

**WORK ORDER # 74081**  
**EQUIPMENT # 2976**

Date In: 08/06/2018 Date Out: 08/06/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364
			M 82,204

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	08/06/2018	PML NS	LUBRICATION	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	08/06/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

08/06/2018 @ 15:02:53

Tracks to Tires 7/30/18  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 74390  
EQUIPMENT # 2976**

Date In: 08/24/2018 Date Out: 08/24/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364
			M 82,909

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	44.88	140.00	-184.88	08/24/2018	Z017TM1165NS	Tire / Tube Tire Heavy Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	08/24/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

08/24/2018 @ 13:00:30

Wingfoot 8/13/18  
Yard Service RFI/O LFI/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 74429**  
**EQUIPMENT # 2976**

Date In: 08/27/2018   Date Out: 08/28/2018   Work Order Status: C   Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H                      8,364
			M                      82,909

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
23	0.70	N	2	08/27/2018	PMI BS	Annual State In	77.00

SUBTOTAL: 77.00

WORK ORDER TOTALS                      TOTAL: 77.00

NOTES

08/27/2018 @ 20:44:23

PMI

JF  
08/27/2018 @ 22:03:54  
ncsi done#23

**FASTER WORK ORDER PRINT**

**WORK ORDER # 74496  
EQUIPMENT # 2976**

Date In: 09/04/2018 Date Out: 09/04/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364
			M 83,136

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	1.50	N	1	09/04/2018	2040000001BN	Engine System Diagnosis	165.00
SUBTOTAL:							165.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
7236-BAT	S	3	140.13	09/04/2018	1000001000BS	Unit Services Complete Unit Part Issue	420.39
7212-MAC	S	1	3.14	09/04/2018	1000001000BS	Unit Services Complete Unit Part Issue	3.14
SUBTOTAL:							423.52

WORK ORDER TOTALS	TOTAL:	588.52
-------------------	--------	--------

NOTES

09/04/2018 @ 06:42:15  
TRUCK WILL NOT START.  
DT  
jumped truck across street  
brought truck to shop and replaced 3 batterys #64

**FASTER WORK ORDER PRINT**

**WORK ORDER # 74524**  
**EQUIPMENT # 2976**

Date In: 09/05/2018 Date Out: 09/05/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364
			M 83,136

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	09/05/2018	PML NS	LUBRICATION	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	09/05/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

09/05/2018 @ 08:56:35

Tracks to Tires 8/27/18  
Lube

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 74976 EQUIPMENT # 2976

Date In: 10/09/2018 Date Out: 10/10/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 8,364
			M 84,088

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	2.00	N	2	10/09/2018	8032000001BN	Cranking System System Diagnosis	220.00
SUBTOTAL:							220.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
7212-MAC	S	1	3.14	10/10/2018	1000001000BS	Unit Services Complete Unit Part Issue	3.14
SUBTOTAL:							3.14

WORK ORDER TOTALS	TOTAL:	223.14
-------------------	--------	--------

### NOTES

10/09/2018 @ 12:48:35

Truck would not restart. Road call to Shell station off High house.  
DT

found bad connection in fuse box under air cleaner on driver side of truck  
was able to get truck started told operator to finish route and bring truck by shop #64

# FASTER WORK ORDER PRINT

## WORK ORDER # 74983 EQUIPMENT # 2976

Date In: 10/09/2018 Date Out: 10/17/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,088 A
			M 84,467 A

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
50	3.00	N	2	10/09/2018	2032MH0001BN	Cranking System Misc Parts Diagnosis	330.00
50	0.50	N	2	10/16/2018	2042CB1165BN	Cooling Engine Clamp Hose Repair	55.00
50	2.00	N	2	10/16/2018	2214FL1165BN	Compact Hopper FLIPPER ASSY. Repair	220.00
SUBTOTAL:							605.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
7051507-BK	S	2	6.15	10/17/2018	1000001000BS	Unit Services Complete Unit Part Issue	12.30
SUBTOTAL:							12.30

WORK ORDER TOTALS	TOTAL:	617.30
-------------------	--------	--------

### NOTES

10/09/2018 @ 16:39:37

Would not start after being shut off.

CL

#50 Fault can not be replicate.

Truck started every time.

On going diagnostic.

During inspection found exaust leak.

Elbow, flex pipe, gasket, blanket, clamps.

Parts on order.

10/10/2018 @ 08:08:41all parts order southern truck

10/10/2018 @ 13:30:27

DRIVER STOPPED BY AND SAID ONE OF THE FLIPPER CONTROLS IS ALSO BROKEN OFF

TT

10/10/2018 @ 17:30:49

#50 Flipper control lever replace.(fabricated similar metal thickness & shape)

10/16/2018 @ 07:58:46 parts in. #50 Parts installed ( Flex pipe)

Low coolant warning light on. 25 qts of coolant added.

#50 Performed a radiator pressure test, a leak was found. Replace a section of the radiator hose and to clamps.

Retested, no leaks.

Unit is at the ready line.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 75098  
EQUIPMENT # 2976**

Date In: 10/17/2018 Date Out: 10/23/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,098 Y
			M 84,508 Y

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
44	3.00	N	2	10/17/2018	2047000001BN	Emission System System Diagnosis	330.00
44	1.00	N	2	10/17/2018	2044F15100BN	Fuel System Filter Fuel Pri Replace	110.00
SUBTOTAL:							440.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
9600-MAC	S	2	8.70	10/19/2018	1000001000BS	Unit Services Complete Unit Part Issue	17.40
3936-FIL	S	1	13.64	10/19/2018	1000001000BS	Unit Services Complete Unit Part Issue	13.64
3604XE-FIL	S	1	24.50	10/19/2018	1000001000BS	Unit Services Complete Unit Part Issue	24.50
SUBTOTAL:							55.54

WORK ORDER TOTALS	TOTAL:	495.54
-------------------	--------	--------

NOTES

10/17/2018 @ 16:23:20

Tow in  
Truck cranks over but will not run, engine light on

CL

10/17/2018 @ 19:06:33

#44 Check for DTCS, code stored for low fuel rail pressure. Perform fuel system test for lift pump. Pump running but not getting enough fuel to injection pump. Primary fuel filter was slightly loose and leaking fuel. Will replace fuel filters, clear DTC and retest.

10/17/2018 @ 20:04:11

#44 Replace fuel filters. Primary filter was leaking and had substantial amount of restriction. Perform fuel test again and all test showed normal. Drove truck, power normal and did not reset any DTCs. Truck parked across street.



# FASTER WORK ORDER PRINT

## WORK ORDER # 75120 EQUIPMENT # 2976

Date In: 10/18/2018 Date Out: 10/18/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,098
			M 84,508

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	10/18/2018	PML NS	LUBRICATION	0.00
SUBTOTAL:							0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	10/18/2018	Z000001Z99NN	Unit Services Complete Unit Transaction Fee	0.00
SUBTOTAL:					0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

### NOTES

10/18/2018 @ 08:15:58

Tracks to Tires 10/9/18  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 75205  
EQUIPMENT # 2976**

Date In: 10/23/2018 Date Out: 10/23/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,098
			M 84,562

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.00	-92.44	10/23/2018	Z017TM2165NS	Tire / Tube Tire Industrial Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/19/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00
WORK ORDER TOTALS					TOTAL: 25.00

NOTES

10/23/2018 @ 08:04:34

Wingfoot 10/2/18  
Yard Service - LFI/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 75262**  
**EQUIPMENT # 2976**

Date In: 10/23/2018 Date Out: 10/23/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,098
			M 84,562

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	1,088.00	105.00	-1,193.00	10/23/2018	Z017TM2100NS	Tire / Tube Tire Industrial Replace	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/19/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00
WORK ORDER TOTALS					TOTAL: 25.00

NOTES

10/23/2018 @ 11:15:47

Wingfoot 10/12/18  
2 tires

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 75303  
EQUIPMENT # 2976**

Date In: 10/25/2018 Date Out: 10/31/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,098
			M 84,632

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
55	0.25	N	1	10/25/2018	2004V30165BN	Heating Vent Vent Repair	27.50
64	0.25	N	1	10/25/2018	2004BLM165BN	Heating Vent Blower Heater Repair	27.50
SUBTOTAL:							55.00

WORK ORDER TOTALS	TOTAL:	55.00
-------------------	--------	-------

NOTES

10/25/2018 @ 07:43:42

RAISE CAB AND TURN ON HEAT

TT

#55 assisted #64 with cab access  
turned on heat #64

**FASTER WORK ORDER PRINT**

**WORK ORDER # 75502  
EQUIPMENT # 2976**

Date In: 11/05/2018 Date Out: 11/05/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,098
			M 84,950

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.00	-92.44	11/05/2018	Z017TM2165NS	Tire / Tube Tire Industrial Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/19/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00
WORK ORDER TOTALS					TOTAL: 25.00

NOTES

11/05/2018 @ 08:53:00

Wingfoot 10/29/18  
Yard Service LRI/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 75686  
EQUIPMENT # 2976**

Date In: 11/15/2018 Date Out: 11/15/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,098
			M 85,148

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
BARBOUR'S TOWING & RECOVERY	0.00	200.00	-200.00	11/15/2018	Z000001500NS	Unit Services Complete Unit Towing	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/18/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	25.00
-------------------	--------	-------

NOTES

11/15/2018 @ 07:22:52

Barbours 10/17/18  
Tow

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 75848**  
**EQUIPMENT # 2976**

Date In: 11/21/2018 Date Out: 11/21/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,098
			M 85,421

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
55	2.00	N	2	11/21/2018	2040000001BN	Engine System Diagnosis	220.00
SUBTOTAL:							220.00

WORK ORDER TOTALS	TOTAL:	220.00
-------------------	--------	--------

NOTES

11/21/2018 @ 11:41:21

CUT OFF ON ROUTE AND WOULD NOT RESTART

TT

#55 several codes in it. cleared and ran for several hours and short test drive. Could not get it to stop running but it did have a code for ignition voltage and when I first got in it to pull in shop it would not turn over at all. Several key attempts and it started fine. Wiggled harnesses and battery cables and could not duplicate issue. Parked it and let driver take it.

# FASTER WORK ORDER PRINT

## WORK ORDER # 75913 EQUIPMENT # 2976

Date In: 11/26/2018 Date Out: 11/27/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,098
			M 85,489

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
44	1.00	N	2	11/26/2018	2040000001BN	Engine System Diagnosis	110.00
44	2.00	N	2	11/26/2018	2044F18100BN	Fuel System Filter Fuel 2nd Replace	220.00
44	4.00	N	2	11/26/2018	2034LN5190BN	Light System Light Exterior Wiring Repair	440.00
50	2.00	N	2	11/26/2018	2102AA3100BN	Light Emergency ASM LightStrobe Replace	220.00
SUBTOTAL:							990.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
3604XE-FIL	S	1	24.50	11/27/2018	1000001000BS	Unit Services Complete Unit Part Issue	24.50
3936-FIL	S	1	13.64	11/27/2018	1000001000BS	Unit Services Complete Unit Part Issue	13.64
9600-MAC	S	2	8.70	11/27/2018	1000001000BS	Unit Services Complete Unit Part Issue	17.40
60362Y-LIT	S	1	68.67	11/27/2018	1000001000BS	Unit Services Complete Unit Part Issue	68.67
725255-NW	S	50	0.56	11/27/2018	1000001000BS	Unit Services Complete Unit Part Issue	28.05
7304378-BK	S	1	155.49	11/27/2018	1000001000BS	Unit Services Complete Unit Part Issue	155.49
7825334-BK	S	1	4.69	11/27/2018	1000001000BS	Unit Services Complete Unit Part Issue	4.69
SUBTOTAL:							312.43

WORK ORDER TOTALS TOTAL: 1,302.43

### NOTES

11/26/2018 @ 14:13:11  
Truck cut off while on route.  
DT

11/26/2018 @ 15:57:08  
#44 DTC 0559, fuel rail pressure low. Has restricted fuel filters  
#44 Replace fuel filters. Clear DTC and verify normal operation.  
11/26/2018 @ 18:30:59  
#44 Side marker not working  
#44 Strobe light on rear of truck broken off

11/26/2018 @ 19:34:39  
#44 Two broken wires inside body causing left side marker to not work.  
#44 Repair harness to left side mid body marker light. Repair harness to rear strobe light. Verify normal operation.  
#50 Replace rear strobe light assembly. Truck parked across street



# FASTER WORK ORDER PRINT

## WORK ORDER # 76011 EQUIPMENT # 2976

Date In: 12/01/2018 Date Out: 12/03/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,298
			M 85,652

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
50	4.00	N	2	12/01/2018	PMA BS	PM A Service	440.00
SUBTOTAL:							440.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1748XD-FIL	S	1	29.41	12/03/2018	1000001000BS	Unit Services Complete Unit Part Issue	29.41
3604-FIL	S	1	21.66	12/03/2018	1000001000BS	Unit Services Complete Unit Part Issue	21.66
3936-FIL	S	1	13.64	12/03/2018	1000001000BS	Unit Services Complete Unit Part Issue	13.64
9600-MAC	S	2	8.70	12/03/2018	1000001000BS	Unit Services Complete Unit Part Issue	17.40
11232-1BG	S	2	28.30	12/03/2018	1000001000BS	Unit Services Complete Unit Part Issue	56.61
DELO400-9OC	S	24	3.97	12/03/2018	1000001000BS	Unit Services Complete Unit Part Issue	95.16
SUBTOTAL:							233.88

WORK ORDER TOTALS	TOTAL:	673.88
-------------------	--------	--------

### NOTES

12/01/2018 @ 10:47:48

PMA Service

JF

12/01/2018 @ 14:06:34

#50 PMA Complete.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 76299  
EQUIPMENT # 2976**

Date In: 12/13/2018 Date Out: 12/13/2018 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,298
			M 85,876

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
BARBOUR'S TOWING & RECOVERY	0.00	250.00	-250.00	12/13/2018	Z000001500NS	Unit Services Complete Unit Towing	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/18/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	25.00
-------------------	--------	-------

NOTES

12/13/2018 @ 13:17:28

Barbours 11/26/18  
Tow

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 76571  
EQUIPMENT # 2976**

Date In: 01/07/2019 Date Out: 01/07/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,298
			M 86,429

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	01/07/2019	PML NS	LUBRICATION	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/15/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

01/07/2019 @ 08:42:59

Tracks to Tires 12/21/18  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 76586  
EQUIPMENT # 2976**

Date In: 01/07/2019 Date Out: 01/07/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,298
			M 86,429

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	01/07/2019	PML NS	LUBRICATION	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/15/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

01/07/2019 @ 09:01:30

Tracks to Tires 12/21/18  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 76701**  
**EQUIPMENT # 2976**

Date In: 01/11/2019 Date Out: 01/11/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,298
			M 86,883

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.00	-92.44	01/11/2019	Z017TM2165NS	Tire / Tube Tire Industrial Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/15/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

01/11/2019 @ 10:33:57

Wingfoot 12/26/18  
Yard Service RFI/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 76847  
EQUIPMENT # 2976**

Date In: 01/17/2019 Date Out: 01/17/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,298
			M 87,015

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.00	-92.44	01/17/2019	Z017TM2165NS	Tire / Tube Tire Industrial Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/15/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

01/17/2019 @ 07:30:39

Wingfoot 1/14/19  
Yard Service RRI/O

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 76904 EQUIPMENT # 2976

Date In: 01/17/2019 Date Out: 01/17/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,298
			M 87,128

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	01/17/2019	PML NS	LUBRICATION	0.00
SUBTOTAL:							0.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/15/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

### NOTES

01/17/2019 @ 14:05:02

Tracks to Tires 1/14/19  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 77189**  
**EQUIPMENT # 2976**

Date In: 02/05/2019 Date Out: 02/06/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,298
			M 87,682

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
28	1.00	N	1	02/05/2019	2000001001BS	Unit Services Complete Unit Diagnosis	110.00
SUBTOTAL:							110.00

WORK ORDER TOTALS	TOTAL:	110.00
-------------------	--------	--------

NOTES

02/05/2019 @ 08:51:04

Check leaking hose

pd

Find leak and repair.  
DT



**FASTER WORK ORDER PRINT**

**WORK ORDER # 77405  
EQUIPMENT # 2976**

Date In: 02/18/2019 Date Out: 02/18/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 88,317

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
55	3.50	N	2	02/18/2019	2040000001BN	Engine System Diagnosis	385.00
SUBTOTAL:							385.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
7031509-BK	S	1	22.20	02/19/2019	1000001000BS	Unit Services Complete Unit Part Issue	22.20
SUBTOTAL:							22.20

WORK ORDER TOTALS	TOTAL:	407.20
-------------------	--------	--------

NOTES

02/18/2019 @ 12:24:59

UNIT TOWED IN. IS BLOWING WHITE SMOKE FROM ENGINE AREA ON ACCELERATION AND WHILE PACKER IS BEING RUN

KEYS IN TRUCK

TT

#55 Could not duplicate smoking problem but did notice the exhaust tip was crushed and could have let in a bunch of rain we had last night. Cut off exhaust and installed a tractor cap to eliminate that possibility. Had to replace switch for PTO to get it running and check the packer operation. Still no smoke issues.

02/19/2019 @ 13:01:36

Issue with tailgate

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 77455**  
**EQUIPMENT # 2976**

Date In: 02/19/2019   Date Out: 02/19/2019   Work Order Status: C   Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H                      9,630
			M                      88,317

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
55	2.50	N	2	02/19/2019	2214000001BN	Compact Hopper System Diagnosis	275.00
SUBTOTAL:							275.00

WORK ORDER TOTALS	TOTAL:	275.00
-------------------	--------	--------

NOTES

02/19/2019 @ 15:00:19

Tailgate locks won't lock

CL

#55 Found a broken air line to hydraulic valving. Close nough to the fitting to be able to reuse the air line and reconnect it.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 77578  
EQUIPMENT # 2976**

Date In: 03/01/2019 Date Out: 03/01/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 88,602

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.00	-92.44	03/01/2019	Z017TM2165NS	Tire / Tube Tire Industrial Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/12/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

03/01/2019 @ 13:13:50

Wingfoot 2/25/19  
Yard Service LFI/O

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 77618 EQUIPMENT # 2976

Date In: 03/05/2019 Date Out: 03/06/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 88,602

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
25	1.00	N	1	03/05/2019	2000001065BN	Unit Services Complete Unit Jump Start	110.00
25	0.50	N	1	03/05/2019	2044F18100BN	Fuel System Filter Fuel 2nd Replace	55.00
25	0.50	N	1	03/05/2019	2044F15100BN	Fuel System Filter Fuel Pri Replace	55.00
25	1.00	N	1	03/05/2019	2041F10100BN	Air Intake Engi Filter Air Replace	110.00
25	1.00	N	1	03/05/2019	2027F58010BN	Transmission Au Fluid Transmiss Fill Fluids	110.00
SUBTOTAL:							440.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
7823215-BK	S	5	1.29	03/05/2019	1000001000BS	Unit Services Complete Unit Part Issue	6.47
3604-FIL	S	1	21.66	03/05/2019	1000001000BS	Unit Services Complete Unit Part Issue	21.66
3936-FIL	S	1	13.64	03/05/2019	1000001000BS	Unit Services Complete Unit Part Issue	13.64
9600-MAC	S	2	8.70	03/05/2019	1000001000BS	Unit Services Complete Unit Part Issue	17.40
500167-FIL	S	1	54.72	03/05/2019	1000001000BS	Unit Services Complete Unit Part Issue	54.72
TRANSYNQT-1BG	S	17	8.94	03/05/2019	1000001000BS	Unit Services Complete Unit Part Issue	152.03
SUBTOTAL:							265.91

WORK ORDER TOTALS TOTAL: 705.91

### NOTES

03/05/2019 @ 08:00:29

#### JUMP START

TT

#25 - No power to gauges when key on. Found ecm fuse corroded. Cleaned connection and replaced fuse.  
Truck cranks but no start.- Pulled code for low fuel rail pressure. Replaced fuel filters.  
When driving truck to shop from ready line transmission was slipping. Found trans fluid low. Added 17 qts test drove and checked for leaks, found none.  
Found air filter clogged and replaced.  
Driver waited for repairs to be made and took truck on route.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 77629**  
**EQUIPMENT # 2976**

Date In: 03/05/2019 Date Out: 03/05/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 88,602

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.00	-92.44	03/05/2019	Z017TM2165NS	Tire / Tube Tire Industrial Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/12/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

03/05/2019 @ 09:46:20

Wingfoot 2/20/19  
Yard Service LRI/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 77660**  
**EQUIPMENT # 2976**

Date In: 03/05/2019 Date Out: 03/05/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 88,602

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	03/05/2019	PML NS	LUBRICATION	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/12/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	27.00
-------------------	--------	-------

NOTES

03/05/2019 @ 10:26:10

Tracks to Tires 2/18/19  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 78031  
EQUIPMENT # 2976**

Date In: 03/28/2019 Date Out: 03/28/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 89,478

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
55	1.00	N	2	03/28/2019	2051000001BN	Air Supply System Diagnosis	110.00
55	1.00	N	2	03/28/2019	2013000040BN	Brakes System Adjust	110.00
SUBTOTAL:							220.00

WORK ORDER TOTALS	TOTAL:	220.00
-------------------	--------	--------

NOTES

03/28/2019 @ 16:45:58

Truck is loosing air pressure. Parked across street.

#55 Air tanks were drained and built up pressure pretty well. Pedal felt a little low but no leaks found at all.  
Adjusted brakes intermediate axle was pretty far out.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 78069**  
**EQUIPMENT # 2976**

Date In: 04/01/2019 Date Out: 04/04/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 89,478

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
25	1.50	N	1	04/01/2019	2051MH0165BN	Air Supply Misc Parts Repair	165.00
SUBTOTAL:							165.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
800404K-MBI	S	1	80.22	04/02/2019	1000001000BS	Unit Services Complete Unit Part Issue	80.22
SUBTOTAL:							80.22

WORK ORDER TOTALS	TOTAL:	245.22
-------------------	--------	--------

NOTES

04/01/2019 @ 10:48:12

AIR LEAK

TT

#25 - Found air leaking from exhaust on purge valve. Replaced valve. Ran truck to verify repair.



**FASTER WORK ORDER PRINT**

**WORK ORDER # 78116  
EQUIPMENT # 2976**

Date In: 04/04/2019 Date Out: 04/04/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 89,478

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	11.22	35.00	-46.22	04/04/2019	Z017TM2165NS	Tire / Tube Tire Industrial Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/12/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

04/04/2019 @ 10:01:09

Wingfoot 3/29/19  
Yard Service LF

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 78277**  
**EQUIPMENT # 2976**

Date In: 04/12/2019 Date Out: 04/12/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 89,891

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.00	-92.44	04/12/2019	Z017TM2165NS	Tire / Tube Tire Industrial Repair	0.00
SUBTOTAL:							0.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/12/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00
WORK ORDER TOTALS					TOTAL: 27.00

NOTES

04/12/2019 @ 09:21:25

Wingfoot 4/8/19  
Yard Service - RRI/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 78337  
EQUIPMENT # 2976**

Date In: 04/15/2019 Date Out: 04/15/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 89,891

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.00	6.50	04/15/2019	Z017TM2165BS	Tire / Tube Tire Industrial Repair	98.94
SUBTOTAL:							98.94

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/15/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	27.00
SUBTOTAL:					27.00

WORK ORDER TOTALS	TOTAL:	125.94
-------------------	--------	--------

NOTES

04/15/2019 @ 14:12:32

Wingfoot 4/15/19  
Yard Service - RFI/O

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 78395 EQUIPMENT # 2976

Date In: 04/23/2019 Date Out: 05/06/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 90,182

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	1.50	N	1	04/23/2019	2000001065BN	Unit Services Complete Unit Jump Start	165.00
64	4.00	N	1	04/26/2019	2065H58100BS	Hydraulic Syste Hose Hydraulic Replace	440.00
64	2.50	N	1	05/03/2019	2047S6U100BS	Emission System SensorEmission Replace	275.00
64	1.00	N	1	05/03/2019	2043A09520BS	Exhaust Engine EXHAUST DPF Disinfect	110.00
SUBTOTAL:							990.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTIION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
3604-FIL	S	1	22.30	04/23/2019	1000001000BS	Unit Services Complete Unit Part Issue	22.30
3936-FIL	S	1	14.04	04/23/2019	1000001000BS	Unit Services Complete Unit Part Issue	14.04
9600-MAC	S	2	8.70	04/23/2019	1000001000BS	Unit Services Complete Unit Part Issue	17.40
500167-FIL	S	1	55.82	04/23/2019	1000001000BS	Unit Services Complete Unit Part Issue	55.82
HYD46-9OC	S	75	11.51	04/23/2019	1000001000BS	Unit Services Complete Unit Part Issue	862.88
5293295RX-CFR	S	1	569.21	04/30/2019	1000001000BS	Unit Services Complete Unit Part Issue	569.21
GWON46100-1BG	S	1	22.80	04/30/2019	1000001000BS	Unit Services Complete Unit Part Issue	22.80
7321202-BK	S	2	4.98	04/30/2019	1000001000BS	Unit Services Complete Unit Part Issue	9.96
5283311RX-CFR	S	1	529.17	04/30/2019	1000001000BS	Unit Services Complete Unit Part Issue	529.17
DEF002-NAF	S	1	16.31	05/03/2019	1000001000BS	Unit Services Complete Unit Part Issue	16.31
SUBTOTAL:							2,119.88

WORK ORDER TOTALS

TOTAL: 3,109.88

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 78395**  
**EQUIPMENT # 2976**

no startt across street

got truck started and brought to shop  
replaced fuel filters  
found leaking hyd line from tank to pump  
filled hyd fluid told operator to bring truck back for repair on thursday #64  
replaced 2 1/2 inch suction hose from hyd tank to pto  
put hose gaurds and straps on line refilled hyd tank #64  
check engine light on for nox sensor #1  
parts on order should be in on monday #64  
replaced intake nox sensor #1  
performed regen #64

# FASTER WORK ORDER PRINT

## WORK ORDER # 78445 EQUIPMENT # 2976

Date In: 04/24/2019 Date Out: 04/24/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 90,182

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.00	6.50	04/24/2019	Z017TM2165BS	Tire / Tube Tire Industrial Repair	98.94
SUBTOTAL:							98.94

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	04/24/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS TOTAL: 123.94

### NOTES

04/24/2019 @ 14:16:22

Wingfoot 4/23/19  
Yard Service - LRI/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 78457**  
**EQUIPMENT # 2976**

Date In: 04/24/2019 Date Out: 05/01/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 90,182

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
50	1.00	N	2	04/24/2019	2000BL4001BN	Unit Services Body Rear Diagnosis	110.00
SUBTOTAL:							110.00

WORK ORDER TOTALS	TOTAL:	110.00
-------------------	--------	--------

NOTES

04/24/2019 @ 15:10:44

REPAIR STEP THAT WORKERS STAND ON IN THE BACK OF THE TRUCK

TT

#50 The step came off the supporting bolt and frame bracket.  
Also a fasten bolt was missing.  
Put the step back on place and replace the bolt.

# FASTER WORK ORDER PRINT

## WORK ORDER # 78560 EQUIPMENT # 2976

Date In: 05/01/2019 Date Out: 05/01/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 90,503

### SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	0.00	05/01/2019	PML BS	LUBRICATION	40.00
SUBTOTAL:							40.00

### MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/01/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	65.00
-------------------	--------	-------

### NOTES

05/01/2019 @ 15:12:54

Tracks to Tires 5/1/19  
Lube

pd



**FASTER WORK ORDER PRINT**

**WORK ORDER # 78581**  
**EQUIPMENT # 2976**

Date In: 05/01/2019   Date Out: 05/01/2019   Work Order Status: C   Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H                      9,630
			M                      90,503

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	0.00	05/01/2019	PML BS	LUBRICATION	40.00
SUBTOTAL:							40.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/01/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	65.00
-------------------	--------	-------

NOTES

05/01/2019 @ 15:43:10

Tracks to Tires 5/1/19  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 78665  
EQUIPMENT # 2976**

Date In: 05/07/2019 Date Out: 05/10/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 90,706

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
44	2.00	N	2	05/08/2019	2047MH0100BN	Emission System Misc Parts Replace	220.00
44	1.50	N	2	05/08/2019	2047REGREGBN	Emission System REGEN REGEN	165.00
44	3.50	N	2	05/08/2019	2040000001BN	Engine System Diagnosis	385.00
SUBTOTAL:							770.00

PARTS ISSUED

PART NUMBER/ DESCRIPTIION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
2888173-CFR	S	1	470.22	05/08/2019	1000001000BS	Unit Services Complete Unit Part Issue	470.22
4376837-CFR	S	1	52.33	05/08/2019	1000001000BS	Unit Services Complete Unit Part Issue	52.33
2880215-CFR	S	2	17.66	05/08/2019	1000001000BS	Unit Services Complete Unit Part Issue	35.31
3604-FIL	S	1	22.30	05/08/2019	1000001000BS	Unit Services Complete Unit Part Issue	22.30
3936-FIL	S	1	14.04	05/08/2019	1000001000BS	Unit Services Complete Unit Part Issue	14.04
9600-MAC	S	2	8.70	05/08/2019	1000001000BS	Unit Services Complete Unit Part Issue	17.40
DELOXLC55-9OC	S	31	2.99	05/09/2019	1000001000BS	Unit Services Complete Unit Part Issue	92.66
SUBTOTAL:							704.26

WORK ORDER TOTALS	TOTAL:	1,474.26
-------------------	--------	----------

NOTES

05/07/2019 @ 14:36:58

CHECK ENGINE LIGHT IS ON AND TRUCK IS LOSING POWER

TT

05/07/2019 @ 21:28:38

#44 DEF injector fault, reactor tube clogged with deposits. Parts ordered, truck is down.  
05/08/2019 @ 11:09:55 parts here

05/08/2019 @ 16:32:54

#44 Replace DEF injector and gaskets. Clean out reactor tube of DEF deposits. Install new gaskets and verify no leaks.  
#44 Perform stationary regen to confirm aftertreatment system working normal. Truck parked across street.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 78983  
EQUIPMENT # 2976**

Date In: 05/30/2019 Date Out: 05/30/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 91,439

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	0.00	05/30/2019	PML BS	LUBRICATION	40.00
SUBTOTAL:							40.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/30/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	65.00
-------------------	--------	-------

NOTES

05/30/2019 @ 12:37:56

Tracks to Tires 5/24/19  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 79146**  
**EQUIPMENT # 2976**

Date In: 06/11/2019 Date Out: 06/11/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 91,654

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.10	6.50	06/11/2019	Z017TM2165BS	Tire / Tube Tire Industrial Repair	99.04
SUBTOTAL:							99.04

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	06/11/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	124.04
-------------------	--------	--------

NOTES

06/11/2019 @ 14:39:04

Wingfoot 6/10/19  
Yard Service - LFI/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 79215  
EQUIPMENT # 2976**

Date In: 06/17/2019 Date Out: 06/25/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 91,702

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
23	4.00	N	2	06/19/2019	PMA BS	PM A Service	440.00
23	0.70	N	2	06/24/2019	PMI BS	Annual State In	77.00
44	1.00	N	2	06/17/2019	2013MH0001BN	Brakes Misc Parts Diagnosis	110.00
50	6.00	N	2	06/24/2019	2034SY5100BN	Light System BRAKE LT\SWITCH Replace	660.00
SUBTOTAL:							1,287.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1748XD-FIL	S	1	30.00	06/19/2019	1000001000BS	Unit Services Complete Unit Part Issue	30.00
3604-FIL	S	1	22.30	06/19/2019	1000001000BS	Unit Services Complete Unit Part Issue	22.30
3936-FIL	S	1	14.04	06/19/2019	1000001000BS	Unit Services Complete Unit Part Issue	14.04
9600-MAC	S	2	8.70	06/19/2019	1000001000BS	Unit Services Complete Unit Part Issue	17.40
11232-1BG	S	2	29.22	06/19/2019	1000001000BS	Unit Services Complete Unit Part Issue	58.44
DELO400-9OC	S	24	3.97	06/19/2019	1000001000BS	Unit Services Complete Unit Part Issue	95.16
SUBTOTAL:							237.34

WORK ORDER TOTALS TOTAL: 1,524.34

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 79215**  
**EQUIPMENT # 2976**

06/17/2019 @ 12:58:31

**PARKING BRAKE IS NOT HOLDING**  
**NCSI**  
**PMA**

**KEYS IN TRUCK**

**TT**

#44 Brakes out of adjustment. Linings just over 3/8 inch. Adjust brakes and verify auto slack adjusters working.

06/18/2019 @ 14:10:49

**TRUCK IS HERE FOR THE PM SERVICE - KEYS INSIDE IT**

**TT**

06/18/2019 @ 22:57:52

pm done #23

needs brake switch will inspect after brake light issue is fixed #23

06/19/2019 @ 17:14:41

tried brake switch we had in stock did not fit will need right brake switch #23

06/21/2019 @ 08:12:31 parts here on his tool box

06/21/2019 @ 21:54:55

both brake switches replaced #23 #50

pmi done #23

06/24/2019 @ 21:26:43

#50 replace the neutral safety switch.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 79330  
EQUIPMENT # 2976**

Date In: 06/24/2019 Date Out: 06/24/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 92,102

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.10	6.50	06/24/2019	Z017TM2165BS	Tire / Tube Tire Industrial Repair	99.04
SUBTOTAL:							99.04

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	06/24/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	124.04
-------------------	--------	--------

NOTES

06/24/2019 @ 14:49:17

Wingfoot 6/24/19  
Yard Service LRI/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 79336  
EQUIPMENT # 2976**

Date In: 06/25/2019 Date Out: 06/25/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 92,102

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	2.00	N	1	06/25/2019	2051000001BN	Air Supply System Diagnosis	220.00
SUBTOTAL:							220.00

WORK ORDER TOTALS	TOTAL:	220.00
-------------------	--------	--------

NOTES

06/25/2019 @ 08:06:47  
Check for air leak  
DT

found two air lines under front of truck that had come loose allowing air to leak out of the system  
repaired air lines  
test drove truck #64



# FASTER WORK ORDER PRINT

## WORK ORDER # 79509 EQUIPMENT # 2976

Date In: 07/05/2019 Date Out: 07/18/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 92,102

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
55	5.50	N	2	07/08/2019	2214000001BN	Compact Hopper System Diagnosis	605.00
55	4.00	N	2	07/09/2019	2210000001BN	Compaction System Diagnosis	440.00
55	6.00	N	2	07/10/2019	2036WU6001BN	Warning Device Wiring Reverse Diagnosis	660.00
55	0.50	N	2	07/10/2019	2214DP2165BN	Compact Hopper Door Hopper Repair	55.00
SUBTOTAL:							1,760.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
G314000202-GAT	S	1	10.31	07/11/2019	1000001000BS	Unit Services Complete Unit Part Issue	10.31
G311000202-GAT	S	1	4.65	07/11/2019	1000001000BS	Unit Services Complete Unit Part Issue	4.65
NBH106-NBH	S	1	19.51	07/11/2019	1000001000BS	Unit Services Complete Unit Part Issue	19.51
735500-BEL	S	100	1.20	07/11/2019	1000001000BS	Unit Services Complete Unit Part Issue	119.60
7821108-BK	S	5	0.55	07/11/2019	1000001000BS	Unit Services Complete Unit Part Issue	2.75
123303-AEC	S	1	321.95	07/18/2019	1000001000BS	Unit Services Complete Unit Part Issue	321.95
120018-AEC	S	1	129.51	07/18/2019	1000001000BS	Unit Services Complete Unit Part Issue	129.51
-FRT	S	1	23.97	07/18/2019	1000001000BS	Unit Services Complete Unit Part Issue	23.97
7709231-BK	S	1	12.59	07/19/2019	1000001000BS	Unit Services Complete Unit Part Issue	12.59
SUBTOTAL:							644.83

WORK ORDER TOTALS TOTAL: 2,404.83

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 79509**  
**EQUIPMENT # 2976**

**07/05/2019 @ 14:49:37**

1. Packer running slow
2. Loose wires at top of arm?

**CL**

#55 Need to repair wiring across top of body, goes to accelerator and to body ajar prox switch. May have to do more wiring repairs and troubleshooting after this. Wiring ripped completely off. Parts ordered  
07/09/2019 @ 11:31:11 parts here

#55 Repaired all the wiring in hopper area and on top of the truck. Everything working except rear camera. Will check this again tomorrow after the truck returns.

**07/10/2019 @ 13:37:11**

**TAILGATE LOCKS NOT LOCKING**

**TT**

#55 Found one broken air line to air solenoid for tailgate lock. Also had some corrosion on air cylinder solenoid. Cleaned up and now working.

Found rear camera cable was not hooked up and tied up on left side in hopper area. Reconnected and still not working. Tried to check the one in 2977 but could not find keys. Will continue to check tomorrow evening

Installed rear camera and cable from camera to junction at body/cab. Functioning fine now

**FASTER WORK ORDER PRINT**

**WORK ORDER # 79806  
EQUIPMENT # 2976**

Date In: 07/31/2019 Date Out: 07/31/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 92,581

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	11.22	35.05	3.45	07/31/2019	Z017TM2165BS	Tire / Tube Tire Industrial Repair	49.72
SUBTOTAL:							49.72

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	07/31/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	74.72
-------------------	--------	-------

NOTES

07/31/2019 @ 07:40:57

Wingfoot 7/22/19  
Yard Service - LF

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 79851 EQUIPMENT # 2976

Date In: 08/01/2019 Date Out: 08/01/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 92,848

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
50	4.00	N	2	08/01/2019	2013MH0165BN	Brakes Misc Parts Repair	440.00
50	1.00	N	2	08/01/2019	2013SC2100BS	Brakes Shoe/LiningA-Br Replace	110.00
50	0.50	N	2	08/01/2019	2000001010BN	Unit Services Complete Unit Fill Fluids	55.00
50	1.50	N	2	08/01/2019	2001A09325BN	Air Conditionin RECHARGE Evacuate/Charge	165.00
SUBTOTAL:							770.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
GG4709ES2G-MBI	S	2	87.62	08/02/2019	1000001000BS	Unit Services Complete Unit Part Issue	175.24
701-1BG	S	1	9.74	08/02/2019	1000001000BS	Unit Services Complete Unit Part Issue	9.74
GG4726ES2G-MBI	S	1	120.45	08/02/2019	1000001000BS	Unit Services Complete Unit Part Issue	120.45
66826B-TWD	S	2	357.83	08/02/2019	1000001000BS	Unit Services Complete Unit Part Issue	715.65
66854B-TWD	S	1	320.87	08/02/2019	1000001000BS	Unit Services Complete Unit Part Issue	320.87
HYD46-90C	S	2	12.20	08/02/2019	1000001000BS	Unit Services Complete Unit Part Issue	24.40
TRANSYNQT-1BG	S	9	8.94	08/02/2019	1000001000BS	Unit Services Complete Unit Part Issue	80.49
R134AOZ-90C	S	38	0.61	08/02/2019	1000001000BS	Unit Services Complete Unit Part Issue	23.18
SUBTOTAL:							1,470.02

WORK ORDER TOTALS	TOTAL:	2,240.02
-------------------	--------	----------

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 79851**  
**EQUIPMENT # 2976**

08/01/2019 @ 15:11:00

**BRAKES SEEM WORN OUT; EMERGENCY BRAKE NOT HOLDING ON HILLS**  
**A/C BLOWING WARM**  
**CHECK TRANS FLUID**

TT

#50 Replace front Shoes & drums.  
#50 Replace L/R Shoes & Drums.  
Adjust the intermediate axle brakes.  
Recover AC, refrigerant.  
Leak test, vacuum and charge.(2.5 lbs)

Check the transmission oil level (add 9 qts )  
Hydraulic fluid power steering reservoir.(2 qts add)  
Unit is back across the street.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 80229**  
**EQUIPMENT # 2976**

Date In: 08/28/2019 Date Out: 08/28/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 93,940

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	0.00	08/28/2019	PML BS	LUBRICATION	40.00
SUBTOTAL:							40.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	08/28/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	65.00
-------------------	--------	-------

NOTES

08/28/2019 @ 15:20:29

Tracks to Tires8/28/19  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 80254**  
**EQUIPMENT # 2976**

Date In: 08/28/2019 Date Out: 08/28/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 93,940

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	0.00	08/28/2019	PML BS	LUBRICATION	40.00
SUBTOTAL:							40.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	08/28/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	65.00
-------------------	--------	-------

NOTES

08/28/2019 @ 15:49:14

Tracks to Tires8/28/19  
Lube

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 80487 EQUIPMENT # 2976

Date In: 09/13/2019 Date Out: 10/11/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 94,634

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
55	2.00	N	2	09/13/2019	2040000001BS	Engine System Diagnosis	220.00
55	1.00	N	2	09/14/2019	2013000001BS	Brakes System Diagnosis	110.00
55	3.00	N	2	09/14/2019	2019S22100BS	BearingHubWheel Seal Wh Bearing Replace	330.00
55	1.50	N	2	09/14/2019	2047REGREGBS	Emission System REGEN REGEN	165.00
55	0.50	N	2	09/14/2019	2000TCD021BS	Unit Services TOWN DECALS INSTALL/REMOVE	55.00
55	6.00	N	2	09/19/2019	2047DEF165BS	Emission System DEF System Repair	660.00
SUBTOTAL:							1,540.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
1643-CR	S	2	21.94	09/16/2019	1000001000BS	Unit Services Complete Unit Part Issue	43.87
DEF002-NAF	S	4	16.31	09/16/2019	1000001000BS	Unit Services Complete Unit Part Issue	65.24
75210-NOL	S	1	6.49	09/16/2019	1000001000BS	Unit Services Complete Unit Part Issue	6.49
TOC1-9HD	S	2	26.47	09/20/2019	1000001000BS	Unit Services Complete Unit Part Issue	52.95
7051050-BK	S	2	1.70	09/20/2019	1000001000BS	Unit Services Complete Unit Part Issue	3.39
DELOXLC55-9OC	S	44	2.99	09/20/2019	1000001000BS	Unit Services Complete Unit Part Issue	131.52
DM5011806C765-ST5	S	1	1,215.93	09/25/2019	1000001000BS	Unit Services Complete Unit Part Issue	1,215.93
-FRT	S	1	31.76	09/25/2019	1000001000BS	Unit Services Complete Unit Part Issue	31.76
SUBTOTAL:							1,551.15

WORK ORDER TOTALS

TOTAL: 3,091.15

NOTES



**FASTER WORK ORDER PRINT**

**WORK ORDER # 80487  
EQUIPMENT # 2976**

09/13/2019 @ 14:40:09

Front brakes screaming and leaving residue  
Check engine light on causing truck to lose power

VB

#55 Had several DEF related codes because DEF tank was empty. Level sensor is reading incorrect so I filled system with fluid from NAPA (could not get outside DEF to work) and Ran several tests to make sure pump was working and had no leaks. Then ran a Regen on it to clear other problems and reset all codes.

Have DEF parts ordered but can run until they come in as long as it gets filled every day.

#55 Replaced both front hub caps and filled with gear oil. Removed both front brake dust shields and adjusted all the brakes. Took up to the wash bay and cleaned all drum assemblies with the heat and pressure washer. Then took through the automated to try and get any spots I may have missed. Drove truck around the lot until brakes were dried up and heard no more noises.

#55 Replaced two tires on Right Rear rear axle. One was bald and the other was starting to come apart on edges.

Parked back across the street and will run until parts come in to fix properly. Driver must fill DEF fluid everyday until then. Will need new town stickers when we do this also.

09/19/2019 @ 11:30:05 def sensor in

#55 Replaced TOC stickers

#55 Replaced def level sensor, had to remove def tank to flush out system and drain and fill coolant. Trimmed coolant hoses and cut off old clamps for removal and installed worm gear style to make it work. Everything is done but still need to top off DEF fluid.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 80612**  
**EQUIPMENT # 2976**

Date In: 09/23/2019 Date Out: 09/24/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 94,863

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
50	1.50	N	2	09/23/2019	2409000001BS	Body Dump System Diagnosis	165.00
SUBTOTAL:							165.00

WORK ORDER TOTALS	TOTAL:	165.00
-------------------	--------	--------

NOTES

09/23/2019 @ 15:08:28

Tailgate locks not working

VB

#50 Found a plastic 1/8" hose cut off. ( No hose on stock)

Hose was short. Has to re routed, to make work.

Unit is back across the street.

Updated.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 80714**  
**EQUIPMENT # 2976**

Date In: 09/26/2019 Date Out: 09/26/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 94,966

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	0.00	09/26/2019	PML BS	LUBRICATION	40.00
SUBTOTAL:							40.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	09/26/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	65.00
-------------------	--------	-------

NOTES

09/26/2019 @ 14:40:01

Tracks to Tires 9/26/19  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 80954  
EQUIPMENT # 2976**

Date In: 10/10/2019 Date Out: 10/10/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 95,187

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
55	1.50	N	1	10/10/2019	2019HS0165BS	BearingHubWheel Hub Wheel Assem Repair	165.00
SUBTOTAL:							165.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
450434K	NS	2	10.23	10/10/2019	2000001001BS	Unit Services Complete Unit Diagnosis	20.45
SUBTOTAL:							20.45

WORK ORDER TOTALS	TOTAL:	185.45
-------------------	--------	--------

NOTES

10/10/2019 @ 16:55:15

RF hub seal leaking

VB

#55 Replaced both rubber seals on the caps. Took to car wash to wash off the wheels.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 81092**  
**EQUIPMENT # 2976**

Date In: 10/21/2019 Date Out: 10/21/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 95,187

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	0.00	10/21/2019	PML BS	LUBRICATION	40.00
SUBTOTAL:							40.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	10/21/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	65.00
-------------------	--------	-------

NOTES

10/21/2019 @ 08:42:34

Tracks to Tires 10/11/19  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 81227**  
**EQUIPMENT # 2976**

Date In: 10/23/2019 Date Out: 10/23/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 95,187

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
23	2.00	N	2	10/23/2019	2000001511BN	Unit Services Complete Unit WELDING/FABRCAT	220.00

SUBTOTAL: 220.00

WORK ORDER TOTALS TOTAL: 220.00

NOTES

10/23/2019 @ 14:49:16

BOLT MISSING FROM RIGHT REAR STEP.

TT

10/23/2019 @ 18:34:05

removed step , rethreaded bolt hole , knocked step back down replaced bolts

**FASTER WORK ORDER PRINT**

**WORK ORDER # 81232  
EQUIPMENT # 2976**

Date In: 10/24/2019 Date Out: 10/24/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 95,187

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
BARBOUR'S TOWING & RECOVERY	0.00	225.00	0.00	10/24/2019	Z000001500BS	Unit Services Complete Unit Towing	225.00
SUBTOTAL:							225.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	10/24/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	250.00
-------------------	--------	--------

NOTES

10/24/2019 @ 06:59:37

Barbours 10/14/19  
Tow

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 81256 EQUIPMENT # 2976

Date In: 10/25/2019 Date Out: 10/25/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 95,187

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	0.50	N	1	10/25/2019	2034LN5165BN	Light System Light Exterior Repair	55.00
64	0.50	N	1	10/25/2019	2247SP4165BN	SNOW PLOW PLOW CONTROL Repair	55.00
SUBTOTAL:							110.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
4800-MAC	S	1	2.54	10/29/2019	1000001000BS	Unit Services Complete Unit Part Issue	2.54
4421440-SCC	S	1	2.53	10/29/2019	1000001000BS	Unit Services Complete Unit Part Issue	2.53
1157N-LMP	S	2	0.44	10/29/2019	1000001000BS	Unit Services Complete Unit Part Issue	0.88
75200-NOL	S	3	3.39	10/29/2019	1000001000BS	Unit Services Complete Unit Part Issue	10.18
SUBTOTAL:							16.12

WORK ORDER TOTALS	TOTAL:	126.12
-------------------	--------	--------

### NOTES

10/25/2019 @ 08:11:17

NEED HYD FLUID  
DIRECTIONAL LIGHT ON PLOW NOT WORKING

TT

replaced light bulbs #64  
topped off hyd fluid #64



# FASTER WORK ORDER PRINT

## WORK ORDER # 81280 EQUIPMENT # 2976

Date In: 10/28/2019 Date Out: 11/14/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 95,187

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
25	0.50	N	2	11/14/2019	2001CG0100BS	Air Conditionin Compressor Replace	55.00
70	1.00	N	1	10/30/2019	2000001001BS	Unit Services Complete Unit Diagnosis	110.00
70	4.00	N	2	11/06/2019	2043MZ0100BN	Exhaust Engine Muffler Exhaust Replace	440.00
SUBTOTAL:							605.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTIION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
119961-9HD	S	1	56.67	10/29/2019	1000001000BS	Unit Services Complete Unit Part Issue	56.67
-FRT	S	1	19.09	10/29/2019	1000001000BS	Unit Services Complete Unit Part Issue	19.09
3120221-9HD	S	1	234.17	11/06/2019	1000001000BS	Unit Services Complete Unit Part Issue	234.17
-FRT	S	1	40.38	11/06/2019	1000001000BS	Unit Services Complete Unit Part Issue	40.38
52669779-9HD	S	6	12.09	11/07/2019	1000001000BS	Unit Services Complete Unit Part Issue	72.54
3945252-9HD	S	12	5.75	11/07/2019	1000001000BS	Unit Services Complete Unit Part Issue	68.95
3944593-9HD	S	12	3.92	11/07/2019	1000001000BS	Unit Services Complete Unit Part Issue	46.99
5264570-9HD	S	1	3.40	11/07/2019	1000001000BS	Unit Services Complete Unit Part Issue	3.40
4934278-9HD	S	4	2.79	11/07/2019	1000001000BS	Unit Services Complete Unit Part Issue	11.18
3883284-9HD	S	1	6.25	11/07/2019	1000001000BS	Unit Services Complete Unit Part Issue	6.25
3818824-9HD	S	4	3.17	11/07/2019	1000001000BS	Unit Services Complete Unit Part Issue	12.69
3755843-9HD	S	1	6.91	11/07/2019	1000001000BS	Unit Services Complete Unit Part Issue	6.91
2866636-9HD	S	2	7.21	11/07/2019	1000001000BS	Unit Services Complete Unit Part Issue	14.42
5262994-9HD	S	1	163.88	11/07/2019	1000001000BS	Unit Services Complete Unit Part Issue	163.88
5263198-9HD	S	1	39.21	11/07/2019	1000001000BS	Unit Services Complete Unit Part Issue	39.21
102408-9HD	S	2	39.17	11/07/2019	1000001000BS	Unit Services Complete Unit Part Issue	78.35
5293295RX-9HD	S	1	512.29	11/07/2019	1000001000BS	Unit Services Complete Unit Part Issue	512.29
-FRT	S	11	23.79	11/07/2019	1000001000BS	Unit Services Complete Unit Part Issue	261.69
25080683HD-NBH	S	1	36.36	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	36.36
101724-NCB	S	1	25.17	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	25.17

**FASTER WORK ORDER PRINT**

**WORK ORDER # 81280  
EQUIPMENT # 2976**

1707018X-TWD	S	1	18.98	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	18.98
9600-MAC	S	2	6.98	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	13.96
11232-1BG	S	2	23.33	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	46.65
DELO400-9OC	S	23	3.15	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	72.40
3936-FIL	S	1	14.05	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	14.05
3604-FIL	S	1	22.30	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	22.30
1748-FIL	S	1	28.44	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	28.44
DELOXLC55-9OC	S	83	2.64	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	218.71
R009020-TWD	S	1	4.42	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	4.42
7051527-BK	S	1	6.64	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	6.64
CV50628-9HD	S	1	107.08	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	107.08
25080893-9NJ	S	1	33.31	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	33.31

SUBTOTAL: 2,297.51

WORK ORDER TOTALS TOTAL: 2,902.51

NOTES

10/28/2019 @ 11:45:46

Excessive play in steering wheel  
Valve body on front of body behind cab leaking hydraulic fluid

pd

70  
check all steering linkages and steer gear for excessive play found ball joint on driver side with about 1/8 gap between the castle nut and the arm removed cotter pin and install washer and retighten castle nut and reinstall cotter pin and that tightened up the steering alot now the wheel only has about 1 inch free play rest of the endplay is in the steer gear box  
needs steer column u joint

70  
small hydraulic leak at control valve for packer behind cab looked over well could not find the source of leak ran truck and worked hydraurlics found a tiny leak at the hydraulic pressure test port and the cas was not on the port cleaned the cap to remove all dirt and reinstall cap and test to check for any more leak needs new hydraulic test port

10/28/2019 @ 15:02:07

70  
i was told to put a exhaust cap on the muffler exhaust pipe was rusted and busted all the way down the seam removed old pipe and ordered new pipe and exhaust cap

11/06/2019 @ 15:13:18

70  
new muffler pipe came in had to cratch off all the shipping lables from pipe and install to correct highth and secure clamps

# FASTER WORK ORDER PRINT

## WORK ORDER # 81297 EQUIPMENT # 2976

Date In: 10/29/2019 Date Out: 12/09/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 96,107

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
25	2.00	N	1	10/29/2019	8042MH0001BN	Cooling Engine Misc Parts Diagnosis	220.00
25	3.00	N	1	11/05/2019	8042MH0001BN	Cooling Engine Misc Parts Diagnosis	330.00
25	12.00	N	1	11/05/2019	2047S7W100BS	Emission System EGR COOLER Replace	1,320.00
25	7.00	N	1	11/07/2019	2043M30165BS	Exhaust Engine Manifold Exhaust Repair	770.00
25	2.50	N	1	11/08/2019	2024Y10100BS	Drive Shaft Yoke Driveshaft Replace	275.00
25	4.00	N	2	11/11/2019	PMA BS	PM A Service	440.00
25	3.00	N	1	11/11/2019	2045MH0001BS	Engine Block Misc Parts Diagnosis	330.00
25	7.00	N	1	11/12/2019	2042R60165BS	Cooling Engine Radiator Repair	770.00
25	3.00	N	2	11/16/2019	2001CG0100BS	Air Conditionin Compressor Replace	330.00
25	1.50	N	1	12/09/2019	2043PB5100BS	Exhaust Engine Pipe Exhaust Replace	165.00
SUBTOTAL:							4,950.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTIION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
5319449-9HD	S	1	129.08	10/30/2019	1000001000BS	Unit Services Complete Unit Part Issue	129.08
5315014-9HD	S	1	60.88	10/30/2019	1000001000BS	Unit Services Complete Unit Part Issue	60.88
4352363-9HD	S	1	592.47	10/30/2019	1000001000BS	Unit Services Complete Unit Part Issue	592.47
4352253RX-9HD	S	1	1,350.15	10/30/2019	1000001000BS	Unit Services Complete Unit Part Issue	1,350.15
500167-FIL	S	1	55.82	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	55.82
500166-FIL	S	1	46.70	11/12/2019	1000001000BS	Unit Services Complete Unit Part Issue	46.70
7709219-BK	S	1	0.00	11/18/2019	001-000	Unknown Group Unknown Compnt Unknown Repair	0.00
701-1BG	S	1	0.00	11/18/2019	001-000	Unknown Group Unknown Compnt Unknown Repair	0.00
MEI5445-TWD	S	1	15.69	11/18/2019	1000001000BS	Unit Services Complete Unit Part Issue	15.69
MEI5349-TWD	S	1	301.93	11/18/2019	1000001000BS	Unit Services Complete Unit Part Issue	301.93
-FRT	S	1	36.65	11/18/2019	1000001000BS	Unit Services Complete Unit Part Issue	36.65
SUBTOTAL:							2,589.35

WORK ORDER TOTALS

TOTAL: 7,539.35

**FASTER WORK ORDER PRINT**

**WORK ORDER # 81297  
EQUIPMENT # 2976**

---

NOTES

10/29/2019 @ 11:04:31

Road call to 105 wedgemere rd  
Engine overheat and hyd oil leak

JF

#25 - Found truck had overheated and egr cooler needs replaced. Truck towed to shop

10/30/2019 @ 11:06:44all parts here

#25 - Replaced egr cooler with upgraded cooler.The a/c compressor will not mount to bracket. Ordered compressor. Wrong part recieved. Researched and found correct compressor. Ordered.

#25 - Replaced short pipe and nox sensor at rear of turbo.

#25 - Removed exhaust manifold and replaced gaskets.

#25 - Replaced crankcase filter.

#25 - Need to replace a/c compressor and reroute lines.I removed compressor and installed shorter belt so we can run truck until part comes in. Replaced compressor. Recoverd 1.88 # freon and charged with 2.5

#25 - Pma complete.

#25 - Yoke damaged during tow. Towing company came out and retapped holes. I pulled the straps off and found lips on mating surfaces. Filed lips off and installed new straps.

#25 - Tried to regen truck and vgt actuator not responding mechanically code came active. Regennd a couple more times to get all water out of system code went inactive.

#25 - Removed condensor and charge air cooler and power washed radiator.

#25 - Flex pipe at rear of turbo needs replaced. Replaced pipe.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 81481  
EQUIPMENT # 2976**

Date In: 11/12/2019 Date Out: 11/12/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 96,165

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
BARBOUR'S TOWING & RECOVERY	0.00	200.00	0.00	11/12/2019	Z000001500BS	Unit Services Complete Unit Towing	200.00
SUBTOTAL:							200.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	11/12/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	225.00
-------------------	--------	--------

NOTES

11/12/2019 @ 07:10:10

Barbours 10/30/19  
Tow

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 81874 EQUIPMENT # 2976

Date In: 12/05/2019 Date Out: 12/13/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 96,743

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
50	1.50	N	1	12/05/2019	2007ME0T01BN	Glass-Component Mirror TIGHTEN	165.00
50	14.00	N	1	12/12/2019	2055CM4165BN	Cargo Handling Control Tail Ga Repair	1,540.00
50	8.00	N	2	12/12/2019	2012001100BS	Axle Rear HUB SEAL Replace	880.00
SUBTOTAL:							2,585.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTIION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
97817-LIT	S	1	17.21	12/09/2019	1000001000BS	Unit Services Complete Unit Part Issue	17.21
110427-9HD	S	2	480.29	12/09/2019	1000001000BS	Unit Services Complete Unit Part Issue	960.58
-FRT	S	1	30.50	12/09/2019	1000001000BS	Unit Services Complete Unit Part Issue	30.50
85601-GAT	S	5	4.55	12/10/2019	1000001000BS	Unit Services Complete Unit Part Issue	22.76
G251700606-GAT	S	4	6.06	12/10/2019	1000001000BS	Unit Services Complete Unit Part Issue	24.25
16PB-NCB	S	1	4.70	12/10/2019	1000001000BS	Unit Services Complete Unit Part Issue	4.70
370003A-NTL	S	1	36.22	12/13/2019	1000001000BS	Unit Services Complete Unit Part Issue	36.22
3303107-TWD	S	1	2.27	12/13/2019	1000001000BS	Unit Services Complete Unit Part Issue	2.27
GG4726ES2G-MBI	S	1	105.59	12/13/2019	1000001000BS	Unit Services Complete Unit Part Issue	105.59
HYD46-9OC	S	35	9.80	12/16/2019	1000001000BS	Unit Services Complete Unit Part Issue	342.90
CS56033-MBI	S	2	104.03	12/16/2019	1000001000BS	Unit Services Complete Unit Part Issue	208.06
7236-BAT	S	3	118.89	12/17/2019	1000001000BS	Unit Services Complete Unit Part Issue	356.67
SUBTOTAL:							2,111.70

WORK ORDER TOTALS TOTAL: 4,696.70

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 81874**  
**EQUIPMENT # 2976**

12/05/2019 @ 14:25:08

**DRIVERS SIDE TAILGATE IS LEAKING. TAILGATE AJAR LIGHT IS ON.**

**ROUND MIRROR ON PASSENGER SIDE WILL NOT STAY IN PLACE**

**TT**

#50 Mirror base bolt joint loose. Replace the mirror.

Need both cylinder for the tail gate locks. ( metal corrotion )\

#50 Install one lock cylinder. Both pin where corrode and stuck.

A bolt and lug nut was use as an anchor for the cylinder , was un able to find same type of pin.

#50 Remove both pins on the right side.

Lock cylinder replace. R side.

Also need a hub seal. R/R.

#50 Hub seal replace.

Found the two intermediate axle slack adjuster need to get replace.

Also the covers for the lock cylinders are no installed yet. Need to drill new holes.( when first remove all broke off)

Install both intermediate axle slack adjusters.

Use self tap screws to put the lock cylinders covers back on.

Parked across the street.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 82177  
EQUIPMENT # 2976**

Date In: 12/30/2019 Date Out: 12/30/2019 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 97,053

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	11.22	35.05	3.45	12/30/2019	Z017TM2165BS	Tire / Tube Tire Industrial Repair	49.72
SUBTOTAL:							49.72

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	12/30/2019	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	74.72
-------------------	--------	-------

NOTES

12/30/2019 @ 06:57:23

Wingfoot 12/20/19  
Yard Service - LF

pd



**FASTER WORK ORDER PRINT**

**WORK ORDER # 82366**  
**EQUIPMENT # 2976**

Date In: 01/13/2020 Date Out: 01/13/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 97,446

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.10	6.50	01/13/2020	Z017TM2165BS	Tire / Tube Tire Industrial Repair	99.04
SUBTOTAL:							99.04

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	01/13/2020	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	124.04
-------------------	--------	--------

NOTES

01/13/2020 @ 14:46:44

Wingfoot 1/13/20  
Yard Service - LFI/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 82635**  
**EQUIPMENT # 2976**

Date In: 02/03/2020 Date Out: 02/03/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 98,130

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	0.00	02/03/2020	PML BS	LUBRICATION	40.00
SUBTOTAL:							40.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	02/03/2020	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	65.00
-------------------	--------	-------

NOTES

02/03/2020 @ 06:56:19

Tracks to Tires 1/31/20  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 82672**  
**EQUIPMENT # 2976**

Date In: 02/03/2020 Date Out: 02/10/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 98,130

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
55	2.00	N	1	02/03/2020	2214FL1100BN	Compact Hopper FLIPPER ASSY. Replace	220.00
SUBTOTAL:							220.00

WORK ORDER TOTALS	TOTAL:	220.00
-------------------	--------	--------

NOTES

02/03/2020 @ 15:06:16

REPLACE BROKEN FLIPPER HANDLE

TT

#55 Made a new handle from some scrap metal we had laying around. Cut out shape and drilled holes for pins. Had to modify it slightly so valve would go all the way in. Parked back across the street

**FASTER WORK ORDER PRINT**

**WORK ORDER # 82906**  
**EQUIPMENT # 2976**

Date In: 02/18/2020 Date Out: 02/18/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHI	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 98,582

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	44.88	140.20	13.00	02/18/2020	Z017TM2165BS	Tire / Tube Tire Industrial Repair	198.08
SUBTOTAL:							198.08

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	02/18/2020	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	223.08
-------------------	--------	--------

NOTES

02/18/2020 @ 13:52:43

Wingfoot 10/18/19  
Yard Service - RFI/O LRI/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 82931  
EQUIPMENT # 2976**

Date In: 02/18/2020 Date Out: 02/18/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 98,582

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	0.00	02/18/2020	PML BS	LUBRICATION	40.00
SUBTOTAL:							40.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	02/18/2020	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	65.00
-------------------	--------	-------

NOTES

02/18/2020 @ 14:29:56

Tracks to Tires 2/17/20  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 83064**  
**EQUIPMENT # 2976**

Date In: 02/26/2020 Date Out: 02/26/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 98,774

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.10	6.50	02/26/2020	Z017TM2165BS	Tire / Tube Tire Industrial Repair	99.04
SUBTOTAL:							99.04

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	02/26/2020	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	124.04
-------------------	--------	--------

NOTES

02/26/2020 @ 06:38:27

Wingfoot 2/21/20  
Yard Service -

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 83220**  
**EQUIPMENT # 2976**

Date In: 03/09/2020 Date Out: 03/09/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 99,188

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	0.00	03/09/2020	PML BS	LUBRICATION	40.00
SUBTOTAL:							40.00

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	03/09/2020	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	65.00
-------------------	--------	-------

NOTES

03/09/2020 @ 11:07:12

Tracks to Tires 3/9/20  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 83292**  
**EQUIPMENT # 2976**

Date In: 03/11/2020 Date Out: 03/11/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,158 A
			M 99,351

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
70	1.00	N	2	03/11/2020	2214FL1165BN	Compact Hopper FLIPPER ASSY. Repair	110.00
SUBTOTAL:							110.00

WORK ORDER TOTALS	TOTAL:	110.00
-------------------	--------	--------

NOTES

03/11/2020 @ 14:27:45

PASSENGER SIDE FLIPPER CONTROL IS NOT WORKING

TT

70  
found the flipper lever hard to push and pull removed handle and it was bend in 2 different directions causing it to bind up beat handle back straight and fixed pivot holes to allow it to be remounted and move properly also found a hydraulic leak on the passenger side flipper motor it had a loose hydraulic fitting tighten fitting and powerwashed area to clean up to be able to check for further leaks



**FASTER WORK ORDER PRINT**

**WORK ORDER # 83382**  
**EQUIPMENT # 2976**

Date In: 03/18/2020 Date Out: 03/19/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 99,351

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
44	0.50	N	2	03/19/2020	2111A00001BS	PTO Assembly Diagnosis	55.00

SUBTOTAL: 55.00

WORK ORDER TOTALS TOTAL: 55.00

NOTES

03/18/2020 @ 08:29:57

PTO not working

pd

#44 Emergency stop switch was active on the RR of truck. Reset switch and verify normal operations of PTO functions.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 83740**  
**EQUIPMENT # 2976**

Date In: 04/16/2020 Date Out: 04/21/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 100,294

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
50	0.50	N	2	04/16/2020	2007WK0165BN	Glass-Component Window Side Repair	55.00
SUBTOTAL:							55.00

WORK ORDER TOTALS	TOTAL:	55.00
-------------------	--------	-------

NOTES

04/16/2020 @ 20:22:33

Driver side window stuck

VB  
#50 Clean up the locks. apply some anti sieze.  
Parked across the street.

# FASTER WORK ORDER PRINT

## WORK ORDER # 83877 EQUIPMENT # 2976

Date In: 04/29/2020 Date Out: 06/04/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 100,711

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
25	1.00	N	1	04/30/2020	2024B16165BN	Drive Shaft Bearing Carrier Repair	110.00
25	8.50	N	1	04/30/2020	2013DT0100BN	Brakes Drum Air Brake Replace	935.00
25	8.50	N	1	04/30/2020	2024Y10100BN	Drive Shaft Yoke Driveshaft Replace	935.00
25	1.00	N	1	05/13/2020	2032B00001BN	Cranking System Battery Diagnosis	110.00
SUBTOTAL:							2,090.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
4376837-9HD	S	1	46.04	04/30/2020	1000001000BS	Unit Services Complete Unit Part Issue	46.04
2888173-9HD	S	1	438.52	04/30/2020	1000001000BS	Unit Services Complete Unit Part Issue	438.52
825-VAL	S	2	6.87	04/30/2020	1000001000BS	Unit Services Complete Unit Part Issue	13.74
370003A-NTL	S	2	36.22	04/30/2020	1000001000BS	Unit Services Complete Unit Part Issue	72.44
3303107-TWD	S	2	2.27	04/30/2020	1000001000BS	Unit Services Complete Unit Part Issue	4.54
091839-CRC	S	1	3.60	04/30/2020	1000001000BS	Unit Services Complete Unit Part Issue	3.60
66854B-TWD	S	2	272.59	04/30/2020	1000001000BS	Unit Services Complete Unit Part Issue	545.17
GG4726ES2G-MBI	S	2	105.59	04/30/2020	1000001000BS	Unit Services Complete Unit Part Issue	211.18
4800-MAC	S	2	2.54	05/08/2020	1000001000BS	Unit Services Complete Unit Part Issue	5.08
3303107-TWD	S	1	2.27	05/11/2020	1000001000BS	Unit Services Complete Unit Part Issue	2.27
101724-NCB	S	1	25.17	05/11/2020	1000001000BS	Unit Services Complete Unit Part Issue	25.17
825-VAL	S	2	6.87	05/18/2020	1000001000BS	Unit Services Complete Unit Part Issue	13.74
370003A-NTL	S	1	36.22	05/18/2020	1000001000BS	Unit Services Complete Unit Part Issue	36.22
3303107-TWD	S	1	2.27	05/18/2020	1000001000BS	Unit Services Complete Unit Part Issue	2.27
1707018X-9HD	S	1	32.93	05/18/2020	1000001000BS	Unit Services Complete Unit Part Issue	32.93
SPL1704X-9HD	S	1	151.35	05/18/2020	1000001000BS	Unit Services Complete Unit Part Issue	151.35
131008K-9HD	S	1	84.41	05/18/2020	1000001000BS	Unit Services Complete Unit Part Issue	84.41
-FRT	S	1	37.61	05/18/2020	1000001000BS	Unit Services Complete Unit Part Issue	37.61
124902AZ-9HD	S	2	67.03	05/18/2020	1000001000BS	Unit Services Complete Unit Part Issue	134.05

# FASTER WORK ORDER PRINT

## WORK ORDER # 83877 EQUIPMENT # 2976

-FRT	S	1	9.71	05/18/2020	1000001000BS	Unit Services Complete Unit Part Issue	9.71
26431-9HD	S	1	500.76	05/19/2020	1000001000BS	Unit Services Complete Unit Part Issue	500.76
SET403-9HD	S	1	68.66	05/19/2020	1000001000BS	Unit Services Complete Unit Part Issue	68.66
SET401-9HD	S	1	57.96	05/19/2020	1000001000BS	Unit Services Complete Unit Part Issue	57.96
2750064-9HD	S	1	121.22	05/19/2020	1000001000BS	Unit Services Complete Unit Part Issue	121.22
-FRT	S	1	194.96	05/19/2020	1000001000BS	Unit Services Complete Unit Part Issue	194.96
SUBTOTAL:							2,813.61
WORK ORDER TOTALS							TOTAL: 4,903.61

### NOTES

04/29/2020 @ 08:26:46

Engine warning light on

JF  
#25  
Active code 3569 . Found def doser being commanded on and pump at 130 psi but doser is not dosing. Ran def over ride test and doser comes on about half the time. Checked ohms on doser coil and reads 13.5 ohms. should be between 11 and 10 ohms. Ordered doser. Installed doser and test drove. During test drive code 3597 came active. Found def control module defective and replaced with no charge module that we already had. Test drove and code did not return.

#25 - While test driving heard drive line noise. Found carrier bearing plate loose, and play in one u-joint / yoke. Ordered u-joint and yoke. Also needs a front drive brake job.

#25 - Adjusted carrier plate and replaced bolts

#25 - Ordered u-joint, yoke and seal.

#25 - While replacing brakes found both front drive wheel seals damp and left front drive hub damaged. Replaced wheel seal and shoes on rfd. Replaced shoes on lfd and ordered hub. Replaced hub and topped off diff.

#25 - Power in cab works intermittantly. Solenoid in dash defective. Ordered solenoid. Replaced solenoid and ran truck to verify repair.

#25 - Checked batteries had to jump truck to get it in shop. Batteries had low charge but tested ok. Charged batteries.

Still waiting on yoke. truck down

#25 - While backing out of bay found monitor not working for reverse. Took monitor from 2977 and installed. ordered new monitor.

06/01/2020 @ 12:01:39 - Installed new yoke and u-joint. Test drove to verify repair. Truck across the street.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 84029**  
**EQUIPMENT # 2976**

Date In: 05/08/2020 Date Out: 05/08/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 9,630
			M 100,711

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.10	6.50	05/08/2020	Z017TM2165BS	Tire / Tube Tire Industrial Repair	99.04
SUBTOTAL:							99.04

MISCELLANEOUS COSTS

CODE	DESCRIPTION	COST POSTED DATE	REPAIR TYPE	RTY DESCRIPTION	MISC COST
SP	SUBLET PROCESSING	05/08/2020	Z000001Z99BS	Unit Services Complete Unit Transaction Fee	25.00
SUBTOTAL:					25.00

WORK ORDER TOTALS	TOTAL:	124.04
-------------------	--------	--------

NOTES

05/08/2020 @ 14:56:38

Wingfoot 5/8/20  
Yard Service

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 84361**  
**EQUIPMENT # 2976**

Date In: 06/02/2020 Date Out: 06/03/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,399 Y
			M 100,711

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
50	0.50	N	2	06/02/2020	PMD BS	PM D Service	55.00
50	1.00	N	1	06/02/2020	2210000001BN	Compaction System Diagnosis	110.00
50	0.50	N	1	06/02/2020	2055CM4001BN	Cargo Handling Control Tail Ga Diagnosis	55.00
SUBTOTAL:							220.00

PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
CV50628-9HD	S	1	108.69	06/05/2020	1000001000BS	Unit Services Complete Unit Part Issue	108.69
SUBTOTAL:							108.69

WORK ORDER TOTALS	TOTAL:	328.69
-------------------	--------	--------

NOTES

06/02/2020 @ 18:06:41

PMD  
Locking clamps for tailgate not working  
Packing cycle and blade seemed weak  
Parked behind fleet,keys in it

VB  
#50 PMD Complete.

----Found the plastic hose feeding air to the pump to actuate the lock, was damage.  
Replace 4FT Of 1/8" plastic hose. Locks are working now.

Need the packer area clean up to check the cylinder and the valve body for leaks. ( pressure washer station is down)  
Truck can be use. Working normal.

Parked across the street.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 84407**  
**EQUIPMENT # 2976**

Date In: 06/08/2020 Date Out: 06/09/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,399
			M 100,844

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	0.50	N	1	06/08/2020	2004MH0165BN	Heating Vent Misc Parts Repair	55.00
SUBTOTAL:							55.00

WORK ORDER TOTALS	TOTAL:	55.00
-------------------	--------	-------

NOTES

06/08/2020 @ 07:46:23

TURN HEAT OFF

TT

turned off heater valves and lubricated cab latches #64

# FASTER WORK ORDER PRINT

## WORK ORDER # 84422 EQUIPMENT # 2976

Date In: 06/08/2020 Date Out: 06/08/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,420
			M 100,948

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
50	0.70	N	2	06/08/2020	PMI BS	Annual State In	77.00
50	3.50	N	2	06/08/2020	2001000001BS	Air Conditionin System Diagnosis	385.00
50	0.50	N	2	06/08/2020	2040000001BN	Engine System Diagnosis	55.00
SUBTOTAL:							517.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTIION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
9600-MAC	S	2	6.98	06/09/2020	1000001000BS	Unit Services Complete Unit Part Issue	13.96
3936-FIL	S	1	14.01	06/09/2020	1000001000BS	Unit Services Complete Unit Part Issue	14.01
3604-FIL	S	1	22.72	06/09/2020	1000001000BS	Unit Services Complete Unit Part Issue	22.72
111633-9HD	S	2	23.16	06/17/2020	1000001000BS	Unit Services Complete Unit Part Issue	46.31
100460N-9HD	S	4	10.43	06/17/2020	1000001000BS	Unit Services Complete Unit Part Issue	41.72
-FRT	S	1	25.95	06/17/2020	1000001000BS	Unit Services Complete Unit Part Issue	25.95
SUBTOTAL:							164.66

WORK ORDER TOTALS	TOTAL:	681.66
-------------------	--------	--------

### NOTES

06/08/2020 @ 15:51:41

Check engine light is on.  
Top speed 30 mph  
AC not working  
NCSI

VB  
#50 NCIS complete.  
Recover the refrigerant, System was low ( 2.3 lbs) Oil was 3 oz recovered. After the system was recharge the machine could not clear the hoses and the refrigerant start to back feed to the AC machine. Force to recover a second time. Recover it and drain and extra 5 oz of oil. At some point the system was recharge with too much oil.  
Also found the heater coolant valve on the back on the engine block, wide open. Close it up.

Recharge 3lbs and only 1 oz of oil. Remove and replace the evaporator /cab filter (was completly block with dirt). AC working normal now.

Parked across the street.



**FASTER WORK ORDER PRINT**

**WORK ORDER # 84434**  
**EQUIPMENT # 2976**

Date In: 06/09/2020 Date Out: 06/09/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,428
			M 101,012

TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
50	0.50	N	2	06/09/2020	2055LV2001BS	Cargo Handling Linkage Tail Ga Diagnosis	55.00
50	0.70	N	2	06/09/2020	PMI BS	Annual State In	77.00
50	0.25	N	2	06/09/2020	2000001520BS	Unit Services Complete Unit Disinfect	27.50
50	0.50	N	2	06/09/2020	2102LN8100BS	Light Emergency Light Strobe Replace	55.00
SUBTOTAL:							214.50
WORK ORDER TOTALS							TOTAL: 214.50

NOTES

06/09/2020 @ 15:43:51

TAILGATE LOCKLY SLOWLY OPEN ON THEIR OWN WHILE DRIVING  
TOP STROBE LIGHT IS MISSING

TT

#50 Found one srobe light in the parts shed.  
Strobe light installed.

This lock are air over hydraulic, with the switch on the dash. Can not replicate the fault. The best option is to order safety pins.

Need two safety pins to keep the locks on place.  
Pins on order.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 84694**  
**EQUIPMENT # 2976**

Date In: 06/26/2020 Date Out: 06/26/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,428
			M 101,152

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
64	0.50	N	1	06/26/2020	2214L32165BN	Compact Hopper Latch Hopper Repair	55.00
64	0.25	N	1	06/26/2020	2000001520BS	Unit Services Complete Unit Disinfect	27.50
SUBTOTAL:							82.50

WORK ORDER TOTALS	TOTAL:	82.50
-------------------	--------	-------

NOTES

06/26/2020 @ 11:24:04

DISINFECT  
TAILGATE LOCKS NOT WORKING

TT

disinfected vehicle  
there is a black button above rocker switches that must be held in for the tailgate locks to function labeled button for driver reference #64

**FASTER WORK ORDER PRINT**

**WORK ORDER # 84845**  
**EQUIPMENT # 2976**

Date In: 07/13/2020 Date Out: 07/13/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,428
			M 101,224

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	07/13/2020	PMZ NS	SUBLET LUBE	0.00
SUBTOTAL:							0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

07/13/2020 @ 10:01:18

Tracks to Tires 7/10/20  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 85282**  
**EQUIPMENT # 2976**

Date In: 08/10/2020 Date Out: 08/10/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,428
			M 101,658

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	11.22	35.05	-46.27	08/10/2020	Z017TM2165NS	Tire / Tube Tire Industrial Repair	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

08/10/2020 @ 07:08:14

Wingfoot 8/7/20  
Yard Service - LF

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 85914**  
**EQUIPMENT # 2976**

Date In: 09/23/2020 Date Out: 09/23/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,428
			M 102,588

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
WINGFOOT/GOO DYEAR COMM TIRE	22.44	70.10	-92.54	09/23/2020	Z017TM2165NS	Tire / Tube Tire Industrial Repair	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

09/23/2020 @ 08:11:52

Wingfoot 9/22/20  
Yard Service - LFI/O

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 86029**  
**EQUIPMENT # 2976**

Date In: 09/29/2020 Date Out: 09/29/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,428
			M 102,588

SUBLET REPAIRS

<u>VENDOR</u>	<u>PARTS</u>	<u>LABOR</u>	<u>OTHER</u>	<u>SUBLET</u> <u>DATE BACK</u>	<u>REPAIR TYPE</u>	<u>RTY DESCRIPTION</u>	<u>SUBLET</u> <u>COST</u>
TRACKS TO TIRES	0.00	40.00	-40.00	09/29/2020	PMZ NS	SUBLET LUBE	0.00
SUBTOTAL:							0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

09/29/2020 @ 08:48:45

Tracks to Tires 9/28/20  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 86444**  
**EQUIPMENT # 2976**

Date In: 10/27/2020 Date Out: 10/27/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,428
			M 102,645

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	10/27/2020	PMZ NS	SUBLET LUBE	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

10/27/2020 @ 12:35:32

Tracks to Tires 10/22/20  
Lube

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 86618 EQUIPMENT # 2976

Date In: 11/05/2020 Date Out: 11/05/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,637
			M 102,645

### TECHNICIAN REPAIRS PERFORMED

TECH ID	OVER HOURS	TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
35	0.50	N	1	11/05/2020	9017TM1100NN	Tire / Tube Tire Heavy Replace	0.00
35	4.00	N	1	11/05/2020	PMA NS	PM A Service	0.00
35	0.25	N	1	11/05/2020	2000001520NS	Unit Services Complete Unit Disinfect	0.00
SUBTOTAL:							0.00

### PARTS ISSUED

PART NUMBER/DESCRIPTION	S/NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
H6054N-LMP	S	1	0.00	11/05/2020	1000001000NN	Unit Services Complete Unit Part Issue	0.00
9600-MAC	S	2	0.00	11/05/2020	1000001000NN	Unit Services Complete Unit Part Issue	0.00
DELO400-9OC	S	23	0.00	11/05/2020	1000001000NN	Unit Services Complete Unit Part Issue	0.00
11232-1BG	S	2	0.00	11/05/2020	1000001000NN	Unit Services Complete Unit Part Issue	0.00
3604-FIL	S	1	0.00	11/05/2020	1000001000NN	Unit Services Complete Unit Part Issue	0.00
3936-FIL	S	1	0.00	11/05/2020	1000001000NN	Unit Services Complete Unit Part Issue	0.00
1748-FIL	S	1	0.00	11/05/2020	1000001000NN	Unit Services Complete Unit Part Issue	0.00
SUBTOTAL:							0.00

WORK ORDER TOTALS TOTAL: 0.00

### NOTES

11/05/2020 @ 14:32:54

DISINFECT  
PMA

TRUCK ACROSS THE STREET

TT

11/05/2020 @ 16:28:52 Changed out RR/O tire on rear tandum  
11/05/2020 @ 19:38:17 pma done # 35  
11/05/2020 @ 19:40:54 disinfected done # 35



**FASTER WORK ORDER PRINT**

**WORK ORDER # 86800**  
**EQUIPMENT # 2976**

Date In: 11/19/2020 Date Out: 11/19/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,637
			M 102,645

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
25	0.25	N	1	11/19/2020	2000001065NN	Unit Services Complete Unit Jump Start	0.00
SUBTOTAL:							0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

11/19/2020 @ 10:03:30

JUMP START ACROSS THE STREET

TT  
#25 - Started truck (2697)

**FASTER WORK ORDER PRINT**

**WORK ORDER # 86852**  
**EQUIPMENT # 2976**

Date In: 11/21/2020 Date Out: 11/21/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,637
			M 102,645

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	11/21/2020	PMZ NS	SUBLET LUBE	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

11/21/2020 @ 13:22:29

Tracks to Tires 11/20/20  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 87085**  
**EQUIPMENT # 2976**

Date In: 12/08/2020 Date Out: 12/08/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,637
			M 102,769

TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
44	0.25	N	1	12/08/2020	2004MH0165NN	Heating Vent Misc Parts Repair	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

12/08/2020 @ 07:29:30

TURN HEAT ON

TT  
#44 Turn on water valves.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 87329**  
**EQUIPMENT # 2976**

Date In: 12/22/2020 Date Out: 12/22/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,637
			M 102,976

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	12/22/2020	PMZ NS	SUBLET LUBE	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

12/22/2020 @ 07:49:17

Tracks to Tires 12/21/20  
Lube

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 87343 EQUIPMENT # 2976

Date In: 12/22/2020 Date Out: 12/22/2020 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,937
			M 103,015

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
50	3.00	N	2	12/22/2020	2065H58100NN	Hydraulic Syste Hose Hydraulic Replace	0.00
SUBTOTAL:							0.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
HYD46-9OC	S	26	0.00	12/23/2020	1000001000NN	Unit Services Complete Unit Part Issue	0.00
7701163-BK	S	5	0.00	12/23/2020	1000001000NN	Unit Services Complete Unit Part Issue	0.00
G251701616-GAT	S	2	0.00	12/23/2020	1000001000NN	Unit Services Complete Unit Part Issue	0.00
85605-GAT	S	12	0.00	12/23/2020	1000001000NN	Unit Services Complete Unit Part Issue	0.00
SUBTOTAL:							0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

### NOTES

12/22/2020 @ 14:35:14

Leaking hydraulic hose

CL

#50 Found a leak on the from the PTO pump to the Valve body.  
Removed and replaced 11 1/2 feet of 1" hose. ( Napa made)  
Recharge with 25 qts of Hydraulic fluid.

Park across the street.  
Desinfected.

**FASTER WORK ORDER PRINT**

**WORK ORDER # 87595  
EQUIPMENT # 2976**

Date In: 01/19/2021 Date Out: 01/19/2021 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,937
			M 103,365

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
TRACKS TO TIRES	0.00	40.00	-40.00	01/19/2021	PMZ NS	SUBLET LUBE	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

01/19/2021 @ 12:03:26

Tracks to Tires 1/19/21  
Lube

pd

# FASTER WORK ORDER PRINT

## WORK ORDER # 88031 EQUIPMENT # 2976

Date In: 02/17/2021 Date Out: 02/23/2021 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,937
			M 103,467

### TECHNICIAN REPAIRS PERFORMED

TECH ID	HOURS	OVER TIME	SHIFT	LABOR END DATE	REPAIR TYPE	RTY DESCRIPTION	LABOR COST
50	9.00	N	2	02/22/2021	2040000001NN	Engine System Diagnosis	0.00
50	0.25	N	2	02/22/2021	2000001520NS	Unit Services Complete Unit Disinfect	0.00
SUBTOTAL:							0.00

### PARTS ISSUED

PART NUMBER/ DESCRIPTION	S/ NS	ISS QTY	UNIT PRICE	PART ISS DATE	REPAIR TYPE	RTY DESCRIPTION	PART COST
4034287-9HD	S	1	0.00	02/22/2021	1000001000NN	Unit Services Complete Unit Part Issue	0.00
DELOXLC55-9OC	S	15	0.00	02/23/2021	1000001000NN	Unit Services Complete Unit Part Issue	0.00
FXCCDA204-9HW	S	1	0.00	02/23/2021	1000001000NN	Unit Services Complete Unit Part Issue	0.00
SUBTOTAL:							0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

**FASTER WORK ORDER PRINT**

**WORK ORDER # 88031  
EQUIPMENT # 2976**

02/17/2021 @ 13:02:04

**DISINFECT  
TRUCK IS GOING INTO DERATE**

**TT**

#50 Scanned. Out of a first scan with 32 codes. follow this next 22 codes:

2636,3572,3566,3676,3425,3258,3578,3571,3561,3429,3426,1677,3422,3237,1669,1668,3567,3579,3597,2554, 11117,0241.  
Further narrow down to the active primary codes.

2387 VGT Actuator driver circuit motor mechanical system not responding or out of adjustment .

3616 Engine VGT nozzle position mechanical system not responding or out of adjustment .

2554 Exhaust gas pressure 1 data erratic intermittent or incorrect.

The only option at this time was to removed and check the VGT actuator to try to reinstall it on the correct position .

Drained the coolant..

Removed the VGT actuator. Clean it up. Reinstalled. Failed to installed a couple times, then passed. Used the correct procedure and prescribe gauge to reinstall the Vgt actuator. The sector gear was in the correct green acceptance zone of gauge. Then the calibration can not be performed. The system did not register the initial installation. Kept asking to installed the component again, Therefore the VGT actuator can not get calibrated .

Put it back together. Recharge coolant.

Need the VGT actuator.  
Park out back.

VGT is here;Rob  
02/19/2021 @ 09:41:56

#50 New VGT Actuator. Installed and calibrated.

Road tested. Working normal.

Add 15 qts of coolant.

Park across the street.

Desinfected.



**FASTER WORK ORDER PRINT**

**WORK ORDER # 88233**  
**EQUIPMENT # 2976**

Date In: 03/01/2021   Date Out: 03/01/2021   Work Order Status: C   Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H                    11,937
			M                    103,776

SUBLET REPAIRS

<u>VENDOR</u>	<u>PARTS</u>	<u>LABOR</u>	<u>OTHER</u>	<u>SUBLET</u> <u>DATE BACK</u>	<u>REPAIR TYPE</u>	<u>RTY DESCRIPTION</u>	<u>SUBLET</u> <u>COST</u>
TRACKS TO TIRES	0.00	40.00	-40.00	03/01/2021	PMZ NS	SUBLET LUBE	0.00
SUBTOTAL:							0.00

WORK ORDER TOTALS	TOTAL:	0.00
-------------------	--------	------

NOTES

03/01/2021 @ 13:10:40

Tracks to Tires 3/1/21  
Lube

pd

**FASTER WORK ORDER PRINT**

**WORK ORDER # 88677**  
**EQUIPMENT # 2976**

Date In: 04/05/2021 Date Out: 04/05/2021 Work Order Status: C Work Order Shop: 01

COLOR: WHT	COMPANY: 001	TIRE SIZE 1: 315/80R22.5	FUEL TYPE 1: D
YEAR: 2012	DEPT: 7027	TIRE SIZE 2: 11R22.5	FUEL T YPE 2:
MAKE: Crane Carrier	CLASS: 120C8AZA4Z	ENGINE SIZE: 345 HP 6 C	FUEL TYPE 3:
MODEL: LET2-46	SITE: PW/UT	TRANS: A5 Allison	EQ AVAIL CODE: 4
LICENSE: 68029V	SERIAL #: 1CYCCL58XCT050314	TITLE:	BILLING CODE: 1
OPERATOR: UD	MONITOR GROUP: 08	CURRENT METERS:	H 11,937
			M 104,319

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	SUBLET DATE BACK	REPAIR TYPE	RTY DESCRIPTION	SUBLET COST
BARBOUR'S TOWING & RECOVERY	0.00	225.00	-225.00	04/05/2021	Z000001500NS	Unit Services Complete Unit Towing	0.00

SUBTOTAL: 0.00

WORK ORDER TOTALS TOTAL: 0.00

NOTES

04/05/2021 @ 07:08:11

Barbours 2/24/21  
Tow to shop

pd

REPORT PARAMETERS

DATE RANGE:	01/01/1980 TO 04/24/2021
PRICES:	BILLING
EQUIPMENT NUMBER:	2976
EQUIPMENT COMPANY:	001
DISPLAY PART DESCRIPTIONS:	NO
VIEW NOTES:	YES
WORK ORDER NUMBER RANGE:	ALL WORK ORDERS
DPN WORK ORDER DEPARTMENT RANGE:	ALL DEPARTMENTS
WSH WORK ORDER SHOP RANGE:	ALL WORK ORDER SHOPS
WST WORK ORDER STATUS RANGE:	ALL WORK ORDER STATUSES