

WORK ORDER: 100630								
EMIS: 3550								
Work Order Status: C - Closed				Date In:		04/02/2018		
Work Order Shop: CEN - Fleet Maintenance				Date Out:		04/22/2018		
EMIS INFORMATION								
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance			TIRE SIZE: LT245/75R17E				
MAKE: GMC	DEPT: 5003-00350 BRRJA			ENGINE SIZE: 6.0L V8				
MODEL: Sierra 2500	BILL CODE: Bill Everything			TRANS: 6 SP AUTO				
LICENSE: 193-514L	PARKING LOCATION:			FUEL TYPE: G				
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573			ASSET AVAIL CODE: 7:00am - 5:00pm				
CLASS: 3/4 Ton Pick-Up				METERS: Meter for odometer - 12453				
SUBLET REPAIRS								
VENDOR	PARTS	LABOR	OTHER	OPID	DATE BACK	REPAIR DESCRIPTION	SUBLET COST	
JIFFY LUBE	\$0.00	\$28.18	\$0.00	210	04/02/2018	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	\$32.266	
WORK ORDER TOTALS								
TOTAL PARTS:		\$0.000	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS:		\$0.000
TOTAL SUBLET:		\$32.266	SUBLET TAX:		\$0.000			
TOTAL LABOR:		\$0.000	TOTAL MISC:		\$0.000	TOTAL COST:		\$32.266
NOTES								
100630 -								
PMA DONE AT JIFFY LUBE								
EXTRA OIL - 1 QRT								
TIRE ROTATION - DONE								

WORK ORDER: 101200					
EMIS: 3550					
Work Order Status: C - Closed		Date In: 05/31/2018			
Work Order Shop: CEN - Fleet Maintenance		Date Out: 05/31/2018			
EMIS INFORMATION					
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E			
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8			
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO			
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G			
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm			
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 18729			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
HICKS	05/31/2018	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	1.37	\$103.099	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
PH48	NS	1.000	\$2.555	05/31/2018	\$2.555
PART NAME: Filter, Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
809332	NS	6.000	\$6.603	05/31/2018	\$39.618
PART NAME: Oil; 5W30 Bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
WORK ORDER TOTALS					
TOTAL PARTS:	\$42.173	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$103.099	TOTAL MISC:	\$0.000	TOTAL COST:	\$145.272
NOTES					
101200 -					
PMA					
CALL 944-4962 WHEN READY, TAKE HOME UNIT, NEED BACK BY 3PM.					
Please annotate current odometer reading when closing out this work order _WAS NOT NOTATED ON WORK ORDER_."					
PMA - DONE					
WORK ORDER: 103239					
EMIS: 3550					
Work Order Status: C - Closed		Date In: 10/24/2018			
Work Order Shop: CEN - Fleet Maintenance		Date Out: 10/24/2018			
EMIS INFORMATION					

YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 27704

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
ADAMS	10/24/2018	Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform	1.35	\$63.069
ADAMS	10/24/2018	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	0.99	\$46.050
ADAMS	10/24/2018	Preventive Maintenance Service / Preventative Maintenance / PM D - State Inspection / Perform	0.49	\$16.000

PARTS ISSUED						
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
PH48	NS	1.000	\$2.416	10/24/2018	\$2.416	
PART NAME: Filter, Oil			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform			
809332	NS	6.000	\$6.603	10/24/2018	\$39.618	
PART NAME: Oil; 5W30 Bulk			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform			

WORK ORDER TOTALS					
TOTAL PARTS:	\$42.034	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$125.119	TOTAL MISC:	\$0.000	TOTAL COST:	\$167.153

NOTES

103239 -
PMA
PMB
PMD
TAKE HOME VEHICLE, MUST HAVE BACK BY 3:00 TODAY
CALL 944-4962 OR 528-3160 EXT218 OR EXT 217
PMA - DONE
PMB - DONE
PMD - DONE
LOF
ADJUSTED FLUIDS AND TIRE PRESSURE

WORK ORDER: 104962

EMIS: 3550

Work Order Status: C - Closed Date In: 02/08/2019
 Work Order Shop: CEN - Fleet Maintenance Date Out: 02/08/2019

EMIS INFORMATION

YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 35990

TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
HENDRICKS	02/08/2019	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	0.91	\$42.360
HENDRICKS	02/08/2019	Repaired From PM Service / ZZWheels & Tires-Win / Tire / ZZRotate-Win	0.67	\$31.380

PARTS ISSUED

PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
PH48	NS	1.000	\$2.454	02/08/2019	\$2.454
PART NAME: Filter, Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
PIC/4620	NS	1.000	\$2.935	02/08/2019	\$2.935
PART NAME: Spray brake kleen		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
809332	NS	6.000	\$7.173	02/08/2019	\$43.038
PART NAME: Oil; 5W30 Bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			

WORK ORDER TOTALS

TOTAL PARTS:	\$48.427	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$73.740	TOTAL MISC:	\$0.000	TOTAL COST:	\$122.167

NOTES

104962 -
 PMA WITH TIRE ROTATION.
 CALL 528-3160 X218 WHEN READY (TAKE HOME UNIT)
 Please annotate current odometer reading when closing out this work order _35990_."
 PMA - DONE
 LOF
 TIRE ROTATION COMPLETED

WORK ORDER: 105663					
EMIS: 3550					
Work Order Status: C - Closed			Date In:	04/05/2019	
Work Order Shop: CEN - Fleet Maintenance			Date Out:	04/18/2019	
EMIS INFORMATION					
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E			
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8			
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO			
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G			
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm			
CLASS: 3/4 Ton Pick-Up	METERS: Meter for odometer - 40539				
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
HENDRICKS	04/05/2019	Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform	1.32	\$61.460	
HENDRICKS	04/05/2019	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	0.58	\$26.920	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
WP10129	NS	1.000	\$18.850	04/05/2019	\$18.850
PART NAME: Filter cabin air		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform			
PH48	NS	1.000	\$2.454	04/05/2019	\$2.454
PART NAME: Filter, Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform			
809332	NS	7.000	\$7.173	04/05/2019	\$50.211
PART NAME: Oil; 5W30 Bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform			
WORK ORDER TOTALS					
TOTAL PARTS:	\$71.515	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$88.380	TOTAL MISC:	\$0.000	TOTAL COST:	\$159.895
NOTES					

105663 -
PMA
PMB
CALL 528-3160 X217 WHEN READY

Please annotate current odometer reading when closing out this work order _40539_"

PMA - DONE

PMB - DONE

REPLACED CABIN FILTER

WORK ORDER: 108395

EMIS: 3550

Work Order Status: C - Closed

Date In: 10/30/2019

Work Order Shop: CEN - Fleet Maintenance

Date Out: 10/31/2019

EMIS INFORMATION

YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 54900

TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
ADAMS	10/30/2019	Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform	1.44	\$87.620
ADAMS	10/30/2019	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	0.85	\$51.649
ADAMS	10/30/2019	Preventive Maintenance Service / Preventative Maintenance / PM T - Transmission Service / Perform	2.01	\$122.480
ADAMS	10/30/2019	Repaired From PM Service / ZZCab & Body-Win / Windshield Wipr-Win / Replace	0.46	\$28.040

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
BG310	NS	1.000	\$14.876	10/30/2019	\$14.876
PART NAME: Conditioner transmission			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform		
BG314B	NS	1.000	\$6.502	10/30/2019	\$6.502
PART NAME: Atf syn bulk qt			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform		
809332	NS	3.000	\$6.224	10/30/2019	\$18.672
PART NAME: Oil; 5W30 Bulk			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform		
23417074	NS	2.000	\$48.061	10/30/2019	\$96.122
PART NAME: BLADE			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform		
PH48	NS	1.000	\$2.454	10/30/2019	\$2.454
PART NAME: Filter, Oil			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform		
809332	NS	6.000	\$6.224	10/30/2019	\$37.344
PART NAME: Oil; 5W30 Bulk			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform		

WORK ORDER TOTALS					
TOTAL PARTS:	\$175.970	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$289.789	TOTAL MISC:	\$0.000	TOTAL COST:	\$465.759

NOTES

108395 -
PMA - 9,000 MILES OVER DUE???

PMB
PMD

PMT - AS LONG AS THE MILEAGE HE GAVE IS CORRECT

E-MAIL BRANDON WHEN READY FOR PICK UP

"Please annotate current odometer reading when closing out this work order _54904_"

PM'S DONE

DID NOT PASS FOR STATE INSPECTION

CHECKED RT HEADLIGHT, NEED TO BE REPLACED FOR INSPECTION

FLUSHED TRANS FLUID

ORDERED NEW W/W BLADES

WORK ORDER: 108564				
EMIS: 3550				
Work Order Status: C - Closed			Date In:	11/13/2019
Work Order Shop: CEN - Fleet Maintenance			Date Out:	11/13/2019
EMIS INFORMATION				
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E		
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8		
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO		
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G		
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm		
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 55330		
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
ADAMS	11/13/2019	Preventive Maintenance Service / Preventative Maintenance / PM D - State Inspection / Perform	0.51	\$16.000
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$16.000	TOTAL MISC:	\$0.000	TOTAL COST: \$16.000
NOTES				
108564 -				
PMD, DRIVER WAITING.				
REPLACED W/W BLADES				
PMD - DONE				

WORK ORDER: 109558			
EMIS: 3550			
Work Order Status: C - Closed	Date In:	02/04/2020	
Work Order Shop: CEN - Fleet Maintenance	Date Out:	02/10/2020	

EMIS INFORMATION		
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 61912

SUBLET REPAIRS							
VENDOR	PARTS	LABOR	OTHER	OPID	DATE BACK	REPAIR DESCRIPTION	SUBLET COST
Valvoline	\$0.00	\$106.12	\$0.00	210	02/04/2020	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	\$119.809

WORK ORDER TOTALS							
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000		
TOTAL SUBLET:	\$119.809	SUBLET TAX:	\$0.000				
TOTAL LABOR:	\$0.000	TOTAL MISC:	\$0.000	TOTAL COST:	\$119.809		

NOTES

109558 -
PMA DONE AT VALVOLINE
EXTRA OIL - 1 QRT OF FULL SYN OIL
TIRE ROTATION - DONE
REPLACED BOTH W/W BLADES

WORK ORDER: 110624			
EMIS: 3550			
Work Order Status: C - Closed	Date In:	05/19/2020	
Work Order Shop: CEN - Fleet Maintenance	Date Out:	05/19/2020	

EMIS INFORMATION		
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 69481

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
BERRY	05/19/2020	General Repair / ZZElectrical-Win / Light-Win / Replace	0.77	\$46.870
BERRY	05/19/2020	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	0.86	\$52.429
BERRY	05/19/2020	Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform	1.90	\$115.979

PARTS ISSUED						
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
809332	NS	6.000	\$7.020	05/19/2020	\$42.120	
PART NAME: Oil; 5W30 Bulk			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
PH48	NS	1.000	\$2.348	05/19/2020	\$2.348	
PART NAME: Filter, Oil			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			

WORK ORDER TOTALS					
TOTAL PARTS:	\$44.468	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$215.278	TOTAL MISC:	\$0.000	TOTAL COST:	\$259.746

NOTES

110624 -
PMA
PMB
TAIL LAMP OUT
NO DAMAGE NOTED
NEED PICS TAKEN PLEASE
CALL 528-3160 EXT 217 OR 218 WHEN COMPLETE
PMS DONE
CHECKED REAR BULBS AND NO ISSUE FOUND WITH REAR TAIL LAMPS
ROTATE TIRES
RELEARN TPMS

WORK ORDER: 111599							
EMIS: 3550							
Work Order Status: C - Closed				Date In:		08/21/2020	
Work Order Shop: CEN - Fleet Maintenance				Date Out:		08/25/2020	
EMIS INFORMATION							
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance			TIRE SIZE: LT245/75R17E			
MAKE: GMC	DEPT: 5003-00350 BRRJA			ENGINE SIZE: 6.0L V8			
MODEL: Sierra 2500	BILL CODE: Bill Everything			TRANS: 6 SP AUTO			
LICENSE: 193-514L	PARKING LOCATION:			FUEL TYPE: G			
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573			ASSET AVAIL CODE: 7:00am - 5:00pm			
CLASS: 3/4 Ton Pick-Up				METERS: Meter for odometer - 76582			
SUBLET REPAIRS							
VENDOR	PARTS	LABOR	OTHER	OPID	DATE BACK	REPAIR DESCRIPTION	SUBLET COST
Valvoline	\$0.00	\$66.97	\$0.00	210	08/21/2020	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	\$76.078
WORK ORDER TOTALS							
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000		
TOTAL SUBLET:	\$76.078	SUBLET TAX:	\$0.000				
TOTAL LABOR:	\$0.000	TOTAL MISC:	\$0.000	TOTAL COST:	\$76.078		
NOTES							
111599 -							
PMA DONE AT VALVOLINE							
EXTRA OIL - 1 QRT OF SYN							
TIRE ROTATION - WAS NOT DONE							
WORK ORDER: 112435							
EMIS: 3550							
Work Order Status: C - Closed				Date In:		11/12/2020	
Work Order Shop: CEN - Fleet Maintenance				Date Out:		11/13/2020	
EMIS INFORMATION							
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance			TIRE SIZE: LT245/75R17E			
MAKE: GMC	DEPT: 5003-00350 BRRJA			ENGINE SIZE: 6.0L V8			
MODEL: Sierra 2500	BILL CODE: Bill Everything			TRANS: 6 SP AUTO			
LICENSE: 193-514L	PARKING LOCATION:			FUEL TYPE: G			
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573			ASSET AVAIL CODE: 7:00am - 5:00pm			
CLASS: 3/4 Ton Pick-Up				METERS: Meter for odometer - 82009			

W300d - WorkOrderDetailsByDate

2/23/2026 8:24:03 AM

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
JONES	11/12/2020	Repaired From PM Service / Brakes / Disc Brakes-Win / Repair	1.06	\$64.970
JONES	11/13/2020	Repaired From PM Service / ZZElectrical-Win / Light-Win / Replace	1.53	\$93.979
JONES	11/13/2020	Repaired From PM Service / ZZWheels & Tires-Win / Misc Parts / Replace	1.05	\$64.290
JONES	11/13/2020	Preventive Maintenance Service / Preventative Maintenance / PM D - State Inspection / Perform	0.13	\$20.000
JONES	11/13/2020	Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform	0.62	\$38.030
JONES	11/13/2020	Repaired From PM Service / General Cleaning / Miscellaneous-Win / ZZDeliver/Trnsprt-Win	0.74	\$45.089
JONES	11/13/2020	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	0.00	\$0.120

PARTS ISSUED						
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
809332	NS	6.000	\$7.020	11/12/2020	\$42.120	
PART NAME: Oil; 5W30 Bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform				
13528566	NS	1.000	\$79.466	11/12/2020	\$79.466	
PART NAME: TPMS SENSOR		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform				
WAEBP7443	NS	2.000	\$1.949	11/12/2020	\$3.898	
PART NAME: BULB		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform				
PH48	NS	1.000	\$2.348	11/12/2020	\$2.348	
PART NAME: Filter, Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform				
23295979	NS	1.000	\$74.554	11/12/2020	\$74.554	
PART NAME: WIRING HARNESS		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform				

WORK ORDER TOTALS					
TOTAL PARTS:	\$202.386	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$326.478	TOTAL MISC:	\$0.000	TOTAL COST:	\$528.864

NOTES

W300d - WorkOrderDetailsByDate

2/23/2026 8:24:03 AM

112435 -

PMA

PMB

PMD

CALL 528-3160 X218 WHEN READY (TAKE HOME VEHICLE)

CHECK FOR NOISE UNDER THE VEHICLE WHEN HITTING BUMPS. SEE WRITE UP.

PMS DONE

TEST RIGHT REAR TAILLAMP, REPLACED TAIL LAMP HARNESS DUE TO SHORT

ROTATED TIRES

REPLACED LF TPMS SENSOR

REBURNISH FRONT BRAKE ROTORS

DID NOT FIND ANYTHING LOOSE OR RATTLING UNDER TRUCK.

WORK ORDER: 113533								
EMIS: 3550								
Work Order Status: C - Closed				Date In:		02/10/2021		
Work Order Shop: CEN - Fleet Maintenance				Date Out:		02/19/2021		
EMIS INFORMATION								
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance			TIRE SIZE: LT245/75R17E				
MAKE: GMC	DEPT: 5003-00350 BRRJA			ENGINE SIZE: 6.0L V8				
MODEL: Sierra 2500	BILL CODE: Bill Everything			TRANS: 6 SP AUTO				
LICENSE: 193-514L	PARKING LOCATION:			FUEL TYPE: G				
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573			ASSET AVAIL CODE: 7:00am - 5:00pm				
CLASS: 3/4 Ton Pick-Up				METERS: Meter for odometer - 87592				
SUBLET REPAIRS								
VENDOR	PARTS	LABOR	OTHER	OPID	DATE BACK	REPAIR DESCRIPTION	SUBLET COST	
Valvoline	\$0.00	\$66.97	\$0.00	210	02/10/2021	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	\$76.078	
WORK ORDER TOTALS								
TOTAL PARTS:		\$0.000	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS:		\$0.000
TOTAL SUBLET:		\$76.078	SUBLET TAX:		\$0.000			
TOTAL LABOR:		\$0.000	TOTAL MISC:		\$0.000	TOTAL COST:		\$76.078
NOTES								
113533 -								
PMA DONE AT VALVOLINE								
EXTRA OIL - 1 QRT FULL SYN OIL								
TIRE ROTATION - WAS NOT DONE								
WORK ORDER: 114166								
EMIS: 3550								
Work Order Status: C - Closed				Date In:		05/03/2021		
Work Order Shop: CEN - Fleet Maintenance				Date Out:		05/04/2021		
EMIS INFORMATION								
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance			TIRE SIZE: LT245/75R17E				
MAKE: GMC	DEPT: 5003-00350 BRRJA			ENGINE SIZE: 6.0L V8				
MODEL: Sierra 2500	BILL CODE: Bill Everything			TRANS: 6 SP AUTO				
LICENSE: 193-514L	PARKING LOCATION:			FUEL TYPE: G				
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573			ASSET AVAIL CODE: 7:00am - 5:00pm				
CLASS: 3/4 Ton Pick-Up				METERS: Meter for odometer - 93745				

W300d - WorkOrderDetailsByDate

2/23/2026 8:24:03 AM

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
HICKS	05/03/2021	Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform	0.92	\$56.242
HICKS	05/03/2021	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	0.79	\$48.394
HICKS	05/03/2021	General Repair / Brakes / Brake Pads & Rotors / Replace	1.89	\$115.872
GAFFORD	05/03/2021	General Repair / Brakes / Brake Pads & Rotors / Replace	0.65	\$39.951
BERRY	05/03/2021	General Repair / Brakes / Brake Pads & Rotors / Replace	0.30	\$18.486

PARTS ISSUED						
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
PH48	NS	1.000	\$3.183	05/03/2021	\$3.183	
PART NAME: Filter, Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform				
809332	NS	6.000	\$7.032	05/03/2021	\$42.192	
PART NAME: Oil; 5W30 Bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform				
SP1411PSH	NS	1.000	\$71.722	05/03/2021	\$71.722	
PART NAME: Raybestos break pads		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform				
SP1411PSH	NS	1.000	\$71.722	05/03/2021	\$71.722	
PART NAME: Raybestos break pads		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform				
88877683	NS	2.000	\$309.776	05/03/2021	\$619.552	
PART NAME: Rear brake rotor		REPAIR: General Repair / Brakes / Brake Pads & Rotors / Replace				
88877681	NS	2.000	\$306.763	05/03/2021	\$613.526	
PART NAME: Front brake rotor		REPAIR: General Repair / Brakes / Brake Pads & Rotors / Replace				

WORK ORDER TOTALS					
TOTAL PARTS:	\$1,421.897	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$278.945	TOTAL MISC:	\$0.000	TOTAL COST:	\$1,700.842

NOTES
 PM - PMA, PMB, REPLACE BRAKE PADS, AND ROTORS, PARTS DEPT, HAS THEM IN STOCK. CALL BRANDON 528-3160 EXT 218 ; 3550 - test drove truck, seated new brake pads to rotors

WORK ORDER: 115462

EMIS: 3550

Work Order Status: C - Closed Date In: 08/19/2021
 Work Order Shop: CEN - Fleet Maintenance Date Out: 08/19/2021

EMIS INFORMATION		
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8

W300d - WorkOrderDetailsByDate

2/23/2026 8:24:03 AM

MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 99769

TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
EUBANK	08/19/2021	General Repair / Brakes / Brake Master Cylinder / Replace	0.93	\$57.881
SANTIGATI	08/19/2021	General Repair / Brakes / Brake Master Cylinder / Replace	3.12	\$193.669
EUBANK	08/19/2021	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	0.18	\$11.021
SANTIGATI	08/19/2021	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	1.05	\$64.936
BERRY	08/19/2021	Preventive Maintenance Service / Preventative Maintenance / PM I - Brake Fluid Flush / Perform	0.22	\$13.798
SANTIGATI	08/19/2021	Preventive Maintenance Service / Preventative Maintenance / PM I - Brake Fluid Flush / Perform	1.00	\$62.090

PARTS ISSUED

PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
PH48	NS	1.000	\$2.324	08/19/2021	\$2.324
PART NAME: Filter, Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
809332	NS	6.000	\$7.455	08/19/2021	\$44.730
PART NAME: Oil; 5W30 Bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
PIC/4620	NS	1.000	\$2.977	08/19/2021	\$2.977
PART NAME: Spray brake kleen		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
872174	NS	1.000	\$6.207	08/19/2021	\$6.207
PART NAME: Grease bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
84543716	NS	1.000	\$177.416	08/19/2021	\$177.416
PART NAME: Cylinder brake master		REPAIR: General Repair / Brakes / Brake Master Cylinder / Replace			
84472897	NS	1.000	\$540.350	08/19/2021	\$540.350
PART NAME: Booster brake		REPAIR: General Repair / Brakes / Brake Master Cylinder / Replace			
PIC/6012	NS	2.000	\$2.324	08/19/2021	\$4.648
PART NAME: Fluid Brake super heavy duty		REPAIR: General Repair / Brakes / Brake Master Cylinder / Replace			
35032	NS	1.000	\$8.547	08/19/2021	\$8.547
PART NAME: Fluid brake dot 3 32oz		REPAIR: General Repair / Brakes / Brake Master Cylinder / Replace			
PIC/6012	NS	1.000	\$2.324	08/19/2021	\$2.324
PART NAME: Fluid Brake super heavy duty		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM I - Brake Fluid Flush / Perform			

WORK ORDER TOTALS

TOTAL PARTS:	\$789.523	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
--------------	-----------	------------	---------	---------------------	---------

W300d - WorkOrderDetailsByDate

2/23/2026 8:24:03 AM

TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$403.395	TOTAL MISC:	\$0.000	TOTAL COST:	\$1,192.918

NOTES
 SERVICE WRITER - REPLACE BRAKE BOOSTER, REPLACE MASTER CYL, PMI - FLUSH BRAKE FLUID PMA **NEEDS VEHICLE BACK TODAY CALL 528-3160 EXT #218 WHEN READY FOR PICK UP** ; PM's complete - Completed PMA and PMI. also rotated tires. -tires- fronts at 7/32 60 psi, rears 11/32 80 psi. -damage- small dent at left rear fender, scratch on right rear door, small chip on hood. no fluid leaks, took extra time on PMI due to missing the adapter for the machine and having to do it manually. also test drove to be certain hydro booster was completely bled after replacement. ; Hydro booster and master cylinder - replaced hydro booster and master cylinder. bench bled master cylinder and then finished the bleeding process after it was installed.

WORK ORDER: 116518

EMIS: 3550

Work Order Status: C - Closed	Date In:	11/30/2021
Work Order Shop: CEN - Fleet Maintenance	Date Out:	12/01/2021

EMIS INFORMATION

YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 104762

TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
EUBANK	12/01/2021	Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform	1.10	\$68.420
EUBANK	12/01/2021	General Repair / Preventative Maintenance / PM A - Oil Change / Perform	0.36	\$22.336
EUBANK	12/01/2021	Preventive Maintenance Service / Preventative Maintenance / PM D - State Inspection / Perform	0.46	\$20.000
EUBANK	12/01/2021	General Repair / Engine / System / Diagnosis	0.94	\$58.398

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
115-100	NS	1.000	\$0.194	12/01/2021	\$0.194
PART NAME: Fitting 1/4 grease			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform		
PH48	NS	1.000	\$2.396	12/01/2021	\$2.396
PART NAME: Filter, Oil			REPAIR: General Repair / Preventative Maintenance / PM A - Oil Change / Perform		
809332	NS	6.000	\$7.455	12/01/2021	\$44.730
PART NAME: Oil; 5W30 Bulk			REPAIR: General Repair / Preventative Maintenance / PM A - Oil Change / Perform		
872174	NS	1.000	\$6.570	12/01/2021	\$6.570
PART NAME: Grease bulk			REPAIR: General Repair / Preventative Maintenance / PM A - Oil Change / Perform		
42487	NS	1.000	\$18.262	12/01/2021	\$18.262
PART NAME: Filter air			REPAIR: General Repair / Preventative Maintenance / PM A - Oil Change / Perform		
4071HP	NS	1.000	\$25.846	12/01/2021	\$25.846
PART NAME: Filter cabin air			REPAIR: General Repair / Preventative Maintenance / PM A - Oil Change / Perform		
WORK ORDER TOTALS					
TOTAL PARTS:	\$97.998	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$169.154	TOTAL MISC:	\$0.000	TOTAL COST:	\$267.152
NOTES					
SERVICE WRITER - PMA PMB PMD MAKING WHISTLING NOISE IN FRONT END WHILE DRIVING. PLEASE TEST DRIVE WHEN THE TRUCK IS COLD TO HEAR IT BETTER ; PMB - Completed PMB Replaced air filter Replaced cabin filter Charged battery While greasing front end noticed LF lower ball joint grease fitting broken off, tried to get fitting out but was unable to. Covered broken fitting with grease and injected grease in boot. ; PMA - Completed PMA Changed oil and filter ; PMD - Completed state inspection					

WORK ORDER: 117768			
EMIS: 3550			
Work Order Status: C - Closed	Date In:	03/14/2022	
Work Order Shop: CEN - Fleet Maintenance	Date Out:	03/16/2022	

EMIS INFORMATION		
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 111216

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
BERRY	03/14/2022	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	1.10	\$68.575
BERRY	03/14/2022	General Repair / Suspension / System / Diagnosis	0.91	\$56.536
HICKS	03/14/2022	General Repair / Suspension / System / Diagnosis	0.07	\$4.381

PARTS ISSUED						
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
PH48	NS	1.000	\$2.517	03/14/2022	\$2.517	
PART NAME: Filter, Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform				
809332	NS	6.000	\$7.455	03/14/2022	\$44.730	
PART NAME: Oil; 5W30 Bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform				
872174	NS	1.000	\$6.570	03/14/2022	\$6.570	
PART NAME: Grease bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform				
OWI/PWN0G3	NS	1.000	\$3.365	03/14/2022	\$3.365	
PART NAME: Fluid washer		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform				

WORK ORDER TOTALS					
TOTAL PARTS:	\$57.182	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$129.492	TOTAL MISC:	\$0.000	TOTAL COST:	\$186.674

NOTES

SERVICE WRITER - PMA DRIVER IS STILL HEARING FRONT END NOISE - I ASKED BRANDON TO BRING IT TO US WHEN HE IS HEARING THE NOISE BUT HE DID NOT BRING IT. THE DRIVER WHO BROUGHT OVER THE VEHICLE DID NOT HEAR ANY NOISE IN THE FRONT END. MAY WANT TO TEST DRIVE TO SEE IF YOU CAN HEAR ANY NOISE. TAKE HOME VEHICLE - CALL 528-3160 EXT 217 OR 218 WHEN READY FOR PICK UP ; 3550 3/14/22 - PMA done Rotated tires. Test drove vehicle before entering building to observe any noise from front end as described, and the tires create lots of road noise, and the front drive axles always turn even when the front differential is disengaged. After rotating tires, test drove vehicle again, and the noise had a significant change. The large wide off road tires create more noise as the tires wear. Driver's seat is beginning to get wear tears from entry and exit of seat because of height from ground to do so.

WORK ORDER: 119157			
EMIS: 3550			
Work Order Status: C - Closed	Date In:	07/06/2022	
Work Order Shop: CEN - Fleet Maintenance	Date Out:	07/06/2022	

EMIS INFORMATION		
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 117558

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
STAFFIERI	07/06/2022	Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform	1.34	\$81.755
STAFFIERI	07/06/2022	Preventive Maintenance Service / Preventative Maintenance / PM T - Transmission Service / Perform	0.41	\$24.719
STAFFIERI	07/06/2022	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	0.10	\$6.006

PARTS ISSUED						
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
OWI/PWNOG3	NS	1.000	\$3.328	07/06/2022	\$3.328	
PART NAME: Fluid washer			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
PH48	NS	1.000	\$2.517	07/06/2022	\$2.517	
PART NAME: Filter, Oil			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
809332	NS	6.000	\$7.455	07/06/2022	\$44.730	
PART NAME: Oil; 5W30 Bulk			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
872174	NS	1.000	\$6.570	07/06/2022	\$6.570	
PART NAME: Grease bulk			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
PIC/4620	NS	2.000	\$2.977	07/06/2022	\$5.954	
PART NAME: Spray brake kleen			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM T - Transmission Service / Perform			
58369	NS	1.000	\$45.931	07/06/2022	\$45.931	
PART NAME: Filter transmission			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM T - Transmission Service / Perform			
BG314B	NS	7.000	\$6.875	07/06/2022	\$48.125	
PART NAME: Atf syn bulk qt			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM T - Transmission Service / Perform			

WORK ORDER TOTALS					
TOTAL PARTS:	\$157.155	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000

TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$112.480	TOTAL MISC:	\$0.000	TOTAL COST:	\$269.635

NOTES

Service Notes - PMA PMB PMT Call 528-3160 ; Pm B - Perform service, grease, rotate and relearn TPMS monitor locations. ; Pm T - Perform service, replace transmission filter, clean pan and reinstall. top off fluid when completed ; Pm A - Perform service. Reset oil change reminder

WORK ORDER: 121108
EMIS: 3550

Work Order Status: C - Closed	Date In:	11/28/2022
Work Order Shop: CEN - Fleet Maintenance	Date Out:	11/28/2022

EMIS INFORMATION

YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 124523

TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
RITTER	11/28/2022	Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform	0.56	\$34.008
RITTER	11/28/2022	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	0.30	\$18.459
RITTER	11/28/2022	Preventive Maintenance Service / Preventative Maintenance / PM D - State Inspection / Perform	0.22	\$20.000

PARTS ISSUED

PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
872174	NS	1.000	\$7.417	11/28/2022	\$7.417
PART NAME: Grease bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
809332	NS	6.000	\$7.455	11/28/2022	\$44.730
PART NAME: Oil; 5W30 Bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform			
PH48	NS	1.000	\$2.517	11/28/2022	\$2.517
PART NAME: Filter, Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform			

WORK ORDER TOTALS

TOTAL PARTS:	\$54.664	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$72.467	TOTAL MISC:	\$0.000	TOTAL COST:	\$127.131

NOTES

SERVICE WRITER - PMA PMB PMD TAKE HOME VEHICLE CALL 528-3160 EXT 217 OR 218 ; PM's - PM's complete. No issues.

WORK ORDER: 122433			
EMIS: 3550			
Work Order Status: C - Closed	Date In:	03/13/2023	
Work Order Shop: CEN - Fleet Maintenance	Date Out:	03/13/2023	

EMIS INFORMATION		
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 131236

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
CAMPBELL	03/13/2023	General Repair / Suspension / System / Diagnosis	1.12	\$67.915
CAMPBELL	03/13/2023	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	0.56	\$34.093
CAMPBELL	03/13/2023	Repaired From PM Service / Transfer Case / Transfer Case Fluid / Replace	0.52	\$31.843

PARTS ISSUED						
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
PH48	NS	1.000	\$2.772	03/13/2023	\$2.772	
PART NAME: Filter, Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform				
809332	NS	6.000	\$9.162	03/13/2023	\$54.972	
PART NAME: Oil; 5W30 Bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform				
872174	NS	1.000	\$7.417	03/13/2023	\$7.417	
PART NAME: Grease bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform				
BG314B	NS	2.000	\$7.698	03/13/2023	\$15.396	
PART NAME: Atf syn bulk qt		REPAIR: Repaired From PM Service / Transfer Case / Transfer Case Fluid / Replace				

WORK ORDER TOTALS					
TOTAL PARTS:	\$80.557	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$133.851	TOTAL MISC:	\$0.000	TOTAL COST:	\$214.408

NOTES

Service Notes - PMA Check 4x4 when engaged the front end is making popping noise. 528-3160 ext 218 ; Diagnosis - Running the vehicle in 4wd creates a clunking noise coming from the transfer case, u joints are all in good condition, transfer case oil is dark and burnt, will change the oil and see if there is any improvement. ; Replace - drained and filled transfer case oil, oil removed from the transfer case was very dark, burnt smelling, and contained alot of metal shavings. After changing the oil I retested the 4wd system and it appears to be operating as it should. ; PMA - Performed PMA

WORK ORDER: 124086					
EMIS: 3550					
Work Order Status: C - Closed		Date In: 07/17/2023			
Work Order Shop: CEN - Fleet Maintenance		Date Out: 07/17/2023			
EMIS INFORMATION					
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E			
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8			
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO			
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G			
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm			
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 137488			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
FERNANDEZ	07/17/2023	Preventive Maintenance Service / Preventative Maintenance / PM B - Six Month Checkup / Perform	0.59	\$41.794	
FERNANDEZ	07/17/2023	Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform	0.25	\$17.962	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
809332	NS	6.000	\$9.162	07/17/2023	\$54.972
PART NAME: Oil; 5W30 Bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
PH48	NS	1.000	\$2.772	07/17/2023	\$2.772
PART NAME: Filter, Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
872174	NS	1.000	\$7.417	07/17/2023	\$7.417
PART NAME: Grease bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A - Oil Change / Perform			
WORK ORDER TOTALS					
TOTAL PARTS:	\$65.161	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$59.756	TOTAL MISC:	\$0.000	TOTAL COST:	\$124.917
NOTES					
Service Notes - PMA PMB 528-3160 ext 218 ; PMB - Topped off all fluids, set tires to placard, rotated tires. ; PMA - Changed old oil and filter out with a new filter and oil, reset reminder, and affixed sticker to windshield.					
WORK ORDER: 126161					
EMIS: 3550					
Work Order Status: C - Closed		Date In: 11/30/2023			
Work Order Shop: CEN - Fleet Maintenance		Date Out: 11/30/2023			
EMIS INFORMATION					
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E			

MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 144790

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
GORDON	11/30/2023	Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform	0.53	\$37.181
CAMPBELL	11/30/2023	Preventive Maintenance Service / Preventative Maintenance / PM D - State Inspection / Perform	0.33	\$20.000
GORDON	11/30/2023	Repaired From PM Service / Tire-Wheel / TPMS / Replace	2.54	\$179.639
GORDON	11/30/2023	Repaired From PM Service / Light System / Headlight Bulb / Diagnosis	0.41	\$29.191

PARTS ISSUED						
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
75525	NS	6.000	\$6.746	11/30/2023	\$40.476	
PART NAME: Oil bulk 5w-30			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
PH48	NS	1.000	\$2.772	11/30/2023	\$2.772	
PART NAME: Filter, Oil			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
AF1519	NS	1.000	\$8.097	11/30/2023	\$8.097	
PART NAME: Filter air			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
OWI/PWN0G3	NS	1.000	\$3.328	11/30/2023	\$3.328	
PART NAME: Fluid washer			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
872174	NS	1.000	\$7.417	11/30/2023	\$7.417	
PART NAME: Grease bulk			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
9L3Z1700A	NS	1.000	\$12.987	11/30/2023	\$12.987	
PART NAME: Kit valve			REPAIR: Repaired From PM Service / Tire-Wheel / TPMS / Replace			

MANUAL ADJUSTMENTS		
REASON	CREATED DATE	AMOUNT
David - Time to replace 2 TPMS sensors should not be 2.75 hours. Adjustment removes about 45 minutes of labor.	12/01/2023	(\$50.000)

WORK ORDER TOTALS					
TOTAL PARTS:	\$75.077	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	(\$50.000)
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$266.011	TOTAL MISC:	\$0.000	TOTAL COST:	\$291.088

NOTES

W300d - WorkOrderDetailsByDate

2/23/2026 8:24:03 AM

Service writer - PMP, PMD, headlights are not as bright as they used to be, customer supplied TPMS sensors for two tires that are malfunctioning. 436-4357 ; PMD - Performed State inspection. ; 3550 - Completed PMP,PMD, inspected headlights, left side LED bulb was out of the housing re adjusted the clamps that holds the bulb re inserted bulb, both low beam and high beam seem to work normally. Inspected the tires TPMS, both rear tires sensors are not responding, replace both sensors.

WORK ORDER: 128070

EMIS: 3550

Work Order Status: C - Closed Date In: 04/16/2024
 Work Order Shop: CEN - Fleet Maintenance Date Out: 04/16/2024

EMIS INFORMATION

YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 150954

TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
RITTER	04/16/2024	Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform	0.92	\$64.918
PARKER	04/16/2024	Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform	0.84	\$0.000
RITTER	04/16/2024	General Repair / Light System / Headlight Bulb / Replace	2.07	\$145.973

PARTS ISSUED

PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
75525	NS	6.000	\$6.746	04/16/2024	\$40.476
PART NAME: Oil bulk 5w-30		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
PH48	NS	1.000	\$2.893	04/16/2024	\$2.893
PART NAME: Filter, Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
872174	NS	1.000	\$7.417	04/16/2024	\$7.417
PART NAME: Grease bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
OWI/PWN0G3	NS	1.000	\$3.365	04/16/2024	\$3.365
PART NAME: Fluid washer		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
D5S	NS	1.000	\$168.371	04/16/2024	\$168.371
PART NAME: Bulb headlight HID		REPAIR: General Repair / Light System / Headlight Bulb / Replace			

WORK ORDER TOTALS

TOTAL PARTS:	\$222.522	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		

W300d - WorkOrderDetailsByDate

2/23/2026 8:24:03 AM

TOTAL LABOR: \$210.891 TOTAL MISC: \$0.000 TOTAL COST: \$433.413

NOTES

Notes - PMP Check drivers headlamp 434-436-4357 ; Headlight - Found LF bulb had fallen out of its mount. The bulb itself was damaged as a result. I installed a new headlight bulb. The LF headlight assembly has multiple broken areas. The assembly is secure regardless. If you are fortunate enough to have to replace a bulb or assembly in the future, let me save you some time... There is a semi-hidden black locking cam for the bulb itself. It is located deeper in the assembly than the bulb. You must reach in with your finger and rotate this tab in order to release the bulb. The long metal fingers on the sides of the ignitor are NOT what hold the bulb assembly in. Hope this helps. If you have to remove the whole assembly then I would recommend just removing the whole front bumper first. Yes the metal front bumper. The problem is that it overlaps a piece that must be removed in order to remove headlight assembly. Mitchell says the piece can be removed but in my experience it could not without the bumper being removed. ; PMP - PMP complete. No issues.

WORK ORDER: 129800

EMIS: 3550

Work Order Status: C - Closed Date In: 08/09/2024

Work Order Shop: CEN - Fleet Maintenance Date Out: 08/26/2024

EMIS INFORMATION

YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 157249

TECHNICIAN REPAIRS PERFORMED

TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
CLARK	08/12/2024	General Repair / Axle Rear Drive / Assembly / Diagnosis	11.50	\$856.491
CAMPBELL	08/16/2024	General Repair / Axle Rear Drive / Rear Axle Housing / Replace	0.23	\$17.029
FERNANDEZ	08/16/2024	General Repair / Axle Rear Drive / Rear Axle Housing / Replace	0.53	\$39.314
CLARK	08/22/2024	General Repair / Axle Rear Drive / Rear Axle Housing / Replace	16.92	\$1,260.413

SUBLET REPAIRS

VENDOR	PARTS	LABOR	OTHER	OPID	DATE BACK	REPAIR DESCRIPTION	SUBLET COST
Jasper Engines & Transmissions	\$2,552.00	\$0.00	\$0.00	215	08/26/2024	General Repair / Axle Rear Drive / Rear Axle Housing / Replace	\$3,074.905

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
102490.	NS	4.000	\$27.154	08/09/2024	\$108.616
PART NAME: Oil gear 75W-140		REPAIR: General Repair / Axle Rear Drive / Assembly / Diagnosis			
PIC/4620	NS	2.000	\$3.098	08/16/2024	\$6.196
PART NAME: Spray brake kleen		REPAIR: General Repair / Axle Rear Drive / Rear Axle Housing / Replace			
16PB-DS	NS	1.000	\$11.192	08/16/2024	\$11.192
PART NAME: Penetrant spray		REPAIR: General Repair / Axle Rear Drive / Rear Axle Housing / Replace			
A70	NS	2.000	\$106.821	08/21/2024	\$213.642
PART NAME: Bearing axle		REPAIR: General Repair / Axle Rear Drive / Rear Axle Housing / Replace			
a71	NS	2.000	\$60.742	08/21/2024	\$121.484
PART NAME: Bearing axle		REPAIR: General Repair / Axle Rear Drive / Rear Axle Housing / Replace			
710927	NS	2.000	\$38.629	08/21/2024	\$77.258
PART NAME: seal axle rear		REPAIR: General Repair / Axle Rear Drive / Rear Axle Housing / Replace			

MANUAL ADJUSTMENTS		
REASON	CREATED DATE	AMOUNT
Stuart over on labor, quoted BRRJ price of \$4,700.00	08/26/2024	(\$1,086.530)

WORK ORDER TOTALS					
TOTAL PARTS:	\$538.388	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	(\$1,086.530)
TOTAL SUBLET:	\$3,074.905	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$2,173.247	TOTAL MISC:	\$0.000	TOTAL COST:	\$4,700.010

NOTES
Notes - Check for noise in rear ; NOISE IN REAR DIFFERENTIAL - drained and refilled rear diff, noise still there, pulled cover , removed axles and removed diff carrier, fond right side carrier bearing pitted and rough, Jasper rear differential was ordered, installed new rear axle in truck, replaced inner and outer axle hub bearings and races and seals, 3 quarts of 75w140 rear axle oil, friction modifier needed for this axle, NEEDS DIFF OIL CHANGE AT 5000 MILES FOR WARRANTY FROM JASPER

WORK ORDER: 130966					
EMIS: 3550					
Work Order Status: C - Closed			Date In:	10/09/2024	
Work Order Shop: CEN - Fleet Maintenance			Date Out:	10/09/2024	
EMIS INFORMATION					
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E			
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8			
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO			
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G			
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm			
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 160329			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
FERNANDEZ	10/09/2024	General Repair / Axle Rear Drive / System / Adjust	1.04	\$77.222	
FERNANDEZ	10/09/2024	Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform	0.52	\$38.632	
FERNANDEZ	10/09/2024	Preventive Maintenance Service / Preventative Maintenance / PM D - State Inspection / Perform	0.54	\$20.000	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
75525	NS	6.000	\$6.458	10/09/2024	\$38.748
PART NAME: Oil bulk 5w-30		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
PH48	NS	1.000	\$2.893	10/09/2024	\$2.893
PART NAME: Filter, Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
872174	NS	1.000	\$7.417	10/09/2024	\$7.417
PART NAME: Grease bulk		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
MBL/104361	NS	2.000	\$17.053	10/09/2024	\$34.106
PART NAME: Oil 75w90 syn gear		REPAIR: General Repair / Axle Rear Drive / System / Adjust			
889785	NS	1.000	\$18.807	10/09/2024	\$18.807
PART NAME: Oil gear 75w90		REPAIR: General Repair / Axle Rear Drive / System / Adjust			
WORK ORDER TOTALS					
TOTAL PARTS:	\$101.971	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$135.854	TOTAL MISC:	\$0.000	TOTAL COST:	\$237.825
NOTES					
Service Writer Notes - PMP PMD CHANGE REAR DIFF FLUID TAKE HOME CALL 436-4357 WHEN READY FOR PICK UP ; Rear Diff - Drained fluid, looked good, filled to proper level with new fluid. ; PMP - Changed old oil and filter out with new oil and filter. Set front tires to 60 psi and rear tires to 80 psi. Topped off all fluids.					

WORK ORDER: 133258				
EMIS: 3550				
Work Order Status: C - Closed		Date In: 02/13/2025		
Work Order Shop: CEN - Fleet Maintenance		Date Out: 02/18/2025		
EMIS INFORMATION				
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E		
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8		
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO		
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G		
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm		
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 163900		
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
BERRY	02/13/2025	General Repair / Tire-Wheel / Tire / Repair	0.49	\$36.500
PARKER	02/13/2025	General Repair / Tire-Wheel / Tire / Repair	0.12	\$8.939
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$45.439	TOTAL MISC:	\$0.000	TOTAL COST: \$45.439
NOTES				
3550 2/13/25 - Removed nail and installed patch/plug. Labeled inside of wheel and propped against hand rail.				

WORK ORDER: 134415			
EMIS: 3550			
Work Order Status: C - Closed		Date In:	04/17/2025
Work Order Shop: CEN - Fleet Maintenance		Date Out:	04/17/2025

EMIS INFORMATION		
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8
MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 168250

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
RITTER	04/17/2025	Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform	1.20	\$89.015

PARTS ISSUED						
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
75525	NS	6.000	\$6.458	04/17/2025	\$38.748	
PART NAME: Oil bulk 5w-30			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
PH48	NS	1.000	\$2.893	04/17/2025	\$2.893	
PART NAME: Filter, Oil			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
OWI/PWN0G3	NS	1.000	\$3.365	04/17/2025	\$3.365	
PART NAME: Fluid washer			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			

WORK ORDER TOTALS					
TOTAL PARTS:	\$45.006	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$89.015	TOTAL MISC:	\$0.000	TOTAL COST:	\$134.021

NOTES
Notes - PMP 528-3160 ext6218 ; PMP - PMP complete. No issues.

WORK ORDER: 137787			
EMIS: 3550			
Work Order Status: C - Closed		Date In:	10/28/2025
Work Order Shop: CEN - Fleet Maintenance		Date Out:	10/31/2025

EMIS INFORMATION		
YEAR: 2018	ORG: Outside Agencies; Fuel-Maintenance	TIRE SIZE: LT245/75R17E
MAKE: GMC	DEPT: 5003-00350 BRRJA	ENGINE SIZE: 6.0L V8

MODEL: Sierra 2500	BILL CODE: Bill Everything	TRANS: 6 SP AUTO
LICENSE: 193-514L	PARKING LOCATION:	FUEL TYPE: G
OPERATOR:	VIN/SERIAL NUMBER: 1GT12REG7JF137573	ASSET AVAIL CODE: 7:00am - 5:00pm
CLASS: 3/4 Ton Pick-Up		METERS: Meter for odometer - 175802

TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
TROWER	10/29/2025	Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform	1.52	\$130.308
TROWER	10/29/2025	Preventive Maintenance Service / Preventative Maintenance / PM T - Transmission Service / Perform	0.84	\$72.202
TROWER	10/31/2025	Damaged / Axle Rear Drive / Axle Seal / Replace	3.12	\$268.129
TROWER	10/31/2025	Preventive Maintenance Service / Preventative Maintenance / PM D - State Inspection / Perform	0.56	\$20.000

PARTS ISSUED						
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
75525	NS	6.000	\$4.773	10/29/2025	\$28.638	
PART NAME: Oil bulk 5w-30			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
2488	NS	1.000	\$23.226	10/29/2025	\$23.226	
PART NAME: Filter, Air			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
PH48	NS	1.000	\$2.893	10/29/2025	\$2.893	
PART NAME: Filter, Oil			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM P - Oil Change / Safety Inspection / Perform			
BG314B	NS	12.000	\$8.254	10/29/2025	\$99.048	
PART NAME: Atf syn bulk qt			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM T - Transmission Service / Perform			
15950	NS	1.000	\$69.303	10/29/2025	\$69.303	
PART NAME: Filter Transmission			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM T - Transmission Service / Perform			
ft8523f	NS	1.000	\$132.409	10/29/2025	\$132.409	
PART NAME: Pads brake front or rear			REPAIR: Damaged / Axle Rear Drive / Axle Seal / Replace			
104361	NS	1.000	\$16.973	10/29/2025	\$16.973	
PART NAME: Oil 75w90			REPAIR: Damaged / Axle Rear Drive / Axle Seal / Replace			
29587A	NS	1.000	\$57.809	10/29/2025	\$57.809	
PART NAME: Seal, Axle			REPAIR: Damaged / Axle Rear Drive / Axle Seal / Replace			
35032	NS	1.000	\$10.138	10/31/2025	\$10.138	
PART NAME: Fluid brake dot 3 32oz			REPAIR: Damaged / Axle Rear Drive / Axle Seal / Replace			
18B5307	NS	1.000	\$90.012	10/31/2025	\$90.012	
PART NAME: Caliper brake rear left			REPAIR: Damaged / Axle Rear Drive / Axle Seal / Replace			
BB1050	NS	1.000	\$49.574	10/31/2025	\$49.574	
PART NAME: Shoe kit parking brake			REPAIR: Damaged / Axle Rear Drive / Axle Seal / Replace			

WORK ORDER TOTALS				
TOTAL PARTS:	\$580.023	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$490.639	TOTAL MISC:	\$0.000	TOTAL COST: \$1,070.662

NOTES
SERVICE WRITER - PMP, PMD, PMT, rotate tires. 944-4962 ; PMP repairs - Completed the PMP rear axle seal leaking ordered seal and brake pads also ordered the trans filter kit ; PMT - Completed the PMT ; state - completed the state insp replaced the inner axle seal

REPORT PARAMETERS:

Time Zone: Eastern Standard Time
Start Date: 10/01/2017
End Date: 02/23/2026
Organization: All Values
Department: All Values
EMIS: 3550
Maint Shop: All Values
Labor Hours: Actual Hours
Page Breaks: No
Display Unit Cost or True Cost or Issue Price: Issue Price

REPORT VERSIONS:

Report Version: 20211207.2000
Script Version: 20211207.1600