



PAID BY USA

OLD CHEV JAW

KE



399 MEMORIAL AVE, THUNDER BAY, ONTARIO P7B 3Y4

PHONE: 807.683.4910 | FAX: 807.345.8440

TOLL FREE: 800.465.3915 | BADANAIMOTORS.COM

HST # 861502599 RT0001

CHEVROLET

Lot

not visible

SO# 115785

SERVICE ORDER 1178

Status Printed 03/20/2025 3:37:25 PM

User amanda Page 1

CUSTOMER COPY

Customer No 45362
Thunder Bay Public Library
285 RED RIVER RD.
THUNDER BAY, ON P7B 1A9
Home (807) 684-6806 Cell (807) 633-6901
Bus (807) 627-6742
Email
Term Cash

Advisor Amanda Burns
Shop S1
Priority 10
Promised
Opened
Cashiered
License AH83276
Odom In 143961
Odom Out 143961
In Service Date 08/14/2014
Tag# 1178
Location
PO #
Year 2014
Make CHEVROLET
Model EXPRESS 1500
Colour SUMMIT WHITE
Type
Vehicle ID No
Ext Warranty 1GCZGTCA0E1207692

Request Description
SES CHECK ENGINE LIGHT IS ON
Labour Description
SES CHECK ENGINE LIGHT IS ON
Rate 185.00
Technician
Notes scan ck codes p2097 & p2099 set post catalyst fuel trim banks 1 & 2 codes p0138 & p0155 banks 1 & 2 sensors 2 high voltage

Job CSR Status
27497 Original
Hours Amount
0.50 92.50
Labour Total
Request Sub-total
02.50 92.50

Request Description
MOT INSPECTION
Labour Description
MOT INSPECTION
Rate 185.00
Technician 60 -
Cause -parking brake inop. intermediate cable snapped. needs diag time, may need more then just the cable
-rear door power lock no working- needs diag
-transmission cooler lines are leaking
-right side exhaust manifold has broken bolts
-all for tires are worn and weather cracked
-play in both inner tie rods
-play in left lower ball joint
-front bumper air deflector damaged
-both wipers streaking

CSR Status
17497 Original
Hours Amount
1.18 279.95
Labour Total
Request Sub-total
279.95 279.95

Correction

Request Description
DIAG EXHAUST LEAK AROUND CATALYTIC CONVERTER
Labour Description
DIAG EXHAUST LEAK AROUND CATALYTIC CONVERTER
Sublet
507/Minute Muffler/exhaust

Job CSR Status
27497 Original
Hours Amount
0.50 92.50
Type
CSUB 27457 155.00

Tire Storage Terms: Any customer who has tires stored will have them stored up to a maximum of 8 months from invoice date or until customer requests to have tires removed from storage, at which point the storage term will end. Badanal Motors is not responsible for unclaimed tired at expiration of storage terms. Tires left beyond 30 days of the term expiration date will be disposed of without any liability or obligation to the customer. Signing of the repair order is deemed to be acceptance of these terms by customer.

Tire manufacturers are responsible for imposing the above tire fee. It is being used to cover the cost of meeting the tire manufactures legal responsibility to collect and recycle used tires. For information on how tires are collected and recycled please visit www.etracks.ca.

PRIVACY—PERSONAL INFORMATION IS COLLECTED IN ACCORDANCE WITH APPLICABLE PRIVACY LEGISLATION AND IS GOVERNED BY OUR DEALERSHIP'S PRIVACY POLICY. YOUR PRIVACY IS IMPORTANT TO US. ASK US IF YOU WOULD LIKE INFORMATION ABOUT OUR DEALERSHIP'S PRIVACY POLICY.

SIGNATURE: