Work Order Detail FLEET-2024-28



Asset ID: 82135 2008 FORD E450 MEDIC UNIT

W-AMBULANCE

License Number: 46486D

Work Order ID: FLEET-2024-28

Job Type: PM

PM Scheduled: **11/21/2023** WO Meter 2: **480 HOURS**

Priority: 1 - 2 HOUR TURN AROUND

A SERVICE

Repair Location: FLEET - CITY OF BREMERTON ESD

Job Status: CLOSED

PM Service: A - PM SERVICE A
WO Meter 1: 75590 MILES
Projected Completion 01/22/2024 07:14

Date:

Next PM Due Date: 01/08/2025

Non Service Request Tasks

Task: A - Pm Service A							
WAC: 97 - PM/INSPECTION	Reason: -						
Work Class: 1 - SCHEDULED	Comments:						
Labor						Labor Hrs	Cost
01/10/2024 14:10 Emp: 4066	- Riley Dever					1.83	157.38
01/11/2024 14:19 4066	- Riley Dever					0.97	83.42
Parts				Qty Issued	Iss Price	Tax & Markup	Total Cost
F3600-0 - FILTER; FUEL FILTER	KIT			1.00	76.05	0.00	76.05
Removed Serial #:		Serial #:	'				
F7311-0 - FILTER; NAPA GOLD (IL FILTER			1.00	22.52	0.00	22.52
Removed Serial #:		Serial #:					
F15W40-0 - OIL; ENGINE OIL				16.00	5.33	0.00	85.21
Removed Serial #:		Serial #:	'			'	

Overhead

Title:

Small Parts - Labor: **0.00** Tools: **0.00** Total Overhead Costs: **7.00**

Small Parts - Parts: **0.00** Overhead Costs: **7.00**

Page 1 of 5

©2025 AssetWorks LLC. All Rights Reserved.

Report Date: 8/13/2025

Work Order Detail

Work Order: FLEET-2024-28

PM Checklist					
Task / Comment	Exception PM: No	Employee	Failed	N/A	Completed
DM 0001 DEDLACE EN		4066 DILEY DEVED	· · · · · · · · · · · · · · · · · · ·		
PM-0001 - REPLACE EN	IGINE OIL AND FILTER	4066 - RILEY DEVER			✓
	NGINE OIL AND FILTER PER OE IF USAGE IS LOW ADD MILES/HOURS				
SINCE LAST OIL CHAN			· · · · · · · · · · · · · · · · · · ·		
PM-0002 - ROAD TEST		4066 - RILEY DEVER			\checkmark
	VEHICLE, SHOULD BE NO MORE THE				
	STEN FOR ODD NOISES, VIBRATIONS AND SUSPENSION ISSUES, CHECK				
FOR TRANSMISSION A	ND ENGINE ISSUES	AOSC DILEVED	· · · · · · · · · · · · · · · · · · ·		
PM-0003 - LUBRICATE	CHASSIS - STEERING - SUSPENSION	4066 - RILEY DEVER			✓
PM-0004 - CHECK TRAI	NSMISSION FLUID	4066 - RILEY DEVER			√
DM 000E CUECK DIES		AOSS DILEV DEVED	·····	—	·····
PM-0005 - CHECK DIFF	ERENTIAL FLUID	4066 - RILEY DEVER			✓
PM-0007 - CHECK AIR	PRESSURE/TREAD DEPTH	4066 - RILEY DEVER			\checkmark
DM 0000 INSPECT TI	RE CONDITION - INCLUDING SPARE &	4066 - RILEY DEVER	······		
JACK	RE CONDITION - INCLUDING SPARE &	14000 - KILLT DEVEK			✓
Procedure: COMPLETE	TEST FOR TIRE TREAD DEPTH				
PM-0010 - CHECK FRO	NT-END FOR ABNORMAL WEAR	4066 - RILEY DEVER			√
PATTERN ON TIRES	NAVE CYCTEM	AOCC DILEV DEVED	·····		·····
PM-0011 - INSPECT BR	ARE SYSTEM	4066 - RILEY DEVER			✓
PM-0012 - CHECK BRAI	KE FLUID LEVEL/CONDITION	4066 - RILEY DEVER			\checkmark
PM-0013 - CHECK COO	I INC SYSTEM	4066 DILEY DEVED	······- ·····		
LEVEL/CONDITION/LEA		4066 - RILEY DEVER			√
PM-0014 - CHECK FAN	AND ACCESSORY BELTS & HOSES	4066 - RILEY DEVER			√
PM-0015 - LOAD TEST	RATTERY	4066 - RILEY DEVER	······ [] ·····		·····
	DATTEN	1000 RILLY BEVER			✓
PM-0016 - CHECK BAT	TERY CONNECTIONS/CABLES	4066 - RILEY DEVER			\checkmark
PM-0017 - INSPECT AI	R FILTER	4066 - RILEY DEVER	· · · · · · · · · · · · · · · · · · ·		
	· · · · - · · - · · · · · · · · · · · · · · · ·		······		· · · · · ·
PM-0019 - INSPECT ST	EERING/SUSPENSION	4066 - RILEY DEVER			\checkmark
PM-0020 - CHECK POW	/ER STEERING FLUID	4066 - RILEY DEVER			
			· · · · · · · · · · · · · · · · · · ·		····
PM-0021 - INSPECT EX	HAUST SYSTEM	4066 - RILEY DEVER			\checkmark
PM-0023 - INSPECT HC	DRN OPERATION	4066 - RILEY DEVER			√
			······································		····
PM-0024 - INSPECT GL	ASS	4066 - RILEY DEVER			\checkmark
PM-0025 - INSPECT WI	INDSHIELD WIPERS	4066 - RILEY DEVER			√

Page 2 of 5

Work Order Detail Work Order: FLEET-2024-28

PM-0026 - INSPECT WINDSHIELD WASHER LEVEL/OPERATION	4066 - RILEY DEVER		\checkmark
PM-0027 - CHECK ALL WARNING LIGHTS, EMERGENCY LIGHTS AND SIRENS	4066 - RILEY DEVER		\checkmark
PM-0030 - CHECK & NOTE EXTERIOR DAMAGE	4066 - RILEY DEVER		\checkmark
PM-0031 - CHECK INTERIOR FOR WEAR/DAMAGE - SEATS/MATS/STEERING WHEEL	4066 - RILEY DEVER		\checkmark
PM-0037 - PERFORMANCE TEST AIR CONDITIONER	4066 - RILEY DEVER		\checkmark
PM-0428 - INSPECT FOR OIL LEAKS- ENGINE, TRANSMISSION, AXLE	4066 - RILEY DEVER		\checkmark
PM-0498 - INSPECT MIRRORS	4066 - RILEY DEVER		\checkmark
PM-0500 - INSPECT SEAT BELTS	4066 - RILEY DEVER		✓
PM-0501 - CHECK HORN AND BACK-UP ALARM	4066 - RILEY DEVER		\checkmark
PM-0503 - CHECK FIRE EXTINGUISHER	4066 - RILEY DEVER		√
PM-0485 - CHECK LIGHTS	4066 - RILEY DEVER		\checkmark

Test Results

Test ID: 12047		Test Date: 01/10/202	24	Result: PASS	Comment:	
Component	Result	Test Date/Time	Numeric Value Found	Numeric Value Adjust	Qualitative Finding	Line Comment
ANTIFREEZE - ANTIFREEZE PROTECTION VALUE	PASS		-30.00			

Test ID: 12048		Test Date: 01/11/202	24	Result: FAIL	Comment:	
Component	Result	Test Date/Time	Numeric Value Found	Numeric Value Adjust	Qualitative Finding	Line Comment
BATTERY TEST - BATTERY LOAD TEST	FAIL		11.23			
BATTERY TEST 2 - BATTERY LOAD TEST	FAIL		11.23			
BATTERY TEST 3 - BATTERY LOAD TEST BATTERY TEST 4 - BATTERY LOAD TEST	FAIL		11.24			

Test ID: 12049		Test Date: 01/10/202	24	Result: PASS	Comment:	
Component	Result	Test Date/Time	Numeric Value Found	Numeric Value Adjust	Qualitative Finding	Line Comment
BRAKE THICKNESS LF - BRAKE LINING THICKNESS LEFT FRONT	PASS		11.00			
BRAKE THICKNESS LR - BRAKE LINING THICKNESS LEFT REAR	PASS		12.00			
Brake Thickness RF - Brake Lining Thickness Right Front	PASS		11.00			
BRAKE THICKNESS RR - BRAKE LINING THICKNESS RIGHT REAR	PASS		12.00			

Test ID: 12050		Test Date: 01/10/20	24	Result: FAIL	Comment:	
Component	Result	Test Date/Time	Numeric Value Found	Numeric Value Adjust	Qualitative Finding	Line Comment
TRK TIRE DEPTH LF - TRUCK TIRE TREAD DEPTH LEFT FRONT	FAIL		5.00			
TRK TIRE DEPTH LR - TRUCK TIRE TREAD DEPTH LEFT REAR	PASS		10.00			
TRK TIRE DEPTH RR - TRUCK TIRE TREAD DEPTH RIGHT REAR	PASS		10.00			
TRK TIRE DEPTH RF - TRUCK TIRE TREAD DEPTH RIGHT FRONT	PASS		5.00			
TRK TIRE DEPTH LRO - TRUCK TIRE TREAD DEPTH LEFT REAR OUTER	PASS		10.00			

AssetW**♥**RKS

Page 4 of 5

©2025 AssetWorks LLC. All Rights Reserved.

Work Order Detail

Work Order: FLEET-2024-28

TRK TIRE DEPTH RRO - PASS TRUCK TIRE TREAD DEPTH RIGHT REAR OUTER

10.00

Comments:

A SERVICE FRONT TIRES WORN NEED REPLACED RIGHT SIDE FRONT SCENE LIGHT INOPERATIVE **ELECTRIC STEP INOPERATIVE** FRONT WHEEL BEARINGS HAVE PLAY FRONT BALL JOINTS HAVE PLAY BATTERIES FAILED LOAD TEST, TRIED TO CHARGE AND RETEST, BATTERIES WOULD NOT ACCEPT CHARGE AND IMMEDIATELY FAILED

Internal Parts Cost:	\$183.78
Internal Labor Cost:	\$240.80
Commercial Parts Cost:	\$0.00
Commercial Labor Cost:	\$0.00
Commercial Misc Cost:	\$0.00
Commercial Tax & Markup:	\$0.00
Equipment Usage Costs:	\$0.00
Overhead Costs:	\$7.00

Internal Total:	\$431.58
Commercial Total:	0.00
Work Order Total:	\$431.58

AssetW**⊅**RKS

Page 5 of 5