

c/r vsi

Precision Tune Auto Care 9290 Gunston Rd. Bldg. 1462 Ft. Belvoir, VA 22060

Phone: 703-669-2317 Center No.: 072-56

ptac07256@precisionac.com

Invoice Number Estimate 14128 47829

07:15

03/12/25

Mileage In 41746 Out 41746 mi

Katie Derr 10051 Day rd	Cell Work	Year 2004 Make Ford		PO#	x Auto Man
	Home 703-819-6425	Model	del Explorer 4 E	4 E	X Auto Man
FORT BELVOIR, VA 22060	Email katherine.a.derr.naf@army.mil	Tag W903291, VA Veh Id			

Customer Comments

Technician Comments

both front lower ball joints excessive play front and rear rotors have excessive rust on inner surfaces right front sway bar link is broken both rear sway bar links are broken for vsi right frontcv axle boot torn recommend replacing

	Part	Description	Quantity	Each	Labor	Total
		Recommended Service	s			
R 03/05/25		FRONT BRAKE PADS	1.00	113.59	181.87	295.46
R 03/05/25		FRONT BRAKE ROTORS	2.00	140.60	55.96	337.16
R 03/05/25		REAR BRAKE PADS	1.00	113.59	181.87	295.46
R 03/05/25		REAR BRAKE ROTORS	2.00	140.60	55.96	337.16
R 03/05/25		FRONT SWAY BAR LINKS	2.00	44.35	167.88	256.58
R 03/05/25		REAR SWAY BAR LINKS	2.00	41.22	167.88	250.32
R 03/05/25		LOWER BALL JOINTS	2.00	86.01	615.56	787.57
R 03/05/25		RIGHT FRONT CV AXLE	1.00	179.20	181.87	361.07
		Services Performed				
-1 25/0/28	vsi	VA State Inspection	1.00		18.61	18.61
-1 25/0/28	VS	. VA State Inspection Sticker	1.00			
0 25/0/28	miod	Diagnostic brake inspection	1.00		41.97	41.97
		Mo Accept The Military Stay Cond				

If the property identified on this order is not picked up within 90 days after the item is ready, the customer donates and transfers all right, title, and interest in the property to the Army and Air Force Exchange Service.

Signature______

Services / Parts Labor Waste Disposal Fee

CASH 60.58

60.58

CHECK

Shop Supplies

Sub - Total

CREDIT CARD

60.58

Sales Tax

Other Tax

TOTAL

ON ACCT

0.00

60.58

0.00

Deposits

Payment

Balance

Durning the pre-alingment check we will check ball joints, tie rods, and other steering & suspension items for play. If during this inspection we find items that have play and would affect adjustments, we will give the customer a price to replace such items. A fee of \$19.90 will be applied

0.00

0.00

60.58

SIGNATURE

We welcome your comments, visit: www.precisiontune.com/WeCare Chance to win free oil changes and promotional discounts!

ESTIMATE: YOU HAVE THE RIGHT TO AN ESTIMATE IF THE EXPECTED COST OF REPAIRS OR SERVICES WILL BE MORE THAN TWENTY-FIVE DOLLARS.

INITIAL YOUR CHOICE

NO ESTIMATE

WRITTEN ESTIMATE _____ ORAL ESTIMATE ____

ESTIMATED COST OF REPAIRS (INCLUDING PARTS AND LABOR) I authorize you to perform the above repairs and furnish necessary materials. I understand any cost quoted heretofore is an estimate only. Your employees may operate vehicle for inspection, testing and delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. If computerized engine control systems services are to be performed, I acknowledge that I understand that a manufacturer's warranty may exist and that I was advised of the limitations described on the back.

Χ

CUSTOMER SIGNATURE

Page 1 of 1 7007256116

DO YOU WANT OLD PARTS?

YES NO

VEHICLE CHECKUP



			Auto Care
STOMER	EXTERIOR DAMAGE: Ye	s No	Notes:
AR MAKE MODEL			
SPECTION PERFORMED BY			
N#:			
TERIOR DAMAGE: Yes No Notes:			
INSPECTED - GOOD CONDITION WILL REQ	UIRE FUTURE SERVICE	DOES N	OT MEET STANDARDS
DASHBOARD LIGHTS NOTES	FILTERS		NOTES
Check/Service Engine	Air		
Air Bag	Fuel		
TPMS	Cabin		
Low Coolant	FILLIDS		NOTES
ABS/Brake	FLUIDS Dealer Fluid Level#		NOTES
Oil Pressure	Brake Fluid Level*		
TRAC Control	Coolant Level		
PATTERV	Power Steering Level		
Terminals NOTES	Washer Fluid Level Oil Level		
Test/Condition	Fluid Leak Yes	S No	
TESU/Condition	Drain Plug Okay? Yes		
BELTS/HOSES NOTES	*For your safety - we do not top off.		
Serpentine	OTHER		NOTES
A/C	Wiper Blades		
Alternator	Lighting		
Power Steering worn - doesn't	Fail PCV Valve		
Upper Hose	Suspension/Steering		<
Lower Hose	CV Boots		
Heater Hose	Brakes		
Bypass Hose	TIRES		NOTES/DEPTH
NOTES Both front lower BJ excessive	Left Front: Condition		
[17] [18] [18] [18] [18] [18] [18] [18] [18	Pressure - In/Out	-	1
Both rear Rotors excession Rust 6	wild up Right Front: Condition		
on inner surfaces - Rear PHR	Pressure - In/Out		1
all as a links Missing Lister	Left Back: Condition		
Both rear sway bar links Missins bushi.	Pressure - In/Out	/	1
RE SWAY bar links broken	Right Back; Condition		
2F Rotor inner surface excession Rust-	Pressure - In/Out		1
Front PHR	Tires Rotated?	es No	

VIRGINIA STATE POLICE REJECTED VEHICLE CERTIFICATE



Date: 03/12/2025 Sticker Number: 9943433

Station: 36405 - PRECISION TUNE AUTO CARE

Inspector: 82381 - LEWIN, MARIO A

License No: W903291 VIN: 1FMDU72K44UB44559

Make: FORD Year Built: 2004

Body Type: SUV Odometer Reading: 41746

Inspection Fee: \$ 20.00 Related Charges: \$ 0.00

Total Charges: \$ 20.00

AIRBAG READINESS LAMP FAILED TO ILLUMINATE STEADY ILLUMINATION FUNCTIONING PROPERLY X WHEELS INSPECTED LF RF. RR LR FAILED **EQUIPMENT INSPECTED** COMMENTS: **AIRBAG** BOTH FRONT LOWER BJ EXCESSIVE BRAKES PLAY, BOTH REAR ROTORS EXCESSIVE HEADLIGHTS RUST ON INNER SURFACES, BOTH SIGNAL LIGHTS REAR SWAY BAR LINKS MISSING OTHER LIGHTS BUSHINGS, RF SWAY BAR LINK STEERING BROKEN. RF ROTOR INNER SURFACE SUSPENSION EXCESSIVE RUST. FRAME EXHAUST SYSTEM FUEL SYSTEM TIRES HOOD LATCH EMISSION CONTROL WINDSHIELD WINDSHIELD WIPERS OTHER GLASS MIRROR DOORS SEATS SEAT BELTS FLOOR PAN DEFROSTER HORN

Printed: 03/12/2025 07:41

ID: 139787146