



PHONE: (630) 355-7150 AR@WSTSALES.COM

| Ship to: | SAME AS BELOW |
|-------------|--|
| Invoice to: | SALT CREEK SANITARY DISTRICT 201 S RT 83 PO BOX 6600 VILLA PARK IL 60181 |

| Branch | | | | | |
|------------------------|---------|----------|--------|---------|---------|
| LISLE | | | | | |
| Date | Time | | | | Page |
| 08/16/24 | | 07:39 | (0) | | 01 |
| Account No. | Phone N | 0. | | Invo | ice No. |
| 8323411313 | 630 | 832341 | .1 | V10 | 0807 |
| Ship Via | | Purchase | e Orde | r | |
| | | | | | |
| Sales Tax License No. | | Federal | Exemp | tion No | D. |
| 999738207 | | | | | |
| F.E.I.N. No. 36-248434 | | Sale | espers | on | |
| | | | | MJP | |

DESCRIPTION

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

JOHN DEERE

1248 KV0270A170148

270A

SEGMENT# 1 C 00718 NA

08/05/24 08/06/24

8/6/24 F/S M/D hyd leak

Villa Park

COMPLAINT:

hyd leak

CAUSE:

left boom cyl packings leaking externally

ADDITIONAL DESCRIPTION:

Contact is Steve Moore at 312-615-6052

Machine is at 201 S Rt 83 Villa Park

2 Trips to Villa Park = 2.60 hours travel time.

LABOR

577.20

10410000

SEGMENT TOTAL ==>

577.20

SEGMENT# 2 C 00995 NA

08/05/24 08/06/24

Rebuild cylinders

CORRECTION:

Shop:

Tore down cylinders. Cleaned barrels and rods. Installed new seals into rod guides. Installed new pistons. Installed new lock rings on rod guides. Torqued rod nuts to spec. Installed rods into barrels. Locked in place and installed snap rings. Tested with air. No leaks. Rod moves freely. Installed new o rings on both sides of fittings. Capped off and set on pallet. Saved all parts.

Field:

Trip 1:

Traveled to machine.

Have operator show me the leak. Found left side boom is all wet, have operator run it. Left boom cylinder is leaking

CONTINUED ON PAGE 02





PHONE: (630) 355-7150 AR@WSTSALES.COM

| Ship to: | SAME AS BELOW | |
|-------------|---|--|
| Invoice to: | SALT CREEK SANITARY DISTRICT 201 S RT 83 PO BOX 6600 VILLA PARK IL 60181 | |

| Branch | | | | | |
|------------------------|------------|---------|---------|-------|---------|
| LISLE | | | | | |
| Date | Time | | | | Page |
| 08/16/24 | 09: | 07:39 | (0) | | 02 |
| Account No. | Phone No | ٥. | | Invoi | ice No. |
| 8323411313 | 630 | 8323411 | | V10 | 0807 |
| Ship Via | Purchase | Orde | r | | |
| | | | | | |
| Sales Tax License No. | Federal Ex | xemp | tion No | D. | |
| 999738207 | | | | | |
| F.E.I.N. No. 36-248434 | | Sale | espers | on | |
| | | | | MJP | |

DESCRIPTION

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

JOHN DEERE

1248 KV0270A170148

48

IDEERE 1246 KVU2/UAI/UI

270A

from the packings and oil is running out of it. Right side is wet also. They want both resealed. Raise cab, support boom. Remove cylinders from

machine and cap all ports. Load up and bring to shop for reseal. Order parts needed.

Trip 2:

Traveled to machine.

Install left and right rebuilt boom cylinders. Pin and hook up hoses. Install new line clamp on left cylinder that was

missing. Grease pins. Rod end zerks would not take grease on both sides. Remove zerks an drill out rust. Install new zerks and grease. Run machine and bleed cylinders of air. Top off hydraulic oil. Bolt cab down. Run and check for proper operation and leaks. All ok.

| AHC11572 | Hydraulic Cylin | 2 | 109.76 | 219.52 |
|----------|------------------------|-------|-----------------|--------|
| | Hydraulic Cylinder Kit | | | |
| AH104837 | CLAMP | 1 N | 17.09 | 17.09 |
| AH160647 | PISTON | 3 M | 135.52 | 406.56 |
| AH212088 | KIT | 2 | 51.09 | 102.18 |
| | Hydraulic Cylinder Kit | | | |
| FRT | | 3 | 10.68 | 32.04 |
| H164982 | SNAP RING | 2 N | 14.52 | 29.04 |
| JD7759 | FITTING | 2 | 2.20 | 4.40 |
| | Lubrication Fitting | | | |
| R26375 | PACKING | 2 | 3.88 | 7.76 |
| R26906 | PACKING | 2 | 5.62 | 11.24 |
| TY22028 | HY-GARD TM | 4 | 24.75 | 99.00 |
| T105773 | GUIDE | 1 N | 26.68 | 26.68 |
| Т77857 | O-RING | 2 | 2.92 | 5.84 |
| | | CONTI | NUED ON PAGE 03 | |





PHONE: (630) 355-7150 AR@WSTSALES.COM

| Ship to: | SAME AS BELOW |
|-------------|--|
| Invoice to: | SALT CREEK SANITARY DISTRICT 201 S RT 83 PO BOX 6600 VILLA PARK IL 60181 |

| Branch | | | | | |
|------------------------|----------------|--------|---------|-------|---------|
| LISLE | | | | | |
| Date | Time | | | | Page |
| 08/16/24 | 09: | 07:39 | (0) | | 03 |
| Account No. | Phone N | 0. | | Invoi | ice No. |
| 8323411313 | 630 | 832341 | 1 | V10 | 0807 |
| Ship Via | Purchase Order | | | | |
| | | | | | |
| Sales Tax License No. | Federal E | Exemp | tion No | ο. | |
| 999738207 | | | | | |
| F.E.I.N. No. 36-248434 | | Sale | spers | on | |
| | | | | MJP | |

| DESCRIPTION | | | | | | | |
|-------------|------------|-------------|---------------|---------------|----------|-----|---------|
| STK#/FLEET# | | HRS PIN/EIN | | WARRANTY DATE | | HRS | |
| ? | JOHN DEERE | 1248 | KV0270A170148 | | | | |
| | 270A | | | | | | |
| Т77932 | | O-RING | | 2 | 3.46 | | 6.92 |
| 14M7517 | | LOCK NU | JТ | 2 | 2.92 | | 5.84 |
| 87A | | BRAKE C | CLEAN | 6 | 3.58 | | 21.48 |
| 98191 | | WIRE WH | IEEL | 2 | 32.13 | | 64.26 |
| | | | | | PARTS | | 1059.85 |
| | | | | | LABOR | | 1799.92 |
| 10410000 | | | S | EGMENT | TOTAL==> | | 2859.77 |

| *** | *** | WORK | ORDER | TOTALS | ***** |
|--------------|-----|------|-------|--------|--------|
| PART | S | | | 10 | 59.85 |
| LABO | R | | | 23 | 77.12 |
| ENVIROMENTA | Ĺ | | | | 35.65 |
| MILEAG | E | | | 2 | 67.38 |
| MISC MATERIA | L | | | | 71.31 |
| TOTAL CHARG | E | | | 38 | 311.31 |