Pryor Automotive Repair LTD

P.O. Box 10280

Whitehorse, YT. Y1A 7A1

Phone: 867-668-4550

Here to serve Yukoners better now, and into the future.

INVOICE

11675

Org. Est. # 015522 M-13-01139 777197468RT0001

INVOICE

Printed Date: 08/21/2024

Work Completed: 08/20/2024

1974 MG - MGB - 1.8L, In-Line4 (110CI) VIN(H)

Odometer In:

80,201 MPH

					VIN#:	50,201 MPH		
Part Description	/ Number	Qty	Sale	Ext	Labor Description		Hours	Ext
electric fuel pump 15436		1.00			Inspection 2 cars got car in checked all fluids oil and antifreez -checked wiring some wiring under car not s		what is	
gas gas		1.00			seen -got starter working	o great lixed	Wilat is	
ign coil 3432 Shop Supplies	1.00			-car cranks -hooked up gas can to carbs was able to get running -drained fuel tanks and cleaned out -changed some fuel lines and put in new fuel -fuel pump ,not working -also replaced ign coil to get spark -installed new inline fuel pump now fuel to front -got running again with own fuel pump and fuel -car wont move no clutch needs master and slave for of then that would work -This is a restoration project will need alot of work to get shape -but is in pretty good condition under car rust is ok and would just need to find right buyer Enviromental			ack onto	
							100	Was William
One surrete 1,003.0	Revisions U		ourrent Es	sumate 1,50		Labor: Parts:	A	
						HazMat:		
						SubTotal:	100	
						Tax: Total:	-	
[Payments -]						Bal Due:	47	-

Ask about pick up and delivery options.

Vehicle Received: 2024-08-20

Customer Number: 4514

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

WARNING: When the work requires removing wheels, please retorque wheels after 100 km! Thank you.

Signature _

Date

Email Address: johnsauto@northwestel.net