

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
51985	03R08	51985	<p>INSERVICE</p> <p>REMOVE VENDOR DECALS</p> <p>INSTALL CITY NUMBER/J</p>
52068	03R08	52068	<p>Stalled while in use - by storage shed &amp; wash rack</p> <p>Wont stay running SA</p> <p>05/09/2003 @ 14:31:24</p>
52135	03R08	52135	<p>service call*jump start at Kenosia*gs</p>
52219	03R08	52219	<p>service call*jump start at work site*gs</p>
54935	03R08	54935	<p>PMA*ck over for use*gs</p>
55370	03R08	55370	<p>will not start-crew on hilton/j</p>
58883	03R08	58883	<p>SC*jump start on hill*gs</p>
58922	03R08	58922	<p>JUMP START IN YARD * sa</p> <p>MAY NEED BATTERY</p>
62170	03R08	62170	<p>SC*dead on County line road*gs</p> <p>09/14/2006 @ 07:25:46 Check alt. It is not charging. Removed alt. So Kelly can get a new one. RTA</p> <p>09/14/2006 @ 07:31:35 Removed battery and put on a charger. RTA</p> <p>09/18/2006 @ 09:21:19 Installed new alt. Still not charging. Found a blown fuse. R&amp;R fuse. Alt is charging. RTA</p>
63740	03R08	63740	<p>wrong eq number</p>
64578	03R08	64578	<p>SC*dead at berna and renwood*gs</p>
69061	03R08	69061	<p>SC*jump start*gs</p>
69065	03R08	69065	<p>PMA*gs</p> <p>weld fuel filter bracket</p>

## W337 - Work Order Notes

01/01/2003 TO 07/21/2025

7/21/2025 3:20:26 PM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
71755	03R08	71755	<p>pma*ck oil leak on rt side of rear roller*repair gear shifter*gs</p> <p>disassembled rt side of rear roller*replaced seals*</p> <p>changed oil &amp; filter ,replaced fuel filter ,hydraulic filter</p> <p>H.K.*</p> <p>05/05/2010 @ 07:07:01 Reassembled roller RTA</p>
74337	03R08	74337	<p>SC*dead at building 46*gs</p> <p>jump started r8 at building 46</p> <p>H.K.*</p> <p>replace fuel line. M.M</p>
74353	03R08	74353	<p>SC*battery dead*blacktop ready*at blackhawk and Cunnington*gs</p> <p>jumped still didn't start*possible trans not in start position????*started fine then??*gs</p>
74877	03R08	74877	<p>replace seat bottom*gs</p> <p>Notes:replaced whole seat ,two switches &amp; wiring harness. per directions</p> <p>H.K.*</p>
75568	03R08	75568	<p>SC*ran out of fuel??*gs filled fuel tank repaired idle stop solenoid. M.M M.G</p>
75589	03R08	75589	<p>GENERAL SERVICE A *</p> <p>recently in for FUEL SOLENOID &amp; FUEL ISSUE</p> <p>pma</p> <p>ordered oil press sender</p> <p>10/05/2011 @ 13:08:27</p>
76620	03R08	76620	<p>check charging and cranking system.MG</p> <p>start at DESC</p> <p>ck alt &amp; bat</p> <p>03/01/2012 @ 14:06:09</p>
77988	03R08	77988	<p>Jump start,MG.</p> <p>12/11/2012 @ 10:46:40</p>

## W337 - Work Order Notes

01/01/2003 TO 07/21/2025

7/21/2025 3:20:26 PM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
78510	03R08	78510	Jump at 46,MG 01/29/2013 @ 09:15:56 SC start 01/29/2013 @ 15:10:57
78944	03R08	78944	Jump start,MG. 04/15/2013 @ 10:55:19 SC start r/r battery 04/23/2013 @ 06:46:43
79008	03R08	79008	Roller vibrates in reverse only,MG. 04/26/2013 @ 13:02:29 repair broken wire for vibe disassemble shifter route wires differently reassemble shifter etc etc etc 04/29/2013 @ 13:46:23
79320	03R08	79320	Jump start at 46,MG. 06/25/2013 @ 13:34:23 ST DEPT GOT STARTED 07/01/2013 @ 08:08:06
79469	03R08	79469	Adjust range shifter,MG. 07/30/2013 @ 13:01:28 modify neutral safety switch & bracket 07/30/2013 @ 14:29:23
79538	03R08	79538	Replace scrappers,MG. 08/14/2013 @ 12:05:36

## W337 - Work Order Notes

01/01/2003 TO 07/21/2025

7/21/2025 3:20:26 PM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
81017	03R08	81017	PMC,Annual Service,MG. 04/09/2014 @ 14:18:01 oil lube filter replaced fuel filter . replaced hydraulic filter repaired broken fuel filter mounting bracket broken installed make shift latch for engine cover latch missing H.K.*
81690	03R08	81690	Service Call,MG. 08/15/2014 @ 12:36:09 service call checked starting system and charging system not charging. M.M. S.H. checked out and r & r alternator and had checked. OK. checked wiring harness and found blown horn/indicator fuse, replaced fuse and repaired horn button wiring, replaced battery, S.H.
83020	03R08	83020	PMC,Annual Service,MG. 04/03/2015 @ 10:02:29 replaced hood latch. 04/08/2015 @ 13:37:05 M.M replaced hood latch cleaned engine compartment H.K.*
83250	03R08	83250	Vibratory Inop,MG. 05/22/2015 @ 13:16:36 checked out and r & r drive handle assy and checked wiring and switches to vibrator, switched out cams for drive handle to work switches properly, installed labels for switches on dash, SH
84565	03R08	84565	PMC,MG. 03/14/2016 @ 08:15:49 checked over and changed oil and filter, 2 fuel filters, hydraulic filter, both air filters, made new bracket for fuel filter housing, greased, degreased and washed unit, checked fluids, checked belt, hoses and battery. SH
86053	03R08	86053	Service Call,MG. 01/26/2017 @ 11:33:14
86629	03R08	86629	pm service due get ready for asphalt season. .M.M 04/17/2017 @ 09:39:40 checked over and changed oil and filter, 2 fuel filters, outer air filter, hydraulic filter, checked drums, isolators, battery and charging system, lubed seat, needs pivot brgs, degreased unit and washed out coolers, replaced worn out pivot brgs, and pivot pin, greased, pulled plugs on spray booms and blew out nozzles and booms, SH

## W337 - Work Order Notes

01/01/2003 TO 07/21/2025

7/21/2025 3:20:26 PM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
86867	03R08	86867	<p>Weld,MG.</p> <p>06/22/2017 @ 14:40:07</p> <p>welded &amp; fabricated new wing nut bolt for roll over</p> <p>bar wing nut missing</p> <p>H.K.*</p>
87923	03R08	87923	<p>PMC,MG.</p> <p>03/30/2018 @ 08:52:27</p> <p>PERFORM PMC,CHECK PARK BRAKE,CHANGE ALL FILTERS, CHECK DRUM AND HYD OIL.REPLACE RAD CAP,REPLACE ALL SPRAY NOZZLES AS THEY WERE DIFFERENT SIZES. CLEAN RADIATOR. CHECK VIBRATOR AND SHOCKS. DRIVE OK RF</p>
88004	03R08	88004	<p>check shifter for vibrate issue. RF</p> <p>04/19/2018 @ 10:41:44</p> <p>remoreplace vibrator handle and switch . RF</p>
89299	03R08	89299	<p>PMC,MG.</p> <p>03/12/2019 @ 12:44:59</p> <p>checked over and changed oil and filter, 2 fuel filters, hydraulic filter, outer air filter, checked battery, charging system, brake system, water system, sprayers are removed for winter storage, lubed, checked coolant and topped off fluids, checked drums and fluid, degreased unit. SH</p>
90933	03R08	90933	<p>WELD RADIATOR BRACKET RF</p> <p>05/13/2020 @ 14:35:54</p> <p>WELDED BRACKET RF</p>
92410	03R08	92410	<p>unit due for PMA; check over unit for spring use.</p> <p>03/16/2021 @ 08:53:47 MS</p> <p>process of pma RF</p> <p>03/16/2021 @ 15:14:56</p> <p>finish pma</p> <p>drive unit,replace 2 fuel filters,oil and filter,hyd filter and check oil, replace 2 air filters,psi cooling system, check freeze, clean rad, degrease engine. test e stop,lube seat and rail. check and clean batt and alt. check vibration isolaters,check ecentric oils check brake check water system clean needed tips. RF 3-17-2021 RF</p> <p>pull outside waiting on parts. RF</p> <p>process replace fan blade and belt. RF</p> <p>03/23/2021 @ 15:07:44</p> <p>run unit check belt ok. take to metal barn. RF</p> <p>03/24/2021 @ 08:16:50</p>

## W337 - Work Order Notes

01/01/2003 TO 07/21/2025

7/21/2025 3:20:26 PM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
92638	03R08	92638	<p>GREASE/OIL LEAK</p> <p>04/23/2021 @ 13:41:45 DLS</p> <p>clean unit, drive and get hot, can see leak but not exactly pinpoint. partially disassemble</p> <p>04/26/2021 @ 12:37:12right front drum/vibrator, run unit with motor removed and found no leak from motor, appears to be drum seal for drum oil. order parts. RF</p> <p>disassemble front drum assembly for seal replacement. clean parts and order more needed parts. RF</p> <p>05/03/2021 @ 14:50:51</p> <p>replace front drum seal and reinstall. top off drum oil and check hyd oil ok. wash and drive and check. no leaks at this time RF</p> <p>05/05/2021 @ 14:58:54</p>
93417	03R08	93417	<p>disassemble for rear drum seal, clean parts. RF</p> <p>08/30/2021 @ 14:57:59</p> <p>process of assembly of new rear drum seal. RF</p> <p>08/31/2021 @ 13:12:59</p> <p>top off rear drum oil and grease rear drum. run and check. all ok at this time. crew needed it. RF</p> <p>09/01/2021 @ 10:33:22</p>
94921	03R08	94921	<p>unit due for PMA &amp; PMS</p> <p>03/22/2022 @ 09:05:02 MS</p> <p>get unit from shed and run, change oil and filter-replace hyd filter-psi cooling system-check dca-replace 2 air filters-replace 2 fuel filter-check hyd oil-check and clean batts and alt-perform brake test-check ecentric oil-check shock mounts. RF</p> <p>03/22/2022 @ 15:02:50</p> <p>check vibrator-degrease engine, clean rad- fill water and check water system and sprayers -cleaned needed ones. -drive and check over ok. drain water out.RF</p> <p>03/23/2022 @ 11:31:01</p>

## W337 - Work Order Notes

01/01/2003 TO 07/21/2025

7/21/2025 3:20:26 PM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
95269	03R08	95269	<p>brakes wanted to keep engaging when using-add needed repair code after diagnosis</p> <p>06/08/2022 @ 08:46:48 MS</p> <p>-checked out and drove around lot for awhile and did not act up</p> <p>-removed panel for brake switches and removed switches</p> <p>-took switches apart and cleaned contacts, both were oxidizing</p> <p>-reinstalled switches</p> <p>-ordered 2 switches</p> <p>-found oil gauge not working after warmed up and at idle, drops to 0 from around 45 psi, ordered new sender</p> <p>-found brake solenoid loose on valve, nut tight</p> <p>-removed solenoid, cleaned valve and solenoid off, found nylon and fiber washers and installed behind solenoid to tighten up</p> <p>-operator stopped by and said what was going on and how it acts</p> <p>-removed shields to get to harness</p> <p>-traced wiring from switch to solenoid, found inline connector and unplugged, found terminals for brake wire corroded inside plug</p> <p>-ran new wire from switch to solenoid</p> <p>-ran unit for awhile again and still no issues, will replace switches when come in</p> <p>-removed water nozzle from hose at wash bays from inside water tank</p> <p>-replaced oil sending unit, oil gauge working</p> <p>-replaced parking brake and brake check switches</p> <p>-ran unit with no issues still</p> <p>-will need to bring back if still acts up</p> <p>-SH</p>
95449	03R08	95449	<p>unit on kettering blvd</p> <p>07/12/2022 @ 10:41:16 MS</p> <p>travel to jobsite. unit stuck on street disassemble cant get brake to release. disassemble switch appears ok mess with wiring around solenoid and got to start moving. load on trailer get in shop. RF</p> <p>07/12/2022 @ 14:02:37</p> <p>run unit finally got to act up would not move. could tug on harness and get to sometimes move. check power and grounds to brake solenoids ok. found wire pulling out of solenoid that was pointed towards ground had to loosen solenoid and rotate to see. was intermittenlt making contact inside solenoid when tugging. order solenoid. RF</p> <p>07/15/2022 @ 11:18:42</p> <p>replace solenoid and hyd block assembly for parking braking. check hyd oil ok. run and clean all ok. RF</p> <p>07/26/2022 @ 15:19:40</p>

## W337 - Work Order Notes

01/01/2003 TO 07/21/2025

7/21/2025 3:20:26 PM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
96567	03R08	tech notes	3/17/2023 12:59:51 PM  replaced oil and filter lubed all lube points charged battery was low when load tested rechecked battery c/k s ok c/ked vibrator , working properly at this time replaced outside air filter inside filter still in good shape replaced water valve elbow was broken
96567	03R08	tech notes	3/22/2023 8:52:14 AM  replaced shifter handle was broken removed handle and rewired connectors back in
96567	03R08	PMA PMS	Needs PMA PMS update hours when brought in shop 3/17/2023 10:32:43 AM
96567	03R08	tech notes	3/17/2023 12:58:12 PM  replaced fuel filter on engine
96567	03R08	tech notes	Note waiting for other filter 3/17/2023 12:59:09 PM replaced hydraulic filter
98001	03R08	Service Call	-dead @ building 46 4/1/2024 1:16:28 PM  -asset due for PMS -add repair codes as needed 4/1/2024 1:16:57 PM MS
98001	03R08	Tech notes	travel to 46 and jump start roller and get back to shop 9:11:13 AM 4/2/2024  jump started unit twice at 46 and let charge.  check air filter psi cooling system check freeze and dca check belt grease machine change oil and filter check battery and replace replace battery process replace fuel filters 4/4/2024 1:59:02 PM replace fuel filters check alt fill and check water check e stop check brake check eccentric oil clean coolers degrease engine 4/8/2024 3:18:29 PM perform pms lube seat run and operate machine ok clean bay 8:07:34 AM 4/9/2024
98001	03R08	PARTS ON ORDER	ORDERED OIL AND FUEL FIILTER FROM OREILLYS ORD: 04/04/24 @ 0805 ETA: 04/04/24 @ 0905 ARR 04/04/24 @ 0900  ORDERED FUEL FILTER FROM AAP ORD: 04/04/24 @ 0805 ETA: 04/04/24 @ 0905 ARR: 04/04/24 @ 0830
99397	03R08	Vehicle Intake Notes	___ Verify Engine Hours and update in FASTER ___ Decommission unit and complete inspection form. 4/7/2025 9:02:17 AM bkb

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
99397	03R08	Tech Notes	<ul style="list-style-type: none"><li>- completed unit decommission form</li><li>- removed all Kettering decals</li><li>- had Steve verify unit was complete and not missing components</li></ul>

This report displays notes for work orders opened within the specified date range.

REPORT PARAMETERS:

Time Zone: Eastern Standard Time  
Start Date: 01/01/2003  
End Date: 07/21/2025  
Record Type: Work Orders  
Work Order Number: All Values  
Asset Number: 03R08  
Organization: All Values  
Department: All Values  
Class: All Values  
Maint Shop: All Values  
Work Order Status: All Values

REPORT VERSIONS:

Report Version: 20190312.1700  
Script Version: 20190314.1700