

PETE'S TIRE & AUTOMOTIVE SERVICE

3704 North Highway 77

Waxahachie, TX 75165

972 617-7029

WWW.PETESTIRES.COM

Repair Order #0086185

Date : 10/19/2018

Page : 1

Center : 1

Customer : MACHO SELF STORAGE

Address : 201 BROTHERS BLVD.

City : RED OAK, TX 75154-

Phone 1 : (972) 617-1191

Ext : MAIN

Phone 2 : (210) 284-4840

Ext : RICK

Vehicle : 1998 FORT E350 VAN

License : CVZ8503

TRL# :

VIN/DR : 1FDWE30L5WHA07541

Engine : V8-330 5.4L SOHC

Trans :

Mileage : 77410

TRK# :

Op	Tech	Description	Part Description	Reason for Replacement	Labor	Parts	Subtotal
Qty	Part Number					Price	
TRA500	DAW	TRANSMISSION LABOR-- HAVE TO HOLD GEAR SHIFT UP/FORCE INTO PARK TO START THE VEHICLE. IS THIS ADJUSTABLE. ALSO, PLEASE TEST DRIVE, CUSTOMER BELIEVES THE TRANSMISSION HAS ISSUES.					Declined
MIS500	DAW	MISCELLANEOUS LABOR-TROUBLE SHOOT INOP SPEEDOMETER** SPEEDOMETER IS WORKING AS IT SHOULD. UNABLE TO IDENTIFY ANY ISSUES AT THIS TIME.			47.50		47.50
CST500	DAW	CHASSIS AND STEERING LABOR--INSTALL STEERING SHAFT BUSHINGS.					
2.00	F3TZ7L278A	BUSHING SET			190.00	17.98	207.98
DIA500	RS	DIAGNOSTIC LABOR--WHEN TEST DRIVING YOU CAN HEAR NOISE IN DRIVESHAFT OR REAR END. YOU CAN MAKE IT CLUNK BY GIVING IT MORE GAS AND LETING OFF. AFTER TEST DRIVE, FOUND THAT DIFFERENTIAL IS ABOUT TO COME APART. NEEDS TO BE REPLACED.			0.00	17.98	
DRT0	DAW	Remove & Replace R Axle Housing			978.50	2949.83	3928.33
1.00	7628041	REAR AXLE HOUSING ASSME				2499.99	
1.00	DY1123	SPEED SENSOR				49.99	
1.00	S583R	R NEW BRAKE SHOES				79.95	
2.00	BD8975	R BRAKE DRUM				319.90	
	DAW	Remove & Replace R Axle Shaft Assembly - Both			95.00		95.00

Payments:

(On Account), \$4523.65, on 10/19/18

OK Bad

Recommendation

OK Bad

Recommendation

OK Bad

Recommendation

Rick P. Camm

e-mailed
Date 10/22/18

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for vehicle damage or articles left in car in case of fire, theft inclement weather or any other cause beyond our control.

Labor :	\$1,311.00
Parts :	\$2,967.81
Sublet :	\$0.00
Other Fees :	\$0.00
Shop Supplis :	\$0.00
Subtotal :	\$4,278.81
Sales Tax :	\$244.84

Paid By :	Total :	\$4,523.65
On Account	Paid :	\$0.00
Pay Ref :	Due :	\$4,523.65

3704 North Highway 77
Waxahachie, TX 75165
972 617-7029
WWW.PETESTIRES.COM

Repair Order #0087612

Date : 1/2/2019

Page : 1

Center : 1

Customer : MACHO SELF STORAGE

Address : 201 BROTHERS BLVD.

City : RED OAK, TX 75154-

Phone 1 : (972) 617-1191

Ext : MAIN

Phone 2 : (210) 284-4840

Ext : RICK

Vehicle : 1998 FORD E350 VAN

License : CVZ8503

TRL# :

VIN/DR : 1FDWE30L5WHA07541

Engine : V8-330 5.4L SOHC

Trans :

Mileage : 77658

TRK# :

Op	Tech	Description	Part Number	Part Description	Reason for Replacement	Labor	Parts	Subtotal
	Qty						Price	
SUB005		SUB WRECKER CHARGE--D&W TOWING (27271)				57.50		57.50
TRA500		DAW TRANSMISSION LABOR--REMOVE AND REINSTALL REMAN TRANSMISSION.				503.50	2761.77	3265.27
	1.00		5604380	REMAN-TRANSMISSION--E4C				
	16.00		1043807	MERCON V	KENDALL MERCON V QT		2600.00	
	1.00		19001	KOOLER KLEEN			130.08	
	4.00		N800594S100	DRIVE SHAFT BOLTS			21.69	
							10.00	

Payments:

(On Account), \$3550.62, on 01/02/19

OK Bad Recommendation OK Bad Recommendation OK Bad Recommendation

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. I understand that dealer/owner is not responsible for delay or other consequence due to the unavailability of parts shipments beyond their control. Not responsible for vehicle damage or articles left in car in case of fire, theft inclement weather or any other cause beyond our control.

Labor : \$503.50
Parts : \$2,761.77
Sublet : \$57.50
Other Fees : \$0.00
Shop Supplies : \$0.00
Subtotal : \$3,322.77
Sales Tax : \$227.85
Total : \$3,550.62
Paid By :
On Account
Pay Ref :
Paid : \$0.00
Due : \$3,550.62

Yvette Puman