

# CITY OF EAST GRAND FORKS



## Work Order Summary

WO #		Hours	Labor Costs	Part Costs	Other Costs	Total Costs
<b>545/2022 [2022 Ford Utility Police Interceptor]</b>						
20747 [Scheduled Oil Change]						
	<b>Service Code</b>					
	<input type="checkbox"/> #545/2022 #545/2022: 2022 Ford Utility Police Interceptor					
	<input type="checkbox"/> 0001 Change Oil and Filters & Check All Fluid Levels					
	<b>Modified By</b>					
Ron Bubendorf	Note Date					
Ron Bubendorf	6/4/2022 #545/2022: 2022 Ford Utility Police Interceptor					
	0001: Change Oil and Filter & Check All Fluid Levels					
	0002: Inspect Air Filter, Change if Needed					
	0003: Check Tire Pressure & Inflate Tires To Proper Pressure					
	0004: Refill Windshield Washer Tank					
	Added Oil Additive And Reset Oil Life Monitor					
Ron Bubendorf	6/4/2022 Installed Battery Post Terminal Proctors					
20804 [Scheduled Oil Change]	0.50 \$15.00 \$40.172910 \$0.00 \$55.17					
	<b>Service Code</b>					
	<input type="checkbox"/> #545/2022 #545/2022: 2022 Ford Utility Police Interceptor					
	<input type="checkbox"/> 0001 Change Oil and Filters & Check All Fluid Levels					
	<b>Modified By</b>					
Ron Bubendorf	Note Date					
Ron Bubendorf	6/28/2022 #545/2022: 2022 Ford Utility Police Interceptor					
	0001: Change Oil and Filter & Check All Fluid Levels					
	0002: Inspect Air Filter, Change if Needed					
	0003: Check Tire Pressure & Inflate Tires To Proper Pressure					
	0004: Refill Windshield Washer Tank					
	Added Oil Additive And Reset Oil Life Monitor					
Ron Bubendorf	6/28/2022 Repair Bottom Of The Front Bumper Cover					
20841 [Flat Tire Left Rear Tire]	0.50 \$15.00 \$1.338400 \$0.00 \$16.34					
	<b>Service Code</b>					
	<input type="checkbox"/> #545/2022 #545/2022: 2022 Ford Utility Police Interceptor					
	<input type="checkbox"/> 6202 Repair Flat Tire, Plugged Tire					
	<input type="checkbox"/> 6222 Left Rear					
	<b>Modified By</b>					
Ron Bubendorf	Note Date					
Ron Bubendorf	7/13/2022 #545/2022: 2022 Ford Utility Police Interceptor					
	Flat Tire Repair Left Rear, Plugged Tire					
20859 [Scheduled Oil Change]	0.50 \$15.00 \$37.913455 \$0.00 \$52.91					
	<b>Service Code</b>					
	<input type="checkbox"/> #545/2022 #545/2022: 2022 Ford Utility Police Interceptor					
	<input type="checkbox"/> 0001 Change Oil and Filters & Check All Fluid Levels					
	<b>Modified By</b>					
Ron Bubendorf	Note Date					
Ron Bubendorf	7/19/2022 #545/2022: 2022 Ford Utility Police Interceptor					
	0001: Change Oil and Filter & Check All Fluid Levels					
	0002: Inspect Air Filter, Change if Needed					
	0003: Check Tire Pressure & Inflate Tires To Proper Pressure					
	0004: Refill Windshield Washer Tank					
	Added Oil Additive And Reset Oil Life Monitor					
20936 [Scheduled Oil Change]	0.50 \$15.00 \$40.133455 \$0.00 \$55.13					

## Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
<b>545/2022 [2022 Ford Utility Police Interceptor]</b>					
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	8/16/2022	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
20980 [Scheduled Oil Change]		0.50	\$15.00	\$40.133455	\$0.00
<b>545/2022 [2022 Ford Utility Police Interceptor]</b>					
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	9/12/2022	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
20981 [Defective Seat Belt Buckle]		0.50	\$15.00	\$97.890000	\$0.00
<b>545/2022 [2022 Ford Utility Police Interceptor]</b>					
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	9/12/2022	#545/2022: 2022 Ford Utility Police Interceptor Replaced Defective Seat Belt Buckle Drivers Seat			
21064 [Scheduled Oil Change]		0.50	\$15.00	\$40.133455	\$0.00
<b>545/2022 [2022 Ford Utility Police Interceptor]</b>					
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	10/11/2022	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
21152 [Scheduled Oil Change]		0.50	\$15.00	\$45.993455	\$0.00
<b>545/2022 [2022 Ford Utility Police Interceptor]</b>					
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	11/7/2022	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			

## Work Order Summary

WO #		Hours	Labor Costs	Part Costs	Other Costs	Total Costs
545/2022	/2022 Ford Utility Police Interceptor/					
21266 [Scheduled Oil Change]	Ron Bubendorf 11/7/2022	0.50	\$15.00	\$40.783455	\$0.00	\$55.78
Service Code	Service Description					
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels					
Modified By	Note Date	Note				
Ron Bubendorf	11/29/2022	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor	0.50	\$15.00	\$1.000000	\$0.00
21306 [Front Bumper Cover Repair]						\$16.00
Service Code	Service Description					
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
Modified By	Note Date	Note				
Ron Bubendorf	12/19/2022	#545/2022: 2022 Ford Utility Police Interceptor Remove Broken Front Bumper Lower Broken Cover And Re Fasten Lower Part Of The Front Bumper	0.50	\$15.00	\$40.783455	\$0.00
21323 [Scheduled Oil Change]						\$55.78
Service Code	Service Description					
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels					
Modified By	Note Date	Note				
Ron Bubendorf	12/20/2022	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor	0.50	\$15.00	\$41.263455	\$0.00
21381 [Scheduled Oil Change]						\$56.26
Service Code	Service Description					
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels					
Modified By	Note Date	Note				
Administrator	1/17/2023	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor	1.00	\$30.00	\$1.338400	\$0.00
21382 [Right Rear Tire Is Flat]						\$31.34
Service Code	Service Description					
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
Modified By	Note Date	Note				
Ron Bubendorf	1/17/2023	#545/2022: 2022 Ford Utility Police Interceptor Right Rear Tire Is Flat	1.00	\$30.00	\$1.338400	\$0.00
Ron Bubendorf	1/17/2023	Service Call To The Police Dept For Flat Tire Repair				

## Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs	
<b>545/2022 [2022 Ford Utility Police Interceptor]</b>						
21466 [Scheduled Oil Change]	Repair Tire Plugged Tire 0.50	\$15.00	\$41.263455	\$0.00	\$56.26	
<b>Service Code</b>						
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels					
<b>Modified By      Note Date</b>						
Ron Bubendorf	2/17/2023	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor				
21545 [Tire Replacement]	3.00	\$100.00	\$647.597200	\$0.00	\$747.60	
<b>Service Code</b>						
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 6203	Tire Replacement					
<input type="checkbox"/> 6206	R&R Tires (All Four)					
<b>Modified By      Note Date</b>						
Ron Bubendorf	3/13/2023	#545/2022: 2022 Ford Utility Police Interceptor Tire Replacement, R&R Tires (All Four)	0.00	\$0.00	\$41.263455	
21546 [Scheduled Oil Change]	0.00	\$0.00	\$41.263455	\$0.00	\$41.26	
<b>Service Code</b>						
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels					
<b>Modified By      Note Date</b>						
Ron Bubendorf	3/13/2023	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor				
21616 [Scheduled Oil Change]	0.50	\$15.00	\$41.263455	\$0.00	\$56.26	
<b>Service Code</b>						
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels					
<b>Modified By      Note Date</b>						
Ron Bubendorf	4/4/2023	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor				
21653 [Scheduled Oil Change]	0.50	\$15.00	\$41.763455	\$0.00	\$56.76	
<b>Service Code</b>						
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels					
<b>Modified By      Note Date</b>						
Ron Bubendorf	4/25/2023	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels				

## Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
545/2022 [2022 Ford Utility Police Interceptor]					
	0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor				
21725 [Scheduled Oil Change]	0.50	\$15.00	\$41.763455	\$0.00	\$56.76
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	5/23/2023	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
21787 [Scheduled Oil Change]	0.50	\$15.00	\$41.763455	\$0.00	\$56.76
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	6/14/2023	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
21867 [Scheduled Oil Change]	0.50	\$15.00	\$41.763544	\$0.00	\$56.76
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	7/11/2023	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
21868 [Left Front Tire Slow Leak]	1.00	\$32.50	\$2.321667	\$0.00	\$34.82
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	7/11/2023	#545/2022: 2022 Ford Utility Police Interceptor			
21934 [Scheduled Oil Change]	0.50	\$15.00	\$41.763544	\$0.00	\$56.76
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			

## Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
<b>545/2022 [2022 Ford Utility Police Interceptor]</b>					
Ron Bubendorf 8/2/2023					
#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor					
22015 [Scheduled Oil Change]	0.50	\$15.00	\$41.763544	\$0.00	\$56.76
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	8/29/2023	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
22111 [Scheduled Oil Change]	0.50	\$15.00	\$43.043636	\$0.00	\$58.04
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	9/26/2023	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
22136 [Brakes Replacement]	3.50	\$140.00	\$903.540002	\$0.00	\$1,043.54
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> BRK6004	Inspect Brakes & Replace				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	10/6/2023	#543/21: 2021 Ford Utility Police Interceptor R&R Brake Pads And Rotors On All Four Wheels			
Ron Bubendorf	10/9/2023	Message Center Came On And Said Parking Brake Sensor Failure, Replaced The Brakes And Will Monitor This Complaint			
22153 [Scheduled Oil Change]	0.50	\$15.00	\$43.613636	\$0.00	\$58.61
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	10/17/2023	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
22171 [Shot Gun Lock Modifaction]	0.50	\$15.00	\$0.624400	\$0.00	\$15.62

## Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
<b>545/2022 [2022 Ford Utility Police Interceptor]</b>					
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022 #545/2022: 2022 Ford Utility Police Interceptor					
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	10/24/2023	#545/2022: 2022 Ford Utility Police Interceptor Shim Out The Shot Gun Lock To Fit For New Shot Gun Stock With Flash-lite And Lazar Lite	0.50	\$15.00	\$43.563636
22208 [Scheduled Oil Change]					\$0.00
<b>Service Code</b>					
<input type="checkbox"/> #545/2022 #545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001 Change Oil and Filters & Check All Fluid Levels					
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	11/8/2023	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor	0.50	\$15.00	\$43.563636
22249 [Scheduled Oil Change]					\$0.00
<b>Service Code</b>					
<input type="checkbox"/> #545/2022 #545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001 Change Oil and Filters & Check All Fluid Levels					
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	11/28/2023	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor	0.50	\$15.00	\$43.563636
22314 [Scheduled Oil Change]					\$0.00
<b>Service Code</b>					
<input type="checkbox"/> #545/2022 #545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001 Change Oil and Filters & Check All Fluid Levels					
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	12/19/2023	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor	0.50	\$15.00	\$43.563636
22315 [Tire Replacement]					\$0.00
<b>Service Code</b>					
<input type="checkbox"/> #545/2022 #545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 6206 R&R Tires (All Four)					
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	12/19/2023	#545/2022: 2022 Ford Utility Police Interceptor R&R Tires (All Four)	3.00	\$100.00	\$588.946000
22337 [Keyless Entry Battery Replacement]					\$0.00
<b>Service Code</b>					
<input type="checkbox"/> #545/2022 #545/2022: 2022 Ford Utility Police Interceptor					

## Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
545/2022 [2022 Ford Utility Police Interceptor]					
<input type="checkbox"/> BAT5229		Replace Battery For Remote Door Locks			
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	1/3/2024	#545/2022: 2022 Ford Utility Police Interceptor Message Center Said KEY:Low Battery Replace Soon Replaced Door Lock-Unlock Key Fob Battery And Message Cleared	0.50	\$15.00	\$43.563636
22369 [Scheduled Oil Change]				\$0.00	\$58.56
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	1/16/2024	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
22371 [Water Pump Replacement]		5.00	\$150.00	\$179.148850	\$0.00
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 5307	R&R Spark Plugs				
<input type="checkbox"/> BELT5700	R&R Alternator/Water Pump Serpentine Belt				
<input type="checkbox"/> BELT5701	R&R A/C Compressor Serpentine Belt				
<input type="checkbox"/> CSS8501	R&R Water Pump				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	1/18/2024	#545/2022: 2022 Ford Utility Police Interceptor R&R Water Pump, Alternator Belt/Water Pump Belt, A/C Compressor Belt, R&R Spark Plugs	0.50	\$15.00	\$103.536048
22451 [Scheduled Oil Change]				\$0.00	\$118.54
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	2/14/2024	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
Ron Bubendorf	2/14/2024	Replaced Air Filter And Cabin Air Filter	0.50	\$15.00	\$279.950000
22453 [Battery Replacement]				\$0.00	\$294.95
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> BAT5202	Run Battery Test / Fail				
<input type="checkbox"/> BAT5204	R&R Battery				
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	2/14/2024	#545/2022: 2022 Ford Utility Police Interceptor Battery Went Dead After Having The Oil Changed. Replaced Battery	0.50	\$15.00	\$42.956048
22493 [Scheduled Oil Change]				\$0.00	\$57.96
<b>Service Code</b>	<b>Service Description</b>				
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				

## Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
<b>545/2022 /2022 Ford Utility Police Interceptor/</b>					
Modified By	Note Date	Note			
Ron Bubendorf	3/5/2024	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
22537 [Scheduled Oil Change]					
		0.50	\$15.00	\$42.956048	\$0.00
<b>Service Code</b>					
<input type="checkbox"/> #545/2022		#545/2022: 2022 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By	Note Date	Note			
Ron Bubendorf	3/26/2024	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
22601 [Scheduled Oil Change]					
		0.50	\$15.00	\$42.956048	\$0.00
<b>Service Code</b>					
<input type="checkbox"/> #545/2022		#545/2022: 2022 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By	Note Date	Note			
Ron Bubendorf	4/23/2024	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
22638 [Loud Noise Coming From The Rear Axle]					
		0.50	\$15.00	\$0.000000	\$0.00
<b>Service Code</b>					
<input type="checkbox"/> #545/2022		#545/2022: 2022 Ford Utility Police Interceptor			
Modified By	Note Date	Note			
Ron Bubendorf	5/13/2024	#545/2022: 2022 Ford Utility Police Interceptor Loud Noise Coming From The Rear Axle			
Ron Bubendorf	5/13/2024	Check And Found A Rock Stuck In Between The Left Rear Brake Rotor And The Dust Shield, Removed The Rock And Noise Is Now Gone.			
22692 [Scheduled Oil Change]					
		0.50	\$15.00	\$42.956048	\$0.00
<b>Service Code</b>					
<input type="checkbox"/> #545/2022		#545/2022: 2022 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By	Note Date	Note			
Ron Bubendorf	6/4/2024	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			

## Work Order Summary

WO #		Hours	Labor Costs	Part Costs	Other Costs	Total Costs	
<b>545/2022 [2022 Ford Utility Police Interceptor]</b>							
22782 [Scheduled Oil Change]		0.50	\$15.00	\$42.956048	\$0.00	\$57.96	
<b>Service Code</b>	<b>Service Description</b>						
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor						
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels						
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>					
Ron Bubendorf	6/25/2024	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor					
22888 [Scheduled Oil Change]		0.50	\$15.00	\$42.956048	\$0.00	\$57.96	
<b>Service Code</b>	<b>Service Description</b>						
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor						
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels						
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>					
Ron Bubendorf	7/30/2024	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor					
22938 [Front Windshield Replacement]		0.50	\$15.00	\$639.000000	\$0.00	\$654.00	
<b>Service Code</b>	<b>Service Description</b>						
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor						
<input type="checkbox"/> WW3002	R&R Front Windshield By Autoglass & Aftermarket						
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>					
Ron Bubendorf	8/19/2024	#545/2022: 2022 Ford Utility Police Interceptor Front Windshield Cracked Up By The Camera, Front Windshield Replaced By Autoglass& Aftermarket					
22943 [Warranty Recall 23S55]		0.50	\$15.00	\$0.000000	\$0.00	\$15.00	
<b>Service Code</b>	<b>Service Description</b>						
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor						
<input type="checkbox"/> WARRANTY1	Warranty Work Vehicle Recall						
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>					
Ron Bubendorf	9/19/2024	#545/2022: 2022 Ford Utility Police Interceptor Warranty Recall 23S55 Vehicle Rollaway From Drive Shaft					
22944 [Transmission Flush]		0.50	\$15.00	\$349.540000	\$0.00	\$364.54	
<b>Service Code</b>	<b>Service Description</b>						
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor						
<input type="checkbox"/> 1NAC	By Nelson Auto Center						
<input type="checkbox"/> TRANS 0001	Service Transmission (Change Transmission Fluid)						
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>					
Ron Bubendorf	9/19/2024	#545/2022: 2022 Ford Utility Police Interceptor Service Transmission (Change Transmission Fluid) By Nelson Auto Center					
22946 [Scheduled Oil Change]		0.50	\$15.00	\$43.296048	\$0.00	\$58.30	
<b>Service Code</b>	<b>Service Description</b>						
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor						
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels						

## Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
<b>545/2022 /2022 Ford Utility Police Interceptor/</b>					
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	8/22/2024	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
22980 [Left Front Tire Nail In It]		0.50	\$15.00	\$1.338400	\$0.00
<b>Service Code</b>					
<input type="checkbox"/> #545/2022		#545/2022: 2022 Ford Utility Police Interceptor			
<input type="checkbox"/> 6202		Repair Flat Tire, Plugged Tire			
<input type="checkbox"/> 6224		Left Front			
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	9/6/2024	#545/2022: 2022 Ford Utility Police Interceptor Flat Tire Repair Left Front Tire			
23092 [Scheduled Oil Change]		0.50	\$15.00	\$43.296048	\$0.00
<b>Service Code</b>					
<input type="checkbox"/> #545/2022		#545/2022: 2022 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	9/24/2024	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
23101 [Tire Replacement]		0.50	\$15.00	\$638.000000	\$0.00
<b>Service Code</b>					
<input type="checkbox"/> #545/2022		#545/2022: 2022 Ford Utility Police Interceptor			
<input type="checkbox"/> 6203		Tire Replacement			
<input type="checkbox"/> 6206		R&R Tires (All Four)			
<input type="checkbox"/> 6285		By Pomp's Tire/Royal Tire			
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	9/27/2024	#545/2022: 2022 Ford Utility Police Interceptor Blew Out Right Rear Tire, Stick Went Thru The Outside Sidewall Tire Where Due For Replacement, Replaced All Four Tire By Pomp's Tire Service			
23130 [Engine Over Hearing]		3.00	\$90.00	\$8.889644	\$0.00
<b>Service Code</b>					
<input type="checkbox"/> #545/2022		#545/2022: 2022 Ford Utility Police Interceptor			
<input type="checkbox"/> CSS8505		Cooling System Service			
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			
Ron Bubendorf	10/7/2024	#545/2022: 2022 Ford Utility Police Interceptor Engine Over Heated			
Ron Bubendorf	10/7/2024	Check And Found Front Of The Radiator Covered With Lint And Cotton. Remove Radiator Fan, Coolant Recover Reservoir And Spray Wash Radiator, Re Assemble And Fill Cooling System.			
23203 [Scheduled Oil Change]		0.50	\$15.00	\$43.296048	\$0.00
<b>Service Code</b>					
<input type="checkbox"/> #545/2022		#545/2022: 2022 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
<b>Modified By</b>	<b>Note Date</b>	<b>Note</b>			

## Work Order Summary

WO #		Hours	Labor Costs	Part Costs	Other Costs	Total Costs
545/2022 [2022 Ford Utility Police Interceptor]						
Ron Bubendorf	11/5/2024					
		#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor				
23259 [Scheduled Oil Change]		0.50	\$15.00	\$43.826048	\$0.00	\$58.83
Service Code	Service Description					
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels					
Modified By	Note Date	Note				
Ron Bubendorf	11/26/2024	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor				
23260 [Right Rear Tire Nail In It]		0.75	\$23.00	\$0.263667	\$0.00	\$23.26
Service Code	Service Description					
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 620-102	Repair Flat Tire, Patch Tire					
<input type="checkbox"/> 6221	Right Rear					
Modified By	Note Date	Note				
Ron Bubendorf	11/26/2024	#545/2022: 2022 Ford Utility Police Interceptor Flat Tire Repair Right Rear Tire				
23299 [Scheduled Oil Change]		0.50	\$15.00	\$43.826048	\$0.00	\$58.83
Service Code	Service Description					
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels					
Modified By	Note Date	Note				
Ron Bubendorf	12/17/2024	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor				
23309 [Drivers Seat Repair]		0.50	\$15.00	\$470.130000	\$0.00	\$485.13
Service Code	Service Description					
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 3045	R&R Seat / Send Out And Have Repaired					
Modified By	Note Date	Note				
Ron Bubendorf	12/19/2024	#545/2022: 2022 Ford Utility Police Interceptor R&R Seat And Have Seat Rebuilt By Finest Auto Trim				
23374 [Scheduled Oil Change]		0.50	\$15.00	\$43.826048	\$0.00	\$58.83
Service Code	Service Description					
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels					
Modified By	Note Date	Note				

## Work Order Summary

WO #		Hours	Labor Costs	Part Costs	Other Costs	Total Costs
545/2022 [2022 Ford Utility Police Interceptor]	Ron Bubendorf 1/15/2025					
		#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor				
23462 [Scheduled Oil Change]		0.50	\$15.00	\$53.846248	\$0.00	\$68.85
Service Code	Service Description					
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels					
Modified By	Note Date	Note				
Ron Bubendorf	2/25/2025	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor				
Ron Bubendorf 2/25/2025		Patch The Left Front Corner Of The Front Bumper Cover	0.50	\$15.00	\$43.826048	\$0.00
23494 [Scheduled Oil Change]						\$58.83
Service Code	Service Description					
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels					
Modified By	Note Date	Note				
Ron Bubendorf	3/18/2025	#545/2022: 2022 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor				
23540 [Windshield Wiper Blade Replacement Drivers Side]		0.20	\$6.00	\$21.800000	\$0.00	\$27.80
Service Code	Service Description					
<input type="checkbox"/> #545/2022	#545/2022: 2022 Ford Utility Police Interceptor					
<input type="checkbox"/> WW3034	R&R Front Windshield Wiper Blade Drivers Side					
Modified By	Note Date	Note				
Ron Bubendorf	4/4/2025	#545/2022: 2022 Ford Utility Police Interceptor R&R Front Windshield Wiper Blade Drivers Side				
23556 [ADD FREON ]		1.00	\$40.00	\$116.120000	\$0.00	\$156.12
Modified By	Note Date	Note				
Kevin Hanson	4/11/2025	ADDED FREON COOLS GOOD NOW				
23582 [2000 MILE SERVICE]		0.50	\$20.00	\$43.826048	\$0.00	\$63.83
Service Code	Service Description					
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels					
Modified By	Note Date	Note				
Kevin Hanson	4/23/2025	2000 MILE SERVICE				
23636 [2000 MILE SERVICE]		0.50	\$20.00	\$47.236048	\$0.00	\$67.24
Service Code	Service Description					
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels					
Modified By	Note Date	Note				

## Work Order Summary

WO #		Hours	Labor Costs	Part Costs	Other Costs	Total Costs
545/2022 /2022 Ford Utility Police Interceptor						
Kevin Hanson	5/20/2025	2000 MILE SERVICE				
23656 [LEAKING FROM FRONT OF MOTOR ]		2.50	\$100.00	\$49.017912	\$0.00	\$149.02
Modified By	Note Date	Note				
Kevin Hanson	5/27/2025	HEATER HOSE ASSEMBLY WAS NOT SECURED ON BRACKET AND PLASTIC Y BROKE DUE TO STRESS ON PLASTIC REPAIRED WITH SILICONE HOSE AND NEW Y CONNECTOR				
66		50.95	\$1,631.50	\$6,853.769341	\$0.00	\$8,485.27
2 [2022 Ford Utility Police Interceptor] Totals : 66		50.95	\$1,631.50	\$6,853.769341	\$0.00	\$8,485.27
Grand Totals : 66		50.95	\$1,631.50	\$6,853.769341	\$0.00	\$8,485.27
Scheduled WOs	Unscheduled WOs	Total WOs	Scheduled Costs	Unscheduled Costs	Total Costs	
42.00	24.00	66.00	\$2,475.979799	\$6,009.289542	\$8,485.269341	