



CITY OF EAST GRAND FORKS

Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
543/21 [2021 Ford Utility Police Interceptor]					
20444 [Stop Sticks]	0.50	\$15.00	\$2.464432	\$0.00	\$17.46
Service Code		Service Description			
<input type="checkbox"/> #544/21		#544/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> PC0050		Installed New Stop Stick Vehicle Tire Deflation Device			
Modified By	Note Date	Note			
Ron Bubendorf	1/21/2022	#544/21: 2021 Ford Utility Police Interceptor Installed Stop Stick Vehicle Tire Deflation Device And Mounted Fire Extinguisher in The Back			
20493 [Scheduled Oil Change]	0.50	\$15.00	\$36.223455	\$0.00	\$51.22
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By	Note Date	Note			
Ron Bubendorf	2/10/2022	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
20575 [Scheduled Oil Change]	0.50	\$15.00	\$36.223455	\$0.00	\$51.22
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By	Note Date	Note			
Ron Bubendorf	3/8/2022	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
20621 [Scheduled Oil Change]	0.50	\$15.00	\$36.223455	\$0.00	\$51.22
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By	Note Date	Note			
Ron Bubendorf	4/5/2022	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
20654 [Scheduled Oil Change]	0.50	\$15.00	\$36.223455	\$0.00	\$51.22
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By	Note Date	Note			
Ron Bubendorf	4/21/2022	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			

Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
543/21 [2021 Ford Utility Police Interceptor]					
20687 [Scheduled Oil Change]	0.50	\$15.00	\$36.223455	\$0.00	\$51.22
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By	Note Date	Note			
Ron Bubendorf	5/10/2022	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
20725 [Reprogram Transmission]					
	4.00	\$177.40	\$0.000000	\$0.00	\$177.40
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> WARRANTY1		Warranty Work Vehicle Recall			
Modified By	Note Date	Note			
Ron Bubendorf	5/28/2022	#543/21: 2021 Ford Utility Police Interceptor Complaint: Transmission Down Shifts Hard			
Ron Bubendorf	5/28/2022	Took Vehicle To Lithia Ford FoP2703 Transmission Warranty Transmission Reprogramming Lithia Ford Found Code P2703 Transmission Friction Element "D" Apply Time Range/Performance Preformed Transmission Break In Procedure And Clutch cycling D. Preformed Adaptive Lean Drive Cycle Test Ok			
20727 [Scheduled Oil Change]					
	0.50	\$15.00	\$36.223455	\$0.00	\$51.22
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By	Note Date	Note			
Ron Bubendorf	5/31/2022	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
20807 [Scheduled Oil Change]					
	0.50	\$15.00	\$37.839455	\$0.00	\$52.84
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By	Note Date	Note			
Ron Bubendorf	6/28/2022	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
Ron Bubendorf	6/28/2022	Repair Bottom Of The Front Bumper Cover			
20861 [Scheduled Oil Change]					
	0.50	\$15.00	\$37.913455	\$0.00	\$52.91
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By	Note Date	Note			
Ron Bubendorf	7/19/2022	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
20932 [Scheduled Oil Change]					
	0.50	\$15.00	\$40.133455	\$0.00	\$55.13

Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
543/21 [2021 Ford Utility Police Interceptor]					
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date	Note		
Ron Bubendorf		8/16/2022	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor		
20975 [Scheduled Oil Change]	0.50	\$15.00	\$40.133455	\$0.00	\$55.13
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date	Note		
Ron Bubendorf		9/12/2022	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor		
20977 [Replacement Battery]	0.00	\$0.00	\$161.178500	\$0.00	\$161.18
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> BAT5202		Run Battery Test / Fail			
<input type="checkbox"/> BAT5204		R&R Battery			
<input type="checkbox"/> BAT5206		Install Battery Terminal Protectors			
Modified By		Note Date	Note		
Ron Bubendorf		9/12/2022	#543/21: 2021 Ford Utility Police Interceptor Battery Goes Dead		
Ron Bubendorf		9/12/2022	Replaced Battery And Installed Battery Post Terminal Protectors		
Ron Bubendorf		9/12/2022	Replaced Missing Nut & Bolt For Right Rear Prisoner Set Belt Buckle		
21065 [Scheduled Oil Change]	0.50	\$15.00	\$40.133455	\$0.00	\$55.13
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date	Note		
Ron Bubendorf		10/11/2022	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor		
21080 [Flat Tire Left Rear]	0.50	\$15.00	\$1.338400	\$0.00	\$16.34
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 6202		Repair Flat Tire, Plugged Tire			
<input type="checkbox"/> 6222		Left Rear			
<input type="checkbox"/> 6283		By City Shop			
Modified By		Note Date	Note		
Ron Bubendorf		11/25/2022	#543/21: 2021 Ford Utility Police Interceptor Repair Flat Tire, Plugged Tire, Left Rear Tire		
21127 [Radar Is Not Working Correctly]	0.50	\$15.00	\$0.000000	\$0.00	\$15.00
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> PC6203		Check And Found The Cable Connector For The Interface Cable For The Watch Guard Camera System To Interface The Radar Not Making Good Connection, Tighten Connector Thump Screws, Run Self Test And Everything Pass Test			

Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
543/21 [2021 Ford Utility Police Interceptor]					
Modified By	Note Date	Note			
Ron Bubendorf	10/25/2022	Check And Found Radar Cable Connector Thumb Screw Missing And Not Making A Good Connection, Tighten The One Thumb Screw And Tape Cable Connector Together, Test And All Working			
Ron Bubendorf	10/25/2022	#543/21: 2021 Ford Utility Police Interceptor Radar Is Not Working Correctly, Radar Will Not Properly Switch Between Moving And Stationary Mode. Radar Defaults To Stationary Mode Even When Driving. When The Button Is Pressed To Switch To Moving Mode, It Momentarily Switches To Moving Mode And Then Back To Stationary			
Ron Bubendorf	10/25/2022	Check And Found The Cable Connector For The Interface Cable For The Watch Guard Camera System To Interface The Radar Not Making Good Connection, Tighten Connector Thump Screws, Run Self Test And Everything Pass Test			
21149 [Scheduled Oil Change]	0.50	\$15.00	\$40.133455	\$0.00	\$55.13
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
Modified By	Note Date	Note			
Ron Bubendorf	11/7/2022	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
21150 [Tire Repair Right Rear]	0.50	\$15.00	\$1.338400	\$0.00	\$16.34
Service Code	Service Description				
<input type="checkbox"/> #544/21	#544/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> 6202	Repair Flat Tire, Plugged Tire				
<input type="checkbox"/> 6221	Right Rear				
Modified By	Note Date	Note			
Ron Bubendorf	11/7/2022	#544/21: 2021 Ford Utility Police Interceptor Repair Flat Tire, Plugged Tire, Right Rear Tire			
21175 [Tire Replacement]	1.00	\$30.00	\$761.480000	\$0.00	\$791.48
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> 6206	R&R Tires (All Four)				
<input type="checkbox"/> 6289	By Todd's Tire Service				
Modified By	Note Date	Note			
Ron Bubendorf	11/14/2022	#543/21: 2021 Ford Utility Police Interceptor Four New Tires Installed By Todd's Tire Service			
21265 [Scheduled Oil Change]	0.50	\$15.00	\$40.783455	\$0.00	\$55.78
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
Modified By	Note Date	Note			
Ron Bubendorf	11/29/2022	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
21332 [Scheduled Oil Change]	0.50	\$15.00	\$41.263455	\$0.00	\$56.26
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
Modified By	Note Date	Note			
Ron Bubendorf	12/22/2022	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure			

Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
543/21 [2021 Ford Utility Police Interceptor]					
21402 [Scheduled Oil Change]	0.50	\$15.00	\$61.193455	\$0.00	\$76.19
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date	Note		
Ron Bubendorf		1/25/2023	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor		
21469 [Scheduled Oil Change]	0.50	\$15.00	\$41.263455	\$0.00	\$56.26
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date	Note		
Ron Bubendorf		2/17/2023	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor		
21494 [Check Engine Is On]	4.00	\$120.00	\$40.689400	\$0.00	\$160.69
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> DTC P0300		Diagnostics Code P0300 Random Misfire			
<input type="checkbox"/> DTC P0301		Diagnostics Code P0301 #1 Cylinder Misfire Detected			
Modified By		Note Date	Note		
Ron Bubendorf		2/24/2023	#543/21: 2021 Ford Utility Police Interceptor Check Genie Light Is On		
Ron Bubendorf		2/24/2023	Check For Codes And Found 3 Codes Diagnostics Code P0300 Random Misfire Diagnostics Code P0301 #1 Cylinder Misfire Detected Replaced Spark Plugs And Cleared Codes		
21550 [Scheduled Oil Change]	0.50	\$15.00	\$41.263455	\$0.00	\$56.26
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date	Note		
Ron Bubendorf		3/14/2023	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor		
21615 [Scheduled Oil Change]	0.50	\$15.00	\$41.263455	\$0.00	\$56.26
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date	Note		
Ron Bubendorf		4/4/2023	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor		

Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
543/21 [2021 Ford Utility Police Interceptor]					
21654 [Scheduled Oil Change]	0.50	\$15.00	\$41.763455	\$0.00	\$56.76
<div> <div>Service Code</div> <div> <input type="checkbox"/> #543/21 <input type="checkbox"/> 0001 </div> </div> <div> <div>Service Description</div> <div> #543/21: 2021 Ford Utility Police Interceptor Change Oil and Filters & Check All Fluid Levels </div> </div>					
<div> <div>Modified By</div> <div> Ron Bubendorf </div> </div> <div> <div>Note Date</div> <div> 4/25/2023 </div> </div> <div> <div>Note</div> <div> #543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor </div> </div>					
21726 [Scheduled Oil Change]	0.50	\$15.00	\$41.901755	\$0.00	\$56.90
<div> <div>Service Code</div> <div> <input type="checkbox"/> #543/21 <input type="checkbox"/> 0001 </div> </div> <div> <div>Service Description</div> <div> #543/21: 2021 Ford Utility Police Interceptor Change Oil and Filters & Check All Fluid Levels </div> </div>					
<div> <div>Modified By</div> <div> Ron Bubendorf </div> </div> <div> <div>Note Date</div> <div> 5/23/2023 </div> </div> <div> <div>Note</div> <div> #543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor Fix The Bottom Of The Front Bumper Cover </div> </div>					
21789 [Scheduled Oil Change]	0.50	\$15.00	\$41.763455	\$0.00	\$56.76
<div> <div>Service Code</div> <div> <input type="checkbox"/> #543/21 <input type="checkbox"/> 0001 </div> </div> <div> <div>Service Description</div> <div> #543/21: 2021 Ford Utility Police Interceptor Change Oil and Filters & Check All Fluid Levels </div> </div>					
<div> <div>Modified By</div> <div> Ron Bubendorf </div> </div> <div> <div>Note Date</div> <div> 6/14/2023 </div> </div> <div> <div>Note</div> <div> #543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor </div> </div>					
21869 [Scheduled Oil Change]	0.50	\$15.00	\$41.763544	\$0.00	\$56.76
<div> <div>Service Code</div> <div> <input type="checkbox"/> #543/21 <input type="checkbox"/> 0001 </div> </div> <div> <div>Service Description</div> <div> #543/21: 2021 Ford Utility Police Interceptor Change Oil and Filters & Check All Fluid Levels </div> </div>					
<div> <div>Modified By</div> <div> Ron Bubendorf </div> </div> <div> <div>Note Date</div> <div> 7/11/2023 </div> </div> <div> <div>Note</div> <div> #543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor </div> </div>					
21891 [Windshield Camera Mount Fell Off]	0.50	\$15.00	\$3.590000	\$0.00	\$18.59
<div> <div>Service Code</div> <div> <input type="checkbox"/> #543/21 <input type="checkbox"/> BW3021 </div> </div> <div> <div>Service Description</div> <div> #543/21: 2021 Ford Utility Police Interceptor Re-glue Rear View Mirror </div> </div>					
<div> <div>Modified By</div> <div> Ron Bubendorf </div> </div> <div> <div>Note Date</div> <div> 7/17/2023 </div> </div> <div> <div>Note</div> <div> #543/21: 2021 Ford Utility Police Interceptor Re-glue Rear View Mirror Mount For The Watchguard Dash Camera </div> </div>					
21916 [Fuel Fill Door Replacement]	1.50	\$45.00	\$69.050000	\$0.00	\$114.05
<div> <div>Service Code</div> <div> <input type="checkbox"/> #543/21 <input type="checkbox"/> FS4378 </div> </div> <div> <div>Service Description</div> <div> #543/21: 2021 Ford Utility Police Interceptor Replace Fuel Fill Door Assembly </div> </div>					

Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
543/21 [2021 Ford Utility Police Interceptor]					
Modified By	Note Date	Note			
Ron Bubendorf	7/27/2023	#543/21: 2021 Ford Utility Police Interceptor Replace Fuel Fill Door Assembly			
21936 [Scheduled Oil Change]	0.50	\$15.00	\$41.763544	\$0.00	\$56.76
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
Modified By	Note Date	Note			
Ron Bubendorf	8/2/2023	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
21977 [Brakes Replacement]	3.50	\$140.00	\$903.540002	\$0.00	\$1,043.54
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> BRK6004	Inspect Brakes & Replace				
Modified By	Note Date	Note			
Ron Bubendorf	8/15/2023	#543/21: 2021 Ford Utility Police Interceptor R&R Brake Pads And Rotors On All Four Wheels			
21986 [Reprogram Transmission]	0.50	\$15.00	\$180.000000	\$0.00	\$195.00
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
Modified By	Note Date	Note			
Ron Bubendorf	8/16/2023	#543/21: 2021 Ford Utility Police Interceptor Complaint Transmission Shifts Harshly Took Vehicle To Nelson Auto Center And Found TSB 23-2250 And Updated PCM Software Cleared TCM Adaptive Learn Shift Strategies, Performed Adaptive Lean Drive Cycle			
22020 [Scheduled Oil Change]	0.50	\$15.00	\$41.763544	\$0.00	\$56.76
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
Modified By	Note Date	Note			
Ron Bubendorf	8/29/2023	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
22103 [Rear windows are not working]	3.00	\$120.00	\$159.250000	\$0.00	\$279.25
Modified By	Note Date	Note			
Kevin Hanson	9/21/2023	Order a master window switch			
Kevin Hanson	9/25/2023	Replaced master window switch and removed driver rear door panel and plug in switch			
22107 [Oil Change]	0.50	\$20.00	\$41.763636	\$0.00	\$61.76
Service Code	Service Description				
<input checked="" type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
Modified By	Note Date	Note			
Kevin Hanson	9/25/2023	2000 mile service			
22154 [Scheduled Oil Change]	0.50	\$15.00	\$43.613636	\$0.00	\$58.61
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
Modified By	Note Date	Note			
Ron Bubendorf		#543/21: 2021 Ford Utility Police Interceptor			

Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
543/21 [2021 Ford Utility Police Interceptor]					
10/17/2023					
0001: Change Oil and Filter & Check All Fluid Levels					
0002: Inspect Air Filter, Change if Needed					
0003: Check Tire Pressure & Inflate Tires To Proper Pressure					
0004: Refill Windshield Washer Tank					
Added Oil Additive And Reset Oil Life Monitor					
22164 [Shot Gun Lock Modifaction]	0.50	\$15.00	\$0.624400	\$0.00	\$15.62
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
Modified By	Note Date	Note			
Ron Bubendorf	10/20/2023	#543/21: 2021 Ford Utility Police Interceptor Shim Out The Shot Gun Lock To Fit For New Shot Gun Stock With Flash-lite And Lazar Lite			
22165 [Tire Replacement]	0.50	\$15.00	\$724.120000	\$0.00	\$739.12
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 62307		Replaced All Four Tires By Pomp's Tire			
Modified By	Note Date	Note			
Ron Bubendorf	10/20/2023	#252: 2017 Dodge Ram 2500 4WD Replaced All Four Tires By Pomp's Tire			
22206 [Scheduled Oil Change]	0.50	\$15.00	\$43.563636	\$0.00	\$58.56
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By	Note Date	Note			
Ron Bubendorf	11/7/2023	#543/21: 2021 Ford Utility Police Interceptor			
		0001: Change Oil and Filter & Check All Fluid Levels			
		0002: Inspect Air Filter, Change if Needed			
		0003: Check Tire Pressure & Inflate Tires To Proper Pressure			
		0004: Refill Windshield Washer Tank			
		Added Oil Additive And Reset Oil Life Monitor			
Ron Bubendorf	11/8/2023	Replaced Oil Pan Drain Plug, Drain Plug Was Leaking			
22231 [Transmission Fluid Exchange Demonstration]	1.00	\$45.26	\$117.650000	\$0.00	\$162.91
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> TRANS 0001		Service Transmission (Change Transmission Fluid)			
Modified By	Note Date	Note			
Ron Bubendorf	11/17/2023	#543/21: 2021 Ford Utility Police Interceptor Had BG Products Come And Due A Demonstration On A New Transmission Fluid Exchange Machine On This Vehicle			
22248 [Scheduled Oil Change]	0.50	\$15.00	\$43.563636	\$0.00	\$58.56
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By	Note Date	Note			
Ron Bubendorf	11/28/2023	#543/21: 2021 Ford Utility Police Interceptor			
		0001: Change Oil and Filter & Check All Fluid Levels			
		0002: Inspect Air Filter, Change if Needed			
		0003: Check Tire Pressure & Inflate Tires To Proper Pressure			
		0004: Refill Windshield Washer Tank			
		Added Oil Additive And Reset Oil Life Monitor			
22316 [Scheduled Oil Change]	0.50	\$15.00	\$43.563636	\$0.00	\$58.56
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By	Note Date	Note			
Ron Bubendorf	12/19/2023	#543/21: 2021 Ford Utility Police Interceptor			
		0001: Change Oil and Filter & Check All Fluid Levels			

Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
543/21 [2021 Ford Utility Police Interceptor]					
0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor					
22336 [Replacement Battery]	1.00	\$30.00	\$197.211000	\$0.00	\$227.21
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> BAT5202		Run Battery Test / Fail			
<input type="checkbox"/> BAT5204		R&R Battery			
<input type="checkbox"/> BAT5229		Replace Battery For Remote Door Locks			
Modified By		Note Date	Note		
Ron Bubendorf		1/3/2024	#543/21: 2021 Ford Utility Police Interceptor Battery Goes Dead, Replaced Battery And Replaced Battery For Keyless Entry Fob		
22366 [Scheduled Oil Change]	0.50	\$15.00	\$43.563636	\$0.00	\$58.56
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date	Note		
Ron Bubendorf		1/16/2024	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor		
22448 [Scheduled Oil Change]	0.50	\$15.00	\$43.563636	\$0.00	\$58.56
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date	Note		
Ron Bubendorf		2/13/2024	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor		
22492 [Scheduled Oil Change]	0.50	\$15.00	\$68.536048	\$0.00	\$83.54
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date	Note		
Ron Bubendorf		3/5/2024	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor		
Ron Bubendorf		3/5/2024	Replaced Cabin Air Filter		
22538 [Scheduled Oil Change]	0.50	\$15.00	\$42.956048	\$0.00	\$57.96
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date	Note		
Ron Bubendorf		3/26/2024	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank		

Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
543/21 [2021 Ford Utility Police Interceptor]					
22599 [Scheduled Oil Change]	0.50	\$15.00	\$42.956048	\$0.00	\$57.96
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date		Note	
Ron Bubendorf		4/23/2024		#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor	
22641 [Scheduled Oil Change]	0.50	\$15.00	\$42.956048	\$0.00	\$57.96
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date		Note	
Ron Bubendorf		5/14/2024		#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor	
22702 [Scheduled Oil Change]	0.50	\$15.00	\$42.956048	\$0.00	\$57.96
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date		Note	
Ron Bubendorf		6/5/2024		#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor	
22780 [Scheduled Oil Change]	0.50	\$15.00	\$62.906048	\$0.00	\$77.91
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date		Note	
Ron Bubendorf		6/25/2024		#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor	
22870 [Scheduled Oil Change]	0.50	\$15.00	\$42.956048	\$0.00	\$57.96
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date		Note	
Ron Bubendorf		7/23/2024		#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor	
22905 [Warranty Recall]	0.50	\$15.00	\$0.000000	\$0.00	\$15.00

Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
543/21 [2021 Ford Utility Police Interceptor]					
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> WARRANTY1		Warranty Work Vehicle Recall			
Modified By		Note Date	Note		
Ron Bubendorf		9/19/2024	#543/21: 2021 Ford Utility Police Interceptor Warranty Recall 23S55 Vehicle Rollaway From DriveShaft Disconnect		
22906 [Check Engine Light Is On]	1.00	\$30.00	\$3,721.410000	\$0.00	\$3,751.41
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> SUP6004		R&R Wheel Bearing Assembly Right Front			
<input type="checkbox"/> SUP6005		R&R Wheel Bearing Assembly Left Front			
<input type="checkbox"/> SUP6010		R&R Left Front Steering Knuckle			
<input type="checkbox"/> TRANS 0001		Service Transmission (Change Transmission Fluid)			
<input type="checkbox"/> WARRANTY1		Warranty Work Vehicle Recall			
Modified By		Note Date	Note		
Ron Bubendorf		10/31/2024	#543/21: 2021 Ford Utility Police Interceptor Took Vehicle To Nelson For Check Engine Light And To Have The Transmission Serviced, Also Found The Front Wheel Bearings Need To Be Replaced And The Left Front Steering Knuckle. Check Engine Light Code P0451 Replaced Fuel Tank Pressure Sensor Tube Assembly		
22915 [Water Pump Replacement]	5.00	\$150.00	\$225.050900	\$0.00	\$375.05
Service Code		Service Description			
<input type="checkbox"/> #545/2022		#545/2022: 2022 Ford Utility Police Interceptor			
<input type="checkbox"/> 5307		R&R Spark Plugs			
<input type="checkbox"/> BELT5700		R&R Alternator/Water Pump Serpentine Belt			
<input type="checkbox"/> BELT5701		R&R A/C Compressor Serpentine Belt			
<input type="checkbox"/> CSS8501		R&R Water Pump			
Modified By		Note Date	Note		
Ron Bubendorf		8/9/2024	#545/2022: 2022 Ford Utility Police Interceptor R&R Water Pump, Alternator Belt/Water Pump Belt, A/C Compressor Belt, R&R Spark Plugs		
22949 [Alternator Replacement]	2.00	\$60.00	\$927.960000	\$0.00	\$987.96
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> ALT5801		Alternator Test / Check Charging System / System Fail			
<input type="checkbox"/> ALT5804		R&R Alternator			
Modified By		Note Date	Note		
Ron Bubendorf		8/27/2024	#543/21: 2021 Ford Utility Police Interceptor Message Center Came On And Said AWD Fault, Electrical System Active Service Soon Check And Found The Alternator Was Not Charging The Battery, Charge The Battery And Started The Vehicle And Would Look To See If The Alternator Was Charging The Battery And It Would Charge For A Few Seconds And Would Shut Off. Replaced Alternator And Run Another Test And Alternator Out Put Was 14.4 Volts And Would Not Shut Off		
22982 [Screw In Left Rear Tire]	0.50	\$15.00	\$1.338400	\$0.00	\$16.34
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 6202		Repair Flat Tire, Plugged Tire			
<input type="checkbox"/> 6222		Left Rear			
Modified By		Note Date	Note		
Ron Bubendorf		9/9/2024	#543/21: 2021 Ford Utility Police Interceptor Repair Flat Tire, Plugged Tire, Left Rear Tire		
22983 [Scheduled Oil Change]	0.50	\$15.00	\$43.296048	\$0.00	\$58.30
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date	Note		

Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
543/21 [2021 Ford Utility Police Interceptor]					
Ron Bubendorf	9/9/2024	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
23072 [Nail In Right Rear Tire]	0.50	\$15.00	\$1.338400	\$0.00	\$16.34
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 6202		Repair Flat Tire, Plugged Tire			
<input type="checkbox"/> 6221		Right Rear			
Modified By		Note Date	Note		
Ron Bubendorf		9/23/2024	#543/21: 2021 Ford Utility Police Interceptor Repair Flat Tire, Plugged Tire, Right Rear Tire		
23134 [Tire Replacement]	0.50	\$15.00	\$142.000000	\$0.00	\$157.00
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 6203		Tire Replacement			
<input type="checkbox"/> 6206		R&R Tires (All Four)			
<input type="checkbox"/> 6285		By Pomp's Tire/Royal Tire			
Modified By		Note Date	Note		
Ron Bubendorf		10/10/2024	#543/21: 2021 Ford Utility Police Interceptor Tire Where Due For Replacement, Replaced All Four Tire By Pomp's Tire Service Installed Four Used Tires Off Of #515/20 K-9 Unit		
23136 [Engine Over Hearing]	3.00	\$90.00	\$7.100644	\$0.00	\$97.10
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> CSS8505		Cooling System Service			
Modified By		Note Date	Note		
Ron Bubendorf		10/10/2024	Check And Found Front Of The Radiator Covered With Lint And Cotton. Remove Radiator Fan, Coolant Recover Reservoir And Spray Wash Radiator, Re Assemble And Fill Cooling System.		
Ron Bubendorf		10/11/2024	#543/2021: 2022 Ford Utility Police Interceptor Engine Over Heated		
23201 [Scheduled Oil Change]	0.50	\$15.00	\$43.296048	\$0.00	\$58.30
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date	Note		
Ron Bubendorf		11/5/2024	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor		
23261 [Scheduled Oil Change]	0.50	\$15.00	\$43.826048	\$0.00	\$58.83
Service Code		Service Description			
<input type="checkbox"/> #543/21		#543/21: 2021 Ford Utility Police Interceptor			
<input type="checkbox"/> 0001		Change Oil and Filters & Check All Fluid Levels			
Modified By		Note Date	Note		
Ron Bubendorf		11/26/2024	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor		
23295 [Tire Replacement]	1.00	\$30.00	\$0.000000	\$0.00	\$30.00
Service Code		Service Description			

Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
543/21 [2021 Ford Utility Police Interceptor]					
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> #544/21	#544/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> 6206	R&R Tires (All Four)				
Modified By	Note Date	Note			
Ron Bubendorf	12/24/2024	#543/21: 2021 Ford Utility Police Interceptor Removed The Four New Tires Off #544/21: 2021 Ford Utility Police Interceptor And Install On This Vehicle Reprogram Tire Pressure Sensors #544/21 Has Engine Problem Not To Be Repaired			
23296 [Scheduled Oil Change]	0.50	\$15.00	\$43.826048	\$0.00	\$58.83
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
Modified By	Note Date	Note			
Ron Bubendorf	12/16/2024	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
23340 [Drivers Seat Repair]	0.50	\$15.00	\$224.500000	\$0.00	\$239.50
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> 3045	R&R Seat / Send Out And Have Repaired				
Modified By	Note Date	Note			
Ron Bubendorf	1/3/2025	#543/2021: 2021 Ford Utility Police Interceptor R&R Seat And Have Seat Rebuilt By Finest Auto Trim			
23414 [Scheduled Oil Change]	0.50	\$15.00	\$43.826048	\$0.00	\$58.83
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
Modified By	Note Date	Note			
Ron Bubendorf	2/3/2025	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
23439 [Tire Pressure Sensor Replacement]	0.50	\$15.00	\$603.860000	\$0.00	\$618.86
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> 62560	Replaced Tire Pressure Monitor Sensor Left Rear				
<input type="checkbox"/> 62561	Replaced Tire Pressure Monitor Sensor Right Rear				
<input type="checkbox"/> 62562	Replaced Tire Pressure Monitor Sensor Left Front				
<input type="checkbox"/> 62563	Replaced Tire Pressure Monitor Sensor Right Front				
Modified By	Note Date	Note			
Ron Bubendorf	2/12/2025	#543/21: 2021 Ford Utility Police Interceptor Complaint: Right Rear Tire Pressure Sensor Fault Come On The Message Center. Had Nelson Ford Replaced The Right Rear Tire Pressure Sensor And I Was Leaving Nelson Ford The Left Rear Tire Pressure Sensor Quit, So Took The Vehicle Back To Nelson Ford And They Installed Another Sensor And That One Would Not Program. So Nelson Ford Ordered The Other Three Sensors And Had Them Installed And Programed Today And Now The System Is Working Right.			
23487 [Scheduled Oil Change]	0.50	\$15.00	\$43.826048	\$0.00	\$58.83
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				

Work Order Summary

WO #	Hours	Labor Costs	Part Costs	Other Costs	Total Costs
543/21 [2021 Ford Utility Police Interceptor]					
Modified By	Note Date	Note			
Ron Bubendorf	3/12/2025	#543/21: 2021 Ford Utility Police Interceptor 0001: Change Oil and Filter & Check All Fluid Levels 0002: Inspect Air Filter, Change if Needed 0003: Check Tire Pressure & Inflate Tires To Proper Pressure 0004: Refill Windshield Washer Tank Added Oil Additive And Reset Oil Life Monitor			
23575 [Scheduled Oil Change]	0.50	\$20.00	\$43.826048	\$0.00	\$63.83
Service Code	Service Description				
<input type="checkbox"/> 0001	Change Oil and Filters & Check All Fluid Levels				
Modified By	Note Date	Note			
Kevin Hanson	4/21/2025	2000 MILE SERVICE			
23578 [Leak at driver side flex pipe]	1.20	\$48.00	\$232.320000	\$0.00	\$280.32
Modified By	Note Date	Note			
Kevin Hanson	4/22/2025	Replace driver side flex pipe			
23774 [Scheduled Transmission Service]	0.00	\$0.00	\$27.000000	\$0.00	\$27.00
Service Code	Service Description				
<input type="checkbox"/> #543/21	#543/21: 2021 Ford Utility Police Interceptor				
<input type="checkbox"/> TRANS 0001	Service Transmission (Change Transmission Fluid)				
Modified By	Note Date	Note			
HAGEN, IVAN	8/25/2025	#543/21: 2021 Ford Utility Police Interceptor Service Transmission (Change Transmission Fluid)			
75	61.70	\$2,010.66	\$11,363.920489	\$0.00	\$13,374.58
1 [2021 Ford Utility Police Interceptor] Totals : 75	61.70	\$2,010.66	\$11,363.920489	\$0.00	\$13,374.58
Grand Totals : 75	61.70	\$2,010.66	\$11,363.920489	\$0.00	\$13,374.58
Scheduled WOs	Unscheduled WOs	Total WOs	Scheduled Costs	Unscheduled Costs	Total Costs
46.00	29.00	75.00	\$2,638.517611	\$10,736.062878	\$13,374.580489