

WORK ORDER: 111202			
ASSET NUMBER: 30633			
Work Order Status: C - C - Closed		Date In:	08/15/2014
Work Order Shop: 1 - TTM-VehicleRepair		Date Out:	08/18/2014
ASSET NUMBER INFORMATION			
YEAR: 2015	ORG: Active Fleet	TIRE SIZE: Goodyear, 245/55R18	
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic	ENGINE SIZE: 3.7L	
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY	TRANS: 6S Auto	
LICENSE: 30-633	SITE: Columbus, Ohio	FUEL TYPE: U, NFT	
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356	ASSET AVAIL CODE: 0000 to 2359 On Call 24/5	
CLASS: SUV, Patrol, Marked		METERS: Mileage - 91	
MISCELLANEOUS COSTS			
CODE	DESCRIPTION	POSTED DATE	MISC COST
Title Work, Administrative	Title Work, Administrative	08/18/2014	\$50.000
WORK ORDER TOTALS			
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000
TOTAL LABOR:	\$0.000	TOTAL MISC:	\$50.000
		TOTAL COST:	\$50.000
NOTES			
111202 -			
08/15/2014 @ 14:48:55 ZANE BARRETT			
TITLE & REGISTRATION			

WORK ORDER: 111203					
ASSET NUMBER: 30633					
Work Order Status: C - C - Closed			Date In:	08/15/2014	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	10/22/2014	
ASSET NUMBER INFORMATION					
YEAR: 2015	ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18		
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L		
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto		
LICENSE: 30-633	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: SUV, Patrol, Marked			METERS: Mileage - 91		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
GILLESPIE	08/18/2014	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform	0.50	\$50.000	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
0590-0100	S	1.000	\$28.327	08/19/2014	\$28.327
PART NAME: Extinguisher, Fire, ABC, 2.5 Lb		REPAIR: Vehicle Prep / Expendable / ExtinguisherFir / PartIssue			
1149-0140	NS	1.000	\$22.103	08/19/2014	\$22.103
PART NAME: First Aid Kit; 25 Person		REPAIR: Vehicle Prep / Expendable / Kit First Aid / PartIssue			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		09/25/2014		\$5.000
WORK ORDER TOTALS					
TOTAL PARTS:	\$50.430	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$50.000	TOTAL MISC:	\$5.000	TOTAL COST:	\$105.430
NOTES					
111203 -					
08/15/2014 @ 14:51:05 ZANE BARRETT					
NEW VEHICLE CHECK IN					
SAFETY INSPECTION					
08/18/2014 @ 15:36:05 SAM GILLESPIE					
SAFETY INSPECTION COMPLETE					

WORK ORDER: 114041					
ASSET NUMBER: 30633					
Work Order Status: C - C - Closed		Date In:	01/30/2015		
Work Order Shop: 1 - TTM-VehicleRepair		Date Out:	01/30/2015		
ASSET NUMBER INFORMATION					
YEAR: 2015	ORG: Active Fleet	TIRE SIZE: Goodyear, 245/55R18			
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic	ENGINE SIZE: 3.7L			
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY	TRANS: 6S Auto			
LICENSE: 30-633	SITE: Columbus, Ohio	FUEL TYPE: U, NFT			
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356	ASSET AVAIL CODE: 0000 to 2359 On Call 24/5			
CLASS: SUV, Patrol, Marked		METERS: Mileage - 137			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION	POSTED DATE	MISC COST		
OSU LOGO INSTALLATION	OSU LOGO INSTALLATION	01/30/2015	\$775.000		
WORK ORDER TOTALS					
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$0.000	TOTAL MISC:	\$775.000	TOTAL COST:	\$775.000
NOTES					
LOGO INSTALL - LOGO INSTALL					

WORK ORDER: 114848					
ASSET NUMBER: 30633					
Work Order Status: C - C - Closed			Date In:	03/11/2015	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	03/12/2015	
ASSET NUMBER INFORMATION					
YEAR: 2015	ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18		
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L		
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto		
LICENSE: 30-633	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: SUV, Patrol, Marked			METERS: Mileage - 137		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
PODOBNIK.1	03/11/2015	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform	0.63	\$17.000	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
045-7502	S	1.000	\$4.080	03/11/2015	\$4.080
PART NAME: Filter,Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
0893-0520	S	6.000	\$2.240	03/11/2015	\$13.440
PART NAME: Oil, 5W20, Synthetic Blend, Bulk;1-Qt.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		03/11/2015		\$1.700
WORK ORDER TOTALS					
TOTAL PARTS:	\$17.520	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$17.000	TOTAL MISC:	\$1.700	TOTAL COST:	\$36.220
NOTES					
PMA - Moscato 2-3703 03/11/2015 Walk-In PMA Keys Yes ; Vehicle Update - Vehicle will get looked at today. ; PMA COMPLETE - Wednesday, March 11, 2015 2:23:00 PM TYLER PODOBNIK PMA COMPLETE ; Vehicle ready call - Left message for Moscato vehicle ready for pick up. ; Vehicle pick up - Moscato picked up vehicle					

WORK ORDER: 119211					
ASSET NUMBER: 30633					
Work Order Status: C - C - Closed			Date In:	09/10/2015	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	01/08/2016	
ASSET NUMBER INFORMATION					
YEAR: 2015	ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18		
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L		
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto		
LICENSE: 30-633	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: SUV, Patrol, Marked		METERS: Mileage - 1479			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
LAUER	09/10/2015	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform	0.22	\$17.000	
LAUER	09/10/2015	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform	1.01	\$50.000	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
045-7502	S	1.000	\$4.080	09/10/2015	\$4.080
PART NAME: Filter,Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
0893-0520	S	6.000	\$1.859	09/10/2015	\$11.154
PART NAME: Oil, 5W20, Synthetic Blend, Bulk;1-Qt.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		09/10/2015		\$6.700
WORK ORDER TOTALS					
TOTAL PARTS:	\$15.234	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$67.000	TOTAL MISC:	\$6.700	TOTAL COST:	\$88.934
NOTES					
PMA, Safety Inspection - Moscato 2-3703 Appointment Time: Tue 9/8/2015 10:00 AM Tue 9/8/2015 11:30 AM PMA, Safety Inspection KEYS YES ; PMA - -DRAINED OLD OIL -REMOVED OLD OIL FILTER -INSTALLED NEW OIL FILTER -ADDED 6 QTZ OF OIL, COULDNT ISSUE OIL INFORMED JOHN MARLOW -TASK COMPLETE ; PMS - -NOTICED TPMS LIGHT WAS ON -CORRECT ALL TIRE PRESSURES -WENT ON MITCHELL AND LEARNED HOW TO EXECUTE TIRE LEARN FOR THIS VEHICLE -USED SCANNER AND RE LEARNED THE TIRES -LIGHT WENT OFF -NO OTHER ISSUES TO REPORT -TASK COMPLETE ; Vehicle ready call - Spoke with Moscato Vehicle ready for pick up. Advised him he would get new paperwork when oil is added to work order. ; Vehicle pick up - Moscato picked up vehicle.					

WORK ORDER: 120959						
ASSET NUMBER: 30633						
Work Order Status: C - C - Closed			Date In:	11/04/2015		
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	11/05/2015		
ASSET NUMBER INFORMATION						
YEAR: 2015	ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18			
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L			
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto			
LICENSE: 30-633	SITE: Columbus, Ohio		FUEL TYPE: U, NFT			
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5			
CLASS: SUV, Patrol, Marked		METERS: Mileage - 18616				
TECHNICIAN REPAIRS PERFORMED						
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST		
RANKIN.165	11/04/2015	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform	0.85	\$17.000		
PARTS ISSUED						
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
045-7502	S	1.000	\$4.080	11/04/2015	\$4.080	
PART NAME: Filter,Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform				
0620-0274	S	1.000	\$2.688	11/04/2015	\$2.688	
PART NAME: Fluid,Washer,Windshield;1-Gal.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform				
0893-0520	S	6.000	\$1.859	11/04/2015	\$11.154	
PART NAME: Oil, 5W20, Synthetic Blend, Bulk;1-Qt.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform				
MISCELLANEOUS COSTS						
CODE	DESCRIPTION		POSTED DATE		MISC COST	
Environmental Charge	Environmental Charge		11/04/2015		\$1.700	
WORK ORDER TOTALS						
TOTAL PARTS:	\$17.922	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:		\$0.000		
TOTAL LABOR:	\$17.000	TOTAL MISC:		\$1.700	TOTAL COST:	\$36.622
NOTES						
PMA, RESET MAINTENANCE LIGHT - Moscato 2-3703 Tue 11/3/2015 11:00 AM Tue 11/3/2015 12:00 PM PMA ; PMA - Wednesday, November 04, 2015 Perform PMA service. Reset oil life reminder. Tire pressure 36 psi, tread depth 7/32" All tires Complete. ; Vehicle ready call - Spoke to Moscato vehicle ready for pick up. ; Vehicle pick up - Moscato picked up vehicle.						

WORK ORDER: 123657					
ASSET NUMBER: 30633					
Work Order Status: C - C - Closed			Date In:	01/12/2016	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	01/12/2016	
ASSET NUMBER INFORMATION					
YEAR: 2015	ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18		
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L		
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto		
LICENSE: 30-633	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: SUV, Patrol, Marked			METERS: Mileage - 21827		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
RANKIN.165	01/12/2016	General Repair / Light System / Bulb Headlight / Replace	0.20	\$17.166	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
034-9005	S	1.000	\$14.480	01/12/2016	\$14.480
PART NAME: Bulb, Headlight		REPAIR: General Repair / Light System / Bulb Headlight / Replace			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		01/14/2016		\$1.710
WORK ORDER TOTALS					
TOTAL PARTS:	\$14.480	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$17.166	TOTAL MISC:	\$1.710	TOTAL COST:	\$33.356
NOTES					
Headlight Bulb - I. Officer stopped by yesterday with headlight bulb out. A. Bulb is here. 01. Spoke w/Mike Moscato letting him know part is here. ? ; head light bulb - Tuesday, January 12, 2016 Replace the left headlight bulb . Complete.					

WORK ORDER: 124086				
ASSET NUMBER: 30633				
Work Order Status: C - C - Closed			Date In:	02/12/2016
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	02/24/2016
ASSET NUMBER INFORMATION				
YEAR: 2015	ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18	
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L	
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto	
LICENSE: 30-633	SITE: Columbus, Ohio		FUEL TYPE: U, NFT	
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5	
CLASS: SUV, Patrol, Marked			METERS: Mileage - 23458	
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$0.000	TOTAL MISC:	\$0.000	TOTAL COST: \$0.000
NOTES				
Thumping Noise. - Moscato 2-3703 This vehicle was dropped off at Kiem Ford yesterday I case they call over there. It has a thumping sound when you make turns. More noticeable at slow speeds. ; Vendor call - Spoke to Pete at Keim. He said they have a steering gear on order. I will call back Wednesday to check back up on repairs. ; Customer update - Emailed customer update on vehicle. ; Vendor call - Spoke with Keim, repairs were done under warranty. Vehicle is ready for pick up. ; Return from Keim - Return from Keim Ford: Replaced steering gear Replace EPAS Front end alignment Replace front sway bar link ; Vehicle ready call - Left message with Moscato, vehicle is ready for pick up. ; vehicle pick up - Patrick picked up the vehicle. ; Warranty Work - See attachments for copy of warranty work performed by Jim Keim Ford on 2/15/16.				

WORK ORDER: 126494					
ASSET NUMBER: 30633					
Work Order Status: C - C - Closed				Date In:	03/18/2016
Work Order Shop: 1 - TTM-VehicleRepair				Date Out:	03/22/2016
ASSET NUMBER INFORMATION					
YEAR: 2015	ORG: Active Fleet			TIRE SIZE: Goodyear, 245/55R18	
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic			ENGINE SIZE: 3.7L	
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY			TRANS: 6S Auto	
LICENSE: 30-633	SITE: Columbus, Ohio			FUEL TYPE: U, NFT	
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356			ASSET AVAIL CODE: 0000 to 2359 On Call 24/5	
CLASS: SUV, Patrol, Marked				METERS: Mileage - 25232	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
017-SW7285	NS	1.000	\$23.693	03/22/2016	\$23.693
PART NAME: Switch, Window		REPAIR: General Repair / Glass Component / Switch Window / Replace			
WORK ORDER TOTALS					
TOTAL PARTS:	\$23.693	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:		\$0.000	
TOTAL LABOR:	\$0.000	TOTAL MISC:		\$0.000	TOTAL COST: \$23.693
NOTES					
Window Switch - I. Mike Moscato stopped by and asked me to order a rear passenger window switch. A. Ordered from Jim Keim Ford; ETA: 03/21/2016. ? ; Window Switch - I. Mike Moscato reports B&C will be replacing window switch. A. He stated they broke the switch. ?					

WORK ORDER: 126788					
ASSET NUMBER: 30633					
Work Order Status: C - C - Closed			Date In:	04/06/2016	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	04/08/2016	
ASSET NUMBER INFORMATION					
YEAR: 2015	ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18		
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L		
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto		
LICENSE: 30-633	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: SUV, Patrol, Marked		METERS: Mileage - 26326			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
LAUER	04/06/2016	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform	0.73	\$17.000	
LAUER	04/06/2016	General Repair / Light System / Headlight Assy / Inspect	0.30	\$38.214	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
045-7502	S	1.000	\$4.080	04/06/2016	\$4.080
PART NAME: Filter,Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
0893-0520	S	6.000	\$1.795	04/06/2016	\$10.770
PART NAME: Oil, 5W20, Synthetic Blend, Bulk;1-Qt.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		04/06/2016		\$5.520
MANUAL ADJUSTMENTS					
REASON			CREATED DATE		AMOUNT
Unable to correct headlight issue at this time			04/06/2016		(\$38.210)
WORK ORDER TOTALS					
TOTAL PARTS:	\$14.850	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	(\$38.210)
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$55.214	TOTAL MISC:	\$5.520	TOTAL COST:	\$37.374
NOTES					
PMA, Headlights - Moscato 2-3703 Appointment Time: Wed 4/6/2016 2:00 PM PMA, Headlights Customer reports that the head lights are not even. KEYS YES ; lights - the lights appear to be fine to me, but I am also trying to see them in a bright shop and with daylight outside... -I could get a better evaluation of them in the morning before the sun is up -cant duplicate error -I am more than happy to trouble shoot the issue I just need a low light environment -task complete ; Vehicle pick up - Chuck picked up vehicle.					

WORK ORDER: 128073					
ASSET NUMBER: 30633					
Work Order Status: C - C - Closed			Date In:	04/22/2016	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	05/06/2016	
ASSET NUMBER INFORMATION					
YEAR: 2015	ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18		
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L		
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto		
LICENSE: 30-633	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: SUV, Patrol, Marked			METERS: Mileage - 27999		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
ANDERSON.772	05/05/2016	General Repair / Tires/Wheels / Tire / Replace	1.58	\$134.583	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
017-0166	NS	4.000	\$160.538	05/04/2016	\$642.152
PART NAME: Tire, Firestone Firehawk GT Pursuit		REPAIR: General Repair / Tires/Wheels / Tire / Replace			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		05/05/2016		\$13.460
WORK ORDER TOTALS					
TOTAL PARTS:	\$642.152	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$134.583	TOTAL MISC:	\$13.460	TOTAL COST:	\$790.195
NOTES					
Tire Replacement - Moscato 2-3703 Customer has requested two tires be ordered for his vehicle. ; Vehicle drop off/Tires - Customer has requested four new tires. ; TIRES - REPLACED TIRES AND RESET TPMS ; Vehicle ready call - Left message with Moscato, vehicle is ready for pick up. ; Vehicle pick up - Moscota picked up vehicle.					

WORK ORDER: 128245				
ASSET NUMBER: 30633				
Work Order Status: C - C - Closed			Date In:	05/09/2016
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	05/20/2016
ASSET NUMBER INFORMATION				
YEAR: 2015	ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18	
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L	
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto	
LICENSE: 30-633	SITE: Columbus, Ohio		FUEL TYPE: U, NFT	
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5	
CLASS: SUV, Patrol, Marked			METERS: Mileage - 28064	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
RANKIN.165	05/10/2016	General Repair / Gauge Instrument / LightCheckEngin / Diagnosis	0.24	\$20.046
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$20.046	TOTAL MISC:	\$0.000	TOTAL COST: \$20.046
NOTES				
Check Engine Light - Moscato 2-3703 Walk-in 5/9/2016 10:08:15 AM Check Engine Light ; Ck engine light - Tuesday, May 10, 2016 Diagnose check engine light. After scan code p0138 is present. This is due to a defective bank 1 sensor position 2 O2 sensor , also a code c1b00 for the steering wheel position sensor fault. This vehicle is still under factory warranty and needs to go to the vendor for repairs. Complete. ; Return from Keim - Return from Keim Replaced O2 sensor ; Vehicle ready call - Spoke with Moscato, vehicle is ready for pick up. ; Vehicle pick up - Brandon picked up vehicle.				

WORK ORDER: 128637					
ASSET NUMBER: 30633					
Work Order Status: C - C - Closed			Date In:	06/09/2016	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	06/14/2016	
ASSET NUMBER INFORMATION					
YEAR: 2015	ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18		
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L		
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto		
LICENSE: 30-633	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: SUV, Patrol, Marked			METERS: Mileage - 29380		
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
RANKIN.165	06/09/2016	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform	1.02	\$17.000	
RANKIN.165	06/09/2016	Repaired From PM Service / Engine Air Intake / Filter Air / Replace	0.01	\$1.039	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
045-7502	S	1.000	\$4.080	06/09/2016	\$4.080
PART NAME: Filter,Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
0893-0520	S	6.000	\$1.725	06/09/2016	\$10.350
PART NAME: Oil, 5W20, Synthetic Blend, Bulk;1-Qt.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
0620-0274	S	1.000	\$2.688	06/09/2016	\$2.688
PART NAME: Fluid,Washer,Windshield;1-Gal.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
041-6935	S	1.000	\$8.288	06/09/2016	\$8.288
PART NAME: Filter, Air		REPAIR: Repaired From PM Service / Engine Air Intake / Filter Air / Replace			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		06/10/2016		\$1.800
WORK ORDER TOTALS					
TOTAL PARTS:	\$25.406	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$18.039	TOTAL MISC:	\$1.800	TOTAL COST:	\$45.245
NOTES					
PMA - Mike Moscato 614-588-2373 06/09/2016 1:00Pm Walk In PMA ; PMA - Thursday, June 09, 2016 Perform vehicle PMA service. Tires @ 11/32" all 4 tires. air pressure set @ 35psi Complete. ; Air filter - Thursday, June 09, 2016 Replace dirty engine air filter. Complete. ; Error - ; Vehicle pick up - Vehicle picked up by Moscato.					

WORK ORDER: 130209					
ASSET NUMBER: 30633					
Work Order Status: C - C - Closed			Date In:	10/17/2016	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	10/20/2016	
ASSET NUMBER INFORMATION					
YEAR: 2015	ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18		
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L		
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto		
LICENSE: 30-633	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: SUV, Patrol, Marked		METERS: Mileage - 35645			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
LAUER	10/18/2016	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform	0.22	\$17.000	
LAUER	10/18/2016	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform	0.41	\$0.000	
LAUER	10/18/2016	Repaired From PM Service / Brakes / BrakeJobFront / Replace	0.94	\$80.042	
LAUER	10/18/2016	Repaired From PM Service / Brakes / BrakeJobRear / Replace	1.43	\$121.338	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
0893-0520	S	6.000	\$1.779	10/18/2016	\$10.674
PART NAME: Oil, 5W20, Synthetic Blend, Bulk;1-Qt.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
045-7502	S	1.000	\$4.336	10/18/2016	\$4.336
PART NAME: Filter,Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
013-0075	S	1.000	\$76.557	10/18/2016	\$76.557
PART NAME: Pads, Brake, Front		REPAIR: Repaired From PM Service / Brakes / BrakeJobFront / Replace			
013-0074	S	2.000	\$55.354	10/18/2016	\$110.708
PART NAME: Rotor, Brake, Front		REPAIR: Repaired From PM Service / Brakes / BrakeJobFront / Replace			
013-FT8488	NS	1.000	\$70.746	10/18/2016	\$70.746
PART NAME: Pads, Brake, Rear		REPAIR: Repaired From PM Service / Brakes / BrakeJobRear / Replace			
013-48880686	NS	2.000	\$38.610	10/18/2016	\$77.220
PART NAME: Rotor, Brake, Rear		REPAIR: Repaired From PM Service / Brakes / BrakeJobRear / Replace			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Environmental Charge	Environmental Charge		10/19/2016		\$21.830
WORK ORDER TOTALS					

W300d - WorkOrderDetailsByDate

4/3/2025 12:06:29 PM

TOTAL PARTS:	\$350.241	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$218.380	TOTAL MISC:	\$21.830	TOTAL COST:	\$590.451

NOTES					
Brakes are grinding, PMA, Safety Inspection - Moscato 2-3703 Walk-In 10/17/2016 3:02:05 PM Brakes are grinding, PMA, Safety Inspection KEYS YES ; pma - -drained old oil -removed old oil filter -installed new oil filter -added 6 qtz of oil -requested front/ rear brakes and rotors due to grinding, etc -no other issues to report at this time -task complete ; front brakes/rotors - -removed old brakes and rotors -installed new brakes and rotors -task complete ; rear brakes/ rotors - -removed old rear brakes and rotors -installed new rear brakes and rotors -test drive, no issues -task complete ; Vehicle ready call - I spoke with Moscato, vehicle is ready for pick up. ; customer picked up - Tyler Stewart picked up vehicle.					

WORK ORDER: 130254				
ASSET NUMBER: 30633				
Work Order Status: C - C - Closed			Date In:	10/20/2016
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	10/24/2016
ASSET NUMBER INFORMATION				
YEAR: 2015	ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18	
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L	
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto	
LICENSE: 30-633	SITE: Columbus, Ohio		FUEL TYPE: U, NFT	
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5	
CLASS: SUV, Patrol, Marked			METERS: Mileage - 35695	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
RANKIN.165	10/21/2016	General Repair / Unit Services / Vehicle / Diagnosis	2.61	\$221.732
MANUAL ADJUSTMENTS				
REASON	CREATED DATE		AMOUNT	
Labor credit for re-checking vehicle after repairs	10/21/2016		(\$221.730)	
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: (\$221.730)
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$221.732	TOTAL MISC:	\$0.000	TOTAL COST: \$0.002
NOTES				
Brake and Front Axle Issue, Previous concern from WO#130209 - Moscato 2-3703 Walk-in 10/20/2016 1:44:57 PM Brake and Steering Issue, Previous concern from WO#130209 Customer states: The front axle for car 36 is making thumping noises. Also the new brakes are very soft and when turning onto Kenny Road from OSU PD, the vehicle's wheels would not straighten out when the steering wheel was for a few moments. ; Diag. brake issue - 10/20/2016 Diagnose brake noise issue. After test driving this vehicle I found the brakes are fine but needed burnished in to brake in brake pads. After test drive I found there was no thumping noise associated with the brake system noticed. I did fin there is a bit of tire noise around 40- 60 mph and I feel this is due to air pressure as when I finished my test drive the tire pressure light came on . I adjusted the tire pressures and was unable to re test drive due to weather conditions. I will try again in the AM. ; Diag. vibration - 10/21/2016 ?Adjust tire air pressure's. Perform test drive and found that the vehicle drove like normal. I feel this vehicle is performing as designed. Note: There was damage to the left rear Quarter panel found when vehicle was received. Complete. ; Vehicle ready call - I spoke with Moscato, Vehicle is ready for pick up. ; Vehicle pick up - Patrick picked up vehicle				

NOTES

W300d - WorkOrderDetailsByDate

4/3/2025 12:06:29 PM

Check Engine Light, Steering concern - Moscato 2-3703 Walk-in 11/1/2016 2:50:38 PM Check Engine Light, Steering concern Customer reports that there is an issue with the steering when the customer is turning right. ; Diag. ck eng. lt. - 11/1/2016 Scan system for fault codes, p1450 evp system, p2196,p2198 ,stuck Rich both banks, c1b00 steering sensor .This is going to cause the check engine light to be on and the steering to be affected. Further diagnosis is required. This vehicle was at the dealer for these codes in may and needs to go back for them to correct . Complete. ; Vehicle Update - Vehicle taken to Keim for repair. ; Vendor call - I spoke with Josh, he said that the vehicle is in need of a air filter and purge valve canister. They are still looking into the steering concern. ; Jim Keim - Vehicle is ready for pick up. They could not verify steering concern ; Vehicle update - Vehicle back from Jim keim. ; Pick up - Gave keys to Mike Moscato ; Keim Notes - Return from Keim:

- 1. Diagnose check engine light
- 2. Replace canister purge valve
- 3. Replace air filter
- 4. Reprogram ECM
- 5. Power steering system; Check PSCM and SCCM both pass at this time. No codes in system

WORK ORDER: 144440				
ASSET NUMBER: 30633				
Work Order Status: C - C - Closed			Date In:	06/12/2018
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	08/30/2018
ASSET NUMBER INFORMATION				
YEAR: 2015	ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18	
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L	
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto	
LICENSE: 30-633	SITE: Columbus, Ohio		FUEL TYPE: U, NFT	
OPERATOR:	SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5	
CLASS: SUV, Patrol, Marked			METERS: Mileage - 49709	
WORK ORDER TOTALS				
TOTAL PARTS:	\$0.000	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS: \$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000	
TOTAL LABOR:	\$0.000	TOTAL MISC:	\$0.000	TOTAL COST: \$0.000
NOTES				
Customer concerns - PMA Safety inspection Replace front tires ; Safety inspection - ; PMA - 6/12/2018 ; Tires - .				

WORK ORDER: 149227							
ASSET NUMBER: 30633							
Work Order Status: C - C - Closed			Date In:	06/27/2019			
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	07/02/2019			
ASSET NUMBER INFORMATION							
YEAR: 2015		ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18			
MAKE: Ford		DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L			
MODEL: Police Interceptor SUV		BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto			
LICENSE: 30-633		SITE: Columbus, Ohio		FUEL TYPE: U, NFT			
OPERATOR:		SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5			
CLASS: SUV, Patrol, Marked		METERS: Mileage - 55087					
TECHNICIAN REPAIRS PERFORMED							
TECH	END DATE	REPAIR DESCRIPTION		HOURS	LABOR COST		
KINER	06/28/2019	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform		0.48	\$0.000		
KINER	06/28/2019	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform		0.95	\$17.000		
PARTS ISSUED							
PART NUMBER		S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST	
045-020		S	6.000	\$3.542	06/28/2019	\$21.252	
PART NAME: Oil, 0W20, Synthetic, Bulk; 1-Qt.			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform				
045-7502		S	1.000	\$5.853	06/28/2019	\$5.853	
PART NAME: Filter,Oil			REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform				
MISCELLANEOUS COSTS							
CODE		DESCRIPTION			POSTED DATE	MISC COST	
Environmental Charge		Environmental Charge			06/28/2019	\$1.700	
WORK ORDER TOTALS							
TOTAL PARTS:		\$27.105	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:		\$0.000	SUBLET TAX:		\$0.000		
TOTAL LABOR:		\$17.000	TOTAL MISC:		\$1.700	TOTAL COST:	\$45.805
NOTES							
PMA, Safety Inspection - Moscato 2-3703 Walk-in 6/27/2019 PMA, Safety Inspection Keys Yes ; PMA - PMA completed. ; Vehicle ready email - Emailed Moscato vehicle is ready for pick up. ; Vehicle pick up - Jeff picked up vehicle.							

WORK ORDER: 175121					
ASSET NUMBER: 30633					
Work Order Status: C - C - Closed			Date In:	11/22/2022	
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	11/23/2022	
ASSET NUMBER INFORMATION					
YEAR: 2015	ORG: Active Fleet		TIRE SIZE: Goodyear, 245/55R18		
MAKE: Ford	DEPT: CC12589 - Administration and Planning DPS University Polic		ENGINE SIZE: 3.7L		
MODEL: Police Interceptor SUV	BILL CODE: YYYYYYNNNY1NYY		TRANS: 6S Auto		
LICENSE: 30-633	SITE: Columbus, Ohio		FUEL TYPE: U, NFT		
OPERATOR: Michael Moscato	SERIAL NUMBER: 1FM5K8AR4FGA46356		ASSET AVAIL CODE: 0000 to 2359 On Call 24/5		
CLASS: SUV, Patrol, Marked		METERS: Mileage - 59103			
TECHNICIAN REPAIRS PERFORMED					
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST	
BOROKHOVICH	11/22/2022	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform	0.78	\$17.000	
BOROKHOVICH	11/22/2022	Repaired From PM Service / Cranking System / Battery / Replace	0.77	\$65.215	
BOROKHOVICH	11/23/2022	Preventive Maintenance Service / Preventative Maintenance / Safety Inspection / Perform	1.24	\$0.000	
KAHANA	11/23/2022	Repaired From PM Service / Tires/Wheels / Tire / Replace	0.57	\$48.426	
BOROKHOVICH	11/23/2022	Repaired From PM Service / Tires/Wheels / Tire / Replace	1.93	\$164.380	
PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
007-0100	S	0.500	\$2.970	11/22/2022	\$1.485
PART NAME: Fluid, Washer, Windshield, Bulk; 1-Gal.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
042-0001	S	0.500	\$2.413	11/22/2022	\$1.207
PART NAME: Coolant, Gold, Universal; 50/50; 1-Qt.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
045-7502	S	1.000	\$6.752	11/22/2022	\$6.752
PART NAME: Filter,Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
0081-8465	S	1.000	\$179.338	11/22/2022	\$179.338
PART NAME: Battery:Paratransit/Police		REPAIR: Repaired From PM Service / Cranking System / Battery / Replace			
045-020	S	6.000	\$5.058	11/22/2022	\$30.348
PART NAME: Oil, 0W20, Synthetic, Bulk; 1-Qt.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
017-0220	NS	3.000	\$217.155	11/23/2022	\$651.465
PART NAME: Tire, Firestone Firehawk Pursuit AWT		REPAIR: Repaired From PM Service / Tires/Wheels / Tire / Replace			
017-0220	NS	1.000	\$197.667	11/23/2022	\$197.667
PART NAME: Tire, Firestone Firehawk Pursuit AWT		REPAIR: Repaired From PM Service / Tires/Wheels / Tire / Replace			

W300d - WorkOrderDetailsByDate

4/3/2025 12:06:29 PM

MISCELLANEOUS COSTS								
CODE		DESCRIPTION		POSTED DATE		MISC COST		
Environmental Charge		Environmental Charge		11/23/2022		\$25.000		
WORK ORDER TOTALS								
TOTAL PARTS:		\$1,068.262	PARTS TAX:		\$0.000	MANUAL ADJUSTMENTS:		\$0.000
TOTAL SUBLET:		\$0.000	SUBLET TAX:		\$0.000			
TOTAL LABOR:		\$295.021	TOTAL MISC:		\$25.000	TOTAL COST:		\$1,388.283
NOTES								
PMA/SAFETY - CUSTOMER REQUESTS TO HAVE A PMA SERVICE AND A SAFETY INSPECTION PERFORMED. ; PMA Service/ Safety Inspection - 11/22/2022 Dent on driver rear quarter panel. Battery failed load test. Aired up tires to 36psi. Green oil dye on A/C compressor, looks to have very slight leak. 5/32's remain on left front tire. 6/32's remain on right front and right rear tires. 7/32's remain on left rear tire. Tires are splitting in between the treads, tires need replaced. 245-55-18 103w Firestone Firehawk GT. 8mm remain on brakes all around, has rust build up on rotors from what looks like the vehicle sitting for long periods of time. Complete ; Battery - 11/23/2022 Replaced battery after failing load test during PM service. Complete ; Tires - 11/23/2022 Replaced all four tires due to dry rotting on tires. Set time and date. Complete								

WORK ORDER: 179322				
ASSET NUMBER: 30633				
Work Order Status: C - C - Closed			Date In:	10/23/2023
Work Order Shop: 1 - TTM-VehicleRepair			Date Out:	11/28/2023
ASSET NUMBER INFORMATION				
YEAR: 2015		ORG: Active Fleet	TIRE SIZE: Goodyear, 245/55R18	
MAKE: Ford		DEPT: CC12589 - Administration and Planning DPS University Polic	ENGINE SIZE: 3.7L	
MODEL: Police Interceptor SUV		BILL CODE: YYYYYYNNNY1NYY	TRANS: 6S Auto	
LICENSE: 30-633		SITE: Columbus, Ohio	FUEL TYPE: U, NFT	
OPERATOR: Michael Moscato		SERIAL NUMBER: 1FM5K8AR4FGA46356	ASSET AVAIL CODE: 0000 to 2359 On Call 24/5	
CLASS: SUV, Patrol, Marked			METERS: Mileage - 60581	
TECHNICIAN REPAIRS PERFORMED				
TECH	END DATE	REPAIR DESCRIPTION	HOURS	LABOR COST
GODDARD	10/23/2023	Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform	1.10	\$110.333
GODDARD	10/24/2023	General Repair / Cranking System / Battery / Replace	0.54	\$54.306
GODDARD	10/25/2023	General Repair / Cranking System / Battery / Diagnosis	4.20	\$420.334
BOROKHOVICH	10/25/2023	General Repair / Cranking System / Battery / Diagnosis	0.15	\$14.639

PARTS ISSUED					
PART NUMBER	S/NS	ISS QTY	PART PRICE	ISSUE DATE	TOTAL PART COST
045-020	S	6.000	\$5.599	10/23/2023	\$33.594
PART NAME: Oil, 0W20, Synthetic, Bulk; 1-Qt.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
007-0100	S	0.250	\$3.212	10/23/2023	\$0.803
PART NAME: Fluid, Washer, Windshield, Bulk; 1-Gal.		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
045-7502	S	1.000	\$3.501	10/23/2023	\$3.501
PART NAME: Filter,Oil		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
041-6935	S	1.000	\$13.104	10/23/2023	\$13.104
PART NAME: Filter, Air		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
007-6011G	S	1.000	\$8.785	10/23/2023	\$8.785
PART NAME: Blade, Wiper, 11"		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
007-22PP	S	1.000	\$11.251	10/23/2023	\$11.251
PART NAME: Blade, Wiper, AccuFit, 22"		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
007-26PP	S	1.000	\$13.578	10/23/2023	\$13.578
PART NAME: Blade, Wiper, 26", AccuFit		REPAIR: Preventive Maintenance Service / Preventative Maintenance / PM A Service / Perform			
0081-8465	S	1.000	\$195.735	10/24/2023	\$195.735
PART NAME: Battery:Paratransit/Police		REPAIR: General Repair / Cranking System / Battery / Replace			
2023-1702	NS	1.000	\$45.955	10/25/2023	\$45.955
PART NAME: Connector, Wire, Coil, Ignition		REPAIR: General Repair / Electrical Accessory / Misc Parts / Replace			
MISCELLANEOUS COSTS					
CODE	DESCRIPTION		POSTED DATE		MISC COST
Supply Fee	Supply Fee		10/23/2023		\$30.000
WORK ORDER TOTALS					
TOTAL PARTS:	\$326.306	PARTS TAX:	\$0.000	MANUAL ADJUSTMENTS:	\$0.000
TOTAL SUBLET:	\$0.000	SUBLET TAX:	\$0.000		
TOTAL LABOR:	\$599.612	TOTAL MISC:	\$30.000	TOTAL COST:	\$955.918
NOTES					

W300d - WorkOrderDetailsByDate

4/3/2025 12:06:29 PM

Check charging system/check fir system draw - Customer states that they have had to jump the vehicle several times, please check the battery/charging system. They also requested to see if the vehicle has a parasitic draw, please check. ; Battery Inspect - 10/23/2023 10:54:57 AM Tested battery and charging system batter tested ok but to recharge. Battery would need to have tender on it when not being driven to ensure battery stays up on charge. Recommend installing battery tender. ; PMA - 10/23/2023 12:52:18 PM Performed PMA service, changed oil and filter. Topped off fluids as needed and inspected vehicle for defects. At this time the following repairs are needed Engine air filter Front wipers rear wiper Battery tender install All 4 tires are at 9/32 tread Front brakes are at 9MM rears are at 8MM ; Repairs - 10/23/2023 12:53:47 PM Engine air filter replaced front wipers replaced rear wiper replaced ; Battery re-check - Spoke with Michael Moscato, they have been using the vehicle regularly in Marion, will have tech recheck the battery tomorrow, he noted while on the phone that the MDT light was blinking after sitting, will be if it is timing out as designed or if it has a internal failure. ; Battery - 10/24/2023 10:38:53 AM Retested battery after letting sit overnight and drained to 7 volts again. Replaced battery. ; Battery Draw update - 10/24/2023 3:44:57 PM Did a draw test on battery and while all systems asleep vehicle is still pulling around 10-50 miliamps. Which is enough to slowly drain battery overtime. Found that MDT power light is flashing. Disconnected breaker under hood which turns off accessories and light is still on. Which indicates that the MDT is still drawing power from the battery even with all other systems off. Will need to have sent out or MDT removed when vehicle is not being driven or in service. Also while inspecting wires for any signs of draw found that coil pack connector had wiring repair done on it and wire was exposed and appeared to be chewed through. This is not causing the battery draw issue but can become a drivability concern if left unfixed. Can connect new pigtail to harness and correct previously repaired wires. ; Part ordered - Spoke with tech, pigtail connector was requested and ordered. ; Parts ~ Ignition Coil Wire Connector Delivered - ; Repair Update Coil connector - 10/25/2023 1:16:50 PM Connector came in and attempted to rewire and found that wrong connector was ordered. Found correct one at NAPA and was ordered. Will wire and installed when arrives. ; Wiring Complete - 10/25/2023 3:03:20 PM Rewired new connector and ensured through scanner that repair was good and no misfires were detected. ; Contacted - Contacted Michael Moscato to inform that repairs have been completed.

W300d - WorkOrderDetailsByDate

4/3/2025 12:06:29 PM

REPORT PARAMETERS:

Time Zone:	Eastern Standard Time
Start Date:	08/13/2014
End Date:	04/03/2025
Organization:	All Values
Department:	All Values
Asset Number:	30633
Maint Shop:	All Values
Labor Hours:	Actual Hours
Page Breaks:	Yes
Display Unit Cost or True Cost or Issue Price:	Issue Price

REPORT VERSIONS:

Report Version:	20200729.1200
Script Version:	20210804.1400