**Customer Number: 12289** 

**INVOICE #** 

423354

\*INVOICE\*

## FORT MCMURRAY

238 Macalpine Cres. Fort McMurray, AB T9H 4A6 Phone: (780) 715-1400

GST# 101382109

## MUNICIPALITY OF WOOD BUFFALO 9909 FRANKLIN AVE

FORT MCMURRAY, AB T9H 2K4

Home: 780-743-7000 Bus: 780-370-1379 Page 1 of 2

Cell: Email: accounts.payable@rmwb.ca

SERVICE ADVISOR:

LICENSE KILOMETRES IN/ OUT TAG UNIT# YEAR MAKE/MODEL T18-01 1HTWBAAN99J192954 77924 / 77924 18-01 **INTERNATIONAL 7300** 09 PO NO. **PAYMENT** INV. DATE **OPTIONS:** 

CHG 18NOV24 TOTAL LINE OPCODE TECH TYPE HOURS LIST NET ENGINE HOURS:4955 20-0000 CONTACT

8118 0.00 LABOR:

LABOR:

LABOR:

0.00 OTHER: \*\*\*\*\*\*\*\*\*\*\*\*\*\*\*

0.00

0.00 TOTAL LINE A:

TOTAL LINE C:

0.00 0.00

B WO:0070377 PO:4500055513

20-0000 FILLING

8118 0.00

0.00 OTHER:

0.00 TOTAL LINE B: 0.00 0.00

\*\*\*\*\*\*\*\*\*\*\*\*\*\*\* C DIAG FOR CUSTOMER CONCERN OF CYLINDER MISFIRE AND TURBO SEIZED

12-0000 DIAGNOSED AND REASSEMBLED ENGINE, CUSTOMER DECLINED REPAIRS AT THIS TIME

1 1842655C92 KIT, OIL FILTER SHORT

1 FLT12 FILTER =>8" ENVIRO FEE 130.80 1396.94 OTHER: 1.25

0.00

PARTS: 77924

PARTS:

PARTS:

8118 brought unit in shop and confirmed customer complaint of misfire and turbo charger selector shaft seized, hooked up service tool to unit and performed relative compression test on unit, found unit has a dead cylinder #1, removed intake air filter housing and wiper cowl, removed upper rad support and removed valve cover, removed high pressure oil rail and rocker lever shaft, inspected push rods and valve height, found cylinder 1 exhaust push rod is bent and 1 exhaust valve is sitting high indicating valve seat failure on cylinder #1 that has dropped and damaged piston, cylinder head and exited exhaust damaging turbo charger, reinstalled valve cover and towed unit in yard, made up parts list for rebuild,

8124-customer declined repair and wants unit reassembled, aired up unit and tow in shop, reassembled unit in reverse order, left out cylinder #1 push rods and valve bridges along with leaving injector #1 unplugged incase customer runs engine, parked unit in yard, job

complete

X

## Thank you! for your business.

VENDOR IS DIAMOND INTERNATIONAL TRUCKS LTD. DIAMOND TRUCK CENTRES IS THE TRADEMARK I HEREBY ACKNOWLEDGE INDEBTEDNESS TO DIAMOND INTERNATIONAL TRUCKS LTD. IN THE AMOUNT SHOWN ON THIS INVOICE FOR WORK REQUESTED BY ME.

Visit our website WWW.DIT.CA

TOTALS DESCRIPTION LABOUR AMOUNT PARTS AMOUNT GAS, OIL, LUBE SUBLET AMOUNT MISC. CHARGES **TOTAL CHARGES** LESS INSURANCE SALES TAX **PLEASE PAY** THIS AMOUNT