

For:
REDACTED

Owner: REDACTED**Job Number:**

Written By: REDACTED

Insured: REDACTED

Policy #:

Claim #:

REDACTED

Type of Loss: Collision

Date of Loss: 9/3/2025 12:00 AM

Days to Repair: 0

Point of Impact: 12 Front

Owner:
REDACTED**Inspection Location:**
REDACTED**Repair Facility:**

VEHICLE

2014 TOYO Avalon Hybrid Limited 4D SED 4-2.5L Hybrid Sequential MPI GREY

VIN: 4T1BD1EBXEU025402

Production Date: 2/2014

Interior Color:

License: REDACTED

Odometer: 138,955

Exterior Color: GREY

State: OR

Condition:

TRANSMISSION

Automatic Transmission

POWER

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

Heated Mirrors

Power Driver Seat

Power Passenger Seat

Memory Package

DECOR

Dual Mirrors

Tinted Glass

Rear Power Sunshade

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Keyless Entry

Alarm

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Climate Control

Navigation System

Backup Camera

Home Link

RADIO

Search/Seek

CD Player

Auxiliary Audio Connection

Premium Radio

Satellite Radio

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Front Side Impact Air Bags

Head/Curtain Air Bags

Communications System

Hands Free Device

Rear Side Impact Air Bags

Blind Spot Detection

Bucket Seats

Leather Seats

Heated Seats

Rear Heated Seats

Ventilated Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps

Traction Control

Stability Control

Signal Integrated Mirrors

Xenon or L.E.D. Headlamps

California Emissions

Owner: REDACTED

Job Number:

2014 TOYO Avalon Hybrid Limited 4D SED 4-2.5L Hybrid Sequential MPI GREY

Console/Storage	AM Radio	ROOF
Overhead Console	FM Radio	Electric Glass Sunroof
Wood Interior Trim	Stereo	SEATS

Preliminary Estimate

Owner: REDACTED

Job Number:

2014 TOYO Avalon Hybrid Limited 4D SED 4-2.5L Hybrid Sequential MPI GREY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		INFORMATION LABELS					
2		Rpl information labels				0.3	
3	Repl	AC label 2.5 liter	8872307060	1	2.76	Incl.	
4	Repl	Emission label 2.5 liter	112980V280	1	1.87	Incl.	
5	Repl	Caution label load testing	1128221010	1	3.28	Incl.	
6		FRONT BUMPER & GRILLE					
7		O/H front bumper				2.1	
8	<>	Repl Bumper cover	5211907910	1	285.10	Incl.	2.8
		Note: PARTS: Component comes unprimed from OEM. Preparation is required. See ADD IF REQUIRED operation. LABOR: Time is after sight shield is removed. Time includes R&I grille.					
9		Add for Clear Coat					1.1
10		Add for fog lamps				0.3	
11	Repl	Prep unprimed bumper		1			0.7
12	Repl	RT Side support	5214507030	1	29.09	0.1	
13	Repl	Absorber	5261107040	1	77.16	Incl.	
14	Repl	Impact bar (UHS)	5202107010	1	191.11	0.4	
		Note: WANTED MORE FOR USED					
15	R&I	License bracket				0.2	
16	*	Repl LKQ Upper grille w/hybrid w/o adaptive cruise +25%	5310107070	1	422.50	0.3	
17		Repl Seal to hood	5339507010	1	39.90	0.2	
18	*	Repl LKQ Lower grille +25%	5310207011	1	35.00	Incl.	
19		FRONT LAMPS					
20	Repl	RT Lens & housing	8114507130	1	1,180.63	0.5	
21		Aim headlamps				0.5	
22	Repl	LT Lens & housing	8118507130	1	1,192.61	0.5	
23	R&I	RT Turn signal lamp				0.2	
24	R&I	LT Turn signal lamp				0.2	
25	R&I	RT Fog lamp assy				0.2	
26	R&I	LT Fog lamp assy				0.2	
27		RADIATOR SUPPORT					
28	Repl	Upper tie bar	5321606130	1	118.25	0.9	0.6
29	Repl	LT Upper support	5320307030	1	89.30	s 2.2	S 0.4
30		Add for Clear Coat					0.1
31	*	R&I Distance sensor			m	0.2	M
32	Repl	Sight shield	5329507030	1	196.70	0.2	
33	Repl	LT Side shield 2.5 liter	5329407071	1	104.24	0.1	
34		COOLING					
35	R&I	Reservoir			m	0.3	M
36	Repl	Inverter cooler	G901033031	1	637.55	m 0.7	M
		Note: LABOR: Time is after air cleaner body, upper tie bar, reservoir assembly and bumper reinforcement are removed.					
37		AIR CONDITIONER & HEATER					

Preliminary Estimate

Owner: REDACTED

Job Number:

2014 TOYO Avalon Hybrid Limited 4D SED 4-2.5L Hybrid Sequential MPI GREY

38		Repl	AC Service evacuate & recharge		1	m	1.4	M
39		R&I	Condenser assy			m	0.6	M
40		Repl	AC Service refrigerant recovery		1	m	0.4	M
41	HOOD							
42		Repl	Hood	5330107061	1	546.35	1.5	3.0
43			Overlap Major Non-Adj. Panel					-0.2
44			Add for Clear Coat					0.6
45			Add for Underside(Complete)					1.5
46			Add for Clear Coat					0.3
47	*	Repl	LKQ RT Hinge +25%	5341007010	1	40.00	0.2	0.4
48			Add for Clear Coat					0.1
49	*	Repl	LKQ LT Hinge +25%	5342007010	1	40.00	0.2	0.4
50			Add for Clear Coat					0.1
51		Repl	Latch	5351007020	1	91.30	Incl.	
52		Repl	Front seal	5338107010	1	43.07	Incl.	
53	FENDER							
54		Repl	RT Fender	5381107080	1	240.72	1.7	2.0
55			Overlap Major Adj. Panel					-0.4
56			Add for Clear Coat					0.3
57			Add for Edging					0.5
58			Add for Clear Coat					0.1
59	*	Blnd	LT Fender					<u>1.0</u>
60		R&I	RT Fender liner				Incl.	
61		R&I	LT Fender liner				Incl.	
62		R&I	RT Protector				Incl.	
63		R&I	LT Protector				Incl.	
64		R&I	RT Corner molding				Incl.	
65		R&I	LT Corner molding				Incl.	
66		R&I	LT R&I fender assy				1.6	
67	ELECTRICAL							
68	*	Repl	LKQ Low note horn +25%	86520AA010	1	58.75	0.2	
69		Repl	High note horn	86510AA010	1	98.13	Incl.	
70	ENGINE / TRANSAXLE							
71		R&I	R&I air cleaner body as an assy			m	0.4	M
72	COWL							
73		Repl	RT Side seal	5386607010	1	26.86	0.1	
			Note: PARTS: Part cannot be reused/reinstalled.					
74		Repl	LT Side seal	5386707010	1	24.57	0.1	
			Note: PARTS: Part cannot be reused/reinstalled.					
75	FRONT DOOR							
76	*	Blnd	RT Outer panel					<u>1.0</u>
77		R&I	RT Water shield				0.1	
78		R&I	RT Belt molding				0.3	
			Note: LABOR: Time is after door glass is removed.					
79		Repl	RT Emblem "HYBRID"	7537433090	1	38.90	0.2	

Preliminary Estimate

Owner: REDACTED

Job Number:

2014 TOYO Avalon Hybrid Limited 4D SED 4-2.5L Hybrid Sequential MPI GREY

80	R&I	RT R&I mirror				0.3
81	R&I	RT Door glass Toyota				0.3
82	R&I	RT Handle, outside gray				0.3
83	R&I	RT R&I trim panel				0.4
84	VEHICLE DIAGNOSTICS					
85	*	Rpr	Pre-repair scan	m	0.5	M
86	*	Rpr	Post-repair scan	m	0.5	M
87	MISCELLANEOUS OPERATIONS					
88	*	Repl	Cover car/bag	1	5.00	0.2
89	#	Subl	Hazardous waste removal	1	5.00	X
90	#		Color tint / color match	1		0.5
91	#	Rpr	Color sand and buff			1.0
92	#	Repl	Corrosion protection primer	1	10.00	T 0.3
93	#	Repl	Flex additive	1	8.00	T
94	#	Rpr	Setup & measure			1.0 F
			Note: UPPER ENGINE BAY			
95	#		Clean up recycled part(s)	1		1.0
96	#	Repl	Weld-through primer	1	10.00	T 0.3
97	#		Electrical/wiring/harness masking	1		T 0.2
98	#		Disconnect battery cable	1		0.2
99	#	Rpr	Memory function resets			0.3
SUBTOTALS				5,893.70	25.6	17.9

ESTIMATE TOTALS

Category	Basis			Rate	Cost \$
Parts					5,860.70
Body Labor	17.4 hrs	@		\$ 75.00 /hr	1,305.00
Paint Labor	17.9 hrs	@		\$ 75.00 /hr	1,342.50
Mechanical Labor	5.0 hrs	@		\$ 130.00 /hr	650.00
Frame Labor	1.0 hrs	@		\$ 80.00 /hr	80.00
Structural Labor	2.2 hrs	@		\$ 80.00 /hr	176.00
Paint Supplies	17.9 hrs	@		\$ 50.00 /hr	895.00
Miscellaneous					33.00
Subtotal					10,342.20
Total Cost of Repairs					10,342.20
Deductible					0.00
Total Adjustments					0.00
Net Cost of Repairs					10,342.20

Preliminary Estimate

Owner: REDACTED

Job Number:

2014 TOYO Avalon Hybrid Limited 4D SED 4-2.5L Hybrid Sequential MPI GREY

*** THIS ESTIMATE IS NOT AN AUTHORIZATION FOR REPAIR ***

AUTHORIZATION FOR REPAIRS CAN ONLY BE GRANTED BY THE VEHICLE OWNER.

DO NOT REPAIR THIS VEHICLE UNTIL ALL GUIDELINES LISTED BELOW ARE ACKNOWLEDGED AND ACCEPTED.

FAILURE TO DO MAY RESULT IN ADDITIONAL COST TO THE VEHICLE OWNER.

THIS ESTIMATE REPORT IS BASED ON OUR INITIAL INSPECTION AND DOES NOT COVER ANY ADDITIONAL PARTS OR LABOR WHICH MAY BE REQUIRED AFTER THE VEHICLE IS IN THE REPAIR FACILITY AND IS DISASSEMBLED.

THE REPAIR FACILITY MUST REVIEW AND CONCUR WITH THE SCOPE, METHODOLOGY AND LABOR RATES OF THE REPAIR ESTIMATE BEFORE BEGINNING REPAIRS. OCCASIONALLY ADDITIONAL DAMAGE IS DISCOVERED AFTER

THE VEHICLE IS DISASSEMBLED. IF THIS HAPPENS, IT IS THE REPAIRER'S RESPONSIBILITY TO NOTIFY THE IAS APPRAISER AS SOON AS POSSIBLE AND TO OBTAIN WRITTEN AUTHORITY TO COMPLETE THE ADDITIONAL

REPAIRS NEEDED. ANY SUPPLEMENT WORK MUST BE MADE AVAILABLE FOR INSPECTION BY THE INSURANCE APPRAISER AND APPROVED BY THE HANDLING INSURANCE COMPANY. VERBAL AUTHORIZATIONS BY

THE FIELD APPRAISER ARE NOT BINDING. SUPPLEMENTAL REPAIR REQUESTS PRESENTED AFTER THE COMPLETION OF REPAIRS MAY BE DENIED. ANY SUPPLEMENTAL CHARGES MUST BE SUPPORTED BY

DOCUMENTATION IN THE FORM OF INVOICES, PICTURES AND RECEIPTS FOR THE ENTIRE REPAIR ESTIMATE. THE

DEDUCTIBLE MAY OR MAY NOT BE LISTED ON THE APPRAISAL. ALL DEDUCTIBLES OTHER OWNER

RESPONSIBILITY COST MUST BE COLLECTED FROM THE OWNER BEFORE RELEASING THE VEHICLE.

ALL REPAIRS MUST BE COMPLETED IN ACCORDANCE WITH THE MANUFACTURER'S SPECIFICATIONS AND

RECOMMENDATIONS. IT IS UNDERSTOOD THAT THE REPAIR FACILITY LISTED ON THIS ESTIMATE, IF ONE IS

LISTED, AGREES TO COMPLETE AND GUARANTEE ALL REPAIRS LISTED ON THE ESTIMATE FOR THE AMOUNT

LISTED ON THE ESTIMATE. INSURANCE APPRAISAL SERVICES DOES NOT WARRANT OR GUARANTEE THE WORK

OF ANY OTHER REPAIR FACILITY OR TECHNICIAN AND ASSUME NO RESPONSIBILITY OR LIABILITY FOR THE

QUALITY OF REPAIRS OR WORKMANSHIP OF ANY REPAIR FACILITY OR TECHNICIAN. OREGON LAW PROHIBITS AN

INSURANCE CARRIER FROM REQUIRING A VEHICLE OWNER TO GET REPAIRS AT A PARTICULAR

MOTOR VEHICLE REPAIR SHOP. A VEHICLE OWNER HAS THE RIGHT TO SELECT THE MOTOR VEHICLE REPAIR

SHOP OF THEIR

CHOICE.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF A MOTOR VEHICLE CRASH

PART NOT MADE BY THE ORIGINAL EQUIPMENT MANUFACTURER. THE USE OF A MOTOR

VEHICLE CRASH PART NOT MADE BY THE ORIGINAL EQUIPMENT MANUFACTURER MAY

INVALIDATE ANY REMAINING WARRANTIES OF THE ORIGINAL EQUIPMENT MANUFACTURER

ON THAT MOTOR VEHICLE PART. THE PERSON WHO PREPARED THIS ESTIMATE WILL

PROVIDE A COPY OF THE PART WARRANTY FOR CRASH PARTS NOT MADE BY THE ORIGINAL

EQUIPMENT MANUFACTURER FOR COMPARISON PURPOSES.

OREGON LAW PROHIBITS AN INSURANCE CARRIER FROM REQUIRING A VEHICLE OWNER

TO GET REPAIRS AT A PARTICULAR MOTOR VEHICLE REPAIR SHOP. A VEHICLE OWNER

HAS THE RIGHT TO SELECT THE MOTOR VEHICLE REPAIR SHOP OF THEIR CHOICE.

This is an estimate only and not an authorization to repair or confirmation of coverage. Authorization must come from the vehicle owner. No supplements will be paid without the appraiser's prior approval.

Any person who knowingly presents a false or fraudulent claim for payment of a loss is subject to criminal and civil penalties.

NOTE: YOU HAVE THE RIGHT TO SELECT THE BODY SHOP THAT WILL REPAIR YOUR VEHICLE.

Owner: REDACTED

Job Number:

2014 TOYO Avalon Hybrid Limited 4D SED 4-2.5L Hybrid Sequential MPI GREY

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ARM8518, CCC Data Date 09/02/2025, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Bld=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Owner: REDACTED

Job Number:

2014 TOYO Avalon Hybrid Limited 4D SED 4-2.5L Hybrid Sequential MPI GREY

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
16	LKQ FOSTER AUTO PARTS SALEM LKQ 3871 BOONE RD. SE SALEM OR 97301 (888) 578-5548	#D13182 LKQ Upper grille w/hybrid w/o adaptive cruise +25% Grille LIMITED ,4DR UPPER, VIN D (5TH DIGIT, HYBRID), W/O ADAPTIVE CRUISE S#D13182	\$ 338.00
18	LKQ FOSTER AUTO PARTS SALEM LKQ 3871 BOONE RD. SE SALEM OR 97301 (888) 578-5548	#D13182 LKQ Lower grille +25% Grille LIMITED ,4DR LOWER, ENDS, W/FOG LAMPS,L. S#D13182	\$ 28.00
47	LKQ FOSTER AUTO PARTS SALEM LKQ 3871 BOONE RD. SE SALEM OR 97301 (888) 578-5548	#RF1278 LKQ RT Hinge +25% Hood Hinge, Rt LH,LIMITED,4DR L, L. S#RF1278	\$ 32.00
49	LKQ FOSTER AUTO PARTS SALEM LKQ 3871 BOONE RD. SE SALEM OR 97301 (888) 578-5548	#RF1278 LKQ LT Hinge +25% Hood Hinge, Lt LH,LIMITED,4DR L, L. S#RF1278	\$ 32.00
68	LKQ FOSTER AUTO PARTS SALEM LKQ 3871 BOONE RD. SE SALEM OR 97301 (888) 578-5548	#D13182 LKQ Low note horn +25% Horn LIMITED ,4DR LOW NOTE S#D13182	\$ 47.00