

VEHICLE MAINTENANCE RECORD

BUS #

PAGE #

74

[illegible]

CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 15

PAGE # 13

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
6/1/22		Replace LEFT Rear small tail light	10.00		mol
7/25/22	109354	REPLACE REARWARD Body Control SOL	63.39		Smitty
9/1/22	109366	3 WINDOW STACKERS - L-small STOP BULB - LEFT AXLE SEAL	2173.81		SE
1/1/22		Air fitting LEAKING BACK OF ENG - REPLACE FUEL TANK # STRAPS			Smitty
1/1/22		Rt-FRT MOD FLAP MOUNT - L-R WHEELWELL REPAIR			mol
9/7/22	109388	Replace door switch	114.14		mol
9/27/22	109421	Replace Heated Mirror Switch	97.04		Smitty
11/27/22		Replace Relay for 8way Flasher	11.95		Smitty
12/6/22		Post Trip Inp Relay	11.95		Smitty
12/17/22	109462	REPLACE Child Check Diodes + 3 10AMP BREAKERS for Dome Light	16.42		SB mol
12/13/22	109487	Replace 8way warning indicators	34.01		Smitty
12/20/22	109511	REPLACE DRIVERS Master control VALVE - ELBOW - 8" of 1" HOSE	104.37		SE
2/17/23		2 WIPER BLADES	16.00		SE
4/6/23		Replace Rear Door hold open Support	18.70		Smitty
4/6/23	110692	SEND to COMET GLASS PLUG Rt CORNER windshield	90.00		SE
5/11/23	111820	Replace Fan Clutch (overheating)	560.00		Smitty
5/17/23	111972	Replace side door Front pins & bushings	65.99		mol
5/22/23	112375	Replace DEF Pump	10.00		Smitty
7/19/23	112375	PM LOF - Air Filter - W/F SENT REPAIR	262.29		SE Smitty
11/20/23	113945	Replace Both left brake bulbs	4.00		Smitty

**CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT**

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 15

PAGE # 12

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
8/29/19	100708	Install Shims in 3 E window latches - both rears & LF	20.00		Smitty
9/1/19		REPLACE ZONAR 2010	200.00		SE
9/14/19		Replace 2 way Radio Knob	4.00		mon
11/20/19	103,348	Replace Exhaust Tip & Clamp	74.88		Smitty
12/13/19	104112	Replaces cond & hoses	70.00		mon
2/10/20	105330	3 REAR 8WAY FIXTURES - 4X SEAT BOTTOM 3 - E WINDOW GASKETS	294.71		SE
4/1/20		IN71 Kit - 2 DOOR CLAMPS - 2 STRINGER REPAIRS - Adjust Brakes			MON
4/28/20	106325	L-R BRAKE CHAMBER	45.00		SE
6/12/20	106338	OIL & FILTER FUEL FILTER LUBE	210.00		mon
9/23/20	106345	REPLACE 3 BATT	347.85		SE
10/16/20		Replace WIPER blades	14.00		mon
1/13/21	106433	REPLACE & REPAIR WIRE CHASE PANELS - REPAIR MIRROR MOUNT (L-CROSSOVER)	107.29		SE
1/13/21	106433	WELD CRACK ON TOP OF REAR DIFF	10.00		mon
4/29/21	106735	RTR Boost Pump	136.00		SE
7/13/21	107675	1 SEAT BACK COVER - 2 HOOD CABLES - REFLECTOR - L-R-T TIRE (USED)	136.33		SE SBS mon
8/1/21		FREE UP EXH BRAKE VALVE - SERV. A09			
8/20/21	107687	Install Patch on rear door inner skin	56.80		Smitty
1/21/22	108184	DRIVER SEAT BOTTOM - #9 SEAT RATTLE - R-F FENDER BOLT - UPPER RAD HOSE	136.85		SBS mon SE
3/23/22		Replace both REAR SHOCKS	112.00		mon
4/26/22	108637	L-LARGE BRAKE/TAIL FIXTURES	25.38		SE

CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 15

PAGE # 11

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
4/5/18	89662	L-F marker Bulb - 2x seat back cushions - CLW ENG	535.62		SBS ML
4/11/18		Replace Rear shoes - drums - hardware			
4/17/18	89997	L-R BRAKE Chamber	59.69		SBS
4/24/18					
11/20/18	95153	Replace Rt hood cable & 2 seat forms	104.00		Smithy Mike
12/5/18		Replace Front Air Filter	7.55		na
12/5/18	95516	Replace Rt front tire (take off)			Smithy
12/20/18	95978	oil 2 FILTER, FUEL FILTER Lube light check	210.00		mon
1/1/19		Replace #3 injector - wiring harness - CPM	1,100.00		mon
2/19/19	97185	R-F Flex Brake Hose	14.16		SB
2/19/19		ADD GAL Coolant	6.50		SBS
4/29/19	99167	SEAT FORMS BACKS X4 - 2x ^{BACKS} COVERS - TURN switch - MARKER LIGHTS	554.01		SE mon
1/1/19		PAINT REAR DOOR - PARK BRAKE VALVE - AIR LEAK TOP of COMP			SBS
4/29/19	99167	2 R-R DRIVE TIRES		574.00	SBS
5/13/19	99625	Replace #5 injector & air comp gov 3way fittings	495.54		Smithy
5/31/19		CHILD Child ✓ Switch	24.95		SE
5/31/19		R-F AMBER RED SWAY BULBS - R-R SMALL TAIL BULB - WELD REAR END	385.17		SE mon
1/1/19		Hanging - L-R TIE RODS & BAR - L-R RED SWAY FIXTURE			SBS
5/31/19	100167	PM LOT FUEL Filter	231.10		SBS
8/9/19	100389	FREE UP EXH BRAKE AIR CIL. REPLACE ECLIPS	3.00		SE

**CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT**

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 15

PAGE # 10

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
10/24/16	77673	Replace Bulb left rear lg tail light	1.00		Smitty
11/1/16	77953	Rt Headlight + Retainer	7.52		SE
12/27/16	79290	PM LOF FUEL Filter - W/F - MARKER BULBS + 1 Fixture - REPAIR MANY	222.31		SE
1/1/17		SEAT BACK RATTLES - REBUILD 2nd CRADLE			
12/27/16	79290	2 L-R TIRES		662.00	SE
2/7/17	80159	1 SEAT BACK - L-R AIR BAG - R-R PANCAKE + CLAMP	159.44		Smitty RDC
3/18/17		RECALL #16510 (HORE) CERNI	N/C		SE
3/20/17		add washer - solvent	3.00		Smitty
3/21/17	81199	ADD 1/2 GAL COOLANT	3.22		SE
4/12/17	81555	#18 SEAT BACK foam - R-R marker - Adjust BRAKES - CLEAN ENG	86.00		SE
6/30/17	83343	Replace Tail pipe turn down	75.00		WOC
8/29/17	83648	R-R BOAT PUMP	130.00		SE
10/14/17	84842	ADD 1 GAL COOLANT	6.00		SE
10/12/17		add 1/2 gal	3.00		WOC
10/24/17	85397	Replace EGR Cooler/Plumbing + Dog house	2218.24		Smitty
11/8/17	85883	PM LOF FUEL Filter - W/F - Rt cross over mirror	145.14		Smitty SE
1/1/18		INNER COOLER COOLANT P.P. - Block Heater -			
1/5/18	86978	SEND to WP Williams For TRANS Repair	2000.00		SE
2/20/18	88377	SEAT RATTLES - 1 foam - DOG BONES - Adjust All BRAKES	196.00		SE WOC
3/28/18	89554	Replace R-R lg Brake bulb	2.00		Smitty

**CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT**

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 15

PAGE # 9

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
10/12/15	63487	Replace boster pump	128.00		mol
11/14/15	65297	Replace Intake hose	187.69		Smitty
11/11/15		Replace Front Roof Hatch	248.71		mon
11/17/15	66045	Replace Rt small brake light fixture	7.39		Smitty
11/19/15	66283	PM LCF & Air dryer - replaced air filter	309.49		Smitty Mike Fied
12/8/15	66349	SEND to LAKE TRUCK (NO POWER) WARE	N/C		SE
12/11/16	68001	Replace plug to block HEATER	32.14		mon
2/17/16		Replace wiper blades add washer Fluid	29.00		mol
2/19/16		Replace LEFT head light bulb	3.00		mon
2/23/16	70674	Repair left X-over mirror	0		Smitty
3/30/16	72165	Oil & Filter, Replace Fuel Filter, Lube			
1 1		Replace seat back cover, Repair SEAT.	270.00		mol Smitty
3/31/16		Replace CROSS OVER tube add coolant	59.00		mol
6/7/16	74991	REPAIR SEATS - 5 MARKER Light fixtures - Adjust BRAKES	65.00		SE/mon
1 1		WASH ENG - INNER FENDER LOOSE	48.34		mon
6/14/16	74991	ROE SURP Belt	48.34		mon
6/14/16		towels	6.50		mon
8/16/16	11395	test and Replace batteries	341.85		mon
8/25/16	75481	R-F AMBER SWAY BUDB	3.30		SE
9/16/16	76308	Replace Right side fanny	10.00		mol

CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 15

PAGE # 8

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
1 1		^{1st} Reposition & ^{2nd} replace left rear brake diaphragm & clamp			
12/31/14	48,932		19.50		Smitty
1/17/15	49,151	Repair wiring to washer pump / add coolant & washer solvent	24.50		Smitty
3/13/15		Washer fluid	2.69		SE
3/17/15	53,793	T-30 - replace wiper blades, rt corner rub rail lower secure			Smitty / Mike
1 1		wires in front bumper & left front anti-lock wiring	46.02		Ego
1 1		Replace driver seat bottom	67.41		mc
3/23/15		Repair wiring to Rt Front lights	20.00		mon
4/2/15	54,588	Replace / seat back	44.00		Mike
4/20/15	55,725	Replace Intake Fitting	11.80		Smitty
4/23/15	55,728	Clean DPF - send to Lake Truck	371.04		Smitty
4/24/15	55,800	LAKE TRUCK CLEAN DPF + RECAL.	M/C		SE
5/12/15		Joules	6.50		mc
5/13/15		Joules	6.50		mon
6/24/15	59,566	PM LOF FUEL Filter - SERV. AIRCRAFT	233.18		SE / prior
7/2/15	59,700	Replace Right Rear Tires		480.00	mon
1 1		Replace air Fitting at GOVELOCK			mc
8/21/15		LAKE TRUCK RECALL REFLASH	M/C		SE
10/8/15		Replace Left Front amber bulb	3.30		mc
10/19/15	63,770	BACK Light Fixture	15.60		SE

CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 15

PAGE # 7

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
6/17/14	40335	R-F RED BULB (SWAY)	4.12		SE
6/26/14		Replace Right Top Flare mirror & headlight	21.06		WV
7/22/14	41,251	Repair drivers seat bottom, left squirts hose, & repair many seats			
1/1		& rt stanchion, replace missing screws in ceiling panels & fuel			
1/1		gauge access panel, replace rt sm brake bulb, stop arm label,			
1/1		clean & protect battery & connections, touch up lettering on			
1/1		bus sides, paint wheels & freestuck heater valve, adjust			
1/1		all brakes, replace 1 front cluster bulb & caulk rear bumper body	109.94		Smithy
8/19/20	41917	Oil & Filter, change Fuel Filter, & air dryer Filter	125.00		SE me
9/12/14	43088	Rtl L- HEADLIGHT	7.79		SE
9/17/14		Towels	6.50		Smithy
9/23/14	44431	REPLACE ZONAR 2010 GRADIE	50.00		SE
10/10/14	44704	SEND to LAKE RTR TEMP SENSOR WARR	N/C		SE
10/17/14	45,000	Replace Rtr & rt center marker	13.50		Smithy
11/7/14	46226	Replace left rear brake chamber	63.89		Smithy
11/20/14	47178	Replace both Front Tires		834.90	mon
12/1/14	47468	Replace Right Front Red Eight way bulb	4.14		me
12/8/14		Replace Right Rear Turn Lens & small brake	1.85		mon
12/15/14	48282	REPLACE 2-1157 + 1-1156 BULBS RT REAR	2.97		SE
12/30/14	48922	PM LOF service air dryer	233.10		Smithy, me

CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 15

PAGE # 6

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
11/5/13		TOWELS	6.50		SE
11/13/13		install Blue Sticker	2.20		
12/11/13	32842	Replace antine For 2 way Radio	30.00		mac
1/10/14	33434	1 GAL COOLANT + washer fluid	15.04		SE
1/15/14	33727	Replace heater back cord	51.48		mac
1/21/14		Washer Fluid	2.27		mac
2/12/14	34714	1 GAL COOLANT	12.44		SE
2/27/14		Washer Fluid	2.60		SE
3/18/14	35621	PM LOF - Replace broken bolts in exhaust & bracket holding			Mike
1/1		wiring harness by oil fill	216.30		Smitty
3/13/14		Washer Solvent	2.80		Smitty
3/14/14		BROWN GLOVES	3.50		SE
3/17/14	36217	Replace Fuel filter	50.26		Smitty
3/17/14	36217	Replace Fuel Pump 3600 97	XXXXXX		Smitty
3/24/14		Replace Right Front amber Eight way bulb	4.31		mac
3/21/14		WASHER FLUID + TOWELS	9.10		SE
6/10/14	40111	Repair wiring connection for acc #1 (Blue wire) on back side of Ign			
1/1		switch plug - wire terminal inserted 180° of how others were mounted	0		Smitty
1/1		momentarily dropping power to acc relay #3			
6/15/14		TOWELS	6.50		mac

CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 15

PAGE # 5

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
5/19/13	25295	SEND to LAKE TRUCK REPLACE FUEL HEADER ASSM	N/C		SE
5/19/13	25295	Replace Rt headlight	7.69		Smitty
5/27/13		1 gal washer solvent	2.60		Smitty
6/11/13		Towels	6.50		Smitty
7/10/13		Replace Right Rib Rail in Front of tire, Replace			
1/1		peeling stickers, tighten Right Front shock			
1/1		Bend back body Right side and Rust Proof, Replace			
1/1		FIRE EXT. bracket, wash off Engine & Rear wheels	100.00		mon
2/18/13		Replace Sun Visor	30.00		Luc
7/26/13	27138	RT REAR BRAKE CHAMBER - REPLACE - MARKER Light	111.41		SE
7/26/13	27138	RT DOG BONE	173.47		SE
8/20/13		Broom	9.43		SE
8/27/13		BROWN GLOVES	3.10		SE
9/2/13		REMOVE Kink in FUEL LEAK HOSE			mon
9/10/13	28168	MARKER BULB	.69		SE
9/27/13		TOWELS	6.50		SE
10/3/13	29377	PM LOF SERV. AIR DRYER + FUEL Filter	238.64		SEE Smitty note
10/22/13	30337	Replace bulb for rt midship marker	1.00		Smitty
10/31/13	30735	Warranty @ Lake Truck - throttle control valve & seats RECALL 135	2 N/C		Smitty
10/31/13	30735	Replace both lower brake light bulbs	2.00		Smitty

CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 15

PAGE # 4

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
7/5/12		TOWELS	6.54		EN
7/19/12	13344	AIR DRYER AD9 27 ⁵²	27.52		SL
7/24/12	14455	REFLASH ECM (RECALL) #12913			SL
8/15/12	14705	REPLACE 4 REAR TIRES - HAD 4 GOOD STEER TIRES on it For stock		1060.00	SE
8/20/12		PAPER TOWELS	8.50		SL
8/24/12	14857	9007 BULB (RT SIDE)	6.27		SL
10/1/12	16088	PM LOF	201.27		Smitty
10/4/12	16274	REPLACE AIR FILTER MINOR	16.96		SE
10/12/12		BELT CUTTER	4.02		SE
10/22/12	17185	Return from Lake Truck recall - reflash computer ^{CAMPAIN #} 12927	0		Smitty
12/4/12	18886	L HEADLIGHT	7.69		SE
12/6/12	19039	RTR 1 CLUSTER BULB	.69		SE
1/10/13	20219	Replace horn pad, replace both horns, replace clamp.	62.00		max
1/1/13		top heater hose and cover			
1/18/13	20658	RTR 8WAY MASTER SWITCH (HAD NO PILOT LIGHT)	18.54		SE
2/1/13		WASHER FLUID	2.15		SE
2/21/13	22126	Replace Starter Solenoid & add gal coolant & 1 hose clamp	80.00		Smitty
3/1/13	22493	Replace Starter motor	295.00		Smitty
3/8/13	22794	PM LOF	198.64		Smitty
3/25/13	23547	MARKER BULB	.69		SE

CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 15

PAGE # 3

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
4/11/12	11375	RETURN FROM LAKE TRUCK RUBBER SEAL PARTS FOUND IN	N/C		SB
4/11/12	11375	High PSI oil pump- (WARR) LAKE HAD BUS FROM 3-9-12 TO 4-11-12			
4/13/12	11375	Tighten oil filter + WASH DOWN ENG OIL EVERYWHERE FROM	N/C		SE
1/1		REPAIR AT DEALER - REPAIR AUX FAN SWITCH			
4/16/12		TOWELS	6.50		SB
4/13/12		REMOVE oil filter Found out oil filter came apart			
1/1		REMOVE Rubber in oil passage, change oil and			
1/1		Replace filter, N/C on filter from lake	10/16		meu
1/1		pick up FROM lake 4/12/12, inspected			
1/1		on 4/13/12 oil leak at filter			
4/23/12	11652	2 BULBS	1.00		SB
5/17/12	12590	SEND to CCI (AKAON) FOR ✓ ENG. Light + NO TRANS con.	N/C		SE
1/1		R+R FUEL Pump + filter WARR - NO PROBLEM FOUND w/ TRANS			
5/20/12	12726	AIR MARKER BULBS	.50		SB
6/18/12		TOWELS	6.50		
6/27/12		GLOVES	3.00		SB
6/26/12	13531	SEAT REPAIR, ³⁰⁰ WING NUT FOR 2WAY RADIO SECURE RT. INNER FENDER, PAULK ⁵⁰			
1/1		REAR BUMPER TO BODY RELOCATE RAD. HOSE @ ALT. FRONT SHOCKS			
1/1		#11073 BRAKE KLEIN 10" SNEATH AIR LINE 6100 WHEEL WELLS			
1/1		SCREW @ DOOR REPLACED, SEAL HOLES @ STEF WELL	128.23		

**CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT**

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 15

PAGE # 2

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
12/12/11		Washer FLUID	1.99		SB
12/15/11	9737	AAA 2ats coolant	6 ⁰⁰		gus
12/19/11		Add 1/2 gal coolant	6 ⁰⁰		Smithy
12/22/11	9934	AAA 1/2 gal coolant	6 ⁰⁰		gus
12/28/11		box of towels	6.00		Smithy
12/28/11	10017	Add 1/2 gal coolant + snow brush	14 ⁰⁰		Smithy
1/10/11	10039	Add 1/2 gal coolant	6 ⁰⁰		gus
1/12/11		New Cord	20 ⁰⁰		gus
1/12/11		Snow Brush	9.00		Smithy
1/15/11	10061	ADD 1/2 GAL COOLANT	6.00		SB
1/19/12		Add 1/2 Gall COOLANT	6.00		Mon
1/11/12	10212	ADD GAL COOLANT	12.40		SB
1/13/12		Add 1/2 gal coolant	6.00		Mon
1/18/12	10370	ADD 1 GAL COOLANT	12.44		SE
1/25/12	10433	SEND to LAKE TRUCK for coolant cons. NPF ALSO they			SB
1/27/12		REPLACED A START RELAY?			
2/13/12	10570	Return from Lake Truck / internal EGR leak repaired	WTR		Smithy
2/23/12	11089	Return from Lake Truck - stop arm repair + transaxle	215.50		Smithy
3/19/12		Picked up from Lake Truck for no throttle response + loose headpipe			
1/1		+ returned because still not right			

4 DRBUAA N5CB 399098

CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT

VEHICLE MAINTENANCE RECORD

CLEVELAND HGTS.-UNIVERSITY

HEIGHTS CITY SCHOOLS



57004

VEHICLE # _____

BUS #

15

PAGE # 1

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
11/18/10		Took delivery From Power city	87,00.00		SW
12/22/10		Less Trade	-2500.00		
12/24/10		Install V2J ZONAR	380.00		SE
12/23/10		Towels	6.00		SW
2/7/11	2349	ADD 6 qts TRANS SYN. FLUID	60.00		SE
1/24/11		Northcoast Radio Camers & Radio Install	480.00		SW
2/15/11		WASHER FLUID	2.50		SE
2/22/11	3004	Replace hood cables & repair mirror wiring on both sides	30.00		Smithy
3/15/11	3753	Replace rt midship marker bulb & left rear marker bulb	2.50		Smithy
4/26/11		Towels	6.00		SW
5/19/11		REFLASH RECALL LAKE TRUCK	N/C		SE
6/8/11	6295	SENT TO LAKE COOLANT LEAK. HOSE FROM HOOD	N/C		MO
7/8/11	6474	Tighten rt mirror - LUBE HINGES - Tighten 2 ^{shocks} rear	N/C		SE
8/15/11		Towels	6.00		SW
8/30/11		BROWN GLOVE	3.00		SE
10/7/11		Towels	6.50		MO
10/13/11		1 marker BULB	.39		SW
11/4/11	8546	Tighten UPPER RAD HOSE ADD 1/2 GAL COOLANT	6.00		SE
11/16/11	8890	PM LOF	186.00		Smithy Mike
11/22/11	9057	LF Amber BULB	4.59		SE