D 10521	7	Description: VA	N, CARGO/TRANSIT RWD		
WO ID	WO Description	WO Type ID	WO Status ID	Scheduled Date	Completed Dat
59717	SET UP 2727	S	Completed	3/18/2014	5/6/201
Part Cost	:				
Part ID		Code ID	Code Description	Cost	: -
33	ELECTRICAL TAPE			\$3.37	•
5410	TRAILER CONNECTOR BRKT	Г.		\$1.57	•
5414	TRAILER CONNECTOR			\$9.03	;
5428	TRAILER BOOT			\$1.26	;
			Tota	al Cost: \$15.23	_
Labor Cos	st:				
Craft	Resource				_
MECH	12	40	NEW VEHICLE / SET UP	\$60.00)
MECH	12	40	NEW VEHICLE / SET UP	\$460.00)
MECH	12	40	NEW VEHICLE / SET UP	\$580.00)
MECH	12	40	NEW VEHICLE / SET UP	\$280.00)
MECH	12	40	NEW VEHICLE / SET UP	\$220.00)
MECH	12	40	NEW VEHICLE / SET UP	\$480.00)
MECH	12	40	NEW VEHICLE / SET UP	\$340.00)
MECH	12	40	NEW VEHICLE / SET UP	\$100.00)
MECH	20	40	NEW VEHICLE / SET UP	\$280.00)
			Total	Cost: \$2.800.00	,
Misc Cost	:				
Sublet ID FASTENER	S FASTENERS			\$6.39	-)
FASTENER	S FASTENERS			\$2.73	1
LIGHTS	LIGHTS			\$372.25	i
STROBE	STROBE			\$301.84	+
SWITCH	SWITCH			\$25.58	}
NEW VEHI	CLE / NEW VEHICLE / SET UP	40	NEW VEHICLE / SET UP	\$490.00)
STEP KIT	STEP KIT			\$590.58	1
			Tota	l Cost: \$1,789.37	7

***iMaint**

		Unit Wo	rk Order History			
70579	IS	IS	Closed	7/2	2/2014	8/14/2014
Misc Cost Sublet ID						
WHEEL	WHEEL				\$111.00	
			To	tal Cost:	\$111.00	
71040	PM'S 2727, STEP INOP, REINSTALL SPARE TIRE	PM	Completed	9/2	2/2014	9/3/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
5W30	OIL MOTOR				\$11.76	
WL10010	FILTER				\$2.51	
			To	otal Cost:	\$14.27	
Labor Cost:						
Craft	Resource					
MECH	ZD15	A10	LUBE,OIL,FILTER SERVIC	Œ	\$40.00	
			Tot	tal Cost:	\$40.00	
71040	PM'S 2727, STEP INOP, REINSTALL SPARE TIRE	PM	Completed	9/2	2/2014	9/3/201
Labor Cost:						
Craft	Resource					
MECH	ZD15	A11	SAFETY / PREVENT. MAINTENANCE SERVI <u>CE</u>		\$120.00	
			Tot	tal Cost:	\$120.00	
71040	PM'S 2727, STEP INOP, REINSTALL SPARE TIRE	PM	Completed	9/2	2/2014	9/3/201



		Unit Wor	k Order History		
71040	PM'S 2727, STEP INOP, REINSTA TIRE	LL SPARE PM	Completed	9/2/2014	9/3/2014
Labor Cost:					
<u>Craft</u>	Resource				
MECH	ZD15	37	DIAGNOSTIC	\$80.00	
MECH	ZD19-2	37	DIAGNOSTIC	\$160.00	
Misc Cost _Sublet ID			Total	Cost: \$240.00	
BRACKET	BRACKET			\$26.33	
			Total	Cost: \$26.33	
71432	IS	IS	Completed	10/17/2014	1/9/2015
Misc Cost Sublet ID					
SUBLET / TIRES		СТ	SUBLET / TIRES	\$514.28	
			Total	Cost: \$514.28	
72211	PM'S 2727	PM	Completed	2/11/2015	2/15/2015
Part Cost:					
Part ID		Code ID	Code Description	Cost	
WL10010	FILTER			\$2.51	
5W30	OIL MOTOR	A10-D	LOF DODGE CHARGER	\$11.52	
			Tota	Cost: \$14.03	
Labor Cost:					
Craft	Resource				
MECH	30	A10	LUBE,OIL,FILTER SERVICE	\$20.00	
			Total	Cost: \$20.00	
72211	PM'S 2727	PM	Completed	2/11/2015	2/15/2015
Labor Cost:					
Craft	Resource				
MECH	30	A11	SAFETY / PREVENT. MAINTENANCE SERVI <u>CE</u>	\$60.00	
			Total	Cost: \$60.00	



		Unit Wo	rk Order History			
72211	PM'S 2727	РМ	Completed		2/11/2015	2/15/2015
Labor Cost:						
Craft	Resource					
MECH	30	A30	BRAKE INSPECTION		\$40.00	
			7	Total Cost:	\$40.00	
72509	IS	IS	Completed		3/18/2015	4/6/201
Misc Cost Sublet ID						
SUBLET / TIRES		CT	SUBLET / TIRES		\$131.49	
			-	Total Cost:	\$131.49	
73951	CHECK TIRES 2727	N	Cancelled		8/20/2015	
74217	GATTOS INVOICES	IS	Completed		9/16/2015	9/16/201
Misc Cost Sublet ID						
TIRES	TIRES	CT	SUBLET / TIRES		\$282.98	
			-	Total Cost:	\$282.98	
75807	LIGHT OUT 2727	N	Completed		2/23/2016	2/29/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
SHG7443LL	BULB				\$5.66	
			-	Total Cost:	\$5.66	
Labor Cost:						
Craft	Resource					
MECH	21	06	ELECTRICAL _		\$75.00	
			1	Total Cost:	\$75.00	
77259	PM'S 2727	РМ	Cancelled		3/2/2015	
	PM'S 2727	PM	Cancelled		8/14/2015	

		Unit Wo	rk Order History			
77261	PM'S 2727	PM	Cancelled		2/15/2016	
77262	PM'S 2727	PM	Cancelled		5/10/2016	
77915	PM'S 2727, BRAKE FLUID LOW	PM	Completed		7/6/2016	7/7/201
Part Cost: Part ID		Code ID	Code Description		Cost	
5W30	OIL MOTOR	PMA	·		\$8.10	
70032	BRAKE FLUID	PMA			\$4.87	
100010	OIL FILTER	PMA			\$2.97	
				Total Cost:	\$15.94	
Labor Cost:						
Craft	Resource				<u> </u>	
MECH	15	PMA			\$187.50	
MECH	15	PMA			\$75.00	
				Total Cost:	\$262.50	
77951	TOW TICKETS FOR JUNE 2016	IS	Completed		7/7/2016	7/8/201
Misc Cost _Sublet ID						
WRECKER CLASS B	WRECKER CLASS B	1	TOWING		\$87.75	
b				Total Cost:	\$87.75	
77915	PM'S 2727, BRAKE FLUID LOW	PM	Completed		7/6/2016	7/7/201
Labor Cost:						
Craft	Resource					
MECH	15	PMC	"C" LEVEL PM		\$187.50	
				Total Cost:	\$187.50	



		Unit Wo	rk Order History		
78085	IS	IS	Completed	7/21/2016	7/21/2016
Misc Cost Sublet ID					
REPAIR ACCIDENT DAMAGE	REPAIR ACCIDENT DAMAGE	CA	SUBLET / ACCIDENT	\$309.76	
B/II I/IGE			Total	Cost: \$309.76	
78839	IS	IS	Completed	10/3/2016	10/7/2016
Part Cost: Part ID		Code ID	Code Description	Cost	
179748217	LT225/75R16 MB WRANGLER	12	TIRES	\$146.29	
			Tota	al Cost: \$146.29	
79890	IS	IS	Completed	1/31/2017	3/21/2017
Part Cost:					
Part ID		Code ID	Code Description	Cost	
179748217	LT225/75R16 MB WRANGLER	12	TIRES	\$146.29	
			Tota	al Cost: \$146.29	
80206	TOW TICKETS FOR FEBRUARY 2017	IS	Completed	3/3/2017	3/1/2017
Misc Cost Sublet ID					
WRECKER CLASS A	CLASS A WRECKER	1	TOWING	\$35.00	
^			 Total	Cost: \$35.00	



80217	PM'S 2727	PM	Completed	3/6/2017	3/7/201
Part Cost:					
Part ID		Code ID	Code Description	Cost	
100010	OIL FILTER	PMC	"C" LEVEL PM	\$3.06	
M506	WASHER FLUID	PMC	"C" LEVEL PM	\$1.15	
NP22	WIPER BLADES	PMC	"C" LEVEL PM	\$3.14	
5W20	SYNTHETIC OIL	PMC	"C" LEVEL PM	\$13.44	
7707018	FIRE EXTINGUISHER	PMC	"C" LEVEL PM	\$18.35	
69173	TEK SCREWS	PMC	"C" LEVEL PM	\$0.12	
NP26	WIPER BLADE	PMC	"C" LEVEL PM	\$4.72	
			-	Total Cost: \$43.98	
Labor Cost:					
Craft	Resource				
MECH	23	PMC	"C" LEVEL PM	\$112.50	
			·	Total Cost: \$112.50	
80217	PM'S 2727	PM	Completed	3/6/2017	3/7/201
Part Cost:					
Part ID		Code ID	Code Description	Cost	
FT8972	BRAKE PADS	15	BRAKES	\$65.44	
35032	BRAKE FLUID	15	BRAKES	\$4.22	
			-	Total Cost: \$69.66	
Labor Cost:					
Craft	Resource				
MECH	23	15	BRAKES	\$112.50	
				Total Cost: \$112.50	

		Unit Wo	rk Order History			
80217	PM'S 2727	PM	Completed		3/6/2017	3/7/2017
Part Cost:						
Part ID		Code ID	Code Description		Cost	
68169379AA	DOOR CHECK	29	BODY / PAINT		\$145.03	
				Total Cost:	\$145.03	
Labor Cost:						
Craft	Resource					
MECH	23	29	BODY / PAINT		\$150.00	
				Total Cost:	\$150.00	
81442	BATTERY DEAD 2727	N	Completed		7/26/2017	7/26/2017
Labor Cost:						
Craft	Resource					
MECH	28	07	BATTERY		\$75.00	
				Total Cost:	\$75.00	
81442	BATTERY DEAD 2727	N	Completed		7/26/2017	7/26/2017
Part Cost:						
Part ID		Code ID	Code Description		Cost	
179748217	LT225/75R16 MB WRANGLER	12	TIRES		\$312.50	
				Total Cost:	\$312.50	
Labor Cost:						
Craft	Resource					
MECH	28	12	TIRES		\$37.50	
				Total Cost:	\$37.50	



Unit	Work	Order	History
------	------	-------	---------

82068	PM'S 2727, BRAKE LIGHT ON, CEL ON	PM	Completed		10/2/2017	10/4/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
4800BC	BRAKE CLEANER	PMC	"C" LEVEL PM		\$2.28	
100010	OIL FILTER	PMC	"C" LEVEL PM		\$3.05	
NP22	WIPER BLADES	PMC	"C" LEVEL PM		\$3.14	
M506	WASHER FLUID	PMC	"C" LEVEL PM		\$1.14	
0W20	SYNTHETIC OIL	PMC	"C" LEVEL PM		\$11.52	
NP26	WIPER BLADE	PMC	"C" LEVEL PM		\$4.72	
				Total Cost:	\$25.85	
Labor Cost:	_					
Craft MECH	Resource 23	PMC	"C" LEVEL PM		\$112.50	
				Total Cost:	\$112.50	
32068	PM'S 2727, BRAKE LIGHT ON, CEL ON	PM	Completed		10/2/2017	10/4/201
82068	PM'S 2727, BRAKE LIGHT ON, CEL ON	PM	Completed		10/2/2017	10/4/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
FT8974	BRAKE PADS	15	BRAKES		\$59.52	
				Total Cost:	\$59.52	
Labor Cost:						
Craft	Resource					
MECH	23	15	BRAKES		\$150.00	
				Total Cost:	\$150.00	
32068	PM'S 2727, BRAKE LIGHT ON, CEL ON	PM	Completed		10/2/2017	10/4/201
Labor Cost:						
Craft	Resource					
MECH	23	16	EMISSION SYSTEM		\$150.00	
				Total Cost:	\$150.00	



		Unit Wo	rk Order History		
82068	PM'S 2727, BRAKE LIGHT ON, CEL ON	PM	Completed	10/2/2017	10/4/2017
Labor Cost:					
Craft	Resource				
MECH	17	ADM	ADMINISTRATIVE TIME	\$15.00	
			Tota	al Cost: \$15.00	
83714	IS	IS	Completed	4/16/2018	4/20/2018
Part Cost: Part ID		Code ID	Code Description	Cost	
179748217	LT225/75R16 MB WRANGLER	12	TIRES	\$468.72	
			То	tal Cost: \$468.72	
83995	UNIT#2727 BATTERY	N	Completed	5/24/2018	5/23/2018
Part Cost:					
Part ID		Code ID	Code Description	Cost	
7549	BATTERY	07	BATTERY	\$93.35	
			To	tal Cost: \$93.35	
Labor Cost:					
Craft	Resource				
MECH	28	07	BATTERY	\$112.50	
			Tota	al Cost: \$112.50	

84865	PM'S 2727	PM	Completed	g	9/12/2018	9/11/20
Part Cost:						
Part ID		Code ID	Code Description		Cost	
21C520XB	5W20 FULL SYN QT	PMC	"C" LEVEL PM		\$14.56	
NP26	WIPER BLADE	PMC	"C" LEVEL PM		\$4.72	
NP21	WIPER BLADE	PMC	"C" LEVEL PM		\$3.14	
4800BC	BRAKE CLEANER	PMC	"C" LEVEL PM		\$2.29	
100010	OIL FILTER	PMC	"C" LEVEL PM		\$3.15	
				Total Cost:	\$27.86	
Labor Cost:						
Craft	Resource					
MECH	23	PMC	"C" LEVEL PM		\$112.50	
				Total Cost:	\$112.50	
84865	PM'S 2727	PM	Completed	g	9/12/2018	9/11/20
Part Cost:						
Part ID		Code ID	Code Description		Cost	
68329056AA	BOLT KIT	26	ENGINE		\$13.38	
683222458AA	LEFT MOTOR MOUNT KIT	26	ENGINE		\$232.54	
				Total Cost:	\$245.92	
Labor Cost:	Deserves					
Craft MECH	Resource 23	26	ENGINE		\$300.00	
				Total Cost:	\$300.00	
85769	BACK UP CAMERA AND RADIO DISP 2727	LAY INOP N	Completed	1	1/14/2019	1/14/20
Labor Cost:						
Craft	Resource					
MECH	28	06	ELECTRICAL		\$346.50	
				Total Cost:	\$346.50	



		Unit Wo	rk Order History		
6741	AC INOP , TIRES AMBIENT TEMP NOT READING 2727	N	Completed	6/4/2019	6/6/201
Labor Cost:					
Craft	Resource				
MECH	12	05	AIR CONDITIONING	\$154.00	
			Tot	tal Cost: \$154.00	
6741	AC INOP , TIRES AMBIENT TEMP NOT READING 2727	N	Completed	6/4/2019	6/6/201
Part Cost:					
Part ID		Code ID	Code Description	Cost	
179748217	LT225/75R16 MB WRANGLER	12	TIRES	\$613.44	
			Ti	otal Cost: \$613.44	
Labor Cost:					
Craft	Resource				
MECH	12	12	TIRES	\$19.25	
			To	tal Cost: \$19.25	
6741	AC INOP , TIRES AMBIENT TEMP NOT READING 2727	N	Completed	6/4/2019	6/6/201
6741 Part Cost:	AC INOP , TIRES AMBIENT TEMP NOT READING 2727	N	Completed	6/4/2019	6/6/201
	AC INOP , TIRES AMBIENT TEMP NOT READING 2727	N Code ID	Completed Code Description	6/4/2019 Cost	6/6/201
Part Cost:	AC INOP , TIRES AMBIENT TEMP NOT READING 2727 DRIVER MIRROR				6/6/201
Part Cost: Part ID	READING 2727	Code ID	Code Description	Cost \$174.00	6/6/201
Part Cost: Part ID 5VE99JXWAF	READING 2727 DRIVER MIRROR	Code ID 06	Code Description ELECTRICAL ELECTRICAL	Cost	6/6/201
Part Cost: Part ID 5VE99JXWAF 5149265AB	READING 2727 DRIVER MIRROR	Code ID 06	Code Description ELECTRICAL ELECTRICAL	Cost \$174.00 \$17.00	6/6/201
Part Cost: Part ID 5VE99JXWAF	READING 2727 DRIVER MIRROR	Code ID 06	Code Description ELECTRICAL ELECTRICAL	Cost \$174.00 \$17.00	6/6/201
Part Cost: Part ID 5VE99JXWAF 5149265AB Labor Cost:	DRIVER MIRROR SENSOR	Code ID 06	Code Description ELECTRICAL ELECTRICAL	Cost \$174.00 \$17.00	6/6/201



		Unit Wo	rk Order History			
741	AC INOP , TIRES AMBIENT TEMP NOT READING 2727	N	Completed		6/4/2019	6/6/201
Part Cost: Part ID		Code ID	Code Description		Cost	
68169379AE	DOOR CHECK	29	BODY / PAINT		\$64.57	
68406665AA	SCREW	29	BODY / PAINT		\$1.16	
			- -	Total Cost:	\$65.73	
729	IS JUNE 2019	IS	Completed		6/3/2019	6/30/201
Misc Cost Sublet ID						
ALIGNMENT-	ALIGNMENT	CAB	SUBLET / ALIGNMENT BALANCING	-	\$29.95	
				Total Cost:	\$29.95	
515	PM'S ,A70, A20 ,2727 CLUCK IN FRONT E	END PM	Completed		9/11/2019	9/24/201
Part Cost: Part ID		Code ID	Code Description		Cost	
21E520SB	5W20 FULL SYN QT	PMC	"C" LEVEL PM		\$15.54	
NP26	WIPER BLADE	PMC	"C" LEVEL PM		\$4.72	
4800BC	BRAKE CLEANER	PMC	"C" LEVEL PM		\$4.56	
100010	OIL FILTER	PMC	"C" LEVEL PM		\$3.29	
M506	WASHER FLUID	PMC	"C" LEVEL PM		\$1.66	
NP22	WIPER BLADES	PMC	"C" LEVEL PM		\$3.14	
200304	AIR FILTER	PMC	"C" LEVEL PM		\$19.81	
			-	Total Cost:	\$52.72	
Labor Cost:						
Craft	Resource					
MECH	19	PMC	"C" LEVEL PM		\$192.50	
MECH	31				\$308.00	
			=	Total Cost:	\$500.50	



87515	PM'S ,A70, A20 ,2727 CLUCK IN	N FRONT END PM	Completed	9/11/2019	9/24/201
Part Cost:					
Part ID		Code ID	Code Description	Cost	
TOS18757	PAN GASKET	A20	TRANSMISSION-REAR AXLE SERVICE	\$8.18	
18839	ATP FILTER	A20	TRANSMISSION-REAR AXLE SERVICE	\$12.41	
VV3246	ATF	A20	TRANSMISSION-REAR AXLE SERVICE	\$35.88	
			Total Cost	\$56.47	
Labor Cost: Craft	Resource				
MECH	19	A20	TRANSMISSION-REAR AXLE SERVICE	\$154.00	
			Total Cost:	\$154.00	
87515	PM'S ,A70, A20 ,2727 CLUCK IN	FRONT END PM	Completed	9/11/2019	9/24/20:
87515	PM'S ,A70, A20 ,2727 CLUCK IN	N FRONT END PM	Completed	9/11/2019	9/24/201
Part Cost:					
Part ID		Code ID	Code Description	Cost	
H283	HOSE	10	FRONT END / ALIGNMENTS	\$35.97	
68094813AA	HUB BEARING	10	FRONT END / ALIGNMENTS	\$401.14	
K201722	BUSHING	10	FRONT END / ALIGNMENTS	\$15.80	
K201723	BUSHING	10	FRONT END / ALIGNMENTS	\$10.21	
			Total Cost	\$463.12	
Labor Cost:					
Craft	Resource				
MECH	19	10	FRONT END / ALIGNMENTS	\$154.00	
MECH	19	10	FRONT END / ALIGNMENTS	\$577.50	
MECH	19	10	FRONT END / ALIGNMENTS	\$269.50	
MECH	31	10	FRONT END / ALIGNMENTS	\$308.00	
			Total Cost:	\$1.309.00	

iMaint

		Unit Wo	rk Order History			
87515	PM'S ,A70, A20 ,2727 CLUCK IN FRONT END) PM	Completed		9/11/2019	9/24/2019
Labor Cost: Craft	Resource					
MECH	19	12	TIRES		\$77.00	
			-	Total Cost:	\$77.00	
87515	PM'S ,A70, A20 ,2727 CLUCK IN FRONT END) PM	Completed		9/11/2019	9/24/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
230263	CABIN FILTER	A15	CABIN AIR FILTER		\$39.10	
				Total Cost:	\$39.10	
87515	PM'S ,A70, A20 ,2727 CLUCK IN FRONT END) PM	Completed		9/11/2019	9/24/201
Part Cost:						
Part ID		Code ID	Code Description		Cost	
1ZP75JXWAC	WINDOW SWITCH ASSEMBLY	06	ELECTRICAL		\$54.82	
				Total Cost:	\$54.82	
87431	SEPTEMBER 2019 ISSUE SLIP	N	Completed		9/5/2019	9/30/201
Misc Cost _Sublet ID						
ALIGNMENT	ALIGNMENT	CAB	SUBLET / ALIGNMENT BALANCING		\$49.95	
				Total Cost:	\$49.95	
89604	TRANSMISSION NOT SHIFTING, COOLING FANS,2727	N	Completed		7/20/2020	8/24/202
89710	ISSUE SLIP AUGUST 2020	N	Completed		8/3/2020	8/31/202
Misc Cost _Sublet ID						
WARRANTY	WARRANTY				\$0.00	
				Total Cost:	\$0.00	

iMaint

89604	TRANSMISSION NOT SHIFTING, COOLING FANS,2727	N	Completed		7/20/2020	8/24/202
Part Cost: Part ID		Code ID	Code Description		Cost	
623730	COOLING FAN ASSEMBLY	03	COOLING SYSTEM		\$188.55	
7709346	PUSH MOUNT	03	COOLING SYSTEM		\$3.42	
				Total Cost:	\$191.97	
Labor Cost:						
Craft	Resource					
MECH	19	03	COOLING SYSTEM		\$154.00	
MECH	19	03	COOLING SYSTEM		\$231.00	
				Total Cost:	\$385.00	
9604	TRANSMISSION NOT SHIFTING, COOLING FANS,2727	N	Completed		7/20/2020	8/24/202
Part Cost:					_	
Part ID		Code ID	Code Description		Cost	
TLIF	THIN ION AMBER WHITE	06	ELECTRICAL		\$163.36	
725103	BUTT CONNECTOR	06	ELECTRICAL		\$0.80	
				Total Cost:	\$164.16	
Labor Cost:						
Craft	Resource					
MECH	19	06	ELECTRICAL		\$154.00	
				Total Cost:	\$154.00	
39998	TOW TICKETS AUGUST 2020	N	Completed		9/18/2020	9/21/202
Misc Cost Sublet ID						
WRECKER LT+	TOW PLUS MILEAGE LIGHT VEHICLE				\$46.25	
				Total Cost:	\$46.25	



1208	PM'S 2727, CHECK ENGINE LIGHT	PM	Completed	3/24/2021	3/29/202
Part Cost: Part ID		Code ID	Code Description	Cost	
7651589	GASKET	A20	TRANSMISSION-REAR AXLE SERVICE	\$5.41	
NP26	WIPER BLADE	PMC	"C" LEVEL PM	\$4.96	
24XMVXRB	ATF QT	PMC	"C" LEVEL PM	\$19.26	
21E520SB	5W20 FULL SYN QT	PMC	"C" LEVEL PM	\$23.64	
NP22	WIPER BLADES	PMC	"C" LEVEL PM	\$3.30	
100010	OIL FILTER	PMC	"C" LEVEL PM	\$3.29	
4800BC	BRAKE CLEANER	PMC	"C" LEVEL PM	\$6.84	
68018555.	TRANS FILTER	PMC	"C" LEVEL PM	\$27.72	
			Total Co	st: \$94.42	
Labor Cost:					
Craft	Resource				
MECH	19	PMC	"C" LEVEL PM	\$154.00	
			Total Cost	: \$154.00	
1208	PM'S 2727, CHECK ENGINE LIGHT	PM	Completed	3/24/2021	3/29/20
Labor Cost:					
Craft	Resource				
MECH	19	A20	TRANSMISSION-REAR AXLE SERVICE	\$115.50	
MECH	19	A20	TRANSMISSION-REAR AXLE SERVICE	\$77.00	
MECH	19	A20	TRANSMISSION-REAR AXLE SERVICE	\$231.00	
			Total Cost	: \$423.50	
1208	PM'S 2727, CHECK ENGINE LIGHT	PM	Completed	3/24/2021	3/29/202
1208	PM'S 2727, CHECK ENGINE LIGHT	PM	Completed	3/24/2021	3/29/20
2480	DEAD BATTERY, ENGINE NOISE TICKING, 2727	N	Completed	9/20/2021	9/29/20

**iMaint*

		Unit Wo	rk Order History			
92480	DEAD BATTERY, ENGINE NOISE TICKIN 2727	IG, N	Completed		9/20/2021	9/29/202
Labor Cost:						
Craft	Resource					
MECH	33	26	ENGINE	Total Cost:	\$423.50 \$423.50	
25.75	DEAD DATTEDY ENGINE TICK 2727	NI NI	Commission	Total Cost.		10/4/20
92575	DEAD BATTERY, ENGINE TICK, 2727	N	Completed		10/1/2021	10/4/20
Part Cost: Part ID		Code ID	Code Description		Cost	
B8H8F001AA	BATTERY	07	BATTERY		\$200.44	
				Total Cost:	\$200.44	
Labor Cost:						
Craft	Resource					
MECH	33	07	BATTERY		\$38.50	
				Total Cost:	\$38.50	
92575	DEAD BATTERY, ENGINE TICK, 2727	N	Completed		10/1/2021	10/4/20
Part Cost:		C- 1- ID	Code Describition		Cont	
Part ID		Code ID	Code Description		Cost	
5184562AC	GASKETS	26	ENGINE		\$26.64	
68240667AC	MANIFOLD	26	ENGINE		\$413.53	
68105583AG	OIL COOLER	26	ENGINE		\$272.80	
68160278AC	TUBE	26	ENGINE		\$23.12	
				Total Cost:	\$736.09	
Labor Cost:						
Craft	Resource					
MECH	33	26	ENGINE		\$269.50	
MECH	33	26	ENGINE		\$154.00	
MECH	33	26	ENGINE		\$154.00	
				Total Cost:	\$577.50	



Unit	Work	Order	History
------	------	-------	---------

93496	PM'S 2727	PM	Completed	2.	/22/2022	2/22/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
WA10304	AIR FILTER	PMC	"C" LEVEL PM		\$25.85	
100010	OIL FILTER	PMC	"C" LEVEL PM		\$3.73	
21E520SB	5W20 FULL SYN QT	PMC	"C" LEVEL PM		\$23.64	
				Total Cost:	\$53.22	
Labor Cost:	_					
Craft MECH	Resource 37	PMC	"C" LEVEL PM		\$0.00	
MECH	3/	PMC	C LEVEL PM	Total Cost:	\$0.00	
93496	PM'S 2727	PM	Completed		/22/2022	2/22/20
93496	PM'S 2727	PM	Completed	2.	/22/2022	2/22/20
93496	PM'S 2727	PM	Completed	2.	/22/2022	2/22/20
Part Cost: Part ID		Code ID	Code Description		Cost	
179748622	LT225/75R16 WRANGLER	12	TIRES		\$357.96	
	·			Total Cost:	\$357.96	
93559	IS	PM	Completed		3/2/2022	3/4/20
Part Cost: Part ID		Code ID	Code Description		Cost	
179748622	LT225/75R16 WRANGLER	12	TIRES		\$357.96	
				Total Cost:	\$357.96	
93794	2727 TRANS NOT SHIFTING	N	Completed		4/4/2022	4/5/20
Labor Cost:						
Craft	Resource					
MECH	33	22	TRANSMISSION / CLU		\$154.00	
MECH	33	22	TRANSMISSION / CLU	JTCH	\$77.00	
				Total Cost:	\$231.00	

≽iMaint

		Unit Wo	rk Order History			
4180	SERVICE TICKET, JUNE 2022	N	Completed		5/31/2022	6/30/20
Misc Cost Sublet ID						
TAG	TAG			Total Cost:	\$33.93 \$33.93	
5922	PM'S 2727, PASSENGER WINDOW INOP, RADIO INOP	PM	Completed		2/8/2023	2/16/20
Part Cost:						
Part ID		Code ID	Code Description		Cost	
100010	OIL FILTER	PMC	"C" LEVEL PM		\$4.19	
75749	5W20 SYN OIL	PMC	"C" LEVEL PM		\$21.42	
				Total Cost:	\$25.61	
Labor Cost: Craft	Resource					
MECH	33	PMC	"C" LEVEL PM		\$115.50	
				Total Cost:	\$115.50	
5922	PM'S 2727, PASSENGER WINDOW INOP, RADIO INOP	PM	Completed		2/8/2023	2/16/20
Part Cost: Part ID		Code ID	Code Description		Cost	
68401986AC	REGULATOR	32	GLASS / INTERIOR		\$165.00	
68462445AA	HARNESS	32	GLASS / INTERIOR		\$84.35	
NP22	WIPER BLADES	32	GLASS / INTERIOR		\$3.52	
M506	WASHER FLUID	32	GLASS / INTERIOR		\$2.55	
NP26	WIPER BLADE	32	GLASS / INTERIOR		\$4.76	
				Total Cost:	\$260.18	
Labor Cost: Craft	Resource					
MECH	33	32	GLASS / INTERIOR	_	\$77.00	
MECH	33	32	GLASS / INTERIOR		\$77.00	
MECH	33	32	GLASS / INTERIOR		\$77.00	
				Total Cost:	\$231.00	

iMaint

	·					
		Unit Wo	rk Order History			
95922	PM'S 2727, PASSENGER WINDOW INOP, RADIO INOP	PM	Completed	2/8/202	3	2/16/202
Labor Cost:						
Craft	Resource					
MECH	33	06	ELECTRICAL	\$	115.50	
MECH	33	06	ELECTRICAL	\$	231.00	
MECH	33	06	ELECTRICAL	\$	385.00	
			5	Fotal Cost: \$	731.50	
95922	PM'S 2727, PASSENGER WINDOW INOP, RADIO INOP	PM	Completed	2/8/202	3	2/16/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
CAF9954	CABIN FILTER	A15	CABIN AIR FILTER		15.39	
			-	Total Cost:	15.39	
Labor Cost:						
Craft	Resource					
MECH	33	A15	CABIN AIR FILTER	!	\$38.50	
			7	Fotal Cost:	\$38.50	
95991	IS	PM	Completed	2/20/202	3	2/24/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
6FK52LXFAA	RADIO	06	ELECTRICAL	\$3	302.50	
FREIGHT	FREIGHT			9	19.25	
			-	Total Cost: \$3	321.75	



5257	INSTALL NEW RADIO, 2727	N	Completed		4/3/2023	4/4/202
Part Cost:						
Part ID		Code ID	Code Description		Cost	
7443N	BULB	06	ELECTRICAL		\$2.20	
6MJ97ZZZ	CAMERA	06	ELECTRICAL		\$268.68	
				Total Cost:	\$270.88	
Labor Cost:						
Craft	Resource					
MECH	33	06	ELECTRICAL		\$115.50	
MECH	33	06	ELECTRICAL		\$77.00	
				Total Cost:	\$192.50	
5589	2727 COOLING FAN RUNS AFTER SHUT DOWN	N	Completed	5	/25/2023	5/26/20
Part Cost:						
Part ID		Code ID	Code Description		Cost	
85533011	RELAY	06	ELECTRICAL		\$85.22	
				Total Cost:	\$85.22	
Labor Cost:						
Craft	Resource					
MECH	33	06	ELECTRICAL		\$154.00	
MECH	33	06	ELECTRICAL		\$77.00	
				Total Cost:	\$231.00	
7277	COOLING FAN VIBRATION , 2727	N	Completed	9	/12/2023	9/13/20
Part Cost:						
Part ID		Code ID	Code Description		Cost	
77011431	DUAL FAN ASSEMBLY	03	COOLING SYSTEM		\$243.23	
				Total Cost:	\$243.23	
Labor Cost:						
Craft	Resource					
MECH	33	03	COOLING SYSTEM		\$77.00	
MECH	33	03	COOLING SYSTEM		\$77.00	
				Total Cost:	\$154.00	

iMaint

Report ID: 1111

		Unit Wo	rk Order History		
576	COOLING FANS STAYING ON, 2727	N	Completed	11/8/2023	11/9/202
Labor Cost:					
Craft	Resource				
MECH	33	03	COOLING SYSTEM	\$41.50	
MECH	33	03	COOLING SYSTEM	\$83.00	
			•	Total Cost: \$124.50	
576	COOLING FANS STAYING ON, 2727	N	Completed	11/8/2023	11/9/20
Part Cost:					
Part ID		Code ID	Code Description	Cost	
68094656	RELAY	06	ELECTRICAL	\$131.18	
FREIGHT	FREIGHT			\$15.00	
			•	Total Cost: \$146.18	
782	PM'S 2727, BROKE DRIVER SIDE BRAKE LIGHT	PM	Completed	5/6/2024	5/10/202
Part Cost:		0 1 70			
Part ID		Code ID	Code Description	Cost	
NP22	WIPER BLADES	PMC	"C" LEVEL PM	\$3.75	
100010	OIL FILTER	PMC	"C" LEVEL PM	\$4.11	
NP26	WIPER BLADE	PMC	"C" LEVEL PM	\$5.06	
AF99079	AIR FILTER	PMC	"C" LEVEL PM	\$17.59	
1SENSORM	SENSOR	PMC	"C" LEVEL PM	\$19.80	
75749	5W20 SYN OIL	PMC	"C" LEVEL PM	\$16.44	
CAF9954	CABIN FILTER	PMC	"C" LEVEL PM	\$15.39	
			•	Total Cost: \$82.14	
Labor Cost:					
Craft	Resource				
MECH	38	PMC	"C" LEVEL PM	\$207.50	
			•	Total Cost: \$207.50	



		Unit Wo	rk Order History		
8782	PM'S 2727, BROKE DRIVER SIDE BRAKE LIGHT	РМ	Completed	5/6/2024	5/10/202
Labor Cost:					
Craft	Resource				
MECH	38	AB	ABUSE	\$373.50	
MECH	38	AB	ABUSE	\$124.50	
			Tot	al Cost: \$498.00	
8782	PM'S 2727, BROKE DRIVER SIDE BRAKE LIGHT	PM	Completed	5/6/2024	5/10/202
Part Cost:					
Part ID		Code ID	Code Description	Cost	
4725947AD	TAIL LAMP ASSY	06	ELECTRICAL	\$225.78	
11005N	BULB	06	ELECTRICAL	\$0.84	
725255	BUTT CONNECTOR	06	ELECTRICAL	\$0.82	
7443N	BULB	06	ELECTRICAL	\$5.00	
			To	otal Cost: \$232.44	
8782	PM'S 2727, BROKE DRIVER SIDE BRAKE LIGHT	PM	Completed	5/6/2024	5/10/202
Part Cost:					
Part ID		Code ID	Code Description	Cost	
4800BC	BRAKE CLEANER	15	BRAKES	\$19.85	
AR8393SCR	ROTORS	15	BRAKES	\$112.58	
AR8394SCR	ROTORS			\$115.86	
TD1540M	BRAKE PADS	15	BRAKES	\$30.42	
TD1746M	PADS	15	BRAKES	\$27.13	
AR8395SCR	ROTOR	15	BRAKES	\$122.10	
			To	otal Cost: \$427.94	
Labor Cost:					
Craft	Resource				
MECH	38	15	BRAKES	\$249.00	
MECH	38	15	BRAKES	\$249.00	
MECH	38	15	BRAKES	\$249.00	
			Tot	al Cost: \$747.00	

≽iMaint

		Unit Wo	rk Order History			
98782	PM'S 2727, BROKE DRIVER SIDE BRAKE LIGHT	PM	Completed		5/6/2024	5/10/2024
Part Cost: Part ID		Code ID	Code Description		Cost	
	COOLANT					
RTU1EXT	COOLANT	03	COOLING SYSTEM	Total Cost:	\$8.35 \$8.35	
98782	PM'S 2727, BROKE DRIVER SIDE BRAKE LIGHT	PM	Completed		5/6/2024	5/10/2024
Part Cost:						
Part ID		Code ID	Code Description		Cost	
1337023R	STRUT	44	SUSPENSION		\$208.99	
1337023L	STRUT	44	SUSPENSION		\$208.99	
				Total Cost:	\$417.98	
Labor Cost: Craft	Resource					
MECH	38	44	SUSPENSION		\$166.00	
MECH	38	44	SUSPENSION		\$332.00	
				Total Cost:	\$498.00	
98782	PM'S 2727, BROKE DRIVER SIDE BRAKE LIGHT	PM	Completed		5/6/2024	5/10/202
Labor Cost:						
Craft	Resource					
MECH	38	A15	CABIN AIR FILTER		\$83.00	
				Total Cost:	\$83.00	
98782	PM'S 2727, BROKE DRIVER SIDE BRAKE LIGHT	PM	Completed		5/6/2024	5/10/202
Labor Cost:						
Craft	Resource					
MECH	38	12	TIRES		\$83.00	
MECH	38	12	TIRES		\$83.00	
MECH	38	12	TIRES		\$166.00	
				Total Cost:	\$332.00	



Unit Work Order History						
98950	IS	PM	Completed	6/	3/2024	6/7/2024
Part Cost: Part ID		Code ID	Code Description		Cost	
131748875	LT2257516 GOODYEAR	12	TIRES		\$181.56	
131748875	LT2257516 GOODYEAR	12	TIRES		\$181.56	
			To	otal Cost:	\$363.12	
99715	IS	PM	Completed	10/	7/2024	10/11/2024
Part Cost:						
Part ID		Code ID	Code Description		Cost	
NP22	WIPER BLADES	32	GLASS / INTERIOR		\$3.75	
NP26	WIPER BLADE	32	GLASS / INTERIOR		\$5.06	
			To	otal Cost:	\$8.81	
nit Totals:						
otal Number of Work O	rders: 93					
tal Labor Costs:	\$14,570.25					
tal Part Costs:	\$8,451.94					
al Sublet	\$3,448.04					
tal Costs:	\$26,470.23					

Cita	Tota	lc:
3116	IOIA	•

 Total Number of Work Orders:
 93

 Total Labor Costs:
 \$14,570.25

 Total Part Costs:
 \$8,451.94

 Total Sublet
 \$3,448.04

 Total Costs:
 \$26,470.23



Report Totals:

 Total Number of Work Orders:
 93

 Total Labor Costs:
 \$14,570.25

 Total Part Costs:
 \$8,451.94

 Total Sublet
 \$3,448.04

 Total Costs:
 \$26,470.23

Filter:

Unit id begins with '105217'

