

Maintenance Log GSD*223

| ID | ID | Date | Description | By | Cost |
|-----|----|------------|--|----------------|------------|
| 41 | 16 | 10/03/2012 | 8 FUEL INJECTORS | Rons Truck | \$3,439.60 |
| 42 | 16 | 10/03/2012 | VALVE COVER | RON'S TRUCK | \$119.62 |
| 43 | 16 | 10/03/2012 | FUEL FILTER | RON'S TRUCK | \$64.27 |
| 44 | 16 | 10/03/2012 | OIL FILTER | RON'S | \$29.75 |
| 45 | 16 | 10/03/2012 | OIL QUART | RON'S | \$57.00 |
| 46 | 16 | 10/03/2012 | WIPER BLADES | RON'S | \$39.80 |
| 47 | 16 | 10/03/2012 | RIGHT FRONT SWAY BAR | RON'S | \$131.29 |
| 48 | 16 | 10/03/2012 | LEFT SWAY BAR | RON'S | \$131.29 |
| 49 | 16 | 10/03/2012 | SWAY BAR BUSHINGS | RON'S | \$25.88 |
| 50 | 16 | 10/03/2012 | LABOR | RON'S | \$910.00 |
| 65 | 16 | 01/02/2013 | Stobe power assembly, freight, strobe l.e.d. | Ron's | \$533.18 |
| 75 | 16 | 02/19/2013 | OIL CHANGE/NEXT CHANGE 39,500 | DAVE R***** | \$70.15 |
| 89 | 16 | 03/28/2013 | REPLACED STEERING BOX AND PITMAN ARM. | CARANFA | \$1,363.21 |
| 102 | 16 | 07/24/2013 | Replaced wiper motor and blades | Ron's | \$436.29 |
| 105 | 16 | 08/12/2013 | Replaced upper and lower ball joints, hub seals, | Caranfa | \$1,270.70 |
| 149 | 16 | 02/14/2014 | Replaced hydraulic line. | D.R. | \$122.25 |
| 150 | 16 | 02/20/2014 | Replaced rear driverside strobe. | D.R. | |
| 153 | 16 | 03/07/2014 | Replaced radiator, upper and lower hose, water | Ron's | \$1,697.94 |
| 184 | 16 | 10/07/2014 | Changed oil and fuel filter. | Dan M***** | \$70.15 |
| 185 | 16 | 10/16/2014 | Repaired short in turn signals. | Wright Motors | \$96.73 |
| 208 | 16 | 01/26/2015 | REPLACED AIR FILTER RESTRICTION GAUGE, | RON'S | \$647.54 |
| 232 | 16 | 03/20/2015 | REPLACED #4 FUEL INJECTOR | RON'S | \$817.91 |
| 248 | 16 | 06/18/2015 | Replaced map sensor, changed oil 43,046 | RON'S | \$474.64 |
| 251 | 16 | 07/30/2015 | Replaced exhaust pressure sensor, mass air flow | RON'S | \$1,137.36 |
| 254 | 16 | 10/06/2015 | Removed and cleaned turbo charger | Baker | \$305.88 |
| 255 | 16 | 10/07/2015 | Lack of power cleaned map sensor hose program | Baker | \$103.01 |
| 260 | 16 | 11/23/2016 | Replaced both batteries | Dan S***** | \$279.78 |
| 296 | 16 | 11/28/2016 | Replaced all six tires | East Side Tire | \$1,252.64 |
| 355 | 16 | 12/11/2017 | REPLACED 4 FUEL INJECTORS AND FUEL FILTER | BAKER AUTOM | \$1,663.96 |
| 511 | 16 | 12/20/2019 | REPLACED BOTH BATTERIES | AUTOZONE | \$269.98 |
| 517 | 16 | 01/27/2020 | REMOVE/REPLACE RADIATOR AND CAP | RUSH REPAIR | \$489.95 |
| 518 | 16 | 01/27/2020 | CALL OUT TO GSD, NOT STARTING NEEDS FUEL | RUSH REPAIR | \$194.50 |
| 525 | 16 | 02/27/2020 | REMOVED WIRING HARNESS FOR PLOW | RUSH REPAIR | \$150.00 |
| 532 | 16 | 03/26/2020 | REPLACED MINI FUSE FOR WINDSHIELD WIPERS | RUSH REPAIR | \$48.49 |
| 538 | 16 | 06/12/2020 | CHANGED OIL, AIR FILTER, AND FUEL FILTER | JOHN B***** | \$226.31 |
| 465 | 16 | 03/05/2019 | REPLACE EGR COOLER | RUSH REPAIR | \$978.32 |
| 578 | 16 | 01/16/2021 | Replaced both front brake calipers and pads | RUSH REPAIR | \$489.64 |
| 594 | 16 | 05/03/2021 | Replaced turbocharger/hardware, high pressure | RUSH REPAIR | \$3,248.68 |
| 666 | 16 | 07/18/2022 | Replaced head gaskets/studs, resurfaced heads, | RUSH REPAIR | \$4,967.62 |
| 672 | 16 | 08/04/2022 | replaced rear brakes/rotors | RUSH REPAIR | \$655.78 |
| 675 | 16 | 10/26/2022 | Replaced front steering stabilizer, LF/RF | RUSH REPAIR | \$1,167.09 |
| 684 | 16 | 10/26/2022 | Replaces fuel pressure regulator/pigtail, fuel | RUSH REPAIR | \$1,398.38 |
| 697 | 16 | | CHANGED OIL 59,501 | | |
| 713 | 16 | 03/15/2023 | REPLACED BOTH UPPER/LOWER BALL JOINTS, U | RUSH REPAIR | \$1,175.08 |
| 714 | 16 | 01/23/2023 | REPLACED FRONT TIMING COVER | RUSH REPAIR | \$1,129.36 |
| 760 | 16 | 02/20/2024 | Replaced rear taillights, lf headlight bulb, front | RUSH REPAIR | \$1,208.50 |
| 771 | 16 | 04/08/2025 | Replaced section of RR brake line | RUSH REPAIR | \$296.92 |
| 827 | 16 | 07/28/2025 | Replaced section of left side brake line | RUSH REPAIR | \$653.58 |
| 861 | 16 | 12/23/2025 | Replaced both batteries (63,950 mi.) | COLE M***** | \$321.68 |