

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
47894	02862	47894	INSERVICE
49077	02862	49077	PMA*GS
50057	02862	50057	pma*gs
50173	02862	50173	Accident damage*hit at fraze 11/15/2002*gs repair est.\$1974.72 state farm ins.*gs dropped off and picked up by parks*gs SUBLET-REPAIR ACCIDENT DAMAGE(STATE FARM)/EDB
51798	02862	51798	PMA/J
53630	02862	53630	pma*gs
54430	02862	54430	remove decals*gs
55205	02862	55205	CHECK ENGINE LIGHT ON TRANSMISSION SEEMS TO BE NOT SHIFTING PROPERLY/J SUBLET-SENT TO VOSS DODGE, RAN DIAGNOSTIC TESTS, REPLACED GOVERNOR PRESSURE TRANSDUCER/EDB
55715	02862	55715	PMA/J
59309	02862	59309	PMA CHECK LEFT FRONT WHEEL FOR SQUEAKING NOISE/J
60943	02862	60943	pma ron heard noise in left front wheel-may be backing plate??/j Installed new front brake pads*rc
62151	02862	62151	pma*install cab strobe*gs SERVICED INSTALLED CAB STROBE

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
62639	02862	62639	speedometer quit working, airbag light came on, abs light came on, it would not shift properly. After shutting it off for a while, all the lights were out and it is running fine now/j ck tires need replaced?*gs installed (4) new tires*rc
64533	02862	64533	PMC*gs
65478	02862	65478	r&r wiper blades/j ISSUED ON FWI#I210917*KC
66594	02862	66594	pma/j installed new front brake pads & rotors*rc
66725	02862	66725	Wrong unit # see 03852*gs
67382	02862	67382	PMA**something grinding - possible rear brakes?/jREPLACED REAR PADS & ROTORS BRAKE PADS METAL TO METAL , DU TO SLIDES HANGING UP on left rear , oil & filter change & replaced serpinteen belt cracked H.K
69357	02862	69357	pma/j oil lube filter C/K over checked a/c ok H.K.*
69903	02862	69903	tail light out/j replaced left rear brake light out replaced 2 bulbs in 3rd brake light H.K.*
70248	02862	70248	pma/j call barry sanders when ready at 2486/j pma done air filter installed replace 2 bulbs M.M
71890	02862	71890	pma service done aired tires topped all fluids. ft brakes need replaced ordered parts per ed b. air filter ok . SHOULD BE IN FRIDAY M.M
71919	02862	71919	needs new brakes/j rnnr ft brakes and install new front pads and rotors M.M

W337 - Work Order Notes

01/01/2001 TO 07/21/2025

7/21/2025 7:12:44 AM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
72615	02862	72615	ck no steering belt off . found waterpump bearing failure. rnr water pump install new belt and refill cooling system. also oe battery marginal shape installed new battery and performed battery service clean and protect terminals . M.M
73033	02862	73033	PMA*gs pma service done topped fluids aired tires. M.M
73326	02862	73326	SC*nail in rt rear tire*gs REPAIRED RIGHT REAR TIRE PLUGGED TIRE H.K.*
73561	02862	73561	no heat at idle*get a little heat while driving*gs ck'd system*temp ok*flushed heater core*test drove*just not hot enough 110 degrees*replaced thermostat*can't bleed air out completely*presuure ck'd system found timing cover gasket seeping coolant at block*R&R timing cover*test drove 145 degrees. ok now*
74910	02862	74910	GENERAL SERVICE A * WIPERS *sa pma service done topped fluids and aired tires to spec. replaced light bulb.replaced air filter also. M.M
76276	02862	76276	PMA*gs oil lube filter c/k over replaced all 4 tires H.K.*
76579	02862	76579	check L/R tire.MG replaced valve stem left rear tire aired all other tires H.K.*
76876	02862	76876	Check transmission out.MG test drive truck for transmission problems. drove ok. checked transmission fluid , low inspect for leaks found transmission pan rusted out . serviced transmission new filter and fluid 5 qts with a new transmission pan. M.M
77388	02862	77388	pma just had transmission serviced in april/j oil lube filter trans has already been done replaced cap rotor wire set mopar topped off all fluids & aired tires brakes in good shape front & rear H.K.*

W337 - Work Order Notes

01/01/2001 TO 07/21/2025

7/21/2025 7:12:44 AM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
77549	02862	77549	<p>Check engine light?MG</p> <p>09/24/2012 @ 08:11:27checked computer for codes found p0133 o2 b1s1 slow response. rnn up and low sensors cleared codes drove truck ok. M.M</p>
78593	02862	78593	<p>pma</p> <p>needs windshield washer fluid/j Check heater/no heat ? pa service done checked electrical system . checked heat . p test no leaks found . heater core lines one hot one not. rnn heater hoses and power flushed cooling system . added 1 gal antifreeze. filled washer fluid and topped all other fluids. .MM</p>
79118	02862	79118	<p>pma</p> <p>r&r wiper blades/j pma service done topped fluids and aired tires checked brakes . brakes pulsate. rnn front brake pads and rotors. rnn rear pads and rotors. replaced wiper blades. exh noisy. rnn exh system from convertor back . M.M</p>
79865	02862	79865	<p>no brakes. possible hyd leak.</p> <p>10/17/2013 @ 08:22:59. pma service due.</p> <p>10/18/2013 @ 08:11:29</p> <p>oil lube filter c/k over</p> <p>aired tires & topped off all fluids</p> <p>replaced 30 feet off rusted 3/16 brake line</p> <p>replaced left upper & lower ball joint left top ready to fall out</p> <p>right side ok at this time</p> <p>H.K.*</p>
81306	02862	81306	<p>RIGHT REAR BRAKE DRAGGING AND GETTING REALLY HOT/J PMA,MG.</p> <p>06/05/2014 @ 14:06:17 pma service done . topped fluids and checked tires. checked brakes rear right brake locking up. removed and replaced calipers hoses and rotors. made new steel lines for rear bled system. replaced air filter. electrical system was checked. removed and replaced serpentine belt and tensioner. M.M</p>
81619	02862	81619	<p>TURN SIGNAL BULB-RIGHT FRONT/J</p> <p>08/06/2014 @ 09:11:14</p>
83139	02862	83139	<p>PMA</p> <p>BRAKES WENT OUT THIS MORNING-VERY SOFT/Jpma service done topped fluids aired tires . checked battery. replaced right side to left side brake lines and bled system.cleared codes and adjusted. mount and balance 2 new front tires. steering loose. found right and left outer tie rods loose. removed and replaced both outers. took to usa for alignment. M.M SUBLET-ALIGNMENT FRONT, THRUST ANGLE/EDB</p>

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
83236	02862	83236	<div>Check Leaf Springs,MG.</div> <div>05/19/2015 @ 08:10:31</div> <div>needs rear spring shackles ordered</div> <div>05/19/2015 @ 11:08:30 SH</div> <div>05/20/2015</div> <div>cut out old rear leaf shackles and replaced spring shackles and bolts SH MM</div>
83926	02862	83926	<div>PMA,MG.</div> <div>10/28/2015 @ 08:03:50</div> <div>oil lube filter c/k over</div> <div>topped off all fluids & aired tires</div> <div>c/ked battery and antifreeze -35 below</div> <div>H.K.*</div>
84390	02862	84390	<div>wiper blade replacment</div> <div>replaced wiper blades</div> <div>H.K.*</div>
84959	02862	84959	<div>pma</div> <div>stobe light inop</div> <div>check engine light on/j</div> <div>call Barry Sanders when ready 4770</div> <div>oil lube filter c/k over</div> <div>topped off all fluids & aired tires</div> <div>replaced strobe light on top bad</div> <div>code p0442 evap found no leaks cleared codes</div> <div>installed right side latch for door from performance dodge</div> <div>H.K.*</div>
85469	02862	85469	<div>Check Brakes,MG.</div> <div>10/31/2016 @ 07:43:50</div> <div>check brakes, ok front backing plate rusted ad rubbing. move out of way. tie up rear diff hose. check a/c got 32 degrees on drive, never acted up park done. RF</div>

W337 - Work Order Notes

01/01/2001 TO 07/21/2025

7/21/2025 7:12:44 AM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
86221	02862	86221	FEELS "BRAKES LOCKING UP" LEAKS WHEN FILLING FUEL PMC,MG. 02/08/2017 @ 10:44:28 oil lube filter , trans service,rear diff service r/r front caliper brackets too clean slides & replaced rubber slide bushings replaced gas tank filler neck rusted through cleared codes for evap leak p0442 small & large replaced battery bad did not need plugs or wires antifreeze -35 below H.K.*
86658	02862	86658	Check Brakes,MG. 04/24/2017 @ 12:27:59 replaced front rotors pads calipers & hoses replaced rear rotors calipers & pads replaced exhaust from catalytic converter back replaced front and rear shocks replaced right rear leaf spring broken replaced right rear lisence plate light housing broken replaced transmission mount broken H.K.*
87213	02862	87213	PMA SERVICE DUE. 10/05/2017 @ 10:03:05 M.M oil lube filter c/k over topped off all fluids & aired tires c/ked battery & antifreeze -35 below replaced both rear tires worn out replaced gas tank straps rusted away H.K.*

W337 - Work Order Notes

01/01/2001 TO 07/21/2025

7/21/2025 7:12:44 AM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
88263	02862	88263	<p>PMA,Runs Rough,AC,Lights.</p> <p>oil lube filter c/k over topped off all fluids & aired up tires</p> <p>replaced intake gasket & lower plantuim gasket leaking oil & fouling number 8 spark plug</p> <p>replaced cap ,rotor & wires</p> <p>evaced & reccharged a/c,added 1 pound freon & added dye</p> <p>removed one shim from a/c cluth ,not making good contact</p> <p>installed clamp on exhaust by convertor leaking</p> <p>replaced upper & lower radiator hoses & by pass hose ,also replaced 4 vacuum hoses split</p> <p>old and split added 3 gallons antifreeze</p> <p>replaced left front turn signal bulb out</p> <p>H.K.*</p>
89642	02862	89642	<p>PMA,MG.</p> <p>06/07/2019 @ 07:32:05 Road test for problems. pma service performed. topped all fluids and aired tires to spec. replaced air filter. checked lights. checked charging and cranking system. load test battery. performance checked ac system. 40 degrees at duct. lubrication performed. M.M</p>
90756	02862	90756	<p>PMA,MG.</p> <p>03/11/2020 @ 14:25:47</p> <p>mileage today 88256</p> <p>oil lube ffilter c/k over</p> <p>replaced two front tires worn</p> <p>replaced front end parts loose</p> <p>ball joints both sides ,idler arm ,& inner & outter tie rod ends</p> <p>all were worn out</p> <p>replaced wiper blades</p> <p>replaced radiator leaking</p> <p>replaced one transmission line leaking fluid at rubber line</p> <p>H.K.*</p> <p>Note needs alignment still</p> <p>parks took truck to have alignment done.</p> <p>ALIGNMENT COMPLETED by Carrol Wuertz Tire on 03/18/2019. Parks Notified to pick up unit via email. bkb</p>
91602	02862	91602	<p>check tail lights</p> <p>11/11/2020 @ 09:47:57 MS</p> <p>replaced right rear brakelight out</p> <p>replaced 4 bulbs at back of cab</p> <p>H.K.*</p>

W337 - Work Order Notes

01/01/2001 TO 07/21/2025

7/21/2025 7:12:44 AM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
91610	02862	91610	<p>due for PMA-MS road test for problems. pma service performed. changed oil and filter. lubricated chassis. checked tires. 11/32 all 4 front tire press 50 rear 70 psi. pulled wheels and checked brakes. front and rear good shape. hand torque wheels to 140 ft lb. checked exhaust. checked steering linkage and suspension. checked driveshaft. check for leaks found transmission line fitting loose. tightened. valve cover bolts loose. tightened. check belt. checked cooling system. checked hoses. protection -35 . checked electrical system. alternator charging 14.2 to 14.4. load test battery. passed. applied protectant to cable ends. checked transmission fluid/ power steering fluid/ brake fluid. checked wipers and washers. filled fluid. checked heater and ac. check air filter and replaced. degreased engine assembly. road test . M.M</p>
92271	02862	92271	<p>BARRY SANDERS STATES BRAKES FAILED ON UNIT.</p> <p>Parked in front of VMC (pool car row).</p> <p>02/25/2021 @ 12:26:03bkb</p> <p>mileage today 93081</p> <p>replaced brake line from front to back rusted out</p> <p>bleed all four calipers to get air out added new brake fluid and cleaned access brake fluid when bleeding calipers</p> <p>H.k.*</p> <p>replaced water pump leaking coolant</p> <p>also replaced belt and idler pulley making bearing noise</p> <p>added new coolant and washed off engine</p> <p>H.K.*</p> <p>KRATZ REQUESTED 3/16 BULK BRAKE LINE. I SUPPLIED HIM WITH THE ROLL IN THE SUPPLY ROOM AND HE TOOK THE FITTING ASSORTMENT WITH HIM TO COMPLETE THE JOB. A WATER PUMP, BELT AND IDLER PULLEY WERE ALL REQUESTED AND SUPPLIED WITHIN THE SAME DAY. BRAKE FLUID (ONE QUART) WAS ALSO SUPPLIED.</p> <p>03/03/2021 @ 15:26:35 DLS</p> <p>KRATZ NOTIFIED ME MORNING OF 03/04/21 OF ANTIFREEZE FLUID USE.</p> <p>03/04/2021 @ 09:13:38 DLS</p>
92890	02862	92890	<p>unit due for PMA</p> <p>06/01/2021 @ 11:47:46 MS</p> <p>mileage today 94586</p> <p>oil lube filter c/k over</p> <p>topped off all fluids and aired up tires</p> <p>pressure tested cooling system has all new radiator and newwer waterpump no leaks found at this time</p> <p>performance tested a/c and heat controls working properly</p> <p>all lights and strobworking properly ,had to replace left rear liscence plate light socket and wiring was missing</p> <p>all tires and brakes c/k good</p> <p>Note truck fenders bed rockers and bumper rusted out</p> <p>H.K.*</p>

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
93359	02862	93359	<p>operator states fron wheel is squeeking really bad; also states that the head lamps and light on top of the truck are very dim--inspect</p> <p>08/02/2021 @ 14:28:02 MS</p> <p>mileage today 95804</p> <p>r/r front wheels to find caliper slides rusted out ,and top slide on left caliper pushed out toward wheel making noise</p> <p>replaced front caliper slides and sand blasted rust off brackets installed new caliper hardware both front brakes</p> <p>H.K.*</p> <p>replaced front headlight assemblies all fogged up aimed them as best as possible</p> <p>removed top strob to wash out lense very dirty ,all lights in strob are working properly</p> <p>H.K.*</p>
93978	02862	93978	<p>unit due for PMA; check heat--when turning on it has a radiator leak smell; operator states there is a rattle in the front end</p> <p>11/02/2021 @ 15:25:19 MS</p> <p>mileage today 97238</p> <p>oil lube filter c/k over</p> <p>topped off all fluids and aired up tires</p> <p>performance tested a/c and heat control working properly</p> <p>all lights and strob working properly at this time</p> <p>tires and brakes in good shape</p> <p>H.K.*</p> <p>replaced bad radiator leaking at left bottom of tank</p> <p>installed new antifreeze and retested for leaks</p> <p>H.K.*</p> <p>replaced belt tensioner making noise</p> <p>H.k.*</p> <p>replaced front stabilizer links broken and making noise</p> <p>H.K.*</p>

W337 - Work Order Notes

01/01/2001 TO 07/21/2025

7/21/2025 7:12:44 AM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
95266	02862	95266	<p>unit due for PMA & PMC</p> <p>06/07/2022 @ 13:18:57 MS</p> <p>mileage today 99901</p> <p>oil lube filter c/k over</p> <p>topped off all fluids and aired up tires</p> <p>rotated tires side to side c/ked brakes will i had tires off ,brakes in good shape ,torqued wheel lug nuts to specs</p> <p>antifreeze in good shape and no leaks found in cooling system</p> <p>all lights and strob working properly at this time</p> <p>belt and hoses in good shape</p> <p>H.k.*</p> <p>did transmission service ,dropped pan ,removed old filter installed new filter</p> <p>cleaned pan and reusable gasket installed fluid</p> <p>test drove truck and brought back in to c/k for leaks</p> <p>H.K.*</p>
95804	02862	95804	<p>turn signal light bulb is out</p> <p>09/14/2022 @ 14:13:13 MS</p> <p>will bring truck back has electrical issue with turn signals left side flashing fast</p> <p>H.K.*</p>
95963	02862	Repairs	<p>-Repair Turn Signal-add needed repair code after diagnosis</p> <p>-Replace wiper blades</p> <p>-asset had loud exhaust-inspect and add needed repair code</p> <p>10/18/2022 10:50:46 AM MS</p> <p>perform PMA</p> <p>10/19/2022 8:34:31 AM MS</p>
95963	02862	tech notes	<p>10/19/2022 9:16:25 AM</p> <p>oil lube filter c/k over</p> <p>topped off all fluids, aired up tires</p> <p>all lights working properly at this time, pressure tested cooling system no leaks found at this time. battery c/ks good and alternator is charging.</p> <p>repaired bad ground at left front turn signal socket, added new ground and replaced bulb.</p> <p>aired up tires</p> <p>replaced wipers</p> <p>replaced exhaust from catalytic convertor back rusted out</p>
96709	02862	Service	<p>-asset due for PMA</p> <p>4/20/2023 8:10:21 AM MS</p>
96709	02862	TECH NOTES	<p>test drive. change oil and filter. lubricate chassis. check all tires. pull all wheels for brake inspection. all brakes good at this time. install wheels and torque to 145 ft lb. air all tires to 65 psi. check rear diff fluid. check transmission fluid. underside of tuck very rusty. also rear bumper rusted out. checked belt and pulleys. checked cooling system for leaks. topped coolant off. pulled air filter housing off to check filter. was dirty . replaced with new. filled washer tank and replaced wiper blades. check electrical system. load test battery 400 amps and it held load test. checked lights.</p>
97245	02862	Vehicle Intake Notes	<p>___ Confirm Odometer and update in FASTER</p> <p>___ Perform PM A Service</p> <p>9/25/2023 10:20:45 AMbkb</p>

W337 - Work Order Notes

01/01/2001 TO 07/21/2025

7/21/2025 7:12:44 AM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
97245	02862	tech notes	test drive. change oil and filter lubricate chassis. checked tires. fronts good rears dry rotted. needs replaced. pull wheels for brake inspection. fronts and rears still okay. checked belt and pulleys. belt makes little noise when first started then goes away. belt still in good shape. checked cooling system. antifreeze good to -40 degrees. filled washer tank. checked electrical system. took surface load off battery. load test and battery fell below 9.6 . needs battery replaced. pull old battery. was told wouldnt have parts till 9/26 in am. dismounted tires. was told wouldnt have till 9/26 am. got parts today. mount and balance 2 new tires and stems. replaced battery and cleaned cables. check power steering check brake fluid. road test after service. check emergency lights and regular lights. no oil life monitor.
97245	02862	PARTS ON ORDER	BATTERY 09/25/23 @ 1340 FROM AAP, ETA 09/26/23 AM.....ARRIVED 09/26/23 @ 0945 TIRES, REAR, ORDERED FROM CW ON 09/25/23 @1350, ETA 09/26/23 AM.....ARRIVED 09/26/23 @ 0955
97668	02862	Vehicle Intake Notes	-heater is not warming up -drivers side seat belt needs replaced -turn signals/flashers blink a couple times then stop -add needed repair codes after diagnosis 1/2/2024 11:47:29 AM MS
97668	02862	TECH NOTES	start repair. check turn signals. would flash for a few seconds and stop. installed new flasher and flashes as long as you want. checked heater. minimal heat. with scan tool hooked up could only get up to 186 to188. ordered thermostat and gasket. will also flush heater core out. removed and replaced thermostat and gasket. power flush heater core. added 2 gal antifreeze. attached scanner. temp got up to 192 to 194 degrees. good heat. belt was making noise. removed and replaced serpentine belt. test drove. turn signals worked. got good heat. went to salvage yard to find seat. went through all aisles told that had seats. could not find any good seats. remove back cover to gain access to belt. going to send out and be rebuilt. installed seatbelt retractor and reinstalled seat cover. tried and mad sure works. installed wiper blades. bad shape.
97668	02862	PARTS ON ORDER	FLASHER FROM OREILLY'S ORD: 01/04/24 @ 1333 ETA: 01/04/24 1430 1:36:30 PM 1/4/2024 ARR: 01/04/24 @ 1345 SEATBELT IS DISCONTINUED FROM DEALERSHIPS, NO LONGER MANUFACTURED. TRYING TO SOURCE FROM A SALVAGE YARD. THERMOSTAT GASKET FROM ORLY ORD : 01/04/24 @ 1427 ETA: 01/05/24 AM ARR: 01/04/24 @ 1450 BELT FROM OREILLYS ORD: 01/05/24 @ 1020 ETA: 01/05/24 @ 1120 ARR: 01/05/24 @ 1100
97668	02862	SERVICE CALL - SEAT	Retrieve seast from U-Pick parts off McGee. 1/9/2024 9:02:45 AMbkb
97668	02862	tech notes	1/9/2024 11:04:33 AM went with Mike to junk yard they did not have a seat
97668	02862	Tech notes	assist tech in seat belt 1/24/2024 10:26:58 AM
98168	02862	Vehicle Intake Notes	____ Verify Odometer reading and update in FASTER ____ Operator states windows fogging up and water on floor board. ____ Perform PM A Service 5/17/2024 12:47:54 PMbkb

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
98168	02862	tech notes	5/20/2024 -checked fluids before starting -low on coolant and oil -test drove before service -found rt front turn light not working -found steam coming from heater when in heat mode -heater core leaking fluid on floor on rt side -dash will need pulled to replace -when driving if turning to the left slightly there is a rumble noise and vibration in steering wheel, front wheel brgs. -placed on lift and checked over -unit is very rusty -found frame is starting to separate on both sides in back due to rust build up between sections -found left rear backing plate rusted off and dragging on rotor -frame is swelled out a little on rt side in middle of truck -front floor boards and rockers are rusted through and sign material was added on left side of floor board -pictures taken by Keith
98168	02862	Vehicle Intake Notes	-decommission asset for govdeals 6/18/2024 1:34:03 PM MS
98168	02862	tech notes	decommissioning truck most of it is done will finish Monday when I come back finished decommissioned truck

This report displays notes for work orders opened within the specified date range.

REPORT PARAMETERS:

Time Zone: Eastern Standard Time
Start Date: 01/01/2001
End Date: 07/21/2025
Record Type: Work Orders
Work Order Number: All Values
Asset Number: 02862
Organization: All Values
Department: All Values
Class: All Values
Maint Shop: All Values
Work Order Status: All Values

REPORT VERSIONS:

Report Version: 20190312.1700
Script Version: 20190314.1700