

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
20161	89214	20161	
21917	89214	21917	
29868	89214	29868	
33024	89214	33024	
46696	89214	46696	
47798	89214	47798	REAR MUD FLAP MISSING*GS HAD TO MAKE NEW MOUNT*GS
48840	89214	48840	install crash bumper to rear frame*gs
48925	89214	48925	air leak under drivers side of cab*gs SUBLET-FABRICATE AIR COMPRESSER LINE/EDB
52436	89214	52436	PMC*gs SUBLET-FABRICATE AIR LINE(METAL WEAVE)/ EDB
57994	89214	57994	PMA*gs
58332	89214	58332	ck air leaks off brake system*gs
60202	89214	60202	SC*won't start*gs jump start
60533	89214	60533	drivers side w/s wiper broken*gs
60972	89214	60972	jump start at street department/j ck start / charge system*gs replace 2 glow plugs*gs
61088	89214	61088	JUMP @ STREETS
62024	89214	62024	Ck coolant leak*radiator??*gs SUBLET-CLEAN & REPAIR RADIATOR ASSY/EDB

W337 - Work Order Notes

01/01/1988 TO 07/23/2025

7/23/2025 8:01:01 AM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
62409	89214	62409	dead on the line at streets jump start at site
62467	89214	62467	jump start/j 10/25/2006 @ 13:13:06 done rta
62865	89214	62865	SC*battery dead*gs
62895	89214	62895	SC*battery dead*gs
63323	89214	63323	JUMP START/J
63833	89214	63833	PMC*gs
67143	89214	67143	Replace all 4 rear tires*gs SUBLET-SERVICE CALL, DISMT/MT (4) 11R22.5 REAR TIRES AND DISPO OF 4 SCRAP TIRES/ EDB
72235	89214	72235	pma*alternator belt missing*p/s belt flipped*gs PMA RNR ALL BELTS 06/08/2010 @ 07:27:43
77561	89214	77561	Replace wipers.MG 09/26/2012 @ 08:58:34 replaced wiper blades. M.M
77615	89214	77615	Replace headlight unit.MG 10/05/2012 @ 14:11:04 replaced headlight & headlight bucket, rusted out & fell out installed new adjusters H.K.*
79187	89214	79187	PMA,has been 3 years sinse last service,MG. 05/31/2013 @ 11:25:52 pma no BU lights breaker good no power to switch on trans 06/06/2013 @ 09:21:25

W337 - Work Order Notes

01/01/1988 TO 07/23/2025

7/23/2025 8:01:01 AM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
81885	89214	81885	<p>Check Brakes, MG.</p> <p>09/25/2014 @ 07:50:25 Replace wipers, MG.</p> <p>replaced wiper blades, checked brakes, pulled pins on slack adjusters and cleaned , adjusted brakes left front pins were froze. S.H. H.K.</p>
84211	89214	84211	<p>Check Exhaust, MG.</p> <p>01/07/2016 @ 07:12:51</p> <p>checked out exhaust, ordered parts, SH</p> <p>01/15/2016</p> <p>replaced exhaust system from manifolds back, pipes, clamps, muffler, hangers, changed oil and filter, greased, lubed brake pins and checked brakes, replaced spin on trans filter, replaced rear brake chambers, air filter, checked belts, hoses, topped off fluids, checked lights, checked tires, checked batteries and charging system, road tested, SH PMA, MG.</p> <p>01/15/2016 @ 12:52:56</p>
84724	89214	84724	<p>Repair Backup Circuit, MG.</p> <p>04/25/2016 @ 08:12:12</p> <p>checked out back up circuit, replaced 2 bulbs and back up alarm, reinstalled rt front fender upper marker bulb, checked lights and fluids. SH</p>
85269	89214	85269	<p>floor repair. M.M</p> <p>09/12/2016 @ 12:39:09 go to KE Rose to pickup plow blades. M.M H.K removed carpet drivers side found rotted out floor. removed all loose rust cut away bad pieces lay out and cut to fit piece for floor. screwed to existing good floor sealed at seams and undercoated underside of truck M.M H.K</p>
86703	89214	86703	<p>SUBLET - Dismount and mount 11R225 LF tire, 10 oz counteract balance bag, brass truck valve stem installed, scrap tire disposal - SMG</p>
87025	89214	87025	<p>service call building 46. jumped brought back to V.M.C. check electrical system. M.M</p> <p>08/09/2017 @ 14:16:20 replaced 3 batteries. cleaned and protected all cables. checked alternator output. M.M</p>
91362	89214	91362	<p>unit wont start</p> <p>09/22/2020 @ 08:39:29 MS Service call David road at Acreview . found truck cranks no start checked for fuel pressure . has pressure all the way to injector pump tapped on housing truck started. truck starts now. may need injector pump in the future. M.M R.F</p>

W337 - Work Order Notes

01/01/1988 TO 07/23/2025

7/23/2025 8:01:01 AM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
92714	89214	92714	<p>unit due for PMA & PMS</p> <p>05/14/2021 @ 09:42:08 MS</p> <p>test drove before service, placed on rack and did inspection, changed oil and filter, 2 fuel filters, coolant filter, trans spin on filter, compressor filter, air filter, replaced wiper blades, checked lights, front and rear ends, brakes, freed up and lubed brake pins, adjusted brakes, checked springs and found front springs have been bent from rust build up between leafs on rear half of springs both sides, greg and keith looked at it. trying to find springs, rears are starting to do the same thing, checked tires, lubed moving parts, checked belts, hoses, topped off fluids, checked batteries and charging system, springs were ordered, removed old springs and installed new springs, ubolts and hardware. test drove after service and spring installation, rechecked torque and checked for any leaks, reinstalled hood insulation support spring on drivers side. SH</p> <p>Note helped steve install new springs H.K.*</p>
93340	89214	93340	<p>operator states unit has a possible transmission leak</p> <p>07/29/2021 @ 07:08:50 MS</p> <p>drive unit to get warm, check transmission fluid slightly over full, drain some out and check no signs of fluid pouring out, clean and degrease really good. let run for a while no signs of leaks again. take for good road test bring back to shop to recheck still no signs of leakage. return to streets. possible fluid come out vent from being overfull. just a guess though. need to monitor unit. added power serve to fuel system. RF</p> <p>07/29/2021 @ 11:42:07</p>
96044	89214	Annual Safety Inspection	Perform annual Safety Inspection.
96044	89214	tech notes	<p>11/1/2022 2:20:55 PM</p> <p>-test drove before inspection</p> <p>-placed on rack and inspected vehicle</p> <p>-checked lights and replaced rt rear light assy., no brake or turn, light old and deteriorated, corroded inside</p> <p>-checked wipers and washer, no washer, pump leaking</p> <p>-removed washer fluid tank and replaced pump with universal and installed new plug in wiring</p> <p>-checked and aired tires, checked brakes, belts, hoses, fluids, battery and charging system, front and rear ends</p> <p>-placed on hill for pick up</p>
97703	89214	Vehicle Intake Notes	<p>-asset due for PMA & PMS</p> <p>-PMA has not been completed since 5/7/2021</p> <p>1/11/2024 7:59:54 AM MS</p>

W337 - Work Order Notes

01/01/1988 TO 07/23/2025

7/23/2025 8:01:01 AM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
97703	89214	tech notes	<p>1/11/2024</p> <p>-got truck from spot at streets</p> <p>-let warm up and did test drive</p> <p>-checked lights and found 1 middle rear clearance light out, found unplugged, plugged back in and works fine</p> <p>-checked wipers and washer, needs blades</p> <p>-checked front and rear ends, belts, hoses, coolant</p> <p>-needs rt front tire, 29 years old,</p> <p>-needs all 4 rear tires, 17 years old</p> <p>-not replacing tires per manager do to truck being replaced this summer</p> <p>-checked batteries and charging system</p> <p>-checked and adjusted front brakes</p> <p>-changed oil and filter</p> <p>-greased and lubed moving parts</p> <p>-replaced air compressor air filter</p> <p>-checked bed</p> <p>1/12/2024</p> <p>-replaced wiper blades</p> <p>-checked and adjusted rear brakes</p> <p>-removed Cadillac decals from both doors</p> <p>-reinstalled inner fenders</p> <p>-rechecked fluids</p> <p>-test drove and placed on hill for pick up</p>
97830	89214	Service Call	<p>-asset dead @ streets</p> <p>-jump start</p> <p>2/12/2024 8:04:15 AM MS</p>
97830	89214	tech notes	<p>2/12/2024</p> <p>-placed on start all to charge batteries</p> <p>-let charge about 10 minutes</p> <p>-started engine and let run</p>
97938	89214	Service Call	<p>-asset is dead...needs jump started</p> <p>-in spot @ streets</p> <p>3/18/2024 8:29:52 AM MS</p>
97938	89214	TECH NOTES	jump start streets. started truck. running . told streets supervisor.
98382	89214	Service Call	<p>-asset wont start</p> <p>-on fence @ streets</p> <p>7/23/2024 1:22:01 PM MS</p>
98382	89214	tech notes	<p>7/23/2024</p> <p>-placed on start all and let batteries charge a few minutes</p> <p>-started truck and crew is going to use</p>
98918	89214	Service Call	<p>-asset will not start</p> <p>-in spot at streets</p> <p>12/20/2024 7:49:14 AM MS</p>
98918	89214	Jump Start	- jump started truck, batteries need charged and tested or replaced, told driver to not shut the truck off and let the batteries charge from alternator
98969	89214	Service Call	<p>-asset will not start</p> <p>1/3/2025 10:40:48 AM MS</p>
98969	89214	TECH NOTES	update mileage. batteries were dead. had to use booster pack and start all to get running. probably needs batteries checked.
99096	89214	tech notes	14 38,711 completely dead. had to use 2 jump boxes and start all to get running.
99107	89214	Service Call	<p>-asset dead @ bobby place</p> <p>-jump start and get city radio in service truck updated</p> <p>1/23/2025 7:27:57 AM MS</p>

W337 - Work Order Notes

01/01/1988 TO 07/23/2025

7/23/2025 8:01:01 AM

This report displays notes for work orders opened within the specified date range.

WORK ORDER	ASSET NUMBER	SUBJECT	NOTES
99107	89214	Tech Notes	<p>1/23/2025</p> <p>-jump started truck and they brought over to shop for batteries</p> <p>-service truck radio updated</p> <p>1/23/2025</p> <p>-went to 46</p> <p>-jump started 216</p> <p>-all batteries dead</p> <p>-key is broke off in switch but can still be started by it</p> <p>1/23/2025</p> <p>-replaced 3 batteries</p> <p>-cleaned cables</p> <p>-checked charging system</p> <p>-placed on hill for pick up</p>
99173	89214	Service Call	<p>-asset dead in spot @ streets</p> <p>-batteries were replaced 1/23</p> <p>2/11/2025 7:50:32 AM MS</p>
99173	89214	Tech Notes	<p>2/11/2025</p> <p>-truck was dead</p> <p>-placed on jump pack and start all from truck and let charge a few minutes</p> <p>-city radio was on when placed on jump pack</p> <p>-used starting fluid to start truck</p> <p>-left running in spot</p>
99510	89214	Service Call	<p>-asset dead in spot at streets</p> <p>5/5/2025 9:39:52 AM MS</p>
99510	89214	Tech Notes	<p>5/5/2025 10:12:33 AM sh</p> <p>-went to streets</p> <p>-placed unit on start all and had to let charge a little while</p> <p>-they said key was left on</p> <p>-got running then quit again</p> <p>-let charge up some more and got running again and it stayed running</p>
99545	89214	TECH NOTES	<p>went to street department. 214 was dead. jump started and is running. operator stopped by and i told him when they got back at the end of day to turn truck off. he said he would.</p>
99626	89214	Service Call	<p>-asset will not start</p> <p>-along fence at streets</p> <p>6/10/2025 12:58:13 PM MS</p>
99626	89214	Tech Notes	<p>6/10/2025 1:08:43 PM sh</p> <p>-went to streets</p> <p>-placed on truck charger and let charge a few minutes</p> <p>-started up unit and they are going to use</p>
99770	89214	Decommission Intake Notes	<p>___ Verify Odometer reading and update in FASTER</p> <p>___ Perform Decommission Inspection</p> <p>___ Take pics</p> <p>7/23/2025 6:43:25 AMbkb</p>
99770	89214	Technician Notes	<p>Inspection completed. Pictures taken for GovDeals</p> <p>7/23/2025 7:58:47 AM</p>

This report displays notes for work orders opened within the specified date range.

REPORT PARAMETERS:

Time Zone: Eastern Standard Time
Start Date: 01/01/1988
End Date: 07/23/2025
Record Type: Work Orders
Work Order Number: All Values
Asset Number: 89214
Organization: All Values
Department: All Values
Class: All Values
Maint Shop: All Values
Work Order Status: All Values

REPORT VERSIONS:

Report Version: 20190312.1700
Script Version: 20190314.1700