



Richmond Equipment Repairs Ltd.

RR#1 Box 18 Site 16

Didsbury, AB T0M 0W0

Phone: (403) 335-8042

Cell: (403) 507-3432

Fax: (403) 335-4820

nrichmondrepairs@gmail.com

www.richmondequipment.ca

Town Of Carstairs

Box 370

Carstairs TOM ONO

Estimate

January 12-24

John Deere 770CH grader

591906

The full cost of repair is not yet known as wiring harnesses are no longer available.

John Deere is in contact with their used department to see if there is any used wiring harnesses that can be used.

Cost of parts excluding wiring harnesses to repair \$16165.33

If no used harnesses available existing wiring will have to be repaired, cost of which will be determined after repair.

Note: This is an estimate not a quote, prices can vary depending on extent of wear or damage on parts when disassembled & increase in parts cost