

GOOD YEAR





KELLY KETTRES

YOKOHAMA

• OIL & LUBE • EMERGENCY • EMISSION • BRAKES • HYDRAULIC TIRE
HOSES REPAIRS SUSPENSION • ALIGNMENT •

HST # 10035 3366 RT 0001

INVOICE

REPRINT

2020 BANTREE ROAD OTTAWA , ON K1B 5A4 (613)741-0878

2005 INTERNATIO LIC#:5718NY	DNAL 7400 VIN#:1HTWGA	AZT65J130975	km in: 5	1466.0 km out:	0.0	RSR#:000	000 UNIT	#:79-0538	
522424			522424						
Bill to:	TAWA	Ship	to:			5	STORE#:		
			a.	R &			INV#:	ž	
1	2		RFSO				DATE:	1/15/25 06:13	
OTTAWA	Ĺ		79-0538	UN KIP OB9			PAGE:	1	
							PO#:	£	
							FBY: 5	ZP	
						SAI	ESMAN: Z	ZZ	
JOB 100 ANNU	AL SAFETY INSP	ECTIONS (A/C BY 52JP							
WARRANTY	SUGG/REQ	PART	DESCRIPTION DESCRIPTION	NC	QTY	LIST	PRICE	EXTENSION	
PREFORM A PMJ/AIC ANNUAL SAFETY INSPECTION AND REPORT.								*	
PARTS				RTS		0.00			
LABOUR						0.00			
JOB 100 ANNUA	AL SAFETY INSP	ECTIONS (A/C BY 52JP							
WARRANTY	SUGG/REQ	PART	DESCRIPTION	ON	QTY	LIST	PRICE	EXTENSION	
2	REQUIRED	998 100	ANNUAL SAFETY	INSPECTIONS (A/C					
3	REQUIRED	NPN 9025	LUBE OIL FILT	TER					
4	REQUIRED	BEN 109685X	***AIR DRYER						
5	REQUIRED	NPN 1842638C92	FUEL FILTER KIT						
6	REQUIRED	998 1099	SHOP SUPPLIES						
7	REQUIRED	NPN CORE	AIR DRIER CORE CREDIT.						
8	REQUIRED	NPN 3532799C1	AIR FILTER						
9	REQUIRED	NPN HF35476	HYDRAULIC FILTER						
10	REQUIRED	NPN AF26430	FILTER						
11	REQUIRED SHE 500010048 ROTELI		ROTELLA T4 TF	RP.PRO.15W-40 BULK					
			HST						
12	REQUIRED	NPN LF3311	FILTER LUBE C	DIL					
	REPLA	REPLACE ONE U-JOINT STRAP		KIT TO TIGHT THE U-JOINT.					
14	REQUIRED	998 101	UNDER CHASSIS	REPAIRS					
	PREFO	PREFORM A PMB OIL AND FILTER		CHANGE. REPLACE THE AIR DRYER					
	AND GREASE THE UNIT. REPLACE		THE AIR DRYER.						
17	REQUIRED	998 105	PM SERVICES						
18	REQUIRED	NPN 0N1-0046	U-JOINT STRAP	KIT					

CONTINUED NEXT PAGE ****

(24 HR. ROADSIDE SERVICE)

***MUST RETORQUE WHEELS & U.BOLTS WITHIN 100 KMS *** 20% RESTOCKING FEE ON SPECIAL ORDER PARTS



you for choosing Benson Complete Truck Repair and Tire Service Since 1953



SUSPENSION . ALIGNMENT .

GOODFYEAR





KELLY KETTIRES

HYDRAULIC TIRE OIL & LUBE FEMERGENCY EMISSION BRAKES OCONDITIONING

HST # 10035 3366 RT 0001

INVOICE

REPRINT

2020 BANTREE ROAD OTTAWA , ON K1B 5A4 (613)741-0878

2005 INTERNATIONAL 7400

LIC#:5718NY VIN#:1HTWGAZT65J130975

522424

km in: 51466.0 km out: 0.0 RSR#:00000 UNIT#:79-0538

LIST

522424 Bill to: -- 7

Ship to:

STORE#:

льAR & H

INV#:

PRICE EXTENSION

2

् ऽऽ OTTAWA

DATE: 1/15/25 06:13

KESU Z 79-0538 O

PAGE:

PO#: FBY: 52P

SALESMAN: ZZZ

JOB 100 ANNUAL SAFETY INSPECTIONS (A/C BY 52JP

WARRANTY SUGG/REQ PART REQUIRED 088 46743 19

DESCRIPTION DBL BULB SEALED RECT-AMBER

1.0

QTY

REPLACE THE RIGHT SIDE REQUIRED 998 102

MARKER LIGHT ASSEMBLY. UPPER CHASSIS REPAIRS PARTS

0.5

21

LABOUR

TOTAL PARTS

TOTAL LABOUR

TERMS NET 30 DAYS. 2% PER MONTH (24% PER ANNUM) AFTER DUE DATE. MINIMUM SERVICE CHARGE \$3.99 THE CUSTOMER ACKNOWLEDGES THAT THE WHOLE AMOUNT IS PAYABLE AND, WHERE PROVIDED BY LAW, A LIEN ON THE VEHICLE WILL BE RETAINED UNTIL PAYMENT IS MADE IN FULL.

(24 HR. ROADSIDE SERVICE)

***MUST RETORQUE WHEELS & U.BOLTS WITHIN 100 KMS *** 20% RESTOCKING FEE ON SPECIAL ORDER PARTS



Thank you for choosing Benson
Complete Truck Repair and Tire Service -- Since 19 Since 1953