

Vehicle	Repair Order	Meter	Date In	Date Out	Instructions	Hour Meter	Operational Status	Accounting Status
559	019469	53	06/17/2020	06/18/2020	INSTALL AIMS MODULE, NEW PATROL CAR SET UP-CLOSED OUT YEAR END	15	Completed	<none>
559	019502	53	07/07/2020	08/20/2020	NEW VEHICLE SET UP, PARTIALLY COMPLETE, FINISH OUT BUILD, FAB AND INSTALL NEW BR		Completed	<none>
559	019600	1878	09/17/2020	09/17/2020	PD TOOK IN TO HAVE BLACKOUT MODE SET IN VEHICLE		Completed	<none>
559	019612	1878	09/22/2020	09/22/2020	CHARGE OUT ANTENNA NOT PREVIOUSLY CHARGED		Completed	<none>
559	019662	2965	10/12/2020	10/16/2020	LAP TOP NOT CHARGING-DIAGNOSE AND REPLACE CHARGE CORD, PM A	377	Completed	<none>
559	019722	4654	11/19/2020	11/19/2020	SNOW TIRE CHANGE OVER, HAD TO REPLACE TIRE SENSORS	608	Completed	<none>
559	019788	6375	12/21/2020	12/21/2020	PM A	845	Completed	<none>
559	019813	6751	01/04/2021	01/04/2021	PM B, SEE HANDWRITTEN NOTES IN FILE-	904	Completed	<none>
559	019902	9974	04/07/2021	04/07/2021	SNOW TIRE CHANGE OVER	1311	Completed	<none>
559	019955	13114	05/18/2021	05/18/2021	PM A/B, REPAIR EXHAUST BRACKETS	1736	Completed	<none>
559	019985	14543	06/17/2021	06/21/2021	CHECK ENGINE LIGHT ON. FOUND P0496, REPLACED VENT VALVE AND TEST DRIVE SEEMS OK.	1925	Completed	<none>
559	020181	20102	11/01/2021	01/27/2022	PM A/B- PD NOTICED LOW ON OIL-FOUND LEAK NEAR L AXLE HOUSING-REFER TO FORD, FORD	2667	Completed	<none>
559	020423	22011	03/29/2022	03/30/2022	SNOW TIRE SWAP	2883	Completed	<none>
559	020477	23235	04/26/2022	05/13/2022	PM A, REPLACE BRAKE PADS AND ROTORS, REAR SHOCKS LEAKING, REPLACE SHOCKS REPLACE	3043	Completed	<none>
559	020605	27220	08/02/2022	08/02/2022	PM A/B-FOUND RIGHT AXLE BAD. WILL REFER TO DOHERTY FOR WARRANTY-PREVIOUSLY REPLA	3483	Completed	<none>
559	020628	27469	08/15/2022	08/16/2022	TOOK TO FORD FOR REPAIR, NO FRONT BUMPER LIGHTING WHEN RETURNED, FOUND ORIGINAL		Completed	<none>
559	020795	32456	12/05/2022	12/29/2022	SWAP SNOW TIRES TO NEW TIRES **DID NOT HAVE VEHICLE FOR 24 DAYS; 2 SEPARATE TRIP		Completed	<none>
559	020908	35521	02/21/2023	02/22/2023	PM A, REPLACE FRONT ROTORS & BRAKES. TEST DROVE	4579	Completed	<none>
559	020931	36166	03/02/2023	03/02/2023	CAME IN W/ SCREW IN TIRE; TOOK TO SCHWAB TO REPAIR TIRE PICKED UP FROM SCHWAB AN	4668	Completed	<none>
559	021081	39363	05/12/2023	05/12/2023	BRAKES FEEL LIKE WARPED ROTORS. TURN ROTORS DING EXHAUST LEAK FOUND BROKEN EXHAU	5141	Completed	<none>
559	021127	40597	06/07/2023	06/07/2023	PM A/B AXLE HOUSING ON LEFT FRONT LEAKING AGAIN NEEDS TO GO TO FORD	5314	Completed	<none>
559	021172		07/01/2023	07/01/2023	FORD REPAIR INVOICE FOR RO#021127		Completed	<none>
559	021261	44181	09/11/2023	09/11/2023	PM A/B FRONT LEFT OUT CV AXLE BOOT TORN NEEDS REPLACED- REFER TO DEALER DIAGNOSE	5878	Completed	<none>
559	021282	44342	09/21/2023	09/21/2023	PARTITION NOT LOCKING CORRECTLY MAKE NEW LOCKING PIN & ADJUSTING FOR PARTITION I	5913	Completed	<none>
559	021314	45172	10/17/2023	10/17/2023	DIAG CK ENGINE LIGHT; EMISSIONS RELATED TO FUEL CAP LEAK RECHECK FUEL FILLER NEC	5481	Completed	<none>
559	021391	46728	12/05/2023	12/05/2023	PM A SNOW TIRE CHANGE OVER NOTE: HAD PURCHASE LUG NUTS INSTALL PD UNIT NUMBER	6295	Completed	<none>
559	021410	47017	12/18/2023	12/18/2023	CEL ON REFERRED TO FORD DEALER. DEALER REPLACED EVAP VALVE	6243	Completed	<none>
559	021449	47765	01/23/2024	01/30/2024	REFER TO FORD FOR REPAIR CHECK ENGINE LIGHT. FORD REPLACED OXYGEN SENSOR PERFORM	6524	Completed	<none>
559	021487	47811	01/29/2024	02/15/2024	PM A/B CHECK ENGINE LIGHT CAME BACK ON; TAKE TO FORD FORD REPLACED REAR OXYGEN S	6673	Completed	<none>
559	021646	50846	05/20/2024	05/23/2024	C/S RIGHT REAR WINDOW BROKEN DURING ARREST, GET ESTIMATE FROM BODY SHOP, TRANSP	6983	Completed	<none>
559	021662	50846	05/20/2024	05/28/2024	PM A - PERFORM DEQ CERT #U680188 SNOW TIRE SWAP REAR BRAKES NEED REAR SHOCKS	6928	Completed	<none>
559	021703	50846	06/14/2024	06/14/2024	DAY WIRELESS INSTALLED OUTSIDE	6928	Completed	<none>
559	021823		09/03/2024	09/03/2024	FLAT LF TIRE- TAKE TO LES SCHWAB	6720	Completed	<none>
559	021964	56930	12/09/2024	12/11/2024	PM A/B/C SNOW TIRES, FRONT LEFT CV AXLE	7696	Completed	<none>
559	022073	59169	02/19/2025	02/19/2025	PM A; VEHICLE MADE CLUNKING NOISE AND SET CODES FOR ANTI-LOCK BRAKES. CHECK OVER	7994	Completed	<none>
559	022179	60668	04/21/2025	05/06/2025	CHECK ON HILL ASSIST FAILURE, TIRE SENSOR FAULTS. FORD PERFORMED TSB REPLACING T	8213	Completed	<none>
559	022292		07/10/2025		OPEN RO TO ACCOUNT FOR LABOR		Open	<none>