

**CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT**

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 25

PAGE # 17

[illegible]

**CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT**

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS #

25

PAGE #

11

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
1/11/23	97882	Replace Fuel Pump + Filter - clean peeling coating from filler neck	10.47 ⁹⁹		Smitty
5/1/23	98467	Replace CB left defrost fan (#38)	3.95		Smitty
6/12/23	98991	REPAIR PLUG FOR DEFFAN AT RESISTOR - ADJUST BRAKES - REPLACE 2 FRONT SHOCKS			SE MOC
1/1		REPAIR OVER DRIVE SHAFT TAIL PIPE	130.94		
7/26/23		MARKER FIXTURE	6.68		SE
8/22/23	99037	AIR LINE TOP OF ETV. to TURBO	60.58		SE
8/29/23	99122	Replace Fuel Pump/Relay & Filter + clear codes	850.06		Smitty
9/18/23		REPLACE ZONAL 4G MOD.	?		SE
10/4/23	99189	SEND to VALORE'S for BODYWORK LEFTSIDE CAR/BUS DAMAGE	N/C		SE
10/11/23	99301	Replace Fuel Pump Relay & Pigtail Connection	67.57		Smitty
10/19/23	99421	L-Back up fixtures	26.95		SE
10/24/23	99484	AIR SEAT SWITCH	38.86		DP
11/8/23	99724	Replace IPR + ICP Chasing a hot sock hardstart/long crank			
1/1		issue - problem still here - possible injector issue	601.04		Smitty
11/21/23	99850	ADD 2 qts oil	8.10		SE
12/29/23	100256	SEAT REPAIRS - Window stickers - Rt small tail BUB - Rear door patch	360.88		SE SBS
1/1		PANEL + FLOOR molding - TAIL OVER WINDOWS - CLEAN ENG - FRONT MUD FLAP MOUNTS			
1/1		L-F AXLE SEAL + BACKING PLATES - 2 REAR SHOCKS - L-F HUB CAP			
1/12/24		Rt small Tail Light Fixture	10.95		SE
3/18/24	101147	Pm LOF W/F	269.89		SE SBS

**CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT**

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 25

PAGE # 10

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
10/22/21	90953	Replace RT hood stay cable	44.40		Smitty
10/28/21		Clean IMT & MAP Sensors & clear codes	0		Smitty
12/8/21	91871	Clear Codes + Run Regen - clean sensors again & order EGR	0		Smitty
12/19/21	91920	Replace EGR - Force Regen - run on freeway to clean out system	169.18		Smitty
12/28/21	92265	2 L-K TIRES		578.00	Mon
12/28/21	92265	SEAT REPAIRS - L-R MARKER BULB - CLEANING - TAIL PIPE PIN	28.14		SE MOL
1/16/22	92418	REPLACE FUEL TANK	1756.34		MAK SS
1/1		Used light check relay for child minder & installed new one			
3/18/22		for Child Minder	4.95		Smitty
3/22/22		Replace Engine Coolant Sensor & Regen/Driver Monitor	74.85		Smitty
3/29/22	94786	PM LOF FUEL Filter - 10 AMP MARKER Lig / RT BREAKER	226.56		SS 555 MORE
5/19/22	96346	Road Call - Power Supply last to fans controller - replace bracket #22	5.00		Smitty
5/24/22		Child Reminder System malfunctioning - checked breakers & found			
6/25/22		#40 to have no continuity - replaced - system worked	5.00		Smitty
7/15/22	104,354	Replace Rear end body control solenoid	63.39		Smitty
7/25/22	96939	RAD CAP - BATT DOOR LATCH - STRINGER REPAIRS	103.99		Mon
9/20/22	97054	CLAMP FOR TURBO HOSE AT TURBO	21.00		SE
10/14/22	97224	RT FLAT minor	27.00		SB
12/18/22	97495	REPLACE OIL SENDER	142.00		MILK
12/18/22	97495	Boost Pump - ROOF SCREWS - STRINGER REPAIRS	157.25		Mon

CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT

VEHICLE MAINTENANCE RECORD

VEHICLE #

25

BUS #

25

PAGE #

9

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
9/13/19		Replace Bay Radio Knob	4.00		mon
9/14/19		install Fire wall Repair Kit, install dog			
9/1/19		house brackets Replace Right Rear tail light			
11/15/19		bulb & Right Front Replace broken Fox Fogs	196.00		Smith mon
11/18/19	84202	Replace Both front tires & rt tie rod	60.00	New Takes off	Smithy
2/20/20	86935	PM Oil & Fuel Filter Lube	225.00		mon
3/13/20	86935	Replace Radiator, lower hose to engine & all trans lines,			
1/1/20		resal crank case ventilation unit on rt side of engine	1670.00		Smithy
3/11/20		Strain Left Rear Em Window	8.00		mon
7/7/20		Replace batteries	345.00		mon
9/15/20		Replace Left Side Tie Rod End.	50.00		mon
1/26/21	87918	Left Headlight - Clean Eng - Adjust Brakes	2.95		SE
3/13/21	88158	Replace Main Body Solenoid	63.39		Smithy
3/30/21	88533	Replace DPF (common broken) Cerni clear codes	3462.30		Smithy
4/21/21		Replace drive seat bottom & Heater Filter	154.00		mon
5/12/21	89322	Repair wiring to left headlight & left little taillight	11.69		Smithy/mon
5/13/21	89355	Replace Head light assemblies	592.72		Smithy
7/16/21	89846	10 AMP CIR BREAKER for Dome Lights - Doc Clamp - Tachup FD # Unit 2nd floor	32.51		SBS
10/1/21	90018	SEND to JIM WILLIAMS REPLACE TRANS CONTROL MODULE	1974.05		SE
10/4/21	90018	2 HEADLIGHT BULBS	6.00		SE

1879

**CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT**

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 25

PAGE # 8

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
9/10/18	72427	R-R TIRES		600.00	JS
10/5/18	73057	Replace #1 Injector & harness, Replace Boost pump & clean	904.03		Smitty
10/11/18	73144	Clean DSI & Run Parked Regen	—		Smitty
10/17/18	73418	Left Amber Sway bulb & center front marker	3.70		Smitty
2/1/19	76457	Replace Right & Left Front Air Lines,			
1/1		Replace clamps on upper hose tighten lower	60.00		mon
2/27/19		R-F Sway Bulb - #7 ZONE ZONE TAGS	10.50		JS
2/28/19		Replace Right Rear taillight bulb	2.00		mon
3/13/19		Replace Right Rear out line with use one			mon
3/29/19	78,266	Replace ITV & Boost, replace breather unit & change to open	957.83		Smitty
1/1		system			
3/29/19	78,266	7 seat bottoms/2 seat back-drivers bottom & back stop light bulb			SE & Mark
5/22/19		& tail light - replace rear brakes	933.80		
5/22/19		3 BRAKE Light Bulbs	4.00		JS
5/30/19		L-R BRAKE CHANGE ANGLE - FRONT FRONT RIMS - CLEAN ENG	33.75		mon
8/16/19	80688	PM LOF FUEL Filter	211.03		SE mon
8/16/19	80688	EXH 90° ELBOW	63.90		mon
8/12/19		Replace heater control Regulation	17.95		mon
8/27/19	81017	Secure latch for E window buzzers repair (RR)	8.00		Smitty
8/29/19	81114	Secure latch for LF E window	8.00		Smitty

**CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT**

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 25

PAGE # 7

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
3/8/17		RECALL #16510 (Hose) CERNI	11/C		RE
4/10/17	601400	Replace RT Rf with flat Repair		65.00	Smithy
5/18/17	62097	2 Dome Lights - REPAIR MANY SEATS - SPILL KIT - CLEAN ENG	24.00		SE mon
1/1		Adjust BRAKES - STRINGER RT-FRT OF AXLE - DOG BONE			
5/18/17	62097	2 L-R TIRES		600.00	SE mon
5/12/17	62898	SEND TO CERNI (LAKETACK) FOR R-R Body DAMAGE	10,625.98		SE
1/1		PICK UP DN 5-31-17			
6/23/17	62908	OIL & FILTER, FUEL FILTER, Lube lights	185.00		mon
8/29/17	63290	R-R New 8 way Bulb 1 Broom	14.69		SE
8/31/17	63363	Replace RT Rf brake chamber	56.08		Smithy
1/19/18	66988	Boost Pump	135.00		SE/SBS
2/12/18	67574	Replace Block Heater Element	116.40		Smithy
4/16/18	69207	Seat repairs - PAINT Rims Adjust BRAKES	65.00		SE mon
4/24/18	69469	L-Handlight - Air Filter - STEADWELL SUPPERS - 2 REAR AIR BAGS	392.35		SE mon/SBS
4/27/18	69615	RTR BELT	48.34		mon
6/25/18	71247	Replace Front Lower door glass, wiper & block	180.00		mon
6/25/18	71247	OIL & FILTER, REPLACE FUEL FILTER, Lube, check lights	220.00		mon
7/24/18	71815	Fueled with mixed drop - drove to Pier 619 - State Ave Akron			
1/1		Hebrew Academy Trip - seemed OK - fuel drained completely upon			
1/1		returning & refilled with fresh clean fuel			Smithy

**CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT**

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 25

PAGE # 6

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
11/19/15	50016	Replace seat belt	246.89		mon
11/11/15	50016	Replace windshield (push glass) Adapters installed	490.16		SE
2/8/16		Repair 7 seats	35.00		Smitty
2/8/16	50987	Replace high psi turbo, Flush & clean			
1/1		inter cooler, send out DPF for cleaning			
1/1		Replace pressure sensor and intake air sensor	2664.45		Smitty mon
3/8/16	51421	Replace breaker for Emergency Exit buzzers	6.00		Smitty
4/8/16	51789	Repair drivers seat cover - #8 seat back broken - 1 roof screw - cleaning	20.00		Smitty mon
4/27/16		Towels	6.50		Smitty
4/27/16	52047	Replace filter minder	40.09		mon
4/29/16		Reattach belt cutter in drivers caddy hole	1.00		Smitty
9/19/16	54951	Rt min bus turn fixture	6.62		SE
10/5/16	55577	FLAT minion - 1 GAL COOLANT	35.99		SE
11/8/16	56759	PM LOP FUEL Filter	173.65		Smitty mon
12/13/16	58067	REBUILD ZOMAR CRADLE	22.95		SE
12/14/16	58125	Replace left rear brake chamber	48.40		Smitty
1/17/17	58608	Replace EGR Cooler, & attaching tubes	1714.17		Smitty
1/24/17		towels	6.50		mon
2/7/17	59429	TAIL BULB - R-F RED 8way BULB	5.18		SE
2/10/17	59583	BLOCK HEAT PLUG END & MARKER fixture	71.23		SE/mon

**CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT**

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 25

PAGE # 5

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
9/30/14		Broom	11.00		SE
10/10/14	39420	ADD 1 GAL COOLANT	12.44		SE
12/12/14		add 1 gal coolant	12.44		Smithy
1/29/15	42371	PM LOF/service air dryer, replace drivers seat bottom & uppers	320.15		Smithy M. K. F. E. R.
3/13/15	43525	MARKER BULB	.69		SE
4/1/15	43958	RT head light	7.69		Smithy
4/19/15	44125	STEP WELL BULB	.69		SE
4/20/15	44432	Replace by pass tube add coolant	45.44		mon
4/30/15	44806	Replace RT Tie Rod & Both front Tires	69.98	892	Smithy
5/14/15		1 SEAT BOTTOM	15.00		SE
7/20/15	47016	ADD 2 gal coolant	24.88		Smithy
8/24/15		Replace left corner marker	8.74		Smithy
8/21/15		LAKE TRUCK RECALL REFLASH	M/C		SE
8/25/15	47317	BACK UP ALARM	47.40		SE
8/13/15	47554	2 MARKER BULBS	1.40		SE
9/16/15	48063	RIR 2WAY ANTENNA	6.00		SE
9/24/15		REFASTEN NO 7 EM WINDOW bracket			mon
9/30/15		L - HEADLIGHT	7.69		SE
10/15/15	48708	ADD 1 GAL COOLANT	12.44		SE
10/27/15	49656	PM LOF FUEL Filter - SERV. AIR DRYER - 1 GAL COOLANT - REPAIR MID	239.79		Smithy

BUS FAN BAD PLUG & MOTOR - BAD CONN. FOR WINDOW LIGHTS & BUZZ AT FUSE PANEL (SPICE) BLAKE WIRE

**CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT**

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 25

PAGE # 4

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
4/17/14	35179	1 GAL COOLANT	12.44		SE
4/17/14	35537	PM 2 OF add 1 gal coolant	241.23		Smithy M. Kefner
4/18/14	35548	R+ - LARGE 1157 BUIB - 2 Rivits For SP. 11 Kit	1.89		SE
5/23/14	36616	Replce left headlight bulb	7.97		Smithy
5/27/14	36716	Replace left lg brake bulb & Rt corner marker	2.29		Smithy
6/11/14	37116	ADD 1 1/2 GAL COOLANT	18.66		SE
7/9/14		TOWELS	6.50		SE
7/9/14	37808	Replce starter	195.00		MOR
7/16/14	37819	REPAIR SEAT COVERS + BACK BATTLES - BACK UP ALARM - Tighten FRONT	72.00		SE
1/1		Bumpak - Push OUT R-R Bumpal CORNER - SCREW ABOVE DRIVER WINDOW			
1/1		WASH ENG + TRANS			
7/22/14		FREE UP WATER SHUT OFF VALVE, REPAIR			
1/1		Right side wheel well CRACK	12.00		MOR
8/27/14	38141	R-F MARKER fixture	14.75		SE
9/4/14	38320	R-F RED SWAY BUIB	4.12		SE
9/17/14		TOWELS	6.50		SE
9/22/14	38962	REPLACE ZONAR ZONE TAG #10 R+ REAR	18.00		SE
9/23/14	38998	REPLACE STARTER FROM CUSTOMEREC. Install By Pass PLUG FOR	245.00		MOR
1/1		OVER HEAT SWITCH			
9/24/14	38998	R+ R-R MARKER fixture	6.49		SE

**CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT**

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 25

PAGE # 3

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
2'25'13	23641	PM LOF	173.94		Smitty
4'14'13	25026	Rt HEADLIGHT + 1 GAL COOLANT	19.43		SE/Smitty
5'22'13	27388	add coolant 1/2 gal	9.50		mon
7'11'13	28043	Tighten mirror- REPAIR SEATS- MARKER LIGHTS- PAINT WHEELS	61.69		SE
1'1'13		CLEAN ENG + TRANS- Adjust BRAKES- add coolant 1/2 GAL.			
7'17'13	28043	Rm DOG BONE	173.47		SE
7'19'13	28121	SEND to LAKE TRUCK FOR NO THROTTLE AT ALL- REPLACE TEMP SENSOR	N/C		SE
8'15'13		TOWEL	6.58		SE
10'7'13	29933	PM LOF- FUEL Filter- serv. AIR DRYER	239.36		SE/mon
11'4'13	30896	PATCH SEATS	10.00		SE
11'5'13		BROOM	9.43		SE
11'15'13	Replace	Center front marker bulb	6.00		Smitty
11'14'13	31255	Replace stop arm motor + update indexing blade	118.90		Smitty
11'25'13	31648	Rm STOP ARM MOTOR Check Adjustment OK 1 AMBER Bulb	123.02		SE/mon
12'10'13	32069	Adjust timing blade on stop arm motor repair coolant leak			
1'1'13		at lower hose to radiator + add washer solvent	15.00		Smitty
12'12'13	32155	REPLACE STOP ARM MOTOR- RECHECK adjustments	118.90		mon
12'13'13	32223	Replace Stop arm motor + control module	295.65		Smitty
12'23'13		Repair LEFT REAR top corner + Replace bulbs	8.24		mon
1'12'13		SEAT RECALL #13512	N/C		SE

CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 25

PAGE # 2

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
6/26/12	17145	CLEAN OIL FILTER SEAT REPAIR, DIPTUBE @ TRANS 15 ⁰⁰	15 ⁰⁰		RP
7/18/12	17216	TIGHTEN HOOD REST, REPLACE BOLT ON CONVERTER 1 ⁰⁰ , REPLACE			
1/1		MISSING SCREWS (INTERIOR) 10 ⁰⁰	2 ⁰⁰		RP
7/20/12	17238	AD-9 AIR DRYER CARTRIDGE	27 ⁵²		RP
7/23/12		EXTINGUISHER BRACKET	25 ⁰⁰		RP
7/24/12	17596	RECALL # 12913 LAKE TRUCK	N/C		SE
7/31/12	17324	LOF + Fuel Filter PF 7879, 1 gal coolant	168 ⁶⁹		RP
8/31/12	17554	Replace Right small brake bulb	.50		Smithy
9/17/12	17600	Replace Right Flarewrench & heater	20 ⁰⁰		mo
9/19/12	18194	Clean Grounds for front marker bulb	0		Smithy
9/21/12	18302	RTR L-R LARGE TAIL BULB	136		SE
10/12/12		Belt CUTTER	4.02		SE
10/16/12	19231	SEND to LAKE TRUCK RTR FUEL PUMP + CLEAN FUEL SYS	N/C		SE
10/16/12	19231	LAKE TRUCK CAMPAIGN # 12927 REFLASH	N/C		SE
10/17/12	19344	Both EXL Lights on DPF + 5 BELTS - PARK REGEN + ROAD TEST OIL	NK		SE
12/4/12		modules	6.51		mo
12/4/12	21396	REPLACE ELBOW HOSE AT HEAT PUMP 10 GAL COOLANT ROAD CALL	130.06		SE
1/15/12	22131	L- HEADLIGHT	7.69		SE
2/15/13		window sticker & STEP light bulb	3.50		mo
2/15/13	23641	Replace Fuel Pump/warr	0		Smithy

CLEVELAND HEIGHTS-UNIVERSITY HEIGHTS CITY SCHOOL DISTRICT
 DEPARTMENT OF BUSINESS SERVICES - TRANSPORTATION DEPARTMENT

VEHICLE MAINTENANCE RECORD

VEHICLE # _____

BUS # 25

PAGE # 1

DATE	MILEAGE	DESCRIPTION OF REPAIR	MAINT. COST	TIRE COST	MEC. INIT.
11/18/10		Took delivery from Power City Int	87.00		SW
1/19/11	1074	Install Zonarc & Trash can	5.00		SE
1/27/11		Towels	6.50		Smithy
1/24/11		Northcoast Radio Camera & Radio Install	530.25		SW
3/2/11	2861	Replace Rt & Lft amber 8 way bulb	6.59		Smithy
3/30/11	3645	Tighten Air Line Top of Comp	N/C		SE
4/28/11	4455	ReFlash & Repair Eight ways	N/C		SW
6/8/11		TOWEL	6.50		SE
6/15/11	6589	Replace Right & Left Em Labels, Lubr batt door	4.00		mon
9/13/11	7866	Sent to Lake Truck ^(warranty) for Check Engine Light, Replaced Fuel Filter & Fuel Pressure Sensor	N/C		SW
10/3/11	8409	Replace left front Amber 8-way bulb	4.59		Smithy
11/14/11	9892	PM LOF add 1gal coolant & tighten upper rad hose	197.92		Smithy
1/13/12	11628	Add 2ats oil	6.77		SW
2/21/12		Bus Wash Gloves	6.00		SW
2/20/12		Towels	6.50		mon
2/29/12	13561	Replace LEFT Top side door glass, install mirror bracket	75.00		mon SE Smithy
3/16/12		RTR marker Bulb	1.36		SE
5/9/12	15983	TAIL Bulb	1.50		SE
6/25/12	17145	Repair seats - shorten Heater Hose - Tighten out Riggers - Wash eng & trans	5.00		SE