

## GovDeals Bus Inspection Form

Inventory ID:

Asset Number: 731

Fair Market Value:

---

**Short Description**

Year: 2015

Make: Champion

Model: C4500

VIN: 1GB6G5BLXF1123838

Title Restriction: ☐ Yes ☒ No

Mileage/ Odometer: 346323

Odometer Accurate ☒ Yes ☐ No [Explain odometer](#)

[inaccuracy](#)

---

**Long Description**

Primary use for bus: Passenger Transport Number of Passengers: 10

This vehicle: ☐ Starts ☒ Starts with a boost and ☒ Runs ☐ Does not run ☐ For Parts Only

Engine Manufacturer: General Motors Duramax Engine Type: 6.6 L, Config.: V8 Fuel Type: Diesel

This vehicle was maintained every 5000 ☐ Days ☐ Hours ☒ Miles

Engine Condition: ☒ Runs ☐ Needs Repair ☐ Does Not Run ☐ Unknown ☐ Rebuilt (Date: N/A)

Engine Repairs Needed: No known issues noted.

Date Removed From Service: [Click here to enter a date.](#) Maintenance Records: ☒ Available ☐ Unavailable

Transmission Manufacturer: GM6L90E ☒ Automatic ☐ Manual 6 Speed

Transmission Condition is: ☒ Operable ☐ Needs Repair ☐ Unknown ☐ Rebuilt (Date: [Click here to enter a date.](#))

Repairs Needed: Unknown.

Date Removed From Service: [Click here to enter a date.](#) Maintenance Records: ☒ Available ☐ Unavailable

---

**Exterior Description:**

Color: White Windows: ☒ No Damaged Glass ☐ Damaged None Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition:  
☒ Low NA ☐ Flat NA

Damage to: Entire exterior of the vehicle has minor dents, dings, and scratches; 9+ year old vehicle.

Additional Damage to: Passenger entry doors does not operate from switch

Decals: ☐ None ☒ Have been sprayed over ☒ Have been removed & ☒ Impressions remain ☐ No impressions

Other Exterior Information:

---

**Interior Description:**

Seat Color: Blue ☐ Vinyl ☐ Cloth ☒ Leather

Floor Color: Blue

Damage to Seats: All seating has minor tears, scratches, wear spots, and stains; 9+ year old vehicle. Drivers seat is Worn.

Damage to Dash/Flooring: Dash has minor scratches, dings, and worn areas. Flooring has stains.

Radio: Brand N/A ☐AM ☐AM/FM Cassette ☐AM/FM CD

Air Conditioner: ☒Yes ☐No AC Operating Condition: ☐Cold ☒Unknown

Other Interior Information/Options: Rear A/C does not operate

---

**Other Equipment: Description** Braun Wheelchair lift

**Manufacturer** Braun **Model** NCL919FIBHB-2 **Serial #** FA-05920