

# Vehicle Inspection Form

Inventory ID: **3346**

Asset Number: **52936**

Fair Market Value: \_\_\_\_\_

**Short Description:**

Year 2011

Make FORD

Model FUSION

**VIN:**

3 F A H P 0 H G 7 B R 2 7 5 5 0 4

Title Restriction: ☐ Y ☒ N

**Odometer:**

5 9 1 0 8   

☒ Miles

☐ Kilometers

Odometer Accurate

☒ Y

☐ N:

\_\_\_\_\_

**Long Description:**

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

**Engine- Type:** 3.0 L, V 6 ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed: BODY DAMAGE ON PASSENGER FRONT DOOR

This vehicle was maintained every 3000 ☐ Days ☐ Hours ☒ Miles

Date Removed From Service: 5-1-25 Maintenance Records: ☒ Available ☐ Not Available For Inspection

**Transmission:** ☒ Automatic ☐ Manual    Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: \_\_\_\_\_

**Drivetrain:** ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: \_\_\_\_\_

**Exterior:** Color: WHITE Windows: ☒ No Cracked Glass ☐ Cracked \_\_\_\_\_

Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: GOOD Tread: \_\_\_\_\_ #Flat \_\_\_\_\_ Hubcaps # \_\_\_\_\_

Major Damage to: PASSENGER FRONT DOOR

Additional Damage: IMPRESSION OF VEHICLE NUMBER LEFT ON ROOF & DAMAGE FROM LIGHT BAR

Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☒ Impressions Remain ☐ No Impressions

Emergency equip: ☒ None ☒ Has been removed & ☒ There are holes in the exterior ☐ There are no holes

**Interior:** Color GRAY ☐ Cloth ☐ Vinyl ☐ Leather

Damage to Seats: MINOR

Damage to Dash/Floor: \_\_\_\_\_

Radio: ☒ Stock or ☐ Brand & Model: \_\_\_\_\_ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD

☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC

Air Bags: ☐ Driver's Side ☐ Dual

☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☒ Climate Control

Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats

**Additional Equipment:** \_\_\_\_\_

Manufacturer \_\_\_\_\_ Model \_\_\_\_\_ Serial # \_\_\_\_\_

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand \_\_\_\_\_ ☐ Hitch: Type \_\_\_\_\_

**Location of Asset:** 830 SE MARTIN LUTHER KING JR BLVD STUART FLORIDA

**For more information contact:** DANIELLE (772) 220-3942

**Reminder:** Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.