

Heavy Truck Inspection Form

Inventory ID:

Asset Number: 2522

Fair Market Value:

Short Description:

Year 2017

Manufacturer Hines Specialty Vehicle Group

Model Cane Carrier Company

VIN: 1H9AAAAC9H1674484

Title: ☐ Clean Title ☐ Salvage Title ☐ No Title ☐ Court Documents Only
☐ SF97 Form ☐ Other

Odometer: 48587 ☒ Miles ☐ Kilometers ☐ Hours Odometer Accurate? ☒ Yes ☐ No ☐ Unknown

Long Description: Primary Use for Vehicle: Recycle Collection GVW: 40,360

This Vehicle: ☐ Starts ☒ Starts with a Boost & ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only

Date Removed From Service: Maintenance Records: ☐ Available ☐ Not Available For Inspection

Engine Manufacture: Cummins Engine: 8.9 L, V ☐ Gas ☒ Diesel

This vehicle was maintained every 5000 ☐ Days ☐ Hours ☒ Miles # of Axles 2

Engine Condition: ☒ Is operable ☐ Needs repair ☐ Is in Unknown Condition Jake Brake: ☐ Yes ☒ No

Engine Repairs needed: None when removed from service

Transmission Manufacture: Allison ☒ Automatic ☐ Manual Speed

Transmission Condition is: ☒ Operable ☐ Needs Repair ☐ Unknown Rebuilt Date:

Transmission Repairs Needed: None when removed from service

Exterior: Color White Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: ☐ Low ☐ Flat

Damage to: Passenger side recycle bin has dent on bottom

Additional Damage to:

Decals: ☐ None ☐ Have been sprayed ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions

Capacity: Loader: ☐ Front ☐ Side Electronic Tarp: ☐ Yes ☒ No Condition:

Interior: Color Dark Gray ☒ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: Driver + Passenger seat bottoms are torn

Damage to Dash/Floor: None

Radio: Brand Dual (Broken) ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD

☐ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors Airbags: ☐ Driver's Side ☐ Dual

☒ AC ☐ No AC AC Condition: ☒ Cold ☐ Unknown Power: ☐ Windows ☐ Doorlocks ☒ Steering ☐ Seats

Additional Equipment: Manufacturer: G-S Products Model: G55035D

Serial # G55035322A17

Description: Recycle Body

Equipment Condition: ☒ Is operable ☐ Needs repair ☐ Is in Unknown Condition

Other Equipment:

Location of Asset: